



**Soderstrom Architects**

Facilities Assessment Report  
Parkrose School District  
Multnomah County, Oregon



# TABLE OF CONTENTS

## I Executive Summary

---

|   |    |
|---|----|
| a. Introduction - Team Members                | 3  |
| b. Introduction - Klamath County and District | 4  |
| c. Purpose, Demographics and Funds            | 5  |
| d. District Map                               | 6  |
| e. District Building Timeline                 | 7  |
| f. Building Data                              | 8  |
| g. Critical Needs Summary                     | 9  |
| h. Condition Performance District Summary     | 14 |
| i. Condition Summary - Structural             | 18 |

## II Facilities Condition Assessments

---

## III Appendix

---

|  |     |
|--|-----|
| a. Facility Condition Assessments - Structural | 85  |
| b. Facility Condition Assessments - MEP        | 142 |
| c. ASHRAE Equipment Life Expectancy Charts     | 194 |
| d. ODE Facility Condition Worksheets           | 196 |
| e. Roofing Report                              | 237 |

# EXECUTIVE SUMMARY

## Introduction - Team Members

Soderstrom Architects was hired in 2021 to provide the Parkrose School District (District) with a Facilities Assessment Report (FAR), after being awarded a Technical Assistance Program (TAP) grant from the Oregon Department of Education (ODE). The following is a list of people and consultants contributing to the assessment process who have provided their time and effort to help everyone understand District needs and concerns.

### District Administration:

Michael Lopes-Serrao, Superintendent  
 Sharie Lewis, Director of Finance  
 Robyn Stolin, Facilities Manager  
 Jon Sanders, HVAC Specialist  
 Sarah Lamp-Christensen, Director of Teaching and Learning  
 Christine Blouke, Technology Director  
 Andrew McLaughlin, IT Systems Support  
 Ryan Gallagher, Athletic Director  
 Debra Garza, Nutrition Services  
 Julie Sams, Student Services  
 Teresa Hooper, Transportation  
 Michele Straub, Aquatics  
 Kirstie Opel, Facilities Coordinator

### Site-Based Administration:

Nichole Watson, Principal, Prescott Elementary  
 Samantha Ragaisis, Principal Russell Academy  
 Megan Filiault, Principal, Sacramento Elementary  
 Nathan Mount, Principal, Shaver Elementary  
 Annette Sweeney, Principal, Parkrose Middle School  
 Molly Ouche, Principal, Parkrose High School

### Architectural:

Marlene Gillis, President, Soderstrom Architects  
 Carson Shields, Project Manager, Soderstrom Architects  
 Priya Kandharkar, Designer, Soderstrom Architects

### Mechanical, Electrical and Plumbing:

Jianpeng Yang, Project Engineer, Ameresco

### Structural:

Kristofer Tønning, Associate, ZCS Engineering

| #  | School Name                               | Grades Served | Attendance (2020-21) | School ID | ODE Building ID | Address                                     |
|--|---|---------------|----------------------|-----------|-----------------|---|
| <b>Elementary Schools (K - 5)</b>          |   |               |                      |           |                 |   |
| 01   | Prescott Elementary School                | K-5           | 331                  | 925       | 21810100        | 10410 NE Prescott St., Portland, OR 97220   |
| 02   | Russell Academy                           | K-5           | 371                  | 926       | 21810200        | 2700 NE 127th Ave., Portland, OR 97230      |
| 03   | Sacramento Elementary School              | K-5           | 305                  | 927       | 21810300        | 11400 NE Sacramento St., Portland, OR 97220 |
| 04   | Shaver Elementary School                  | K-5           | 275                  | 928       | 21810400        | 3701 NE 131st Pl., Portland, OR 97230       |
| <b>Middle Schools (6-8)</b>                |   |               |                      |           |                 |   |
| 05   | Parkrose Middle School                    | 6-8           | 778                  | 930       | 21810500        | 11800 NE Shaver St., Portland, OR 97220     |
| <b>High Schools (9-12)</b>                 |   |               |                      |           |                 |   |
| 06A  | Parkrose High School                      | 9-12          | 976                  | 931       | 21810600        | 12003 NE Shaver St., Portland, OR 97220     |
| 06B  | Parkrose High School - Fine Arts Building |               |                      |           | 21810601        |   |
| 06C  | Parkrose High School - Stadium            |               |                      |           | 21810602        |   |
| <b>District Rental / Leased Properties</b> |   |               |                      |           |                 |   |
| 07   | Sumner Elementary / Helensview School     | 9-12          | MESD                 | 2181      | 21810005        | 8678 NE Sumner St., Portland, OR 97220      |
| 08   | Thompson Elementary / Wheatley School     | 6-8           | MESD                 | 2181      | 21810004        | 14030 NE Sacramento St., Portland, OR 97230 |
| 09   | Knott Elementary / Knott Creek School     | K-5           | MESD                 | 2181      | 21810003        | 11456 NE Knott St., Portland, OR 97220      |
| <b>District Administration and Support</b> |   |               |                      |           |                 |   |
| 10A  | District Office                           | N/A           | N/A                  | 2181      | 21810000        | 10636 NE Prescott St., Portland, OR, 97220  |
| 10B  | Maintenance Offices + Shop                |               |                      |           | 21810001        |   |
| 10C  | Bus Barn + Shop                           |               |                      |           | 21810002        |   |
| Total Enrollment:                          |   |               | <b>3,036</b>         |           |                 |   |

# EXECUTIVE SUMMARY

## Introduction -

### Parkrose and Multnomah County, Oregon

Parkrose is a neighborhood in the Northeast section of Portland, Oregon and includes Maywood Park. The Parkrose plat was filed October 5, 1911. A branch post office of Portland was established there in 1921.

Parkrose had been a small farming and residential suburb of Portland until the 1920s. The Oregon Journal noted on May 23, 1925, "Parkrose is a primary commuting center. . . It is one of the most progressive and promising commuting districts on the eastern border of the city." A significant community identifier is the Rossi Farms property adjacent to the middle and high school, off NE 122nd north of Shaver Street. Planned development of these farms in the near future by the City of Portland will have significant impacts on future growth and enrollment for the District.

Parkrose was annexed by Portland, and the community was enumerated as a "Census-designated place" in 1980, when the community recorded a population of 21,108.

### Introduction - Parkrose School District

The Parkrose School District (District) is a small urban district in the northeast section of Portland with four (4) elementary schools, one (1) middle school and one (1) high school serving the community. The District began in 1885 as a schoolhouse on Sandy and 122nd. District records begin in the summer of 1913 with 131 students enrolled, ranging in age from four to 19.

That same year, the district bonded for \$10,000 to construct and furnish a four-room building, Parkrose Elementary at 106th and Wygant. The upper floor became the first Parkrose high school a few years later. In the mid-1920s, a \$31,000 bond measure passed, 72-9, and a new brick high school, Prescott High School, was built at 10629 NE Prescott.

The growth of the 1950s and 1960s created a building boom, with Prescott Elementary completed in 1947, the new Parkrose High School in 1950, Knott Street Elementary in 1951, Sumner Elementary in 1954, Thompson Elementary in 1957, Parkrose Heights Junior High in 1957, Sacramento Elementary in 1960, Parkrose Middle School (Formerly Fremont) in 1961, Shaver Elementary in 1963 and Russell Elementary in 1963.

District enrollment peaked during the 1969-70 school year at 5,656, with just over 1,400 of those high school students. Enrollment reduced and then leveled off in the 1980s and has stayed fairly stable between 3,300 and 3,500 since. Three schools (Knott, Thompson, and Heights) are rented to other education providers. Parkrose High School was built in 1950 and received a significant replacement in the late 1990s, replacing all but the "Fine Arts Building," which is still in use today. In the spring of 2011, by a margin of 6 votes, the

Parkrose voters approved a \$63 million bond measure. This bond allowed the district to completely replace Parkrose Middle School and renew all four elementary schools.



# EXECUTIVE SUMMARY

## Purpose

This report is an evaluation of the existing District buildings, all built at different times using a variety construction methods. Using the Oregon Department of Education's School Facilities Assessment Template, this report identifies the cost of deferred maintenance for each of the school buildings relative to complete replacement versus 'As New' condition.

The purpose of this report is to provide the District with a thorough evaluation of existing buildings and site conditions, including recommended remediation steps for all buildings evaluated. The assessment is a multi-disciplinary on-site inspection of the existing buildings that focuses specifically on architectural, structural, mechanical, electrical and plumbing systems.

Items evaluated include the following:

- Exterior: Walls, foundations, doors, windows, soffits.
- Interior: Partitions, floors, ceilings, doors, casework.
- Roof: Membrane, drains, downspouts, flashing.
- Structural: Rapid assessment of seismic resistance.
- MEP: HVAC, plumbing fixtures, electrical equipment.

This assessment is the first step in the long-range facility planning process and is a rapid visual assessment of buildings that provides costs and facility condition numbers that can then be carried forward into the master planning phase, used as a baseline with which to evaluate all future planning decisions.

## Demographics

As part of the Long-Range Facilities Planning (LRFP) efforts, the District will develop a 10-year enrollment projection report. In general the area has not seen significant growth in the last 10 years or so, with several key communities economically depressed and experiencing net job losses overall. This information will be used in conjunction with the capacity calculations done as part of this FAR to determine if there needs to be additional classrooms and / or support spaces planned for in the near future.

## Sources of Funds

There are currently three readily available sources of funds to upgrade and / or replace of aging school facilities, the primary one being a bond election. Most districts find that maintaining the existing tax rate is much more palatable to the voters than increasing the tax rate and will attempt to 'capture' funds from an expiring bond, if possible.


The second income source is through the Oregon School Capital Improvement Matching grant program (OSCIM), which provides up to \$4 million in matching grant funds, and can be used to upgrade, improve, add onto existing buildings, or to build new.

The third option is the Seismic Rehabilitation Grant Program (SRGP), which provides up to \$2.5 million per building to seismically upgrading existing building(s). These funds can't be used for additions or new buildings, but only for making existing unsafe buildings more structurally sound.




# EXECUTIVE SUMMARY

## Parkrose School District



# EXECUTIVE SUMMARY

## District Building Age Timeline



# EXECUTIVE SUMMARY

## Summary - Building Data

This report represents an evaluation of all district buildings, with the goal to identify those at highest need of work overall, creating a detailed list of concerns to be prioritized during the Long-Range Planning process. Some entire buildings are simply very old and beyond their practical lifespan, while some are struggling with accessibility or other more specific concerns. Each school has a complete evaluation further in this report that provides a detailed breakdown of all identified issues and estimated costs for repairs.

### The District has four (4) elementary schools:

- Prescott Elementary School
- Russell Academy
- Sacramento Elementary School
- Shaver Elementary School

### The District has three (3) former elementary schools rented out to the Multnomah County ESD:

- Sumner Elementary School (Helensview HS)
- Thompson Elementary School (Wheatley MS)
- Knott Elementary School (Knott Creek ES)

### The District has one (1) middle school:

- Parkrose Middle School

### The District has three (3) District Buildings:

- Main Administration Office Building
- Facilities Office and Workshop Building
- Transportation Maintenance and Storage Building

### The District has one (1) comprehensive high school:

- Parkrose High School

| #  | School Name                               | Building Area     | Site Area        | Repair Budget       | Replacement Costs    | FCI Index |
|--|---|-------------------|------------------|---------------------|----------------------|-----------|
| <b>Elementary Schools (K - 5)</b>          |   |                   |                  |                     |                      |           |
| 01   | Prescott Elementary School                | 48,544 SF         | 6 Acres          | \$2,422,350         | \$24,820,062         | 9.4%      |
| 02   | Russell Academy                           | 40,036 SF         | 10 Acres         | \$3,899,749         | \$20,470,006         | 18.3%     |
| 03   | Sacramento Elementary School              | 41,107 SF         | 12 Acres         | \$2,135,800         | \$21,017,598         | 9.8%      |
| 04   | Shaver Elementary School                  | 43,916 SF         | 9 Acres          | \$3,961,863         | \$22,453,812         | 17.0%     |
| <b>Middle Schools (6-8)</b>                |   |                   |                  |                     |                      |           |
| 05   | Parkrose Middle School                    | 155,453 SF        | 17 Acres         | \$777,894           | \$83,149,944         | 0.9%      |
| <b>High Schools (9-12)</b>                 |   |                   |                  |                     |                      |           |
| 06A  | Parkrose High School                      | 260,497 SF        | 41 Acres         | \$13,928,573        | \$153,680,205        | 8.7%      |
| 06B  | Parkrose High School - Fine Arts Building | 3,700 SF          |                  |                     |                      |           |
| 06C  | Parkrose High School - Stadium            | 2,500 SF          |                  |                     |                      |           |
| <b>District Rental / Leased Properties</b> |   |                   |                  |                     |                      |           |
| 07   | Sumner Elementary / Helensview School     | 42,900 SF         | 9 Acres          | \$8,843,719         | \$21,934,341         | 38.8%     |
| 08   | Thompson Elementary / Wheatley School     | 50,400 SF         | TBD              | \$8,133,795         | \$25,769,016         | 30.4%     |
| 09   | Knott Elementary / Knott Creek School     | 32,592 SF         | 5 Acres          | \$6,721,749         | \$16,663,964         | 38.8%     |
| <b>District Administration and Support</b> |   |                   |                  |                     |                      |           |
| 10A  | District Office                           | 4,000 SF          | 2 Acres          | \$1,905,945         | \$10,420,877         | 17.6%     |
| 10B  | Maintenance Offices + Shop                | 4,700 SF          |                  |                     |                      |           |
| 10C  | Bus Barn + Shop                           | 12,000 SF         |                  |                     |                      |           |
| Totals:                                    |   | <b>742,345 SF</b> | <b>110 Acres</b> | <b>\$52,731,438</b> | <b>\$400,379,825</b> |           |



# EXISTING FACILITY OVERVIEW

## Critical Needs Summary

### 00 - District Wide

- Evaluate air conditioning needs at elementary schools (currently only Prescott Annex and a few Admin offices)
- Improved ventilation and air circulation overall.
- Accessibility upgrades to restrooms, access.
- Secure entry and site access, site safety.
- Lighting and controls retrofit and upgrade.
- Upgrade interior finishes and exterior envelope.
- Additional cameras and / or exterior lighting desired.

### 01 - Prescott Elementary School

- Create accessible main entry, path inside building.
- Create a Nurse / "Sick Room" (none existing).
- Create on-site parking (none currently existing).
- Better site support (trash enclosure and access).
- Significant storage needed (many support programs).
- Replace failing windows that were replaced.
- Repair and / or replace exterior siding.
- Covered play structure (west) too low for ball play.
- Cafeteria undersized and needs expansion.
- Water intrusion at boiler room exterior stair wall.
- Evaluate Annex classroom unit ventilator replacement.
- Add controls to mechanical system and commission.
- Entire building is listed as 'Very High' seismic risk.

### 02 - Russell Academy

- Replace individual unit ventilators in each classroom.
- Classroom casework does not function as needed.
- Classroom restrooms not accessible typically.
- Remove folding walls between classrooms.
- Front entry needs secure vestibule / controlled access.
- Evaluate existing Kitchen equipment and walk-ins.

- More storage needed (Music Room, etc.).
- Upgrade existing signage for accessibility, consistency.
- Provide additional electrical outlets throughout school.
- Evaluate adding fire sprinklers for added safety.
- Original building is listed as 'Very High' seismic risk.

### 03 - Sacramento Elementary School

- Evaluate expanding Cafeteria for capacity.
- Review Servery expansion - undersized, not accessible.
- Evaluate covered play structures (both) for needs:
  - Roof replacement needed for (1)
  - Roof repair and coating needed for (1) urgently
- Desire to add a walking track to the site.
- Evaluate repair of rolling site fence / gate.
- Evaluate safety of large, older trees on site.
- Original building is listed as 'Very High' seismic risk.

### 04 - Shaver Elementary School

- Sewer line elevation issue under parking lot (4" drop).
- Connect buildings with interior hallway.
- Fix water intrusion under covered canopy.
- Additional general building storage requested.
- Deter roof access via trash enclosure canopy.
- Refurbish mechanical units.
- Replace older electrical panels and hot water heater.
- Evaluate adding fire sprinklers for added safety.
- Original building is listed as 'Very High' seismic risk.



Shaver ES Exterior Canopy



Sacramento ES Multi-Purpose Room (MPR)

# EXISTING FACILITY OVERVIEW

## Critical Needs Summary (cont.)

### 05 - Parkrose Middle School

- Elevator access, custodial closet at lower floor desired.
- Replace carpet in high traffic areas (showing wear).
- Add sun control in gym for projection (high windows).
- Repair warped /door frames at Commons CMU wall.
- Repair / replace easily damaged grille covers (custom).
- Mitigate cracking in polished concrete flooring.
- Grounds garage needs improved access.

### 06 - Parkrose High School

#### OVERALL:

- Professionally repair and repaint exterior stucco.
- Overall short on classroom space, renovation needed.
- Science Labs too small to be effective.
- Evaluate removal of folding partition walls.
- Evaluate use of courtyard, added CTE building.
- Create direct entry / access to Rossi Field House (gym).
- Renovate Library for better use / function.
- Add more cameras throughout for security.
- Upgrade and improve exterior building lighting.
- Fix security alarm zoning to be more efficient, clear.
- Replace all bleachers inside gym fully.
- Replace locker room lockers (rusted out at base).
- Interior lighting inaccessible, inefficient (replace).
- Replace Auditorium house lights (inaccessible).
- Evaluate flooring replacement at Auditorium.
- Upgrade existing boiler, condensing unit / chiller.
- Replace hot water heaters, fixtures and piping.

#### EXTERIOR / SITE:

- Repair building canopies and columns.
- Fix drainage issues at sloped building corner.
- Evaluate converting to turf football field.
- Stadium / Grandstand needs upgrades.
- Add paving between running track and building.
- Improve track amenities to host meets / events.
- Close off pool covered entry area for safety.
- Clean, repair tennis courts, add spectator support area.
- Exterior light poles sway in wind, replace.
- Provide additional Grounds storage.
- Clean, rebuild and re-stripe track.
- Irrigation system is beyond practical lifespan, leaking.

#### FINE ARTS BUILDING (FAB):

- Improve ventilation throughout.
- Upgrade finishes, windows and casework throughout.
- Improve interior circulation for wayfinding, safety.
- Renovate to improve program inefficiencies.

#### POOL BUILDING:

- Improve ventilation at pool.

#### SEISMIC / STRUCTURAL:

- All but FAB is listed as 'High' seismic risk.



# EXISTING FACILITY OVERVIEW

## Critical Needs Summary (cont.)

### 07 - Sumner Elementary School (Helensview)\*

- Fully replace roofing, including gutters, fascia, etc.
- Replace all existing windows.
- Remove extensive glass block windows existing.
- Remove / brace existing brick chimney.
- Replace existing boiler and mechanical units.
- Upgrade mechanical controls to digital, commission.
- Replace old electrical panels.
- Replace hot water heaters, fixtures and piping.
- Evaluate flower beds at entry for security risk.
- Original building is listed as 'Very High' seismic risk.

### 08 - Thompson Elementary School (Wheatley)\*

- Replace all existing windows.
- Remove extensive glass block windows existing.
- Repair exterior concrete canopy at entry.
- Consider removing textured ceiling finish (ACM).
- Add paved pedestrian access from sidewalk / street.
- Clean, re-point and re-seal brick at entry, planter.
- Repair downspouts at Covered Play Structure (CPS).
- Remove rust, replace roof panels at CPS.
- Replace existing boiler and mechanical units.
- Upgrade mechanical controls to digital, commission.
- Replace old electrical panels.
- Replace hot water heaters, fixtures and piping.
- Recommend additional fire sprinklers be added.
- Original building is listed as 'Very High' seismic risk.

### 09 - Knott Elementary School (Knott Creek)\*

- Fully replace roofing, including gutters, fascia, etc.
- Upgrade inadequate existing ventilation (tunnels).
- Replace all existing windows.
- Remove extensive glass block windows existing.
- Replace existing boiler and mechanical units.
- Upgrade mechanical controls to digital, commission.
- Replace old electrical panels.
- Replace hot water heaters, fixtures and piping.
- Recommend additional fire sprinklers be added.
- Original building is listed as 'Very High' seismic risk.

\* For Sumner, Thommpson and Knott: As District rental properties, scope of work will be focused on building systems and infrastructure. Any items requiring repair and / or replacement due to use or age otherwise will be the responsibility of the building tenants.



Knott ES Exterior Entry Wall



Sumner Campus Exterior Windows

# EXISTING FACILITY OVERVIEW

## Critical Needs Summary (cont.)

### 10 - District Office / Maintenance Building

#### DISTRICT OFFICE:

- Enclose courtyard for better use / functionality.
- Regular exterior painting required for maintenance.
- Renovate Work Room, Student Services.
- Add upgraded, electric monument entry sign.
- Upgrade IT closet / rack to larger space.
- Add cameras at building side.
- Replace perimeter fencing.
- Fix problematic roof drains (waterfalls in heavy rain).
- Minor roofing maintenance recommended.
- Replace individual AC units with central system.
- Replace hot water heaters, fixtures and piping.
- Recommend additional fire sprinklers be added.
- Original building is listed as 'High' seismic risk.

#### MAINTENANCE BUILDING:

- Exterior painting needed (summer 2021 or later).
- Full restore of metal roof needed.
- Relocate Nutrition staff to Warehouse.
- Renovate / clean out Shop area for functionality.
- Remove underground gas tanks and pumps.
- Original building is listed as 'Very High' seismic risk.

#### WAREHOUSE / BUS BARN:

- Exterior alarms needed, to deter activity.
- Additional Grounds storage needed overall.
- Repair overhead doors to be functional (hardware).
- Evaluate 'notch' missing in several (structural).
- Repair ceiling where debris falling down regularly.
- Replace both vehicle lifts (original, not efficient).
- Repair heater (too loud, can't hear when running).
- Provide added power to separate light + computers.
- Replace hot water heater platform.
- Restore metal roofing, replace built-up roofing.
- Original building is listed as 'Very High' seismic risk.



# EXISTING FACILITY OVERVIEW

## Facilities Condition Index (FCI)

Within the Facilities Assessment Report (FAR) is the Facilities Condition Index (FCI), calculated from the deficiencies found in each building and the corresponding costs to address them. Specifically, the FCI outcome is the ratio of the estimated cost of renovations compared to complete building replacement, assuming the same square footage and program as the existing. The closer the renovation costs get to the full replacement cost of the building, the higher the FCI percentage.


The FCI is one tool used to determine if it's more cost-effective to replace or renovate a building, rather than try to address each individual deficiency. An FCI of 30% or higher indicates that replacement is recommended, since the cost to repair is a significant portion of the entire building's value. The FCI is a benchmark indicator of the building's condition used to compare its relative condition to other similar buildings.

This FCI number is only used to measure the relative costs of repair versus replacement, and doesn't take into account the following factors:

- Structural Resiliency
- Suitability to Program
- Accessibility Requirements
- Hazardous Materials Abatement
- Educational Adequacy

As part of this evaluation, we will review all these aspects, as well as the ODE requirements for physical facilities.

The chart below graphically shows the rankings of each District school building relative to the 'tipping point' of the 30% cut-off for replacement. This shows quite clearly that the three rental elementary schools are the highest need buildings, with Russell, Shaver and the District Office the next highest need group of buildings.



# EXECUTIVE SUMMARY

## Average Overall Condition


While all of the district’s buildings are well-maintained, many have identified a long list of needs, particularly the older buildings and the high school. With an average building age of over 50 years, there are several buildings with their practical lifespan already extended beyond what is practical.

The following pages provide summary analysis on the specific aspects of each building’s overall condition. Refer to the school specific pages further in the report for more detailed site-specific information. On the charts below, zero is the lowest performing score, while a score of 100 means the building is performing ‘Perfectly’, or exactly as needed.

Note: Sumner, Thompson and Knott were not evaluated for educational adequacy or program support, as these are currently rented out and not used directly by Parkrose SD students.

|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |

## Summary - All Buildings: Average



# EXECUTIVE SUMMARY

## General Condition + Summary Building Grades by Category

### Program Suitability

The high school likely has the worst performance relative to program, due to both the small, inefficient size of the classrooms and the overall low classroom count.

Russell Academy is another candidate that has classrooms with exterior doors and casework that doesn't function for what a modern classroom requires. All four elementaries lack adequate Cafeteria space and gymnasium spaces. The Multi-Purpose Room (MPR) additions in 2014 at all but Prescott helped mitigate this.

There are other minor issues relative to supervision, adjacency and changes in pedagogy that are impacted.

### Structural


Every campus except the middle and high school has buildings listed as "Very High" risk categories for seismic, while the high school is listed as "High Risk." Only the newly constructed all-new middle school performs well overall.

### HVAC / Mechanical


Ameresco performed walkthroughs at each of the District's buildings and their full report is included as an appendix to this document. In general the high school and rental buildings need to have their boilers and piping replaced, along with their control systems and balancing, along with mechanical units replaced or repaired as well. Testing and commissioning was also recommended.

|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |


Summary - All Buildings: Suitability to Program



Summary - All Buildings: Structural



Summary - All Buildings: HVAC




# EXECUTIVE SUMMARY

## General Condition + Summary Building Grades by Category

### Electrical

The electrical issues focused on two primary issues, lighting and replacement of older electrical panels. Many of the rental properties had issues with low voltage systems, such as intercoms, bells / clocks and cameras.


Summary - All Buildings: Electrical



### Plumbing

The three rental elementaries all list as a priority full replacement of plumbing fixtures and piping, while a handful of other schools are only 'recommended' for replacement. More than half the schools are recommended to have existing domestic hot water heaters replaced.

Summary - All Buildings: Plumbing




Several call for either the extension of or complete installation of fire sprinkler systems as well.

### Exterior Envelope

Many of the district properties require roofing maintenance, and additionally the three rentals all require complete window replacement. There are minor issues with brick veneer at a handful of schools, and several painted buildings required maintenance.

Summary - All Buildings: Envelope



The high school needs a complete restoration and cleaning of the stucco system, including repair from woodpecker damage.

|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# EXECUTIVE SUMMARY

## General Condition + Summary Building Grades by Category

### Interior Finishes

Many schools received finish upgrades with the last bond, but not the rental properties as that would be the responsibility of the tenant. Prescott and Shaver have finishes remaining that are approaching end of life, including flooring and damaged ceiling systems.


Parkrose High also has several interior finish elements that require either maintenance or replacement, as they've reached the end of their practical lifespan.



### Accessibility


Prescott is the highest need school building, as it's lacking an accessible main entry and elevator. Generally speaking otherwise, the school sites are flat and level, allowing for adequate pathways into and circulating through each campus.

The three rental elementary schools have non-accessible restrooms inside the classrooms that need to be upgraded. The playgrounds should be evaluated for universal access as well.



### Hazardous Materials

Many of the schools have received significant abatement over the years, and all perform generally well. There is very little visible, accessible hazardous materials in each school, with the possible exception of the three rental elementaries. These still have asbestos flooring and 'popcorn' texture ceiling with trace amounts of hazardous materials.



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |

# EXISTING FACILITY OVERVIEW

## Summary - Mechanical / Electrical

The table below is an excerpt from the full structural report, prepared by ZCS, that identifies that there are several buildings at the highest risk of collapse in a seismic event. As you would expect, the older buildings generally score lower, with the exception of the relatively new high school, which is still listed as 'High Risk.'

The last bond scope provided seismic upgrades of the elementary schools in use by the District, but not the ones rented / leased out. Refer to the full evaluation, included at the back of this report, for complete details.

| Risk           | Score              | Probability                                   |
|----------------|--------------------|---|
| LOW            | >2.0               | Less than 1 in 100 chance of collapse         |
| MODERATE (MOD) | >1 AND < or = 2.00 | Between 1 in 10 & 1 in 100 chance of collapse |
| HIGH           | >0.0 AND < or =1.0 | Between 100% & 1 in 10 chance of collapse     |
| VERY HIGH      | 0.0 OR LESS        | 100% chance of collapse                       |

In alignment with this ranking system, FEMA, has determined that all buildings with a score 2.0 should be considered to have inadequate performance during a design level seismic event.

| Facility Name                       | Risk             |
|-------------------------------------|------------------|
| <b>Prescott Elementary School</b>   |                  |
| Original Classroom Building         | -1.0 – VERY HIGH |
| 1959 Addition (Annex)               | -0.4 – VERY HIGH |
| <b>Russell Elementary School</b>    |                  |
| Original School Building            | -1.1 – VERY HIGH |
| 2014 Addition                       | 5.1 – LOW        |
| <b>Sacramento Elementary School</b> |                  |
| Original School Building            | -1.8 – VERY HIGH |
| 2014 Additions                      | 5.1 – LOW        |
| <b>Shaver Elementary School</b>     |                  |
| Original School Building            | -1.8 – VERY HIGH |
| 2014 Addition                       | 5.1 - LOW        |
| <b>Parkrose Middle School</b>       |                  |
| Original School Building            | 3.8 – LOW        |
| <b>Parkrose High School</b>         |                  |
| Classroom Wings                     | 1.0 – HIGH       |
| Student Center/Library              | 1.0 – HIGH       |
| Auditorium, Gym and Pool            | 0.7 – HIGH       |
| Band/Music                          | 1.0 – HIGH       |
| Fine Arts Building                  | 1.3 – MODERATE   |
| <b>Sumner Elementary School</b>     |                  |
| Original School Building            | -1.8 – VERY HIGH |
| <b>Thompson Elementary School</b>   |                  |
| Original School Building            | -1.8 – VERY HIGH |
| <b>Knott Elementary School</b>      |                  |
| Original School Building            | -1.8 – VERY HIGH |
| 1965 Addition                       | 0.2 – HIGH       |
| <b>District Office/Maintenance</b>  |                  |
| District Office Building            | 0.6 – HIGH       |
| Maintenance Facility                | -0.6 – VERY HIGH |
| Garage and Storage                  | -1.6 – VERY HIGH |

# EXISTING FACILITY OVERVIEW

## Summary - Mechanical / Electrical

The table below is an excerpt from the full mechanical, electrical and plumbing report, prepared by Ameresco. This identifies the specific scope items on each campus with the highest needs and anticipated approximate costs to repair or replace items indicated. In general, all sites are recommended for testing and retro commissioning, as well as lighting upgrades.

indicated at all three sites. The four elementary schools were upgraded in the most recent bond, so they show a lower need based on their age. The middle school is also showing few needs since it was most recently built new.

Refer to the full evaluation, included at the back of this report, for complete details.

Many are recommended for complete mechanical unit replacement. In general, the three 'rental' elementary schools show the highest system needs overall, with significant mechanical, electrical and plumbing work

| Facilities Summary            | HVAC                               |                                   |                |                                      |                              |                 | ELECTRICAL                    |   | PLUMBING   |                                 |                           | Total       |
|-------------------------------|------------------------------------|-----------------------------------|----------------|--------------------------------------|------------------------------|-----------------|-------------------------------|---|--|---------------------------------|---------------------------|-------------|
|                               | Replace existing old boiler system | Replace condensing unit / chiller | Refurbish AHUs | AHU/ HV/ RTU/ UV/ UH/ FF replacement | Test and retro commissioning | Control upgrade | Replace old electrical panels | Lighting and lighting control retrofit to LED | Replace water fixtures and water piping for the school | Replace existing old DHW heater | Add fire sprinkler system |             |
| Prescott Elementary           |                                    |                                   |                |                                      | \$ 22,000                    | \$ 75,000       |                               | \$ 110,000                                    | \$ 55,000  | \$ 60,000                       |                           | \$ 322,000  |
| Russell Elementary            |                                    |                                   |                | \$ 530,000                           | \$ 18,000                    |                 |                               | \$ 90,000                                     |  |                                 | \$ 40,000                 | \$ 678,000  |
| Sacramento Elementary         |                                    |                                   |                |                                      | \$ 21,000                    |                 |                               | \$ 95,000                                     |  |                                 |                           | \$ 116,000  |
| Shaver Elementary             |                                    |                                   | \$ 80,000      |                                      | \$ 30,000                    |                 | \$ 65,000                     | \$ 100,000                                    |  | \$ 30,000                       | \$ 40,000                 | \$ 345,000  |
| Parkrose Middle School        |                                    |                                   |                |                                      | \$ 64,000                    |                 |                               | \$ 215,000                                    |  |                                 |                           | \$ 279,000  |
| Parkrose High School          | \$ 75,000                          | \$ 50,000                         |                | \$3,200,000                          | \$ 85,000                    | \$ 105,000      |                               | \$ 500,000                                    | \$ 35,000  | \$ 120,000                      |                           | \$4,170,000 |
| Sumner /Helensview            | \$ 800,000                         |                                   |                | \$ 550,000                           | \$ 22,000                    | \$ 300,000      | \$ 100,000                    | \$ 90,000                                     | \$ 240,000   | \$ 30,000                       |                           | \$2,132,000 |
| Thompson / Wheatley           | \$ 800,000                         |                                   |                | \$ 550,000                           | \$ 22,000                    | \$ 300,000      | \$ 140,000                    | \$ 90,000                                     | \$ 270,000   |                                 | \$ 250,000                | \$2,422,000 |
| Knott / Knott Creek           | \$ 680,000                         |                                   |                | \$ 450,000                           | \$ 18,000                    | \$ 240,000      | \$ 110,000                    | \$ 75,000                                     | \$ 200,000   | \$ 30,000                       | \$ 210,000                | \$2,013,000 |
| District Office / Maintenance |                                    |                                   |                | \$ 55,000                            | \$ 12,000                    | \$ 115,000      |                               | \$ 43,000                                     | \$ 135,000   | \$ 17,000                       | \$ 130,000                | \$ 507,000  |
|                               | Priority                           |                                   |                |                                      |                              |                 |                               |   |  |                                 |                           |             |
|                               | Recommended                        |                                   |                |                                      |                              |                 |                               |   |  |                                 |                           |             |


- AHU Air Handling Unit
- HV Heating Ventilating Unit
- RTU Rooftop Unit
- UV Unit Ventilator
- DHW Unit Heater
- FF Forced Air Furnace
- Domestic Hot Water

# FACILITY ASSESSMENTS BY BUILDING

|   |    |
|---|----|
| <b>00 Overall District Site Plan</b>            | 21 |
| <b>01 Prescott Elementary School</b>            | 22 |
| <b>02 Russell Academy</b>                       | 28 |
| <b>03 Sacramento Elementary School</b>          | 34 |
| <b>04 Shaver Elementary School</b>              | 40 |
| <b>05 Parkrose Middle School</b>                | 46 |
| <b>06 Parkrose High School</b>                  | 53 |
| <b>07 Sumner Elementary School (Helensview)</b> | 61 |
| <b>08 Thompson Elementary School (Wheatley)</b> | 67 |
| <b>09 Knott Elementary School (Knott Creek)</b> | 73 |
| <b>10 District Office &amp; Maintenance</b>     | 79 |

# 00 - PARKROSE SCHOOL DISTRICT

## SITE PLAN



# 01 - PRESCOTT ELEMENTARY SCHOOL

## SITE PLAN



# 01 - PRESCOTT ELEMENTARY SCHOOL

## FLOOR PLAN



# 01 - PRESCOTT ELEMENTARY SCHOOL



## Facility Summary

Prescott Elementary is one of the highest needs schools in the District, due to its age, its tight sight that doesn't easily provide for parking and its two-story configuration that creates accessibility challenges.

Starting at the building entry, there is no accessible path from the sidewalk to the main office, with the side curving ramp very narrow and steep and the lower ramp into the Cafeteria not appropriate to leave open for security. Prescott's lack of parking onsite is an issue for both parents and staff, as well as neighbors who deal with significant site circulation issues twice daily.


Prescott was the only elementary in the District that didn't receive a 'Multi-Purpose Room' (MPR) addition in the previous bond, since it did have a separate gymnasium and cafeteria, unlike the other schools.

In addition to overall system issues with mechanical, electrical and plumbing, there is a very high seismic risk, increased by the fact that the cafeteria is underneath the gymnasium. Further evaluation is recommended.

|                        |   |
|------------------------|---|
| Site Name:             | Prescott Elementary                         |
| Building Name:         | Main Building + Annex                       |
| ODE Building ID:       | 21810100                                    |
| Building Type:         | Elementary School                           |
| Students:              | 331   |
| Building Address:      | 10410 NE Prescott St,<br>Portland, OR 97220 |
| County:                | Multnomah                                   |
| Gross Square Footage:  | 48,544                                      |
| Site Acreage:          | 5.75  |
| Year Built:            | 1947  |
| Additions/Renovations: | 1959, 1996, 2014                            |
| Number of Floors:      | Two (2)                                     |
| Primary Structure:     | Wood Framing                                |
| Roof Type:             | Built-Up (SBS), Membrane                    |
| Replacement Budget:    | \$24,820,062                                |



# 01 - PRESCOTT ELEMENTARY SCHOOL



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 01 - PRESCOTT ELEMENTARY SCHOOL

## Architectural

- Cafeteria is undersized for current capacity.
- Previous window replacement resulted in non-functioning units that now require replacement.
- Window coverings require replacement.
- Repair / replace damaged and failing siding, both vinyl and cementitious.
- Minor kitchen equipment upgrades needed.
- Repair leak at exterior brick wall near building boiler room corner.
- Upgrade / replace interior finishes, including flooring, ceilings and door hardware.
- Built-in cabinets and moveable furniture require repair and replacement.
- Dedicated Health / Sick Room needed at Main Office.
- Additional storage needed due to multiple community and District groups' use of the building.
- Covered Play canopy at West side of site is too low for ball play, consider revising play equipment to more age-appropriate configuration.

## Site Safety and Security Analysis

- Main Entry doesn't have good line-of-site to people entering.
- Secure vestibule strongly recommended to be added.
- Repair site asphalt paving where cracked, uneven.
- Students travel from main building to Annex, which requires exterior doors to remain unlocked and creates a security risk.
- Multiple, smaller windows in Annex requires lengthy time to shut blinds in a lockdown situation, creating higher risk to staff.

## Accessibility

- Add elevator and / or repair lift at stairs.
- Upgrade restroom washbasins that aren't accessible, provide required clearance.
- Steep site creates challenges accessing playground, Annex building for some.
- Evaluate need for power-operated door openers at key locations.

## Hazardous Materials and Indoor Air Quality

- There is some surface-applied ceiling and wall tiles that may have asbestos-containing mastic / glue.
- Most flooring has been replaced throughout and asbestos-containing material was abated at that time.
- Due to the age of the building, it is assumed there would be lead paint encapsulated below newer paint.
- Radon mitigation was completed prior to / near Summer 2021. Re-testing is planned for Fall 2021.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



Accessible Ramp to Building



Classroom

# 01 - PRESCOTT ELEMENTARY SCHOOL

## Building Systems

### Fire Protection:

- The entire building and Annex have a fire sprinkler system currently installed that is routinely tested and inspected.

### Plumbing:

- Replace plumbing fixtures and supply piping to the building.
- Replacement of existing domestic hot water heaters is recommended, due to age, capacity and overall condition.

### Mechanical:

- Main Office does not currently have air conditioning, evaluate adding.
- Repair Kitchen mechanical piping that has been chronically freezing up and condensing.
- Evaluate adding digital controls for remote monitoring and access of mechanical system.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.
- Provide full mechanical controls upgrade.

### Electrical:

- The school's main distribution panel was replaced in 1987 and appears to be performing adequately for current needs.
- Most building subpanels were replaced in 2013 and appear to have adequate capacity overall.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- The existing fire alarm system appears to be functioning adequately and work is not recommended at this time.

### Communication and Security:

- There is an older PA (Public Address) system for operational communications.
- There seems to be no functional two-way intercom system in the school, or between the school and Annex building.
- Wireless internet appears to be adequate throughout the school.

Refer to full report from Ameresco for more detail.

## Structural


- The original classroom building is rated as a 'Very High' seismic risk.
- The Annex addition is also considered to be a 'Very High' seismic risk, although not quite as high as the original building.

Refer to full report from ZCS Engineering and Architecture for more detail.



# 02 - RUSSELL ACADEMY

## SITE PLAN



# 02 - RUSSELL ACADEMY

## FLOOR PLAN



# 02 - RUSSELL ACADEMY



## Facility Summary

Russell Academy’s physical configuration, with exterior classroom entries, creates significant security risks that should be considered. The front office is across the corridor from the entry doors, creating a significant security risk, which could be mitigated by adding a vestibule.


This building in particular has significant mechanical issues, as each classroom has an independent unit ventilator that is beyond its practical lifespan and requires replacement. In addition to this, there is inadequate electrical outlets throughout the school.

The classrooms themselves have antiquated, outdated casework and folding walls that aren’t well utilized in modern teaching environments. The restrooms inside these classrooms are very small and not accessible to differently-abled students.

There are several smaller issues with the building, including inconsistent signage, inadequate storage, and upgraded kitchen equipment.

|                        |   |
|------------------------|---|
| Site Name:             | Russell Academy                           |
| Building Name:         | Russell Main                              |
| ODE Building ID:       | 21810200                                  |
| Building Type:         | Elementary School                         |
| Students:              | 371                                       |
| Building Address:      | 2700 NE 127th Ave.,<br>Portland, OR 97230 |
| County:                | Multnomah                                 |
| Gross Square Footage:  | 40,036                                    |
| Site Acreage:          | 9.83                                      |
| Year Built:            | 1963                                      |
| Additions/Renovations: | 1996, 2013                                |
| Number of Floors:      | One (1)                                   |
| Primary Structure:     | Wood Framing                              |
| Roof Type:             | Built-Up (SBS)                            |
| Replacement Budget:    | \$20,470,006                              |

# 02 - RUSSELL ACADEMY



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 02 - RUSSELL ACADEMY

## Architectural

- Classrooms have outdated, antiquated casework and folding walls that should be considered for replacement.
- The gate access from the parking lot is problematic and should be replaced.
- The Kitchen is outdated, with some original equipment, including the walk-in freezer and cooler, still in use. We recommend an allowance to upgrade this equipment.
- Hallway flooring is very difficult to get clean and recommended for replacement, unless it can be stripped and re-finished effectively.
- Additional storage is requested, particularly for the Music Room.
- Signage building-wide is inconsistent, illegible and should be replaced with a consistent version.
- Re-roof of small area recommended within next 5-7 years.

## Site Safety and Security Analysis

- Main entry doesn't connect directly to the Main Office, limiting ability to screen and control visitor access.
- Secure vestibule should be added to assist in controlling access and screening visitors.
- Exterior classroom door entries a significant security risk, consider options to enclose.
- Additional cameras have been requested, both interior and exterior.
- Additional exterior lighting has been requested by the building users, as the existing is minimal.

## Accessibility

- The restrooms within the classrooms are very small and don't meet guidelines for accessibility. These are recommended for reconfiguration to accommodate differently-abled students.
- Evaluate need for power-operated door openers at key locations.
- Provide accessible route to stage area.

## Hazardous Materials and Indoor Air Quality

- Radon mitigation was completed prior to / near Summer 2021. Re-testing is planned for Fall 2021.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.





# 02 - RUSSELL ACADEMY

## Building Systems

### Fire Protection:

- While not required, it is recommended to extend the existing fire sprinkler system, which is minimal.
- The new Multi-Purpose Room (MPR) does not have a fire sprinkler system installed.

### Plumbing:

- No issues identified.

### Mechanical:

- Replace the existing independent unit ventilators in each classroom that are well beyond their practical lifespan.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.

### Electrical:

- The majority of the school's main distribution panel was replaced in 2013 and appears to be performing adequately for current needs.
- Most building subpanels were replaced in either 1996 or 2013 and appear to have adequate capacity overall.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- The existing fire alarm system, while not required, could increase safety by upgrading the existing system to add visual strobes and to modernize the current system.

### Communication and Security:

- There is an older PA (Public Address) system for operational communications.
- Wireless internet appears to be adequate throughout the school.

Refer to full report from Ameresco for more detail.

## Structural

- The original classroom building is rated as a 'Very High' seismic risk.
- The most recent 2014 addition is considered to be a 'Low' seismic risk and should meet or nearly meet current structural code guidelines.

Refer to full report from ZCS Engineering and Architecture for more detail.




# 03 - SACRAMENTO ELEMENTARY SCHOOL

## SITE PLAN



# 03 - SACRAMENTO ELEMENTARY SCHOOL

## FLOOR PLAN



# 03 - SACRAMENTO ELEMENTARY SCHOOL



## Facility Summary

Sacramento Elementary is one of the best elementary schools in the District relative to its overall physical condition. The last bond provided significant mechanical, electrical and plumbing upgrades, and it also received a Multi-Purpose Room (MPR) addition.


The largest current need is around the Cafeteria and Servery, which are both under capacity. In addition, the Servery does not provide accessible clearance for access.

Both Covered Play Structures show signs of wear and it's recommended to repaint the main structural frame and replace the roofing panels. The basketball hoops are beyond their practical lifespan and mounting heights are not ideal for elementary students. Interest has been expressed in developing a walking track on the site.

Seismically, similar to all other elementary schools, the original building is listed as a 'Very High' seismic risk. The new MPR addition is very safe and built to current

|                        |  |
|------------------------|--|
| Site Name:             | Sacramento Elementary                          |
| Building Name:         | Main School                                    |
| ODE Building ID:       | 21810300                                       |
| Building Type:         | Elementary School                              |
| Students:              | 305  |
| Building Address:      | 11400 NE Sacramento St.,<br>Portland, OR 97220 |
| County:                | Multnomah                                      |
| Gross Square Footage:  | 41,107   |
| Site Acreage:          | 11.59  |
| Year Built:            | 1960   |
| Additions/Renovations: | 1960, 1980, 1996, 2013                         |
| Number of Floors:      | One (1)  |
| Primary Structure:     | Wood Framing                                   |
| Roof Type:             | Single-Ply Membrane (PVC)                      |
| Replacement Budget:    | \$21,017,598                                   |

# 03 - SACRAMENTO ELEMENTARY SCHOOL



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 03 - SACRAMENTO ELEMENTARY SCHOOL

## Architectural

- Evaluate Cafeteria / Commons capacity.
- Evaluate Server configuration and clearances to confirm adequacy.
- Evaluate Covered Play Structures for overall safety and longevity of performance, including basketball goals.
- Consider adding a walking track to the site.

## Site Safety and Security Analysis

- Replace broken rolling gate at West end of site (chronic issues).

## Accessibility

- Evaluate original restrooms in corridor for accessibility.
- Consider renovation of restrooms inside classrooms to make them fully accessible.
- Provide accessible route to stage area.

## Hazardous Materials and Indoor Air Quality

- The most recent bond scope abated most visible hazardous materials in the building.
- The hazardous materials remaining are typically concealed behind wall finishes.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



# 03 - SACRAMENTO ELEMENTARY SCHOOL

## Building Systems

### Fire Protection:

- No issues identified.

### Plumbing:

- No issues identified.

### Mechanical:

- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.

### Electrical:

- No issues identified.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No issues identified.

### Communication and Security:

- No issues identified.

## Structural

- The original classroom building is rated as a 'Very High' seismic risk.
- The most recent 2014 additions are considered to be a 'Low' seismic risk and should meet or nearly meet current structural code guidelines.

Refer to full report from ZCS Engineering and Architecture for more detail.



# 04 - SHAVER ELEMENTARY SCHOOL

## SITE PLAN





# 04 - SHAVER ELEMENTARY SCHOOL

## FLOOR PLAN



# 04 - SHAVER ELEMENTARY SCHOOL



## Facility Summary

Shaver Elementary is a very old but well-maintained school building that has seen several significant upgrades over the years. There are still needs identified but overall the building has solid value and can serve the District well for many years to come.


The largest issue this school is dealing with is connection and internal circulation of their students between the three building areas on the site, with the original building, the 1996 addition and the newest Multi-Purpose Room (MPR) building all having exterior entry doors and paths.

There are infrastructure needs identified, including replacement of mechanical units, electrical panels and hot water heaters. Overall building storage is also needed.


Seismically, similar to many other elementary schools, the original building is listed as a 'Very High' seismic risk. The new MPR addition is very safe and built to current code requirements.

|                        |                                       |
|------------------------|---------------------------------------|
| Site Name:             | Shaver Elementary School              |
| Building Name:         | Main Building                         |
| ODE Building ID:       | 21810400                              |
| Building Type:         | Elementary School                     |
| Students:              | 275                                   |
| Building Address:      | 3701 NE 131st Pl., Portland, OR 97230 |
| County:                | Multnomah                             |
| Gross Square Footage:  | 43,916                                |
| Site Acreage:          | 8.73                                  |
| Year Built:            | 1963                                  |
| Additions/Renovations: | 1996, 2013                            |
| Number of Floors:      | One (1)                               |
| Primary Structure:     | Wood Framing                          |
| Roof Type:             | Single-Ply Membrane                   |
| Replacement Budget:    | \$22,453,812                          |

# 04 - SHAVER ELEMENTARY SCHOOL



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 04 - SHAVER ELEMENTARY SCHOOL

## Architectural

- Consider strategies to enclose corridor connection between original classroom building and older addition.
- Evaluate Cafeteria / Commons capacity.
- Evaluate Covered Play Structures for overall safety and longevity of performance, including basketball goals.
- Review exterior envelope for water intrusion issues, particularly at South elevation of older building addition, below windows.
- Provide solution for water intrusion at south covered canopy at older classroom addition.
- Look to determine how storage could be added.
- Trash enclosure roof access needs to be deterred.

## Site Safety and Security Analysis

- No issues identified.

## Accessibility

- Upgrades to older restrooms should be considered, although many upgrades have occurred already.
- Provide accessible route to stage area.

## Hazardous Materials and Indoor Air Quality

- The most recent bond scope abated most visible hazardous materials in the building.
- The hazardous materials remaining are typically concealed behind wall finishes.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



# 04 - SHAVER ELEMENTARY SCHOOL

## Building Systems

### Fire Protection:

- While not required by code, it is recommended to add fire sprinklers to the MPR, in order to increase the overall safety of the building.

### Plumbing:

- Replacement of existing domestic hot water heaters is recommended, due to age, capacity and overall condition.

### Mechanical:

- Refurbish old air handling units (AHUs) that are close to their natural lifespan.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.

### Electrical:

- This building requires replacement of the existing electrical panels and upgrades / replacement of the older light fixtures, with new controls.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No scope identified.

### Communication and Security:

- There is an older PA (Public Address) system for operational communications.
- There seems to be no functional two-way intercom system in the school, or between the school and Annex building.
- Wireless internet appears to be adequate throughout the school.

### Structural

- The original classroom building is rated as a 'Very High' seismic risk.
- The most recent 2014 additions are considered to be a 'Low' seismic risk and should meet or nearly meet current structural code guidelines.

Refer to full report from ZCS Engineering and Architecture for more detail.




# 05 - PARKROSE MIDDLE SCHOOL

## SITE PLAN




# 05 - PARKROSE MIDDLE SCHOOL

## FLOOR PLAN



# 05 - PARKROSE MIDDLE SCHOOL

## FLOOR PLAN





# 05 - PARKROSE MIDDLE SCHOOL



## Facility Summary


The newest building in the school, Parkrose Middle School was completely replaced in the last bond, and as expected it has the shortest list of needs due to it's age.

There is a strong desire expressed to provide elevator access to the lower level of the building, where the District IT space is located along with much of the custodial and facilities support and storage areas are. The Grounds Garage has a problematic path in and out of the garage itself that makes it very difficult to maneuver.


There are some minor finish replacment needs, including carpet in high-traffic areas. The polished concrete shows a lot of cracking that should be attempted to be mitigated.

|                        |  |
|------------------------|--|
| Site Name:             | Parkrose Middle School                     |
| Building Name:         | Main Building                              |
| ODE Building ID:       | 21810500                                   |
| Building Type:         | Middle School                              |
| Students:              | 778  |
| Building Address:      | 11800 NE Shaver St.,<br>Portland, OR 97220 |
| County:                | Multnomah                                  |
| Gross Square Footage:  | 155,453                                    |
| Site Acreage:          | 16.65                                      |
| Year Built:            | 2013                                       |
| Additions/Renovations: | N/A  |
| Number of Floors:      | Two (2)                                    |
| Primary Structure:     | CMU bearing                                |
| Roof Type:             | Single-Ply Membrane, Metal                 |
| Replacement Budget:    | \$83,149,944                               |

# 05 - PARKROSE MIDDLE SCHOOL



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 05 - PARKROSE MIDDLE SCHOOL

## Architectural

- Replace carpet in high-traffic areas.
- Come up with better solution for mechanical wall grilles that are easily damaged and a custom product that is very expensive to replace.
- Provide sun control at Gym high exterior windows (powered blinds or similar, as done for the Commons).
- Repair damaged door frames at Commons in CMU wall that are warped.
- Evaluate polished concrete flooring to mitigate cracking that is currently visible.
- Revise cracks in corridor wall that travels upward along upper window at two story area.
- Renovate Media Center patio for better utilization.
- Running track will be due for cleaning and re-stripping.
- Evaluate adding irrigation controls for remote access and higher efficiency.

## Site Safety and Security Analysis

- Evaluate adding exterior lighting at track for increased safety, extension of hours of use.
- A request has been made to enclose the upper playground area, to provide additional recess options for the students. This would remove community access during school hours, which requires evaluation by the District.

## Accessibility

- Provide elevator access to the lower level of the building that houses the District Information Technology (IT) workshop and office spaces, as well as District meeting rooms.


## Hazardous Materials and Indoor Air Quality

- Due to the building age, there is no evidence or hazardous materials present anywhere in the building.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



Main Entry Corridor



Science Classroom

# 05 - PARKROSE MIDDLE SCHOOL

## Building Systems

### Fire Protection:

- No issues identified.

### Plumbing:

- No issues identified.

### Mechanical:

- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.

### Electrical:

- No issues identified.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No issues identified.

### Communication and Security:


- No issues identified.

Refer to full report from Ameresco for more detail.

## Structural


- As a completely new building less than 10 years old, it's assumed to meet all current structural code requirements.

Refer to full report from ZCS Engineering and Architecture for more detail.




# 06 - PARKROSE HIGH SCHOOL

## SITE PLAN




# 06 - PARKROSE HIGH SCHOOL

## MAIN LEVEL FLOOR PLAN



# 06 - PARKROSE HIGH SCHOOL

## UPPER LEVEL FLOOR PLAN



# 06 - PARKROSE HIGH SCHOOL



## Facility Summary

Parkrose High School is a relatively newer building that is in overall good condition for its age, but has some fundamental misalignments with the original design and how the District wants to use the building today and into the future. Fundamentally, there are too few classrooms, the classrooms are too small, and there is too much unused circulation space. The Media Center is oversized and underutilized, and the exterior courtyard and main student entry are areas that should be studied for better utilization.


As a comprehensive high school, the site has significant needs relative to athletic fields, utilities and support. The Stadium / Grandstand has not seen upgrades in many years, other than the press box, which was recently upgraded. The track facilities need significant upgrades to be able to host meets.

The only building remaining from the previous high school, the Fine Arts Building (FAB) has significant needs, both in the physical condition and educational adequacy.

|                        |  |
|------------------------|--|
| Site Name:             | Parkrose High School                       |
| Building Name:         | Main Building                              |
| ODE Building ID:       | 21810600                                   |
| Building Type:         | High School                                |
| Students:              | 976  |
| Building Address:      | 12003 NE Shaver St.,<br>Portland, OR 97220 |
| County:                | Multnomah                                  |
| Gross Square Footage:  | 260,497                                    |
| Site Acreage:          | 40.82                                      |
| Year Built:            | 1996                                       |
| Additions/Renovations: | N/A  |
| Number of Floors:      | Two (2)                                    |
| Primary Structure:     | Steel Frame                                |
| Roof Type:             | Built-Up (SBS)                             |
| Replacement Budget:    | \$153,680,205                              |



# 06 - PARKROSE HIGH SCHOOL



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 06 - PARKROSE HIGH SCHOOL

## Architectural

- Exterior stucco needs professional cleaning and complete repaint.
- Lack of classrooms overall and other classrooms undersized, folding walls under utilized.
- Science Labs outdated and too small to be truly effective.
- Library is oversized and larger than needed for use.
- Opportunities for future development include a Vocational / CTE (Career Technical Education) building, on SE corner of site, at Shaver.
- Evaluate better utilization / development of student entry and theater courtyard, including direct gym entry from exterior entry courtyard.
- Roof actively leaking in some areas and should be evaluated.
- Irrigation requires evaluation and repair.
- Revise alarm zones at Pool area for better clarity, particularly after hours, consider adding key pads.
- Site has drainage issues, especially at back of site by gym, where slope meets the building edge.
- Building canopies and columns require repair - peeling, failing in several areas.
- Lockers inside locker room has rusted out bases that need repair / replacement.
- The Pool building ventilation is inadequate and could be improved.
- Interior lighting is problematic, numerous inaccessible recessed fluorescent lights that frequently fail.
- Reroofing recommended for approximately half of the building, restoration recommended for other half.

## FINE ARTS BUILDING (FAB)

- Poor ventilation overall, antiquated systems throughout.
- Restrooms require accessibility upgrade due to age.
- Entire building requires finishes repair and / or replacement.
- Windows are original aluminum, recommend replacement.

## ATHLETICS AND FIELDS

- There is a strong desire to convert football field from grass to turf.
- Older softball field has outdated equipment, drainage issues at the concrete paving.
- Stadium has not had significant upgrade for many years, except recent Press Box rebuild.
- Stadium lighting requires upgrade overall.
- Consider developing opposite slope from Stadium for visitor area.
- Tennis courts are cracked, don't have a spectator area or support that is accessible. Goal is to support meets.
- Track perimeter fence is not tall enough to control site traffic.
- Paving needed between end of track and building, where it's currently gravel / unpaved.
- Adequate track support missing for events such as javelin, discus, shot put, hammer throw, etc. Goal is to be able to host meets.
- Track is recommended for resurfacing and restriping.
- Gym bleachers are recommended for complete replacement.
- Replace galvanized irrigation piping (40+ years old), add controls for remote access and higher efficiency.



Media Center



Science Classroom

# 06 - PARKROSE HIGH SCHOOL

## Site Safety and Security Analysis

- Exterior building lighting requires upgrade, as its mounted too low to be effective. Convert to LED.
- Main building entry doesn't have direct access to secure vestibule. Evaluate adding.

## Accessibility

- Stadium restrooms are not accessible and require significant upgrade.

## Hazardous Materials and Indoor Air Quality

- The main building is new enough that no hazardous materials are expected.
- The Fine ARts Building (FAB) is original to the campus and built at a time when hazardous materials are likely present, including asbestos, lead paint and possibly radon.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



# 06 - PARKROSE HIGH SCHOOL

## Building Systems

### Fire Protection:

- Other than the FAB, the entire building has a fully functional fire sprinkler system.

### Plumbing:

- Replace plumbing fixtures and supply piping to the building.
- Replacement of existing domestic hot water heaters is recommended, due to age, capacity and overall condition.

### Mechanical:

- Replace existing boiler system that is beyond its natural lifespan.
- Replace condensing unit / chiller.
- Replace the mechanical units that are well beyond their practical lifespan.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.
- Provide full mechanical controls upgrade.

### Electrical:

- No scope identified.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No scope identified.

### Communication and Security:

- No scope identified.

Refer to full report from Ameresco for more detail.

## Structural

- All but the Fine Arts Building is rated as 'High' seismic risk, but has undergone a recent seismic retrofit that will have it brought up to current code.
- The FAB is listed as 'Moderate' risk seismically.

Refer to full report from ZCS Engineering and Architecture for more detail.




Shop



Classroom


# 07 - SUMNER ELEMENTARY SCHOOL (HELENSVIEW)

## SITE PLAN



# 07 - SUMNER ELEMENTARY SCHOOL (HELENSVIEW)

## SITE PLAN



# 07 - SUMNER ELEMENTARY SCHOOL (HELENSVIEW)



## Facility Summary


The original Sumner Elementary School has been operated by the Multnomah County Educational Services District (MESD) as Helensview School alternative high school for several years. As such, the building’s educational adequacy was not fully evaluated and this assessment focuses primarily on the physical infrastructure of the building and it’s supporting systems.

The building has significant needs as much of the repair and renovation scope has been deferred for several years. The school has not seen major projects as part of the last two bond cycles. Instead, the District has provided smaller-scale, more targeted projects that could be performed ‘in-house’ or the District could directly hire vendors to complete the work.

Major work identified includes roofing, window replacement (including seismically dangerous glass block), mechanical system replacement, boiler replacement, electrical panel replacement, and replacement of hot water heaters, plumbing fixtures and piping. Similar to all other elementary schools, this building is also listed as a ‘Very High’ seismic risk, and has a masonry chimney that should be considered.

|                        |   |
|------------------------|---|
| Site Name:             | Sumner Elementary                         |
| Building Name:         | Helensview School                         |
| ODE Building ID:       | 21810005                                  |
| Building Type:         | High School                               |
| Students:              | MESD                                      |
| Building Address:      | 8678 NE Sumner St.,<br>Portland, OR 97220 |
| County:                | Multnomah                                 |
| Gross Square Footage:  | 2,900                                     |
| Site Acreage:          | 8.9                                       |
| Year Built:            | 1954                                      |
| Additions/Renovations: | 1968, 1996, 1998                          |
| Number of Floors:      | One (1)                                   |
| Primary Structure:     | Wood Framing                              |
| Roof Type:             | Built-Up (SBS)                            |
| Replacement Budget:    | \$21,934,341                              |

# 07 - SUMNER ELEMENTARY SCHOOL (HELENSVIEW)



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |





# 07 - SUMNER ELEMENTARY SCHOOL (HELENSVIEW)

## Architectural

- Complete roofing replacement, including gutters, fascia and trim.
- Replace all exterior windows, including glass block.
- Remove or reduce masonry chimney that represents a seismic risk.
- Evaluate modifying planter at entry that allows easier access to the roof.

## Site Safety and Security Analysis

- Consider adding a secure vestibule in future (not required at this time).
- The immediate neighborhood has a very busy street to the North with Killingsworth and represents a safety risk due to traffic.
- The surrounding neighborhood has an increased incident of crime and is not very conducive to outreach.

## Accessibility

- Restrooms are original in many situations and not designed to current accessibility standards.
- Rear entry has stairs up to access building but no ramp.
- Several interior corridor ramps exist that are too steep to meet accessibility requirements.
- Provide accessible route to stage area.

## Hazardous Materials and Indoor Air Quality

- Existing 9x9 asbestos floor tile remains in several classrooms and corridor areas that still requires abatement (sheet vinyl preferred material for replacement).
- Surface-mounted acoustic ceiling tile could potentially have asbestos in the mastic (glue) and should be evaluated if modified.
- Air quality has not been sampled for this report, but a health risk due to indoor air quality in this facility is unlikely due to the forced air heating and cooling system.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



Interior Corridor



Kitchen

# 07 - SUMNER ELEMENTARY SCHOOL (HELENSVIEW)

## Building Systems

### Fire Protection:

- No issues identified.

### Plumbing:

- Replace plumbing fixtures and supply piping to the building.
- Replacement of existing domestic hot water heaters is recommended, due to age, capacity and overall condition.

### Mechanical:

- Replace existing boiler system that is beyond its natural lifespan.
- Replace the mechanical units that are well beyond their practical lifespan.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.
- Provide full mechanical controls upgrade.

### Electrical:

- This building requires replacement of the existing electrical panels and upgrades / replacement of the older light fixtures, with new controls.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No issues identified.

### Communication and Security:

- No issues identified.

Refer to full report from Ameresco for more detail.

### Structural

- The original classroom building is rated as a 'Very High' seismic risk.

Refer to full report from ZCS Engineering and Architecture for more detail.




Outdoor Canopy




Boiler Room

# 08 - THOMPSON ELEMENTARY SCHOOL (WHEATLEY) SITE PLAN



# 08 - THOMPSON ELEMENTARY SCHOOL (WHEATLEY) FLOOR PLAN



# 08 - THOMPSON ELEMENTARY SCHOOL (WHEATLEY)



## Facility Summary

The original Thompson Elementary School has been operated by the Multnomah County Educational Services District (MESD) as Wheatley Middle School for several years. As such, the building’s educational adequacy was not fully evaluated and this assessment focuses primarily on the physical infrastructure of the building and it’s supporting systems.


Like Helensview, no major bond projects have been completed recently and there are significant needs throughout.

Major needs identified include window replacement (including seismically dangerous glass block), mechanical system replacement, boiler replacement, electrical panel replacement, and replacement of plumbing fixtures and piping. It’s a site that has been recommended to add fire sprinklers for added safety. The concrete entry canopy needs repair as well.

Similar to all other elementary schools, this building is also listed as a ‘Very High’ seismic risk.

|                        |  |
|------------------------|--|
| Site Name:             | Thompson Elementary                            |
| Building Name:         | Wheatley School                                |
| ODE Building ID:       | 21810004                                       |
| Building Type:         | Middle School                                  |
| Students:              | MESD   |
| Building Address:      | 14030 NE Sacramento St.,<br>Portland, OR 97230 |
| County:                | Multnomah                                      |
| Gross Square Footage:  | 50,400   |
| Site Acreage:          | TBD  |
| Year Built:            | 1958   |
| Additions/Renovations: | TBD  |
| Number of Floors:      | One(1)   |
| Primary Structure:     | Wood Framing                                   |
| Roof Type:             | Built-Up (SBS)                                 |
| Replacement Budget:    | \$25,769,016                                   |

# 08 - THOMPSON ELEMENTARY SCHOOL (WHEATLEY)



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 08 - THOMPSON ELEMENTARY SCHOOL (WHEATLEY)

## Architectural

- Replace all exterior windows, including glass block.
- Repair exterior concrete entry canopy showing water damage.
- Re-point, clean and re-seal brick masonry veneer exterior.
- Interior finishes, ceilings and casework are all beyond their natural life and are recommended for replacement.
- Repair downspouts at Covered Play Structure, where they have been cut short and daylight / dump out onto the site.
- Remove rust and repair / replace panels at Covered Play Structure as needed.
- Re-roofing is recommended for the entire school.

## Site Safety and Security Analysis

- Add pedestrian pathway (sidewalk) from the public right-of-way along the entry drive.
- Repair site paving at playground, parking area and roadway.

## Accessibility

- Restrooms are original in many situations and not designed to current accessibility standards.
- Provide accessible route to stage area.

## Hazardous Materials and Indoor Air Quality

- There is significant 9x9 resilient floor tile, typically an indication of asbestos-containing material.
- The age of the building would indicate a typically high level of hazardous materials otherwise, including lead paint and radon.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



# 08 - THOMPSON ELEMENTARY SCHOOL (WHEATLEY)

## Building Systems

### Fire Protection:

- While not required by code, it is recommended to add fire sprinklers to the building, in order to increase the overall safety of the site.

### Plumbing:

- Replace plumbing fixtures and supply piping to the building.

### Mechanical:

- Replace existing boiler system that is beyond its natural lifespan.
- Replace the mechanical units that are well beyond their practical lifespan.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.
- Provide full mechanical controls upgrade.

### Electrical:

- This building requires replacement of the existing electrical panels and upgrades / replacement of the older light fixtures, with new controls.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No issues identified.

### Communication and Security:

- No issues identified.

Refer to full report from Ameresco for more detail.

## Structural

- The original classroom building is rated as a 'Very High' seismic risk.

Refer to full report from ZCS Engineering and Architecture for more detail.



Playground Paving and Play Structure




Restroom Facilities



# 09 - KNOTT ELEMENTARY SCHOOL (KNOTT CREEK)

## SITE PLAN



# 09 - KNOTT ELEMENTARY SCHOOL (KNOTT CREEK)

## FLOOR PLAN



# 09 - KNOTT ELEMENTARY SCHOOL (KNOTT CREEK)



## Facility Summary

The original Knott Elementary School has been operated by the Multnomah County Educational Services District (MESD) as Knott Creek Elementary for several years. As such, the building’s educational adequacy was not fully evaluated and this assessment focuses primarily on the physical infrastructure of the building and it’s supporting systems.


Similar to Helensview and Wheatley, there has been years of deferred maintenance.

Major work identified includes roofing, window replacement (including seismically dangerous glass block), mechanical equipment replacement, electrical panel replacement, and replacement of hot water heaters, plumbing fixtures and piping. Similar to all other elementary schools, this building is also listed as a ‘Very High’ seismic risk, and has a masonry chimney that should be considered.

The original classroom building is also listed as a ‘Very High’ seismic risk.

|                        |   |
|------------------------|---|
| Site Name:             | Knott Elementary School                   |
| Building Name:         | Knott Creek Elementary                    |
| ODE Building ID:       | 21810003                                  |
| Building Type:         | Elementary School                         |
| Students:              | MESD                                      |
| Building Address:      | 11456 NE Knott St.,<br>Portland, OR 97220 |
| County:                | Multnomah                                 |
| Gross Square Footage:  | 32,592                                    |
| Site Acreage:          | 5.29                                      |
| Year Built:            | 1951                                      |
| Additions/Renovations: | N/A                                       |
| Number of Floors:      | One (1)                                   |
| Primary Structure:     | Wood Framing                              |
| Roof Type:             | Built-Up (SBS)                            |
| Replacement Budget:    | \$16,663,964                              |

# 09 - KNOTT ELEMENTARY SCHOOL (KNOTT CREEK)



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 09 - KNOTT ELEMENTARY SCHOOL (KNOTT CREEK)

## Architectural

- Complete exterior window replacement is recommended, both aluminum and glass block.
- Exterior painting is recommended.
- Interior finishes, including flooring, ceilings, paint and casework, are worn and beyond their practical lifespan. Most are recommended for replacement.

## Site Safety and Security Analysis

- The school doesn't currently have a secure vestibule and it's recommended to add it if the District were to take over use of the building again.
- Card key access is also recommended for future.
- With an entire wing that has an exterior corridor, there is a higher level of risk associated with them. The site is fully fenced to mitigate some of this risk.


## Accessibility

- Several restrooms are not fully accessible and are recommended for replacement.
- Accessible path is needed to the stage area.
- Most plumbing fixtures are not installed to meet accessible guidelines, including sinks, toilets and drinking fountains.
- Steep ramps across the corridors are not to code and represent a potential risk.

## Hazardous Materials and Indoor Air Quality

- There is significant 9x9 resilient floor tile, typically an indication of asbestos-containing material.
- The age of the building would indicate a typically high level of hazardous materials otherwise, including lead paint and radon.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



# 09 - KNOTT ELEMENTARY SCHOOL (KNOTT CREEK)

## Building Systems

### Fire Protection:

- While not required by code, it is recommended to add fire sprinklers to the building, in order to increase the overall safety of the site.

### Plumbing:

- Replace plumbing fixtures and supply piping to the building.
- Replacement of existing domestic hot water heaters is recommended, due to age, capacity and overall condition.

### Mechanical:

- Replace existing boiler system that is beyond its natural lifespan.
- Replace the mechanical units that are well beyond their practical lifespan.
- Testing and retro-commissioning existing system is recommended to increase performance and efficiency overall.
- Provide full mechanical controls upgrade.

### Electrical:

- This building requires replacement of the existing electrical panels and upgrades / replacement of the older light fixtures, with new controls.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No issues identified.

### Communication and Security:

- No issues identified.

Refer to full report from Ameresco for more detail.

## Structural

- The original classroom building is rated as a 'Very High' seismic risk.

Refer to full report from ZCS Engineering and Architecture for more detail.




Classroom Canopy



Corridor Ramp


# 10 - DISTRICT OFFICE AND MAINTENANCE

## SITE PLAN



# 10 - DISTRICT OFFICE AND MAINTENANCE

## FLOOR PLAN





# 10 - DISTRICT OFFICE AND MAINTENANCE



## Facility Summary

The District Office campus consists of three main buildings - the District Administration office, the Facilities Office and workshop, and the Bus Maintenance and Warehouse building. All are a similar age and have a significant needs at various levels. The District Office has seen the most recent upgrades, including window replacement, roofing and a secure vestibule added.

There are some renovations desired, including possibly infilling the Admin office courtyard and modifying the work room to modernize the space. The District has discussed also shifting the Nutrition Services staff to the Warehouse.

The Facilities and Maintenance buildings are both older industrial buildings that have had minimal maintenance but are still generally functional.

Many of these buildings represent a ‘High’ risk seismically and should be evaluated for long-term future use.

|                        |   |
|------------------------|---|
| Site Name:             | District Administration                           |
| Building Name:         | Office, Facilities and Transportation / Warehouse |
| ODE Building ID:       | 21810000  |
| Building Type:         | Administration / Facilities                       |
| Students:              | N/A   |
| Building Address:      | 10636 NE Prescott St.,<br>Portland, OR 97220      |
| County:                | Multnomah   |
| Gross Square Footage:  | 4,000   |
| Site Acreage:          | 2.13  |
| Year Built:            | 1965  |
| Additions/Renovations: | N/A   |
| Number of Floors:      | One (1)   |
| Primary Structure:     | Wood Framing / CMU                                |
| Roof Type:             | Built-Up (SBS), Metal                             |
| Replacement Budget:    | \$10,420,877                                      |

# 10 - DISTRICT OFFICE AND MAINTENANCE



|                            |          |
|----------------------------|----------|
| Excellent                  | 90 - 100 |
| Satisfactory               | 70 - 90  |
| Minor Modernization Needed | 50 - 70  |
| Modernization Needed       | 30 - 50  |
| Major Modernization Needed | 0 - 30   |



# 10 - DISTRICT OFFICE AND MAINTENANCE

## Architectural

### ADMINISTRATION OFFICE

- Evaluate infilling the exterior courtyard for better utilization.
- Work Room minor renovation desired to better utilize the space.
- Modify Student Services for better efficiency.
- Minor wall reconfiguration to allow copier to be located in central alcove.
- Consider adding electronic monument sign for District identity.
- Roof requires evaluation, as gutters overflow regularly in strong rain.
- Reroofing recommended prior to 2035.

### FACILITIES BUILDING

- Restore metal roofing throughout.
- Entire exterior planned for repainting soon.

### WAREHOUSE / BUS + GROUNDS GARAGE

- Grounds storage isn't adequate and needs to be expanded.
- Replace hardware at all overhead doors, look to add power-operated doors throughout.
- Debris falls from ceiling in bus garage shop.
- Replace both vehicle lifts (original to the building).
- Restore metal roofing and replace built-up roofing.

## Site Safety and Security Analysis

### ADMINISTRATION OFFICE

- Add cameras at east side of building where multiple break ins have occurred in the past.
- Replace the older, worn sections of site fencing.

### WAREHOUSE + BUS BARN

- Consider adding exterior alarms to deter thieves that get in past the fence / gate.

## Accessibility

- For all buildings, the restrooms are not fully accessible and could be renovated to accommodate differently abled persons.

## Hazardous Materials and Indoor Air Quality

- Due to the age of all three buildings, it's likely to assume there are hazardous materials within the building.
- The more recent renovations of the Administration Building has likely removed some or most of the hazardous materials.

No hazardous materials testing has been performed as part of this evaluation. All information on the presence and performance of these materials has been provided by the District.



# 10 - DISTRICT OFFICE AND MAINTENANCE

## Building Systems

### Fire Protection:

- While not required by code, it is recommended to add fire sprinklers to the building, in order to increase the overall safety of the site.

### Plumbing:

#### WAREHOUSE / BUS + GROUNDS GARAGE

- Replace hot water heater platform (relatively new seismic strapping exists).
- Evaluate removing underground gas tanks and pumps.

### Mechanical:

#### ADMINISTRATION OFFICE

- The building has four separate air conditioning units, which are inefficient and should be replaced with a centralized system, particularly considering the size of the building.

#### WAREHOUSE / BUS + GROUNDS GARAGE

- Space heater is too loud in bus garage shop and should be evaluated.

### Electrical:

#### ADMINISTRATION OFFICE

- Modernize and upgrade the existing IT server room.

#### WAREHOUSE / BUS + GROUNDS GARAGE

- Electrical was upgraded but tied to computer, so turning off lights also turns off the computer and should be rectified.

### Lighting:

- While some lighting replacement has occurred by the District already, we recommend full replacement of all non-LED fixtures with new.
- With new lighting, adding controls will increase efficiency and assist with ease of operations.

### Fire Alarm:

- No issues identified.

### Communication and Security:

- No issues identified.

Refer to full report from Ameresco for more detail.

## Structural

- The original office building is rated as a 'High' seismic risk.
- Both the Facilities and Warehouse buildings are listed as 'Very High' seismic risk.
- At the overhead doors in the Bus Barn / Grounds Garage, the header has a huge notch removed from it, and likely compromised the structural integrity.

Refer to full report from ZCS Engineering and Architecture for more detail.



# APPENDIX A

## FACILITY CONDITION ASSESSMENT

## STRUCTURAL



September 3, 2021

Marlene Gillis  
Soderstrom Architects  
1200 NW Naito Pkwy #410  
Portland, Oregon 97209

Reference: Parkrose School District

Subject: Facilities Assessment Report

At your request, Soderstrom Architects has retained the services of ZCS Engineering and Architecture to review the existing facilities conditions for Parkrose School District (District). Per your request, ZCS representatives visited the facilities on a tour to observe the existing construction and identify and document any damaged structural elements. A review of as-built drawings provided by the District was also performed.

We have provided a comprehensive assessment of all the observable structural deficiencies for the school facilities throughout the District, Prescott Elementary School, Russell Academy, Sacramento Elementary School, Shaver Elementary School, Parkrose Middle School, Parkrose High School, Sumner Elementary School (Helensview), Thompson Elementary School (Wheatley), Knott Elementary School (Knott Creek), and the District Office and Maintenance. The deficiencies noted in this assessment should be addressed with any future repairs, retrofits, or remodels as budget allows. Unless otherwise noted in this report very little distress to structural components were observed. Destructive investigation, testing, or any other formal analysis were not performed during this investigation.

The following outlines each of the facility evaluations referenced above.

### **Prescott Elementary School**

Prescott Elementary School is located at 10410 NE Prescott St. in Portland, Oregon and was constructed in 1947 with an approximate footprint of 33,300 square feet. The building is a single-story structure consisting of wood framed bearing walls with brick veneer on exterior walls. A partial basement consisting of cast-in-place concrete exterior walls is located at the eastern portion of the building. The basement floor consists of a concrete slab on grade and the second floor framing consists of wood beams and joists supported by bearing walls and steel columns in the basement. The classroom wing floor consist of wood framed joists over

crawlspace. The roof structure is framed with trusses in the multipurpose room and conventional 2x wood framing in the remaining areas. Portions of the building has glass block, which lacks structural integrity and is considered a seismic falling hazard. The north side of the classroom wing consists of fiber cement siding, which has a large amount of damage. Although this damage is primarily cosmetic, it is possible that the compromised siding can cause structural damage in the form of rotting framing members, mold and rodent damage if left unmitigated.



**Figure 1: Damage to siding and downspout**

A separate annex building is located to the south of the original school building. This 12,100 square foot building was constructed in 1959 and consists of cast-in-place concrete exterior walls. The floor consists of concrete slab on grade, and the roof structure is 1x diagonal sheathing over wood joists supported by bearing walls and steel beams.

Between the main school building and the annex is a covered play area, with a structure consisting of knee-braced steel columns, glulam beams and purlins, and corrugated plastic roof. On the west end of the original school building is another covered play with a structure consisting of steel columns and a wood frame roof. These structures are excluded from this evaluation.

In 1996, a number of seismic upgrades were implemented as part of larger fire and life safety upgrades. The upgrades include installation of plywood shear walls, installation of hardware for in-plane force transfer from roof to walls, installation of plywood roof diaphragms, and attachment of walls to the foundations. These upgrades do not constitute a comprehensive seismic retrofit, and further efforts to evaluate the current seismic hazards of this school is recommended.

No other structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

## **Russell Academy**

Russell Academy is located at 2700 NE 127<sup>th</sup> Ave. in Portland, Oregon and was constructed in 1963 with an approximate footprint of 47,000 square feet. The building is a single-story structure consisting of wood framed interior and exterior walls. The floor consists of concrete slab on grade, and the roof structure is framed with glulam beams and straight decking. Moisture damage to the exterior glulam beams and decking was observed at the exterior covered areas. Further investigation into the condition of these members and suggested treatment is recommended.



**Figure 2: Damage at covered walkway areas**

In 1966, the original classroom wing was expanded with an additional 4 classrooms and a covered play area. This structure was constructed using similar methods to that of the original building.

In 1996, a number of seismic upgrades were implemented as part of larger fire and life safety upgrades. The upgrades include installation of plywood shear walls, installation of hardware for in-plane force transfer from roof to walls, installation of plywood roof diaphragms, and attachment of walls to the foundations. These upgrades do not constitute a comprehensive seismic retrofit, and further efforts to evaluate the current seismic hazards of this school is recommended.



In 2014, a new 5,200 square foot multipurpose room addition was constructed in the northwest corner of the campus. This is a post-benchmark building constructed to current code and therefore have no seismic or structural deficiencies.

Damage and cracking is also apparent in brick veneer pilasters, which was reconstructed as part of the 1996 seismic upgrades. It is our recommendation to remove and reinstall the veneer at these locations.



**Figure 3: Damaged brick veneer**

Adjacent to the classroom wing is a covered play area, with a structure consisting of pre-engineered metal building with metal roof. This structure is excluded from this evaluation.

No other structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

## **Sacramento Elementary School**

Sacramento Elementary School is located at 11400 NE Sacramento St. in Portland, Oregon and was originally constructed in 1960 with an approximate footprint of 43,500 square feet. The school structure consists of a single-story classroom building with a centrally located multipurpose room. The entire school is constructed using cast-in-place concrete foundations

and wall elements. The interior bearing walls consist of wood framed stud walls. The floor consists of concrete slab on grade. The roof framing consists of diagonal 1x sheathing supported by 2x wood framing.

In 1996, a number of seismic upgrades were implemented as part of larger fire and life safety upgrades. The upgrades include installation of plywood shear walls, installation of hardware for in-plane force transfer from roof to walls, and attachment of walls to the foundations. These upgrades do not constitute a comprehensive seismic retrofit, and further efforts to evaluate the current seismic hazards of this school is recommended.

A new gymnasium building was added on the south side of the existing school building in 2014. This 4,400 square foot structure consists of wood framed exterior bearing walls with brick veneer. The floor is slab on grade and the roof framing consists of wood open web joists and plywood sheathing. At the same time, new administration offices were added to the north side of the existing building. This 2,100 square foot portion of the building is also constructed using wood framed bearing walls with brick veneer. The floor is slab on grade and roof framing consists of wood I-joists and plywood sheathing. These additions are considered post-benchmark buildings and therefore have no seismic or structural deficiencies.

On the campus there are two covered play areas, with structures consisting of pre-engineered metal buildings with metal roof. These structures are excluded from this evaluation.

No structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given their age.

### **Shaver Elementary School**

Shaver Elementary School is located at 3701 NE 131<sup>st</sup> Pl. in Portland, Oregon and was constructed in 1963 with an approximate footprint of 50,400 square feet. The building is a single-story structure consisting of cast-in-place concrete exterior walls. The floor consists of concrete slab on grade, and the roof structure is framed with 1x diagonal sheathing and wood joists supported by bearing walls and steel beams. The gymnasium roof structure consists of 1x diagonal sheathing and wood joists supported by glulam beams.

In 1965, a 6-classroom expansion of the existing classroom wing was constructed. The structural system is similar to that of the original construction.

In 1996, a number of seismic upgrades were implemented as part of larger fire and life safety upgrades. The upgrades include installation of plywood shear walls, installation of hardware for in-plane force transfer from roof to walls, and attachment of walls to the foundations. These upgrades do not constitute a comprehensive seismic retrofit, and further efforts to evaluate the current seismic hazards of this school is recommended.

In 2014, a new 5,200 square foot multipurpose room addition was constructed in the southeast corner of the campus. This is a post-benchmark building constructed to current code and therefore have no seismic or structural deficiencies.

On the campus there is also a covered play area, with a structure consisting of a pre-engineered metal building with metal roof. This structure is excluded from this evaluation.

No structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

### **Parkrose Middle School**

Parkrose Middle School is located at 11800 NE Shaver St. in Portland, Oregon and was constructed in 2013 with an approximate footprint of 145,000 square feet. The building is a two-story structure consisting of reinforced masonry exterior walls. The floor consists of concrete slab on grade, the second floor consists of concrete slab on metal deck, and the roof structure is framed with steel beams and metal decking.

This is a post-benchmark building constructed to current code and therefore have no seismic or structural deficiencies.

### **Parkrose High School**

Parkrose High School is located at 12003 NE Shaver St. in Portland, Oregon and was constructed in 1996 with an approximate footprint of 190,500 square feet. The campus consists of multiple building parts with different structural systems. The classroom wings are two-story buildings supported by steel framing, braced frames, and a concrete slab on grade for the main level and concrete slab on metal deck for the elevated second floor. The library and student center is a single-story structure similarly constructed using steel framing and braced frames. The auditorium, gymnasium and pool buildings are all constructed using reinforced concrete masonry unit (CMU) bearing walls with steel framed roof systems. The band and music spaces are constructed as a two-story building attached to the north side of the auditorium building. This portion of the building is also steel framed, with a concrete slab on metal deck for the second floor.

A separate fine arts building is located to the west of the high school building and is the only remaining portion of the original 1968 high school facility on this campus. This structure is a 16,400 square foot building also consisting of cast-in-place concrete exterior walls. The floor consists of concrete slab on grade, and the roof structure is wood framed joists and 1x diagonal sheathing supported on steel beams.

A grandstand structure built in 1962 is also included on the campus. This building is constructed using CMU walls below the grandstands and a roof structure consisting of metal decking over

steel purlins supported by steel beams and columns. It appears that the press box superstructure installed on the roof of the grandstands is of newer construction, but we would recommend investigating the adequacy of the existing structure to accommodate this newer addition. Other buildings associated with the athletic fields have been excluded from this evaluation.

No other structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

### **Sumner Elementary School (Helensview)**

Sumner Elementary School is located at 8678 NE Sumner St. in Portland, Oregon. The original school building was constructed in 1954 with an approximate footprint of 42,900 square feet. The building is a single-story structure consisting of cast-in-place concrete exterior walls. The interior bearing walls consist of wood framed stud walls. The floor consists of concrete slab on grade, the roof framing consists of diagonal 1x sheathing supported by 2x wood framing. The multipurpose room has glulam roof beams supporting 2x rafters and 1x diagonal sheathing. Portions of the building has glass block, which lacks structural integrity and is considered a seismic falling hazard. The multipurpose roof has a large crack in the exterior concrete wall, which appears to have been repaired multiple times. The cause of this crack is not clear, but does not appear to pose significant risk to the building.



**Figure 4: Crack in exterior concrete wall**

On the campus there is also a covered play area, with a structure consisting of a pre-engineered metal building with metal roof. This structure is excluded from this evaluation.

No other structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

### **Thompson Elementary School (Wheatley)**

Thompson Elementary School is located at 14030 NE Sacramento St. in Portland, Oregon. The original school building was constructed in 1958 with an approximate footprint of 50,400 square feet. The building is a single-story structure consisting of cast-in-place concrete exterior walls. The interior bearing walls consist of wood framed stud walls. The floor consists of concrete slab on grade, the roof framing consists of concrete frames supporting concrete channel slab. The multipurpose room has concrete roof beams supporting concrete channel slab. Portions of the building has glass block, which lacks structural integrity and is considered a seismic falling hazard.

The front entry canopy shows significant decay of the concrete, with corroded rebar exposed. We would recommend repairing or replacing this canopy to avoid further deterioration resulting in falling debris or collapse.

On the campus there is also a covered play area, with a structure consisting of a pre-engineered metal building with metal roof. This structure is excluded from this evaluation.



**Figure 5: Deteriorated concrete at front entry canopy**

No other structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

## **Knott Elementary School (Knott Creek)**

Knott Elementary School is located at 11456 NE Knott St. in Portland, Oregon and was constructed in 1951 with an approximate footprint of 36,600 square feet. The building is a single-story structure consisting of cast-in-place concrete exterior walls. The interior bearing walls consist of wood framed stud walls. The floor consists of concrete slab on grade, the roof framing consists of diagonal 1x sheathing supported by 2x wood framing. The multipurpose room has glulam roof beams supporting 2x rafters and 1x diagonal sheathing. Portions of the building has glass block, which lacks structural integrity and is considered a seismic falling hazard.

In 1958, a 2-classroom addition was constructed on the west end of the existing classroom wing. This was built using a similar structural system to the original structure.

A 3,000 square foot addition was constructed in 1965. This building addition is a single-story structure consisting of cast-in-place concrete exterior walls. The interior bearing walls consist of wood framed stud walls. The floor consists of concrete slab on grade, the roof framing consists of diagonal 1x sheathing supported by 2x wood framing.

On the campus there is also a covered play area, with a structure consisting of a pre-engineered metal building with metal roof. This structure is excluded from this evaluation.

No structural deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given its age.

## **District Office/Maintenance**

The district office and maintenance facilities are located at 10636 NE Prescott St. in Portland, Oregon. The district office is a 7,200 square foot wood framed structure constructed in 1965. The roof structure consists of wood rafters supporting 1x diagonal sheathing. The board room roof structure consists of steel beams supporting wood rafters and 1x decking. Portions of the exterior walls have brick veneer.

The 7,600 square foot maintenance facility buildings were constructed in 1955 and consist of cast-in-place concrete walls with wood rafted trusses and straight decking. Several garage door openings are located on the north side of the building, with sections of the concrete headers removed. It appears that existing rebar in the headers was cut to accommodate these notches in the headers. It is not clear that these headers are adequate to support the roof structure in their current state. Further investigation of these headers and possible strengthening is recommended.



**Figure 6: Damage to concrete headers**

The bus garage and storage buildings were constructed in 1965 and consists of concrete exterior walls and moment frames. Some interior walls are CMU and the roof framing consists of 1x diagonal sheathing supported by 2x joists and glulam beams.

No other obvious structural damage or deficiencies were noted during the site walk. The buildings appeared to be in relatively good condition given their age.

## **Preliminary Seismic Assessment**

To assist the District, understand the seismic vulnerabilities of their facilities ZCS has performed Rapid Visual Assessments (RVS) of the seismic resisting systems utilizing the procedures outlined in Federal Emergency Management Act (FEMA) document P-154, “Rapid Visual Screening of Buildings for Potential Seismic Hazards: A Handbook, 3<sup>rd</sup> Edition, January 2015. As part of these assessments a score is provided to rank the buildings regarding their potential for collapse during a design level seismic event. The following table outlines the rankings system for the four different categories.

| <b><u>Risk</u></b> | <b><u>Score</u></b> | <b><u>Probability</u></b>                     |
|--------------------|---------------------|---|
| LOW                | >2.0                | Less than 1 in 100 chance of collapse         |
| MODERATE (MOD)     | >1 AND < or = 2.00  | Between 1 in 10 & 1 in 100 chance of collapse |
| HIGH               | >0,0 AND < or =1.0  | Between 100% & 1 in 10 chance of collapse     |
| VERY HIGH          | 0.0 OR LESS         | 100% chance of collapse                       |

In alignment with this ranking system, FEMA, has determined that all buildings with a score 2.0 should be considered to have inadequate performance during a design level seismic event.

For conformance, FEMA P-154 has set a score of 2.0 as the cut-off, at which, any score below would require additional structural evaluation. It is recommended that the District utilize the Seismic evaluation reporting as part of the Technical Assistance Program through ODE to perform the additional seismic evaluations.



The following is the risk evaluation determined by the RVS evaluations attached in Appendix A. Given the varying types of construction and ages of those construction found throughout the schools we have tried our best to identify the differences in risk associated with each construction types when they could be determined.

| Facility Name                       | Risk             |
|-------------------------------------|------------------|
| <b>Prescott Elementary School</b>   |                  |
| Original Classroom Building         | -1.0 – VERY HIGH |
| 1959 Addition (Annex)               | -0.4 – VERY HIGH |
| <b>Russell Elementary School</b>    |                  |
| Original School Building            | -1.1 – VERY HIGH |
| 2014 Addition                       | 5.1 – LOW        |
| <b>Sacramento Elementary School</b> |                  |
| Original School Building            | -1.8 – VERY HIGH |
| 2014 Additions                      | 5.1 – LOW        |
| <b>Shaver Elementary School</b>     |                  |
| Original School Building            | -1.8 – VERY HIGH |
| 2014 Addition                       | 5.1 - LOW        |
| <b>Parkrose Middle School</b>       |                  |
| Original School Building            | 3.8 – LOW        |
| <b>Parkrose High School</b>         |                  |
| Classroom Wings                     | 1.0 – HIGH       |
| Student Center/Library              | 1.0 – HIGH       |
| Auditorium, Gym and Pool            | 0.7 – HIGH       |
| Band/Music                          | 1.0 – HIGH       |
| Fine Arts Building                  | 1.3 – MODERATE   |
| <b>Sumner Elementary School</b>     |                  |
| Original School Building            | -1.8 – VERY HIGH |
| <b>Thompson Elementary School</b>   |                  |
| Original School Building            | -1.8 – VERY HIGH |
| <b>Knott Elementary School</b>      |                  |
| Original School Building            | -1.8 – VERY HIGH |
| 1965 Addition                       | 0.2 – HIGH       |
| <b>District Office/Maintenance</b>  |                  |
| District Office Building            | 0.6 – HIGH       |
| Maintenance Facility                | -0.6 – VERY HIGH |
| Garage and Storage                  | -1.6 – VERY HIGH |

## **Conclusion**

The findings described in this report have been limited to visual observations and a general assessment of the structural systems. Based on our visual observations, we find the structures to be in good condition and generally safe for occupancy.

No significant damage to the existing structural systems was discovered.

Given the current condition of the structures, the current code section on existing buildings does not mandate that upgrades are required unless the building is scheduled for repairs, alterations, additions, or change in occupancy.

We have attempted to identify all areas where structural damage was evident. It should be known that many areas of the structures were covered with interior or exterior finishes and could not be observed.

## **Limitations & Exclusions**

This inspection was performed for the purpose of providing information regarding major and obvious structural deficiencies specifically identified by the Client as referenced in the above scope and excludes the following:

- General exterior: including exterior envelopes (paint, siding and weather proofing, etc.), drainage systems, grading, roofing, gutters, downspouts, retaining structures, and chimneys.
- General interior: including insulation, ventilation, windows, ceilings, wall coverings, and floor coverings.
- All mechanical systems: including plumbing, fixtures and piping, hot water heater, heating, ventilation, and air-conditioning.
- All electrical systems: including all panels, low voltage, and high voltage circuitry and fixtures.
- Pests and other wood destroying organisms.
- Wells, swimming pools, septic systems, fire sprinkler and detection systems, and lawn sprinkler systems.

Maintenance and other items not specifically identified in the scope of our assignment may have been discussed, but they are not part of this inspection and report.

The inspection is not a code compliance inspection or certification based on past or present municipal codes of any kind.

This report is for the sole, confidential and exclusive use of the Client and the District.

This inspection took place within the readily accessible areas of the building and is limited to visual observations of evident conditions existing at the time of the inspection only. No structural analysis was performed to substantiate the structure's performance during prescribed code loading events.

Concealed and latent defects and deficiencies are excluded from this inspection.

Systems were not dismantled to provide inspection access.

Destructive investigation and testing was not performed.

It is understood that ZCS Engineering, Inc. is not an insurer and that this inspection and report are not intended or to be construed as an express or implied guarantee or warranty of adequacy, performance, or condition of the structure at the inspected property address. No guarantee or warranty of the structure's performance outside the loading observed at the time of inspection can be made.

We hope this information is helpful in identifying the next steps for the District with respect to this facility. In the event additional investigation or design is desired, please contact us. We would be happy to help the district achieve any goals for these facilities.


Please review this information and contact our office with any questions. Should you have any concerns, please call our office at (503) 659-2205.

Thank you,



Matthew R. Smith, PE, SE





SKETCH

Address: 10410 NE Prescott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Prescott Elementary School - Main

Use: \_\_\_\_\_

Latitude: 45.5550437 Longitude: -122.5560473

Ss: 0.628 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 1 Year Built: 1947  EST

Total Floor Area (sq. ft.): 33,300 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: 1959

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) Sloping site/moderate  
 Plan (type)

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| W2                                       |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| Basic Score                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Benchmark                            |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 1.0

**EXTENT OF REVIEW**

Exterior:  Partial  All Sides  Aerial  
Interior:  None  Visible  Entered  
Drawings Reviewed:  Yes  No  
Soil Type Source: Assumed  
Geologic Hazards Source: DOGAMI  
Contact Person: \_\_\_\_\_

**OTHER HAZARDS**

Are There Hazards That Trigger A Detailed Structural Evaluation?

Pounding potential (unless  $S_{L2} >$  cut-off, if known)  
 Falling hazards from taller adjacent building  
 Geologic hazards or Soil Type F  
 Significant damage/deterioration to the structural system

**ACTION REQUIRED**

Detailed Structural Evaluation Required?

Yes, unknown FEMA building type or other building  
 Yes, score less than cut-off  
 Yes, other hazards present  
 No

Detailed Nonstructural Evaluation Recommended? (check one)

Yes, nonstructural hazards identified that should be evaluated  
 No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary  
 No, no nonstructural hazards identified  DNK

**LEVEL 2 SCREENING PERFORMED?**

Yes, Final Level 2 Score,  $S_{L2}$  -1.0  No  
Nonstructural hazards?  Yes  No

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |                                    |
|---|--|---|------------------------------------|
| <b>Bldg Name:</b> Prescott Elementary School - Main | <b>Final Level 1 Score:</b> $S_{L1} = 1.0$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                               | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -1.0$ |
| <b>Date/Time:</b> 8/16/2021                         | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 2.0$       |                                    |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic   | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)   | Yes   | Subtotals                         |
|---|--|---|-----------------------------------|
| Vertical Irregularity, $V_{L2}$   | Sloping Site   | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                              |
|   |  | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | <u>-0.3</u>                       |
|   | Weak and/or Soft Story (circle one maximum)  | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                              |
|   |  | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                              |
|   |  | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                              |
|   |  | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                              |
|   |  | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                              |
|   | Setback  | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                              |
|   |  | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                              |
|   |  | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                              |
| Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level. | -0.5  |                                   |
|   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.           | -0.5  |                                   |
| Split Level   | There is a split level at one of the floor levels or at the roof.  | -0.5  |                                   |
| Other Irregularity  | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.  | <u>-1.0</u>   |                                   |
|   | There is another observable moderate vertical irregularity that may affect the building's seismic performance.   | -0.5  |                                   |
| Plan Irregularity, $P_{L2}$   | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)        | <u>-0.7</u>   |                                   |
|   | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.  | -0.4  |                                   |
|   | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.   | -0.4  |                                   |
|   | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.  | -0.2  |                                   |
|   | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.   | -0.4  |                                   |
|   | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.   | -0.7  |                                   |
| Redundancy  | The building has at least two bays of lateral elements on each side of the building in each direction.   | +0.3  |                                   |
| Pounding  | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:  | The floors do not align vertically within 2 feet. (Cap total  | <u>-1.0</u>                       |
|   |  | One building is 2 or more stories taller than the other. : pounding   | -1.0                              |
|   |  | The building is at the end of the block. : modifiers at -1.2)   | -0.5                              |
| S2 Building   | "K" bracing geometry is visible.   | -1.0  |                                   |
| C1 Building   | Flat plate serves as the beam in the moment frame.   | -0.4  |                                   |
| PC1/RM1 Bldg  | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                        | +0.3  |                                   |
| PC1/RM1 Bldg  | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).   | +0.3  |                                   |
| URM   | Gable walls are present.   | -0.4  |                                   |
| MH  | There is a supplemental seismic bracing system provided between the carriage and the ground.   | +1.2  |                                   |
| Retrofit  | Comprehensive seismic retrofit is visible or known from drawings.  | +1.4  |                                   |
| <b>FINAL LEVEL 2 SCORE, <math>S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}</math>.</b> $-1.0$ |  |   | <i>(Transfer to Level 1 form)</i> |

$V_{L2} = -1.3$   
(Cap at -1.2)

$P_{L2} = -0.7$   
(Cap at -1.1)

$M = -1.0$

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   | x   |    | Glass block  |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   | x   |    | Glass block  |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)  
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended  
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required  
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 10410 NE Prescott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Prescott Elementary School - 1959 Addition (Annex)

Use: \_\_\_\_\_

Latitude: 45.5550437 Longitude: -122.5560473

Ss: 0.628 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1959  EST

Total Floor Area (sq. ft.): 12,100 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                       |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> -0.4 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**B HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                    |
|--|--|---|------------------------------------|
| <b>Bldg Name:</b> Prescott Elementary School - 1959 Addition (Annex) | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT  | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -0.8$ |
| <b>Date/Time:</b> 8/16/2021  | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$       |                                    |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals |
|---------------------------------|---|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |           |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | <del>-1.0</del>   |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | <del>-0.7</del>   |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |           |
| URM                             | Gable walls are present.  | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |           |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -0.7$   
(Cap at -1.1)

$M = 0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{-0.4}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 2700 NE 127th Ave.  
Portland, OR Zip: 97230

Other Identifiers: \_\_\_\_\_

Building Name: Russell Elementary School - Main

Use: \_\_\_\_\_

Latitude: 45.5413694999 Longitude: -122.5313001

Ss: 0.630 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1963  EST

Total Floor Area (sq. ft.): 47,000 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: 1966, 2014

Occupancy: Assembly  Commercial  Emer. Services  Historic  Shelter  
Industrial  Office  School  Government  
Utility  Warehouse  Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity)  
 Plan (type) Reentrant corners

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| Basic Score                                     |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 1.0

|   |  |   |
|---|--|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S<sub>L2</sub> -1.1 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|--|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm



# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                    |
|--|--|---|------------------------------------|
| <b>Bldg Name:</b> Russell Elementary School - Main | <b>Final Level 1 Score:</b> $S_{L1} = 1.0$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                              | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -1.0$ |
| <b>Date/Time:</b> 8/16/2021                        | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 2.0$       |                                    |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)   | Yes   | Subtotals |
|---------------------------------|--|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site   | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |  | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)  | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |  | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |  | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |  | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |  | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback  | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |  | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |  | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
| Short Column/ Pier              | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level. | -0.5  |           |
|                                 | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.           | -0.5  |           |
|                                 | Split Level  | There is a split level at one of the floor levels or at the roof.   | -0.5      |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.  | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.   | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)        | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.  | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.   | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.  | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.   | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.   | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.   | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:  | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |  | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |  | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.   | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.   | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                        | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).   | +0.3  |           |
| URM                             | Gable walls are present.   | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.   | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.  | +1.4  |           |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -1.1$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $S_{L2} = -1.1$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick Veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. | x   |    |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

**Address:** 2700 NE 127th Ave.  
Portland, OR Zip: 97230

**Other Identifiers:**

**Building Name:** Russell Elementary School - 2014 Addition

**Use:**

**Latitude:** 45.54136949999 **Longitude:** -122.5313001

**Ss:** 0.630 **Sr:** 0.270

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 1 Below Grade: 0 **Year Built:** 2014  EST

**Total Floor Area (sq. ft.):** 5,200 **Code Year:** 2010 OSSC

**Additions:**  None  Yes, Year(s) Built:

**Occupancy:** Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units:

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.  
Rock Rock Soil Soil Soil Soil

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity)  Plan (type)

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other:

**COMMENTS:**

Additional sketches or comments on separate page

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 5.1**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b></p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|--|--|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**B HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |                                 |
|---|--|---|---------------------------------|
| <b>Bldg Name:</b> Russell Elementary School - 2014 Addition | <b>Final Level 1 Score:</b> $S_{L1} = 5.1$ | (do not consider $S_{MIN}$ )            |                                 |
| <b> Screener:</b> KNT                                       | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$     | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                                 | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 5.1$ |                                 |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic   | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals                  |
|---|---|---|----------------------------|
| Vertical Irregularity, $V_{L2}$   | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                       |
|   |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                       |
|   | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                       |
|   |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                       |
|   |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                       |
|   |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                       |
|   |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                       |
|   | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                       |
|   |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                       |
|   |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                       |
|   | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5                       |
|   |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5                       |
| Split Level   |   | There is a split level at one of the floor levels or at the roof.   | -0.5                       |
| Other Irregularity  | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |                            |
|   | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                            |
| Plan Irregularity, $P_{L2}$   | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |                            |
|   | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |                            |
|   | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |                            |
|   | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                            |
|   | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                            |
|   | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                            |
| Redundancy  | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |                            |
| Pounding  | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0                       |
|   |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0                       |
|   |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5                       |
| S2 Building   | "K" bracing geometry is visible.  | -1.0  |                            |
| C1 Building   | Flat plate serves as the beam in the moment frame.  | -0.4  |                            |
| PC1/RM1 Bldg  | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                            |
| PC1/RM1 Bldg  | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                            |
| URM   | Gable walls are present.  | -0.4  |                            |
| MH  | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                            |
| Retrofit  | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                            |
| <b>FINAL LEVEL 2 SCORE, <math>S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}</math>.</b> <sup>5.1</sup> |   |   | (Transfer to Level 1 form) |

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
 If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)  
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended  
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required  
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 11400 NE Sacramento St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Sacramento Elementary School - Original Building

Use: \_\_\_\_\_

Latitude: 45.539014 Longitude: -122.545169

Ss: 0.633 Sr: 0.272

Screener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1960  EST

Total Floor Area (sq. ft.): 49,500 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: 2014

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity)  Plan (type) Reentrant Corners

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                       |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> -1.8 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                    |
|--|--|---|------------------------------------|
| <b>Bldg Name:</b> Sacramento Elementary School | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                          | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -0.8$ |
| <b>Date/Time:</b> 8/16/2021                    | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$       |                                    |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)   | Yes   | Subtotals |
|---------------------------------|--|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site   | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |  | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)  | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |  | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |  | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |  | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |  | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback  | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |  | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |  | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
| Short Column/ Pier              | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level. | -0.5  |           |
|                                 | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.           | -0.5  |           |
| Split Level                     | There is a split level at one of the floor levels or at the roof.  | -0.5  |           |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.  | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.   | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)        | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.  | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.   | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.  | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.   | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.   | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.   | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:  | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |  | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |  | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.   | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.   | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                        | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).   | +0.3  |           |
| URM                             | Gable walls are present.   | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.   | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.  | +1.4  |           |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -1.1$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $S_{L2} = -1.8$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   | x   |    |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

- Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
- Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
- Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 11400 NE Sacramento St. Zip: 97220  
 Portland, OR  
 Other Identifiers:  
 Building Name: Sacramento Elementary School - 2014 additions  
 Use:  
 Latitude: 45.539014 Longitude: -122.545169  
 Ss: 0.633 Sr: 0.272  
 Screener(s): KNT Date/Time: 8/16/2021  
 No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 2014  EST  
 Total Floor Area (sq. ft.): 6,500 Code Year: 2010  
 Additions:  None  Yes, Year(s) Built:  
 Occupancy: Assembly Commercial Emer. Services  historic  Shelter  
 Industrial Office  School  Government  
 Utility Warehouse Residential, # Units:  
 Soil Type:  A  B  C  D  E  F  DNK  
 Hard Avg Dense Stiff Soft Poor DNK  
 Rock Rock Soil Soil Soil Soil If DNK, assume Type D.  
 Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK  
 Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building  
 Irregularities:  Vertical (type/severity)  Plan (type)  
 Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other:

COMMENTS:  
 Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| Basic Score                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 5.1

|  |  |  |
|--|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>         Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>         Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>         Soil Type Source: Assumed<br/>         Geologic Hazards Source: DOGAMI<br/>         Contact Person:</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> <sup>5.1</sup> <input type="checkbox"/> No<br/>         Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/> <input type="checkbox"/> Falling hazards from taller adjacent building<br/> <input type="checkbox"/> Geologic hazards or Soil Type F<br/> <input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/> <input type="checkbox"/> Yes, score less than cut-off<br/> <input type="checkbox"/> Yes, other hazards present<br/> <input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/> <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/> <input checked="" type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|--|--|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
 BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**B HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |   |   |   |
|--|---|---|---|
| <b>Bldg Name:</b> Sacramento Elementary School | <b>Final Level 1 Score:</b> $S_{L1} = 5.1$                              | <i>(do not consider <math>S_{MIN}</math>)</i>       |   |
| <b> Screener:</b> KNT                          | <b>Level 1 Irregularity Modifiers:</b>                                  | <i>Vertical Irregularity, <math>V_{L1} =</math></i> | <i>Plan Irregularity, <math>P_{L1} =</math></i> |
| <b>Date/Time:</b> 8/16/2021                    | <b>ADJUSTED BASELINE SCORE:</b> $S' = (S_{L1} - V_{L1} - P_{L1}) = 5.1$ |   |   |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals               |
|---------------------------------|---|---|-------------------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                    |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                    |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                    |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                    |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                    |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                    |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                    |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                    |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                    |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                    |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5                    |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5                    |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |                         |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |                         |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                         |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |                         |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |                         |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |                         |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                         |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                         |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                         |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |                         |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet.   | (Cap total) -1.0        |
|                                 |   | One building is 2 or more stories taller than the other.  | pounding -1.0           |
|                                 |   | The building is at the end of the block.  | modifiers at -1.2) -0.5 |
| S2 Building                     | "K" brace geometry is visible.  | -1.0  |                         |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |                         |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                         |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                         |
| URM                             | Gable walls are present.  | -0.4  |                         |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                         |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                         |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = 0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .** <sup>5.1</sup> (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  | x   |    |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
|          | Other observed exterior nonstructural falling hazard:   |     | x  |         |
| Interior | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 3701 NE 131st PL  
Portland, OR Zip: 97230

**Other Identifiers:**

**Building Name:** Staver Elementary School - Main

**Use:**

**Latitude:** 45.549440999 **Longitude:** -122.5287883

**Ss:** 0.628 **Sr:** 0.269

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 1 Below Grade: 0 **Year Built:** 1963/65  EST

**Total Floor Area (sq. ft.):** 50,400 **Code Year:** Unknown

**Additions:**  None  Yes, Year(s) Built: 2014

**Occupancy:** Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity)  Plan (type) Reentrant corners

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

**COMMENTS:**

Additional sketches or comments on separate page

SKETCH

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 0.5**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b> _____</p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
| <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S<sub>L2</sub> -1.8 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>   |  |  |

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm



# Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Level 2 (Optional)

**A** HIGH Seismicity

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |  |
|---|--|---|--|
| <b>Bldg Name:</b> Shaver Elementary School - Main | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i>         |  |
| <b> Screener:</b> KNT                             | <b>Level 1 Irregularity Modifiers:</b>     | <i>Vertical Irregularity, <math>V_{L1} = 0</math></i> | <i>Plan Irregularity, <math>P_{L1} = -0.8</math></i> |
| <b>Date/Time:</b> 8/16/2021                       | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$               |  |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals       |
|---------------------------------|---|---|-----------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2            |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3            |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6            |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2            |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2            |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9            |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5            |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0            |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5            |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3            |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5            |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5            |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |                 |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | <del>-1.0</del>   |                 |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                 |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | <del>-0.7</del>   |                 |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |                 |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | <del>-0.4</del>   |                 |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                 |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                 |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                 |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |                 |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | <del>-1.0</del> |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0            |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5            |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |                 |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |                 |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                 |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                 |
| URM                             | Gable walls are present.  | -0.4  |                 |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                 |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                 |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -1.1$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $S_{L2} = -1.8$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |


**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 3701 NE 131st PL  
Portland, OR Zip: 97230

**Other Identifiers:**

**Building Name:** Staver Elementary School - 2014 Addition (MPR)

**Use:**

**Latitude:** 45.54944099999 **Longitude:** -122.5287883

**Ss:** 0.628 **Sr:** 0.269

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 1 Below Grade: 0 **Year Built:** 2014  EST

**Total Floor Area (sq. ft.):** 5,200 **Code Year:** 2010 OSSC

**Additions:**  None  Yes, Year(s) Built: \_\_\_\_\_

**Occupancy:** Assembly  Commercial  Emer. Services  Historic  Shelter  
Industrial  Office  School  Government  
Utility  Warehouse  Residential, # Units: \_\_\_\_\_

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

**COMMENTS:**

Additional sketches or comments on separate page

SKETCH

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 5.1**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b> _____</p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input checked="" type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
| <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S<sub>L2</sub><sup>5.1</sup> _____ <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>  |  |  |

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Level 2 (Optional)

**B** HIGH Seismicity

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                 |
|--|--|---|---------------------------------|
| <b>Bldg Name:</b> Shaver Elementary School - 2014 Addition (MPR) | <b>Final Level 1 Score:</b> $S_{L1} = 5.1$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT  | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                                      | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 5.1$       |                                 |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals |
|---------------------------------|---|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5      |
| Split Level                     |   | There is a split level at one of the floor levels or at the roof.   | -0.5      |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |           |
| URM                             | Gable walls are present.  | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |           |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = 0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $S_{L2} = 5.1$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)  
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended  
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required  
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 11800 NE Shawyer St.  
Portland, OR Zip: 97220

**Other Identifiers:**

**Building Name:** Parkrose Middle School

**Use:**

**Latitude:** 45.5509324 **Longitude:** -122.5406015

**Ss:** 0.629 **Sr:** 0.270

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 2 Below Grade: 0 **Year Built:** 2013  EST

**Total Floor Area (sq. ft.):** 145,054 **Code Year:** 2010 OSSC

**Additions:**  None  Yes, Year(s) Built:

**Occupancy:** Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units:

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity)  Plan (type)

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other:

**COMMENTS:**

Additional sketches or comments on separate page

SKETCH

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| RM1   |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 3.8**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b></p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input checked="" type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
| <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S<sub>L2</sub> 3.8 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>  |  |  |

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

HIGH Seismicity

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                 |
|--|--|---|---------------------------------|
| <b>Bldg Name:</b> Parkrose Middle School | <b>Final Level 1 Score:</b> $S_{L1} = 3.8$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT                    | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021              | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 3.8$       |                                 |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals               |
|---------------------------------|---|---|-------------------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                    |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                    |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                    |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                    |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                    |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                    |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                    |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                    |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                    |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                    |
|                                 | Short Column/Pier   | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5                    |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5                    |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |                         |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |                         |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                         |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |                         |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |                         |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |                         |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                         |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                         |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                         |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |                         |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet.   | (Cap total) -1.0        |
|                                 |   | One building is 2 or more stories taller than the other.  | pounding -1.0           |
|                                 |   | The building is at the end of the block.  | modifiers at -1.2) -0.5 |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |                         |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |                         |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                         |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                         |
| URM                             | Gable walls are present.  | -0.4  |                         |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                         |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                         |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = 0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $3.8$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
|          | Other observed exterior nonstructural falling hazard:   |     | x  |              |
| Interior | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)  
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended  
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required  
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 12003 NE Shaver St.  
Portland, OR Zip: 97220

**Other Identifiers:**

**Building Name:** Parkrose High School - Classroom Wings

**Use:**

**Latitude:** 45.55313049999 **Longitude:** -122.5401505

**Ss:** 0.628 **Sr:** 0.269

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 2 Below Grade: 0 **Year Built:** 1999  EST

**Total Floor Area (sq. ft.):** 62,860 **Code Year:** 1994 UBC

**Additions:**  None  Yes, Year(s) Built: \_\_\_\_\_

**Occupancy:** Assembly  Commercial  Emer. Services  Historic  Shelter  
Industrial  Office  School  Government  
Utility  Warehouse  Residential, # Units: \_\_\_\_\_

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.  
Rock Rock Soil Soil Soil Soil

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

**COMMENTS:**

Additional sketches or comments on separate page

SKETCH

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 2.0**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b> _____</p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|--|--|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |   |   |                                 |
|--|---|---|---------------------------------|
| <b>Bldg Name:</b> Parkrose High School - Classroom Wings | <b>Final Level 1 Score:</b> $S_{L1} = 2.0$                              | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT                                    | <b>Level 1 Irregularity Modifiers:</b>                                  | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                              | <b>ADJUSTED BASELINE SCORE:</b> $S' = (S_{L1} - V_{L1} - P_{L1}) = 2.0$ |   |                                 |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals                            |                                      |
|---------------------------------|---|---|--------------------------------------|--------------------------------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                                 | $V_{L2} = 0$<br><i>(Cap at -1.2)</i> |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                                 |                                      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                                 |                                      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                                 |                                      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                                 |                                      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                                 |                                      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                                 |                                      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                                 |                                      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                                 |                                      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                                 |                                      |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5                                 |                                      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5                                 |                                      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |                                      |                                      |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |                                      |                                      |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                                      |                                      |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  | $P_{L2} = 0$<br><i>(Cap at -1.1)</i> |                                      |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |                                      |                                      |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |                                      |                                      |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                                      |                                      |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                                      |                                      |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                                      |                                      |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  | $M = -1.0$                           |                                      |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. <i>(Cap total pounding modifiers at -1.2)</i>   |                                      | -1.0                                 |
|                                 |   | One building is 2 or more stories taller than the other.  |                                      | -1.0                                 |
|                                 |   | The building is at the end of the block.  |                                      | -0.5                                 |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |                                      |                                      |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |                                      |                                      |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                                      |                                      |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                                      |                                      |
| URM                             | Gable walls are present.  | -0.4  |                                      |                                      |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                                      |                                      |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                                      |                                      |

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{1.0}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
 If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |


**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 12003 NE Shaver St.  
Portland, OR Zip: 97220

**Other Identifiers:**

**Building Name:** Parkrose High School - Student Center/Library

**Use:**

**Latitude:** 45.55313049999 **Longitude:** -122.5401505

**Ss:** 0.628 **Sr:** 0.269

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 1 Below Grade: 0 **Year Built:** 1999  EST

**Total Floor Area (sq. ft.):** 54,048 **Code Year:** 1994 UBC

**Additions:**  None  Yes, Year(s) Built: \_\_\_\_\_

**Occupancy:** Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.  
Rock Rock Soil Soil Soil Soil

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

**COMMENTS:**

Additional sketches or comments on separate page

SKETCH

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 2.0**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b> _____</p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|--|--|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm



# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**B HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |   |   |                                 |
|---|---|---|---------------------------------|
| <b>Bldg Name:</b> Parkrose High School - Student Center/Library | <b>Final Level 1 Score:</b> $S_{L1} = 2.0$                              | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT   | <b>Level 1 Irregularity Modifiers:</b>                                  | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                                     | <b>ADJUSTED BASELINE SCORE:</b> $S' = (S_{L1} - V_{L1} - P_{L1}) = 2.0$ |   |                                 |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals |
|---------------------------------|---|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
|                                 | Short Column/Pier   | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |           |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |           |
| URM                             | Gable walls are present.  | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |           |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{1.0}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

- Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
- Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
- Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 12003 NE Shaver St.  
Portland, OR Zip: 97220

**Other Identifiers:**

**Building Name:** Parkrose High School - Auditorium, Gym, Pool

**Use:**

**Latitude:** 45.55313049999 **Longitude:** -122.5401505

**Ss:** 0.628 **Sr:** 0.269

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 1 Below Grade: 1 **Year Built:** 1999  EST

**Total Floor Area (sq. ft.):** 56,415 **Code Year:** 1994 UBC

**Additions:**  None  Yes, Year(s) Built: \_\_\_\_\_

**Occupancy:** Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.  
Rock Rock Soil Soil Soil Soil

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

**COMMENTS:**

Additional sketches or comments on separate page

SKETCH

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| RM1   |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| <b>Basic Score</b>                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 1.7

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b> _____</p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|--|--|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**C HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                 |
|--|--|---|---------------------------------|
| <b>Bldg Name:</b> Parkrose High School - Auditorium, Gym, Pool | <b>Final Level 1 Score:</b> $S_{L1} = 1.7$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT  | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                                    | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.7$       |                                 |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals |
|---------------------------------|---|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
|                                 | Short Column/Pier   | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |           |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" brace geometry is visible.  | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |           |
| URM                             | Gable walls are present.  | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |           |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{0.7}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

- Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
- Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
- Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



Address: 12003 NE Shaver St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Parkrose High School - Band/Music

Use: \_\_\_\_\_

Latitude: 45.5531304999 Longitude: -122.5401505

Ss: 0.628 Sr: 0.269

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1999  EST

Total Floor Area (sq. ft.): 17,320 Code Year: 1994 UBC

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.  
Rock Rock Soil Soil Soil Soil

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS: \_\_\_\_\_

Additional sketches or comments on separate page

SKETCH

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>Basic Score</b>                       |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 2.0

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2} \geq 1.0</math> <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**D HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |   |   |                                 |
|---|---|---|---------------------------------|
| <b>Bldg Name:</b> Parkrose High School - Band/Music | <b>Final Level 1 Score:</b> $S_{L1} = 2.0$                              | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT                               | <b>Level 1 Irregularity Modifiers:</b>                                  | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                         | <b>ADJUSTED BASELINE SCORE:</b> $S' = (S_{L1} - V_{L1} - P_{L1}) = 2.0$ |   |                                 |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals |
|---------------------------------|---|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |           |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |           |
| URM                             | Gable walls are present.  | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |           |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{1.0}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



Address: 12003 NE Shaver St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Parkrose High School - Fine Arts

Use: \_\_\_\_\_

Latitude: 45.5531304999 Longitude: -122.5401505

Ss: 0.628 Sr: 0.269

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1950 EST

Total Floor Area (sq. ft.): 16,400 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.  
Rock Rock Soil Soil Soil Soil

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

SKETCH

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>

| FEMA BUILDING TYPE                              | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| C2  |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| Basic Score                                     |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 1.3

|  |   |  |
|--|---|--|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>Soil Type Source: Assumed</p> <p>Geologic Hazards Source: DOGAMI</p> <p>Contact Person: _____</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|--|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**E HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                 |
|--|--|---|---------------------------------|
| <b>Bldg Name:</b> Parkrose High School - Fine Arts | <b>Final Level 1 Score:</b> $S_{L1} = 1.3$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                 |
| <b> Screener:</b> KNT                              | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = 0$ |
| <b>Date/Time:</b> 8/16/2021                        | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$       |                                 |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals               |
|---------------------------------|---|---|-------------------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                    |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                    |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                    |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                    |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                    |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                    |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                    |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                    |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                    |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                    |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5                    |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5                    |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |                         |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |                         |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                         |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |                         |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |                         |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |                         |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                         |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                         |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                         |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |                         |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet.   | (Cap total) -1.0        |
|                                 |   | One building is 2 or more stories taller than the other.  | pounding -1.0           |
|                                 |   | The building is at the end of the block.  | modifiers at -1.2) -0.5 |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |                         |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |                         |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                         |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                         |
| URM                             | Gable walls are present.  | -0.4  |                         |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                         |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                         |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = 0$   
(Cap at -1.1)

$M = 0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .** <sup>1,3</sup> (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 8678 NE Sumner St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Summer Elementary School (Helensview)

Use: \_\_\_\_\_

Latitude: 45.5619285999999 Longitude: -122.5749032

Ss: 0.626 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1954  EST

Total Floor Area (sq. ft.): 42,900 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity)  Plan (type) Reentrant corners

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: Glass block

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | Do Not Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|-------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| C2                                       |             |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| Basic Score                              |             | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |             | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |             | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |             | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |             | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |             | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |             | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |             | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |             | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |             | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> -1.8 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm



# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

HIGH Seismicity

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |   |   |  |
|---|---|---|--|
| <b>Bldg Name:</b> <i>Sumner Elementary School</i> | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$                              | <i>(do not consider <math>S_{MIN}</math>)</i>         |  |
| <b> Screener:</b> <i>KNT</i>                      | <b>Level 1 Irregularity Modifiers:</b>                                  | <i>Vertical Irregularity, <math>V_{L1} = 0</math></i> | <i>Plan Irregularity, <math>P_{L1} = -0.8</math></i> |
| <b>Date/Time:</b> <i>8/16/2021</i>                | <b>ADJUSTED BASELINE SCORE:</b> $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$ |   |  |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals   |
|---------------------------------|---|---|-------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2        |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3        |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6        |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2        |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2        |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9        |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5        |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0        |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5        |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3        |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5        |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5        |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |             |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | <u>-1.0</u>   |             |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |             |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | <u>-0.7</u>   |             |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |             |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | <u>-0.4</u>   |             |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |             |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |             |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |             |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |             |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | <u>-1.0</u> |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0        |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5        |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |             |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |             |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |             |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |             |
| URM                             | Gable walls are present.  | -0.4  |             |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |             |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |             |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -1.1$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .** *-1.8* (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment     |
|----------|---|-----|----|-------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         | x   |    | URM Chimney |
|          | There is heavy cladding or heavy veneer.  | x   |    |             |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. | x   |    |             |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |             |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |             |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |             |
| Interior | Other observed exterior nonstructural falling hazard:   | x   |    | Glass block |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |             |
|          | Other observed interior nonstructural falling hazard:   | x   |    | Glass block |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)  
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended  
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required  
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



**Address:** 14030 NE Sacramento St.  
Portland, OR Zip: 97230

**Other Identifiers:**

**Building Name:** Thompson Elementary School (Wheatley)

**Use:**

**Latitude:** 45.539998 **Longitude:** -122.5187248

**Ss:** 0.629 **Sr:** 0.269

**Screeener(s):** KNT **Date/Time:** 8/16/2021

**No. Stories:** Above Grade: 1 Below Grade: 0 **Year Built:** 1958  EST

**Total Floor Area (sq. ft.):** 50,400 **Code Year:** Unknown

**Additions:**  None  Yes, Year(s) Built:

**Occupancy:** Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units:

**Soil Type:**  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

**Geologic Hazards:** Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

**Adjacency:**  Pounding  Falling Hazards from Taller Adjacent Building

**Irregularities:**  Vertical (type/severity)  Plan (type) Reentrant corner

**Exterior Falling Hazards:**  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: Glass block

**COMMENTS:**

SKETCH

Additional sketches or comments on separate page

**BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S<sub>L1</sub>**

| FEMA BUILDING TYPE                              | Do Not Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|---|-------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| <b>C2</b>                                       |             |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| <b>Basic Score</b>                              |             | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, V <sub>L1</sub>   |             | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, V <sub>L1</sub> |             | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, P <sub>L1</sub>              |             | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code  |             | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                                  |             | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                                |             | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                       |             | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                       |             | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, S <sub>MIN</sub>                 |             | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

**FINAL LEVEL 1 SCORE, S<sub>L1</sub> ≥ S<sub>MIN</sub>: 0.5**

|   |  |  |
|---|--|--|
| <p><b>EXTENT OF REVIEW</b></p> <p><b>Exterior:</b> <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p><b>Interior:</b> <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p><b>Drawings Reviewed:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Soil Type Source:</b> Assumed</p> <p><b>Geologic Hazards Source:</b> DOGAMI</p> <p><b>Contact Person:</b></p> | <p><b>OTHER HAZARDS</b></p> <p><b>Are There Hazards That Trigger A Detailed Structural Evaluation?</b></p> <p><input type="checkbox"/> Pounding potential (unless S<sub>L2</sub> &gt; cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p><b>Detailed Structural Evaluation Required?</b></p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input checked="" type="checkbox"/> No</p> <p><b>Detailed Nonstructural Evaluation Recommended? (check one)</b></p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
| <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S<sub>L2</sub> -1.8 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>   |  |  |

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

## FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |                                    |
|---|--|---|------------------------------------|
| <b>Bldg Name:</b> Thompson Elementary School (Wheatley) | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                                   | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -0.8$ |
| <b>Date/Time:</b> 8/16/2021                             | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$       |                                    |

### STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)   | Yes   | Subtotals                        |             |
|---------------------------------|--|---|----------------------------------|-------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site   | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                             |             |
|                                 |  | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                             |             |
|                                 | Weak and/or Soft Story (circle one maximum)  | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                             |             |
|                                 |  | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                             |             |
|                                 |  | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                             |             |
|                                 |  | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                             |             |
|                                 |  | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                             |             |
|                                 | Setback  | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                             |             |
|                                 |  | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                             |             |
|                                 |  | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                             |             |
| Short Column/ Pier              | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level. | -0.5  |                                  |             |
|                                 | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.           | -0.5  |                                  |             |
|                                 | Split Level  | There is a split level at one of the floor levels or at the roof.   | -0.5                             |             |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.  | <u>-1.0</u>   | $V_{L2} = -1.0$<br>(Cap at -1.2) |             |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.   | -0.5  |                                  |             |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)        | <u>-0.7</u>   | $P_{L2} = -1.1$<br>(Cap at -1.1) |             |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.  | -0.4  |                                  |             |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.   | <u>-0.4</u>   |                                  |             |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.  | -0.2  |                                  |             |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.   | -0.4  |                                  |             |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.   | -0.7  |                                  |             |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.   | +0.3  | $M = -1.0$                       |             |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:  | The floors do not align vertically within 2 feet. (Cap total  |                                  | <u>-1.0</u> |
|                                 |  | One building is 2 or more stories taller than the other. : pounding   |                                  | -1.0        |
|                                 |  | The building is at the end of the block. : modifiers at -1.2)   |                                  | -0.5        |
| S2 Building                     | "K" bracing geometry is visible.   | -1.0  |                                  |             |
| C1 Building                     | Flat plate serves as the beam in the moment frame.   | -0.4  |                                  |             |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                        | +0.3  |                                  |             |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).   | +0.3  |                                  |             |
| URM                             | Gable walls are present.   | -0.4  |                                  |             |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.   | +1.2  |                                  |             |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.  | +1.4  |                                  |             |

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $S_{L2} = -1.8$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
 If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

### OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment     |
|----------|---|-----|----|-------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         | x   |    | URM Chimney |
|          | There is heavy cladding or heavy veneer.  | x   |    |             |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. | x   |    |             |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |             |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |             |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |             |
| Interior | Other observed exterior nonstructural falling hazard:   | x   |    | Glass block |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |             |
|          | Other observed interior nonstructural falling hazard:   | x   |    | Glass block |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 11456 NE Knott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Knott Elementary School (Knott Creek) - Main

Use: \_\_\_\_\_

Latitude: 45.5414431671686 Longitude: -122.54490024755934

Ss: 0.632 Sr: 0.271

Screener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1951  EST

Total Floor Area (sq. ft.): 36,600 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: 1956, 1965

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity)  
 Plan (type) Reentrant corners

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: Glass blocks

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| C2                                       |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| Basic Score                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|   |   |   |
|---|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> <sup>-1.8</sup> _____ <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |  |
|---|--|---|--|
| <b>Bldg Name:</b> Knott Elementary School (Knott Creek) | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i>         |  |
| <b> Screener:</b> KNT                                   | <b>Level 1 Irregularity Modifiers:</b>     | <i>Vertical Irregularity, <math>V_{L1} = 0</math></i> | <i>Plan Irregularity, <math>P_{L1} = -0.8</math></i> |
| <b>Date/Time:</b> 8/16/2021                             | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$               |  |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)   | Yes   | Subtotals |
|---------------------------------|--|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site   | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |  | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)  | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |  | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |  | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |  | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |  | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback  | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |  | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |  | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
| Short Column/ Pier              | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level. | -0.5  |           |
|                                 | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.           | -0.5  |           |
|                                 | Split Level  | There is a split level at one of the floor levels or at the roof.   | -0.5      |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.  | -1.0  |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.   | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)        | -0.7  |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.  | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.   | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.  | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.   | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.   | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.   | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:  | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |  | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |  | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.   | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.   | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                        | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).   | +0.3  |           |
| URM                             | Gable walls are present.   | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.   | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.  | +1.4  |           |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -1.1$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $-1.8$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment     |
|----------|---|-----|----|-------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |             |
|          | There is heavy cladding or heavy veneer.  |     | x  |             |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |             |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |             |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |             |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |             |
| Interior | Other observed exterior nonstructural falling hazard:   | x   |    | Glass block |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |             |
|          | Other observed interior nonstructural falling hazard:   | x   |    | Glass block |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

- Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
- Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
- Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 11456 NE Knott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Knott Elementary School (Knott Creek) - 1965 Addition

Use: \_\_\_\_\_

Latitude: 45.5414431671686 Longitude: -122.54490024755934

Ss: 0.632 Sr: 0.271

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1965  EST

Total Floor Area (sq. ft.): 3,000 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office  School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) Reentrant corners

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| C2                                       |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| Basic Score                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|   |   |   |
|---|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> 0.2 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|---|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**B HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |                                    |
|---|--|---|------------------------------------|
| <b>Bldg Name:</b> Knott Elementary School (Knott Creek) | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                                   | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -0.8$ |
| <b>Date/Time:</b> 8/16/2021                             | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$       |                                    |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals                               |                                      |
|---------------------------------|---|---|---|--------------------------------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2                                    | $V_{L2} = 0$<br><i>(Cap at -1.2)</i> |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3                                    |                                      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6                                    |                                      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2                                    |                                      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2                                    |                                      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9                                    |                                      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5                                    |                                      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0                                    |                                      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5                                    |                                      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3                                    |                                      |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5                                    |                                      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5                                    |                                      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |   |                                      |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |   |                                      |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |   |                                      |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | <u>-0.7</u>   | $P_{L2} = -1.1$<br><i>(Cap at -1.1)</i> |                                      |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |   |                                      |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | <u>-0.4</u>   |   |                                      |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |   |                                      |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |   |                                      |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |   |                                      |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  | $M = 0$                                 |                                      |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. <i>(Cap total</i>   |   | -1.0                                 |
|                                 |   | One building is 2 or more stories taller than the other. <i>pounding</i>  |   | -1.0                                 |
|                                 |   | The building is at the end of the block. <i>modifiers at -1.2)</i>  |   | -0.5                                 |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |   |                                      |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |   |                                      |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |   |                                      |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |   |                                      |
| URM                             | Gable walls are present.  | -0.4  |   |                                      |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |   |                                      |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |   |                                      |

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{0.2}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
 If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 10636 NE Prescott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Parkrose District Office

Use: \_\_\_\_\_

Latitude: 45.5550043 Longitude: -122.5529517

Ss: 0.628 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1964 EST

Total Floor Area (sq. ft.): 7,200 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor DNK  
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity)  
 Plan (type) Non-parallel systems

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| Basic Score                              |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.4     | -0.7    | -0.1         | -0.5     | -0.3 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 1.0

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> <sup>0.6</sup> _____ <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm



# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**A HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |                                    |
|--|--|---|------------------------------------|
| <b>Bldg Name:</b> Parkrose District Office | <b>Final Level 1 Score:</b> $S_{L1} = 1.0$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                      | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -1.0$ |
| <b>Date/Time:</b> 8/16/2021                | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 2.0$       |                                    |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals       |
|---------------------------------|---|---|-----------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2            |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3            |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6            |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2            |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2            |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9            |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5            |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0            |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5            |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3            |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5            |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5            |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |                 |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | -1.0  |                 |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |                 |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | -0.7  |                 |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | <del>-0.4</del>   |                 |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |                 |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |                 |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |                 |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |                 |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |                 |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total  | <del>-1.0</del> |
|                                 |   | One building is 2 or more stories taller than the other. : pounding   | -1.0            |
|                                 |   | The building is at the end of the block. : modifiers at -1.2)   | -0.5            |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |                 |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |                 |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |                 |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |                 |
| URM                             | Gable walls are present.  | -0.4  |                 |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |                 |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |                 |

$V_{L2} = 0$   
(Cap at -1.2)

$P_{L2} = -0.4$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}^{0.6}$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment      |
|----------|---|-----|----|--------------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |              |
|          | There is heavy cladding or heavy veneer.  | x   |    | Brick veneer |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |              |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |              |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |              |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |              |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |              |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |              |
|          | Other observed interior nonstructural falling hazard:   |     | x  |              |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 10636 NE Prescott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Parkrose Maintenance Facility

Use: \_\_\_\_\_

Latitude: 45.5550043 Longitude: -122.5529517

Ss: 0.628 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1955 EST

Total Floor Area (sq. ft.): 7,600 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: 1965

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| C1                                       |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| <b>Basic Score</b>                       |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.7     | -0.1    | -0.5         | -0.3     | -0.5 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> -0.6 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**B HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|   |  |   |                                    |
|---|--|---|------------------------------------|
| <b>Bldg Name:</b> Parkrose Maintenance Facility | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i> |                                    |
| <b> Screener:</b> KNT                           | <b>Level 1 Irregularity Modifiers:</b>     | Vertical Irregularity, $V_{L1} = 0$           | Plan Irregularity, $P_{L1} = -0.6$ |
| <b>Date/Time:</b> 8/16/2021                     | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.1$       |                                    |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals |
|---------------------------------|---|---|-----------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2      |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3      |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6      |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2      |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2      |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9      |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5      |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0      |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5      |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3      |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5      |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5      |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |           |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | <u>-1.0</u>   |           |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |           |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | <u>-0.7</u>   |           |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |           |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |           |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |           |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |           |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |           |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |           |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | -1.0      |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0      |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5      |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |           |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |           |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |           |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |           |
| URM                             | Gable walls are present.  | -0.4  |           |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |           |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |           |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -0.7$   
(Cap at -1.1)

$M = 0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN} = -0.6$**  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**



SKETCH

Address: 10636 NE Prescott St.  
Portland, OR Zip: 97220

Other Identifiers: \_\_\_\_\_

Building Name: Parkrose Maintenance Facility - Garage and Storage

Use: \_\_\_\_\_

Latitude: 45.5550043 Longitude: -122.5529517

Ss: 0.628 Sr: 0.270

Screeener(s): KNT Date/Time: 8/16/2021

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1965 EST

Total Floor Area (sq. ft.): 7,700 Code Year: Unknown

Additions:  None  Yes, Year(s) Built: \_\_\_\_\_

Occupancy: Assembly Commercial Emer. Services  Historic  Shelter  
Industrial Office School  Government  
Utility Warehouse Residential, # Units: \_\_\_\_\_

Soil Type:  A  B  C  D  E  F  DNK  
Hard Avg Dense Stiff Soft Poor  
Rock Rock Soil Soil Soil Soil  
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency:  Pounding  Falling Hazards from Taller Adjacent Building

Irregularities:  Vertical (type/severity) \_\_\_\_\_  
 Plan (type) \_\_\_\_\_

Exterior Falling Hazards:  Unbraced Chimneys  Heavy Cladding or Heavy Veneer  
 Parapets  Appendages  
 Other: \_\_\_\_\_

COMMENTS:

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE,  $S_{L1}$

| FEMA BUILDING TYPE                       | DoNot Know | W1   | W1A  | W2   | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2  | RM1 (FD) | RM2 (RD) | URM  | MH   |
|--|------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|------|
| C1                                       |            |      |      |      |          |         |         |            |              |          |         |              |          |      |          |          |      |      |
| <b>Basic Score</b>                       |            | 3.6  | 3.2  | 2.9  | 2.1      | 2.0     | 2.6     | 2.0        | 1.7          | 1.5      | 2.0     | 1.2          | 1.6      | 1.4  | 1.7      | 1.7      | 1.0  | 1.5  |
| Severe Vertical Irregularity, $V_{L1}$   |            | -1.2 | -1.2 | -1.2 | -1.0     | -1.0    | -1.1    | -1.0       | -0.8         | -0.9     | -1.0    | -0.7         | -1.0     | -0.9 | -0.9     | -0.9     | -0.7 | NA   |
| Moderate Vertical Irregularity, $V_{L1}$ |            | -0.7 | -0.7 | -0.7 | -0.6     | -0.6    | -0.7    | -0.6       | -0.5         | -0.5     | -0.6    | -0.4         | -0.6     | -0.5 | -0.5     | -0.5     | -0.4 | NA   |
| Plan Irregularity, $P_{L1}$              |            | -1.1 | -1.0 | -1.0 | -0.8     | -0.7    | -0.9    | -0.7       | -0.6         | -0.6     | -0.8    | -0.5         | -0.7     | -0.6 | -0.7     | -0.7     | -0.4 | NA   |
| Pre-Code                                 |            | -1.1 | -1.0 | -0.9 | -0.6     | -0.6    | -0.8    | -0.6       | -0.2         | -0.7     | -0.1    | -0.5         | -0.3     | -0.5 | -0.5     | -0.5     | 0.0  | -0.1 |
| Post-Benchmark                           |            | 1.6  | 1.9  | 2.2  | 1.4      | 1.4     | 1.1     | 1.9        | NA           | 1.9      | 2.1     | NA           | 2.0      | 2.4  | 2.1      | 2.1      | NA   | 1.2  |
| Soil Type A or B                         |            | 0.1  | 0.3  | 0.5  | 0.4      | 0.6     | 0.1     | 0.6        | 0.5          | 0.4      | 0.5     | 0.3          | 0.6      | 0.4  | 0.5      | 0.5      | 0.3  | 0.3  |
| Soil Type E (1-3 stories)                |            | 0.2  | 0.2  | 0.1  | -0.2     | -0.4    | 0.2     | -0.1       | -0.4         | 0.0      | 0.0     | -0.2         | -0.3     | -0.1 | -0.1     | -0.1     | -0.2 | -0.4 |
| Soil Type E (> 3 stories)                |            | -0.3 | -0.6 | -0.9 | -0.6     | -0.6    | NA      | -0.6       | -0.4         | -0.5     | -0.7    | -0.3         | NA       | -0.4 | -0.5     | -0.6     | -0.2 | NA   |
| Minimum Score, $S_{MIN}$                 |            | 1.1  | 0.9  | 0.7  | 0.5      | 0.5     | 0.6     | 0.5        | 0.5          | 0.3      | 0.3     | 0.3          | 0.2      | 0.2  | 0.3      | 0.3      | 0.2  | 1.0  |

FINAL LEVEL 1 SCORE,  $S_{L1} \geq S_{MIN}$ : 0.5

|  |   |   |
|--|---|---|
| <p><b>EXTENT OF REVIEW</b></p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial<br/>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered<br/>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br/>Soil Type Source: Assumed<br/>Geologic Hazards Source: DOGAMI<br/>Contact Person: _____</p> <p><b>LEVEL 2 SCREENING PERFORMED?</b></p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, <math>S_{L2}</math> -1.6 <input type="checkbox"/> No<br/>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> | <p><b>OTHER HAZARDS</b></p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless <math>S_{L2} &gt;</math> cut-off, if known)<br/><input type="checkbox"/> Falling hazards from taller adjacent building<br/><input type="checkbox"/> Geologic hazards or Soil Type F<br/><input type="checkbox"/> Significant damage/deterioration to the structural system</p> | <p><b>ACTION REQUIRED</b></p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building<br/><input type="checkbox"/> Yes, score less than cut-off<br/><input type="checkbox"/> Yes, other hazards present<br/><input checked="" type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated<br/><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary<br/><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p> |
|--|---|---|

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm  
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

# Rapid Visual Screening of Buildings for Potential Seismic Hazards

Level 2 (Optional)

FEMA P-154 Data Collection Form

**C HIGH Seismicity**

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

|  |  |   |  |
|--|--|---|--|
| <b>Bldg Name:</b> Parkrose Maintenance Facility - Garage and Storage | <b>Final Level 1 Score:</b> $S_{L1} = 0.5$ | <i>(do not consider <math>S_{MIN}</math>)</i>         |  |
| <b> Screener:</b> KNT  | <b>Level 1 Irregularity Modifiers:</b>     | <i>Vertical Irregularity, <math>V_{L1} = 0</math></i> | <i>Plan Irregularity, <math>P_{L1} = -0.6</math></i> |
| <b>Date/Time:</b> 8/16/2021  | <b>ADJUSTED BASELINE SCORE:</b>            | $S' = (S_{L1} - V_{L1} - P_{L1}) = 1.1$               |  |

## STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

| Topic                           | Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)  | Yes   | Subtotals   |
|---------------------------------|---|---|-------------|
| Vertical Irregularity, $V_{L2}$ | Sloping Site  | W1 building: There is at least a full story grade change from one side of the building to the other.  | -1.2        |
|                                 |   | Non-W1 building: There is at least a full story grade change from one side of the building to the other.  | -0.3        |
|                                 | Weak and/or Soft Story (circle one maximum)   | W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.   | -0.6        |
|                                 |   | W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum). | -1.2        |
|                                 |   | W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.  | -1.2        |
|                                 |   | Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.   | -0.9        |
|                                 |   | Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.                                       | -0.5        |
|                                 | Setback   | Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.   | -1.0        |
|                                 |   | Vertical elements of the lateral system at upper stories are inboard of those at lower stories.   | -0.5        |
|                                 |   | There is an in-plane offset of the lateral elements that is greater than the length of the elements.  | -0.3        |
|                                 | Short Column/ Pier  | C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.                                | -0.5        |
|                                 |   | C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.  | -0.5        |
| Split Level                     | There is a split level at one of the floor levels or at the roof.   | -0.5  |             |
| Other Irregularity              | There is another observable severe vertical irregularity that obviously affects the building's seismic performance.   | <u>-1.0</u>   |             |
|                                 | There is another observable moderate vertical irregularity that may affect the building's seismic performance.  | -0.5  |             |
| Plan Irregularity, $P_{L2}$     | Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.) | <u>-0.7</u>   |             |
|                                 | Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.   | -0.4  |             |
|                                 | Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.  | -0.4  |             |
|                                 | Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.   | -0.2  |             |
|                                 | C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.  | -0.4  |             |
|                                 | Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.  | -0.7  |             |
| Redundancy                      | The building has at least two bays of lateral elements on each side of the building in each direction.  | +0.3  |             |
| Pounding                        | Building is separated from an adjacent structure by less than 1% of the height of the shorter of the building and adjacent structure and:   | The floors do not align vertically within 2 feet. (Cap total)   | <u>-1.0</u> |
|                                 |   | One building is 2 or more stories taller than the other. (pounding)   | -1.0        |
|                                 |   | The building is at the end of the block. (modifiers at -1.2)  | -0.5        |
| S2 Building                     | "K" bracing geometry is visible.  | -1.0  |             |
| C1 Building                     | Flat plate serves as the beam in the moment frame.  | -0.4  |             |
| PC1/RM1 Bldg                    | There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)                 | +0.3  |             |
| PC1/RM1 Bldg                    | The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).  | +0.3  |             |
| URM                             | Gable walls are present.  | -0.4  |             |
| MH                              | There is a supplemental seismic bracing system provided between the carriage and the ground.  | +1.2  |             |
| Retrofit                        | Comprehensive seismic retrofit is visible or known from drawings.   | +1.4  |             |

$V_{L2} = -1.0$   
(Cap at -1.2)

$P_{L2} = -0.7$   
(Cap at -1.1)

$M = -1.0$

**FINAL LEVEL 2 SCORE,  $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$ .**  $S_{L2} = 1.1 - 1.0 - 0.7 - 1.0 = -1.6$  (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance:  Yes  No  
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

## OBSERVABLE NONSTRUCTURAL HAZARDS

| Location | Statement (Check "Yes" or "No")   | Yes | No | Comment |
|----------|---|-----|----|---------|
| Exterior | There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.         |     | x  |         |
|          | There is heavy cladding or heavy veneer.  |     | x  |         |
|          | There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported. |     | x  |         |
|          | There is an unreinforced masonry appendage over exit doors or pedestrian walkways.                  |     | x  |         |
|          | There is a sign posted on the building that indicates hazardous materials are present.              |     | x  |         |
|          | There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney. |     | x  |         |
| Interior | Other observed exterior nonstructural falling hazard:   |     | x  |         |
|          | There are hollow clay tile or brick partitions at any stair or exit corridor.                       |     | x  |         |
|          | Other observed interior nonstructural falling hazard:   |     | x  |         |

**Estimated Nonstructural Seismic Performance** (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

**Comments:**

# APPENDIX B

## FACILITY CONDITION ASSESSMENT

## MECHANICAL ELECTRICAL PLUMBING



# Parkrose School District Facility MEP Assessment Report

Prepared for

Parkrose SD &  
Soderstrom Architects

Presented by

Ameresco, Inc.

September 3, 2021

## Contents

|  |    |
|--|----|
| <b>General</b> .....                             | 3  |
| <b>Facility MEP Assessment</b> .....             | 5  |
| <b>#1 --- Prescott Elementary School</b> .....   | 5  |
| <b>#2 --- Russell Elementary School</b> .....    | 10 |
| <b>#3 --- Sacramento Elementary School</b> ..... | 15 |
| <b>#4 --- Shaver Elementary School</b> .....     | 19 |
| <b>#5 --- Parkrose Middle School</b> .....       | 24 |
| <b>#6 --- Parkrose High School</b> .....         | 29 |
| <b>#7 --- Sumner Elementary School</b> .....     | 35 |
| <b>#8 --- Wheatley Elementary School</b> .....   | 39 |
| <b>#9 --- Knott Elementary School</b> .....      | 44 |
| <b>#10 --- District Admin/Maintenance</b> .....  | 48 |

"Page content is subject to Confidentiality Restrictions"



## General

The Parkrose School District began in 1885 and it's been serving the neighborhood in the northeast section of Portland for more than 135 years. The district currently has nine (9) schools and a district admin/maintenance building complex, which gives a total building area of approximately 707,400 sq.ft. The nine (9) schools include four (4) elementary schools (K-5), one (1) middle school (6-8), one (1) high school (9-12) and three (3) that used to be elementary schools that are now leased buildings.

Ameresco, along with Soderstrom Architects and ZCS Engineering & Architecture, conducted a walk-through of ten (10) facilities in July 2021 to assess facility conditions. This assessment report is limited to documents, readily visible portions of facility MEP systems, and notes based on interviews with District/facility staff during site walk-throughs. This resulting report identifies noted deficiencies and recommended upgrades. All schools were not in session at the time of the visit due to summer break.

| #  | School Name                            | Grades Served | Year Built | Additions              | Building Area | Address                                     |
|----|--|---------------|------------|------------------------|---------------|---|
| 01 | Prescott Elementary School             | K-5           | 1947       | 1959, 1996, 2014       | 48,544 SF     | 10410 NE Prescott St., Portland, OR 97220   |
| 02 | Russell Elementary School              | K-5           | 1963       | 1996, 2013             | 40,036 SF     | 2700 NE 127th Ave., Portland, OR 97230      |
| 03 | Sacramento Elementary School           | K-5           | 1960       | 1960, 1980, 1996, 2013 | 41,107 SF     | 11400 NE Sacramento St., Portland, OR 97220 |
| 04 | Shaver Elementary School               | K-5           | 1963       | 1996, 2013             | 43,916 SF     | 3701 NE 131st Pl., Portland, OR 97230       |
| 05 | Parkrose Middle School                 | 6-8           | 2013       | N/A                    | 140,000 SF    | 11800 NE Shaver St., Portland, OR 97220     |
| 06 | Parkrose High School                   | 9-12          | 1996       | 1968 (FAB)             | 260,497 SF    | 12003 NE Shaver St., Portland, OR 97220     |
| 07 | Sumner Elementary / Helensview School* | N/A           | 1954       | 1968, 1996, 1998       | 40,000 SF     | 8678 NE Sumner St., Portland, OR 97220      |
| 08 | Thompson Elementary / Wheatley School* | N/A           | 1958       | Data Not Available     | 40,000 SF     | 14030 NE Sacramento St., Portland, OR 97230 |
| 09 | Knott Elementary / Knott Creek School* | N/A           | 1951       | N/A                    | 32,592 SF     | 11456 NE Knott St., Portland, OR 97220      |
| 10 | District Admin /Maintenance            | N/A           | 1955       | 1955, 1963             | 20,700 SF     | 10636 NE Prescott St., Portland, OR, 97220  |

\* District leased building

The following table shows a summary of items and priority for each school.

| School Name                            | HVAC                               |                                |                |                                  |                              |                 | Electrical                    |  | Plumbing   |                                 |                           |
|--|------------------------------------|--------------------------------|----------------|----------------------------------|------------------------------|-----------------|-------------------------------|--|--|---------------------------------|---------------------------|
|  | Replace existing old boiler system | Repair Condensing Unit/Chiller | Refurbish AHUs | AHU/HV/RTU/UV/ UH/FF Replacement | Test and retro-commissioning | Control upgrade | Replace old electrical panels | Lighting and lighting control retrofit | Replace water fixtures and water piping for the school | Replace existing old DHW heater | Add fire sprinkler system |
| Prescott Elementary School             |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Russell Elementary School              |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Sacramento Elementary School           |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Shaver Elementary School               |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Parkrose Middle School                 |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Parkrose High School                   |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Sumner Elementary / Helensview School* |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Thompson Elementary / Wheatley School* |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| Knott Elementary / Knott Creek School* |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
| District Admin /Maintenance            |                                    |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
|  | Priority                           |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |
|  | Recommended                        |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |

- AHU --- Air Handling Unit
- HV --- Heating Ventilating Unit
- RTU --- Rooftop Unit
- UV --- Unit Ventilator
- UH --- Unit Heater
- FF --- Forced-air Furnace
- DHW --- Domestic Hot Water

\*Page content is subject to Confidentiality Restrictions\*

## Facility MEP Assessment

The following assessment is limited to readily visible portions of facility MEP systems based on a walk through and interview with district/facility staff. At the end of each school's section, deficiencies and recommendations are identified along with estimated construction costs for improvements.

### #1 --- Prescott Elementary School

Prescott elementary school is located at 10410 NE Prescott St., Portland, OR 97220. The school was built in 1947 and it's had several renovations and additions since then. The current main school building is a partial two-story building and there is a separated stand-alone classroom building to the south side of the main building. The total area is approximately 48,544 sq.ft. The school includes classrooms, offices, library, computer room, gym, kitchen, multi-purpose room/cafeteria, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. The plumbing and water fixtures inside the buildings were upgraded in 2013, but the water piping system between the two buildings is still original.

There are two gas-fired tank type domestic hot water heaters to provide domestic hot water for the whole school. One is located in the main building boiler room, and it's a 100-gallon A.O. Smith gas-fired tank heater with 199,000 Btu/hr. of heating capacity that was installed in 2004; the other unit is a 60-gallon A.O. Smith gas-fired tank heater with 125,000 Btu/hr. of heating capacity that was installed in 2002.



"Page content is subject to Confidentiality Restrictions"

### HVAC

The whole HVAC system was upgraded in a 2013 renovation project. The main building currently has one central heating system that consists of three Aerco gas-fired condensing hot water boilers with an input heating capacity of 750,000 Btu/hr each.



There are two air handling units with heat recovery connected to a central heating loop to provide heating and ventilation for the gym and multi-purpose room. There are three heat recovery ventilators located in the attic to provide fresh air to the hallway, classrooms and offices. One gas-fired make-up air unit on the roof provides heat and ventilation for the kitchen space. The majority of the main building has a heating water radiator system connected to the central heating loop.



The main building has no central mechanical cooling system, but there are two mini-split units on the roof to provide cooling for the computer lab and IT room.



"Page content is subject to Confidentiality Restrictions"

The stand-alone classroom building is served by 10 packaged rooftop units (RTUs) that use gas-fired furnaces and DX cooling to provide space heating, cooling and ventilation. All units were installed in 2013 as part of the renovation project.



The HVAC control system was upgraded as part of the 2013 project. The main building has a Delta DDC control system that is tied into the district-wide BAS to control all the major HVAC equipment. The separate classroom building has stand-alone programmable thermostats that control the 10 RTUs.



## Fire Protection

The main elementary school building has a sprinkler system that receives routine testing and inspection.

## Electrical

### *Electrical Service & Distribution*

The school's main distribution panel is in the boiler room and was upgraded in 1987. It's a 1200 A 120/208 V three-phase 4-wire Siemens I-T-E switchboard that provides electrical service for the whole school. Most of the subpanels were upgraded as part of 2013 project and those observed in the walk through have enough space for current conditions.



*Lighting*

The school’s interior lighting is primarily 4’ T8 fluorescent lamp fixtures with standard electric ballasts. The majority of the spaces use manual wall switches to control the lights, but some occupancy sensors were noticed during the visit in the gym, cafeteria, computer lab and office spaces. There are also incandescent, CFLs and LEDs in certain places.

The exterior lighting is very minimal—there are fixtures over exterior doors and some wall mounts. They are a mixture of CFL and high-intensity discharge (HID) lamps. The current exterior lights are controlled by photocell sensors.

The interior and exterior lighting retrofit is recommended to make school lighting systems consistent/durable, increase student productivity, and reduce energy consumption.

*Communication & Security*

The elementary school has an old PA speaker system for operational communications. There was no two-way intercom noticed during the visit. The main office and classrooms have a Polycom IP phone system. The school is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering exterior and interior locations. The fire alarm system is a Honeywell system and covers the whole school building. Wi-Fi coverage appears to be complete throughout the building.



“Page content is subject to Confidentiality Restrictions”

## Recommendation and Estimated Construction Costs

### *Priority and Estimated Construction Costs*

- Interior and exterior lighting and lighting control retrofit to LED \$110,000
- Test and retro commissioning the existing HVAC system \$22,000

### *Recommended and Estimated Construction Costs*

- Control upgrade for classroom building \$75,000
- Replace old DHWs \$60,000
- Replace plumbing pipe between buildings \$55,000

"Page content is subject to Confidentiality Restrictions"

## #2 --- Russell Elementary School

Russell elementary school is located at 2700 NE 127<sup>th</sup> Ave., Portland, OR 97230. The school was built in 1963 and it's been through several renovations and additions since then. The latest major addition was to add a multi-purpose room in 2013. The current main school building is a single story building and the total area is approximately 40,036 sq.ft. The school includes classrooms, offices, library, computer room, kitchen, gym/cafeteria, multi-purpose room, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. The plumbing and water fixtures were upgraded in 2013 as part of a previous project.

There are a total of five (5) domestic hot water heaters to provide domestic hot water for the whole school. The major one is a 100-gallon Bradford gas-fired tank type heater with 199,999 Btu/hr. of heating capacity. It was installed in 2013 and is located in the kitchen area to serve the majority of the school's hot water. The other four (4) are tank type electric hot water heaters installed in 2013 to serve specific areas.



"Page content is subject to Confidentiality Restrictions"



## HVAC

There is one central heating system that consists of two Advanced Thermal Hydronics gas-fired condensing hot water boilers with an input heating capacity of 1.6 MMBTU each that were installed in 2013. New heating water pipe for whole school was installed at the same time.



The majority of the school uses hot water unit ventilators (UVs) to provide classroom/office heating and ventilation. There are two heating ventilating units (HVUs) in the gym attic space to provide the gym and kitchen heating and ventilation. The exterior entrances, corridor and restrooms use heating water radiators to maintain space temperature. All UVs, HVUs and radiators are original to the building and replacement is recommended. There is only one ceiling mount hot water fan coil unit that serves the office at the northeast corner of the school. As part of the 2013 project, a multi-purpose room and office space were added. A Mitsubishi split heat pump on the roof provides cooling and heating to the office space. Two 3.3 ton each Aermec reversible air/water heat pumps on the roof provide chilled/heating water to floor radiant panels for cooling and heating in the multi-purpose room. There is one air-to-air heat recovery unit on the roof to provide ventilation to the office and multi-purpose room.

The school has no central cooling system, but two mini split units were noticed on the roof to provide cooling for the computer lab and IT room.



"Page content is subject to Confidentiality Restrictions"



The HVAC control system was upgraded as part of the 2013 project. The school has a Delta DDC control system that is tied into the district-wide BAS to control all the major HVAC equipment.



### Fire Protection

The majority of the elementary school has a sprinkler system that is under routine testing and inspection. The 2013 multi-purpose area does not have a sprinkler system.

### Electrical

#### *Electrical Service & Distribution*

The majority of the electrical system was upgraded in 2013 and the new main distribution panel is in the boiler room. It is an 800 A 120/208 V three-phase 4-wire Siemens switchboard that provide electrical service for the whole school building. Most of the subpanels were upgraded as a part of projects in 1996 and 2013 and the panels observed in the building have enough space for current conditions.



"Page content is subject to Confidentiality Restrictions"

*Lighting*

The elementary school interior lighting is primarily 4’ T8 fluorescent lamp fixtures with standard electric ballasts. There are also incandescent, CFLs and LEDs in certain places. A majority of the school spaces use manual wall switches to control the lights but some occupancy sensors were noticed during the visit in the gym, cafeteria, offices and multi-purpose room. There is one Leviton lighting control system currently used to control hallway lights.

The exterior lighting is a mixture of CFL and high-intensity discharge (HID) lamps. Half of the exterior lights are controlled by photocell sensors. The other half are controlled by the same Leviton system that controls the hallway lights. The lighting for the parking lot could be improved by the addition of more light fixtures.

The interior and exterior lighting retrofit is recommended to make the school lighting systems consistent/durable, increase student productivity, and reduce energy consumption.

*Communication & Security*

The elementary school has an old PA speaker system for operational communications. There was no two-way intercom noticed during the visit. The main office and classrooms have a Polycom IP phone system. The school is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering exterior and interior locations. The fire alarm system is a Honeywell system and covers the whole school building. Wi-Fi coverage appears to be complete throughout the building.



"Page content is subject to Confidentiality Restrictions"



**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- |   |           |
|---|-----------|
| • Replace original UVs and HVs  | \$530,000 |
| • Interior and exterior lighting and lighting control retrofit to LED | \$90,000  |
| • Test and retro commissioning the existing HVAC system               | \$18,000  |

*Recommended and Estimated Construction Costs*

- |  |          |
|--|----------|
| • Add fire sprinkler system for multi-purpose room | \$40,000 |
|--|----------|

"Page content is subject to Confidentiality Restrictions"

### #3 --- Sacramento Elementary School

Sacramento Elementary School is located at 11400 NE Sacramento St., Portland, OR 97220. The school was built in 1960 and it's had several additions/renovations. The latest major mechanical, plumbing and control system renovation was in 2013 as part of a bond project. A new multi-purpose room was added as part of that project as well. The current school building is a single floor building, and its area is approximately 41,107 sq.ft. The school includes classrooms, offices, gym/cafeteria, library, multi-purpose room, restrooms, storage and mechanical/electrical rooms.



#### Plumbing

The school uses the city water and sewer system. The plumbing and water fixtures were upgraded in 2013 and the system is in good condition.

There are two gas-fired tank type domestic hot water heaters located in the boiler room to provide building hot water. One unit is a 100-gallon American Standard gas-fired tank heater with 199,000 Btu/hr. of heating capacity that was installed in 2009. The other unit is a 100-gallon Bradford gas-fired tank heater with 199,999 Btu/hr. of heating capacity that was installed in 2013.



#### HVAC

The school HVAC system was upgraded in 2013 as part of the bond project. There is one central heating system that contains two condensing gas-fired hot water boilers that were installed in 2013. Each boiler has 3 MMBTU of

input heating capacity that provides heating water to the majority of the building by using two heating water pumps with variable speed drive.



Most spaces are ventilated by fans distributing outside air via tunnels below the corridors to the rooms. Outside air is taken in via the roof and pre-heated with a hot water coil connected to the central heating loop. There is no make-up air unit for the kitchen area.

There are four types of systems to provide space heating. The first is heating water radiators for the corridor and some office spaces. The second is a ducted booster heating water unit in the tunnel that serves classrooms. The third is a heating water fan coil unit that serves the cafeteria and classrooms. The fourth is two packaged heat pump rooftop units that provide heating, cooling and ventilation for the main office (8 tons) and the multi-purpose room (13 tons with heat recovery).

In addition to the packaged heat pump units, there are two mini-split units on the roof to provide cooling for the IT/computer room. There is no central cooling system for the building.



"Page content is subject to Confidentiality Restrictions"



As part of the 2013 project, the control system was upgraded to a centralized Delta DDC system that controls all the major HVAC equipment.



## Fire Protection

The elementary school building has a sprinkler system that receives routine testing and inspection.

## Electrical

### *Electrical Service & Distribution*

The school electrical system was upgraded in 2013. There is one 800 A 120/208 V three-phase 4-wire main panelboard (Square D) in the boiler room that serves the whole school. Panels observed in the building have enough space for current conditions. Future expansion needs to be re-evaluated if the district wants to add cooling.

### *Lighting*

The interior lighting is primarily 4' T8 fluorescent lamp fixtures with standard electric ballasts. There are also CFLs and incandescent lights in certain places. There are a few occupancy sensors in common areas (cafeteria, multi-purpose room and storage room, etc.) to control the lights, but the majority of the lights are controlled manually.

The exterior lighting is a mixture of CFL, metal halide and high-pressure sodium fixtures, and is controlled by photocell sensors.

An interior and exterior lighting retrofit is recommended to make the school lighting system consistent/durable, increase student productivity, and reduce energy consumption.

### *Communication & Security*

The elementary school has an old PA speaker system for operational communications. There was no two-way intercom noticed during the visit. The main office and classrooms have a Polycom IP phone system. One old Lathem LTR6-384 time clock system was noticed during the visit. The school is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering exterior and interior locations. The fire alarm system was upgraded to a Honeywell Silent Knight system within the last few years. Wi-Fi coverage appears to be complete throughout the building.

"Page content is subject to Confidentiality Restrictions"



**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- |   |          |
|---|----------|
| • Interior and exterior lighting and lighting control retrofit to LED | \$95,000 |
| • Test and retro commissioning the existing HVAC system               | \$21,000 |

*Recommended and Estimated Construction Costs*

NA

"Page content is subject to Confidentiality Restrictions"



#### #4 --- Shaver Elementary School

Shaver elementary school is located at 3701 NE 131<sup>st</sup> Pl., Portland, OR 97230. The school was built in 1963 and has had several renovations and additions. Similar to Russell elementary school, the latest major addition for Shaver elementary school was to add a multi-purpose room in 2013. The main school building is a single story building (north wing and south wing) and its total area is approximately 43,916 sq.ft. The school includes classrooms, offices, library, computer room, kitchen, gym/cafeteria, multi-purpose room, restrooms, storage, and mechanical/electrical rooms.



#### Plumbing

The school uses the city water and sewer system. The plumbing and water fixtures were upgraded in 2013 as part of a previous project. There was a water leak between the main water supply and boiler room at the parking lot to the northeast of the main building that was fixed a few years ago.

There are three domestic hot water heaters to provide domestic hot water for the school. The major one is a 100-gallon A.O. Smith gas-fired tank type heater with 199,000 Btu/hr. of heating capacity installed in 2003. It is located in the boiler room and provides hot water for the kitchen and north wing of the school. One 80-gallon A.O. Smith electric tank type heater with 3 kW of heating capacity was installed in 2013 and is located in a custodial room. It provides hot water for the south wing. One 30-gallon Bradford electric tank type heater with 4.5 kW of heating capacity was installed in 2013. It provides hot water for the new multi-purpose room.



"Page content is subject to Confidentiality Restrictions"

## HVAC

There is one central heating system that consists of two Aerco gas-fired condensing hot water boilers with an input heating capacity of 1.5 MMBTU each that were installed in 2013. They provide heating for the majority of the school.



There is one dual duct (DD) air handling unit (AHU) located in the boiler room to distribute air via tunnels below corridors to dual duct terminal units serving the majority of the school. The AHU pulls in outside air through a sidewall louver and return air is routed below ground in tunnels back to the AHU. Relief air is provided via relief hoods at each classroom. There are two tunnel systems per wing.

The main office area uses two heat pump furnaces installed in 2014 to provide space heating, cooling and ventilation. An electric cadet heater provides heat for the main entrance area. It was also installed in 2014.

A Mitsubishi split heat pump on the roof provides cooling and heating to the multi-purpose office space. There are two 3.3 ton Aermec reversible air/water heat pumps on the roof to provide chilled/heating water to radiant panels in the floor of the multi-purpose room for space cooling and heating. An air-to-air heat recovery unit on the roof provides ventilation to the office and multi-purpose room.

The school has no central cooling system, but a mini-split unit provides cooling for an IT closet.





The majority of the HVAC control system was upgraded as part of the 2013 project. The school has a Delta DDC control system that is tied into the district-wide BAS to control all the major HVAC equipment. The two heat pump furnaces are controlled by stand-alone programmable thermostats with the BAS only monitoring space temperature.



## Fire Protection

The majority of the school has a sprinkler system that is under routine testing and inspection. The 2013 multi-purpose area does not have a sprinkler system.

## Electrical

### *Electrical Service & Distribution*

The majority of the electrical system was upgraded in 2013/2014 and the new main distribution panel is in the boiler room. It is a 600 A 120/208 V three-phase 4-wire Eaton panelboard that provides electrical service for the whole school building. Most of the subpanels were upgraded as part of projects in 1996 and 2013/2014. The panels observed in the building have enough space for current conditions.

A solar PV system was installed on the multi-purpose room roof in 2013 to provide renewable energy.



### Lighting

The interior lighting is primarily 4' and 8' T8 fluorescent lamp fixtures with standard electric ballasts. There are also incandescent, CFLs and LEDs in certain places. A majority of the school spaces use manual wall switches to control the lights but there are some occupancy sensors in the gym/cafeteria, offices and multi-purpose room.

The exterior lighting is a mixture of CFL and high-intensity discharge (HID) lamps. The exterior lighting is controlled by photocell sensors. The lighting for the parking lot could be improved by the addition of more light fixtures.

The interior and exterior lighting retrofit is recommended to make school lighting systems consistent/durable, increase student productivity, and reduce energy consumption.

### Communication & Security

The elementary school has an old PA speaker system for operational communications. There was no two-way intercom noticed during the visit. The main office and classrooms have a Polycom IP phone system. The school is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering exterior and interior locations. The fire alarm system is a Honeywell system that covers the whole school building. Wi-Fi coverage appears to be complete throughout the building.



"Page content is subject to Confidentiality Restrictions"



## Recommendation and Estimated Construction Costs

### *Priority and Estimated Construction Costs*

- |   |           |
|---|-----------|
| • Refurbish existing AHU  | \$80,000  |
| • Test and retro commissioning the HVAC system                        | \$30,000  |
| • Replace old electrical panels                                       | \$65,000  |
| • Interior and exterior lighting and lighting control retrofit to LED | \$100,000 |

### *Recommended and Estimated Construction Costs*

- |  |          |
|--|----------|
| • Replace old NG DHW                               | \$30,000 |
| • Add fire sprinkler system for multi-purpose room | \$40,000 |

"Page content is subject to Confidentiality Restrictions"

## #5 --- Parkrose Middle School

Parkrose Middle School is located at 11800 NE Shaver St., Portland, OR 97220. The school was built in 2014 to replace the original middle school that was built in 1962. The new middle school is a two-story building except at the northeast corner, which is just one-story and houses the IT department office and boiler/main electrical room. The school's total area is approximately 140,000 sq.ft. It includes classrooms, offices, library, computer room, kitchen, gyms, cafeteria, district IT department, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. Overall, the plumbing system is in good condition.

The school has four gas-fired hot water heaters to provide domestic hot water for the whole building. The heaters are located in two different mechanical rooms and each location has two units. Two heaters are in the boiler room and are 100-gallon A.O. Smith gas-fired tank type heaters with 150,000 Btu/hr. of heating capacity each. They were installed in 2014 and provide hot water for classrooms. The other two heaters are located in a mechanical room in the kitchen area and are 100-gallon A.O. Smith gas-fired tank type heaters with 199,900 Btu/hr. of heating capacity each. They were installed in 2014 and provide hot water for the kitchen and gym.



"Page content is subject to Confidentiality Restrictions"

## HVAC

The middle school has one central heating system that consists of three HydroTherm gas-fired condensing hot water boilers with a heating input capacity of 1,999,999 BTU each that were installed in 2013 to provide heating for rooftop units (RTUs), air handling units (AHUs), radiators and terminal VAV box reheat coils.



The building has eight RTUs and three AHUs to provide heating, cooling and ventilation. Four RTUs, which have air-cooled DXs for cooling and hot water coils for heating, serve classroom sector A, classroom sector B, the arts/band area, and offices. Two RTUs, which have air source heat pumps and hot water coils, serve the media center/computer lab and the main gym. The last two RTUs serve the cafeteria and kitchen and have air source heat pumps for cooling and heating. Most of the units run as variable flow system and have terminal VAV boxes with hot water reheat coil. AHU#1 has a heating water coil and DX cooling connected to a 10-ton air-cooled condensing unit on the roof. It has terminal VAV boxes with HW reheat coils to serve the ground floor IT department. AHU#2 has a heating water coil and air-to-air heat exchanger serving the small gym area. AHU#3 has a heating water coil only to provide the locker rooms with heating and ventilation.

Heating water radiators are used to provide supplemental heat for corridors and perimeter room spaces.

The school does not have a central cooling system, but there are a few mini split units to serve IT rooms.



"Page content is subject to Confidentiality Restrictions"



The middle school has a Delta DDC control system installed in 2013 that is tied into the district-wide BAS to control all the major HVAC equipment.



**Fire Protection**

The school building has a sprinkler system that receives routine testing and inspection.

**Electrical**

*Electrical Service & Distribution*

The main electrical distribution panel is in the main electrical room right beside the boiler room. It is a 1,600 A 480/277 V three-phase 4-wire Square D panelboard that provide electrical service to transformers and subpanels for the whole school building. Overall, the existing electrical infrastructure is in good condition.

A solar PV system and a small wind turbine system were installed as part of the new middle school building project.

"Page content is subject to Confidentiality Restrictions"





There is one Cummins 85 kW natural gas-fired generator beside the main electrical room to provide the school with emergency power.



### Lighting

The interior lighting is primarily 4' T8 fluorescent lamp fixtures with standard electric ballasts. There are also CFLs and LEDs noticed in certain places. There is a lighting control system in place to control interior and exterior lights. Most of the classrooms, offices and common areas have occupancy sensors as part of the lighting control.

The exterior lighting is a mixture of CFL and high-intensity discharge (HID) lamps. The lighting control system, in addition to photocell sensors, control the exterior lights.

An interior and exterior lighting retrofit is recommended to make school lighting systems consistent/durable, increase student productivity, and reduce energy consumption.

### Communication & Security

The new middle school building has a Telecor all-in-one communication system that provides school intercom and clock services. The school is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering exterior and interior locations. The fire alarm system is a Honeywell system serving the whole school building. Wi-Fi coverage appears to be complete throughout the building.

"Page content is subject to Confidentiality Restrictions"



**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- Interior and exterior lighting and lighting control retrofit to LED \$215,000
- Test and retro commissioning the existing HVAC system \$64,000

*Recommended and Estimated Construction Costs*

NA

"Page content is subject to Confidentiality Restrictions"

## #6 --- Parkrose High School

Parkrose High School is located at 12003 NE Shaver St., Portland, OR 97220. The school was built in 1996 to replace the original high school building. There is one old stand-alone fine arts building, which was built in 1968, to the northwest of the main building. The main high school is a two-story building and the fine arts is a one-story building. The school's total area is approximately 260,497 sq.ft. The school includes classrooms, offices, library, computer room, kitchen, gym, cafeteria, indoor swimming pool, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. The existing irrigation system has leak issues, but the plumbing system is in fair condition overall.

The main school building has two gas-fired hot water heaters to provide domestic hot water. The heaters are located in the main building boiler room with one 400-gallon and one 600-gallon storage tanks. The smaller heater is an A.O. Smith gas-fired heater with 720,000 Btu/hr. of heating capacity installed in 1996. The other heater is an A.O. Smith gas-fired heater with 1,480,000 Btu/hr. of heating capacity installed in 1996. Both units are in fair condition, but they are beyond their expectancy life.

The stand-alone fine arts building has one 80-gallon tank type electric heater with 3.38 kW of heating capacity installed in 1998. It is recommended that unit be replaced.



"Page content is subject to Confidentiality Restrictions"

There is an indoor swimming pool that uses one HydroTherm gas-fired condensing boiler to heat pool water with an input heating capacity of 1.0 MMBTU. It was installed in the early 2010s. The school is looking at replacing this boiler with a new one due to corrosion of the heat exchanger.



## HVAC

The main school building has one central heating system that consists of two Bryan gas-fired hot water boilers with input heating capacities of 7 MMBTU and 4.5 MMBTU. They were installed in 1996 to provide heating for coils in fan systems, radiators and terminal VAV box reheat coils.



The main building has 18 rooftop units (RTUs) installed between 1996 and 1997, but the unit that serves the indoor pool was replaced 12 years ago. They provide space heating, cooling and ventilation. Eight RTUs have gas-fired furnaces as heating source. Seven RTUs are constant volume units and the other 11 RTUs are variable volume that use inlet guide vanes to modulate air flow based on space load. Those 11 VAV RTUs have terminal VAV boxes with hot water reheat coils connected to the central heating system. The district is working with a contractor to replace the existing inlet guide vanes with VFDs to provide better flow control and save energy. Only 14 out of the 18 units have cooling capacity. The RTUs that serve the student center, kitchen and weight lost cooling capacity due to compressor issues. The remote air-cooled condensing unit to cool and dehumidify supply air currently is not working.

The kitchen has two make-up air units with gas-furnaces to provide the kitchen area with ventilation and heat.

The school does not have a central cooling system, but there are a few mini-split units to serve IT rooms.



The fine arts building has five packaged rooftop units with gas-fired furnaces and DX cooling that were installed in 2009 to provide building heating, cooling and ventilation.



"Page content is subject to Confidentiality Restrictions"

The main HS building uses an Alerton electric control system to control all major HVAC equipment. The school district is working with a controls contractor to upgrade the controls to a Delta DDC system and the new DDC system will be tied into the district-wide BAS.

The fine arts building uses five stand-alone programmable thermostats to control the existing RTUs.

It is recommended to replace the RTUs with high efficiency models as they are beyond their useful life, but the district could refurbish them and repair the failed cooling sections as a more economical option.



## Fire Protection

The main school building has a sprinkler system that receives routine testing and inspection. No sprinkler system was noticed for the fine arts building.

## Electrical

### *Electrical Service & Distribution*

The main electrical distribution panel is in the main electrical room beside the boiler room and it is a 4,000 A 480/277 V three-phase 4-wire Siemens switchboard that provides electrical service to transformers and subpanels for the whole school building. Overall, the existing electrical infrastructure is in good condition.



There is one Kohler 50 kW diesel fired generator outside the main electrical room to provide the school emergency power.



*Lighting*

The interior lighting is primarily 4' T8 fluorescent lamp fixtures with standard electric ballasts. There are also CFLs and LEDs noticed in certain places. There is a lighting control system in place to control interior and exterior lights.

The exterior lighting is a mixture of CFL and high-intensity discharge (HID) lamps. The lighting control system, in addition to photocell sensors, controls the exterior lights.

An interior and exterior lighting retrofit is recommended to make the school lighting systems consistent/durable, increase student productivity, and reduce energy consumption.



*Communication & Security*

The school uses a Peavey PZS 80 with Simplex as the PA and clock system for the whole school. There was no intercom system noticed during the site visit. The school is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering exterior and interior locations. The fire alarm system is a Honeywell system for the whole school building. Wi-Fi coverage appears to be complete throughout the building.

"Page content is subject to Confidentiality Restrictions"



## Recommendation and Estimated Construction Costs

### *Priority and Estimated Construction Costs*

- |   |             |
|---|-------------|
| • Replace indoor pool boiler  | \$75,000    |
| • Repair condensing unit for pool unit                                | \$50,000    |
| • Old RTU replacement for main building                               | \$3,200,000 |
| • Interior and exterior lighting and lighting control retrofit to LED | \$500,000   |
| • Test and retro commissioning the HVAC system                        | \$85,000    |

### *Recommended and Estimated Construction Costs*

- |  |           |
|--|-----------|
| • Replace old DHWs                       | \$120,000 |
| • Repair irrigation piping               | \$35,000  |
| • Control upgrade for fine arts building | \$105,000 |

"Page content is subject to Confidentiality Restrictions"



## #7 --- Sumner Elementary School

Sumner/Helensview Elementary school is located at 8678 NE Sumner St., Portland, OR 97220. The school was built in 1954 and has had several renovations and additions since then. The building is a single floor and the total area is approximately 40,000 sq.ft. This school is currently used as a leased facility. The building includes classrooms, offices, library, computer lab, kitchen/cafeteria, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. Most of the plumbing fixtures are original with high water usage. Overall, the plumbing system is old and replacement is recommended.

There is one gas-fired State Industries 100-gallon tank type domestic hot water heater located in the boiler room that was installed in 1994 with a heating capacity of 199,990 Btu/hr. This unit is beyond its useful life expectancy and is recommended to be replaced with a new unit.




### HVAC

There is one central heating system for the majority of the building that consists of one original gas-fired low pressure steam boiler located in the boiler room. Steam is used directly in fan systems and fin tube radiators. In addition, there is a steam-to-hot water converter in the boiler room to provide heating hot water to floor radiant

"Page content is subject to Confidentiality Restrictions"

panels, but the district maintenance team reports there were some leaking issues in the system so it was shut off. Therefore, some of the spaces do not have floor heating to maintain space heating setpoint during peak winter season. The main office area is served by steam radiators. A heating system replacement is recommended.



Most spaces are ventilated by a fan distributing outside air via tunnels below corridors to rooms. Outside air is taken in via a roof head and pre-heated with a steam coil. Most of the classrooms have ducted booster coils to reheat outside air before it goes into each space. The multi-purpose room is heated and ventilated by a fan coil unit with a steam coil. The school upgraded the kitchen system within the last few years with a new RTU as the make-up air unit.

There is no central cooling system for the building, but some portable ACs were noticed during the visit.



The majority of the existing control system is the original pneumatic system, and it appears minimal Honeywell electronic controls were installed in the 1996 upgrade to provide scheduling control. Some local thermostats are in disrepair. Overall, the control system is in poor condition and a new DDC control system upgrade is recommended in addition to the mechanical system replacement.

"Page content is subject to Confidentiality Restrictions"



### Fire Protection

The elementary school building has a sprinkler system that receives routine testing and inspection

### Electrical

#### *Electrical Service & Distribution*

The main electrical panelboard is located in the boiler room and was replaced in the 1996 renovation project. The current distribution panel is 800 A 208/120 V three-phase 4-wire panelboard (Square D). There are some old electrical panels that were noticed during the visit, but overall the power infrastructure is sufficient to support the current building condition.



### *Lighting*

The interior lighting is primarily 4' T8 fluorescent lamp fixtures with standard electric ballasts and they are controlled by switches. There are also CFLs and incandescent lights in certain places.

The exterior lighting is a mixture of fluorescent, CFL and metal halide fixtures. Most of the exterior lights are controlled by photocell sensors. The lighting for the parking lot could be improved by the addition of more light fixtures.

"Page content is subject to Confidentiality Restrictions"

An interior and exterior lighting retrofit is recommended to make the school lighting system consistent/durable, increase student productivity, and reduce energy consumption.

*Communication & Security*

No intercom/clock system was observed during the walk through. Only one old PA system was noticed and it is not clear whether the system is functional; building tenants use two-way radios to communicate. The building is served by an extensive Sonitrol security system that includes sensors and cameras covering interior and exterior locations. The building uses a Notifier fire system that was upgraded within the last few years. Wi-Fi coverage appears to be complete throughout the building.



**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- Upgrade boiler and heating system \$800,000
- Replace old HVs and coil heaters \$550,000
- Upgrade existing control system \$300,000
- Test and retro commissioning the HVAC system \$22,000
- Replace old electrical panels \$100,000
- Interior and exterior lighting and lighting control retrofit to LED \$90,000
- Replace water fixtures and water piping \$240,000

*Recommended and Estimated Construction Costs*

- Replace existing DHW \$30,000

"Page content is subject to Confidentiality Restrictions"

## #8 --- Wheatley Elementary School

Wheatley/Thompson Elementary school is located at 14030 NE Sacramento St., Portland, OR 97230. The school was built in 1958 as a single floor building and the total area is approximately 40,000 sq.ft. This school is currently used as a leased facility and Multnomah Education Service District uses this building to provide a learning community that fosters academic and vocational growth for students ages K-21. The building includes classrooms, offices, library, computer lab, kitchen, multi-propose room, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. Most of the plumbing fixtures are original with high water usage. The water from the tap flows dusty yellow, which indicates that the existing plumbing piping system is corroded. A plumbing system replacement is recommended.



There is one gas-fired Reliance 100-gallon tank type domestic hot water heater located in the boiler room that was installed in 2019 with a heating capacity of 199,000 Btu/hr.



### HVAC

There is one central heating system for the majority of the building that consists of one original Birchfield gas-fired low pressure steam boiler located in the boiler room. Steam is used directly for coils in fan systems and fin tube radiators. The steam is also converted to heating water in the boiler room with a heat converter and pumped to floor radiant panels. Per the district maintenance team, there were some leaking issues in the floor radiant panels so those heating water loops were shut off for certain locations. Therefore, some of the spaces do not have floor heating to help maintain space heating setpoints during peak winter season. A heating system replacement is recommended.



Most spaces are ventilated by a fan distributing outside air via tunnels below corridors to rooms. Outside air is taken in via a sidewall louver and is pre-heated with a steam coil. Most of the classrooms have ducted booster coils to reheat outside air before it goes into each space. The gym area is heated and ventilated by a fan coil unit with a steam coil. Kitchen hood make-up air is transferred from the multi-purpose room.

There is no central cooling system for the building, but window ACs were noticed during the visit for most of the classrooms and offices.



"Page content is subject to Confidentiality Restrictions"



The majority of the existing control system is the original pneumatic system and minimal electronic controls were installed for scheduling major equipment operation. All of the window ACs are controlled manually. Overall, the control system is in poor condition and a new DDC control system upgrade is recommended in addition to the mechanical system replacement.



### Fire Protection

The school building has no sprinkler system.

### Electrical

#### *Electrical Service & Distribution*

The main electrical panelboard is located in the boiler room and is the original one. The current distribution panel (Square D) is 600 A 120/208 V three-phase 4 wire panelboard to provide electrical service for the whole building. There are some old electrical panels noticed during the visit. Overall, the power infrastructure is sufficient for current conditions but replacement of some of the old panels is recommended.

"Page content is subject to Confidentiality Restrictions"



*Lighting*

The interior lighting is primarily 4’ T8 fluorescent lamp fixtures with standard electronic ballasts. There are also CFLs and incandescent lights in certain places. It appears interior lights are controlled by manual switches.

The exterior lighting is a mixture of CFL and metal halide fixtures. Most of the exterior lights are controlled by photocell sensors. The lighting for the parking lot could be improved by the addition of more light fixtures.

An interior and exterior lighting retrofit is recommended to make the school lighting system consistent/durable, increase student productivity, and reduce energy consumption.

*Communication & Security*

There is one old time control system in place and it is not clear whether the system is functional. The main office and building tenants appear to use an intercom feature from the existing Polycom IP phone system. The building is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering interior and exterior locations. The building uses a Honeywell fire system. Wi-Fi coverage appears to be complete throughout the building.



**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- |                                     |           |
|-------------------------------------|-----------|
| • Upgrade boiler and heating system | \$800,000 |
| • Replace old HVs and coil heaters  | \$550,000 |
| • Upgrade existing control system   | \$300,000 |

"Page content is subject to Confidentiality Restrictions"



- Test and retro commissioning the HVAC system \$22,000
- Replace old electrical panels \$140,000
- Interior and exterior lighting and lighting control retrofit to LED \$90,000
- Replace water fixtures and water piping \$270,000

*Recommended and Estimated Construction Costs*

- Add fire sprinkler system \$250,000

"Page content is subject to Confidentiality Restrictions"

## #9 --- Knott Elementary School

Knott Elementary school is located at 11456 NE Knott St., Portland, OR 97220. The school was built in 1951 and has had a few minor renovations. The building is a single floor and the total area is approximately 32,592 sq.ft. This school is currently used as a leased facility with Multnomah Education Service District using the building to provide educational programs for students aged K-21 on IEPs who have had persistent behavior challenges in school. The building includes classrooms, offices, library, computer lab, kitchen, restrooms, storage, and mechanical/electrical rooms.



### Plumbing

The school uses the city water and sewer system. Most of the plumbing fixtures are original with high water usage. Overall, the plumbing system is old and replacement is recommended.

There is one gas-fired State Industries 100-gallon tank type domestic hot water heater located in the boiler room that was installed in 1991 with a heating capacity of 199,990 Btu/hr. This unit is beyond its useful life expectancy and it is recommended to replace it with a new unit.



### HVAC

There is one central heating system for the majority of the building that consists of one original West Coast gas-fired low pressure steam boiler located in the boiler room. Steam is used directly for coils in fan systems and fin

"Page content is subject to Confidentiality Restrictions"

tube radiators. The steam is also converted to heating water in the boiler room with a heat converter and pumped to floor radiant panels. Per the district maintenance team, there were some leaking issues for floor radiant panels serving the south section of the school so the heating water loops were shut off to that section. Therefore, some of the spaces do not have floor heating to maintain space heating setpoints during peak winter season. A heating system replacement is recommended.



Most spaces are ventilated by a fan distributing outside air via tunnels below corridors to rooms. Outside air is taken in via a roof head and pre-heated with a steam coil. Most of the classrooms have ducted booster coils to reheat outside air before it goes into each space. The gym is heated and ventilated by a fan coil unit with a steam coil. Kitchen ventilation and hood make-up air were not observed during the visit.

There are two packaged units (gas-fired furnace and DX cooling) that were installed in 2018 to provide heating, cooling and ventilation for a couple classrooms at the northwest corner of the facility. They each have a cooling capacity of 3 tons and a heating capacity of 60,000 btu/hr.

There is no central cooling system for the building, but window ACs were noticed during the visit for some classrooms and offices.



The majority of the existing controls are an old electronic system that was upgraded in the 1990s, but most of the rooms use programmable thermostats to control their heating. All the window ACs are controlled manually. Overall, the control system is in poor condition and a new DDC control system upgrade is recommended in addition to the mechanical system replacement.

"Page content is subject to Confidentiality Restrictions"



## Fire Protection

The school building has no sprinkler system.

## Electrical

### *Electrical Service & Distribution*

The main electrical panelboard is located in the boiler room and is the original one. The current distribution panel is a 400 A 480 V three-phase panelboard working with local transformers to provide electrical service for the whole building. Some old electrical panels were noticed during the visit. Overall, the power infrastructure is sufficient for current conditions but replacement of the old panels is recommended.



### *Lighting*

The interior lighting is primarily 4' T8 & T12 fluorescent lamp fixtures with standard ballasts. There are also CFLs and incandescent lights in certain places. Only a few locations have occupancy sensors to control the lights; most of them are controlled by switches.

The exterior lighting is a mixture of CFL, HID and high pressure sodium fixtures. Most of the exterior lights are controlled by photocell sensors. The lighting for the parking lot could be improved by the addition of more light fixtures.

An interior and exterior lighting retrofit is recommended to make the school lighting system consistent/durable, increase student productivity, and reduce energy consumption.

### *Communication & Security*

There is one old intercom system but it is not clear whether the system is functional. The main office and building tenants appear to use the intercom feature from the existing Polycom IP phone system. The building is served by an extensive Sonitrol security system that includes sensors, card access, and cameras covering interior and exterior

locations. The building uses a Honeywell fire system that was upgraded within the last few years. Wi-Fi coverage appears to be complete throughout the building.



**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- Upgrade boiler and heating system \$680,000
- Replace old HVs and coil heaters \$450,000
- Upgrade existing control system \$240,000
- Test and retro commissioning the HVAC system \$18,000
- Replace old electrical panels \$110,000
- Interior and exterior lighting and lighting control retrofit to LED \$75,000
- Replace water fixtures and water piping \$200,000

*Recommended and Estimated Construction Costs*

- Replace existing DHW \$30,000
- Add fire sprinkler system \$210,000

"Page content is subject to Confidentiality Restrictions"

## #10 --- District Admin/Maintenance

The Parkrose School District admin/maintenance office is located at 10636 NE Prescott St., Portland, OR 97220. The campus includes the district office, maintenance office, bus garage, bus shop, key shop and food warehouse buildings. They are all one floor buildings and were built between 1955 and 1963. The total building area is approximately 20,700 sq.ft.



### Plumbing

The buildings use the city water and sewer system. Most plumbing fixtures/system are original with high water consumption.

There is one gas-fired American Water Heater Company 40-gallon tank type domestic hot water heater located in the main administration building's mechanical room. It was installed in 1997 with a heating capacity of 34,000 Btu/hr. This unit is beyond its useful life expectancy and it is recommended to replace it with a new unit.

There is one gas-fired Rheem 40-gallon tank type domestic hot water heater located in the maintenance office work area that was installed in 2013 with a heating capacity of 38,000 Btu/hr.

The bus shop building has one tank type electric hot water heater and it appears the unit is beyond its useful life expectancy, so it is recommended to replace it with a new unit.



"Page content is subject to Confidentiality Restrictions"

## HVAC

There are four residential forced-air gas-fired furnaces equipped with split DX coils and condensing units. They are in the mechanical room and provide heating, cooling and ventilation for the district office building. They were installed in 2015. All four forced-air units are controlled by stand-alone programmable thermostats.

There is also one residential forced-air gas-fired furnace equipped with a split DX coil and condensing unit to provide heating, cooling and ventilation for maintenance office spaces. This unit is controlled by a stand-alone programmable thermostat. The maintenance shop area has one gas-fired unit heater that was installed in 1995 and is controlled by a stand-alone thermostat.

The bus shop, food warehouse and key shop use three old gas-fired unit heaters to maintain space temperature and they are all controlled by stand-alone thermostats.



## Fire Protection

The buildings have no sprinkler systems.

## Electrical

### *Electrical Service & Distribution*

The master distribution panel is located in the main office building mechanical room and was upgraded in 2014. It is a 400 A 240/120 V three-phase four wire Emerson panel to provide electrical service for the whole campus. Some old electrical panels were noticed during the visit for the maintenance building, bus shop, food warehouse

"Page content is subject to Confidentiality Restrictions"

and key shop. Overall, the power infrastructure is sufficient for current conditions but replacement of the old panels is recommended.



*Lighting*

The majority of interior lighting for the campus is a mixture of 4’ T8 fluorescent lamp fixtures with standard electronic ballasts and 4’ T12 fluorescent lamp fixtures with standard magnetic ballasts. There are some CFLs and incandescent bulbs still in place. Some occupancy sensors are used in the district office building to control interior lights. The rest of the interior lights are controlled by manual switches.

The parking lot pole lights have been converted to LED and the majority of exterior lights attached to the buildings are either CFLs or high intensity discharge lights. Most of the exterior lights are controlled by photocell sensors.

*Communication & Security*

The campus uses a Sonitrol security system that includes sensors, card access, and cameras covering the majority of exterior locations. No fire system was noticed during the visit. Wi-Fi coverage appears to be complete throughout the campus.

**Recommendation and Estimated Construction Costs**

*Priority and Estimated Construction Costs*

- Test and retro commissioning the HVAC system \$12,000
- Interior and exterior lighting and lighting control retrofit to LED \$43,000

*Recommended and Estimated Construction Costs*

- Replace water fixtures and water piping \$135,000
- Replace existing DHW \$17,000
- Replace old furnace, split DX and gas unit heaters \$55,000
- Upgrade existing control system \$115,000
- Add fire sprinkler system \$130,000

"Page content is subject to Confidentiality Restrictions"



The following table shows the summary of estimated budget costs for each school improvements.

| Prescott Elementary School             | HVAC                               |                                |                |                                  |                              | Electrical      |                               |  | Plumbing   |                                 |                           | Total       |
|--|------------------------------------|--------------------------------|----------------|----------------------------------|------------------------------|-----------------|-------------------------------|--|--|---------------------------------|---------------------------|-------------|
|  | Replace existing old boiler system | Repair Condensing Unit/Chiller | Refurbish AHUs | AHU/HV/RTU/UV/ UH/FF Replacement | Test and retro-commissioning | Control upgrade | Replace old electrical panels | Lighting and lighting control retrofit | Replace water fixtures and water piping for the school | Replace existing old DHW heater | Add fire sprinkler system |             |
| Prescott Elementary School             |                                    |                                |                |                                  | \$ 22,000                    | \$ 75,000       |                               | \$ 110,000                             | \$ 55,000  | \$ 60,000                       |                           | \$ 322,000  |
| Russell Elementary School              |                                    |                                |                | \$ 530,000                       | \$ 18,000                    |                 |                               | \$ 90,000                              |  |                                 | \$ 40,000                 | \$ 678,000  |
| Sacramento Elementary School           |                                    |                                |                |                                  | \$ 21,000                    |                 |                               | \$ 95,000                              |  |                                 |                           | \$ 116,000  |
| Shaver Elementary School               |                                    |                                | \$ 80,000      |                                  | \$ 30,000                    |                 | \$ 65,000                     | \$ 100,000                             |  | \$ 30,000                       | \$ 40,000                 | \$ 345,000  |
| Parkrose Middle School                 |                                    |                                |                |                                  | \$ 64,000                    |                 |                               | \$ 215,000                             |  |                                 |                           | \$ 279,000  |
| Parkrose High School                   | \$ 75,000                          | \$ 50,000                      |                | \$ 3,200,000                     | \$ 85,000                    | \$ 105,000      |                               | \$ 500,000                             | \$ 35,000  | \$ 120,000                      |                           | \$4,170,000 |
| Sumner Elementary / Helensview School* | \$ 800,000                         |                                |                | \$ 550,000                       | \$ 22,000                    | \$ 300,000      | \$ 100,000                    | \$ 90,000                              | \$ 240,000   | \$ 30,000                       |                           | \$2,132,000 |
| Thompson Elementary / Wheatley School* | \$ 800,000                         |                                |                | \$ 550,000                       | \$ 22,000                    | \$ 300,000      | \$ 140,000                    | \$ 90,000                              | \$ 270,000   |                                 | \$ 250,000                | \$2,422,000 |
| Knott Elementary / Knott Creek School* | \$ 680,000                         |                                |                | \$ 450,000                       | \$ 18,000                    | \$ 240,000      | \$ 110,000                    | \$ 75,000                              | \$ 200,000   | \$ 30,000                       | \$ 210,000                | \$2,013,000 |
| District Admin /Maintenance            |                                    |                                |                | \$ 55,000                        | \$ 12,000                    | \$ 115,000      |                               | \$ 43,000                              | \$ 135,000   | \$ 17,000                       | \$ 130,000                | \$ 507,000  |
|  | Priority                           |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |             |
|  | Recommended                        |                                |                |                                  |                              |                 |                               |  |  |                                 |                           |             |

- AHU --- Air Handling Unit
- HV --- Heating Ventilating Unit
- RTU --- Rooftop Unit
- UV --- Unit Ventilator
- UH --- Unit Heater
- FF --- Forced-air Furnace
- DHW --- Domestic Hot Water

\*Page content is subject to Confidentiality Restrictions\*

# APPENDIX C

## AMERICAN SOCIETY OF HEATING, REFRIGERATION AND AIR CONDITIONING ENGINEERS (ASHRAE)

## EQUIPMENT LIFE EXPECTANCY CHART

# APPENDIX C

## ASHRAE EQUIPMENT LIFE EXPECTANCY CHART

| Equipment Item                      | Median Years | Equipment Item                    | Median Years | Equipment Item         | Median Years |
|-------------------------------------|--------------|-----------------------------------|--------------|------------------------|--------------|
| Air conditioners                    |              | Air terminals                     |              | Air-cooled condensers  | 20           |
| Window unit                         | 10           | Diffusers, grilles, and registers | 27           | Evaporative condensers | 20           |
| Residential single or Split Package | 15           | Induction and fan coil units      | 20           | Insulation             |              |
| Commercial through-the wall         | 15           | VAV and double-duct boxes         | 20           | Molded Blanket         | 20<br>24     |
| Water-cooled package                | 15           | Air washers                       | 17           | Pumps                  |              |
| Heat Pumps                          |              | Ductwork                          | 30           | Base-mounted           | 20           |
| Residential air-to-air              | 15           | Dampers                           | 20           | Pipe-mounted           | 10           |
| Commercial air-to-air               | 15           | Fans                              |              | Sump and well          | 10           |
| Commercial water-to-air             | 19           | Centrifugal                       | 25           | Condensate 15          |              |
| Roof-top air conditioners           |              | Axial                             | 20           | Reciprocating engines  | 20           |
| Single-zone                         | 15           | Propeller                         | 15           | Steam turbines         | 30           |
| Multi-zone                          | 15           | Ventilating roof-mounted          | 20           | Electric motors        | 18           |
| Boilers, hot water (steam)          |              | Coils                             |              | Motor starters         | 17           |
| Steel water-tube                    | 24 (30)      | DX, water, or steam               | 20           | Electric transformers  | 30           |
| Steel fire-tube                     | 25 (25)      | Electric                          | 15           | Controls               |              |
| Cast iron                           | 35 (30)      | Heat Exchangers                   |              | Pneumatic              | 20           |
| Electric                            | 15           | Shell-and-tube                    | 24           | Electric               | 16           |
| Burners                             | 21           | Reciprocating compressors         | 20           | Electronic             | 15           |
| Furnaces                            |              | Packaged chillers                 |              | Valve actuators        |              |
| Gas- or oil-fired                   | 18           | Reciprocating                     | 20           | Hydraulic              | 15           |
| Unit heaters                        |              | Centrifugal                       | 23           | Pneumatic              | 20           |
| Gas or electric                     | 13           | Absorption                        | 23           | Self-contained         | 10           |
| Hot water or steam                  | 20           | Cooling towers                    |              |                        |              |
| Radiant Heaters                     |              | Galvanized metal                  | 20           |                        |              |
| Electric                            | 10           | Wood                              | 20           |                        |              |
| Hot water or steam                  | 25           | Ceramic                           | 34           |                        |              |

# APPENDIX D

## OREGON DEPARTMENT OF EDUCATION (ODE)

## FACILITIES CONDITION ASSESSMENT REPORTS

**REMEMBER: FILL OUT ALL INFORMATION ON "BASE INFORMATION SHEET" BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Prescott Elementary School  
 Building Name: Main  
 Building ID: 21810100

| Level 1                 | Level 2      | Level 3                    | Type (as applicable) | % of Building or Number | LEVEL OF ACTION |          |          |           |                                | Automated Budget Estimate | Notes |
|-------------------------|--------------|----------------------------|----------------------|-------------------------|-----------------|----------|----------|-----------|--------------------------------|---------------------------|-------|
|                         |              |                            |                      |                         | None            | Minor    | Moderate | Major     | Replace as part of Renovation  |                           |       |
| A                       | SUBSTRUCTURE | A10 Foundations            |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | A1010 Standard Foundations | X                    | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | A1020 Special Foundations  |                      | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | A1030 Slab on Grade        | X                    | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | A20 Basement Construction  |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | A2010 Basement Excavation  |                      | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | A2020 Basement Walls       | X                    | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | NOT USED                   |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | 100%                       |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | 35%                        |                      |                         |                 |          |          |           |                                |                           |       |
| B                       | SHELL        | B10 Superstructure         |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | B1010 Floor Construction   |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | Wood                       | X                    | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | Steel                      |                      | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | Concrete                   |                      | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | Wood                       | X                    | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | Steel                      |                      | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | Concrete                   |                      | None                    | Minor           | Moderate | Major    | Replace   |                                | \$0                       |       |
|                         |              | B20 Exterior Enclosure     |                      |                         |                 |          |          |           |                                |                           |       |
|                         |              | B2010 Exterior Walls       |                      |                         |                 |          |          |           |                                |                           |       |
| Concrete Formed / Tilt  |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Masonry                 |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Framed w/ Wood Siding   |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$319,050 |                                |                           |       |
| Framed w/Metal Panel    | 40%          | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Framed w/Stucco         |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Framed w/Masonry Veneer | 60%          | None                       | Minor                | Moderate                | Major           | Replace  |          | \$46,150  |                                |                           |       |
| Wood                    |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Aluminum/Steel          |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Clad                    | 100%         | None                       | Minor                | Moderate                | Major           | Replace  |          | \$475,261 |                                |                           |       |
| Curtain Wall            |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Wood                    |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Hollow Metal Storefront | 15           | None                       | Minor                | Moderate                | Major           | Replace  |          | \$25,120  | Upgrade hardware + repaint     |                           |       |
| B30 Roofing             |              |                            |                      |                         |                 |          |          |           |                                |                           |       |
| B3010 Roof Coverings    |              |                            |                      |                         |                 |          |          |           |                                |                           |       |
| Asphalt Shingle         |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Built-Up                | 100%         | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       | Missing data on roofing report |                           |       |
| Single Ply              |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Metal                   |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Concrete Tile           |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       |                                |                           |       |
| Skylights               |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       | By Building GSF                |                           |       |
| Access Hatch            |              | None                       | Minor                | Moderate                | Major           | Replace  |          | \$0       | Per Hatch                      |                           |       |



**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Prescott Elementary School  
 Building Name: Main  
 Building ID: Z1810100

| Level 1                           | Level 2                                 | Level 3                          | Type (as applicable)              | % of Building or Number | LEVEL OF ACTION |          |           |                               | Automated Budget Estimate                                | Notes  |   |
|-----------------------------------|---|----------------------------------|-----------------------------------|-------------------------|-----------------|----------|-----------|-------------------------------|--|--|---|
|                                   |   |                                  |                                   |                         | Minor           | Moderate | Major     | Replace as part of Renovation |  |  |   |
| D SERVICES                        | D10 Conveying                           | D1010 Elevators & Lifts          |                                   | 2                       | None            |          | Major     | X Replace                     | \$132,448  | Broken platform lift at Stage  |   |
|                                   |   | D1020 Escalators & Moving Walks  |                                   |                         | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   | D1090 Other Conveying Systems    |                                   |                         | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   | D20 Plumbing                     | D2010 Plumbing fixtures           | 100%                    | N               | None     |           | Major                         | Replace  | \$55,000   | All (N) fixtures req'd to meet ADA by code.                   |
|                                   |   |                                  | D2020 Domestic Water Distribution | 100%                    | Y               | None     |           | Major                         | X Replace  | \$60,000   | Estimate to replace old DHWS and water pipe between buildings |
|                                   |   |                                  | D2030 Sanitary Waste              | 100%                    | N               | None     |           | Major                         | Replace  | \$0  |   |
|                                   |   | D2040 Rain Water Drainage        | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   | D2090 Other Plumbing Systems     | NOT USED                          |                         | None            |          | Major     | Replace                       |  |  |   |
|                                   |   | D30 HVAC                         | D3010 Energy Supply               | 100%                    | N               | None     |           | Major                         | Replace  | \$0  | NG on site for heating and kitchen                            |
|                                   |   |                                  | D3020 Heat Generating Systems     | 65%                     | N               | None     |           | Major                         | Replace  | \$0  | 3 condensing boilers installed in 2013                        |
| Boiler                            |   |                                  |                                   |                         |                 |          |           |                               |  | Package RTUs for CR building (2013); Main building has (2) HVs with heat recovery section for gym and cafeteria, (3) heat recovery ventilators to provide OA, and (1) make-up air unit for kitchen |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  | Main building has 2 HVs with heat recovery section for gym and cafeteria and 3 heat recovery ventilators to provide OA   |   |
| Air Handler Furnace               |   |                                  | 0%                                | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  |                                   |                         |                 |          |           |                               |  |  |   |
| Heat Exchanger                    |   |                                  | 65%                               | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  |                                   |                         |                 |          |           |                               |  |  |   |
| D3030 Cooling Generating Systems  |   |                                  | 35%                               | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 0%                                | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
| D3040 Distribution Systems        |   | 100%                             | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
|                                   |   | 65%                              | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
| D3050 Terminal & Package Units    |   | 0%                               | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
|                                   |   | 40%                              | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
| D3060 Controls & Instrumentation  |   | 100%                             | Y                                 | None                    |                 | Major    | X Replace | \$75,000                      | HW radiator for main building CRs + offices              |  |   |
|                                   |   | 100%                             | Y                                 | None                    |                 | Major    | X Replace | \$22,000                      | Control upgrade for classroom building estimated for RCx |  |   |
| D40 Fire Protection               | D4010 Sprinklers                        | 100%                             | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
|                                   | D4020 Standpipes                        | 0%                               | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
| D4030 Fire Protection Specialties |   | 0%                               | N                                 | None                    |                 | Major    | Replace   | \$0                           |  |  |   |
|                                   | D4090 Other Fire Protection Systems     | NOT USED                         |                                   | None                    |                 | Major    | Replace   |                               |  |  |   |
| D50 Electrical                    | D5010 Electrical Service & Distribution | D5020 Lighting and Branch Wiring | 100%                              | Y                       | None            |          | Major     | Replace                       | \$0  | Lighting and lighting control retrofit   |   |
|                                   |   | D5030 Communications & Security  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | X Replace                     | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 100%                              | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
|                                   |   |                                  | 35%                               | N                       | None            |          | Major     | Replace                       | \$0  |  |   |
| D5090 Other Electrical Systems    |   |                                  |                                   |                         |                 |          |           |                               |  |  |   |
|                                   |   |                                  |                                   |                         |                 |          |           |                               |  |  |   |

District Name: Parkrose SD 3  
 Site Name: Prescott Elementary School  
 Building Name: Main  
 Building ID: 21810100

**REMEMBER: FILL OUT ALL INFORMATION ON "BASE INFORMATION SHEET" BEFORE ENTERING DATA ON THIS SHEET**  
 An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1  | Level 2 | Level 3 | Type (as applicable)                  | % of Building or Number | LEVEL OF ACTION |          |       |         | Major   | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate                  | Notes |
|--|---------|---------|---------------------------------------|-------------------------|-----------------|----------|-------|---------|---------|-------------------------------|-----------------------|--|-------|
|  |         |         |                                       |                         | Minor           | Moderate | Major | Replace |         |                               |                       |  |       |
| <b>E. EQUIPMENT &amp; FURNISHINGS</b>                      |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| E10 Equipment  |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
|  |         |         | Food Service                          | 100%                    | X               | Minor    |       | Major   | Replace | 15%                           | \$4,221               |  |       |
|  |         |         | Vocational Science                    |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | Art                                   |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | Stage Performance                     |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | Restroom Accessories/Stalls           | 100%                    | X               | Minor    |       | Major   | Replace | 20%                           | \$2,752               |  |       |
|  |         |         | NOT USED                              |                         |                 | Minor    |       | Major   | Replace |                               |                       |  |       |
|  |         |         | NOT USED                              |                         |                 | Minor    |       | Major   | Replace |                               |                       |  |       |
| E20 Furnishings  |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
|  |         |         | E2010 Fixed Furnishings               | 100%                    | X               | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | E2020 Movable Furnishings             | 100%                    | X               | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
| <b>F. SPECIAL CONSTRUCTION &amp; DEMOLITION - NOT USED</b> |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| <b>G. BUILDING SITE WORK</b>                               |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| G10 Site Preparation                                       |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| G20 Site Improvements                                      |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
|  |         |         | G2010 Roadways                        | 7833                    |                 | Minor    |       | Major   | Replace | 100%                          | \$65,588              | Cost/SF of surface area                    |       |
|  |         |         | G2020 Parking Lots                    | 4000                    | X               | Minor    |       | Major   | Replace |                               | \$0                   | Cost/SF of surface area                    |       |
|  |         |         | G2030 Pedestrian Paving               | 12031                   | X               | Minor    |       | Major   | Replace |                               | \$0                   | Cost/SF of surface area                    |       |
|  |         |         | G2040 Site Development                | 1430                    | X               | Minor    |       | Major   | Replace |                               | \$0                   | Cost/LF of fencing                         |       |
|  |         |         | G2050 Landscaping                     | 153066                  | X               | Minor    |       | Major   | Replace |                               | \$0                   | Cost/SF of irrigated area                  |       |
| G30 Site Mechanical Utilities                              |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
|  |         |         | G3010 Water Supply                    |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter LF of pipe in cell E143              |       |
|  |         |         | G3020 Sanitary Sewer                  |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter LF of pipe in cell E144              |       |
|  |         |         | G3030 Storm Sewer                     |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter LF of sewer lines in cell E145       |       |
|  |         |         | G3040 Heating Distribution            |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter SF of area to be drained             |       |
|  |         |         | G3050 Cooling Distribution            |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter LF of heating ducts in cell E147     |       |
|  |         |         | G3060 Fuel Distribution               |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter LF of duct work in cell E148         |       |
|  |         |         | G3090 Other Site Mechanical Utilities |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   | Enter LF of natural gas lines in cell E149 |       |
| G40 Site Electrical Utilities                              |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
|  |         |         | G4010 Electrical Distribution         | 100%                    | X               | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | G4020 Site Lighting                   | 100%                    | X               | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | G4030 Site Communications & Security  |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
|  |         |         | G4090 Other Site Electrical Utilities |                         |                 | Minor    |       | Major   | Replace |                               | \$0                   |  |       |
| G90 Other Site Construction                                |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| <b>OTHER</b>   |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| Description of System                                      |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| Extended   |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| Unit Budget  |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| Quantity   |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| Measure  |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |
| Notes  |         |         |                                       |                         |                 |          |       |         |         |                               |                       |  |       |

Physical Condition Budget Sub-Total \$1,480,538  
 Budgeted Development Costs \$562,605  
 Physical Condition Budget TOTAL \$2,043,143  
 Cost with Escalation to June 2021 \$2,329,183  
 Cost with Escalation to June 2022 \$2,422,350  
 Cost with Escalation to June 2023 \$2,519,244  
 Replacement Budget \$24,820,062  
 Facility Condition Index (FCI) 9.4%



**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Russell Academy  
 Building Name: Main  
 Building ID: 21810200

| Level 1                   | Level 2 | Level 3 | Type (as applicable)       | % of Building or Number | LEVEL OF ACTION |       |          |       |   | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                      |
|---------------------------|---------|---------|----------------------------|-------------------------|-----------------|-------|----------|-------|---|-------------------------------|-----------------------|---------------------------|----------------------------|
|                           |         |         |                            |                         | None            | Minor | Moderate | Major |   |                               |                       |                           |                            |
| <b>A SUBSTRUCTURE</b>     |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
| A10 Foundations           |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
|                           |         |         | A1010 Standard Foundations |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | A1020 Special Foundations  |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | A1030 Slab on Grade        | 100%                    | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
| A20 Basement Construction |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
|                           |         |         | A2010 Basement Excavation  |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | A2020 Basement Walls       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
| <b>B SHELL</b>            |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
| B10 Superstructure        |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
|                           |         |         | B1010 Floor Construction   | 100%                    | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Concrete                   |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | B1020 Roof Construction    | 90%                     | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Steel                      | 10%                     | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Concrete                   |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
| B20 Exterior Enclosure    |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
|                           |         |         | B2010 Exterior Walls       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Concrete Formed / Tilt     |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Masonry                    |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Framed w/ Wood Siding      | 10%                     |                 | Minor | Moderate | Major | X | Replace                       | 100%                  | \$30,016                  |                            |
|                           |         |         | Framed w/ Metal Panel      |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Framed w/ Stucco           |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Framed w/ Masonry Veneer   | 90%                     |                 | Minor | Moderate | Major | X | Replace                       | 60%                   | \$124,769                 |                            |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Aluminum/Steel             |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Clad                       | 100%                    | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Curtain Wall               |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | B2030 Exterior Doors       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Hollow Metal               | 28                      |                 | Minor | Moderate | Major |   | Replace                       | 100%                  | \$36,070                  | Upgrade hardware and paint |
|                           |         |         | Storefront                 | 10                      | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
| B30 Roofing               |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                            |
|                           |         |         | B3010 Roof Coverings       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Asphalt Shingle            |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Built-Up                   | 100%                    |                 | Minor | Moderate | Major | X | Replace                       | 20%                   | \$268,187                 | Scheduled 2027             |
|                           |         |         | Single Ply                 |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Metal                      |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Concrete Tile              |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                            |
|                           |         |         | Skylights                  |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       | By Building OSF            |
|                           |         |         | B3020 Roof Openings        |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       | Per hatch                  |

District Name: Parkrose SD 3  
 Site Name: Russell Academy  
 Building Name: Main  
 Building ID: 21810200

**REMINER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION |       |          |       |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes   |
|---------------------------|---------|---------|-----------------------|-------------------------|-----------------|-------|----------|-------|-------|-------------------------------|-----------------------|---------------------------|---|
|                           |         |         |                       |                         | None            | Minor | Moderate | Major | Major |                               |                       |                           |   |
| <b>C INTERIORS</b>        |         |         |                       |                         |                 |       |          |       |       |                               |                       |                           |   |
| C10 Interior Construction |         |         |                       |                         |                 |       |          |       |       |                               |                       |                           |   |
|                           |         | C1010   | Partitions            |                         | None            | Minor | Moderate | Major |       | Replace                       |                       | \$0                       |   |
|                           |         |         | Framed Masonry        | 80%                     | X               |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Masonry               | 20%                     | X               |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Wood                  | 80                      |                 | X     |          |       |       |                               |                       | \$82,445                  | Door hardware                                 |
|                           |         |         | Hollow Metal          | 22                      |                 |       |          | X     |       |                               |                       | \$31,174                  | Door hardware, paint                          |
|                           |         |         | NOT USED              |                         |                 |       |          |       |       |                               |                       |                           |   |
| C20 Stairs                |         |         |                       |                         |                 |       |          |       |       |                               |                       |                           |   |
|                           |         | C2010   | Stair Construction    |                         | None            | Minor | Moderate | Major |       | Replace                       |                       | \$0                       | Cost/Flight                                   |
|                           |         |         | Wood                  |                         |                 |       |          |       |       |                               |                       | \$0                       | Cost/Flight                                   |
|                           |         |         | Metal                 |                         |                 |       |          |       |       |                               |                       | \$0                       | Cost/Flight                                   |
|                           |         |         | Concrete              |                         |                 |       |          |       |       |                               |                       | \$0                       | Cost/Flight                                   |
|                           |         |         | Concrete Fill         |                         |                 |       |          |       |       |                               |                       | \$0                       | Cost/Flight                                   |
|                           |         |         | Resilient             |                         |                 |       |          |       |       |                               |                       | \$0                       | Cost/Flight                                   |
| C30 Interior Finishes     |         |         |                       |                         |                 |       |          |       |       |                               |                       |                           |   |
|                           |         | C3010   | Wall Finishes         |                         | None            | Minor | Moderate | Major |       | Replace                       |                       | \$0                       | Clear sealer (not paint)                      |
|                           |         |         | Paint on Masonry      | 20%                     | X               |       |          |       |       |                               |                       | \$47,577                  |   |
|                           |         |         | Wallboard             | 75%                     |                 |       | X        |       |       |                               |                       | \$0                       |   |
|                           |         |         | Wainscot              |                         |                 |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Ceramic Tile          | 5%                      |                 |       |          |       | X     |                               |                       | \$6,266                   |   |
|                           |         |         | Carpet / Soft Surface | 5%                      |                 |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Resilient Tile        | 70%                     |                 |       |          |       |       |                               |                       | \$171,846                 |   |
|                           |         |         | Resilient Sheet       | 10%                     |                 |       |          |       | X     |                               |                       | \$30,945                  |   |
|                           |         |         | Polished Concrete     | 10%                     |                 |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Ceramic Tile          | 5%                      |                 |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Liquid Applied        |                         |                 |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Wood Sports Floor     |                         |                 |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Wallboard             | 5%                      | X               |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Lay-in Ceiling Tile   | 5%                      | X               |       |          |       |       |                               |                       | \$0                       |   |
|                           |         |         | Glued-Up Ceiling Tile | 80%                     |                 |       |          |       | X     |                               |                       | \$48,893                  | Cafeteria Tectum panels, minor CR replacement |
|                           |         |         | Painted Structure     | 10%                     | X               |       |          |       |       |                               |                       | \$0                       | Stained exposed GLBs throughout               |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Russell Academy  
 Building Name: Main  
 Building ID: 21810200

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes  |
|----------------------------|---------|---------|---|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|--|
|                            |         |         |   |                         | None            | Minor | Moderate | Major |                               |                       |                           |  |
| <b>D SERVICES</b>          |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
| <b>D10 Conveying</b>       |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D1010 Elevators & Lifts                 |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D1020 Escalators & Moving Walks         |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D1090 Other Conveying Systems           |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
| <b>D20 Plumbing</b>        |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | All (N) fixtures req'd to meet ADA by code.  |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | System upgraded in 2013 project and DRWS replaced in 2013  |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D2090 Other Plumbing Systems            |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
| <b>D30 HVAC</b>            |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D3010 Energy Supply                     | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | NG on site   |
|                            |         |         | D3020 Heat Generating Systems           | 85%                     | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | Boiler installed in 2013 to provide HW to majority of the building except new multi-purpose room                           |
|                            |         |         | Air Handler                             | 35%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$53,000                  | HVs and DOAS for gym, kitchen and multi-purpose room. Estimate included in UV system replacement for gym and kitchen units |
|                            |         |         | Furnace                                 | 0%                      | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Heat Exchanger                          | 15%                     | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | DOAS unit with heat recover for new MPR (2013)   |
|                            |         |         | Component of air handler                | 0%                      | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | (2) Aermec reversible air/water heat pumps on roof provide chilled water + heating water to MPR floor radiant panel (2014) |
|                            |         |         | Stand alone chiller                     | 15%                     | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Ductwork                                | 35%                     | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Hot water return & supply               | 85%                     | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | In-room ventilator unit                 | 65%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$530,000                 | UVs and HVs replacement  |
|                            |         |         | In-room radiant unit                    | 0%                      | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         |   | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         |   | 100%                    | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$18,000                  | Estimated for RCX  |
| <b>D40 Fire Protection</b> |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D4010 Sprinklers                        | 85%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$40,000                  | Add fire sprinkler system for MPR  |
|                            |         |         | D4020 Standpipes                        | 0%                      | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D4090 Other Fire Protection Systems     |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
| <b>D50 Electrical</b>      |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | Lighting and lighting control retrofit   |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D5030 Communications & Security         | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Voice / Data System                     | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Clock / Intercom System                 | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Closed Circuit Surveillance             | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Access Control System                   | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Intrusion Alarm System                  | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Lighting Control System                 | 35%                     | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | NOT USED                                |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D5090 Other Electrical Systems          |                         | None            | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Russell Academy  
 Building Name: Main  
 Building ID: 21810200

| Level 1   | Level 2 | Level 3                 | Type (as applicable)        | % of Building or Number | LEVEL OF ACTION |       |          |       |         | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate                  | Notes |
|---|---------|-------------------------|-----------------------------|-------------------------|-----------------|-------|----------|-------|---------|-------------------------------|-----------------------|--|-------|
|   |         |                         |                             |                         | None            | Minor | Moderate | Major | Major   |                               |                       |  |       |
| <b>E EQUIPMENT &amp; FURNISHINGS</b>                      |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| E10 Equipment   |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
|   | E1010   | Commercial Equipment    | Food Service                | 20%                     |                 | Minor | Moderate | Major | Replace | 100%                          | \$4,642               | Kitchen Equipment                          |       |
|   |         |                         | Vocational                  |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
|   |         |                         | Science                     |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
|   |         |                         | Art                         |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
|   |         |                         | Stage Performance           |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
|   |         |                         | Restroom Accessories/Stalls |                         |                 | Minor | Moderate | Major | Replace |                               | \$5,673               |  |       |
|   |         |                         | NOT USED                    | 100%                    | X               |       |          |       | Replace | 50%                           |                       |  |       |
|   |         |                         | NOT USED                    |                         |                 | Minor | Moderate | Major | Replace |                               |                       |  |       |
| E1030 Vehicular Equipment                                 |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| E1090 Other Equipment                                     |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| E20 Furnishings   |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
|   | E2010   | Fixed Furnishings       |                             | 100%                    |                 | Minor | Moderate | Major | Replace | 80%                           | \$384,539             |  |       |
|   |         |                         |                             | 100%                    |                 | Minor | Moderate | Major | Replace | 20%                           | \$247,557             |  |       |
| E2020 Movable Furnishings                                 |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>F SPECIAL CONSTRUCTION &amp; DEMOLITION - NOT USED</b> |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>G BUILDING SITE WORK</b>                               |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| G10 Site Preparation                                      |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| G20 Site Improvements                                     |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
|   | G2010   | Roadways                |                             | 5940                    |                 | Minor | Moderate | Major | Replace | 50%                           | \$24,869              | Cost/SF of surface area                    |       |
|   |         |                         |                             | 16139                   |                 | Minor | Moderate | Major | Replace | 50%                           | \$67,568              | Cost/SF of surface area                    |       |
|   |         |                         |                             | 6812                    |                 | Minor | Moderate | Major | Replace | 50%                           | \$39,488              | Cost/SF of surface area                    |       |
|   |         |                         |                             | 2300                    | X               | Minor | Moderate | Major | Replace |                               | \$0                   | Cost/LF of fencing                         |       |
|   |         |                         |                             | 341000                  | X               | Minor | Moderate | Major | Replace |                               | \$0                   | Cost/SF of irrigated area                  |       |
| G30 Site Mechanical Utilities                             |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
|   | G3010   | Water Supply            | Domestic                    | 100                     | X               | Minor | Moderate | Major | Replace |                               | \$0                   | Enter LF of pipe in cell E143              |       |
|   |         |                         | Fire                        |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   | Enter LF of pipe in cell E144              |       |
|   |         |                         |                             | 100                     | X               | Minor | Moderate | Major | Replace |                               | \$0                   | Enter LF of sewer lines in cell E145       |       |
|   |         |                         |                             |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   | Enter SF of area to be drained             |       |
|   |         |                         |                             |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   | Enter LF of heating ducts in cell E147     |       |
|   |         |                         |                             |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   | Enter LF of duct work in cell E148         |       |
|   |         |                         |                             |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   | Enter LF of natural gas lines in cell E149 |       |
| G3090 Other Site Mechanical Utilities                     |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| G40 Site Electrical Utilities                             |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
|   | G4010   | Electrical Distribution | Service                     | 100%                    | X               | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
|   |         |                         | Generator                   |                         |                 | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
|   |         |                         |                             | 100%                    | X               | Minor | Moderate | Major | Replace |                               | \$0                   |  |       |
| G4020 Site Lighting                                       |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| G4030 Site Communications & Security                      |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| G4090 Other Site Electrical Utilities                     |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| G90 Other Site Construction                               |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>OTHER</b>  |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>Description of System</b>                              |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>Quantity</b>   |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>Unit Budget</b>  |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>Unit of Measure</b>                                    |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>Extended</b>   |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |
| <b>Notes</b>  |         |                         |                             |                         |                 |       |          |       |         |                               |                       |  |       |

Physical Condition Budget Sub-Total \$2,383,523  
 Budgeted Development Costs \$905,739  
 Physical Condition Budget TOTAL \$3,289,262  
 Cost with Escalation to June 2021 \$3,749,759  
 Cost with Escalation to June 2022 \$3,899,749  
 Cost with Escalation to June 2023 \$4,055,739

Replacement Budget \$20,470,006  
 Facility Condition Index (FCI) 18.5%

**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Sacramento Elementary School  
 Building Name: Main  
 Building ID: 21810300

| Level 1                   | Level 2 | Level 3 | Type (as applicable)       | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                         |
|---------------------------|---------|---------|----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|-------------------------------|
|                           |         |         |                            |                         | None            | Minor | Moderate | Major |                               |                       |                           |                               |
| <b>A SUBSTRUCTURE</b>     |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
| A10 Foundations           |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
|                           |         |         | A1010 Standard Foundations |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | A1020 Special Foundations  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | A1030 Slab on Grade        | 100%                    | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
| A20 Basement Construction |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
|                           |         |         | A2010 Basement Excavation  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | A2020 Basement Walls       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
| <b>B SHELL</b>            |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
| B10 Superstructure        |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
|                           |         |         | B1010 Floor Construction   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Concrete                   | 100%                    | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | B1020 Roof Construction    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Concrete                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
| B20 Exterior Enclosure    |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
|                           |         |         | B2010 Exterior Walls       | 10%                     | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Concrete Formed / Tilt     |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Masonry                    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Framed w/ Wood Siding      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Framed w/ Metal Panel      | 10%                     | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Framed w/ Stucco           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Framed w/ Masonry Veneer   | 80%                     | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Aluminum/Steel             |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Clad                       | 100%                    | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Curtain Wall               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | B2030 Exterior Doors       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Hollow Metal               | 15                      |                 | Minor | Moderate | Major | Replace                       | 50%                   | \$9,662                   | Minor hardware upgrade, paint |
|                           |         |         | Storefront                 | 8                       | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
| B30 Roofing               |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                               |
|                           |         |         | B3010 Roof Coverings       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Asphalt Shingle            |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Built-Up                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Single Ply                 | 100%                    |                 | Minor | Moderate | Major | Replace                       | 100%                  | \$598,910                 |                               |
|                           |         |         | Metal                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Concrete Tile              |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |
|                           |         |         | Skylights                  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | By Building GSF               |
|                           |         |         | B3020 Roof Openings        |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Per hatch                     |
|                           |         |         | Access Hatch               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                               |

District Name: Parkrose SD 3  
 Site Name: Sacramento Elementary School  
 Building Name: Main  
 Building ID: 21810300

**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**  
 An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION   |                      |                         |                                  |                         | Replace as part of Renovation | % of System or Finish         | Automated Budget Estimate | Notes                            |
|---------------------------|---------|---------|-----------------------|-------------------------|-------------------|----------------------|-------------------------|----------------------------------|-------------------------|-------------------------------|-------------------------------|---------------------------|----------------------------------|
|                           |         |         |                       |                         | None              | Minor                | Moderate                | Major                            |                         |                               |                               |                           |                                  |
| <b>C INTERIORS</b>        |         |         |                       |                         |                   |                      |                         |                                  |                         |                               |                               |                           |                                  |
| C10 Interior Construction |         |         |                       |                         |                   |                      |                         |                                  |                         |                               |                               |                           |                                  |
|                           |         | C1010   | Partitions            |                         | 90%<br>10%<br>112 | None<br>None<br>None | Minor<br>Minor<br>Minor | Moderate<br>Moderate<br>Moderate | Major<br>Major<br>Major |                               | Replace<br>Replace<br>Replace | \$0<br>\$0<br>\$75,025    |                                  |
|                           |         | C1020   | Interior Doors        |                         | 12                | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$12,367                  | Hardware                         |
|                           |         | C1030   | Fittings              |                         | 12                | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       |                           | Upgrade hardware + repaint       |
|                           |         | C20     | Stairs                |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       | Cost/Flight                      |
|                           |         | C2010   | Stair Construction    |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       | Cost/Flight                      |
|                           |         | C2020   | Stair Finishes        |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       | Cost/Flight                      |
|                           |         | C2030   | Stair Finishes        |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       | Cost/Flight                      |
|                           |         | C30     | Interior Finishes     |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       | Cost/Flight                      |
|                           |         | C3010   | Wall Finishes         |                         | 10%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$11,862                  |                                  |
|                           |         | C3010   | Wallboard             |                         | 75%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$20,056                  |                                  |
|                           |         | C3010   | Wainscot              |                         | 10%               | None                 | Minor                   | Moderate                         | Major                   | X                             | Replace                       | \$7,096                   | Rectum panels at Gym / Cafeteria |
|                           |         | C3020   | Floor Finishes        |                         | 5%                | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3020   | Carpet / Soft Surface |                         | 7%                | None                 | Minor                   | Moderate                         | Major                   | X                             | Replace                       | \$6,190                   |                                  |
|                           |         | C3020   | Resilient Tile        |                         | 75%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$37,809                  |                                  |
|                           |         | C3020   | Resilient Sheet       |                         | 8%                | None                 | Minor                   | Moderate                         | Major                   | X                             | Replace                       | \$25,418                  |                                  |
|                           |         | C3020   | Polished Concrete     |                         | 5%                | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3020   | Ceramic Tile          |                         | 5%                | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3020   | Liquid Applied        |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3020   | Wood Sports Floor     |                         |                   | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3030   | Wallboard             |                         | 10%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3030   | Lay-in Ceiling Tile   |                         | 50%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3030   | Glued-Up Ceiling Tile |                         | 25%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |
|                           |         | C3030   | Painted Structure     |                         | 15%               | None                 | Minor                   | Moderate                         | Major                   |                               | Replace                       | \$0                       |                                  |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Sacramento Elementary School  
 Building Name: Main  
 Building ID: 21810300

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | LEVEL OF ACTION         |      |       |          |          | Automated Budget Estimate | Notes   |                               |                       |   |
|----------------------------|---------|---------|---|-------------------------|------|-------|----------|----------|---------------------------|---------|-------------------------------|-----------------------|---|
|                            |         |         |   | % of Building or Number | None | Minor | Moderate | Major    |                           |         | Replace as part of Renovation | % of System or Finish |   |
| <b>D SERVICES</b>          |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
| <b>D10 Conveying</b>       |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|                            |         |         | D1010 Elevators & Lifts                 | 0                       | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D1020 Escalators & Moving Walks         | 0                       | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D1090 Other Conveying Systems           | 0                       | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D20 Plumbing</b>        |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | All (N) fixtures req'd to meet ADA by code.                             |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | 2009 and 2013 gas-fired DRHWs   |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D2090 Other Plumbing Systems            |                         | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D30 HVAC</b>            |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|                            |         |         | D3010 Energy Supply                     | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Gas to boiler and kitchen area  |
|                            |         |         | D3020 Heat Generating Systems           | 80%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Gas-fired condensing HW boilers installed in 2013                       |
|                            |         |         | Boiler                                  |                         | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Package HP RTU for main office + MPR; FCUs for cafeteria and CJs (2013) |
|                            |         |         | Air Handler                             | 40%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Furnace                                 | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Heat Exchanger                          | 12%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Heat recovery unit for MPR (2013)                                       |
|                            |         |         | Component of air handler                | 15%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Package HP RTU for main office + MPR (2013)                             |
|                            |         |         | Stand alone chiller                     | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Ductwork                                | 40%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Hot water return & supply               | 85%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | In-room ventilator unit                 | 30%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | ducted booster HW heater and HW FCU                                     |
|                            |         |         | In-room radiant unit                    | 60%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | HW radiator   |
|                            |         |         | NOT USED                                | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Estimated for RCX   |
|                            |         |         | NOT USED                                | 100%                    | Y    | None  | Minor    | Moderate | Major                     | Replace | 100%                          | \$21,000              |   |
| <b>D40 Fire Protection</b> |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|                            |         |         | D4010 Sprinklers                        | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D4020 Standpipes                        | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D4090 Other Fire Protection Systems     |                         | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D50 Electrical</b>      |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y    | None  | Minor    | Moderate | Major                     | Replace | 100%                          | \$95,000              | Lighting and lighting control retrofit                                  |
|                            |         |         | D5030 Communications & Security         | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Voice / Data System                     | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Close Circuit Surveillance              | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Access Control System                   | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Intrusion Alarm System                  | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | Lighting Control System                 | 35%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | NOT USED                                |                         | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|                            |         |         | D5090 Other Electrical Systems          |                         | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Sacramento Elementary School  
 Building Name: Main  
 Building ID: 21810300

| Level 1                              | Level 2 | Level 3              | Type (as applicable)        | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                   |
|--------------------------------------|---------|----------------------|-----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|---|
|                                      |         |                      |                             |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
| <b>E EQUIPMENT &amp; FURNISHINGS</b> |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |   |
| E10 Equipment                        |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |   |
|                                      | E1010   | Commercial Equipment | Food Service                | 100%                    | None            | Minor | Moderate | Major | X                             | 25%                   | \$31,110                  | Walk-ins are original, need replacement |
|                                      |         |                      | Vocational Science          |                         | None            | Minor | Moderate | Major |                               |                       | \$0                       |   |
|                                      |         |                      | Art                         |                         | None            | Minor | Moderate | Major |                               |                       | \$0                       |   |
|                                      |         |                      | Stage Performance           |                         | None            | Minor | Moderate | Major |                               |                       | \$0                       |   |
|                                      |         |                      | Restroom Accessories/Stalls |                         | None            | X     | Moderate | Major |                               |                       | \$5,825                   | Minor ADA upgrades                      |
|                                      |         |                      | NOT USED                    | 100%                    | None            | Minor | Moderate | Major |                               |                       |                           |   |
|                                      |         |                      | NOT USED                    |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
|                                      | E1030   | Vehicular Equipment  |                             |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
|                                      | E1090   | Other Equipment      |                             |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
| E20 Furnishings                      |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |   |
|                                      | E2010   | Fixed Furnishings    |                             | 100%                    | None            | Minor | Moderate | Major | X                             | 40%                   | \$197,413                 |   |
|                                      | E2020   | Movable Furnishings  |                             | 100%                    | None            | Minor | Moderate | Major | X                             | 5%                    | \$63,545                  |   |

**F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED**

**G BUILDING SITE WORK**

|                                       |                               |                                 |                   |        |      |       |          |       |   |      |          |  |
|---------------------------------------|-------------------------------|---------------------------------|-------------------|--------|------|-------|----------|-------|---|------|----------|--|
| G10 Site Preparation                  |                               |                                 |                   |        |      |       |          |       |   |      |          |  |
| G20 Site Improvements                 |                               |                                 |                   |        |      |       |          |       |   |      |          |  |
|                                       | G2010                         | Roadways                        |                   | 2623   | None | Minor | Moderate | Major | X | 100% | \$21,963 | Cost/SF of surface area                    |
|                                       | G2020                         | Parking Lots                    |                   | 15561  | None | Minor | Moderate | Major | X | 50%  | \$65,148 | Cost/SF of surface area                    |
|                                       | G2030                         | Pedestrian Paving               |                   | 13014  | None | Minor | Moderate | Major |   |      | \$0      | Cost/SF of surface area                    |
|                                       | G2040                         | Site Development                |                   | 121346 | None | Minor | Moderate | Major |   |      | \$0      | Cost/LF of fencing                         |
|                                       | G2050                         | Landscaping                     |                   | 388467 | None | Minor | Moderate | Major |   |      | \$0      | Cost/SF of irrigated area                  |
| G30 Site Mechanical Utilities         |                               |                                 |                   |        |      |       |          |       |   |      |          |  |
|                                       | G3010                         | Water Supply                    | Domestic          | 100    | None | Minor | Moderate | Major |   |      | \$0      | Enter LF of pipe in cell E143              |
|                                       |                               |                                 | Fire              |        | None | Minor | Moderate | Major |   |      | \$0      | Enter LF of pipe in cell E144              |
|                                       | G3020                         | Sanitary Sewer                  |                   |        | None | Minor | Moderate | Major |   |      | \$0      | Enter LF of sewer lines in cell E145       |
|                                       | G3030                         | Storm Sewer                     |                   | 100    | None | Minor | Moderate | Major |   |      | \$0      | Enter SF of area to be drained             |
|                                       | G3040                         | Heating Distribution            |                   |        | None | Minor | Moderate | Major |   |      | \$0      | Enter LF of heating ducts in cell E147     |
|                                       | G3050                         | Cooling Distribution            |                   |        | None | Minor | Moderate | Major |   |      | \$0      | Enter LF of duct work in cell E148         |
|                                       | G3060                         | Fuel Distribution               |                   |        | None | Minor | Moderate | Major |   |      | \$0      | Enter LF of natural gas lines in cell E149 |
| G3090 Other Site Mechanical Utilities |                               |                                 |                   |        |      |       |          |       |   |      |          |  |
|                                       | G40 Site Electrical Utilities |                                 |                   |        | None | Minor | Moderate | Major |   |      |          |  |
|                                       | G4010                         | Electrical Distribution         | Service Generator | 100%   | None | Minor | Moderate | Major |   |      | \$0      |  |
|                                       |                               |                                 |                   |        | None | Minor | Moderate | Major |   |      | \$0      |  |
|                                       | G4020                         | Site Lighting                   |                   | 100%   | None | Minor | Moderate | Major |   |      | \$0      |  |
|                                       | G4030                         | Site Communications & Security  |                   |        | None | Minor | Moderate | Major |   |      | \$0      |  |
|                                       | G4090                         | Other Site Electrical Utilities | NOT USED          |        | None | Minor | Moderate | Major |   |      |          |  |
| G90 Other Site Construction           |                               |                                 |                   |        |      |       |          |       |   |      |          |  |

**OTHER**

| Description of System | Unit of Measure | Quantity | Unit Budget | Extended | Notes |
|-----------------------|-----------------|----------|-------------|----------|-------|
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |

Physical Condition Budget Sub-Total \$1,305,399  
 Budgeted Development Costs \$496,052  
 Physical Condition Budget TOTAL \$1,801,451  
 Cost with Escalation to June 2021 \$2,053,654  
 Cost with Escalation to June 2022 \$2,135,800  
 Cost with Escalation to June 2023 \$2,221,232

Replacement Budget \$21,017,598  
 Facility Condition Index (FCI) 9.8%





**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Shaver Elementary School  
 Building Name: Main  
 Building ID: 21810400

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                      |
|---------------------------|---------|---------|-----------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|----------------------------|
|                           |         |         |                       |                         | None            | Minor | Moderate | Major |                               |                       |                           |                            |
| <b>C INTERIORS</b>        |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
| C10 Interior Construction |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         | C1010   | Partitions            |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                            |
|                           |         |         | Framed Masonry        | 85%                     | X               | None  |          |       |                               |                       |                           |                            |
|                           |         |         | Wood                  | 15%                     | X               | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Hollow Metal          | 100                     |                 | None  | X        | Major | Replace                       | 50%                   | \$51,528                  | Upgrade hardware           |
|                           |         |         | NOT USED              | 17                      |                 | None  | X        | Major | Replace                       | 100%                  | \$17,520                  | Upgrade hardware + repaint |
| C20 Stairs                |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         | C2010   | Stair Construction    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Cost/Flight                |
|                           |         |         | Wood                  |                         |                 | None  |          |       |                               |                       |                           |                            |
|                           |         |         | Metal                 |                         |                 | None  |          |       |                               |                       |                           | Cost/Flight                |
|                           |         |         | Concrete              | 1                       | X               | None  |          |       | Replace                       |                       | \$0                       | Cost/Flight                |
|                           |         |         | Concrete Fill         | 1                       | X               | None  |          |       | Replace                       |                       | \$0                       | Cost/Flight                |
|                           |         |         | Resilient             |                         |                 | None  |          |       | Replace                       |                       | \$0                       | Cost/Flight                |
| C30 Interior Finishes     |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         | C3010   | Wall Finishes         |                         | None            | Minor | Moderate | Major | Replace                       | 25%                   | \$3,168                   | Clear sealer on masonry    |
|                           |         |         | Paint on Masonry      | 10%                     |                 | None  |          |       |                               |                       |                           |                            |
|                           |         |         | Wallboard             | 90%                     |                 | None  | X        | Major | Replace                       | 30%                   | \$37,576                  |                            |
|                           |         |         | Wainscot              |                         |                 | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Ceramic Tile          |                         |                 | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Carpet / Soft Surface | 5%                      |                 | None  |          |       | X                             | 50%                   | \$9,448                   |                            |
|                           |         |         | Resilient Tile        | 70%                     |                 | None  |          |       | X                             | 10%                   | \$26,929                  |                            |
|                           |         |         | Resilient Sheet       | 15%                     |                 | None  |          |       | X                             | 20%                   | \$20,366                  |                            |
|                           |         |         | Polished Concrete     |                         | X               | None  |          |       | Replace                       |                       | \$0                       | Sealed concrete            |
|                           |         |         | Ceramic Tile          | 5%                      |                 | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Liquid Applied        | 5%                      | X               | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Wood Sports Floor     |                         |                 | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Wallboard             | 20%                     | X               | None  |          |       | Replace                       |                       | \$0                       |                            |
|                           |         |         | Lay-in Ceiling Tile   | 30%                     |                 | None  |          |       | Replace                       | 25%                   | \$4,243                   |                            |
|                           |         |         | Glued-Up Ceiling Tile | 40%                     |                 | None  |          |       | Replace                       | 20%                   | \$2,942                   |                            |
|                           |         |         | Painted Structure     | 10%                     | X               | None  |          |       | Replace                       |                       | \$0                       |                            |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Shaver Elementary School  
 Building Name: Main  
 Building ID: 21810400

| Level 1   | Level 2 | Level 3 | Type (as applicable)                    | LEVEL OF ACTION         |      |       |          |          | Automated Budget Estimate | Notes   |                               |                       |   |
|---|---------|---------|---|-------------------------|------|-------|----------|----------|---------------------------|---------|-------------------------------|-----------------------|---|
|   |         |         |   | % of Building or Number | None | Minor | Moderate | Major    |                           |         | Replace as part of Renovation | % of System or Finish |   |
| <b>D SERVICES</b>                               |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
| <b>D10 Conveying</b>                            |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | D1010 Elevators & Lifts                 | 0                       | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | D1020 Escalators & Moving Walks         | 0                       | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | D1090 Other Conveying Systems           | 0                       | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D20 Plumbing</b>                             |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | D2010 Plumbing Fixtures                 | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | All (N) fixtures need to meet ADA by code.  |
|   |         |         | D2020 Domestic Water Distribution       | 100%                    | Y    | None  | Minor    | Moderate | Major                     | Replace | 100%                          | \$30,000              | Replace existing old NG DRW   |
|   |         |         | D2030 Sanitary Waste                    | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | D2040 Rain Water Drainage               | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | D2090 Other Plumbing Systems            |                         | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D30 HVAC</b>                                 |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | D3010 Energy Supply                     | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | NG on site  |
|   |         |         | D3020 Heat Generating Systems           | 75%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | Boiler installed 2013, serves majority of the building except new MPR + main office   |
|   |         |         | Boiler                                  |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | Air Handler                             | 100%                    | Y    | None  | Minor    | Moderate | Major                     | Replace | 75%                           | \$80,000              | DD unit for most areas, HP furnaces for main office, DOAS for MPR. Refurbish DD unit  |
|   |         |         | Furnace                                 | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Heat Exchanger                          | 15%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | DOAS unit with heat recover for new MPR installed in 2013   |
|   |         |         | Component of air handler                | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D3030 Cooling Generating Systems</b>         |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | Stand alone chiller                     | 25%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   | (2) Aermec reversible air/water heat pumps on roof provides chilled water + heating water to MPR floor radiant panel installed in 2014, (2) split HPs to furnaces serving main office area (2014) |
| <b>D3040 Distribution Systems</b>               |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | Ductwork                                | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D3050 Terminal &amp; Package Units</b>       |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | Hot water return & supply               | 75%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Above ceiling VAV unit                  | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | In-room ventilator unit                 | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | In-room radiant unit                    | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D3060 Controls &amp; Instrumentation</b>     |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
| <b>D3070 Systems Testing &amp; Balancing</b>    |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
| <b>D3090 Other HVAC Systems &amp; Equipment</b> |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
| <b>D40 Fire Protection</b>                      |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | D4010 Sprinklers                        | 85%                     | Y    | None  | Minor    | Moderate | Major                     | Replace | 100%                          | \$40,000              | Add fire sprinkler system for multi-purpose room  |
|   |         |         | D4020 Standpipes                        | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | D4030 Fire Protection Specialties       | 0%                      | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D4090 Other Fire Protection Systems</b>      |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
| <b>D50 Electrical</b>                           |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |
|   |         |         | D5010 Electrical Service & Distribution | 100%                    | Y    | None  | Minor    | Moderate | Major                     | Replace | 15%                           | \$65,000              | Replace old electrical panels   |
|   |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y    | None  | Minor    | Moderate | Major                     | Replace | 100%                          | \$100,000             | Lighting and lighting control retrofit  |
|   |         |         | D5030 Communications & Security         | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Voice / Data System                     | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Clock / Intercom System                 | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Closed Circuit Surveillance             | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Access Control System                   | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Intrusion Alarm System                  | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Fire Alarm / Detection                  | 100%                    | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
|   |         |         | Lighting Control System                 | 35%                     | N    | None  | Minor    | Moderate | Major                     | Replace | 0%                            | \$0                   |   |
| <b>D5090 Other Electrical Systems</b>           |         |         |   |                         |      |       |          |          |                           |         |                               |                       |   |



**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Parkrose Middle School  
 Building Name: Main  
 Building ID: 21810500

| Level 1                   | Level 2 | Level 3 | Type (as applicable)       | LEVEL OF ACTION         |      |       |          |       | Automated Budget Estimate | Notes    |
|---------------------------|---------|---------|----------------------------|-------------------------|------|-------|----------|-------|---------------------------|----------|
|                           |         |         |                            | % of Building or Number | None | Minor | Moderate | Major |                           |          |
| <b>A SUBSTRUCTURE</b>     |         |         |                            |                         |      |       |          |       |                           |          |
| A10 Foundations           |         |         |                            |                         |      |       |          |       |                           |          |
|                           |         |         | A1010 Standard Foundations | 20%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | A1020 Special Foundations  |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | A1030 Slab on Grade        | 80%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
| A20 Basement Construction |         |         |                            |                         |      |       |          |       |                           |          |
|                           |         |         | A2010 Basement Excavation  |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | A2020 Basement Walls       | 100%<br>X               | None | Minor | Moderate | Major | Replace                   | \$0      |
| <b>B SHELL</b>            |         |         |                            |                         |      |       |          |       |                           |          |
| B10 Superstructure        |         |         |                            |                         |      |       |          |       |                           |          |
|                           |         |         | B1010 Floor Construction   |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Wood                       | 100%<br>X               | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Steel                      |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Concrete                   |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Wood                       |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Steel                      | 100%<br>X               | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Concrete                   |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
| B20 Exterior Enclosure    |         |         |                            |                         |      |       |          |       |                           |          |
|                           |         |         | B2010 Exterior Walls       |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Concrete Formed / Tilt     |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Masonry                    | 15%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Framed w/ Wood Siding      |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Framed w/ Metal Panel      | 15%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Framed w/ Stucco           |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Framed w/ Masonry Veneer   | 70%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Wood                       |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Aluminum/Steel             | 100%<br>X               | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Clad                       |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Curtain Wall               |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Wood                       |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Hollow Metal               | 18                      | None | Minor | Moderate | Major | Replace                   | \$1,594  |
|                           |         |         | Storefront                 | 26                      | None | Minor | Moderate | Major | Replace                   | \$20,096 |
| B30 Roofing               |         |         |                            |                         |      |       |          |       |                           |          |
|                           |         |         | B3010 Roof Coverings       |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Asphalt Shingle            |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Built-Up                   | 85%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Single Ply                 |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Metal                      | 15%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Concrete Tile              |                         | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Skylights                  | 10%<br>X                | None | Minor | Moderate | Major | Replace                   | \$0      |
|                           |         |         | Access Hatch               | 4<br>X                  | None | Minor | Moderate | Major | Replace                   | \$0      |

District Name: Parkrose SD 3  
 Site Name: Parkrose Middle School  
 Building Name: Main  
 Building ID: 21810500

REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable) | % of Building or Number  | LEVEL OF ACTION  |   |  |   | Replace as part of Renovation   | % of System or Finish  | Automated Budget Estimate                   | Notes  |
|---------------------------|---------|---------|----------------------|--|--|---|--|---|---|--|---|--|
|                           |         |         |                      |  | None   | Minor   | Moderate   | Major   |   |  |   |  |
| <b>C INTERIORS</b>        |         |         |                      |  |  |   |  |   |   |  |   |  |
| C10 Interior Construction |         |         |                      |  |  |   |  |   |   |  |   |  |
|                           |         | C1010   | Partitions           | 90%<br>10%<br>294<br>28  | None<br>None<br>None<br>None   | Minor<br>Minor<br>Minor<br>Minor  | Moderate<br>Moderate<br>Moderate<br>Moderate   | Major<br>Major<br>Major<br>Major  | X<br>Replace<br>Replace<br>Replace  | 1%   | \$28,260<br>\$0<br>\$75,746<br>\$14,428     | Cracking at corridor walls<br>Hardware<br>Hardware |
|                           |         | C1020   | Interior Doors       |  |  |   |  |   |   |  |   |  |
|                           |         | C1030   | Fittings             |  |  |   |  |   |   |  |   |  |
|                           |         | C20     | Stairs               |  |  |   |  |   |   |  |   |  |
|                           |         | C2010   | Stair Construction   | 4  | None   | Minor   | Moderate   | Major   | Replace   |  | \$0   | Cost/Flight  |
|                           |         | C2020   | Stair Finishes       | 4  | None   | Minor   | Moderate   | Major   | Replace   |  | \$0   | Cost/Flight  |
|                           |         | C2030   | Stair Finishes       | 4  | None   | Minor   | Moderate   | Major   | Replace   |  | \$0   | Cost/Flight  |
|                           |         | C2040   | Stair Finishes       | 4  | None   | Minor   | Moderate   | Major   | Replace   | 100%   | \$12,882                                    | Cost/Flight  |
|                           |         | C30     | Interior Finishes    |  |  |   |  |   |   |  |   |  |
|                           |         | C3010   | Wall Finishes        | 10%<br>65%<br>15%<br>5%<br>15%<br>10%<br>55%<br>5%<br>5%<br>10%<br>65%<br>10%<br>15% | None<br>None<br>None<br>None<br>None<br>None<br>None<br>None<br>None<br>None<br>None<br>None<br>None | Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor<br>Minor | Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate<br>Moderate | Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major<br>Major | Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace<br>Replace | \$0<br>\$0<br>\$0<br>\$33,443<br>\$0<br>\$0<br>\$0<br>\$0<br>\$0<br>\$0<br>\$0<br>\$0<br>\$0 | High traffic areas / areas with light color |  |
|                           |         | C3020   | Floor Finishes       |  |  |   |  |   |   |  |   |  |
|                           |         | C3030   | Ceiling Finishes     |  |  |   |  |   |   |  |   |  |

District Name: Parkrose SD 3  
 Site Name: Parkrose Middle School  
 Building Name: Main  
 Building ID: 21810500

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | % of Building or Number | LEVEL OF ACTION |       |          |          | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes   |
|----------------------------|---------|---------|---|-------------------------|-----------------|-------|----------|----------|-------------------------------|-----------------------|---------------------------|---|
|                            |         |         |   |                         | None            | Minor | Moderate | Major    |                               |                       |                           |   |
| <b>D SERVICES</b>          |         |         |   |                         |                 |       |          |          |                               |                       |                           |   |
| <b>D10 Conveying</b>       |         |         |   |                         |                 |       |          |          |                               |                       |                           |   |
|                            |         |         | D1010 Elevators & Lifts                 | 2                       | X               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D1020 Escalators & Moving Walks         |                         |                 | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D1090 Other Conveying Systems           |                         |                 | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
| <b>D20 Plumbing</b>        |         |         |   |                         |                 |       |          |          |                               |                       |                           |   |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | All (N) fixtures req'd to meet ADA by code.                   |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | New building & new system                                     |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D2090 Other Plumbing Systems            |                         |                 | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
| <b>D30 HVAC</b>            |         |         |   |                         |                 |       |          |          |                               |                       |                           |   |
|                            |         |         | D3010 Energy Supply                     | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | NG on site  |
|                            |         |         | D3020 Heat Generating Systems           | 90%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | Boilers were installed in 2013                                |
|                            |         |         | Boiler                                  | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | 8 RTUs and 3 AHUs for whole building                          |
|                            |         |         | Air Handler                             | 0%                      | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Furnace                                 | 5%                      | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | AHU with TX serves small gym                                  |
|                            |         |         | Heat Exchanger                          | 75%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | 8 RTUs have DX cooling for majority of the school             |
|                            |         |         | Component of air handler                | 15%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | condensing unit for one AHU serves ground floor IT department |
|                            |         |         | Stand alone chiller                     | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Ductwork                                | 90%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Hot water return & supply               | 90%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | In-room ventilator unit                 | 30%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | In-room radiant unit                    | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | NOT USED                                | 100%                    | Y               | None  | Minor    | Moderate | Major                         | X                     | \$64,000                  | Estimated for RCX   |
| <b>D40 Fire Protection</b> |         |         |   |                         |                 |       |          |          |                               |                       |                           |   |
|                            |         |         | D4010 Sprinklers                        | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D4020 Standpipes                        | 0%                      | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D4090 Other Fire Protection Systems     |                         |                 | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
| <b>D50 Electrical</b>      |         |         |   |                         |                 |       |          |          |                               |                       |                           |   |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       | Lighting and lighting control retrofit                        |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y               | None  | Minor    | Moderate | Major                         | X                     | \$215,000                 |   |
|                            |         |         | D5030 Communications & Security         | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Voice / Data System                     | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Closed Circuit Surveillance             | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Access Control System                   | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Intrusion Alarm System                  | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | Lighting Control System                 | 70%                     | N               | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | NOT USED                                |                         |                 | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |
|                            |         |         | D5090 Other Electrical Systems          |                         |                 | None  | Minor    | Moderate | Major                         |                       | \$0                       |   |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Parkrose Middle School  
 Building Name: Main  
 Building ID: 21810500

| Level 1                              | Level 2 | Level 3              | Type (as applicable)        | % of Building or Number | LEVEL OF ACTION |       |          |          | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes |
|--------------------------------------|---------|----------------------|-----------------------------|-------------------------|-----------------|-------|----------|----------|-------------------------------|-----------------------|---------------------------|-------|
|                                      |         |                      |                             |                         | None            | Minor | Moderate | Major    |                               |                       |                           |       |
| <b>E EQUIPMENT &amp; FURNISHINGS</b> |         |                      |                             |                         |                 |       |          |          |                               |                       |                           |       |
| E10 Equipment                        |         |                      |                             |                         |                 |       |          |          |                               |                       |                           |       |
|                                      | E1010   | Commercial Equipment | Food Service                | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      |         |                      | Vocational                  | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      |         |                      | Science                     | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      |         |                      | Art                         | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      |         |                      | Stage Performance           | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      |         |                      | Restroom Accessories/Stalls | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      |         |                      | NOT USED                    |                         |                 | None  | Minor    | Moderate | Major                         | Replace               |                           |       |
|                                      |         |                      | NOT USED                    |                         |                 | None  | Minor    | Moderate | Major                         | Replace               |                           |       |
| E20 Furnishings                      |         |                      |                             |                         |                 |       |          |          |                               |                       |                           |       |
|                                      | E2010   | Fixed Furnishings    |                             | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |
|                                      | E2020   | Movable Furnishings  |                             | 100%                    | X               | None  | Minor    | Moderate | Major                         | Replace               | \$0                       |       |

**F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED**

**G BUILDING SITE WORK**

|                               |       |                                 |           |        |   |      |       |          |       |         |     |  |
|-------------------------------|-------|---------------------------------|-----------|--------|---|------|-------|----------|-------|---------|-----|--|
| G10 Site Preparation          |       |                                 |           |        |   |      |       |          |       |         |     |  |
| G20 Site Improvements         |       |                                 |           |        |   |      |       |          |       |         |     |  |
|                               | G2010 | Roadways                        |           | 81308  | X | None | Minor | Moderate | Major | Replace | \$0 | Cost/SF of surface area                    |
|                               | G2020 | Parking Lots                    |           | 13161  | X | None | Minor | Moderate | Major | Replace | \$0 | Cost/SF of surface area                    |
|                               | G2030 | Pedestrian Paving               |           | 47607  | X | None | Minor | Moderate | Major | Replace | \$0 | Cost/SF of surface area                    |
|                               | G2040 | Site Development                |           | 2051   | X | None | Minor | Moderate | Major | Replace | \$0 | Cost/LF of fencing                         |
|                               | G2050 | Landscaping                     |           | 241032 | X | None | Minor | Moderate | Major | Replace | \$0 | Cost/SF of irrigated area                  |
| G30 Site Mechanical Utilities |       |                                 |           |        |   |      |       |          |       |         |     |  |
|                               | G3010 | Water Supply                    | Domestic  | 100    | X | None | Minor | Moderate | Major | Replace | \$0 | Enter LF of pipe in cell E143              |
|                               |       |                                 | Fire      | 100    | X | None | Minor | Moderate | Major | Replace | \$0 | Enter LF of pipe in cell E144              |
|                               | G3020 | Sanitary Sewer                  |           | 100    | X | None | Minor | Moderate | Major | Replace | \$0 | Enter LF of sewer lines in cell E145       |
|                               | G3030 | Storm Sewer                     |           |        |   | None | Minor | Moderate | Major | Replace | \$0 | Enter SF of area to be drained             |
|                               | G3040 | Heating Distribution            |           |        |   | None | Minor | Moderate | Major | Replace | \$0 | Enter SF of area to be heated              |
|                               | G3050 | Cooling Distribution            |           |        |   | None | Minor | Moderate | Major | Replace | \$0 | Enter LF of heating ducts in cell E147     |
|                               | G3060 | Fuel Distribution               |           |        |   | None | Minor | Moderate | Major | Replace | \$0 | Enter LF of duct work in cell E148         |
|                               | G3090 | Other Site Mechanical Utilities | NOT USED  |        |   | None | Minor | Moderate | Major | Replace | \$0 | Enter LF of natural gas lines in cell E149 |
| G40 Site Electrical Utilities |       |                                 |           |        |   |      |       |          |       |         |     |  |
|                               | G4010 | Electrical Distribution         | Service   | 100%   | X | None | Minor | Moderate | Major | Replace | \$0 |  |
|                               |       |                                 | Generator |        |   | None | Minor | Moderate | Major | Replace | \$0 |  |
|                               | G4020 | Site Lighting                   |           | 100%   | X | None | Minor | Moderate | Major | Replace | \$0 |  |
|                               | G4030 | Site Communications & Security  |           |        |   | None | Minor | Moderate | Major | Replace | \$0 |  |
|                               | G4090 | Other Site Electrical Utilities | NOT USED  |        |   | None | Minor | Moderate | Major | Replace | \$0 |  |
| G90 Other Site Construction   |       |                                 |           |        |   |      |       |          |       |         |     |  |

| Description of System | Unit of Measure | Quantity | Unit Budget | Extended | Notes |
|-----------------------|-----------------|----------|-------------|----------|-------|
|                       |                 |          |             |          |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |

Physical Condition Budget Sub-Total \$475,448  
 Budgeted Development Costs \$180,670  
**Physical Condition Budget TOTAL \$656,118**  
 Cost with Escalation to June 2021 \$747,975  
**Cost with Escalation to June 2022 \$777,894**  
 Cost with Escalation to June 2023 \$809,010

Replacement Budget \$83,149,944  
 Facility Condition Index (FCI) 0.9%



**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Parkrose High School  
 Building Name: Main  
 Building ID: 21810600

| Level 1                   | Level 2 | Level 3 | Type (as applicable)       | % of Building or Number | LEVEL OF ACTION |       |          |       |                               | Automated Budget Estimate | Notes       |                                  |
|---------------------------|---------|---------|----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|---------------------------|-------------|----------------------------------|
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace as part of Renovation |                           |             | % of System or Finish            |
| <b>A SUBSTRUCTURE</b>     |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
| A10 Foundations           |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
|                           |         |         | A1010 Standard Foundations |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         | A1020 Special Foundations  |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         | A1030 Slab on Grade        | 100%                    | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
| A20 Basement Construction |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
|                           |         |         | A2010 Basement Excavation  |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         | A2020 Basement Walls       | 100%                    | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
| <b>B SHELL</b>            |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
| B10 Superstructure        |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
|                           |         |         | B1010 Floor Construction   | 65%                     | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 35%                     | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 25%                     | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 75%                     | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         | B1020 Roof Construction    |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
| B20 Exterior Enclosure    |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
|                           |         |         | B2010 Exterior Walls       | 8%                      |                 | Minor | Moderate | Major | Replace                       | 50%                       | \$43,624    | Repair / repaint exterior of FAB |
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 10%                     | X               | Minor | Moderate | Major | Replace                       | 100%                      | \$976,515   |                                  |
|                           |         |         |                            | 50%                     |                 | Minor | Moderate | Major | Replace                       | 20%                       | \$52,832    |                                  |
|                           |         |         |                            | 32%                     |                 | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 90%                     | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 10%                     | X               | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
|                           |         |         |                            | 63                      |                 | Minor | Moderate | Major | Replace                       | 50%                       | \$40,578    | Upgrade hardware                 |
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         |                                  |
| B30 Roofing               |         |         |                            |                         |                 |       |          |       |                               |                           |             |                                  |
|                           |         |         | B3010 Roof Coverings       | 30%                     |                 | Minor | Moderate | Major | Replace                       | 100%                      | \$400,673   |                                  |
|                           |         |         |                            | 40%                     |                 | Minor | Moderate | Major | Replace                       | 100%                      | \$1,518,129 |                                  |
|                           |         |         |                            | 10%                     |                 | Minor | Moderate | Major | Replace                       | 10%                       | \$107,383   | Underside of entry canopies      |
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         | By Building GSF                  |
|                           |         |         |                            |                         | None            | Minor | Moderate | Major | Replace                       |                           | \$0         | Per hatch                        |

District Name: Parkrose SD 3  
 Site Name: Parkrose High School  
 Building Name: Main  
 Building ID: 21810600

**REMINER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION         |                              |                                  |  |                                  | Replace as part of Renovation            | % of System or Finish               | Automated Budget Estimate                   | Notes |
|---------------------------|---------|---------|-----------------------|-------------------------|-------------------------|------------------------------|----------------------------------|--|----------------------------------|--|-------------------------------------|---|-------|
|                           |         |         |                       |                         | None                    | Minor                        | Moderate                         | Major  | Major                            |  |                                     |   |       |
| <b>C INTERIORS</b>        |         |         |                       |                         |                         |                              |                                  |  |                                  |  |                                     |   |       |
| C10 Interior Construction |         |         |                       |                         |                         |                              |                                  |  |                                  |  |                                     |   |       |
|                           |         | C1010   | Partitions            |                         | 90%<br>10%<br>390<br>42 | None<br>None<br>None<br>None | Minor<br>Minor<br>Minor<br>Minor | Moderate<br>Moderate<br>Moderate<br>Moderate | Major<br>Major<br>Major<br>Major | Replace<br>Replace<br>Replace<br>Replace | \$0<br>\$0<br>\$140,671<br>\$43,284 | Upgrade hardware<br>Upgrade hardware, paint |       |
|                           |         | C1020   | Interior Doors        |                         |                         | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 | Cost/Flight                                 |       |
|                           |         | C1030   | Fittings              |                         |                         | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 | Cost/Flight                                 |       |
|                           |         | C20     | Stairs                |                         |                         | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 | Cost/Flight                                 |       |
|                           |         | C2010   | Stair Construction    |                         | 8                       | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 | Cost/Flight                                 |       |
|                           |         | C2020   | Stair Finishes        |                         | 4                       | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 | Cost/Flight                                 |       |
|                           |         | C2030   | Stair Finishes        |                         | 4                       | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$6,441                             | Cost/Flight                                 |       |
|                           |         | C30     | Interior Finishes     |                         |                         | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$22,550                            |   |       |
|                           |         | C3010   | Wall Finishes         |                         | 10%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3010   | Wallboard             |                         | 60%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$22,483                            |   |       |
|                           |         | C3010   | Wainscot              |                         | 20%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Floor Finishes        |                         | 10%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$252,183                           |   |       |
|                           |         | C3020   | Carpet / Soft Surface |                         | 15%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$84,658                            |   |       |
|                           |         | C3020   | Resilient Tile        |                         | 53%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Resilient Sheet       |                         | 7%                      | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$24,161                            | FAB Concrete floors in classrooms           |       |
|                           |         | C3020   | Polished Concrete     |                         | 8%                      | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Ceramic Tile          |                         | 10%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Liquid Applied        |                         |                         | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Wood Sports Floor     |                         | 7%                      | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Wallboard             |                         | 20%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Lay-in Ceiling Tile   |                         | 58%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$29,195                            |   |       |
|                           |         | C3020   | Glued-Up Ceiling Tile |                         | 10%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$0                                 |   |       |
|                           |         | C3020   | Painted Structure     |                         | 12%                     | None                         | Minor                            | Moderate                                     | Major                            | Replace                                  | \$25,852                            | Exterior canopies at entry peeling          |       |





**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Summer Elementary School  
 Building Name: Main  
 Building ID: 21810005

| Level 1                   | Level 2 | Level 3 | Type (as applicable)       | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                     |
|---------------------------|---------|---------|----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|---|
|                           |         |         |                            |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
| <b>A SUBSTRUCTURE</b>     |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
| A10 Foundations           |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
|                           |         |         | A1010 Standard Foundations |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | A1020 Special Foundations  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | A1030 Slab on Grade        | 100%                    | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| A20 Basement Construction |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
|                           |         |         | A2010 Basement Excavation  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | A2020 Basement Walls       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| <b>B SHELL</b>            |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
| B10 Superstructure        |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
|                           |         |         | B1010 Floor Construction   | 100%                    | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Concrete                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | B1020 Roof Construction    | 70%                     | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Concrete                   | 30%                     | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| B20 Exterior Enclosure    |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
|                           |         |         | B2010 Exterior Walls       | 100%                    |                 | Minor | Moderate | Major | Replace                       | 25%                   | \$44,902                  | Exterior cracks visible, repaint          |
|                           |         |         | Concrete Formed / Tilt     |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Masonry                    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Framed w/ Wood Siding      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Framed w/ Metal Panel      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Framed w/ Stucco           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Framed w/ Masonry Veneer   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Wood                       | 10%                     |                 | Minor | Moderate | Major | Replace                       | 100%                  | \$51,395                  |   |
|                           |         |         | Aluminum/Steel             | 90%                     |                 | Minor | Moderate | Major | Replace                       | 100%                  | \$497,374                 | Glass block replacement                   |
|                           |         |         | Clad                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Curtain Wall               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Hollow Metal               | 26                      |                 | Minor | Moderate | Major | Replace                       | 100%                  | \$33,493                  | Upgrade / replace hardware, paint         |
|                           |         |         | Storefront                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| B30 Roofing               |         |         |                            |                         |                 |       |          |       |                               |                       |                           |   |
|                           |         |         | B3010 Roof Coverings       | 100%                    |                 | Minor | Moderate | Major | Replace                       | 100%                  | \$1,436,858               | Complete replacement within next 10 years |
|                           |         |         | Asphalt Shingle            |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Built-Up                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Single Ply                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Metal                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Concrete Tile              |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                           |         |         | Skylights                  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | By Building OSF                           |
|                           |         |         | Access Hatch               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Per hatch                                 |

District Name: Parkrose SD 3  
 Site Name: Summer Elementary School  
 Building Name: Main  
 Building ID: 21810005

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION |       |          |       |   | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                             |
|---------------------------|---------|---------|-----------------------|-------------------------|-----------------|-------|----------|-------|---|-------------------------------|-----------------------|---------------------------|-----------------------------------|
|                           |         |         |                       |                         | None            | Minor | Moderate | Major |   |                               |                       |                           |                                   |
| <b>C INTERIORS</b>        |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
| C10 Interior Construction |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
|                           |         | C1010   | Partitions            |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Framed Masonry        | 70%                     | X               |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Wood                  | 30%                     | X               |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Hollow Metal          | 73                      |                 | X     |          |       |   | Replace                       |                       | \$75,231                  | Upgrade / replace hardware        |
|                           |         |         | NOT USED              | 22                      |                 | X     |          |       |   | Replace                       |                       | \$22,672                  | Upgrade / replace hardware, paint |
| C20 Stairs                |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
|                           |         | C2010   | Stair Construction    |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Wood                  |                         |                 |       |          |       |   | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Metal                 |                         |                 |       |          |       |   | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Concrete              |                         |                 |       |          |       |   | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Concrete Fill         |                         |                 |       |          |       |   | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Resilient             |                         |                 |       |          |       |   | Replace                       |                       | \$0                       | Cost/Flight                       |
| C30 Interior Finishes     |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
|                           |         | C3010   | Wall Finishes         |                         | None            | Minor | Moderate | Major |   | Replace                       | 15%                   | \$9,284                   |                                   |
|                           |         |         | Paint on Masonry      | 50%                     | X               |       |          |       |   | Replace                       |                       | \$12,559                  |                                   |
|                           |         |         | Wallboard             | 45%                     | X               |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Wainscot              | 5%                      | X               |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Ceramic Tile          |                         |                 |       |          |       |   | Replace                       | 100%                  | \$129,207                 |                                   |
|                           |         |         | Carpet / Soft Surface | 35%                     |                 |       |          |       | X | Replace                       |                       | \$150,317                 |                                   |
|                           |         |         | Resilient Tile        | 40%                     |                 |       |          |       | X | Replace                       |                       | \$66,317                  |                                   |
|                           |         |         | Resilient Sheet       | 10%                     |                 |       |          |       | X | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Polished Concrete     | 5%                      | X               |       |          |       |   | Replace                       |                       | \$138,933                 |                                   |
|                           |         |         | Ceramic Tile          | 10%                     |                 |       |          |       | X | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Liquid Applied        |                         |                 |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Wood Sports Floor     |                         |                 |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Wallboard             | 15%                     |                 |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Ceiling Finishes      | 15%                     | X               |       |          |       |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Lay-in Ceiling Tile   | 60%                     | X               |       |          |       |   | Replace                       | 25%                   | \$39,293                  |                                   |
|                           |         |         | Glued-Up Ceiling Tile | 10%                     |                 |       |          |       | X | Replace                       |                       | \$8,870                   | Repaint                           |
|                           |         |         | Painted Structure     | 10%                     |                 |       |          |       | X | Replace                       |                       |                           |                                   |

District Name: Parkrose SD 3  
 Site Name: Summer Elementary School  
 Building Name: Main  
 Building ID: 21810005

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                       |
|----------------------------|---------|---------|---|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|---|
|                            |         |         |   |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
| <b>D SERVICES</b>          |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
| <b>D10 Conveying</b>       |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D1010 Elevators & Lifts                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                            |         |         | D1020 Escalators & Moving Walks         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                            |         |         | D1090 Other Conveying Systems           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| <b>D20 Plumbing</b>        |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$240,000                 | All (N) fixtures req'd to meet ADA by code. |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$30,000                  | Replace existing old DRHW                   |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D2090 Other Plumbing Systems            |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D30 HVAC</b>            |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D3010 Energy Supply                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | NG on site                                  |
|                            |         |         | D3020 Heat Generating Systems           | 90%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$800,000                 | Upgrade boiler and heating water piping     |
|                            |         |         | Boiler                                  | 90%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$550,000                 | Replace existing HVS and coil heaters       |
|                            |         |         | Air Handler                             | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Furnace                                 | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Heat Exchanger                          | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Component of air handler                | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Stand alone chiller                     | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Ductwork                                | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Hot water return & supply               | 90%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$0                       | Included in boiler replacement item         |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | In-room ventilator unit                 | 60%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$0                       | coil booster heaters included in AHU item   |
|                            |         |         | In-room radiant unit                    | 0%                      | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$300,000                 | upgrade to district BAS                     |
|                            |         |         | D3090 Other HVAC Systems & Equipment    | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$22,000                  | Estimated for RCX                           |
| <b>D40 Fire Protection</b> |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D4010 Sprinklers                        | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4020 Standpipes                        | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4090 Other Fire Protection Systems     |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D50 Electrical</b>      |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 35%                   | \$100,000                 | Replace old electrical panels               |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$50,000                  | Lighting and lighting control retrofit      |
|                            |         |         | D5030 Communications & Security         | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Voice / Data System                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Clock / Intercom System                 | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Closed Circuit Surveillance             | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Access Control System                   | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Intrusion Alarm System                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Lighting Control System                 | 5%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D5090 Other Electrical Systems          |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |

**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Summer Elementary School  
 Building Name: Main  
 Building ID: 21810005

| Level 1                              | Level 2 | Level 3              | Type (as applicable)        | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes |
|--------------------------------------|---------|----------------------|-----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|-------|
|                                      |         |                      |                             |                         | None            | Minor | Moderate | Major |                               |                       |                           |       |
| <b>E EQUIPMENT &amp; FURNISHINGS</b> |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |       |
| E10 Equipment                        |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |       |
|                                      | E1010   | Commercial Equipment | Food Service                | 10%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$4,974                   |       |
|                                      |         |                      | Vocational Science          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |       |
|                                      |         |                      | Art                         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |       |
|                                      |         |                      | Stage Performance           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |       |
|                                      |         |                      | Restroom Accessories/Stalls |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$109,422                 |       |
|                                      |         |                      | NOT USED                    | 100%                    | None            | Minor | Moderate | Major | Replace                       | 100%                  |                           |       |
|                                      |         |                      | NOT USED                    |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |       |
| E20 Furnishings                      |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |       |
|                                      | E2010   | Fixed Furnishings    |                             | 50%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$51,672                  |       |
|                                      | E2020   | Movable Furnishings  |                             | 50%                     | None            | Minor | Moderate | Major | Replace                       | 25%                   | \$165,791                 |       |

**F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED**

**G BUILDING SITE WORK**

|                               |       |                                 |                   |        |      |       |          |       |         |      |           |  |
|-------------------------------|-------|---------------------------------|-------------------|--------|------|-------|----------|-------|---------|------|-----------|--|
| G10 Site Preparation          |       |                                 |                   |        |      |       |          |       |         |      |           |  |
| G20 Site Improvements         |       |                                 |                   |        |      |       |          |       |         |      |           |  |
|                               | G2010 | Roadways                        |                   | 11507  | None | Minor | Moderate | Major | Replace | 100% | \$96,352  | Cost/SF of surface area                    |
|                               | G2020 | Parking Lots                    |                   | 19494  | None | Minor | Moderate | Major | Replace | 75%  | \$122,422 | Cost/SF of surface area                    |
|                               | G2030 | Pedestrian Paving               |                   | 1024   | None | Minor | Moderate | Major | Replace | 50%  | \$5,936   | Cost/SF of surface area                    |
|                               | G2040 | Site Development                |                   | 1261   | None | Minor | Moderate | Major | Replace |      | \$0       | Cost/LF of fencing                         |
|                               | G2050 | Landscaping                     |                   | 260459 | None | Minor | Moderate | Major | Replace |      | \$0       | Cost/SF of irrigated area                  |
| G30 Site Mechanical Utilities |       |                                 |                   |        |      |       |          |       |         |      |           |  |
|                               | G3010 | Water Supply                    | Domestic          | 100    | None | Minor | Moderate | Major | Replace |      | \$0       | Enter LF of pipe in cell E143              |
|                               |       |                                 | Fire              |        | None | Minor | Moderate | Major | Replace |      | \$0       | Enter LF of pipe in cell E144              |
|                               | G3020 | Sanitary Sewer                  |                   |        | None | Minor | Moderate | Major | Replace |      | \$0       | Enter LF of sewer lines in cell E145       |
|                               | G3030 | Storm Sewer                     |                   | 100    | None | Minor | Moderate | Major | Replace |      | \$0       | Enter SF of area to be drained             |
|                               | G3040 | Heating Distribution            |                   |        | None | Minor | Moderate | Major | Replace |      | \$0       | Enter LF of heating ducts in cell E147     |
|                               | G3050 | Cooling Distribution            |                   |        | None | Minor | Moderate | Major | Replace |      | \$0       | Enter LF of duct work in cell E148         |
|                               | G3060 | Fuel Distribution               |                   |        | None | Minor | Moderate | Major | Replace |      | \$0       | Enter LF of natural gas lines in cell E149 |
|                               | G3090 | Other Site Mechanical Utilities | NOT USED          |        | None | Minor | Moderate | Major | Replace |      |           |  |
| G40 Site Electrical Utilities |       |                                 |                   |        |      |       |          |       |         |      |           |  |
|                               | G4010 | Electrical Distribution         | Service Generator | 100%   | None | Minor | Moderate | Major | Replace |      | \$0       |  |
|                               |       |                                 |                   |        | None | Minor | Moderate | Major | Replace |      | \$0       |  |
|                               | G4020 | Site Lighting                   |                   | 100%   | None | Minor | Moderate | Major | Replace |      | \$0       |  |
|                               | G4030 | Site Communications & Security  |                   |        | None | Minor | Moderate | Major | Replace |      | \$0       |  |
|                               | G4090 | Other Site Electrical Utilities | NOT USED          |        | None | Minor | Moderate | Major | Replace |      |           |  |
| G90 Other Site Construction   |       |                                 |                   |        |      |       |          |       |         |      |           |  |

**OTHER**

| Description of System | Unit of Measure | Quantity | Unit Budget | Extended | Notes |
|-----------------------|-----------------|----------|-------------|----------|-------|
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |

Physical Condition Budget Sub-Total \$5,405,274  
 Budgeted Development Costs \$2,054,004  
 Physical Condition Budget TOTAL \$7,459,277  
 Cost with Escalation to June 2021 \$8,503,576  
 Cost with Escalation to June 2022 \$8,843,719  
 Cost with Escalation to June 2023 \$9,197,468

Replacement Budget \$21,934,341  
 Facility Condition Index (FCI) 38.8%



**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Thompson Elementary School  
 Building Name: Main  
 Building ID: 21810004

| Level 1                   | Level 2 | Level 3              | Type (as applicable)           | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                 |
|---------------------------|---------|----------------------|--------------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|---------------------------------------|
|                           |         |                      |                                |                         | None            | Minor | Moderate | Major |                               |                       |                           |                                       |
| <b>A SUBSTRUCTURE</b>     |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
| A10 Foundations           |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
|                           | A1010   | Standard Foundations |                                |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           | A1020   | Special Foundations  |                                |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           | A1030   | Slab on Grade        |                                | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
| A20 Basement Construction |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
|                           | A2010   | Basement Excavation  | NOT USED                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           | A2020   | Basement Walls       |                                |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
| <b>B SHELL</b>            |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
| B10 Superstructure        |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
|                           | B1010   | Floor Construction   | Wood                           | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Steel                          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Concrete                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           | B1020   | Roof Construction    | Wood                           | 70%                     | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Steel                          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Concrete                       | 30%                     | None            | Minor | Moderate | Major | Replace                       | 15%                   | \$45,811                  | Concrete canopy at entry needs repair |
| B20 Exterior Enclosure    |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
|                           | B2010   | Exterior Walls       | Concrete Formed / Tilt Masonry | 80%                     | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Framed w/ Wood Siding          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Framed w/ Metal Panel          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Framed w/ Stucco               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Framed w/ Masonry Veneer       | 20%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$31,943                  | Clean / repaint / reseal brick        |
|                           |         |                      | Wood                           | 10%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$60,381                  | Glass block replacement               |
|                           |         |                      | Aluminum/Steel                 | 90%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$584,328                 |                                       |
|                           |         |                      | Clad                           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Curtain Wall                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           | B2030   | Exterior Doors       | Wood                           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Hollow Metal                   | 30                      | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$38,646                  | Upgrade / replace hardware, paint     |
|                           |         |                      | Storefront                     |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
| B30 Roofing               |         |                      |                                |                         |                 |       |          |       |                               |                       |                           |                                       |
|                           | B3010   | Roof Coverings       | Asphalt Shingle                |                         | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$0                       |                                       |
|                           |         |                      | Built-Up                       | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$381,761                 |                                       |
|                           |         |                      | Single Ply                     |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Metal                          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Concrete Tile                  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                       |
|                           |         |                      | Skylights                      | 20%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$25,970                  | Most roofed over, need framing work   |
|                           |         |                      | Access Hatch                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Per hatch                             |

District Name: Parkrose SD 3  
 Site Name: Thompson Elementary School  
 Building Name: Main  
 Building ID: 21810004

**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION |       |          |       |   | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                             |
|---------------------------|---------|---------|-----------------------|-------------------------|-----------------|-------|----------|-------|---|-------------------------------|-----------------------|---------------------------|-----------------------------------|
|                           |         |         |                       |                         | None            | Minor | Moderate | Major |   |                               |                       |                           |                                   |
| <b>C INTERIORS</b>        |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
| C10 Interior Construction |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
|                           |         | C1010   | Partitions            |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                   |
|                           |         |         | Framed Masonry        | 70%                     | X               |       |          |       |   |                               |                       |                           |                                   |
|                           |         |         | Masonry               | 30%                     | X               |       |          |       |   |                               |                       | \$0                       |                                   |
|                           |         |         | Wood                  | 72                      |                 | X     |          |       |   |                               |                       | \$74,200                  | Upgrade / replace hardware        |
|                           |         |         | Hollow Metal          | 14                      |                 | X     |          |       |   |                               |                       | \$14,428                  | Upgrade / replace hardware, paint |
|                           |         |         | NOT USED              |                         |                 |       |          |       |   |                               |                       |                           |                                   |
| C20 Stairs                |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
|                           |         | C2010   | Stair Construction    |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Wood                  |                         |                 |       |          |       |   |                               |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Metal                 |                         |                 |       |          |       |   |                               |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Concrete              |                         |                 |       |          |       |   |                               |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Concrete Fill         |                         |                 |       |          |       |   |                               |                       | \$0                       | Cost/Flight                       |
|                           |         |         | Resilient             |                         |                 |       |          |       |   |                               |                       | \$0                       | Cost/Flight                       |
| C30 Interior Finishes     |         |         |                       |                         |                 |       |          |       |   |                               |                       |                           |                                   |
|                           |         | C3010   | Wall Finishes         |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$72,716                  | Repaint                           |
|                           |         |         | Paint on Masonry      | 50%                     | X               |       |          |       |   |                               |                       | \$59,017                  | Repaint                           |
|                           |         |         | Wallboard             | 45%                     | X               |       |          |       |   |                               |                       | \$0                       |                                   |
|                           |         |         | Wainscot              | 5%                      | X               |       |          |       |   |                               |                       | \$0                       |                                   |
|                           |         |         | Ceramic Tile          |                         |                 |       |          |       |   |                               |                       | \$0                       |                                   |
|                           |         |         | Carpet / Soft Surface | 10%                     |                 |       |          |       | X |                               |                       | \$43,370                  |                                   |
|                           |         |         | Resilient Tile        | 65%                     |                 |       |          |       | X |                               |                       | \$286,970                 | ACM                               |
|                           |         |         | Polished Sheet        | 10%                     |                 |       |          |       | X |                               |                       | \$38,955                  |                                   |
|                           |         |         | Polished Concrete     | 5%                      | X               |       |          |       |   |                               |                       | \$0                       | Sealed concrete                   |
|                           |         |         | Ceramic Tile          | 10%                     |                 |       |          |       | X |                               |                       | \$163,222                 |                                   |
|                           |         |         | Liquid Applied        |                         |                 |       |          |       |   |                               |                       | \$0                       |                                   |
|                           |         |         | Wood Sports Floor     |                         |                 |       |          |       |   |                               |                       | \$0                       |                                   |
|                           |         |         | Wallboard             | 70%                     |                 |       |          |       |   |                               |                       | \$35,676                  |                                   |
|                           |         |         | Lay-in Ceiling Tile   | 10%                     | X               |       |          |       |   |                               |                       | \$1,354                   |                                   |
|                           |         |         | Glued-Up Ceiling Tile | 10%                     |                 |       |          |       | X |                               |                       | \$15,387                  |                                   |
|                           |         |         | Painted Structure     | 10%                     |                 |       |          |       | X |                               |                       | \$10,421                  | Repaint                           |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Thompson Elementary School  
 Building Name: Main  
 Building ID: 21810004

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                       |
|----------------------------|---------|---------|---|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|---|
|                            |         |         |   |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
| <b>D SERVICES</b>          |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
| <b>D10 Conveying</b>       |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D1010 Elevators & Lifts                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                            |         |         | D1020 Escalators & Moving Walks         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                            |         |         | D1090 Other Conveying Systems           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| <b>D20 Plumbing</b>        |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$270,000                 | All (N) fixtures req'd to meet ADA by code. |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | New DRW installed in 2019                   |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D2090 Other Plumbing Systems            |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D30 HVAC</b>            |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D3010 Energy Supply                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | NG on site                                  |
|                            |         |         | D3020 Heat Generating Systems           | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$800,000                 | Upgrade boiler and heating water piping     |
|                            |         |         | Boiler                                  | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$550,000                 | Replace existing HVS and coil heaters       |
|                            |         |         | Air Handler                             | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Furnace                                 | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Heat Exchanger                          | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Component of air handler                | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Stand alone chiller                     | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Ductwork                                | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | Included in boiler replacement item         |
|                            |         |         | Hot water return & supply               | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$0                       |   |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | In-room ventilator unit                 | 60%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$0                       | Coil booster heaters included in AHU item   |
|                            |         |         | In-room radiant unit                    | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D3050 Terminal & Package Units          | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$300,000                 | Upgrade to district BAS                     |
|                            |         |         | D3060 Controls & Instrumentation        | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$22,000                  | Estimated for RCX                           |
|                            |         |         | D3070 Systems Testing & Balancing       |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
|                            |         |         | D3090 Other HVAC Systems & Equipment    |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D40 Fire Protection</b> |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D4010 Sprinklers                        | 0%                      | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$250,000                 | Add fire sprinkler system                   |
|                            |         |         | D4020 Standpipes                        | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4090 Other Fire Protection Systems     |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D50 Electrical</b>      |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 45%                   | \$140,000                 | Replace old electrical panels               |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y               | Minor | Moderate | Major | Replace                       | 100%                  | \$50,000                  | Lighting and lighting control retrofit      |
|                            |         |         | D5030 Communications & Security         | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Voice / Data System                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Clock / Intercom System                 | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Closed Circuit Surveillance             | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Access Control System                   | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Intrusion Alarm System                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Lighting Control System                 | 5%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D5090 Other Electrical Systems          |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Thompson Elementary School  
 Building Name: Main  
 Building ID: 21810004

| Level 1                              | Level 2 | Level 3              | Type (as applicable)        | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes |
|--------------------------------------|---------|----------------------|-----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|-------|
|                                      |         |                      |                             |                         | None            | Minor | Moderate | Major |                               |                       |                           |       |
| <b>E EQUIPMENT &amp; FURNISHINGS</b> |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |       |
| E10 Equipment                        |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |       |
|                                      | E1010   | Commercial Equipment | Food Service                | 10%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$5,843                   |       |
|                                      |         |                      | Vocational Science          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |       |
|                                      |         |                      | Art                         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |       |
|                                      |         |                      | Stage Performance           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |       |
|                                      |         |                      | Restroom Accessories/Stalls |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$128,552                 |       |
|                                      |         |                      | NOT USED                    | 100%                    | None            | Minor | Moderate | Major | Replace                       | 100%                  |                           |       |
|                                      |         |                      | NOT USED                    |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |       |
| E20 Furnishings                      |         |                      |                             |                         |                 |       |          |       |                               |                       |                           |       |
|                                      | E2010   | Fixed Furnishings    |                             | 50%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$60,705                  |       |
|                                      | E2020   | Movable Furnishings  |                             | 50%                     | None            | Minor | Moderate | Major | Replace                       | 25%                   | \$194,776                 |       |

**F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED**

**G BUILDING SITE WORK**

|                               |       |                                 |                   |        |      |       |          |       |         |     |           |  |
|-------------------------------|-------|---------------------------------|-------------------|--------|------|-------|----------|-------|---------|-----|-----------|--|
| G10 Site Preparation          |       |                                 |                   |        |      |       |          |       |         |     |           |  |
| G20 Site Improvements         |       |                                 |                   |        |      |       |          |       |         |     |           |  |
|                               | G2010 | Roadways                        |                   | 10300  | None | Minor | Moderate | Major | Replace | 45% | \$38,810  | Significant paving cracks                  |
|                               | G2020 | Parking Lots                    |                   | 29500  | None | Minor | Moderate | Major | Replace | 50% | \$123,506 | Significant paving cracks                  |
|                               | G2030 | Pedestrian Paving               |                   | 3110   | None | Minor | Moderate | Major | Replace | 35% | \$12,620  | Significant paving cracks at play area     |
|                               | G2040 | Site Development                |                   | 2900   | None | Minor | Moderate | Major | Replace |     | \$0       | Cost/LF of fencing                         |
|                               | G2050 | Landscaping                     |                   | 556246 | None | Minor | Moderate | Major | Replace |     | \$0       | Cost/SF of irrigated area                  |
| G30 Site Mechanical Utilities |       |                                 |                   |        |      |       |          |       |         |     |           |  |
|                               | G3010 | Water Supply                    | Domestic          | 100    | None | Minor | Moderate | Major | Replace |     | \$0       | Enter LF of pipe in cell E143              |
|                               | G3020 | Sanitary Sewer                  | Fire              |        | None | Minor | Moderate | Major | Replace |     | \$0       | Enter LF of pipe in cell E144              |
|                               | G3030 | Storm Sewer                     |                   | 100    | None | Minor | Moderate | Major | Replace |     | \$0       | Enter LF of sewer lines in cell E145       |
|                               | G3040 | Heating Distribution            |                   |        | None | Minor | Moderate | Major | Replace |     | \$0       | Enter SF of area to be drained             |
|                               | G3050 | Cooling Distribution            |                   |        | None | Minor | Moderate | Major | Replace |     | \$0       | Enter LF of heating ducts in cell E147     |
|                               | G3060 | Fuel Distribution               |                   |        | None | Minor | Moderate | Major | Replace |     | \$0       | Enter LF of duct work in cell E148         |
|                               | G3090 | Other Site Mechanical Utilities | NOT USED          |        | None | Minor | Moderate | Major | Replace |     | \$0       | Enter LF of natural gas lines in cell E149 |
| G40 Site Electrical Utilities |       |                                 |                   |        |      |       |          |       |         |     |           |  |
|                               | G4010 | Electrical Distribution         | Service Generator | 100%   | None | Minor | Moderate | Major | Replace |     | \$0       |  |
|                               | G4020 | Site Lighting                   |                   |        | None | Minor | Moderate | Major | Replace |     | \$0       |  |
|                               | G4030 | Site Communications & Security  |                   | 100%   | None | Minor | Moderate | Major | Replace |     | \$0       |  |
|                               | G4090 | Other Site Electrical Utilities | NOT USED          |        | None | Minor | Moderate | Major | Replace |     | \$0       |  |
| G90 Other Site Construction   |       |                                 |                   |        |      |       |          |       |         |     |           |  |

**OTHER**

| Description of System | Unit of Measure | Quantity | Unit Budget | Extended | Notes |
|-----------------------|-----------------|----------|-------------|----------|-------|
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |

Physical Condition Budget Sub-Total \$4,971,369  
 Budgeted Development Costs \$1,889,120  
 Physical Condition Budget TOTAL \$6,860,489  
 Cost with Escalation to June 2021 \$7,820,957  
 Cost with Escalation to June 2022 \$8,133,795  
 Cost with Escalation to June 2023 \$8,459,147

Replacement Budget \$25,769,016  
 Facility Condition Index (FCI) 30.4%

**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: Knott Elementary School  
 Building Name: Main  
 Building ID: 21810003

| Level 1               | Level 2 | Level 3 | Type (as applicable)       | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                             |
|-----------------------|---------|---------|----------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|-----------------------------------|
|                       |         |         |                            |                         | None            | Minor | Moderate | Major |                               |                       |                           |                                   |
| <b>A SUBSTRUCTURE</b> |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                                   |
| A10 Foundations       |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                                   |
|                       |         |         | A1010 Standard Foundations |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | A1020 Special Foundations  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | A1030 Slab on Grade        | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | A20 Basement Construction  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | A2010 Basement Excavation  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | A2020 Basement Walls       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
| <b>B SHELL</b>        |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                                   |
| B10 Superstructure    |         |         |                            |                         |                 |       |          |       |                               |                       |                           |                                   |
|                       |         |         | B1010 Floor Construction   | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Steel                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Concrete                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | B1020 Roof Construction    | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Steel                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Concrete                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | B20 Exterior Enclosure     |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | B2010 Exterior Walls       | 100%                    | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Concrete Formed / Tilt     |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Masonry                    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Framed w/ Wood Siding      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Framed w/ Metal Panel      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Framed w/ Stucco           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Framed w/ Masonry Veneer   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Wood                       | 10%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$39,046                  |                                   |
|                       |         |         | Aluminum/Steel             | 90%                     | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$377,865                 | Glass block replacement           |
|                       |         |         | Clad                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Curtain Wall               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Wood                       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Hollow Metal               | 33                      | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$42,511                  | Upgrade / replace hardware, paint |
|                       |         |         | Storefront                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | B30 Roofing                |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | B3010 Roof Coverings       | 100%                    | None            | Minor | Moderate | Major | Replace                       | 60%                   | \$654,966                 | Re-coat / re-seal by 2024         |
|                       |         |         | Asphalt Shingle            |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Built-Up                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Single Ply                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Metal                      |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Concrete Tile              |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                       |         |         | Skylights                  |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | By Building OSF                   |
|                       |         |         | Access Hatch               |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Per hatch                         |

District Name: Parkrose SD 3  
 Site Name: Knott Elementary School  
 Building Name: Main  
 Building ID: 21810003

**REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3 | Type (as applicable)  | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                      |
|---------------------------|---------|---------|-----------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|----------------------------|
|                           |         |         |                       |                         | None            | Minor | Moderate | Major |                               |                       |                           |                            |
| <b>C INTERIORS</b>        |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
| C10 Interior Construction |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         | C1010   | Partitions            |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                            |
|                           |         |         | Framed Masonry        | 85%                     | X               |       |          |       |                               |                       |                           |                            |
|                           |         |         | Wood                  | 15%                     | X               |       |          |       |                               |                       |                           |                            |
|                           |         |         | Hollow Metal          | 50                      |                 | X     |          |       |                               | 100%                  | \$51,528                  | Upgrade / replace hardware |
|                           |         |         | NOT USED              | 19                      |                 | X     |          |       |                               | 100%                  | \$19,581                  | Upgrade / replace hardware |
| C20 Stairs                |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         | C2010   | Stair Construction    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Cost/Flight                |
|                           |         |         | Wood                  |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Metal                 |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Concrete              |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Concrete Fill         |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Resilient             |                         |                 |       |          |       |                               |                       |                           |                            |
| C30 Interior Finishes     |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         | C3010   | Wall Finishes         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                            |
|                           |         |         | Paint on Masonry      | 10%                     |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Wallboard             |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Wainscot              | 5%                      |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Ceramic Tile          |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Carpet / Soft Surface | 7%                      |                 |       |          |       | X                             | 100%                  | \$19,632                  |                            |
|                           |         |         | Resilient Tile        | 78%                     |                 |       |          |       | X                             | 100%                  | \$222,689                 | ACM                        |
|                           |         |         | Polished Sheet        | 5%                      |                 |       |          |       | X                             | 100%                  | \$25,191                  |                            |
|                           |         |         | Polished Concrete     | 5%                      | X               |       |          |       |                               |                       | \$0                       | Sealed concrete            |
|                           |         |         | Ceramic Tile          | 5%                      |                 |       |          |       | X                             | 100%                  | \$52,775                  |                            |
|                           |         |         | Liquid Applied        |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Wood Sports Floor     |                         |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Wallboard             | 5%                      | X               |       |          |       |                               |                       |                           |                            |
|                           |         |         | Lay-in Ceiling Tile   | 10%                     |                 |       |          |       |                               |                       |                           |                            |
|                           |         |         | Glued-Up Ceiling Tile | 80%                     |                 | X     |          |       |                               | 25%                   | \$1,050                   |                            |
|                           |         |         | Painted Structure     | 5%                      | X               |       |          |       |                               | 50%                   | \$79,604                  |                            |
|                           |         |         |                       |                         |                 |       |          |       |                               |                       |                           |                            |

District Name: Parkrose SD 3  
 Site Name: Knott Elementary School  
 Building Name: Main  
 Building ID: 21810003

REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                       |
|----------------------------|---------|---------|---|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|---|
|                            |         |         |   |                         | None            | Minor | Moderate | Major |                               |                       |                           |   |
| <b>D SERVICES</b>          |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
| <b>D10 Conveying</b>       |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D1010 Elevators & Lifts                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                            |         |         | D1020 Escalators & Moving Walks         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
|                            |         |         | D1090 Other Conveying Systems           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |   |
| <b>D20 Plumbing</b>        |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$200,000                 | All (N) fixtures req'd to meet ADA by code. |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$30,000                  | Replace old NG DHW                          |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D2090 Other Plumbing Systems            |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D30 HVAC</b>            |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D3010 Energy Supply                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | NG on site                                  |
|                            |         |         | D3020 Heat Generating Systems           | 90%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$680,000                 | Upgrade boiler and heating water piping     |
|                            |         |         | Boiler                                  | 90%                     | Y               | Minor | Moderate | Major | X Replace                     | 90%                   | \$450,000                 | Replace existing HVS and coil heaters       |
|                            |         |         | Furnace                                 | 10%                     | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Heat Exchanger                          | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Component of air handler                | 10%                     | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Stand alone chiller                     | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Ductwork                                | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Hot water return & supply               | 90%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$0                       | Included in boiler replacement item         |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | In-room ventilator unit                 | 60%                     | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$0                       | coil booster heaters included in AHU item   |
|                            |         |         | In-room radiant unit                    | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D3050 Terminal & Package Units          | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$240,000                 | upgrade to district BAS                     |
|                            |         |         | D3060 Controls & Instrumentation        |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$18,000                  | Estimated for RCX                           |
|                            |         |         | D3070 Systems Testing & Balancing       |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
|                            |         |         | D3090 Other HVAC Systems & Equipment    |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D40 Fire Protection</b> |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D4010 Sprinklers                        | 0%                      | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$210,000                 | add sprinkler system                        |
|                            |         |         | D4020 Standpipes                        | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D4090 Other Fire Protection Systems     |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |
| <b>D50 Electrical</b>      |         |         |   |                         |                 |       |          |       |                               |                       |                           |   |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 40%                   | \$110,000                 | Replace old electrical panels               |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$75,000                  | Lighting and lighting control retrofit      |
|                            |         |         | D5030 Communications & Security         | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Voice / Data System                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Clock / Intercom System                 | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Closed Circuit Surveillance             | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Access Control System                   | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Intrusion Alarm System                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | Lighting Control System                 | 10%                     | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |   |
|                            |         |         | D5090 Other Electrical Systems          |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |   |





**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

District Name: Parkrose SD 3  
 Site Name: District Office  
 Building Name: Main  
 Building ID: 0

| Level 1                   | Level 2 | Level 3 | Type (as applicable)       | % of Building or Number | LEVEL OF ACTION |       |          |       |   | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                                 |
|---------------------------|---------|---------|----------------------------|-------------------------|-----------------|-------|----------|-------|---|-------------------------------|-----------------------|---------------------------|---------------------------------------|
|                           |         |         |                            |                         | None            | Minor | Moderate | Major |   |                               |                       |                           |                                       |
| <b>A SUBSTRUCTURE</b>     |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
| A10 Foundations           |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
|                           |         |         | A1010 Standard Foundations |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | A1020 Special Foundations  |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | A1030 Slab on Grade        | 100%                    | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
| A20 Basement Construction |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
|                           |         |         | A2010 Basement Excavation  |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | A2020 Basement Walls       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
| <b>B SHELL</b>            |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
| B10 Superstructure        |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
|                           |         |         | B1010 Floor Construction   |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Concrete                   |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | B1020 Roof Construction    | 100%                    | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Steel                      |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Concrete                   |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
| B20 Exterior Enclosure    |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
|                           |         |         | B2010 Exterior Walls       | 50%                     | None            | Minor | Moderate | Major |   | Replace                       | 25%                   | \$10,833                  | Header repair at maintenance building |
|                           |         |         | Masonry                    |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Framed w/ Wood Siding      | 25%                     | None            | Minor | Moderate | Major |   | Replace                       | 100%                  | \$20,466                  |                                       |
|                           |         |         | Framed w/Metal Panel       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Framed w/Stucco            |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Framed w/Masonry Veneer    | 25%                     | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Aluminum/Steel             | 100%                    | X               | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Clad                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Curtain Wall               |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Wood                       |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Hollow Metal               | 6                       | None            | Minor | Moderate | Major | X | Replace                       | 100%                  | \$10,048                  | Upgrade / replace hardware            |
|                           |         |         | Storefront                 | 4                       | None            | Minor | Moderate | Major | X | Replace                       | 50%                   | \$3,092                   | Hardware repair / replacement         |
| B30 Roofing               |         |         |                            |                         |                 |       |          |       |   |                               |                       |                           |                                       |
|                           |         |         | B3010 Roof Coverings       | 65%                     | None            | Minor | Moderate | Major |   | Replace                       | 50%                   | \$225,326                 | Restore DO, Replace Maintenance + Bus |
|                           |         |         | Asphalt Shingle            |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Built-Up                   |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Single Ply                 | 35%                     | None            | Minor | Moderate | Major |   | Replace                       | 100%                  | \$50,212                  | Restore                               |
|                           |         |         | Metal                      |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Concrete Tile              |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |
|                           |         |         | Skylights                  |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       | By Building GSF                       |
|                           |         |         | B3020 Roof Openings        |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       | Per hatch                             |
|                           |         |         | Access Hatch               |                         | None            | Minor | Moderate | Major |   | Replace                       |                       | \$0                       |                                       |

District Name: Parkrose SD 3  
 Site Name: District Office  
 Building Name: Main  
 Building ID: 0

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

█ An unused cell or system that should not receive direct user input  
 █ An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                   | Level 2 | Level 3                  | Type (as applicable)    | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes                             |
|---------------------------|---------|--------------------------|-------------------------|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|-----------------------------------|
|                           |         |                          |                         |                         | None            | Minor | Moderate | Major |                               |                       |                           |                                   |
| <b>C INTERIORS</b>        |         |                          |                         |                         |                 |       |          |       |                               |                       |                           |                                   |
| C10 Interior Construction |         |                          |                         |                         |                 |       |          |       |                               |                       |                           |                                   |
|                           |         | C1010 Partitions         | Framed Masonry          | 75%<br>X                | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         | C1020 Interior Doors     | Wood                    | 25%<br>X                | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$12,367                  | Upgrade / replace hardware        |
|                           |         | C1030 Fittings           | Hollow Metal            | 12                      | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$18,421                  | Upgrade / replace hardware, paint |
|                           |         | C20 Stairs               | NOT USED                | 13                      | None            | Minor | Moderate | Major | Replace                       |                       |                           |                                   |
|                           |         | C2010 Stair Construction | Wood                    |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         | C2020 Stair Finishes     | Metal                   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         | C30 Interior Finishes    | Concrete                |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         | C3010 Wall Finishes      | Concrete Fill Resilient |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       | Cost/Flight                       |
|                           |         | C3020 Floor Finishes     | Paint on Masonry        | 30%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$8,960                   |                                   |
|                           |         |                          | Wallboard               | 60%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$16,159                  |                                   |
|                           |         |                          | Wainscot                | 5%                      | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         |                          | Ceramic Tile            | 5%                      | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         |                          | Carpet / Soft Surface   | 40%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$35,625                  |                                   |
|                           |         |                          | Resilient Tile          | 10%                     | None            | Minor | Moderate | Major | Replace                       | 50%                   | \$6,346                   |                                   |
|                           |         |                          | Resilient Sheet         | 5%                      | None            | Minor | Moderate | Major | Replace                       | 100%                  | \$15,999                  |                                   |
|                           |         |                          | Polished Concrete       | 50%                     | X               | Minor | Moderate | Major | Replace                       |                       | \$0                       | Sealed concrete                   |
|                           |         |                          | Ceramic Tile            |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         |                          | Liquid Applied          |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         |                          | Wood Sports Floor       |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         | C3030 Ceiling Finishes   | Wallboard               | 5%                      | None            | Minor | Moderate | Major | Replace                       | 25%                   | \$1,047                   |                                   |
|                           |         |                          | Lay-in Ceiling Tile     | 40%                     | None            | Minor | Moderate | Major | Replace                       | 25%                   | \$2,667                   |                                   |
|                           |         |                          | Glued-Up Ceiling Tile   |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |                                   |
|                           |         |                          | Painted Structure       | 55%                     | None            | Minor | Moderate | Major | Replace                       | 20%                   | \$9,416                   |                                   |

District Name: Parkrose SD 3  
 Site Name: District Office  
 Building Name: Main  
 Building ID: 0

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**  
 An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                    | Level 2 | Level 3 | Type (as applicable)                    | % of Building or Number | LEVEL OF ACTION |       |          |       | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes  |
|----------------------------|---------|---------|---|-------------------------|-----------------|-------|----------|-------|-------------------------------|-----------------------|---------------------------|--|
|                            |         |         |   |                         | None            | Minor | Moderate | Major |                               |                       |                           |  |
| <b>D SERVICES</b>          |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
| <b>D10 Conveying</b>       |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D1010 Elevators & Lifts                 |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |  |
|                            |         |         | D1020 Escalators & Moving Walks         |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |  |
|                            |         |         | D1090 Other Conveying Systems           |                         | None            | Minor | Moderate | Major | Replace                       |                       | \$0                       |  |
| <b>D20 Plumbing</b>        |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D2010 Plumbing Fixtures                 | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$135,000                 | All (N) fixtures req'd to meet ADA by code.      |
|                            |         |         | D2020 Domestic Water Distribution       | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$17,000                  | Replace old DHWs                                 |
|                            |         |         | D2030 Sanitary Waste                    | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D2040 Rain Water Drainage               | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D2090 Other Plumbing Systems            |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |  |
| <b>D30 HVAC</b>            |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D3010 Energy Supply                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | NG on site                                       |
|                            |         |         | D3020 Heat Generating Systems           | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Boiler                                  | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Air Handler                             | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Furnace                                 | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 50%                   | \$55,000                  | Replace old furnace and gas unit heaters         |
|                            |         |         | Heat Exchanger                          | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Component of air handler                | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D3030 Cooling Generating Systems        |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |  |
|                            |         |         | Stand alone chiller                     | 50%                     | Y               | Minor | Moderate | Major | X Replace                     | 20%                   | \$0                       | Included in furnace replacement for one split DX |
|                            |         |         | Ductwork                                | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Hot water return & supply               | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Above ceiling VAV unit                  | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | In-room ventilator unit                 | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | In-room radiant unit                    | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D3060 Controls & Instrumentation        | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$115,000                 | Upgrade to district BAS                          |
|                            |         |         | D3070 Systems Testing & Balancing       | 100%                    | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$12,000                  | Estimated for RCX                                |
|                            |         |         | D3090 Other HVAC Systems & Equipment    |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |  |
| <b>D40 Fire Protection</b> |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D4010 Sprinklers                        | 0%                      | Y               | Minor | Moderate | Major | X Replace                     | 100%                  | \$130,000                 | add sprinkler system                             |
|                            |         |         | D4020 Standpipes                        | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D4030 Fire Protection Specialties       | 0%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D4090 Other Fire Protection Systems     |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |  |
| <b>D50 Electrical</b>      |         |         |   |                         |                 |       |          |       |                               |                       |                           |  |
|                            |         |         | D5010 Electrical Service & Distribution | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       | Lighting and lighting control retrofit           |
|                            |         |         | D5020 Lighting and Branch Wiring        | 100%                    | Y               | Minor | Moderate | Major | Replace                       | 0%                    | \$43,000                  |  |
|                            |         |         | D5030 Communications & Security         | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Voice / Data System                     | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Clock / Intercom System                 | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Closed Circuit Surveillance             | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Access Control System                   | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Intrusion Alarm System                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Fire Alarm / Detection                  | 100%                    | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | Lighting Control System                 | 5%                      | N               | Minor | Moderate | Major | Replace                       | 0%                    | \$0                       |  |
|                            |         |         | D5090 Other Electrical Systems          |                         | None            | Minor | Moderate | Major | Replace                       |                       |                           |  |

**REMEMBER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET**

District Name: Parkrose SD 3  
 Site Name: District Office  
 Building Name: Main  
 Building ID: 0

An unused cell or system that should not receive direct user input  
 An automatically populated cell from user input elsewhere in the file - do not overwrite

| Level 1                              | Level 2 | Level 3              | Type (as applicable)        | % of Building or Number | LEVEL OF ACTION |       |          |       |         | Replace as part of Renovation | % of System or Finish | Automated Budget Estimate | Notes |
|--------------------------------------|---------|----------------------|-----------------------------|-------------------------|-----------------|-------|----------|-------|---------|-------------------------------|-----------------------|---------------------------|-------|
|                                      |         |                      |                             |                         | None            | Minor | Moderate | Major | Major   |                               |                       |                           |       |
| <b>E EQUIPMENT &amp; FURNISHINGS</b> |         |                      |                             |                         |                 |       |          |       |         |                               |                       |                           |       |
| E10 Equipment                        |         |                      |                             |                         |                 |       |          |       |         |                               |                       |                           |       |
|                                      | E1010   | Commercial Equipment | Food Service                |                         | None            | Minor | Moderate | Major | Replace |                               | \$0                   |                           |       |
|                                      |         |                      | Vocational Science          |                         | None            | Minor | Moderate | Major | Replace |                               | \$0                   |                           |       |
|                                      |         |                      | Art                         |                         | None            | Minor | Moderate | Major | Replace |                               | \$0                   |                           |       |
|                                      |         |                      | Stage Performance           |                         | None            | Minor | Moderate | Major | Replace |                               | \$0                   |                           |       |
|                                      |         |                      | Restroom Accessories/Stalls |                         | None            | Minor | Moderate | Major | Replace |                               | \$26,999              |                           |       |
|                                      |         |                      | NOT USED                    | 100%                    | None            | Minor | Moderate | Major | Replace |                               |                       |                           |       |
|                                      |         |                      | NOT USED                    |                         | None            | Minor | Moderate | Major | Replace |                               |                       |                           |       |
| E20 Furnishings                      |         |                      |                             |                         |                 |       |          |       |         |                               |                       |                           |       |
|                                      | E2010   | Fixed Furnishings    |                             | 50%                     | None            | Minor | Moderate | Major | Replace | 50%                           | \$24,932              |                           |       |
|                                      | E2020   | Movable Furnishings  |                             | 50%                     | None            | Minor | Moderate | Major | Replace | 15%                           | \$47,998              |                           |       |

**F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED**

**G BUILDING SITE WORK**

|                                       |       |                                 |                   |       |      |       |          |       |         |      |          |  |
|---------------------------------------|-------|---------------------------------|-------------------|-------|------|-------|----------|-------|---------|------|----------|--|
| G10 Site Preparation                  |       |                                 |                   |       |      |       |          |       |         |      |          |  |
| G20 Site Improvements                 |       |                                 |                   |       |      |       |          |       |         |      |          |  |
|                                       | G2010 | Roadways                        |                   |       | None | Minor | Moderate | Major | Replace | 100% | \$28,211 | Cost/SF of surface area                    |
|                                       | G2020 | Parking Lots                    |                   | 40088 | None | Minor | Moderate | Major | Replace | 100% | \$81,077 | Cost/SF of surface area                    |
|                                       | G2030 | Pedestrian Paving               |                   | 2901  | None | Minor | Moderate | Major | Replace |      | \$0      | Cost/SF of surface area                    |
|                                       | G2040 | Site Development                |                   | 927   | None | Minor | Moderate | Major | Replace |      | \$0      | Cost/LF of fencing                         |
|                                       | G2050 | Landscaping                     |                   | 7175  | None | Minor | Moderate | Major | Replace | 10%  | \$2,311  | Site by DO east side                       |
| G30 Site Mechanical Utilities         |       |                                 |                   |       |      |       |          |       |         |      |          |  |
|                                       | G3010 | Water Supply                    | Domestic          | 100   | None | Minor | Moderate | Major | Replace |      | \$0      | Enter LF of pipe in cell E143              |
|                                       |       |                                 | Fire              |       | None | Minor | Moderate | Major | Replace |      | \$0      | Enter LF of pipe in cell E144              |
|                                       | G3020 | Sanitary Sewer                  |                   |       | None | Minor | Moderate | Major | Replace |      | \$0      | Enter LF of sewer lines in cell E145       |
|                                       | G3030 | Storm Sewer                     |                   | 100   | None | Minor | Moderate | Major | Replace |      | \$0      | Enter SF of area to be drained             |
|                                       | G3040 | Heating Distribution            |                   |       | None | Minor | Moderate | Major | Replace |      | \$0      | Enter LF of heating ducts in cell E147     |
|                                       | G3050 | Cooling Distribution            |                   |       | None | Minor | Moderate | Major | Replace |      | \$0      | Enter LF of duct work in cell E148         |
|                                       | G3060 | Fuel Distribution               |                   |       | None | Minor | Moderate | Major | Replace |      | \$0      | Enter LF of natural gas lines in cell E149 |
| G3090 Other Site Mechanical Utilities |       |                                 |                   |       |      |       |          |       |         |      |          |  |
| G40 Site Electrical Utilities         |       |                                 |                   |       |      |       |          |       |         |      |          |  |
|                                       | G4010 | Electrical Distribution         | Service Generator | 100%  | None | Minor | Moderate | Major | Replace |      | \$0      |  |
|                                       |       |                                 |                   |       | None | Minor | Moderate | Major | Replace |      | \$0      |  |
|                                       | G4020 | Site Lighting                   |                   | 100%  | None | Minor | Moderate | Major | Replace |      | \$0      |  |
|                                       | G4030 | Site Communications & Security  |                   |       | None | Minor | Moderate | Major | Replace |      | \$0      |  |
|                                       | G4090 | Other Site Electrical Utilities | NOT USED          |       | None | Minor | Moderate | Major | Replace |      | \$0      |  |
| G90 Other Site Construction           |       |                                 |                   |       |      |       |          |       |         |      |          |  |

**OTHER**

| Description of System | Unit of Measure | Quantity | Unit Budget | Extended | Notes |
|-----------------------|-----------------|----------|-------------|----------|-------|
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |
|                       |                 |          |             | \$0      |       |

Physical Condition Budget Sub-Total \$1,164,912  
 Budgeted Development Costs \$442,667  
 Physical Condition Budget TOTAL \$1,607,579  
 Cost with Escalation to June 2021 \$1,832,640  
 Cost with Escalation to June 2022 \$1,905,945  
 Cost with Escalation to June 2023 \$1,982,183

Replacement Budget \$10,420,877  
 Facility Condition Index (FCI) 17.6%

# APPENDIX E

# ROOFING REPORT




**Site Map**



**Parkrose**  
School District

Parkrose HS



**Total Sq. Per Roof Section**

| Section      | Total sq. ft.  |
|--------------|----------------|
| 1H           | 10000          |
| 2H           | 13000          |
| 3H           | 23000          |
| 4H           | 11000          |
| 5H           | 12000          |
| 6H           | 10000          |
| 7H           | 7000           |
| 8H           | 3500           |
| 9H           | 3500           |
| 10H          | 3000           |
| 11H          | 1800           |
| 12H          | 4600           |
| 13H          | 7500           |
| 14H          | 11000          |
| 15H          | 1600           |
| 16H          | 1500           |
| 17H          | 13200          |
| 18H          | 20000          |
| 19H          | 3500           |
| 20H          | 9000           |
| 21H          | 3500           |
| 22H          | 8000           |
| <b>Total</b> | <b>181,200</b> |

| Color  | Existing                        | Scope   |
|--------|---------------------------------|---------|
| Green  | Bur/Coating                     | n/a     |
| Blue   | 4h, 7h, 18h, 20h, 22h           | Restore |
| Yellow | 5h, 8h, 12h, 15h, 17h, 19h, 21h | Restore |
| Red    | BUR                             | Replace |

THE GARLAND COMPANY INC.  
3800 E 91<sup>st</sup> ST | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

February 2021  
Travis Cox  
tcx@garlandinc.com  
503-522-7626



Roof Budgets



**Parkrose**  
School District

Parkrose HS



| <u>Color</u> | <u>Existing</u>                            | <u>Scope</u> | <u>Action Years</u> | <u>Estimated Cost</u> | <u>Expected Life</u> |
|--------------|--|--------------|---------------------|-----------------------|----------------------|
|              | Bur/Coating<br>4h, 7h, 18h, 20h, 22h       | n/a          | 2032                | n/a                   | n/a                  |
|              | PVC<br>1h, 3h, 8h, 12h, 15h, 17h, 19h, 21h | Restore      | 2023-2025           | \$475,000             | 15                   |
|              | BUR<br>2h, 5h, 6h, 9h, 10h, 11h, 13h, 14h  | Restore      | 2021-2024           | \$475,000             | 15                   |
|              | BUR<br>16h                                 | Replace      | 2022                | \$30,000              | 30                   |

THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST | CLEVELAND, OH 44105-2197  
PHONE (216) 841-7500 | FAX (216) 841-0633



Parkrose SD

February 2021  
Travis Cox  
tc Cox@garlandind.com  
503-522-7626



### Site Map



# Parkrose School District

Parkrose HS



## Total Sq. Per Roof Section

| Section      | Total sq. ft.  |
|--------------|----------------|
| 1H           | 10000          |
| 2H           | 13000          |
| 3H           | 23000          |
| 4H           | 11000          |
| 5H           | 12000          |
| 6H           | 10000          |
| 7H           | 7000           |
| 8H           | 3500           |
| 9H           | 3500           |
| 10H          | 3000           |
| 11H          | 1800           |
| 12H          | 4600           |
| 13H          | 7500           |
| 14H          | 11000          |
| 15H          | 1600           |
| 16H          | 1500           |
| 17H          | 13200          |
| 18H          | 20000          |
| 19H          | 3500           |
| 20H          | 9000           |
| 21H          | 3500           |
| 22H          | 8000           |
| <b>Total</b> | <b>181,200</b> |

| Color  | Existing                            | Scope   |
|--------|-------------------------------------|---------|
| Green  | Bur/Coating                         | n/a     |
| Blue   | 4h, 7h, 18h, 20h, 22h               | Restore |
| Yellow | 1h, 3h, 8h, 12h, 15h, 17h, 19h, 21h | Restore |
| Red    | 2h, 5h, 6h, 9h, 10h, 11h, 13h, 14h  | Replace |
| Blue   | BUR                                 | Replace |
| Red    | 16h                                 | Replace |







**Site Map**



**Parkrose**  
School District

District Office



| Color   | Existing   |
|---|------------|
| <span style="display: inline-block; width: 20px; height: 20px; background-color: yellow; border: 1px solid black;"></span>    | Bur        |
|   | 1 DO       |
|   | 2 DO       |
| <span style="display: inline-block; width: 20px; height: 20px; background-color: lightblue; border: 1px solid black;"></span> | Metal      |
|   | 3 DO, 4 DO |

**Total Sq. Per Roof Section**

|                 |        |
|-----------------|--------|
| • 1 DO          | 7,000  |
| • 2 DO          | 7,000  |
| • 3 DO          | 3,200  |
| • 4 DO          | 4,000  |
| • Total sq. ft. | 21,200 |

THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

Travis Cox  
tc Cox@garlandind.com  
503-522-7626

February 2021

Page 1 of 2  
Not to scale - contractor responsible for field measurements



Roof Budgets



**Parkrose**  
School District

District Office

| <u>Color</u> | <u>Existing</u>     | <u>Scope</u>           | <u>Action Years</u> | <u>Estimated Cost</u> | <u>Expected Life</u> |
|--------------|---------------------|------------------------|---------------------|-----------------------|----------------------|
| Yellow       | Bur                 | Maintenance<br>Replace | 2021-2035<br>2023   | \$5000<br>\$140,000   | 15<br>30             |
|              | 1 DO                |                        |                     |                       |                      |
| Blue         | 2 DO                | Restore                | 2023                | \$60,000              | 10-15                |
|              | Metal<br>3 DO, 4 DO |                        |                     |                       |                      |







**Site Map**



Russel Elementary



**Total Sq. Per Roof Section**

| Color   | Existing Bur | BUR/Coating | 1 RE   | 2 RE  | Total sq. ft. |
|---|--------------|-------------|--------|-------|---------------|
|  | <b>1RE</b>   |             | 46,000 | 7,000 | 53,000        |
|  | <b>2RE</b>   |             |        |       |               |

THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

February 2021  
Travis Cox  
tcox@garlandinc.com  
503-522-7626






Roof Budgets



**Parkrose**  
School District

Russel Elementary

| Color   | Existing                  | Scope            | Action Years | Estimated Cost | Expected Life |
|---|---------------------------|------------------|--------------|----------------|---------------|
|  | Bur<br><b>1RE</b>         | New Roof         | N/a          |                | 25            |
|  | BUR/Coating<br><b>2RE</b> | Replace/retrofit | 2027         | \$145,000      | 30            |





**Site Map**



Wheatley



**Total Sq. Per Roof Section**

| Color  | Existing      | 2-ply Mod. Bit |
|--|---------------|----------------|
| <span style="display:inline-block; width:20px; height:20px; background-color:lightgreen;"></span>  | BUR           | 1 WE           |
| <span style="display:inline-block; width:20px; height:20px; background-color:lightcoral;"></span>  | BUR           | 2 WE           |
| <span style="display:inline-block; width:20px; height:20px; background-color:lightyellow;"></span> | BUR           | 3 WE           |
|  | 1 WE          | 28,000         |
|  | 2 WE          | 2,300          |
|  | 3 WE          | 25,000         |
|  | Total sq. ft. | 55,500         |



THE GARLAND COMPANY INC.  
3800 E 91<sup>st</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633

Parkrose SD

February 2021  
Travis Cox  
tcox@garlandinc.com  
503-522-7626



**Roof Budgets**



**Parkrose**  
School District

Wheatley

| Color   | Existing               | Scope         | Action Years | Estimated Cost | Expected Life |
|---|------------------------|---------------|--------------|----------------|---------------|
|  | 2-ply Mod. Bit<br>1 WE | Replaced 2021 |              | n/a            | 30            |
|  | BUR<br>2 WE            | Replace       | 2022         | \$50,000       | 30            |
|  | BUR<br>3 WE            | Resurface     | 2028         | \$175,000      | 10            |



THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

Travis Cox  
tc Cox@garlandind.com  
503-522-7626

2021




**Site Map**



**Parkrose**  
School District

Shaver



**Total Sq. Per Roof Section**

| Color | Existing                              | Scope   |
|-------|---------------------------------------|---------|
|       | Single Ply<br>1SE, 2SE, 3SE, 4SE, 5SE | Restore |

|               |       |
|---------------|-------|
| • 1SE         | 2000  |
| • 2SE         | 20000 |
| • 3SE         | 21000 |
| • 4SE         | 500   |
| • 5SE         | 11500 |
| Total sq. ft. | 55000 |



THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)841-7500 | FAX (216)841-0633

Parkrose SD

March 2021  
Travis Cox  
tcox@garlandind.com  
503-522-7626



### Roof Budgets



## Parkrose School District

Sacramento Elementary

| Color   | Existing                              | Scope                       | Action Years           | Estimated Cost           | Expected Life |
|---|---------------------------------------|-----------------------------|------------------------|--------------------------|---------------|
|  | Single Ply<br>1SE, 2SE, 3SE, 4SE, 5SE | Restore<br>Replace/retrofit | 2023-2025<br>2026-2027 | \$650,000<br>\$1,100,000 | 20<br>30      |



Existing

Scope


Action Years

Estimated Cost

Expected Life

20

30









**Site Map**



Sacramento Elementary



**Total Sq. Per Roof Section**

| Color   | Existing                       |
|---|--------------------------------|
|  | Sika PVC<br>1S, 2S, 3S, 4S, 5S |

|                      |              |
|----------------------|--------------|
| • 1S                 | 1000         |
| • 2S                 | 16500        |
| • 3S                 | 2500         |
| • 4S                 | 4500         |
| • 5S                 | 23000        |
| <b>Total sq. ft.</b> | <b>47500</b> |

THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

March 2021  
Travis Cox  
tcox@garlandinc.com  
503-522-7626

Page 1 of 2  
Not to scale - contractor responsible for field measurements





Roof Budgets



**Parkrose**  
School District

Sacramento Elementary

|   |                                   |              |                     |                       |                      |
|---|-----------------------------------|--------------|---------------------|-----------------------|----------------------|
| <b>Color</b>  | <b>Existing</b>                   | <b>Scope</b> | <b>Action Years</b> | <b>Estimated Cost</b> | <b>Expected Life</b> |
|  | Sika PVC<br><b>1S,2S,3S,4S,5S</b> | Restore      | 2022-2024           | \$550,000             | 20                   |





**Site Map**



**Parkrose**  
School District

Helenview



**Total Sq. Per Roof Section**

| Color | Existing             |               |
|-------|----------------------|---------------|
|       | Bur                  | 23000         |
|       | 3HV, 4HV             | 1200          |
|       | BUR                  | 3800          |
|       | 1HV, 2HV, 5HV        | 15500         |
|       |                      | 1500          |
|       | <b>Total sq. ft.</b> | <b>45,000</b> |



THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633

Parkrose SD

February 2021  
Travis Cox  
tcox@garlandind.com  
503-522-7626

Not to scale - contractor responsible for field measurements



Roof Budgets



**Parkrose**  
School District

Helenview



| Color | Existing             | Scope               | Action Years | Estimated Cost         | Expected Life |
|-------|----------------------|---------------------|--------------|------------------------|---------------|
|       | Bur<br>3HV, 4HV      | Retrofit<br>Replace | 2022<br>2022 | \$325,000<br>\$410,000 | 30<br>30      |
|       | BUR<br>1HV, 2HV, 5HV | Restore<br>Retrofit | 2022<br>2024 | \$200,000<br>\$470,000 | 15<br>30      |

THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

Travis Cox  
tc Cox@garlandind.com  
503-522-7626

February 2021

Not to scale - contractor  
responsible for field  
measurements

Page 2 of 2



**Site Map**



Knott Creek



**Total Sq. Per Roof Section**

| Color       | Existing | Bur/Coating    |
|-------------|----------|----------------|
| [Red Box]   | BUR      | 1k, 3k, 4k, 5k |
| [Green Box] | BUR      | 2k             |

|                      |               |
|----------------------|---------------|
| • 1K                 | 5000          |
| • 2K                 | 9000          |
| • 3K                 | 4500          |
| • 4K                 | 4100          |
| • 5K                 | 17800         |
| <b>Total sq. ft.</b> | <b>40,400</b> |



THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633

Parkrose SD

Travis Cox  
tcox@garlandinc.com  
503-522-7626

February 2021






Roof Budgets



**Parkrose**  
School District

Knott Creek



| Color   | Existing                      | Scope   | Action Years | Estimated Cost | Expected Life |
|---|-------------------------------|---------|--------------|----------------|---------------|
|  | Bur/Coating<br>1k, 3k, 4k, 5k | Replace | 2022-2024    | \$625,000      | n/a           |
|  | BUR<br>2k                     | n/a     | n/a          | n/a            | 20            |

THE GARLAND COMPANY INC.  
3800 E 91<sup>ST</sup> ST. | CLEVELAND, OH 44105-2197  
PHONE (216)641-7500 | FAX (216)641-0633



Parkrose SD

Travis Cox  
tc Cox@garlandind.com  
503-522-7626

February 2021

Not to scale - contractor responsible for field measurements