

Bethel Board of Education Special Meeting - HVAC Feasibility

Tuesday, June 28, 2022 7:30 PM

Board of Education Conference Room E, 1 School Street, PO Box 253, Bethel, CT 06801

1. **Call to Order**

Speaker(s): Policy
9326

1.A. Roll Call for Quorum

1.B. Pledge of Allegiance

2. **BOARD REPORTS - PROGRESS TOWARDS DISTRICT INITIATIVES**

2.A. HVAC Feasibility - Master Plan Study at Bethel High School

3. **Adjourn**

Bethel High School Mechanical Upgrades Study

June 3, 2022



93 Lake Avenue, Danbury, CT 06810
203.778.1017

171 Madison Avenue, New York, NY 10016
212.695.2422

Table of Contents

I.	PURPOSE	3
II.	EXECUTIVE SUMMARY	4
III.	BUILDING INFORMATION & LAYOUT	5
IV.	BUILDING PLANS	7
V.	EXISTING HVAC ZONING PLANS	10
VI.	MECHANICAL SYSTEM DEFICIENCIES & RECOMMENDATIONS	13
VII.	BUILDING AND HVAC DISTRIBUTION EVALUATION	47
VIII.	BUILDING MANAGEMENT SYSTEM EVALUATION	51
IX.	ELECTRICAL	52
X.	PRIORITY PHASING	54
XI.	APPENDIX A – HEATING AND COOLING LOADS	57
XII.	APPENDIX B – MECHANICAL UPGRADES ESTIMATES	76
XIII.	APPENDIX D – DRAWINGS	78

I. PURPOSE

The purpose and goal of this engineering study is to provide a path to modernize the mechanical systems serving the Bethel High School to meet operational needs for the next 20 to 30 years. Particular attention based on the original RFP is to address AHX-1 deficiencies, add air conditioning to the non-air-conditioned classrooms, add air conditioning to the athletic facilities and provide a long-term replacement plan for all AHU's. Additionally, Kohler Ronan has identified miscellaneous items that were discovered during building investigations outside of the scope of the original RFP. Items discovered are noted within this report.

The HVAC systems serving the high school are the heart of the approximate 167,000 square foot building. The building was originally constructed in 1970, with a significant addition built in 1975 and 2007. Most of the mechanical rooftop units were replaced in 2007.

This report and its recommendations are based on:

1. Initial on-site kickoff meeting with the staff to discuss and review the current building deficiencies on March 25, 2022.
2. Site visits to visually review existing rooftop equipment conditions on April 4, 2022.
3. Additional site visits on April 12th, 13th, and 14th 2022 for further field investigation.
4. An incomplete set of original building design drawings from 1968.
5. Various design drawings from renovations dated 1998, 2002, and 2006.
6. Design drawings to replace RTU-9 and RTU-13 dated January 2022 along with pre-demo testing performed by Wing's Testing and Balancing Co. Replacement of these units is scheduled for second quarter 2022.
7. Various email correspondence during 2020 noting controls issues, airflow issues, and repair orders.
8. Commissioning report performed by Wing's Testing and Balancing Co. dated October 29, 2020
9. Review of the building management system.
10. Bethel High School McQuay Rooftop Unit Re-Commissioning Memo by Pelegrine Energy Group dated December 18, 2018.
11. Bethel High School Identification of Priority High School HVAC Updates Memo by Pelegrine Energy Group dated February 4, 2020.
12. Bethel High School Rooftop Unit Commissioning Check Memo by Pelegrine Energy Group dated August 13, 2020.
13. Bethel High School RTU-5 Rebalancing Report Memo by Pelegrine Energy Group dated October 18, 2020.
14. Bethel High School HVAC Improvement Options Memo by Pelegrine Energy Group dated March 29, 2021
15. Bethel High School HVAC Update Planning Memo by Pelegrine Energy Group dated July 14, 2021
16. A spreadsheet by Pelegrine Energy Group documenting mechanical equipment issues experienced in 2018 and 2019.
17. A spreadsheet by Pelegrine Energy Group documenting general mechanical equipment information, opinions of condition, and issues experienced in 2017.
18. A building operating schedule by Pelegrine Energy Group dated September 25, 2018.
19. Electrical Utility bills from January 2020 to January 2022.
20. A spreadsheet summarizing natural gas usage from January 2020 to January 2021.

II. EXECUTIVE SUMMARY

The building boiler plant is nearly new and in proper operating condition. The air handling equipment and its associated DX cooling equipment is at the end of its expected lifespan or has exceeded it. The school has about 36 classrooms without cooling along with the gym, locker rooms, weight room, and wrestling room. Many exterior spaces are heated with perimeter radiation, unit ventilator or combination thereof. Select classrooms have been retrofitted with split air conditioning units but lack the means for mechanical ventilation air. All variable volume rooftop units supply conditioned air to their respective spaces via ducted VAV boxes. Air is typically distributed to the spaces via a combination of linear and square diffusers.

The building has been experiencing many HVAC related issues over the years. These deficiencies include:

1. Inability to maintain space temperature setpoint during hot summer days.
2. Rooftop units tripping on flame out.
3. Air handling and cooling equipment is unreliable requiring costly repairs and replacements.
4. Failure of ERU-2 energy wheel.
5. Visible areas of air infiltration through the building envelope.
6. History of damaged and leaking ductwork.
7. Insufficient airflow at the offices and classrooms served by AHX-1.
8. Insufficient airflow at the administration offices served by AHU-5
9. Noise complaints from unit ventilators.
10. Lack of ventilation air to some classrooms.
11. Exhaust fan failures and lack of bathroom exhaust.
12. Control issues and communication difficulties between the BMS.
13. Lack of maintenance performed on MAU-1

Kohler Ronan has determined the heating plant is sized appropriately with capacity to spare. Furthermore, the rooftop unit DX cooling sections are sized appropriately for their zones with the exception of AHX-1. However, the inability to maintain temperature in certain spaces is most likely due to the system's incapability to supply and distribute the proper amount of air to the rooms. Detailed analysis and recommendations addressing each of these deficiencies can be found later in this report.

Further complicating efforts to address the deficiencies and improvements are lack of funds, available time at which the school is unoccupied to perform renovation work (ie. Summer recess or holiday breaks), the fire rating and classification of the building and the current supply chain/inflation concerns driving the cost of construction to be higher than normal.

Bethel has identified up to a maximum of \$1,400,000 in funds that is compiled from grants and town funds that may be available for immediate upgrades. Based on limited initial project funds available, the school has identified priority 1 items for design such as adding cooling to classrooms that are currently heated only and replacement of unit ERU-2. To work within the budget, two alternatives would be designed as additional priority 1 and a priority 2 space if funds allow. A phased approach to these upgrades may be implemented in order to manage the timing and initial costs with annual budgets.

Adding air conditioning to all classrooms and addressing ERU-2 has cost ranging from \$3.8M to \$4.7M depending on the option selected. Replacement of AHX-1, adding air conditioning to the gym, locker rooms, weight room, and wrestling room has a budget around \$2.64M. A full detail list of costs are summarized in Appendix B-Mechanical Upgrades Estimates.

III. BUILDING INFORMATION & LAYOUT

Bethel High School is a three-story building originally constructed in 1970 with an addition built in 1975 and 2007 totaling approximately 167,000 total square feet. The building consists of a gymnasium, weight room, locker rooms, cafeteria, administrative offices, and a variety of classrooms on floors 1-3.



Building Location & Surrounding Area



Southwest Elevation




Example of Rooftop Equipment




Boiler Plant


IV. BUILDING PLANS



1st Floor




2nd Floor




3rd Floor


V. EXISTING HVAC ZONING PLANS



First Floor Existing Zoning



Second Floor Existing Zoning



Third Floor Existing Zoning

VI. MECHANICAL SYSTEM DEFICIENCIES & RECOMMENDATIONS

Heating and Cooling Plants

Bethel High School is heated by a gas fired condensing boiler plant producing hot water at the first-floor level. The boiler plant consists of (4) 3,840 MBh Patterson-Kelley boilers each furnished with a dedicated inline primary pump. The hot water plant is piped in a primary loop / secondary loop fashion with (3) secondary loops leaving the boiler room. The first secondary loop is served by Taco end suction lead/standby pumps sized for 80 gpm at 90 feet of head. The second secondary loop is served by Taco end suction lead/standby pumps sized for 140 gpm at 175 feet of head. Similarly, the third secondary loop is served by Taco end suction lead/standby pumps sized for 460 gpm at 130 feet of head. Hot water is distributed to air handling units AHX-1, ERU-1, and ERU-2 on the roof. Hot water is also circulated to indoor equipment such as MAU-1, AHU-3A, AHU-3B, perimeter radiation, duct mounted reheat coils, terminal box reheat coils, unit ventilators and unit heaters. A glycol feeder is connected to the building hot water loop maintaining a propylene glycol concentration of approximately 30%. The boiler plant equipment in good condition and appears to be only 2 or 3 years old. Building heat is also provided by gas fired packaged rooftop units AHU-2, 4, 5, 6, 7, 8, 9, 10, and 13.

Cooling is provided to portions of the building via packaged DX rooftop units AHU-2,5, 7, 8, 9, 10, and 13 as well as split DX units AHX-1, ERU-1 and ERU-2. Additional mini split units were installed as means to cool select rooms in the building. AHU-12 was removed from the roof under the 2007 renovation, and it's associated steel dunnage was abandoned in place. The maintenance staff noted that AHU-11 was inactive and abandoned in place.




Typical Hot Water Boiler




Typical Packaged RTU Condenser Section


Currently, air conditioning is provided in the core of the 1975 building, cafeteria, auditorium, library, computer labs, office areas and approximately 12 perimeter classrooms. Rooms that are not cooled are being targeted for a new cooling system including 36 classrooms, the gymnasium, its nearby wrestling room and exercise room. Refer to the diagrams below for rooms requiring cooling.



First Floor Rooms with No Air Conditioning



Second Floor Rooms with No Air Conditioning



Third Floor Rooms with No Air Conditioning

Air Handling Units

AHX-1 Description:

Unit AHX-1 is built up in multiple sections all housed within a rooftop penthouse. This air handling unit provides conditioned air to core classrooms on floors 1, 2, and 3 of the 1975 addition. It is sized for 38 tons of cooling, 449 MBh of heating, and 9,200 CFM. The unit is a variable air volume Trane Climate Changer consisting of a sheet metal mixing box, filter section, hot water coil, DX cooling coil, remote condensing unit, remote belt driven supply fan, and a remote belt driven return fan. Signs of repair and improvements were observed such as re-sealing of ductwork, a new motor on the supply fan, and both fans have been retrofitted with variable frequency drives. AHX-1 provides conditioned air to VAV boxes without reheat coils.

AHX-1 Analysis:


It was noted that AHX-1 was not delivering sufficient airflow. This was apparent as the fan drives were constantly operating at 100% in an attempt to satisfy the spaces. AHX-1 is original to the 1975 construction and although it is in fair condition for its age it is well past its expected lifespan. Additionally, the return air ductwork within the penthouse was damaged and air leakage was observed at the roof penetration access doors.

The rooftop condensing unit serving AHX-1, tagged as CU-3, is mounted on steel dunnage without external vibration isolation. The unit is comprised of 4 compressors which have damaged and missing refrigerant pipe insulation and mild corrosion at the pipe fittings. The condensing unit utilizes R-22 refrigerant which has been phased out. The unit was installed during the 2007 renovation and replaced an existing chilled water coil serving AHX-1.

After performing heating and cooling load calculations it appears that AHX-1 is undersized by approximately 400 CFM. to maintain 75°F on a design summer day. Upon a review of the controls, a majority of the AHX-1 spaces had a setpoint of 70°F – 73°F. In order to maintain a more comfortable 72°F average, this unit will need to increase in capacity from 38 to 45 tons, and 10,800 CFM of total supply air.



Damaged CU-3 Insulation



CU-3 on Dunnage

AHX-1 Recommendations:

Remove AHX-1 and its associated condensing unit entirely. Replace this unit in kind with a modular air handling unit sized for 10,800 CFM similar to a Trane Climate Changer matching the components of the existing AHX-1 including its remote condensing unit. Cooling capacity shall be increased to 45 tons. Existing steel dunnage supporting the condensing unit shall be cleaned, treated for corrosion, and painted. New ductwork shall connect to the existing duct risers at the floor of the penthouse.


All existing ductwork serving AHX-1 shall be cleaned, pressure tested, sealed as needed, and reused. AHX-1 zoning shall not change. Refer to equipment pricing as this is not a priority item.

Option 1, Priority 1: All classrooms in the 1975 addition that are not served by AHX-1 or split AC units shall be cooled via 33"x33" ceiling cassette VRF units similar to Trane model TPLFY. Exterior classrooms shall be sized for approximately 2.5 tons of cooling each and interior classrooms shall be sized for approximately 2 ton of cooling each. The cassette units shall be connected to outdoor roof mounted VRF heat pump condensing units similar to Trane model TUHY with a total capacity of approximately 60 tons. Condensing units shall be mounted on 24" high rooftop equipment rails.


Ventilation to the perimeter classrooms shall be provided via (2) new rooftop dedicated outside air unit sized for approximately 6,250 CFM each similar to a Greenheck model RVE, tagged as DOAS-3 and DOAS-4 on the plans. The new units shall compose of filter sections, an energy recovery wheel, DX cooling coil, hot gas reheat coil, hot water reheat coil, supply air fan section and exhaust air fan section. New DOAS unit ductwork shall be routed on the roof to new risers located inside the building. Much of the existing exhaust ductwork can be retained with some modifications to serve as exhaust air back to the DOAS units. DOAS unit ventilation air shall distribute to all classrooms in the 1975 addition not served by AHX-1. All existing unit ventilators shall be removed and replaced with finned tube radiation. The new DOAS units and radiation shall be controlled via the BMS. The VRF system shall be controlled by factory controllers and monitored by the BMS.

Option 2, Priority 1: Remove AHX-1 and its associated condensing unit entirely. Replace this unit with a custom dedicated outside air unit sized for approximately 15,350 CFM similar to a Trane's custom offering, tagged as DOAS-5 on the plans. The new unit shall be installed within the existing penthouse and shall include filter sections, an energy recovery wheel controlled via VFD, DX cooling coil, a hot water reheat coil, supply air fan section and exhaust air fan section. New ductwork shall connect to the existing duct risers at the floor of the penthouse. Additional ductwork shall route on the roof to new risers located inside the building. A remote condensing unit shall be installed on the existing condensing unit dunnage using new supplemental galvanized steel supports. Existing steel dunnage shall be cleaned, treated for corrosion, and painted.


Existing ductwork through the building shall be cleaned, pressure tested, sealed as needed, and reused. New duct mains and risers shall be installed as necessary to provide ventilation to all rooms in the 1975 addition. Existing unit ventilators shall be removed and replaced with finned tube radiation. All classrooms in the 1975 addition shall be conditioned via 33"x33" ceiling cassette units similar to Trane model TPLFY. Exterior classrooms shall be sized for approximately 2.5 tons of cooling each and interior classrooms shall be sized for approximately 2 ton of cooling each. The cassette units shall be connected to outdoor roof mounted VRF heat pump condensing units similar to Trane model TUHY with a total capacity of approximately 86 tons. VRF condensing units shall be mounted on 24" high rooftop equipment rails. The new outside air unit, VRF system, and radiation shall be controlled via the building BMS. Option 2 is not a recommended option as it would be expensive, very disruptive, and difficult to achieve over a short summer break. It is shown for reference only and not being recommended.




Option 1 - VRF Classrooms - First Floor (AHX-1 for Reference Only)




Option 1 VRF Classrooms – Second Floor (AHX-1 for Reference Only)




Option 1 VRF Classrooms – Third Floor (AHX-1 for Reference Only)



Option 2 All VRF Classrooms – First Floor



Option 2 All VRF Classrooms – Second Floor



Option 2 All VRF Classrooms – Third Floor

AHX-1 Penthouse Analysis:

The rooftop penthouse containing the components for AHX-1 has internal dimensions of approximately 44'-6"L x 17'-6"W x 8'-9"H. The penthouse is heated via a hot water unit heater. At the time of survey, the unit heater fan was running continuously without any hot water flowing through it. A hot water control valve serving this unit heater was not found.

The penthouse is cooled via a sidewall propeller exhaust fan and intake air damper. The damper appeared to be in good condition, but it is controlled via an antiquated actuator. The exhaust fan is corroded, in poor condition and appears to be inoperable. An abandoned suspended expansion tank was found in the penthouse which appears to be left over from the 2007 renovation. This is typical of items that were specified to be removed and were not as part of the renovation project.



Penthouse Unit Heater



Penthouse Exhaust Fan



Penthouse Intake Damper



Abandoned Expansion Tank

AHX-1 Penthouse Recommendations:

Provide a new DDC 2-way hot water control valve to serve the penthouse unit heater. Remove and replace the penthouse propeller exhaust fan with a new fan in kind sized for approximately 700 CFM. Remove and replace the penthouse make up air damper actuator with a new actuator.

Connect the penthouse fan and makeup damper to the building BMS and monitor penthouse temperature. Remove the abandoned expansion tank and any other abandoned appurtenances.

AHU-2 Description:

AHU-2 is installed on the original 1970 building roof and provides conditioned air to classrooms on the third floor, and teacher lounges and a classroom on the second floor. It is sized for 31 tons of cooling, 320 MBh of heating, 3,500 CFM of ventilation air, and 9,300 CFM of total supply air. The unit is a variable air volume McQuay model RPS030CLA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, DX cooling coil, integral condensing unit, belt driven supply fans, and belt driven return fans. This unit provides conditioned air to VAV boxes with reheat coils.

AHU-2 Analysis:

The unit was installed during the 2007 renovation and is in fair condition. Dirt and debris were seen inside the unit and on the cooling coil. Damaged cooling coil fins were observed as well as corrosion at the base of the coil. The unit contains 3 compressors which have damaged refrigerant insulation. Wiring splices were found in the supply fan section exposed to the airstream which should be contained in a junction box. AHU-2 does not have any reported issues with cooling, but it has been reported that AHU-2 spaces are subject to overheating. Since there are VAV boxes with reheat coils on this system, this can be avoided.



AHU-2 Cooling Coil Damage



AHU-2 Cooling Coil Corrosion



AHU-2 Damaged Refrigerant Insulation



AHU-2 Cooling Coil Corrosion

AHU-2 Recommendations:

Prior to the replacement of AHU-2 it is recommended that the controls be retro-commissioned to determine the cause of the occasional over heating concerns. Control sequence modifications shall be completed as required.

Option 1 (Recommended): Remove and replace AHU-2 in kind with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized to match the existing unit capacity. Provide a new adaptor curb and reconnect to the existing supply and return air main risers. All existing ductwork serving AHU-2 shall be cleaned, pressure tested and sealed as needed. All existing VAV boxes served by AHU-2 shall be inspected, cleaned, and reused. Two offices and one special education classroom on the second floor currently have no airflow and shall be furnished with new VAV boxes with hot water reheat coils fed from AHU-2.

Neighboring history and special education classrooms on the third floor that do not have cooling shall be outfitted with 33"x33" VRF ceiling cassette units similar to Trane model TPLFY. Cassette units serving the western bank of rooms on the third floor shall connect to outdoor roof mounted VRF heat pump condensing units sized for approximately 14 tons of cooling. VRF condensing units shall be similar to Trane Model TUHY mounted on 24" high equipment rails.

The history and special education classrooms served by VRF shall be ventilated via a dedicated rooftop outside air ventilator sized for approximately 2,600 CFM similar to a Greenheck model RVE tagged as DOAS-2 on the drawings. The new unit shall be installed on a new 18" high rooftop curb with supplemental structural framing. The rooftop ventilator shall include filter sections, an energy recovery wheel, DX cooling coil, hot gas reheat coil for dehumidification, a hot water reheat coil, supply air fan section and exhaust air fan section. Hot water piping shall be extended from nearby mains. The new AHU-2 and DOAS-2 shall be controlled via the BMS. The VRF system shall be controlled by factory controllers and monitored by the BMS

Option 2: Remove and replace AHU-2 with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized for 50 tons of cooling, 688 MBh of heating, 4,800 CFM of ventilation air, and 12,000 CFM of total supply air. Connect to existing supply and return air risers. Provide new roof mounted supply and return air mains to new roof penetration serving history and special education classrooms on the third floor that do not currently have cooling. Outfit these rooms with new VAV boxes complete with hot water reheat coils. Provide (1) VAV box per classroom. Extend hot water from nearby mains serving radiation. Existing VAV boxes shall be reused and shall have their reheat coils inspected and cleaned. Re-balance all existing

VAV boxes. All existing ductwork serving AHU-2 to remain shall be cleaned, pressure tested and sealed as needed. New AHU-2, VAV boxes, and reheat coils shall be controlled by the BMS.



Option 1- AHU-2 & VRF (ACCU3-3) – Third Floor




Option 2 – Larger AHU-2 – Third Floor

AHU-3A and AHU-3B Description:

Units AHU-3A and AHU-3B are installed in a small mechanical room on first floor and provides heating to the boy's locker rooms and girl's locker rooms respectively. Each unit is sized for 267 MBh of heating, 2,000 CFM of ventilation air, and 4,000 CFM of total supply air. The units are vertical constant air volume McQuay model CAH008GHAC indoor unit consisting of a mixing box, filter section, hot water heating coil and supply fan.

AHU-3A and AHU-3B Analysis:

The units were installed during the 2007 renovation and are in good condition. Dirt and debris were seen inside the units and on the heating coils. The unit dampers, gaskets, fans, and components all appear to be in good working order. Hot water is controlled via a 3-way control valve and no deficiencies to the piping, components, or insulation were found. These units have a ducted outside air connection sized for airside economizer and no insulation was seen on the outside air ductwork. Insulation is required by the energy code. It was also cold to the touch at the time of survey. Although no condensation or water damage was found, this ductwork should be insulated to eliminate potential condensation issues and to comply with the energy code. Breakout noise from AHU-3A and 3B is audible within the locker rooms.



AHU-3A Heating Coil Piping



AHU-3A Dirty Heating Coil

AHU-3A and AHU-3B Recommendations:

Although these units are in good operating condition, they do not cool nor dehumidify the locker rooms. Furthermore, they are not modular construction so adding a cooling coil to the existing units is not feasible. Both units shall be removed and replaced with new vertical modular air handling units similar to Trane Climate Changers, matching the current 4,000 CFM each. Each unit shall include a filter section, DX cooling coil, and vertical supply fan section. New duct mounted hot water reheat coils shall be installed in the supply air duct main above the ceiling of both locker rooms. All existing ductwork shall be cleaned and reused. The existing outside air ductwork shall be insulated with R-6 fiberglass duct wrap. The remote condensing units shall be mounted on the roof on 24" high equipment rails. The locker room inline exhaust fan (EF-1) shall be inspected and reused. The sidewall discharge louver associated with EF-1 shall be inspected and cleaned. The new air handlers and reheat coils shall be controlled by the BMS. Noise output of the new replacement units should be evaluated during the next phase of design. Duct silencers may be considered based on the new unit's published acoustical data.

AHU-4 Description:

AHU-4 is installed on the original 1970 building roof and provides heated air to the gymnasium. It is sized for 1,500 MBh of heating, 6,000 CFM of ventilation air, and 18,000 CFM of total supply air. The unit is a constant air volume McQuay model RAH077CYA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, belt driven supply fans, and belt driven return fans.

AHU-4 Analysis:

The unit was installed during the 2007 renovation and is in good condition. Dirt and debris were seen inside the unit and on the fan bearings. Light corrosion was observed on the heat exchanger condensate discharge. At the time of survey, the outside air damper and relief dampers were fully closed, and the unit was only recirculating air. The facilities staff noted this unit frequently shuts off on flameout. The gas pressure regulator is tagged with a 6 to 13 in. w.c. spring and the unit burner is tagged as requiring 8 in. w.c. minimum. Lastly, duct lining was not seen on the unit supply or return ductwork.



AHU-4 Casing and Shut Relief Damper



AHU-4 Natural Gas Train



AHU-4 Debris on Fan Bearing



AHU-4 Corrosion on Condensate Discharge

AHU-4 Recommendations:

Remove and replace AHU-4 in kind with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized to match the existing unit airflow and heating capacity. Provide a new adaptor curb and reconnect to the existing supply and return air main risers. The new unit shall be composed of a mixing box, filter section, DX cooling coil, hot gas reheat coil, integral condensing unit, indirect natural gas burner, belt driven supply fans, and belt driven return fans. The condensing unit section shall be sized for 70 tons of cooling. All existing ductwork serving AHU-4 shall be cleaned and sealed as needed. Internal lining should be added at least 15 feet downstream of the supply fan and 15 upstream of the return/relief air fan. New AHU-4 shall be controlled by the BMS.

Until this unit is replaced it is recommended to remove and clean the gas regulator orifice, inspect the internal condition of the gas piping, and verify the spring is adjusted to properly deliver the 8 in. w.c. minimum gas pressure.

AHU-5 Description:

AHU-5 is installed on the original 1970 building roof and provides conditioned air to the Administration and Guidance offices on the second floor. It is sized for 250 MBh of heating, 24 tons of cooling, 2,500 CFM of ventilation air, and 7,400 CFM of total supply air. The unit is a variable air volume McQuay model RPS020CSA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, DX cooling coil, integral condensing unit, belt driven supply fans, and belt driven return fans. This unit provides conditioned air to VAV boxes with reheat coils.

AHU-5 Analysis:


The unit was installed during the 2007 renovation and is in poor condition. Minor damage to the exterior duct insulation and refrigerant piping was observed. The cooling coil has damage to the fins and corrosion at the coil base. The return fan was out of balance with visible oscillation and excessive noise radiated from the supply fan possibly indicating a failing bearing. Excessive air leakage was observed at the unit module junctions. A plumbing vent was installed close to the outside air intake which does not comply with current code. The air balance report indicates this unit is providing less airflow than design. Lastly, the exterior ductwork was routed in such a way that it prevents access to the unit heating section.




AHU-5 Damaged and Corroded DX Coil



AHU-5 Supply Fan



Plumbing Vent Near AHU-5 Intake




Exterior Ductwork Obstructing Access

AHU-5 Recommendations:

Remove and replace AHU-5 with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized to match the existing unit airflow and capacity. New AHU-5 shall be relocated on the roof to avoid service conflict with the existing duct penetrations and to avoid existing plumbing vents. The unit shall be mounted on new steel dunnage at its new location.

Existing VAV boxes and ductwork serving the administrative and guidance offices shall be inspected, cleaned, and reused. Provide a new VAV box with reheat coil dedicated to the administrative office lobby. Extend hot water from nearby existing reheat coil piping. Re-balance all existing VAV boxes to original design airflows. All existing ductwork serving AHU-5 to remain shall be cleaned, pressure tested and sealed as needed. New AHU-5, VAV box, and reheat coil shall be controlled by the BMS.



AHU-5 Proposed Correction – Second Floor

AHU-6 Description:

AHU-6 is installed on the original 1970 building roof and provides heated air to the Weight Room and Wrestling Room. It is a 100% outside air unit sized for 320 MBh of heating and 3,600 CFM of total supply air all of which is used for ventilation. The unit is a constant air volume McQuay model RDS800CYA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, belt driven supply fans, and belt driven return fans.

AHU-6 Analysis:

The unit was installed during the 2007 renovation and is in good condition. Heavy dirt and debris were observed on the return fan bearings. Mild corrosion was found on the unit casing as a result of the acidic burner condensate. The facilities staff noted this unit occasionally shuts off on flameout, although not as frequently as the neighboring AHU's.



Debris on AHU-6 Fan Bearing



AHU-6 Overall

AHU-6 Recommendations:

Remove and replace AHU-6 in kind with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model HAXX sized to match the existing unit airflow and 18 tons of cooling. Provide a new adaptor curb and reconnect to the existing supply and return air risers. If noise is a concern, consider installing duct mounted supply and return air silencers at this time. The new unit shall be composed of a mixing box, filter section, DX cooling coil, hot gas reheat coil, indirect natural gas burner, integral condensing unit, supply air fan, and exhaust air fan.

New VAV boxes shall be provided to serve the weight room and wrestling room as individual zones. Both VAV boxes shall be furnished with a hot water reheat coil. Hot water shall be extended to the new VAV boxes from nearby mains. Each room shall be outfitted with a thermostat and CO2 sensor for temperature and ventilation control. Existing supply air ductwork shall be modified as needed to accommodate the new VAV boxes. All existing ductwork serving AHU-6 shall be cleaned, pressure tested and sealed as needed. New AHU-6, VAV boxes, and reheat coils shall be controlled by the BMS.

Until this unit is replaced it is recommended to remove and clean the gas regulator orifice, inspect the internal condition of the gas piping, and verify the regulator spring is adjusted properly to deliver the minimum gas pressure noted on the unit burner.




AHU-6 Proposed Correction – First Floor

AHU-7 Description:

AHU-7 is installed on the original 1970 building roof and provides conditioned air to the Main Lobby. It is sized for 650 MBh of heating, 32 tons of cooling, 4,720 CFM of ventilation air, and 9,000 CFM of total supply air. The unit is a constant air volume McQuay model RPS030CSA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, DX cooling coil, integral condensing unit, belt driven supply fans, and belt driven return fans.

AHU-7 Analysis:

The unit was installed during the 2007 renovation and is in fair condition. Minor damage to the cooling coil fins was observed along with clogging debris, mold growth, and corrosion at the base of the coil. The unit outside air dampers were closed at the time of survey and the unit was operating under a heavy negative pressure. The condensate drain off the gas fired heat exchanger is causing acidic damage to the unit casing. Mild damage to the condenser coil fins and fan guard corrosion was discovered. The facilities staff noted this unit frequently shuts off on flameout when in heating mode. Lastly, no duct lining or silencers was found on the supply or return air ductwork leading to audible noise transmission in the lobby below. In addition, condensate was found on the supply air ductwork in the lobby which appears to be a result of the absence of duct lining along with air infiltrating the lobby from frequent use of the building entrances.



AHU-7 Cooling Coil



AHU-7 Cooling Coil Drain Pan



AHU-7 Heat Exchanger Condensate



AHU-7 Condenser Section

AHU-7 Recommendations:

Remove and replace AHU-7 in kind with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized to match the existing unit airflow and capacity. The new unit shall be furnished with a hot gas reheat coil for dehumidification. Provide a new adaptor curb and reconnect to the existing supply and return air risers. If noise is a concern, consider installing duct mounted supply and return air silencers at this time. The new unit shall be composed of a mixing box, filter section, DX cooling coil, hot gas reheat coil, indirect natural gas burner, supply fans, and return fans. All existing ductwork serving AHU-7 shall be cleaned and sealed as needed. Internal duct lining is recommended at portions of supply air ductwork and return air ductwork near the building entrance. New AHU-7 shall be controlled by the BMS.

Until this unit is replaced it is recommended to remove and clean the gas regulator orifice, inspect the internal condition of the gas piping, and verify the regulator spring is adjusted properly to deliver the minimum gas pressure noted on the unit burner.

AHU-8 Description:


AHU-8 is installed on the original 1970 building roof and provides conditioned air to the athletic offices on the first floor as well as music classrooms on the second floor. It is sized for 320 MBh of heating, 24 tons of cooling, 3,000 CFM of ventilation air, and 11,400 CFM of total supply air. The unit is a variable air volume McQuay model RPS025CLA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, DX cooling coil, integral condensing unit, belt driven supply fans, and belt driven return fans. This unit provides conditioned air to VAV boxes with reheat coils.

AHU-8 Analysis:

The unit was installed during the 2007 renovation and is in fair condition. Minor damage to the cooling coil fins was observed. The coil had considerable amount of dirt on the as did the inside of the unit in general. Additionally, the cooling coil was found to have significant corrosion along the base. The outside air and relief air dampers appear to be operating correctly at the time of survey. The facilities staff noted this unit frequently shuts off on flameout when in heating mode. Lastly, no duct lining or silencers was found on the supply or return air ductwork. This appears to be contributing to the audible noise observed in the lobby below.



AHU-8 Cooling Coil



AHU-8 Cooling Coil Corrosion

AHU-8 Recommendations:

Remove and replace AHU-8 in kind with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized to match the existing unit airflows and capacity. Provide a new adaptor curb and reconnect to the existing supply and return air risers. All existing ductwork serving AHU-8 shall be cleaned, pressure tested and sealed as needed. All existing VAV boxes served by AHU-8 shall be inspected, cleaned, and reused. New AHU-8 shall be controlled by the BMS. If noise is a concern, consider installing duct mounted supply and return air silencers.

Until this unit is replaced it is recommended to remove and clean the gas regulator orifice, inspect the internal condition of the gas piping, and verify the regulator spring is adjusted properly to deliver the minimum gas pressure noted on the unit burner.


AHU-9 Description:

AHU-9 is installed on the original 1970 building roof and provides conditioned air to the cafeteria on the first floor. It is sized for 40 tons of cooling, 3,450 CFM of ventilation air, and 14,770 CFM of total supply air. According to the air balance report dated 7/22/21, the supply airflow was reduced to 9,300 cfm under the 2007 renovation. The unit is a constant air volume Trane model TCH480A40A1A3LG1 packaged rooftop unit consisting of a mixing box, filter section, DX cooling

coil, integral condensing unit, belt driven supply fans, and belt driven return fans. The unit does not have a heating section however a duct mounted 399 MBh hot water reheat coil was added to the supply air main during the 2007 renovation.

AHU-9 Analysis:

The unit was installed in 1995 and is in poor condition. The unit is scheduled for replacement during second and third quarter of 2022, therefore a detailed investigation was not performed. However, the unit support structure and existing exterior ductwork was examined. The dunnage and associated service platform is constructed of painted carbon steel structural beams. The paint has weathered over time and the structural dunnage is in poor condition. The exterior ductwork appears to have minor holes in the fiberglass insulation which led to sagging and degradation from rain.



AHU-9 Support Dunnage



AHU-9 Duct Insulation

AHU-9 Recommendations:

Remove all abandoned and unused steel dunnage. Provide new galvanized steel supports as part of the new AHU-9 replacement. If this is not practical the existing steel dunnage should be stripped and painted with a rust inhibitive type paint. It is recommended to have the existing ductwork and reheat coil inspected, cleaned, pressure tested, and sealed as needed prior to final unit operation. It is also recommended to replace the insulation on any rooftop ductwork to be reused with a closed cell insulation such as polyisocyanurate or flexible elastomeric. New exterior duct insulation should be a minimum R-12 and shall be protected with a self-adhesive aluminum jacketing.

AHU-10 Description:

AHU-10 is installed on the original 1970 building roof and provides conditioned air to the Media Center and adjacent computer labs on the third floor. It is sized for 400 MBh of heating, 25 tons of cooling, 4,720 CFM of ventilation air, and 8,450 CFM of total supply air. The unit is a variable air volume McQuay model RPS020CSA packaged rooftop unit consisting of a mixing box, filter section, indirect natural gas burner, DX cooling coil, integral condensing unit, belt driven supply fans, and belt driven return fans.

AHU-10 Analysis:

The unit was installed during the 2007 renovation and is in poor condition. The cooling coil has excessive damage to the fins and corrosion at the coil base. Unit access door gaskets are ripped or dislodged from their mounting seam. The outside air damper was completely shut at the time of survey causing a high negative pressure inside the unit. The exterior roof mounted ductwork is

wrapped with fiberglass insulation which has holes and signs of water damage. Similarly, the refrigerant insulation is ripped, and corrosion was found at the compressor fittings.



AHU-10 Damaged Cooling Coil



AHU-10 Damaged Door Gasket



AHU-10 Water Damaged Duct Insulation



AHU-10 Damaged and Corroding Compressor

AHU-10 Recommendations:

Remove and replace AHU-10 in kind with a new variable air volume gas fired / DX packaged rooftop unit similar to a Trane model IPAK sized to match the existing unit airflows and capacity. Provide a new adaptor curb and reconnect to the existing supply and return air mains on the roof. All existing rooftop ductwork shall be reinsulated with a closed cell product such as polyisocyanurate or flexible elastomeric insulation. Exterior insulation shall be protected with a self-adhesive aluminum jacketing. A new supply air main shall be routed to the (2) computer labs adjacent to the media center. Each computer lab shall be furnished with a new VAV box. The existing supply air main serving the media center shall be furnished with a slip in retrofit VAV box. New space mounted thermostats and CO2 sensors shall be installed to control temperature and ventilation. All existing ductwork serving AHU-10 shall be cleaned, pressure tested and sealed as needed. New AHU-10 and VAV boxes shall be controlled by the BMS.



AHU-10 Proposed Correction – Second Floor

AHU-11 Description:

AHU-11 is installed on the original 1970 building roof and provides cooling to the Broadcast Studio. No documentation is available for this unit however it was determined to have 6 tons of cooling capacity. It is a Trane model TSC072A3R0A0HH100A100A6C0 packaged rooftop unit consisting of a mixing box, filter section DX cooling coil, integral condensing unit, and a supply air fan. The unit is designed for 208 / 230V – 3 phase power which is different than all the other 480V rooftop units.

AHU-12 was removed during the 2007 renovation with its ductwork capped at the roofline and dunnage abandoned in place. This unit used to serve the 1970 Choral Room behind the auditorium stage on the second floor. The Choral room was converted to two classrooms in 2007 with no cooling at the time but have since been furnished with mini split units.

AHU-11 Analysis:

AHU-11 was installed around 2002 and is in inoperable condition. The facilities staff noted this unit has not operated in years. The exterior ductwork serving this unit is not protected and has an excessive amount of corrosion as a result. Rust was observed around the unit base along with damaged condenser fins.



AHU-11 Corroded Ductwork



Abandoned AHU-12 Dunnage and Ductwork

AHU-11 Recommendations:

Remove and replace AHU-11 in kind with a new variable air volume DX heat pump packaged rooftop unit similar to a Trane Precedent sized for 5 tons of cooling, 400 CFM of ventilation air, and 2,000 CFM of supply air. Provide a new roof curb and reconnect to the existing supply and return sidewall duct penetrations. Damaged exterior ductwork shall be removed, replaced, and insulated with a closed cell R-12 insulation such as polyisocyanurate or flexible elastomeric and protected with a self-adhesive aluminum jacketing. All existing ductwork serving AHU-11 shall be cleaned and sealed as needed for reuse.

All abandoned dunnage serving the previous AHU-12 should be removed entirely.

AHU-13 Description:


AHU-13 is installed on the original 1970 building roof and provides conditioned air to the Auditorium on the second floor. It is sized for 75 tons of cooling and 23,900 CFM of total supply air. According to the air balance report dated 7/22/21, the unit was operating at 84% airflow and damaged ductwork with excessive leakage was since repaired. The unit is a Trane model SXHFC7540EC5C79D1001AELRT packaged rooftop unit consisting of a mixing box, filter section, DX cooling coil, integral condensing unit, belt driven supply fans, and belt driven return fans. The unit provides conditioned air to (5) duct mounted reheat coils.

AHU-13 Analysis:

The unit was installed in 1995 and is in poor condition. The unit is scheduled for replacement during second and third quarter of 2022, therefore a detailed investigation was not performed. However, the unit support structure and existing exterior ductwork was examined. The base rail and associated service platform is constructed of painted carbon steel structural beams. The paint has weathered over time and the structural dunnage is rusting. Additional dunnage from previous units remains adjacent to AHU-13, abandoned in place. The exterior supply air ductwork serving AHU-13 is in poor condition and has excessive air leakage at all seams.



AHU-13 & Abandoned Dunnage



AHU-13 Example of Leaking Duct Seam

AHU-13 Recommendations:

Remove all abandoned and unused steel dunnage. Provide new galvanized steel supports as part of the new AHU-13 replacement. If this is not practical the existing steel dunnage should be stripped and painted with a rust inhibitive type paint. It is recommended to have the existing ductwork, lining, and reheat coils inspected, cleaned, and sealed as needed prior to final unit operation.

ERU-1 and ERU-2 Description:

Units ERU-1 and ERU-2 are installed on the original 1970 building roof. ERU-1 provides 100% conditioned outside air to the science classrooms on the third floor and ERU-2 provides 100% conditioned outside air to the science classrooms on the second floor. Both units are nearly identical, each sized for 287 MBh of heating and 30 tons of cooling. The only difference between the units is ERU-1 is sized for 7,800 CFM and ERU-2 is sized for 7,600 CFM. Both units are constant air volume Venmar model 9318 modular rooftop units consisting of a filter section, hot water coil, DX cooling coil, energy recovery wheel, remote R22 condensing unit, belt driven supply fans, belt driven exhaust fans, and a bypass for unoccupied mode. Both units provide conditioned air to duct mounted reheat coils inside the building.

It was reported that ERU-2 was not providing proper airflow to the science classrooms on the second floor during our initial walkthrough. The explanation of no supply airflow while the fan was running seemed to point to clogged duct mounted hot water coils or a closed damper. During the initial kickoff meeting we identified the location of the ERU-2 duct risers along with their associated fire dampers using the 2006 design drawings. At that point we investigated the duct chase, opened the fire damper access door, and found the fire damper completely closed due to broken linkage. That was the cause of the airflow issue and facilities immediately called the service company to replace the linkage. Apparently, this flow issue was ongoing for some time but was a simple fix.

ERU-1 and ERU-2 Analysis:

ERU-1 was installed during the 2007 renovation and is in poor condition. The cooling coil has corrosion at its base and debris was seen on both coils. The hot water and refrigerant valves and hangers have excessive surface rust. Rust was also observed on the remote condensing unit frame, coil guard, and compressor fittings. Lastly, the hot water piping serving ERU-1 is supported by pipe clamps at the roof penetration that have rotted and are crumbling. The exhaust fan is furnished with a nearly new electric motor.

ERU-2 was installed during the 2007 renovation and is also in poor condition. Most notably, the energy wheel has failed completely and is currently dismantled. The unit is actively running with its bypass damper open recirculating air to lab spaces. Airflow from the science labs should not be circulated under occupied periods. These science rooms should be restricted in use until this unit is either repaired or replaced as to not recirculate any potential odors or limited hazards. The cooling coil has heavy corrosion at its drain pan locations and up the casing of the coil. An excessive amount of dirt and grime was observed on both the heating and cooling coils as well as corrosion of exterior valves and components.

ERU-1 and ERU-2 Recommendations:

It is recommended to remove and replace both ERU-1 and ERU-2 in kind with a new constant air volume hot water / DX packaged rooftop unit similar to a Semco model EPHC sized to match the existing unit airflows and capacity. Provide steel modifications based on unit size and reconnect to the existing supply and return air main risers for each unit. The new units shall be composed of a mixing box, filter section, DX cooling coil, hot gas reheat coil, hot water heating coil, supply air fans, and exhaust air fans. The cooling coil shall be connected to a new remote roof mounted condensing unit at the existing unit location. New supplemental steel dunnage shall be added to support the new condensing unit. All existing ductwork and reheat coils serving ERU-1 and ERU-2 shall be inspected, cleaned, pressure tested and sealed as needed. The cost to replace the failed energy wheel in ERU-2 is approximately \$80,000 compared to an estimated \$288,000 for full unit replacement. Repair of the wheel is not recommended.




ERU-1 Cooling Coil



ERU-1 Exterior Pipe Hanger and Valves



ERU-1 Compressors



ERU-1 Hot Water Penetration



ERU-2 Energy Wheel



ERU-2 Cooling Coil Corrosion

MAU-1 Description:

Unit MAU-1 is installed above the ceiling of the kitchen and provides heated make up air for the kitchen hood exhaust. It is sized for 450 MBh of heating and 5,000 CFM of outside air. The unit is a constant air volume McQuay model CAH010GHAC suspended air handler consisting of a filter section, hot water coil, and a belt driven supply air fan. Access to this unit is difficult but not impossible.

MAU-1 Analysis:

MAU-1 was installed during the 2007 renovation and is in good condition. The duct insulation on the unit inlet is deteriorating and the inlet louver is completely obstructed with debris. Likewise, the hot water coil is coated, almost entirely with dirt. One filter was observed to be dislodged from its frame allowing the coil to become contaminated. The supply fan motor was running at the time of survey. However, a loose fan belt prevented the fan wheel from spinning. The unit is actively running in "hand" mode. The design drawings indicate a freeze pump serving the hot water coil however that freeze pump could not be located and may not exist. Glycol in the hot water system is likely protecting this coil from freezing.

Access to repair or replace major components for MAU-1 is blocked by adjacent wall framing and the kitchen equipment below. Routine maintenance items such as filter and belt replacement is very difficult with the current unit location.



Clogged MAU-1 Heating Coil



MAU-1 Supply Fan with Loose Belt

MAU-1 Recommendations:

MAU-1 is in good working condition and shall remain. However, this unit requires a thorough cleaning as well as a new, properly adjusted fan belt. The inlet ductwork, discharge ductwork, and outside air louver should be thoroughly cleaned as well. Service access is a challenge with the current unit arrangement. It is recommended to add a service platform above the kitchen hood in order to properly maintain this unit. Note upon discovery, facilities was notified and the service company was contacted to address the concerns of the dirty coil and belt but the other items still need attention.

Split AC Units Description:


Supplemental split air conditioning units have been installed in select rooms throughout the building in order to provide cooling for some rooms that are not served by a central air handling unit. Split units by Mitsubishi and Sanyo were found on the building roof and supported on some exterior walls. These split systems seem to date back to 2017 and range from good condition to nearly new. A Mitsubishi City Multi VRF system was found serving 3 offices on the third floor.

Split AC Units Analysis:

One condensing unit on the back of the building was noted to have damaged insulation and a pipe support that is obstructing its disconnect switch. Some roof mounted condensing units are mounted on wood blocking a few inches off the roof making them subject to snow entrainment. The Sanyo condensing units on the roof have missing casing sections with exposed control wiring that have been weathered at an accelerated rate. The indoor units are ductless wall mounted units or ductless ceiling cassettes. These indoor units provide cooling only and do not supply their spaces with ventilation air.

Split AC Units Recommendations:

Mount all rooftop condensing units on 24" high equipment rails to avoid snow infiltration. Relocate the pipe hanger on the wall mounted unit to avoid the unit's disconnect switch.



Obstructed Disconnect Switch



Example Indoor Ceiling Cassette Unit



Roof Mounted Condensing Unit On Wood Blocks



Sanyo Condensing Unit With Water Damage

Art, Culinary and Science Rooms Without Cooling

The art, culinary, and science rooms on the second floor are heated only with finned tube radiation and exhausted with rooftop fans. The fans did not appear to be running at the time of survey. The culinary room is furnished with a heat capture hood above commercial cooking equipment. This hood has a sidewall exhaust to the exterior of the building with no backdraft damper allowing a large amount of infiltration.

Recommendations:


Option 1: Provide a new 100% outside air variable volume rooftop air handling unit sized for 560 MBh of heating, 40 tons of cooling, and 11,000 CFM total supply air, tagged as AHU-14 on the drawings. The unit shall be similar to a Trane Horizon and shall be composed of filter sections, an energy recovery wheel, DX cooling coil, indirect gas fired burner, a recirc damper for unoccupied mode, supply air fans, and exhaust air fans. The unit shall deliver 100% outside air to these classrooms without any recirculation. This unit shall be installed on new galvanized steel dunnage.

New exterior roof mounted ductwork shall extend to new vertical duct risers installed through the third floor in order to distribute conditioned air to the second-floor classrooms. Each classroom shall be outfitted with new VAV boxes complete with hot water reheat coils. Provide (1) VAV box and thermostat per classroom. Extend hot water from nearby mains serving radiation. Remove the exhaust fans and exhaust ductwork serving these classrooms. All exhaust shall be ducted back to the new rooftop air handling unit, sized to maintain a negative cfm offset in relation to the new supply VAV boxes. Existing perimeter radiation shall remain. New AHU-14, VAV boxes, and


reheat coils shall be controlled via the BMS. Option 1 is not recommended due to the first cost, disruption to the areas of concern and the limited time in which to perform the work over the summer periods.

Option 2: The art, culinary, and science classrooms on the second floor shall be outfitted with 33"x33" VRF ceiling cassette units similar to Trane model TPLFY. Cassette units serving these classrooms shall connect to outdoor roof mounted VRF heat pump condensing units sized for approximately 24 tons of cooling. VRF condensing units shall be similar to Trane Model TUHY and shall be mounted on 24" high equipment rails.

The classrooms shall be ventilated via a dedicated rooftop outside air ventilator sized for approximately 4,500 CFM similar to a Greenheck model RVE, tagged as DOAS-1 on the drawings. The new unit shall be installed on new galvanized steel dunnage. The rooftop ventilator shall include filter sections, an energy recovery wheel, a DX cooling coil, hot gas reheat coil for dehumidification, a hot water reheat coil, supply air fan section and exhaust air fan section. Hot water piping shall be extended to the unit from nearby mains. Provide new exterior roof mounted duct mains extending to new duct risers through the third floor. New supply and exhaust ductwork shall distribute inside the building to feed the classrooms on the second floor. The existing exhaust system serving the art rooms shall be removed completely. Ventilation air shall be controlled via (1) VAV box per classroom and a space mounted CO2 sensor. Existing finned tube radiation shall remain. New DOAS-1 and associated VAV boxes shall be controlled by the BMS. The VRF system shall be controlled by a factory controller and monitored by the BMS.



Art, Culinary and Science Option 1 – Second Floor



Art, Culinary and Science Option 1 – Second Floor

Building Exhaust Fans

Approximately 40 rooftop exhaust fans were discovered. Of them, approximately 12 were installed during the 2007 renovation and were in proper working order. The fans original to 1970 and 1975 are in poor condition, have exterior damage, and most were not running at the time of survey. These older fans can be identified by their dull aluminum fan shrouds. A general overview of the rooftop fans showed that warm building air was exfiltrating out of the fans that were inoperable. This was further confirmed with a thermal imaging camera noting 80°F to 90°F air exfiltrating from the inoperable fans on a 50°F day. It is apparent that some fans either do not have an isolation damper or the damper is no longer holding a seal. Most of the old fans are fed from the existing motor control centers and we believe are controlled by time clocks although all could not be confirmed. Upon reviewing the controls system, approximately 5 fans were found on the BMS.

Fans demolished during the 2007 renovation had existing abandoned curbs with sheet metal caps. However, not all abandoned fans were removed, and some were left in place on the roof, disconnected. Much of the interior ductwork was also abandoned in place during the 2007 renovation.

Recommendations:

It is not in the scope of this report to thoroughly investigate every exhaust fan on a case-by-case basis. It is recommended to have these fans traced out and investigated further to confirm which fans from 1970 and 1975 construction should be active and which fans are abandoned in place. Once determined, said fans should be replaced in kind with new fans, new motor starters and new motorized isolation dampers. All new fans and dampers should be controlled by the BMS. Fans installed under the 2007 renovation shall remain as is. A similar investigation should take

place for the exhaust fans inside the building. At a minimum the fans serving the toilets should be changed as this is an area of biggest complaint for odors. Fans that provide ventilation to unconditioned classrooms also need to be addressed.



EF-32 Thermal Image with Leakage



EF-32 Reference Image with Notable Damage



EF-41 Thermal Image without Leakage



EF-41 Reference Image



Example of Abandoned Fan



Example of Capped Fan Curb

VII. BUILDING AND HVAC DISTRIBUTION EVALUATION

General:

Over to the past 5 years or so there has been an effort to address operating deficiencies within the existing systems. It is recommended that these efforts continue in order to keep equipment and systems not yet scheduled for replacement or renovations operating as efficiently as possible.

Not all areas of the building can be addressed due to budget limitations. That being said, the areas that are not renovated should have the temperature control operations confirmed in order to provide proper controllability to the remaining areas without cooling until future budgets allow for additional renovations.

Many of the original duct systems were abandoned in place during the 2007 renovation. It is recommended that these be removed as time allows or under a scheduled renovation.

During the 2007 renovation the school was changed from a 2B to a 2A classification. This required the creation of fire rated ceilings in certain areas as well extensive spray on fire proofing. This classification makes renovation more costly due to the repair of fire proofing and fire dampers required throughout the building.

Noted miscellaneous grilles are missing throughout the spaces. New grilles should be installed. These areas not specifically noted in the report but can be replaced at Bethels convenience.

Most of the electrical closets with transformers have transfer ducts to the corridors without exhaust and these rooms are hot. It is recommended to add exhaust to these rooms.

The 1970 and 1975 portions of the school utilize natural ventilation in classrooms without unit ventilators. The use of natural ventilation requires operable openings to be sized for 4% of the room's floor area or greater. The existing classroom operable windows are not large enough to achieve this criteria in itself. It appears that exhaust fans were provided under the original building designs to draw ventilation air through the operable windows. Most of these fans are currently inoperable and in some cases the distribution has deficiencies, such as grilles located above the ceiling, which hinder the system from operating as intended. Furthermore, the use of natural ventilation, although allowable by code, results in a large amount of untreated outside air entering a conditioned or non-conditioned space which could result in poor indoor air quality and lack of temperature and humidity control. Therefore, natural ventilation should not be considered for new design options. Instead, mechanical ventilation with outside air treatment shall be utilized to comply with the International Mechanical Code.

The existing corridors do not currently have any means of ventilation. The 2015 International Mechanical Code requires corridors to be ventilated at rate of 0.06 cfm per square foot of floor area. It is recommended to add ventilation to the corridors under the next phase of design to comply with this code requirement.

It has been reported that there are issues with the natural gas system serving the units on the roof. Mainly, several units at times will lockout via internal safeties which require a manual reset. There has been several attempts to try and correct this by the equipment manufacturer and several service companies. The initial issues with regulator vents and regulator spring adjustments have improved the situation but have not completely solved the issue. This is further compounded by the fact that the trips are not solely contingent on load or weather conditions as units have tripped with minimal heating demand.

The gas company supplies high pressure gas to building. Gas pressure is regulated down to 2 psi after the gas meter to feed two main loads. One set of regulators feeds the boilers and kitchen. The other has a single regulator that serves the rooftop equipment and science classrooms. We first thought the piping was potentially undersized. After review of the existing

gas loads with respect to the piping that was ruled out. The gas piping appears to be sized adequately based on the current loads served. At the time of this report there was no conclusive evidence as to the cause of the problem other than a few recommendations identified under each respective unit recommendations.

1970 Wing

First Floor:

Noted mold above the ceiling in the kitchen area above the walk in coolers. It appears to be from condensation caused by the refrigeration piping. This should be remediated, and the insulation and surfaces should be replaced.

The kitchen make-up air louver should be cleaned. The unit was addressed but the louver is partially plugged with debris.

Old EF-22 serves the maintenance shop. This fan was left as part of the 2007 renovation but no longer used. The make-up duct that served the fan has been removed. The fan is located above the kitchen coolers and exhausts through a sidewall louver above the kitchen make up air louver. Separation of exhaust and make up air does not comply with the mechanical code for minimal separation distance. This is not an issue if the systems do not operate simultaneously.

Reheat coils exist that serve the spaces controlled by the Mitsubishi City Multi VRF system which are on the DDC system. The ductwork that these are installed in does not connect to any system as the unit was removed in the 2007 renovation.

Second Floor:

Classroom 228 has the active ducted exhaust pushed above the ceiling and the ceiling tile is set below. This is part of the ventilation system and should be in the classroom, not above the ceiling. Note this classroom is not air conditioned and this condition should be corrected under the proposed scope.

Third Floor:

Classroom 307 has an open-ended exhaust duct above the ceiling with no grille in the classroom. As with classroom 335 it is part of the ventilation system and would be corrected under option 1.

Classroom 309, 310, 312 and 315 have abandoned exhaust ducts or a capped roof curb duct above the ceiling wrapped in plastic. The capped duct is part of the ventilation serving 312 and needs to be active as there are no exhaust grilles for ventilation in the ceiling. Classroom 309, 310 and 315 is served by AHU-2 so this is not an issue other than capping the ducts. These ducts are to be removed or properly capped. Room 312 would be addressed under one of the air conditioning options.

The small boy's bathroom plan west of the TV Studio has the exhaust duct located above the ceiling with no exhaust in the toilet. Exhaust shall be added if the bathroom is to remain in use.

Bathrooms plan east and south of the TV Studio appear to be abandoned. The associated exhaust system was not active. No further action is recommended at this time but when they are renovated, the ventilation system should be upgraded.

Electrical room plan west of 312 has a transfer duct for make-up air. The corridor side has the grill removed and has an open-ended duct above ceiling. The duct needs to be extended to the ceiling as the space above a corridor ceiling cannot be used as a plenum.

Duct mounted reheat coils on the plan west side of the auditorium are dirty and should be cleaned. These coils are served by AHU-13. All the coils on this system should be inspected and

cleaned as well. Access doors should be added for proper service and cleaning where access is not available.

Nurses' area finned tube radiation has pneumatic control valves. It is not clear if they function, but the valves should be replaced with electronic valves connected to the BMS.

1975 Wing:

General:

The spaces served by AHX-1 used to be plenum return according to the 2007 renovation drawings. At some point a ducted return was implemented but many of the spaces still have the open return to the ceiling plenum above. Within this plenum is uninsulated supply duct. When there was a plenum ceiling this was acceptable as the temperature differentials allowed for this condition. Since the ceiling cavity is no longer a plenum this supply ductwork should be insulated.

Also noted in some of these areas is the presence of PVC roof drain piping which would not have been allowed within a plenum space. As long as the ceiling cavities are not being used as plenums this is no longer an issue. The PVC piping appears to have replaced the original cast iron as a repair.

First Floor:

Many on the cabinet unit heaters at the entrances are original and damaged. It is recommended that the operation be confirmed, and units repaired or replaced as needed. Units are controlled from local return air or wall thermostats.

Room 105 VAV box has a poor inlet connection. Flexible ductwork is utilized throughout the AHX-1 system. Although flex duct is not an issue, the reliability of VAV operation is contingent upon maintaining 3 diameters of straight duct length at the inlet. This should be corrected.

There is excessive supply air duct leakage in the first-floor main corridor and a duct restriction in the AHX-1 supply main outside of classroom 102. The main duct is an acoustically lined 26x14 and there is a reduction in the duct to 24x10 for no apparent reason. This reduction acts as a restriction and should be corrected. Accessible ductwork should be sealed. Unlined ductwork should be insulated.

Health Classroom 105 has the ducted return pushed above the ceiling and ceiling tile set below. this is part of the ventilation system and should be in the classroom ceiling not above it. Please note, this classroom is not air conditioned and this grille should be corrected under the proposed scope.

Classroom 102 has an open louver above the ceiling. The louver feeds a unit ventilator on the floor above. Open portions of louver shall be blanked off with insulated sheet metal panels. This classroom also has no exhaust to remove ventilation air brought in by the unit ventilator. However, a grille exists above the ceiling. This should be addressed under the proposed scope.

Classroom 101 has a grille in the ceiling with plastic laid on top, most likely to prevent down drafts. An exhaust source for ventilation air removal introduced by the unit ventilator could not be found. This should be addressed under the proposed scope.

The ROTC room has several concerns. First, EF-10 needs service as it has no fan belt. The fan is controlled by the BMS. Second, this room has historically experienced cold complaints. The exhaust louver is not completely covered with a sheet metal plenum and is open above the ceiling. There was a piece of insulation stuck to it at one point, which has fallen off. A more permanent insulated enclosure is needed. Third, the radiation located on the plan northeast side is completely blocked by cabinets which is reducing the effectiveness of convection and capacity.

Lastly, there are abandoned exhaust systems which may be retained for future ventilation air and exhaust.

Second Floor:

Offices plan west of room 226 on the exterior are controlled by a common VAV box that also serves interior classroom 226. The control is located in classroom 226. There is no apparent heating for the exterior room and no complaints have been noted but it is not typical to have exterior and interior rooms on the same zone. If there are no temperature complaints, then no further action required at this time.

Room 224 has a portion of the space served by a VAV box off AHX-1 with the remainder only heated and ventilated with a unit ventilator and finned tube radiation. Both systems operate together and a cooling setpoint cannot be maintained. This VAV box used to be in an enclosed work room which was demolished as apparent by the unfinished radiation cover where the old wall was. This area should be addressed under Option 1 or Option 2.

Third Floor:

Classroom 304 has the active ducted exhaust pushed above the ceiling and ceiling tile set below. This is part of the ventilation system and should be in the classroom ceiling, not above it. This condition should be corrected under the proposed scope.

Noted finned tube radiation was installed above the ceiling of classroom 337. Functionality could not be determined, but it was most likely added to curb roof loss. Typically, this is not required with an insulated roof above. This needs to be further evaluated as it is reported by SNE that it is not under BMS control.

Classrooms 324 through 333 have abandoned roof mounted relief penthouses with the old pneumatic dampers closed. These were most likely part of the original relief air strategy with the unit ventilators as there is no exhaust in these rooms. Most of these room still have the relief grille in the ceiling but some have been removed. One item to note is the 2006 drawings indicate fire dampers at all of these grilles as existing to remain. We did not notice these in the field and the ceiling is not clipped or appear to be a fire rated ceiling.

2007 Wing:

Second Floor:

Repair AHU-8 supply air duct insulation that has fallen off the corridor.

There are numerous eggcrate type grilles in the ceiling of the instrument storage which is part of the corridor serving the band and music areas. These grilles were not part of the original design and it is not clear why they were added. They communicate the corridor with the ceiling cavity above. Open grilles to the ceiling cavity are not allowed in a school's egress corridor. If ventilation is the concern, then a ducted solution is necessary.

VIII. BUILDING MANAGEMENT SYSTEM EVALUATION

A central Building Management System (BMS) controls and monitors all major pieces of HVAC equipment in the building. The BMS is a direct digital control (DDC) system which has been modified throughout the building's life as necessary and is connected to the Town wide controls server located at the Town Hall. The BMS is manufactured by Schneider Electric with SNE Building Systems as the sole source vendor. Controllers are vintage but parts and components are still available. Controllers shall be updated as renovated work is performed. The system currently utilizes a LonWorks communication protocol. A BACnet communications protocol is currently being implemented as renovations and equipment replacements are being completed. Within the last few years, air handling unit factory controllers were removed and replaced with Schneider Electric controllers to improve controllability.

The BMS also controls perimeter radiation control valves, unit ventilators, VAV boxes, reheat coil control valves, the VRF system, and exhaust fans EF-1, 7, 8, 9, and 10. Exhaust fans on BMS control were part of the 2007 renovation.

As part of the BMS investigation the following discoveries were made:

1. The local building controls system server is located in the first floor IT room.
2. At the time of survey, AHU-10 was in a fan failure alarm. The BMS was not receiving a fan status which then leads to no control of the heating, cooling, and dampers.
3. Unit AHX-1 and all other AHU's appear to utilize a dry bulb economizer set at 54°F in lieu of an enthalpy economizer. With replacement units an enthalpy-based economizer should be employed.
4. The VRF system serves the AV room and associated offices and operates as a heat pump without simultaneous heating and cooling. The AV room contains radiation which is not under control of the BMS.
5. Three abandoned reheat coils that served the offices and AV room now conditioned by the VRF system are on the BMS. A coil leaving temperature sensor noted approximately 80°F in the duct with the valve fully closed, further confirming no airflow through this abandoned system. These should be valved off. These spaces do not have any outside air for ventilation.
6. Rooftop units are programmed with a linear outdoor temperature reset schedule.
7. ERU-1 is programmed to recirculate air when space humidity rises above 60%. These Science rooms should never recirculate air when in occupied mode.
8. The ERU-1 and ERU-2 economizer outside air temperature values are noted to enable when above 60° and below 45°F. This sequence is backwards, and the economizer programming should be confirmed as this may be a graphical error. Stoppage of wheel in economizer mode should be confirmed.
9. ERU-1 and 2 do not have any upstream or downstream temperature readings. It is recommended these be installed for monitoring of unit conditions.
10. AHU-11 is not in service but is mislabeled as AHU-13 on the graphics.
11. VAV boxes with reheat coils do not have leaving air temperature readings. This is not required but these readings are useful for troubleshooting and operations.
12. Reheat coil 13-2 appears to have a failed leaving air temperature sensor as the hot water valve is open but is reading nearly the same temperature as AHU-13 leaving air.
13. AHU-5 is operating at 100% fan speed. The static pressure setpoint is set to 2" but the unit is only maintaining 1.09" of static. See section on AHU-5 for additional comments.
14. The radiation in the health suite does not have BMS control.
15. The radiation in room 106 does not have BMS control.
16. Cabinet unit heaters, suspended unit heaters, and convectors do not have BMS control. Control operation should be confirmed.
17. AHU-7 is retrofitted with variable frequency drives but the unit operates in a constant volume fashion.
18. The BMS provides a hot water header temperature setpoint to the boilers. The boilers autorotate, cascade, and modulate using packaged controls to satisfy the header temperature setpoint.

IX. ELECTRICAL

The Bethel High School electric service originates from a Eversource overhead utility distribution system on Whittlesey Drive to a pad mounted 1000kVA utility transformer in the east parking lot. The service conductors enter the east side of the building and terminate into a 2500 Amp, 277/480 Volt 3 phase, 4 wire service disconnect CT combination unit, located in Switch Gear D006 on the Lower Level. The service is metered at the service disconnect CT combination unit via Eversource Meter#08103588.

The building main distribution switchboard, located in Switch Gear D006, is a 2500 amp, 277/480 volt 3 phase, 4 wire switchboard. The switchboards contain (9) positions with bolt on circuit breakers energizing an existing distribution switchboard, motor starters, IT loads, receptacle/lighting panelboards and elevator. The existing switchboard, located in Switch Gear D006, is a 1200 amp, 277/480 volt 4 phase, 4 wire switchboard. The existing switchboard contains (13) positions with bolt on circuit breakers energizing several lighting/ receptacle panelboards, PDU, Liebert units, mechanical panelboards and kitchen panelboard. Additionally, the main distribution switchboard contains an in-line standby automatic transfer switch, used to energize the entire facility, that connects to an exterior pad mounted standby generator in the east parking lot. The electrical distribution from the Switch Gear D006 room to other mechanical and electrical rooms throughout the building is in 480-volt three phase. Once the feeders reach the remote electrical and mechanical rooms, a local step-down transformer is provided for 120/208-volt 3 phase, 4 wire distribution.

In preparation for the mechanical air handling unit replacement options, the following electrical revisions shall be provided:

1. Electrical contractor shall meter existing panelboard "PP-7" located on Storage Room D239 on third floor. The metering information shall identify the electrical load for the existing stage lighting panelboard energized by panelboard "PP-7". The metering of "PP-7" shall be performed while the auditorium is being used. Once the load is identified, electrical contractor shall disconnect and remove existing panelboard "PP-7" located in Storage Room D239. Provide one two section 600 amp, 480/277 volt, three phase, 4 wire, 84 pole surface panelboard in existing panelboard "PP-7" location. The new panelboard shall energize air handling unit replacement options and the existing stage lighting panelboard.
2. Electrical contractor shall meter existing "MOTOR CONTROL 4" located in Storage Room D239 on the third floor. The metering information shall identify the electrical load for existing studio lighting panelboard and studio audio panelboard energized by panelboard "MOTOR CONTROL 4". The metering of "MOTOR CONTROL 4" shall be performed while the auditorium is being used. Once the load is identified, electrical contractor shall disconnect and remove existing "MOTOR CONTROL 4" located in Storage Room D239. Provide (1) two section 225 amp, 84 pole, 480/277 volt, three phase, 4 wire surface panelboard in existing "MOTOR CONTROL 4" location. The new panelboard shall energize air handling unit replacement options and the existing auditorium panelboards.
3. Electrical contractor shall disconnect and remove existing "MOTOR CONTROL 3" located in Storage Room D203. Provide (1) 100 amp, 42 pole, 480/277 volt, three phase, 4 wire surface panelboard in existing "MOTOR CONTROL 3" location. The new panelboard shall energize air handling unit replacement options.
4. Electrical contractor shall meter existing panelboard "MP2C" located in Storage Room C203 on the third floor. The metering information shall identify the existing mechanical equipment load for the panelboard. The metering of "MP2C" shall be performed while the building is occupied and mechanical units are being used. Once the load is identified and mechanical options outside of option one priority one are selected, electrical contractor shall provide one (1) two section 1000amp, 480/277 volt, three phase, 4 wire, 84 pole panelboard in existing panelboard "MP2C" location. Additionally, electrical contractor shall provide one (1) 1000A 3 pole circuit breaker in switchboard "MSB-1", located in Switch Gear room D006, re-use existing conduit/wire (with new 2/0 ground wire) previously utilized by existing panelboard "MP2C" and provide 4 # 600kcmil + #2/0G in 4" conduit from Switch Gear room D006 to

Storage Room C203. The new panelboard shall energize air handling unit replacement options and the existing stage lighting panelboard.

Electrical Revisions for Air Handling Units

AHX-1

In support of replacing AHX-1, the electrical contractor shall disconnect and remove associated branch circuit conduit and wire back to existing panelboard. The AHX-1 equipment located on the roof shall be energized by panelboard "PP-7" while the local VRF equipment is energized by panelboard "RP-7" on second floor and panelboard "RP-E" on first floor. The new equipment located within AHX-1 penthouse shall be energized by existing to remain panelboard "PP-2P" located within the penthouse.

AHU-2

In support of replacing AHU-2, the electrical contractor shall disconnect and remove associated branch circuit conduit and wire back to existing panelboard "MP2C". The rooftop equipment for both options shall be energized by new panelboard "MP2C" while the local VRF equipment in option 1 is energized by panelboard RP-8 on third floor and panelboard "RP-7" on first floor.

AHU- 3A and AHU-3B

In support of replacing AHU-3A and AHU-3B, the electrical contractor shall disconnect and extend existing branch circuit conduit and wire from existing AHU-3A and AHU-3B to new AHU-3A and AHU-3B. The rooftop equipment shall be energized by new panelboard "MP2C".

AHU-4

In support of replacing AHU-4, the electrical contractor shall disconnect and remove associated branch circuit conduit and wire back to existing panelboard "MP2C". The new rooftop equipment shall be energized by new panelboard "MP2C".

AHU-5, AHU-7, AHU-8, AHU-10, AHU-11, ERU-1, ERU-2 and Building Exhaust Fans


All equipment identified in this section shall be replaced in kind. The electrical contractor shall disconnect and extend existing branch circuiting energizing equipment to new location.

AHU-6


In support of replacing AHU-6, the electrical contractor shall disconnect and remove associated branch circuit conduit and wire back to existing panelboard "MP2C". The new rooftop equipment shall be energized by new panelboard "MP2C".

X. PRIORITY PHASING

Regardless of design option, the school would like to prioritize replacement of ERU-2 and add cooling to required classrooms under priority one prior to other mechanical work. Construction shall be limited to timeframes outside the normal school schedule. Therefore, a phased approach to demolition and construction must be taken into consideration in order to minimize building downtime and to remain within annual budgetary parameters. Refer to diagrams below for order of space priority



First Floor Priority Cooling



Second Floor Priority Cooling

PRIORITY 3 SPACES
Option 1 and 2 – Add this room to AHU-2 with new VAV box.

PRIORITY 3 SPACES
Option 1 – VRF units served by ACCU3-3. Ventilation via DOAS-2.
Option 2 – Larger AHU-2 with new VAV boxes.

PRIORITY 2 SPACES ALT#2
Option 1 – VRF units served by ACCU2-3. Ventilation via DOAS-3.
Option 2 – VRF units served by ACCU2-3 along with interior classrooms also served by ACCU2-3. Ventilation via DOAS-5.

PRIORITY 1 SPACES
Option 1 – VRF units served by ACCU1-3. Ventilation via DOAS-4.
Option 2 – VRF units served by ACCU1-3. Ventilation via DOAS-5.



Third Floor Priority Cooling

XI. APPENDIX A – HEATING AND COOLING LOADS

The calculations below were performed by Kohler Ronan which serve as a basis for verifying the heating and cooling capacities of the plants as well as sizing of both system options. The calculations are based on the following assumptions:

- Original building plans.
- Inspection of the existing glazing
- Credit for window blinds are included in order to reduce heat gains from the envelope.
- Neutral building construction with average infiltration is included.
- Lighting loads are based on florescent light fixtures typical for school building of this vintage.
- Quantity of people is based on approximate seat counts with diversity assumed.
- Ventilation air is based on ASHRAE recommendations for schools.

System Checksums

By Kohler Ronan

AXH-1 Option 1

VAV w/Baseboard Skin Heating

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: OADB/WB/HR: 88 / 73 / 98				Mo/Hr: 7 / 17 OADB: 86				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat.	Plenum Sens. + Lat.	Net Total	Percent Of Total	Space Sensible	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	SADB	Cooling	Heating	
Btu/h	Btu/h	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)				
0	0	0	0	0	0	0	0	0	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
0	26,073	26,073	5	0	0	0	0	-20,285	7.39	0	0				
9,106	0	9,106	2	10,566	5	0	0	0	0	0	0				
909	0	909	0	775	0	0	0	-3,877	1.41	0	0				
2,349	1,021	3,370	1	2,854	1	0	0	-2,957	1.15	0	0				
-421	0	-421	0	-421	0	0	0	-18,285	6.66	0	0				
-233	0	-233	0	-233	0	0	0	-10,128	3.69	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
299	0	299	0	116	0	0	0	-526	0.19	0	0				
12,009	27,094	39,103	7	13,658	7	-35,773	20.89	-35,773	20.89	-57,358	20.89				
Envelope Loads				Envelope Loads				Envelope Loads							
SkyLite Solar				SkyLite Solar				SkyLite Solar							
SkyLite Cond				SkyLite Cond				SkyLite Cond							
Roof Cond				Roof Cond				Roof Cond							
Glass Solar				Glass Solar				Glass Solar							
Glass/Door Cond				Glass/Door Cond				Glass/Door Cond							
Wall Cond				Wall Cond				Wall Cond							
Partition/Door				Partition/Door				Partition/Door							
Floor				Floor				Floor							
Adjacent Floor				Adjacent Floor				Adjacent Floor							
Infiltration				Infiltration				Infiltration							
Sub Total ==>				Sub Total ==>				Sub Total ==>							
Internal Loads				Internal Loads				Internal Loads							
Lights				Lights				Lights							
People				People				People							
Misc				Misc				Misc							
Sub Total ==>				Sub Total ==>				Sub Total ==>							
260,267	10,608	270,875	51	186,027	91	0	0	0	0	0	0				
3,594	-3,594	0	0	4,092	2	-12,217	0	-12,217	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
0	-5,606	-5,606	-1	0	0	0	0	0	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
0	-23,702	-23,702	0	0	0	0	0	0	0	0	0				
0	0	0	0	0	0	0	0	0	0	0	0				
275,871	4,799	533,426	100.00	203,777	100.00	-47,990	-274,542	-47,990	-274,542	100.00	100.00				
Grand Total ==>				Grand Total ==>				Grand Total ==>							

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter	Capacity	Coil Airflow	Enter	Lvg
ton	MBh	cfm	°F	MBh	cfm	°F	°F
44.5	533.4	10,631	81.0	0.0	0	0.0	0.0
0.0	0.0	0	0.0	-48.0	0	0.0	0.0
0.0	0.0	0	0.0	-294.0	5,734	7.0	53.0
44.5	533.4	10,631	81.0	-61.1	3,226	53.0	70.0
Total				Total			
44.5	533.4	10,631	81.0	0.0	0	0.0	0.0

AREAS			
Gross Total	Glass	ft²	(%)
12,950	0	0	0
1,381	0	0	0
3,800	0	0	0
3,800	125	14	0
877	0	0	0
0	0	0	0
Total			
20,708	125	14	0

ENGINEERING CKS			
% OA	Cooling	Heating	
cfm/ft²	ft³/ton	ft³/ton	No. People
53.3	241.90	100.0	418
0.83	291.32	0.25	418
41.19	41.19	-27.43	418
Grand Total ==>			
53.3	241.90	100.0	418

Project Name: BHS-TRC
 Dataset Name: BHS-TRC

TRACE® 700 v6.3.4 calculated at 09:19 AM on 06/02/2022
 Alternative - 2 - System Checksums Report Page 13 of 17

System Checksums

By Kohler Ronan

Variable Volume Reheat (30% Min Flow Default)

AHU-2 Option 1

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: OADB/WB/HR: 86 / 73 / 103				Mo/Hr: 7 / 18 OADB: 83				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat.	Plenum Sens. + Lat.	Net Total	Percent Of Total	Space Sensible	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total
Btu/h	Btu/h	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)
Envelope Loads															
SkyLite Solar	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SkyLite Cond	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Roof Cond	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Glass Solar	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Glass/Door Cond	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wall Cond	1,652	426	1	2,670	3	-4,322	2.24	-4,322	2.24	-4,322	2.24	-4,322	2.24	-4,322	2.24
Partition/Door	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Floor	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Infiltration	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sub Total ==>	1,652	20,916	9	2,670	3	-4,322	10.95	-4,322	10.95	-4,322	10.95	-4,322	10.95	-4,322	10.95
Internal Loads															
Lights	20,082	5,020	9	20,082	24	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
People	74,850	0	28	44,500	53	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Misc	10,751	0	4	10,751	13	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Sub Total ==>	105,683	5,020	42	75,333	90	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Ceiling Load	4,518	-4,518	0	5,569	7	-8,640	0.00	-8,640	0.00	-8,640	0.00	-8,640	0.00	-8,640	0.00
Ventilation Load	0	0	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Adj Air Trans Heat	0	0	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Dehumid. Ov Sizing	0	0	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Ov/Undr Sizing	0	0	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Exhaust Heat	-11,098	-11,098	-4	-11,098	-4	13,755	-5.64	13,755	-5.64	13,755	-5.64	13,755	-5.64	13,755	-5.64
Sup. Fan Heat	2,647	2,647	1	2,647	1	-36,212	14.84	-36,212	14.84	-36,212	14.84	-36,212	14.84	-36,212	14.84
Ret. Fan Heat	2,647	2,647	1	2,647	1	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Duct Heat PkUp	-9,900	-9,900	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Underflr Sup Ht PkUp	0	0	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Supply Air Leakage	0	0	0	0	0	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Grand Total ==>	111,853	3,067	100.00	83,571	100.00	-12,962	100.00	-12,962	100.00	-243,957	100.00	-243,957	100.00	-243,957	100.00

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter DB/WB/HR	Leave DB/WB/HR	Capacity	Coil Airflow	Ent Lvg
ton	MBh	cfm	°F	°F	MBh	cfm	°F
Main Cfg	22.1	265.4	152.9	83.9	71.2	95.5	53.0
Aux Cfg	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Opt Vent	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Total	22.1	265.4	152.9	83.9	71.2	95.5	53.0

AREAS			
Gross Total	Glass	ft²	(%)
Floor	6,129	0	0
Part	0	0	0
Int Door	0	0	0
ExFlr	0	0	0
Roof	3,629	0	0
Wall	980	0	0
Ext Door	0	0	0
Total	10,738	0	0

ENGINEERING CKS			
% OA	cfm/ft²	cfm/ton	Btu/hr-ft²
76.4	0.75	207.04	43.31
100.0	0.46	277.08	-39.80
Total	185	484.12	3.51

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC

TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 System Checksums Report Page 4 of 17

System Checksums

By Kohler Ronan

AHU-3B

Single Zone

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: OADB/WB/HR: 86 / 73 / 103				Mo/Hr: Sum of OADB: Peaks				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat. Btu/h	Plenum Sens. + Lat. Btu/h	Net Total Btu/h	Percent Of Total (%)	Space Sensible Btu/h	Percent Of Total (%)	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	SADB	Cooling	Heating	
Envelope Loads															
Skylite Solar	0	0	0	0	0	0	0	0.00	0	0	0.00		56.5	73.8	
Skylite Cond	0	0	0	0	0	0	0	0.00	0	0	0.00		70.8	70.0	
Roof Cond	0	0	0	0	0	0	0	0.00	0	0	0.00		78.6	38.5	
Glass Solar	0	0	0	0	0	0	0	0.00	0	0	0.00		0.0	0.0	
Glass/Door Cond	0	0	0	0	0	0	0	0.00	0	0	0.00		0.0	0.0	
Wall Cond	0	0	0	0	0	0	0	0.00	0	0	0.00		0.0	0.0	
Partition/Door	-1,498	-1,498	-1	-1,498	-2	-11,368	-11,368	7.27	-11,368	-11,368	7.27	Diffuser	4,000	4,000	
Floor	-709	-709	-1	-708.54	-1	-5,377	-5,377	3.44	-5,377	-5,377	3.44	Terminal	4,000	4,000	
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	Main Fan	4,000	4,000	
Infiltration	0	0	0	0	0	0	0	0.00	0	0	0.00	Sec Fan	0	0	
Sub Total ==>	-2,207	0	-1	-2,207	-3	-16,746	-16,746	-10.71	-16,746	-16,746	-10.71	AHU Vent	2,000	2,000	
												Infil	0	0	
Internal Loads												MinStop/Rh	0	0	
Lights	9,829	2,457	7	9,829	14	0	0	0.00	0	0	0.00	Return	4,000	4,000	
People	0	0	0	0	0	0	0	0.00	0	0	0.00	Exhaust	2,000	2,000	
Misc	0	0	0	0	0	0	0	0.00	0	0	0.00	Rm Exh	0	0	
Sub Total ==>	9,829	2,457	7	9,829	14	0	0	0.00	0	0	0.00	Auxiliary	0	0	
												Leakage Dwn	0	0	
Ceiling Load	-1,132	1,132	0	-1,132	-2	0	0	0.00	0	0	0.00	Leakage Ups	0	0	
Ventilation Load	0	0	0	0	0	0	-139,645	89.29	0	0	0.00				
Adj Air Trans Heat	0	0	0	0	0	0	0	0.00	0	0	0.00				
Dehumid. Ov Sizing	0	0	0	0	0	0	0	0.00	0	0	0.00				
Ov/Undr Sizing	62,223	2,639	37	62,223	91	0	0	0.00	0	0	0.00				
Exhaust Heat	2,639	2,639	2	2,639	2	0	0	0.00	0	0	0.00				
Sup. Fan Heat	0	0	0	0	0	0	0	0.00	0	0	0.00				
Ret. Fan Heat	0	0	0	0	0	0	0	0.00	0	0	0.00				
Duct Heat PkUp	-8,866	0	0	0	0	0	0	0.00	0	0	0.00				
Underflr Sup Ht PkUp	0	0	0	0	0	0	0	0.00	0	0	0.00				
Supply Air Leakage	0	0	0	0	0	0	0	0.00	0	0	0.00				
Grand Total ==>	68,714	-2,639	100.00	68,714	100.00	-16,746	-156,391	100.00	-16,746	-156,391	100.00				

AIRFLOWS				ENGINEERING CKS			
	Cooling	Heating		Cooling	Heating		
Diffuser	4,000	4,000	% OA	50.0	50.0		
Terminal	4,000	4,000	cfm/ft²	1.33	1.33		
Main Fan	4,000	4,000	cfm/ton	287.90	287.90		
Sec Fan	0	0	ft²/ton	215.93	215.93		
AHU Vent	2,000	2,000	Btu/hr-ft²	55.57	55.57		
Infil	0	0	No. People	35	35		

HEATING COIL SELECTION			
Capacity	Coil Airflow	Ent	Lvg
MBh	cfm	°F	°F
Main Htg	4,000	38.5	73.8
Aux Htg	0	0.0	0.0
Preheat	-70.9	4,000	38.5
Humidif	0.0	0.0	0.0
Opt Vent	0.0	0.0	0.0
Total	-156.4		

AREAS			
Gross Total	Glass		
ft²	ft²	(%)	
Floor	3,000		
Part	779		
Int Door	0		
ExFlr	1,831		
Roof	0		
Wall	0		
Ext Door	0		

COOLING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter DB/WB/HR
ton	MBh	cfm	°F
Main Clg	13.9	4,000	78.6
Aux Clg	0.0	0	0.0
Opt Vent	0.0	0	0.0
Total	13.9	4,000	78.6

COOLING COIL SELECTION			
Leave DB/WB/HR	Enter DB/WB/HR	Leave DB/WB/HR	Enter DB/WB/HR
°F	°F	gr/lb	gr/lb
54.5	53.6	60.1	60.1
0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC

TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 System Checksums Report Page 7 of 17

System Checksums

By Kohler Ronan

AHU-4

Single Zone Variable Air Volume

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Mo/Hr: 7 / 15				Mo/Hr: 7 / 9				Mo/Hr: Heating Design							
Outside Air: OADB/WB/HR: 88 / 73 / 98				OADB: 73				OADB: 7							
Envelope Loads	Space Sens. + Lat.	Plenum Sens. + Lat.	Net Total	Space Sensible	Percent Of Total	Envelope Loads	Space Peak	Coil Peak	Percent Of Total	SADB	Cooling	Heating			
Btu/h	Btu/h	Btu/h	Btu/h	Btu/h	(%)	Btu/h	Space Sens	Tot Sens	(%)		Btu/h	Btu/h			
Skylite Solar	0	0	0	0	0	Skylite Solar	0	0	0.00	Ra Plenum	55.5	85.9			
Skylite Cond	0	0	0	0	0	Skylite Cond	0	0	0.00	Return	74.7	63.1			
Roof Cond	0	68,138	68,138	9	0	Roof Cond	0	-58,707	12.14	Ret/OA	75.3	7.0			
Glass Solar	11,375	0	11,375	1	0	Glass Solar	-16,107	-16,107	3.33	Fn MtrTD	79.5	0.0			
Glass/Door Cond	3,492	0	3,492	1	0	Glass/Door Cond	-28,694	-35,877	7.42	Fn BidTD	0.1	0.0			
Wall Cond	12,895	3,408	16,303	2	0	Wall Cond	-27,919	-27,919	0.00	Fn Frict	0.4	0.0			
Partition/Door	0	0	0	0	0	Partition/Door	0	0	0.00						
Floor	-1,878	0	-1,878	0	0	Floor	-1,853	-1,853	0.38						
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	Adjacent Floor	-74,573	-140,463	29.05						
Infiltration	1,048	0	1,048	6	0	Infiltration									
Sub Total ==>	27,131	71,547	98,678	12	12	Sub Total ==>									
Internal Loads				Internal Loads				AIRFLOWS							
Lights	34,321	8,580	42,901	5	0	Lights	0	0	0.00	Diffuser	18,317	5,495			
People	412,500	0	412,500	52	0	People	0	0	0.00	Terminal	18,317	5,495			
Misc	1,365	0	1,365	0	0	Misc	0	0	0.00	Main Fan	18,317	5,495			
Sub Total ==>	448,186	8,580	456,767	57	0	Sub Total ==>				Sec Fan	0	0			
Ceiling Load	5,702	-5,702	0	0	0	Ceiling Load	-23,084	-23,084	0.00	Nom Vent	6,000	5,495			
Ventilation Load	0	0	0	30	0	Ventilation Load	0	0	0.00	AHU Vent	6,000	5,495			
Adj Air Trans Heat	0	0	0	0	0	Adj Air Trans Heat	0	0	0.00	Infil	26	26			
Dehumid. Ov Sizing	0	0	0	0	0	Dehumid. Ov Sizing	0	0	0.00	MinStop/Rh	5,495	5,495			
OvUndr Sizing	0	0	0	0	0	OvUndr Sizing	0	0	0.00	Return	18,343	5,521			
Exhaust Heat	-15,112	0	-15,112	-2	0	Exhaust Heat	0	0	0.00	Exhaust	6,026	5,521			
Sup. Fan Heat	10,642	10,642	21,284	1	0	Sup. Fan Heat	0	0	0.00	Rm Exh	0	0			
Ret. Fan Heat	-39,977	0	-39,977	0	0	Ret. Fan Heat	0	0	0.00	Auxiliary	0	0			
Duct Heat PkUp	0	0	0	0	0	Duct Heat PkUp	0	0	0.00	Leakage Dwn	0	0			
Underfir Sup Ht PkUp	0	0	0	0	0	Underfir Sup Ht PkUp	0	0	0.00	Leakage Ups	0	0			
Supply Air Leakage	0	0	0	0	0	Supply Air Leakage	0	0	0.00						
Grand Total ==>	481,019	29,978	799,850	100.00	100.00	Grand Total ==>	-97,657	-483,561	100.00						

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter DB/WB/HR	Leave DB/WB/HR	Gross Total	Glass	Total
ton	MBh	cfm	°F	°F		ft²	(%)
Main Clg	66.7	799.9	530.1	17,931	10,475	Floor	10,475
Aux Clg	0.0	0.0	0.0	53.0	0	Part	0
Opt Vent	0.0	0.0	0.0	0.0	0	Int Door	0
Total	66.7	799.9	530.1	17,931	10,475	Roof	10,475
						Wall	6,925
						Ext Door	196

ENGINEERING CKS			
% OA	Cooling	Heating	
cfm/ft²	cfm/ton	°F	
100.0	32.8	100.0	
0.52	1.75	0.52	
	274.80	157.15	
	76.36	1,250	

AREAS			
Capacity	Coil Airflow	Ent	Lvg
MBh	cfm	°F	°F
Main Htg	-483.6	5,495	7.0
Aux Htg	0.0	0	0.0
Preheat	0.0	0	0.0
Humidif	0.0	0	0.0
Opt Vent	0.0	0	0.0
Total	-483.6		

Project Name: BHS.TRC
Dataset Name: BHS.TRC

TRACE® 700 v6.3.4 calculated at 09:19 AM on 06/02/2022
Alternative - 2 - System Checksums Report Page 8 of 17

System Checksums

By Kohler Ronan

Variable Volume Reheat (30% Min Flow Default)

AHU-5

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: Mo/Hr: 7 / 15 OADB/WB/HR: 87 / 73 / 100				Mo/Hr: 9 / 16 OADB: 77				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat. Btu/h	Plenum Sens. + Lat. Btu/h	Net Total Btu/h	Percent Of Total (%)	Space Sensible Btu/h	Percent Of Total (%)	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	SADB	Cooling	Heating	Diffuser	Cooling	Heating	
0	0	0	0	0	0	0	0	0.00	55.0	70.9	7,400	7,400	55.0	70.9	
0	0	0	0	0	0	0	0	0.00	72.5	69.9	7,400	7,400	72.5	69.9	
11,887	0	11,887	4	15,216	11	0	0	0.00	77.4	48.6	7,400	7,400	77.4	48.6	
847	0	847	0	170	0	-3,883	-3,883	0.00	0.0	0.0	0	0	0.0	0.0	
2,353	1,058	3,410	1	2,864	2	-2,606	-3,787	1.41	0.0	0.0	0	0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	0.0	0.0	0	0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	0.0	0.0	0	0	0.0	0.0	
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	0	0.00	0.00	
356	356	356	0	37	0	-523	-523	0.19	2,500	2,500	0	0	2,500	2,500	
15,443	1,058	16,501	6	18,287	13	-7,012	-8,192	3.05	2,500	2,500	7	7	2,500	2,500	
Internal Loads				Internal Loads				AIRFLOWS				AIRFLOWS			
26,539	6,635	33,174	12	26,539	19	0	0	0.00	7,400	7,400	7,400	7,400	7,400	7,400	
22,500	0	22,500	8	12,500	9	0	0	0.00	7,400	7,400	7,400	7,400	7,400	7,400	
15,017	0	15,017	5	15,017	11	0	0	0.00	2,507	2,507	0	0	2,507	2,507	
64,057	6,635	70,692	26	54,057	39	0	0	0.00	0	0	0	0	0	0	
1,345	-1,345	0	0	1,329	1	-281	-281	0.00	0	0	0	0	0	0	
0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
68,811	-1,456	67,355	25	65,750	47	0	0	0.00	324.71	324.71	0	0	324.71	324.71	
Exhaust Heat	0	0	-1	0	0	-86,295	-86,295	32.11	355.42	355.42	0	0	355.42	355.42	
Sup. Fan Heat	0	0	0	0	0	0	0	0.00	33.76	33.76	0	0	33.76	33.76	
Ret. Fan Heat	0	0	0	0	0	0	0	0.00	50	50	0	0	50	50	
Duct Heat PkUp	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
Underflr Sup Ht PkUp	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
Supply Air Leakage	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
Grand Total ==>	149,655	-3,310	100.00	139,423	100.00	-7,293	-288,739	100.00	7,400	54.0	70.9	7,400	54.0	70.9	

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity ton	Sens Cap. MBh	Coil Airflow cfm	Enter DB/WB/HR °F	Leave DB/WB/HR °F	Capacity MBh	Coil Airflow cfm	Ent °F
22.8	273.5	7,400	77.4	54.0	-138.5	7,400	54.0
0.0	0.0	0	0.0	0.0	0.0	0	0.0
0.0	0.0	0	0.0	0.0	-130.2	2,500	7.0
22.8	273.5	0	0.0	0.0	-131.2	7,400	54.0
Total	22.8	7,400	77.4	54.0	0.0	0	0.0

AREAS			
Gross Total	Glass ft²	Opt Vent	Ext Door
8,100	0	16	0
Floor	0	0	0
Part	0	0	0
Int Door	0	0	0
ExFlr	0	0	0
Roof	793	125	0
Wall	0	0	0
Ext Door	0	0	0

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC
 TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 System Checksums Report Page 9 of 17

System Checksums

By Kohler Ronan

AHU-6

Rooftop Multizone

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: OADB/WB/HR: 86 / 73 / 103				Mo/Hr: 7 / 14 OADB: 86				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat. Btu/h	Plenum Sens. + Lat. Btu/h	Net Total Btu/h	Percent Of Total (%)	Space Sensible Btu/h	Percent Of Total (%)	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	SADB	Cooling	Heating	Fn MtrTD	Fn BlqTD	Fn Frict	
0	0	0	0	0	0	0	0	0.00	56.0	56.0	86.2	0.0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	72.6	72.6	69.9	0.0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	86.4	86.4	69.9	0.0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	86.4	86.4	7.0	0.0	0.0	0.0	
784	497	1,281	1	1,139	2	-1,191	-1,956	0.62							
-2,470	0	-2,470	-1	-2,470	-4	-18,745	-18,745	5.93							
-1,380	0	-1,380	-1	-1,379.55	-2	-10,470	-10,470	3.31							
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00							
12,691	497	13,188	6	5,454	9	-23,224	-23,224	7.35							
9,626	497	10,123	5	2,743	4	-53,630	-54,395	17.22							
Envelope Loads				Internal Loads				AIRFLOWS				ENGINEERING CKS			
SkyLite Solar				Lights	7	11,681	0	0.00							
SkyLite Cond				People	12	18,000	0	0.00							
Roof Cond				Misc	2	4,096	0	0.00							
Glass Solar				Sub Total ==>	21	33,776	0	0.00							
Glass/Door Cond															
Wall Cond															
Partition/Door															
Floor															
Adjacent Floor															
Infiltration															
Sub Total ==>															
11,681	2,920	14,601	7	11,681	18	746	-157	0.00							
26,400	0	26,400	12	18,000	28	0	0	0.00							
4,096	0	4,096	2	4,096	6	0	0	0.00							
42,176	2,920	45,096	21	33,776	53	0	0	0.00							
703	-703	0	0	746	1	746	-157	0.00							
0	0	0	0	0	0	0	0	0.00							
0	0	0	0	0	0	0	0	0.00							
26,573	-2,714	23,859	12	26,573	42	-10,740	-10,740	3.40							
0	0	0	0	0	0	0	607	-0.19							
0	0	0	0	0	0	0	0	0.00							
0	0	0	0	0	0	0	0	0.00							
0	0	0	0	0	0	0	0	0.00							
0	0	0	0	0	0	0	0	0.00							
0	0	0	0	0	0	0	0	0.00							
79,078	0	79,078	100.00	63,838	100.00	-64,528	-315,889	100.00							
COOLING COIL SELECTION				COOLING COIL SELECTION				HEATING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity ton	Sens Cap. MBh	Coil Airflow cfm	Enter °F	Leave DB/WB/HR °F	gr/lb	DBWB/HR °F	gr/lb	Gross Total ft²	Main Htg	Aux Htg	Preheat	Capacity MBh	Coil Airflow cfm	Ent °F	
18.0	216.4	120.7	86.4	73.2	102.8	56.0	55.5	3,565	-120.4	0.0	-195.5	-120.4	3,600	56.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	86.2	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
18.0	216.4	120.7	86.4	73.2	102.8	56.0	55.5	3,565	0.0	0.0	0.0	0.0	0.0	86.2	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1,285	0.0	0.0	0.0	0.0	0.0	0.0	
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3,565	0.						

System Checksums

By Kohler Ronan

AHU-7

Single Zone

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: OADB/WB/HR: 86 / 73 / 103				Mo/Hr: Sum of OADB: Peaks				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat. Btu/h	Plenum Sens. + Lat. Btu/h	Net Total Btu/h	Percent Of Total (%)	Space Sensible Btu/h	Percent Of Total (%)	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	Envelope Loads	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	SADB	Cooling	Heating
0	0	0	0	0	0	0	0	0	SkyLite Solar	0	0	0	59.0	72.1	72.1
0	0	0	0	0	0	0	0	0	SkyLite Cond	0	0	0	Ra Plenum	72.8	67.7
0	23,960	23,960	7	0	0	0	0	0	Roof Cond	0	0	0	Return	72.8	67.7
6,102	6,102	6,102	2	9,500	7	0	0	0	Glass Solar	-3,666	0	0	Ret/OA	79.9	35.9
757	757	757	0	673	1	0	0	0	Glass/Door Cond	-2,426	0	0	Fn MtrTD	0.0	0.0
1,448	1,271	2,718	1	1,699	1	0	0	0	Wall Cond	-11,307	0	0	Fn BltTD	0.0	0.0
0	0	0	0	0	0	0	0	0	Partition/Door	-11,307	0	0	Fn Frict	0.0	0.0
-1,490	-1,490	-1,490	-1	-1,489.83	-1	0	0	0	Floor	0.00	0.00	0.00			
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	Adjacent Floor	-352	0.10	0.10			
210	210	210	0	73	0	0	0	0	Infiltration	-17,750	11.98	11.98			
7,026	25,230	32,256	9	10,454	8	0	0	0	Sub Total ==>	-43,223	11.98	11.98			
									Internal Loads						
12,614	3,154	15,768	4	12,614	10	0	0	0	Lights	0	0	0			
16,000	0	16,000	5	9,800	8	0	0	0	People	0	0	0			
0	0	0	0	0	0	0	0	0	Misc	0	0	0			
28,614	3,154	31,768	9	22,414	17	0	0	0	Sub Total ==>	0	0	0			
917	-917	0	0	1,467	1	-2,775	0	0	Ceiling Load	-2,775	0	0			
0	0	0	0	0	0	0	0	0	Ventilation Load	0	0	0			
0	0	196,384	56	0	0	0	0	0	Adj Air Trans Heat	-329,562	91.32	91.32			
0	0	0	0	0	0	0	0	0	Ov/Undr Sizing	0	0	0			
95,334	-3,938	91,396	27	95,334	74	0	0	0	Exhaust Heat	11,910	-3.30	-3.30			
0	0	-3,938	-1	0	0	0	0	0	OA Preheat Diff.	0	0	0			
0	0	0	0	0	0	0	0	0	RA Preheat Diff.	0	0	0			
0	0	0	0	0	0	0	0	0	Additional Reheat	0	0	0			
-19,949	-19,949	0	0	0	0	0	0	0	Underflr Sup Ht PkUp	0	0	0			
0	0	0	0	0	0	0	0	0	Supply Air Leakage	0	0	0			
131,892	3,579	135,471	100.00	129,670	100.00	-20,524	-360,875	100.00	Grand Total ==>						

AIRFLOWS			
	Cooling	Heating	
Diffuser	9,000	9,000	
Terminal	9,000	9,000	
Main Fan	9,000	9,000	
Sec Fan	0	0	
Nom Vent	4,720	4,720	
AHU Vent	4,720	4,720	
Infil	5	5	
MinStop/Rh	0	0	
Return	9,005	9,005	
Exhaust	4,725	4,725	
Rm Exh	0	0	
Auxiliary	0	0	
Leakage Dwn	0	0	
Leakage Ups	0	0	

ENGINEERING CKS			
	Cooling	Heating	
% OA	52.4	52.4	
cfm/ft²	2.34	2.34	
cfm/ton	306.99		
ft³/ton	131.32		
Btu/hr-ft²	91.38	-93.73	
No. People	40		

HEATING COIL SELECTION			
	Capacity	Coil Airflow	Ent Lvg °F
Main Htg	-360.9	9,000	35.9
Aux Htg	0.0	0	0.0
Preheat	-210.7	9,000	35.9
Humidif	0.0	0	0.0
Opt Vent	0.0	0	0.0
Total	-360.9		

AREAS			
	Gross Total	Glass ft²	(%)
Floor	3,850		
Part	0		
Int Door	0		
ExFlr	3,850		
Roof	3,850		
Wall	895	84	9
Ext Door	84	0	0

COOLING COIL SELECTION			
	Total Capacity ton	Sens Cap. MBh	Coil Airflow cfm
Main Clg	29.3	351.8	9,000
Aux Clg	0.0	0.0	0
Opt Vent	0.0	0.0	0
Total	29.3	351.8	

COOLING COIL SELECTION			
	Enter °F	DBWB/HR °F	Leave DBWB/HR °F
Main Clg	79.9	68.2	57.0
Aux Clg	0.0	0.0	0.0
Opt Vent	0.0	0.0	0.0
Total	79.9	68.2	57.0

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC

TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 System Checksums Report Page 11 of 17

System Checksums

By Kohler Ronan

Variable Volume Reheat (30% Min Flow Default)

AHU-8

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: Mo/Hr: 7 / 17 OADB/WB/HR: 85 / 72 / 100				Mo/Hr: 7 / 17 OADB: 85				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat.	Plenum Sens. + Lat.	Net Total	Percent Of Total	Space Sensible	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Sens	Percent Of Total	Space Peak	Percent Of Total	Space Sens	Percent Of Total
Btu/h	Btu/h	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)
Envelope Loads															
SkyLite Solar	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SkyLite Cond	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Roof Cond	0	31,257	11	0	0	0	0	0	0	-25,563	10.36	0	0	0	0
Glass Solar	42,977	0	15	42,977	37	0	0	0	0	0	0	0	0	0	0
Glass/Door Cond	2,941	0	1	2,941	3	-15,857	6.43	-15,857	6.43	-13,529	5.48	-15,857	6.43	-13,529	5.48
Wall Cond	7,714	3,383	4	7,714	7	-9,545	2.06	-9,545	2.06	-5,074	2.06	-9,545	2.06	-5,074	2.06
Partition/Door	-669	0	0	-669	-1	-7,797	3.16	-7,797	3.16	-7,797	3.16	-7,797	3.16	-7,797	3.16
Floor	-1,027	0	0	-1,027	-1	0	0	0	0	0	0	0	0	0	0
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Infiltration	1,253	0	0	1,253	1	-2,136	0.87	-2,136	0.87	-2,136	0.87	-2,136	0.87	-2,136	0.87
Sub Total ==>	53,189	34,639	31	52,376	45	-40,409	28.35	-40,409	28.35	-69,956	28.35	-69,956	28.35	-69,956	28.35
Internal Loads															
Lights	23,509	5,877	10	23,509	20	0	0	0	0	0	0	0	0	0	0
People	53,580	0	19	30,850	26	0	0	0	0	0	0	0	0	0	0
Misc	3,754	0	1	3,754	3	0	0	0	0	0	0	0	0	0	0
Sub Total ==>	80,843	5,877	30	58,113	50	0	0	0	0	0	0	0	0	0	0
Ceiling Load	6,595	-6,595	0	6,595	6	-14,653	0	-14,653	0	-14,653	0	-14,653	0	-14,653	0
Ventilation Load	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Adj Air Trans Heat	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Dehumid. Ov Sizing	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Ov/Undr Sizing	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Exhaust Heat	-9,744	0	-3	-9,744	-3	14,148	-5.73	14,148	-5.73	-53,531	21.70	-53,531	21.70	-53,531	21.70
Sup. Fan Heat	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Ret. Fan Heat	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Duct Heat PkUp	-13,775	0	0	-13,775	0	0	0	0	0	0	0	0	0	0	0
Underflr Sup Ht PkUp	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Supply Air Leakage	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Grand Total ==>	140,627	10,403	100.00	117,085	100.00	-55,062	100.00	-55,062	100.00	-246,715	100.00	-246,715	100.00	-246,715	100.00

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter DB/WB/HR	Leave DB/WB/HR	Capacity	Coil Airflow	Ent Lvg
ton	MBh	cfm	°F	°F	MBh	cfm	°F
Main Clg	24.0	287.7	184.5	62.14	79.8	67.2	80.7
Aux Clg	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Opt Vent	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Total	24.0	287.7	184.5	62.14	79.8	67.2	80.7

AREAS			
Gross Total	Glass	ft²	(%)
Floor	7,175		
Part	348		
Int Door	0		
ExFlr	2,655		
Roof	4,520		
Wall	2,976	510	17
Ext Door	0		

ENGINEERING CKS			
% OA	Cooling	Heating	
cfm/ft²	cfm/ton	ft²/ton	No. People
48.3	0.87	94.9	
259.20	299.27	0.29	
40.10		-34.39	
		126	

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC
 TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 - System Checksums Report Page 12 of 17

System Checksums

By Kohler Ronan

Variable Volume Reheat (30% Min Flow Default)

AHU-10

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: Mo/Hr: 7 / 14 OADB/WB/HR: 86 / 73 / 103				Mo/Hr: 7 / 9 OADB: 73				Mo/Hr: Heating Design OADB: 7							
Space Sens. + Lat. Btu/h	Plenum Sens. + Lat. Btu/h	Net Total Btu/h	Percent Of Total (%)	Space Sensible Btu/h	Percent Of Total (%)	Space Peak Btu/h	Coil Peak Tot Sens Btu/h	Percent Of Total (%)	SADB	Cooling	Heating	Fn MtrTD	Fn BlqTD	Fn Frict	
0	0	0	0	0	0	0	0	0.00	55.0	88.4	0.0	0.0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	76.1	61.2	0.0	0.0	0.0	0.0	
0	47,047	47,047	16	0	0	0	-47,565	20.72	76.1	61.2	0.0	0.0	0.0	0.0	
20,950	0	20,950	7	56,985	36	0	0	0.00	80.1	7.0	0.0	0.0	0.0	0.0	
4,270	0	4,270	1	-268	0	0	-20,476	8.92	0.0	0.0	0.0	0.0	0.0	0.0	
2,001	960	2,961	1	2,937	2	0	-5,930	2.58	0.0	0.0	0.0	0.0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	0.0	0.0	0.0	0.0	0.0	0.0	
0	0	0	0	0	0	0	0	0.00	0.0	0.0	0.0	0.0	0.0	0.0	
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
1,801	1,801	1,801	1	39	0	0	-2,758	1.20	0.0	0.0	0.0	0.0	0.0	0.0	
29,023	48,006	77,029	25	59,693	37	0	-76,730	33.42	0.0	0.0	0.0	0.0	0.0	0.0	
Internal Loads				Internal Loads				AIRFLOWS				AIRFLOWS			
Lights	7,186	35,931	12	28,745	18	0	0	0.00	8,450	2,535	8,450	2,535	8,450	2,535	
People	0	67,500	22	37,500	24	0	0	0.00	8,450	2,535	8,450	2,535	8,450	2,535	
Misc	0	17,065	6	17,065	11	0	0	0.00	0	0	0	0	0	0	
Sub Total ==>	113,310	120,496	40	83,310	52	0	0	0.00	2,553	2,535	2,553	2,535	2,553	2,535	
Ceiling Load	11,259	0	0	-1,150	-1	0	-24,413	0.00	0	0	0	0	0	0	
Ventilation Load	0	116,418	39	0	0	0	-177,000	77.10	0	0	0	0	0	0	
Adj Air Trans Heat	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
Dehumid. Ov Sizing	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	
Ov/Undr Sizing	0	0	0	17,354	11	0	0	0.00	30.2	100.0	0.96	0.29	0.00	0.00	
Exhaust Heat	-11,637	-11,637	-4	0	0	0	25,059	-10.92	0.96	0.29	335.42	348.24	34.46	-26.17	
Sup. Fan Heat	0	0	0	0	0	0	-905	0.39	0.00	0.00	0.00	0.00	0.00	0.00	
Ret. Fan Heat	0	0	0	0	0	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
Duct Heat PkUp	-14,402	0	0	0	0	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
Underflr Sup Ht PkUp	0	0	0	0	0	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
Supply Air Leakage	0	0	0	0	0	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
Grand Total ==>	153,591	17,895	100.00	159,206	100.00	0	-51,671	100.00	-229,576	100.00	0	0	0	0	

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity ton	Sens Cap. MBh	Coil Airflow cfm	Enter DB/WB/HR °F	Leave DB/WB/HR °F	Gross Total	Glass ft²	Opt Vent
25.2	302.3	6,498	80.1	53.0	8,773	0	0
0.0	0.0	0	0.0	0.0	0	0	0
0.0	0.0	0	0.0	0.0	0	0	0
Total	25.2	302.3	80.1	53.0	8,773	0	0

ENGINEERING CKS			
% OA	cfm/ft²	cfm/ton	Btu/hr-ft²
30.2	0.96	335.42	34.46
100.0	0.29	348.24	150

HEATING COIL SELECTION			
Main Htg	Aux Htg	Preheat	Reheat
-99.4	0.0	-130.1	-47.8
2,535	0.0	2,535	53.0
53.0	0.0	53.0	70.0
Total	0	0	0

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC

TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 System Checksums Report Page 1 of 17

System Checksums

By Kohler Ronan

Variable Volume Reheat (30% Min Flow Default)

AHU-14 Option 1

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: Outside Air: OADB/WB/HR: 86 / 73 / 103				Mo/Hr: 7 / 9 OADB: 73				Mo/Hr: Heating Design OADB: 7				SADB Heating			
Space Sens. + Lat.	Plenum Sens. + Lat.	Net Total	Percent Of Total	Space Sensible	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total	Space Peak	Percent Of Total
Btu/h	Btu/h	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)	Btu/h	(%)
Envelope Loads															
Skylite Solar	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Skylite Cond	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Roof Cond	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Glass Solar	26,654	0	6	80,421	39	0	0	-27,302	0	0	0	-27,302	0	0	0
Glass/Door Cond	5,693	0	1	-358	0	0	0	-27,302	0	0	0	-27,302	0	0	0
Wall Cond	3,990	1,652	1	6,288	3	0	0	-8,115	0	0	0	-11,366	0	0	0
Partition/Door	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Floor	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Infiltration	2,321	0	0	52	0	-3,677	0	-3,677	0	0	0	-3,677	0	0	0
Sub Total ==>	38,659	1,652	8	86,403	42	-39,095	42	-39,095	42	-42,345	6.38	-42,345	6.38	-42,345	6.38
Internal Loads															
Lights	39,318	9,829	10	39,318	19	0	0	0	0	0	0	0	0	0	0
People	62,700	0	13	42,750	21	0	0	0	0	0	0	0	0	0	0
Misc	13,652	0	3	13,652	7	0	0	0	0	0	0	0	0	0	0
Sub Total ==>	115,670	9,829	26	95,720	46	0	0	0	0	0	0	0	0	0	0
Ceiling Load	-3,064	3,084	0	-2,865	-1	-1,644	-1	-1,644	-1	-1,644	-1	-1,644	-1	-1,644	-1
Ventilation Load	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Adj Air Trans Heat	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Dehumid. Ov Sizing	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Ov/Undr Sizing	0	0	0	27,993	14	1,607	14	1,607	0	0	0	1,607	-0.24	0	0
Exhaust Heat	0	6,240	1	0	0	-392,557	0	-392,557	0	0	0	-392,557	59.15	0	0
Sup. Fan Heat	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Ret. Fan Heat	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Duct Heat PkUp	0	-15,272	0	0	0	0	0	0	0	0	0	0	0	0	0
Underflr Sup Ht PkUp	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Supply Air Leakage	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Grand Total ==>	151,245	5,533	100.00	207,251	100.00	-40,739	100.00	-40,739	100.00	-663,710	100.00	-663,710	100.00	-663,710	100.00

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter DB/WB/HR	Capacity	Coil Airflow	Ent	Lvg
ton	MBh	cfm	°F	MBh	cfm	°F	°F
Main Cfg	39.6	475.7	260.5	-102.9	3,300	53.0	81.1
Aux Cfg	0.0	0.0	86.4	0.0	0.0	0.0	0.0
Opt Vent	0.0	0.0	0.0	-560.8	11,000	7.0	53.0
Total	39.6	475.7	0.0	-62.2	3,300	53.0	70.0
				Humidif	0.0	0.0	0.0
				Opt Vent	0.0	0.0	0.0
				Total	-663.7		

AREAS			
Gross Total	Glass	ft²	(%)
Floor	12,000		
Part	0		
Int Door	0		
ExFlr	0		
Roof	0		
Wall	2,886	878	30
Ext Door	0		

Project Name: BHS 2.TRC
 Dataset Name: BHS 2.TRC
 TRACE® 700 v6.3.4 calculated at 05:58 PM on 06/06/2022
 Alternative - 2 System Checksums Report Page 3 of 17

Room Checksums

By Kohler Ronan

Third Floor East Rm - VRF

COOLING COIL PEAK		CLG SPACE PEAK		HEATING COIL PEAK		TEMPERATURES		
Peaked at Time: Mo/Hr: 7 / 16		Mo/Hr: 7 / 9		Mo/Hr: Heating Design		Cooling Heating		
Outside Air: OADBWB/HR: 87 / 73 / 97		OADB: 73		OADB: 7		SADB	50.9	77.6
						Ra Plenum	87.2	58.7
						Return	72.0	70.0
						Ret/OA	72.0	70.0
						Fn MtrTD	0.0	0.0
						Fn BltdTD	0.0	0.0
						Fn Frict	0.0	0.0
Envelope Loads		Space Percent		Space Peak		AIRFLOWS		
SkyLite Solar	0	0	0	0	0	Diffuser	826	826
SkyLite Cond	0	0	0	0	0	Terminal	826	826
Roof Cond	0	0	0	0	0	Main Fan	826	826
Glass Solar	1,888	22	0	-2,631	-4,758	Sec Fan	0	0
Glass/Door Cond	591	7	38	-672	-2,631	MinStop/Rh	5	83
Wall Cond	308	2	0	0	-942	Return	831	831
Partition/Door	0	2	3	0	0	Rm Exh	5	5
Floor	0	0	0	0	0	Auxiliary	0	0
Adjacent Floor	0.00	0	0.00	0.00	0.00	Leakage Dwn	0	0
Infiltration	225	7	0	-357	-357	Leakage Ups	0	0
Sub Total ==>	3,012	7,911	41	-3,659	-8,687	No. People	26.0	28.3/1000 ft²
Internal Loads		Internal Loads		Internal Loads		ENGINEERING CKS		
Lights	3,014	16	0	0	0	% OA	0.0	0.0
People	11,700	33	0	0	0	cfm/ft²	0.90	0.90
Misc	1,024	5	0	0	0	cfm/ton	392.80	
Sub Total ==>	15,738	54	0	0	0	ft²/ton	437.45	
Ceiling Load	4,434	5	955	-3,289	0	Btu/hr-ft²	27.43	-7.55
Ventilation Load	0	0	0	0	0	No. People	26.0	28.3/1000 ft²
Adj Air Trans Heat	0	0	0	0	0	HEATING COIL SELECTION		
Dehumid. Ov Sizing	0	0	0	0	0	Capacity	MBh	
Exhaust Heat	0	0	0	0	0	Coil Airflow	cfm	
Sup. Fan Heat	0	0	0	0	0	Enter	°F	
Ret. Fan Heat	0	0	0	0	0	Leave	°F	
Duct Heat PkUp	0	0	0	0	0	Enter DBWB/HR	gr/lb	
Supply Air Leakage	0	0	0	0	0	Enter	°F	
Grand Total ==>	23,185	2,052	25,237	100.00	100.00	Sens Cap.	MBh	
						Sens. + Lat.	Btu/h	
						Plenum	Btu/h	
						Sens. + Lat. Sens. + Lat	Btu/h	
						Net Total	Btu/h	
						Total Of Total	(%)	
						Space Sensible	Btu/h	
						Percent Of Total	(%)	
						Envelope Loads	Btu/h	
						SkyLite Solar	0	0.00
						SkyLite Cond	0	0.00
						Roof Cond	0	0.00
						Glass Solar	7,415	68.48
						Glass/Door Cond	-2,631	0.00
						Wall Cond	-942	37.86
						Partition/Door	0	13.56
						Floor	0	0.00
						Adjacent Floor	0.00	0.00
						Infiltration	-357	5.14
						Sub Total ==>	-8,687	125.03
						Internal Loads	0	0.00
						Lights	0	0.00
						People	0	0.00
						Misc	0	0.00
						Sub Total ==>	0	0.00
						Ceiling Load	0	0.00
						Ventilation Load	0	0.00
						Adj Air Trans Heat	0	0.00
						Dehumid. Ov Sizing	0	0.00
						Exhaust Heat	0	0.00
						Sup. Fan Heat	0	0.00
						Ret. Fan Heat	0	0.00
						Duct Heat PkUp	0	0.00
						Supply Air Leakage	0	0.00
						Grand Total ==>	-6,948	100.00

Project Name: BHS.TRC
 Dataset Name: BHS.TRC

TRACE® 700 v6.3.4 calculated at 03:53 PM on 06/02/2022
 Alternative - 2 - System Checksums Report Page 25 of 29

Room Checksums

By Kohler Ronan

Third Floor West Rm - VRF

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES			
Peaked at Time: 7 / 17				Mo/Hr: 7 / 17				Mo/Hr: Heating Design							
Outside Air: OADBWB/HR: 86 / 72 / 95				OADB: 86				OADB: 7							
Space Sens. + Lat.	Plenum	Net Total	Space Sensible	Space Percent	Envelope Loads	Space Peak	Coil Peak	SADB	Ra Plenum	Return	Ret/OA	Fn BlrTD	Fn BlrTD	Fn Frict	
Btu/h	Btu/h	Btu/h	Btu/h	(%)		Btu/h	Btu/h								
0	0	0	0	0	Skyllite Solar	0	0	51.6	75.8	87.3	72.0	70.0	0.0	0.0	
0	0	0	0	0	Skyllite Cond	0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
0	5,549	5,549	0	0	Roof Cond	0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
4,297	0	4,297	0	20	Glass Solar	4,297	-4,655	72.0	58.7	72.0	70.0	0.0	0.0	0.0	
263	0	263	15	21	Glass/Door Cond	263	-1,315	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
1,379	373	1,752	6	7	Wall Cond	1,379	-1,538	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
0	0	0	0	0	Partition/Door	0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
0	0	0	0	0	Floor	0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
0	0	0	0	0	Adjacent Floor	0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
105	0	105	39	0	Infiltration	-178	-178	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
6,044	5,922	11,966	5,979	29	Sub Total ==>	-2,694	-7,686	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
Internal Loads				Internal Loads				AIRFLOWS							
2,949	737	3,686	2,949	14	Lights	0	0	913	913	913	913	913	913	913	
11,700	0	11,700	6,500	31	People	0	0	0	0	0	0	0	0	0	
1,024	0	1,024	1,024	5	Misc	0	0	0	0	0	0	0	0	0	
15,673	737	16,410	10,473	50	Sub Total ==>	0	0	0	0	0	0	0	0	0	
4,365	-4,365	0	4,365	21	Ceiling Load	-3,218	0	0	0	0	0	0	0	0	
0	0	0	0	0	Ventilation Load	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	Adj Air Trans Heat	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	Ov/Undr Sizing	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	Exhaust Heat	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	OA Preheat Diff.	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	RA Preheat Diff.	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	Additional Reheat	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	System Plenum Heat	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	Underfir Sup Ht PkUp	0	0	0	0	0	0	0	0	0	
0	0	0	0	0	Supply Air Leakage	0	0	0	0	0	0	0	0	0	
26,082	2,294	28,376	20,817	100.00	Grand Total ==>	-5,911	-5,911	26.0	28.9	1000	ft²	ft²	ft²	ft²	

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter DBWB/HR	Leave DBWB/HR	Gross Total	Glass	Ent Lvg
ton	MBh	cfm	°F	°F		ft² (%)	°F
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1	900	0	75.8
0.0	0.0	0	0.0	0.0	0	0	0.0
0.0	0.0	0	0.0	0.0	0	0	0.0
2.4	23.1	913	72.0	60.1			

Room Checksums

By Kohler Ronan

Third Floor SW Corner Rm - VRF

COOLING COIL PEAK				CLG SPACE PEAK				HEATING COIL PEAK				TEMPERATURES						
Peaked at Time:		Mo/Hr: 7 / 17		Mo/Hr: 7 / 17		Mo/Hr: Heating Design		Mo/Hr: Heating Design		Mo/Hr: Heating Design		Mo/Hr: Heating Design		Mo/Hr: Heating Design		Mo/Hr: Heating Design		
Outside Air:		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		OADBWB/HR: 86 / 72 / 95		
Envelope Loads	Space Sens. + Lat.	Plenum Sens. + Lat.	Net Total	Space Sensible	Space Percent Of Total	Envelope Loads	Space Peak	Space Percent Of Total	Envelope Loads	Space Sensible	Space Percent Of Total	Envelope Loads	Space Peak	Space Percent Of Total	Envelope Loads	Space Sensible	Space Percent Of Total	
Btu/h	Btu/h	Btu/h	Btu/h	Btu/h	(%)	Btu/h	Btu/h	(%)	Btu/h	Btu/h	(%)	Btu/h	Btu/h	(%)	Btu/h	Btu/h	(%)	
Skylite Solar	0	0	0	0	0	Skylite Solar	0	0	0	0	0	Skylite Solar	0	0	0	0	0	0
Skylite Cond	0	0	0	0	0	Skylite Cond	0	0	0	0	0	Skylite Cond	0	0	0	0	0	0
Roof Cond	0	4,198	4,198	0	13	Roof Cond	0	0	0	0	0	Roof Cond	0	0	0	0	0	0
Glass Solar	9,577	0	9,577	9,577	36	Glass Solar	9,577	36	9,577	36	36	Glass Solar	9,577	36	9,577	36	36	36
Glass/Door Cond	526	0	526	526	2	Glass/Door Cond	526	2	526	2	2	Glass/Door Cond	526	2	526	2	2	2
Wall Cond	1,608	363	1,970	1,608	6	Wall Cond	1,608	6	1,608	6	6	Wall Cond	1,608	6	1,608	6	6	6
Partition/Door	0	0	0	0	0	Partition/Door	0	0	0	0	0	Partition/Door	0	0	0	0	0	0
Floor	0	0	0	0	0	Floor	0	0	0	0	0	Floor	0	0	0	0	0	0
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	Adjacent Floor	0.00	0.00	0.00	0.00	0.00	Adjacent Floor	0.00	0.00	0.00	0.00	0.00	0.00
Infiltration	209	0	209	79	0	Infiltration	209	0	79	0	0	Infiltration	209	0	79	0	0	0
Sub Total ==>	11,919	4,561	16,480	11,789	44	Sub Total ==>	11,789	44	11,789	44	44	Sub Total ==>	11,789	44	11,789	44	44	44
Internal Loads				Internal Loads				Internal Loads				Internal Loads						
Lights	2,457	614	3,072	2,457	9	Lights	2,457	9	2,457	9	9	Lights	2,457	9	2,457	9	9	9
People	11,700	0	11,700	6,500	24	People	6,500	24	6,500	24	24	People	6,500	24	6,500	24	24	24
Misc	1,024	0	1,024	1,024	4	Misc	1,024	4	1,024	4	4	Misc	1,024	4	1,024	4	4	4
Sub Total ==>	15,181	614	15,796	9,981	37	Sub Total ==>	9,981	37	9,981	37	37	Sub Total ==>	9,981	37	9,981	37	37	37
Ceiling Load	4,943	-4,943	0	4,943	19	Ceiling Load	4,943	19	4,943	19	19	Ceiling Load	4,943	19	4,943	19	19	19
Ventilation Load	0	0	0	0	0	Ventilation Load	0	0	0	0	0	Ventilation Load	0	0	0	0	0	0
Adj Air Trans Heat	0	0	0	0	0	Adj Air Trans Heat	0	0	0	0	0	Adj Air Trans Heat	0	0	0	0	0	0
Dehumid. Ov Sizing	0	0	0	0	0	Dehumid. Ov Sizing	0	0	0	0	0	Dehumid. Ov Sizing	0	0	0	0	0	0
Ov/Undr Sizing	0	0	0	0	0	Ov/Undr Sizing	0	0	0	0	0	Ov/Undr Sizing	0	0	0	0	0	0
Exhaust Heat	0	0	0	0	0	Exhaust Heat	0	0	0	0	0	Exhaust Heat	0	0	0	0	0	0
Sup. Fan Heat	0	0	0	0	0	Sup. Fan Heat	0	0	0	0	0	Sup. Fan Heat	0	0	0	0	0	0
Ret. Fan Heat	0	0	0	0	0	Ret. Fan Heat	0	0	0	0	0	Ret. Fan Heat	0	0	0	0	0	0
Duct Heat PkUp	0	0	0	0	0	Duct Heat PkUp	0	0	0	0	0	Duct Heat PkUp	0	0	0	0	0	0
Underfir Sup Ht PkUp	0	0	0	0	0	Underfir Sup Ht PkUp	0	0	0	0	0	Underfir Sup Ht PkUp	0	0	0	0	0	0
Supply Air Leakage	0	0	0	0	0	Supply Air Leakage	0	0	0	0	0	Supply Air Leakage	0	0	0	0	0	0
Grand Total ==>	32,043	232	32,276	26,713	100.00	Grand Total ==>	26,713	100.00	26,713	100.00	100.00	Grand Total ==>	-8,581	-8,581	-8,581	100.00	100.00	100.00

COOLING COIL SELECTION				HEATING COIL SELECTION			
Total Capacity	Sens Cap.	Coil Airflow	Enter	Total Capacity	Sens Cap.	Coil Airflow	Enter
ton	MBh	cfm	°F	ton	MBh	cfm	°F
Main Cig	2.7	32.3	27.0	1,268	-8.6	1,268	70.0
Aux Cig	0.0	0.0	0.0	0	0.0	0	0.0
Opt Vent	0.0	0.0	0.0	0	0.0	0	0.0
Total	2.7	32.3	27.0	1,268	-8.6	1,268	70.0

AREAS			
Gross Total	Glass	Total	Ext
ft²	ft²	ft²	ft²
Floor	750	750	0
Part	0	0	0
Int Door	0	0	0
ExFlr	0	0	0
Roof	750	750	0
Wall	522	522	16
Ext Door	0	0	0
Total	2,022	2,022	16

ENGINEERING CKS			
% OA	cfm/ft²	ft²/ton	Btu/hr-ft²
0.0	1.69	471.40	-11.44
0.0	0.0	278.85	
0.0	0.0	43.03	
No. People	26.0	34.7/1000 ft²	-11.44

Project Name: BHS.TRC
 Dataset Name: BHS.TRC
 TRACE® 700 v6.3.4 calculated at 03:53 PM on 06/02/2022
 Alternative - 2 System Checksums Report Page 28 of 29

Room Checksums

By Kohler Ronan

Third Floor Internal Rm - VRF

COOLING COIL PEAK		CLG SPACE PEAK		HEATING COIL PEAK		TEMPERATURES	
Peaked at Time: Outside Air: Mo/Hr: 7 / 17 OADBWB/HR: 86 / 72 / 95		Mo/Hr: 7 / 17 OADB: 86		Mo/Hr: Heating Design OADB: 7			
Space Sens. + Lat. Btu/h	Plenum Sens. + Lat. Btu/h	Space Sensible Btu/h	Space Percent Of Total (%)	Space Peak Sens Btu/h	Coil Peak Tot Sens Btu/h	Space Percent Of Total (%)	
Envelope Loads							
SkyLite Solar	0	0	0	0	0	0	0.00
SkyLite Cond	0	0	0	0	0	0	0.00
Roof Cond	0	5,116	24	0	-4,242	93.79	650
Glass Solar	0	0	0	0	0	0	650
Glass/Door Cond	0	0	0	0	0	0	650
Wall Cond	0	0	0	0	0	0	0
Partition/Door	0	0	0	0	0	0	0
Floor	0	0	0	0	0	0	0
Adjacent Floor	0.00	0.00	0.00	0.00	0.00	0.00	0
Infiltration	0	0	0	0	0	0	0
Sub Total ==>	0	5,116	24	0	-4,242	93.79	0
Internal Loads							
Lights	2,949	737	17	0	0	0	65
People	11,700	0	54	0	0	0	650
Misc	1,024	0	5	0	0	0	0
Sub Total ==>	15,673	737	76	10,473	0	0	0
Ceiling Load	5,931	-5,931	36	5,931	-4,523	0	0
Ventilation Load	0	0	0	0	0	0	0
Adj Air Trans Heat	0	0	0	0	0	0	0
Dehumid. Ov Sizing	0	0	0	0	0	0	0
Ov/Undr Sizing	0	0	0	0	0	0	0
Exhaust Heat	0	0	0	0	0	0	0
Sup. Fan Heat	0	0	0	0	0	0	0
Ret. Fan Heat	0	0	0	0	0	0	0
Duct Heat PkUp	0	0	0	0	0	0	0
Underfir Sup Ht PkUp	0	0	0	0	0	0	0
Supply Air Leakage	0	0	0	0	0	0	0
Grand Total ==>	21,604	-78	100.00	16,404	-4,523	100.00	0

COOLING COIL SELECTION		HEATING COIL SELECTION	
Total Capacity ton	Sens Cap. MBh	Coil Airflow cfm	Capacity MBh
Main Clg	1.8	21.5	-4.5
Aux Clg	0.0	0.0	0.0
Opt Vent	0.0	0.0	0.0
Total	1.8	21.5	-4.5

AREAS		HEATING COIL SELECTION	
Gross Total	Glass ft² (%)	Coil Airflow cfm	Capacity MBh
Floor	900	650	-4.5
Part	0	0	0.0
Int Door	0	0	0.0
ExFlr	0	0	0.0
Roof	900	0	0.0
Wall	0	0	0.0
Ext Door	0	0	0.0
Total	1800	650	-4.5

ENGINEERING CKS	
% OA	Heating
0.0	0.0
0.72	0.72
362.35	
501.73	
23.92	
No. People	26.0
	28.9/1000 ft²

Project Name: BHS.TRC
 Dataset Name: BHS.TRC
 TRACE® 700 v6.3.4 calculated at 03:53 PM on 06/02/2022
 Alternative - 2 - System Checksums Report Page 26 of 29

XII. APPENDIX B – MECHANICAL UPGRADES ESTIMATES

		Option 1				
FLR/Roof	Equip Tags	Quantities	UM	Price	Totals	Notes
Option 1 / Priority 1						
Roof	ERU-2	1 EA		\$ 288,000	\$ 288,000	Remove and Replace DOAS-4 Firs 1,2,3. See Equip Matrix for details
Roof	DOAS-4	1 EA		\$ 385,656	\$ 385,656	
Floor 1(Alt 1)	ACCU-1-1 14T	1 EA		\$ 30,131	\$ 30,131	New roof top equipment
	VRF-A	2 EA		\$ 3,000	\$ 6,000	
	VRF-B					
	VRF-C	6 EA		\$ 2,500	\$ 15,000	
	VRF Refrig Piping	9 EA		\$ 4,500	\$ 40,500	
	Electrical	9 EA		\$ 2,500	\$ 22,500	New Circuits/Panels
	ACCU-1-1 Electrical	1 EA		\$ 17,000	\$ 17,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 21,000	\$ 21,000	
	Floor 1 Subtotal				\$ 195,131	
Floor 2	ACCU-1-2 18T	1 EA		\$ 45,162	\$ 45,162	New roof top equipment
	VRF-A	6 EA		\$ 3,000	\$ 18,000	
	VRF-B	0				
	VRF-C	2 EA		\$ 2,500	\$ 5,000	
	VRF Refrig Piping	9 EA		\$ 4,500	\$ 40,500	
	Electrical	9 EA		\$ 2,500	\$ 22,500	New Circuits/Panels
	ACCU-1-2 Electrical	1 EA		\$ 17,000	\$ 17,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 21,000	\$ 21,000	
	Floor 2 Subtotal				\$ 212,162	
Floor 3	ACCU-1-3 14T	1 EA		\$ 30,131	\$ 30,131	New roof top equipment
	VRF-A	5 EA		\$ 3,000	\$ 15,000	
	VRF-B	0				
	VRF-C	2 EA		\$ 2,500	\$ 5,000	
	VRF Refrig Piping	8 EA		\$ 4,500	\$ 36,000	
	Electrical	8 EA		\$ 2,500	\$ 20,000	New Circuits/Panels
	ACCU-1-3 Electrical	1 EA		\$ 17,000	\$ 17,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 19,000	\$ 19,000	
	Floor 3 Subtotal				\$ 185,131	
Option 1 / Priority 1 Subtotal					\$ 1,266,079	
	Soft Costs					
	Design	10%		\$ 126,608	\$ 126,608	
	Contingency	10%		\$ 126,608	\$ 126,608	
	Escalation	7.5%		\$ 94,956	\$ 94,956	
Option 1 / Priority 1 Total					\$ 1,614,251	
Priority 2						
Roof	DOAS-3	1 EA		\$ 385,656	\$ 385,656	New roof top equipment. See Equip Matrix for details
Floor 3	ACCU-2-3 14T	1 EA		\$ 30,131	\$ 30,131	
	VRF-A	5 EA		\$ 3,000	\$ 15,000	
	VRF-B	0				
	VRF-C	0				
	VRF Refrig Piping	6 EA		\$ 4,500	\$ 27,000	
	Electrical	6 EA		\$ 2,500	\$ 15,000	New Circuits/Panels
	ACCU-2-3 Electrical	1 EA		\$ 20,000	\$ 20,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 15,000	\$ 15,000	
Option 1 / Priority 2 Subtotal					\$ 547,787	
	Soft Costs					
	Design	10%		\$ 54,779	\$ 54,779	
	Contingency	10%		\$ 54,779	\$ 54,779	
	Escalation	7.5%		\$ 41,084	\$ 41,084	
Option 1 / Priority 2 Total					\$ 698,428	
Priority 3						
Roof	DOAS-2	1 EA		\$ 259,500	\$ 259,500	New roof top equipment. See Equip Matrix for details
Floor 3	ACCU-3-3 14T	1 EA		\$ 30,131	\$ 30,131	
	VRF-A	5 EA		\$ 3,000	\$ 15,000	
	VRF Refrig Piping	6 EA		\$ 4,500	\$ 27,000	
	VAV @ Rm C205	2 EA		\$ 4,500	\$ 9,000	
	Electrical	14 EA		\$ 2,500	\$ 35,000	New Circuits/Panels
	ACCU-3-3 Electrical	1 EA		\$ 20,000	\$ 20,000	
	Duct Work	1 allow		\$ 10,000	\$ 10,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 31,000	\$ 31,000	
Option 1 / Priority 3 Subtotal					\$ 476,631	
	Soft Costs					
	Design	10%		\$ 47,663	\$ 47,663	
	Contingency	10%		\$ 47,663	\$ 47,663	
	Escalation	7.5%		\$ 35,747	\$ 35,747	
Option 1 / Priority 3 Total					\$ 607,704	
Priority 4						
Roof	AHU-14	1 EA		\$ 666,750	\$ 666,750	New roof top equipment. See Equip Matrix for details
Floor 2	VAV Boxes	10 EA		\$ 4,000	\$ 40,000	
	Electrical	11 EA		\$ 2,500	\$ 27,500	
	Duct Work					
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1				Included in AHU-14 Cost
	Temp Controls	1 allow		\$ 18,000	\$ 18,000	
Option 1 / Priority 4 Subtotal					\$ 772,250	
	Soft Costs					
	Design	10%		\$ 77,225	\$ 77,225	
	Contingency	10%		\$ 47,663	\$ 47,663	
	Escalation	7.5%		\$ 35,747	\$ 35,747	
Option 1 / Priority 4 Total					\$ 932,885	
OPTION 1 TOTAL					\$ 3,853,268	

		Option 2				
FLR/Roof	Equip Tags	Quantities	UM	Price	Totals	Notes
Option 2 / Priority 1						
Roof	DOAS-5	1 EA		\$ 761,969	\$ 761,969	Remove and Replace Mod Dummage
Floor 1	ACCU-1-1 20T	1 EA		\$ 30,131	\$ 30,131	New roof top equipment
	VRF-A	3 EA		\$ 3,000	\$ 9,000	
	VRF-B	2 EA		\$ 2,750	\$ 5,500	
	VRF-C	6 EA		\$ 2,500	\$ 15,000	
	VRF Refrig Piping	12 EA		\$ 4,500	\$ 54,000	
	Electrical	12 EA		\$ 2,500	\$ 30,000	New Circuits/Panels
	ACCU-1-1 Electrical	1 EA		\$ 20,000	\$ 20,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 27,000	\$ 27,000	
	Floor 1 Subtotal				\$ 230,631	
Floor 2	ACCU-1-2 28T	1 EA		\$ 57,162	\$ 57,162	New roof top equipment
	VRF-A	7 EA		\$ 3,000	\$ 21,000	
	VRF-B	5 EA		\$ 2,750	\$ 13,750	
	VRF-C	4 EA		\$ 2,500	\$ 10,000	
	VRF Refrig Piping	17 EA		\$ 4,500	\$ 76,500	
	Electrical	17 EA		\$ 2,500	\$ 42,500	New Circuits/Panels
	ACCU-1-2 Electrical	1 EA		\$ 20,000	\$ 20,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 37,000	\$ 37,000	
	Floor 2 Subtotal				\$ 317,912	
Floor 3 Alt 2	ACCU-1-3 14T	1 EA		\$ 30,131	\$ 30,131	New roof top equipment
	VRF-A	5 EA		\$ 3,000	\$ 15,000	
	VRF-B	0				
	VRF-C	2 EA		\$ 2,500	\$ 5,000	
	VRF Refrig Piping	8 EA		\$ 4,500	\$ 36,000	
	Electrical	8 EA		\$ 2,500	\$ 20,000	New Circuits/Panels
	ACCU-1-3 Electrical	1 EA		\$ 20,000	\$ 20,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 19,000	\$ 19,000	
	Floor 3 Subtotal				\$ 185,131	
Option 2 / Priority 1 Subtotal					\$ 2,229,316	
	Soft Costs					
	Design	10%		\$ 222,931	\$ 222,931	
	Contingency	10%		\$ 222,931	\$ 222,931	
	Escalation	7.5%		\$ 167,199	\$ 167,199	
Option 2 / Priority 1 Total					\$ 2,842,376	
Priority 2						
Floor 3	ACCU-2-3 24T	1 EA		\$ 52,428	\$ 52,428	New roof top equipment
	VRF-A	5 EA		\$ 3,000	\$ 15,000	
	VRF-B	5 EA		\$ 2,750	\$ 13,750	
	VRF-C	0				
	VRF Refrig Piping	11 EA		\$ 4,500	\$ 49,500	
	Electrical	11 EA		\$ 2,500	\$ 27,500	New Circuits/Panels
	ACCU-2-3 Electrical	1 EA		\$ 20,000	\$ 20,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 25,000	\$ 25,000	
Option 2 / Priority 2 Subtotal					\$ 243,178	
	Soft Costs					
	Design	10%		\$ 24,318	\$ 24,318	
	Contingency	10%		\$ 24,318	\$ 24,318	
	Escalation	7.5%		\$ 18,238	\$ 18,238	
Option 2 / Priority 2 Total					\$ 310,052	
Priority 3						
Floor 3	AHU-2	1 EA		\$ 242,469	\$ 242,469	Remove and Replace
	VAVs	6 EA		\$ 2,000	\$ 12,000	
	VAV Piping	7 EA		\$ 4,500	\$ 31,500	
	Duct					Included in AHU-2 Cost
	Electrical	14 EA		\$ 2,500	\$ 35,000	
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 30,000	\$ 30,000	
	Temp Controls	1 allow		\$ 19,000	\$ 19,000	
Option 2 / Priority 3 Subtotal					\$ 389,969	
	Soft Costs					
	Design	10%		\$ 38,997	\$ 38,997	
	Contingency	10%		\$ 38,997	\$ 38,997	
	Escalation	7.5%		\$ 29,248	\$ 29,248	
Option 2 / Priority 3 Total					\$ 497,210	
Priority 4						
Roof	DOAS-1	1 EA		\$ 346,188	\$ 346,188	New roof top equipment. See Equip Matrix for details
Floor 2	ACCU-4-2 24T	1 EA		\$ 52,428	\$ 52,428	
	VRF-A	2 EA		\$ 4,000	\$ 8,000	
	VRF-B	4 EA		\$ 2,750	\$ 11,000	
	VRF-C	6 EA		\$ 2,500	\$ 15,000	
	Electrical	13 EA		\$ 2,500	\$ 32,500	
	ACCU-4-2 Electrical	1 EA		\$ 20,000	\$ 20,000	New Circuits/Panels
	Roof LVL Work	1 allow		\$ 20,000	\$ 20,000	
	Interiors Work	1 allow		\$ 20,000	\$ 20,000	
	Temp Controls	1 allow		\$ 10,000	\$ 10,000	
Option 2 / Priority 4 Subtotal					\$ 636,116	
	Soft Costs					
	Design	10%		\$ 53,612	\$ 53,612	
	Contingency	10%		\$ 53,612	\$ 53,612	
	Escalation	7.5%		\$ 40,134	\$ 40,134	
Option 2 / Priority 4 Total					\$ 682,272	
OPTION 2 TOTAL					\$ 4,331,911	

Discretionary Equipment Replacement

Equip Tag	Tons	CFM	Quant	UM	Equip Price	Status	Remove	Set Unit	Dunnage/S truct	Duct Mods/New Duct	Elec Reconnect/ New	Temprature Controls	Piping Reconnect/ New	Curb Mods/New	Roofing	Interiors	SubTotal	Contractors OH&P	Installed Price	Notes
AHU-3A Interior + CU on Roof	14	4,000	1	EA	\$34,208	R&R	\$2,500	\$1,600	\$5,000	\$2,500	\$1,500	\$20,000	\$1,500	N/A	N/A	N/A	\$68,808	\$17,202	\$86,010	Remove and Replace. Roof level work only. Includes mark-ups
AHU-3B Interior + CU on Roof	14	4,000	1	EA	\$34,208	R&R	\$2,500	\$1,600	\$5,000	\$2,500	\$1,500	\$20,000	\$1,500	N/A	N/A	N/A	\$68,808	\$17,202	\$86,010	Remove and Replace. Roof level work only. Includes mark-ups
AHU-4	70	18,000	1	EA	\$200,849	R&R	\$7,500	\$14,900	N/A	\$5,000	\$100,000	\$45,000	\$2,500	\$5,500	N/A	N/A	\$381,249	\$95,312	\$476,561	Remove and Replace. Panel Upgrade.
AHU-5	25	7,400	1	EA	\$118,206	New	N/A	\$14,900	\$15,000	\$148,000	\$15,000	\$18,500	\$12,500	\$15,000	\$7,500	\$44,400	\$409,006	\$102,252	\$511,258	New Location. Dunnage, roof mods and connections
AHU-6	15	3,600	1	EA	\$83,582	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$15,000	\$2,500	\$5,500	N/A	N/A	\$137,482	\$34,371	\$171,853	Remove and Replace, separate installs
AHU-7	30	9,000	1	EA	\$128,992	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$22,500	\$2,500	\$5,500	N/A	N/A	\$190,392	\$47,598	\$237,990	Remove and Replace, separate installs
AHU-8	25	11,400	1	EA	\$120,277	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$28,500	\$2,500	\$5,500	N/A	N/A	\$187,677	\$46,919	\$234,596	Remove and Replace, separate installs
AHU-10	25	8,450	1	EA	\$118,206	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$21,125	\$2,500	\$5,500	N/A	N/A	\$178,231	\$44,558	\$222,789	Remove and Replace
AHU-11	5	2,000	1	EA	\$16,674	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$12,000	\$2,500	\$5,500	N/A	N/A	\$67,574	\$16,894	\$84,468	Remove and Replace
ERU-1	30	7,800	1	EA	\$172,000	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$19,500	\$2,500	\$5,500	N/A	N/A	\$230,400	\$57,600	\$288,000	Remove and Replace
AHX-1	50	10,800	1	EA	\$107,487	R&R	\$7,500	\$14,900	N/A	\$5,000	\$20,000	\$27,000	\$2,500	\$5,500	N/A	N/A	\$189,887	\$47,472	\$237,359	Included in Option 1, Priority 1
	271	83,450	11		\$1,134,689		\$65,000	\$137,300	\$25,000	\$193,000	\$159,000	\$249,125	\$35,500	\$59,000	\$7,500	\$44,400	\$2,109,514	\$527,379	\$2,636,893	

Equipment Included in Options 1&2

Equip Tag	Tons	CFM	Quant	UM	Equip Price	Status	Remove	Set Unit	Dunnage/S truct	Duct Mods/New Duct	Elec Reconnect/ New	Temprature Controls	Piping Reconnect/ New	Curb Mods/New	Roofing	Interiors	SubTotal	Contractors OH&P	Installed Price	Notes
AHU-2 Opt 1	30	9,300	1	EA	\$128,029	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$23,250	\$2,500	\$5,500	N/A	N/A	\$190,179	\$47,545	\$237,724	Included in Option 2, Priority 3
AHU-2 Opt 2	50	12,000	1	EA	\$161,646	R&R	\$7,500	\$14,900	N/A	\$5,000	\$20,000	\$30,000	\$2,500	\$5,500	N/A	N/A	\$247,046	\$61,762	\$308,808	Included in Option 2, Priority 3
AHU-14 Opt 1	40	11,000	1	EA	\$140,000	New	N/A	\$14,900	\$15,000	\$220,000	\$15,000	\$27,500	\$12,500	\$15,000	\$7,500	\$66,000	\$533,400	\$133,350	\$666,750	Included in Option 1, Priority 4
DOAS-1 Opt 2	16	4,500	1	EA	\$68,800	New	N/A	\$14,900	\$15,000	\$90,000	\$15,000	\$11,250	\$12,500	\$15,000	\$7,500	\$27,000	\$276,950	\$69,238	\$346,188	New Location. Dunnage, roof mods and connections
DOAS-2 Opt 1	12	2,600	1	EA	\$50,100	New	N/A	\$14,900	\$15,000	\$52,000	\$15,000	\$10,000	\$12,500	\$15,000	\$7,500	\$15,600	\$207,600	\$51,900	\$259,500	New Location. Dunnage, roof mods and connections
DOAS-3 Opt 1	28	6,250	1	EA	\$66,750	New	N/A	\$14,900	\$15,000	\$93,750	\$30,000	\$15,625	\$12,500	\$15,000	\$7,500	\$37,500	\$308,525	\$77,131	\$385,656	New Location. Dunnage, roof mods and connections
DOAS-4 Opt 1	28	6,250	1	EA	\$66,750	New	N/A	\$14,900	\$15,000	\$93,750	\$30,000	\$15,625	\$12,500	\$15,000	\$7,500	\$37,500	\$308,525	\$77,131	\$385,656	New Location. Dunnage, roof mods and connections
DOAS-5 Opt 2	50	15,350	1	EA	\$215,000	New	N/A	\$14,900	\$15,000	\$184,200	\$15,000	\$38,375	\$12,500	\$15,000	\$7,500	\$92,100	\$609,575	\$152,394	\$761,969	Included in Option 2, Priority 1
ERU-2	30	7,800	1	EA	\$172,000	R&R	\$7,500	\$14,900	N/A	\$5,000	\$3,500	\$19,500	\$2,500	\$5,500	N/A	N/A	\$230,400	\$57,600	\$288,000	Remove and Replace

XIII. APPENDIX D – DRAWINGS

Below is a compilation of drawings created by the design team to further describe and illustrate the required work. Both 11x17 and full size drawings are included for convenience. The drawings consist of:

Mechanical:

- M1.1: First Floor Plan Option 1 - Mechanical
- M1.2: First Floor Plan Option 2 - Mechanical
- M2.1: Second Floor Plan Option 1 - Mechanical
- M2.2: Second Floor Plan Option 2 - Mechanical
- M3.1: Third Floor Plan Option 1 - Mechanical
- M3.2: Third Floor Plan Option 2 - Mechanical
- M4.1: Roof Plan Option 1 - Mechanical
- M4.2: Roof Plan Option 2 – Mechanical

Structural:

- S1.1: Schematic Roof Dunnage Part Plan For Proposed RTU's (Option 1, Area A & B)
- S1.2: Schematic Roof Dunnage Part Plan For Proposed RTU's (Option 1, Area C)
- S1.3: Schematic Roof Dunnage Part Plan For Proposed RTU's (Option 1, Area D)
- S2.1: Schematic Roof Dunnage Part Plan For Proposed RTU's (Option 2, Area A & B)
- S2.2: Schematic Roof Dunnage Part Plan For Proposed RTU's (Option 2, Area C)
- S2.3: Schematic Roof Dunnage Part Plan For Proposed RTU's (Option 2, Area D)

Glossary of Acronyms and Terms Related to HVAC

Acronym / Term	Meaning
ACCU	Air Cooled Condensing Unit
AHU	Air Handling Unit. Some have air conditioning, some do not.
AHX	Active Heat Extractor, which is a type of AHU with air conditioning.
BMS	Building Management Systems (BMS) control and monitor the large energy consuming systems within a building, such as HVAC, lighting, fire and security systems.
BTU	The British thermal unit is a unit of heat; it is defined as the amount of heat required to raise the temperature of one pound of water by one degree Fahrenheit.
CFM	Cubic Feet Per Minute, which is a measurement of airflow volume
DOAS	Dedicated Outdoor Air System, which is used for ventilation.
Dunnage	Roof dunnage provides structurally sound support and security for large and expensive items that are placed on rooftops. These structural supports are often made of steel and tied into cross beams or roof trusses. The equipment is then placed on top of the supports.
DX	Direct Expansion Cooling
ERU	Energy Recovery Unit
HVAC	Heating, Ventilation, and Air Conditioning
MAU	Makeup Air Unit, which is used to replace large volumes of air that is vented out.
MBH	Thousand BTU's per hour
RTU	Roof Top Unit
Taco	short for Taco Comfort Solutions, which is a brand of equipment
VFD	A variable frequency drive (VFD) is a type of motor controller that drives an electric motor by varying the frequency and voltage of its power supply.
VRF	Variable Refrigerant Flow (VRF) HVAC systems consist of outdoor units connected to multiple indoor units via refrigerant piping to provide cooling and heating to individual zones.

Bethel High School



Bethel High School Mechanical Upgrades Study
Board of Education Presentation
June 28, 2022 Meeting

Kohler Ronan LLC

Engineering consultancy firm focused on delivering Mechanical, Electrical, Plumbing, Fire Protection, IT/AV/S and Commissioning solutions.

70 plus staff between CT and NYC offices.

KOHLER RONAN



Outline of Meeting Discussion

- Review of scope of services
- Discussions
- Existing conditions
- Findings
- Building options
- Building priorities

Scope of Services

Phase I – Feasibility and Master Plan (Complete)

- Meetings to further understand the project
- Conducted multiple field visits for site assessment
- Interview facilities staff
- Review of existing documentation
- Analyze 2 years of utility bills for capacity
- Analyze existing conditions to prepare for options
- Conduct load calculations for equipment sizing
- Prepared multiple options for review
- Present report to the committee
- Prioritized options based on available funding

Scope of Services


Phase II – Design and Construction Administration (Pending)

- Prepare design development and construction documents of selected priorities
- Update initial cost estimates
- Assist in bidding
- Perform basic construction administration
- Commission installed systems (CxA TBD)
- Prepare final punch list

Discussions

What We Heard (Goals)

- Address areas without Air Conditioning
 - Classroom A/C
 - Athletic Facility A/C
- Gas service concerns
- Failed energy recovery
- Full building generator
- Dehumidification concerns
- Boilers recently replaced
- AHX-1 service issues
- Classroom units noisy
- Long term replacement
- Inadequate toilet exhaust
- Maintenance concerns
- Controls issues



Existing Conditions


- Original 1970 building with additions in 1975 and 2007. Overall building has 3 floors
- Partially air conditioned by packaged rooftop units, rooftop split units, indoor air handler (AHU) with remote condensing units and miscellaneous mini-splits.
- Central boiler serves radiation, terminal units, unit ventilators, some rooftop units and indoor AHUs.
- Ventilation is provided by rooftop units, AHU's and unit ventilators.
- Over 40 misc. exhaust fans in various conditions
- Major addition/renovation in 2007 changed building classification from 2B to 2A. Designation made renovation challenging.
- Building DDC controls system
- Zoning for building consists of.....






KOHLER RONAN

First Floor Zoning



Second Floor Zoning



Third Floor Zoning

Findings

- AHX-1
 - Installed in 1975.
 - Refurbished in 2007 and miscellaneous times after.
 - Located in rooftop penthouse.
 - Serves mostly interior classrooms of the 1975 wing.
 - Old unit but still has service life.
 - Original plenum return converted to ducted but many open grilles exist to ceiling cavity.
 - Supply and return ductwork in old plenum spaces not insulated.
- Issues:
 - Lack of capacity due to adjacent non-air-conditioned spaces.
 - Duct leakage.
 - Slightly undersized to achieve desired 72°F space temperatures.
- Recommendations:
 - Replace unit when budget allows.
 - Address misc. issues identified such as insulation and duct sealing.
 - Option 2 replacement recommended when Variable Refrigerant Flow (VRF) is installed in adjacent classrooms.



Findings

- Classroom Air Conditioning
 - Units have either unit ventilators only, radiation only or combination of both.
 - Exhaust fans with ducts to classrooms are inconsistent. Some grilles capped above ceilings or not connected to duct.
 - Abandoned rooftop relief penthouses.
 - Unit ventilators are noisy. Do not comply with ANSI classroom sound standards.
- Issues:
 - Noise.
 - No air conditioning.
 - Lack of ventilation in some non-air-conditioned and air-conditioned spaces (mini-splits).
 - Tight conditions.
- Recommendations:
 - Option 1/Priority 1 and 2 with VRF and Dedicated Outside Air System (DOAS)



Findings

- Athletic Area Air Conditioning
 - Heating and ventilating units only.
- Issues:
 - No air conditioning
- Recommendations:
 - Add air conditions
 - To be discussed in priorities
- Long Term Replacement of Units
 - Update or replace as funds allow
 - To be discussed in the priority section



Findings (Miscellaneous)

Highlights:

- Lots of abandoned ducts from the 2007 renovation that were supposed to be removed.
- Direct opens to the exterior. I.e., open louvers.
- Mold on ceiling tiles in kitchen area.
- No means of ventilation in corridors throughout.
- Natural gas issues to rooftop units.
- Plugged outside air louver to kitchen make up unit.
- Abandoned equipment on roof and above ceilings.
- Dead systems with controlled heating coils.
- Misc. exhaust ductwork capped above ceiling with plastic
- Some pneumatic control valves on radiation (nurses' area).
- Exhaust grilles located above ceilings, not in space served.
- Some plenum areas with PVC drain piping.
- Inoperable exhaust fans.
- AHU-8 open grilles in egress corridor.
- Windows too small for natural ventilation without operable exhaust.
- Fire proofing throughout




Findings (Controls)

Highlights:

- Schneider Electric controls.
- Handles most of the major equipment
- Control conversions.
- Many variations in unit operations and sequences.
- Does not control:
 - Original exhaust fans (majority of fans)
 - Cabinet and unit heaters
 - Some radiation

Recommendations:

- Add all equipment not currently controlled by DDC system as they are replaced.
- Retro-commission all the controls
- Review and update all control sequences
- Update controllers as work proceeds




Building Options (AHX-1)

Option 1: Leave AHX-1 and provide DOAS and VRF to unconditioned classrooms



Option 1 - VRF Classrooms - First Floor (AHX-1 for Reference Only)



Option 1 VRF Classrooms – Second Floor (AHX-1 for Reference Only)



Option 1 VRF Classrooms – Third Floor (AHX-1 for Reference Only)

Building Options (AHX-1)


Option 2: Replace AHX-1 with DOAS unit to serve entire 1975 wing. Costly and not recommended as this is very disruptive.



Option 2 All VRF Classrooms – First Floor



Option 2 All VRF Classrooms – Second Floor



Option 2 All VRF Classrooms – Third Floor

Building Options (AHU-2)

Option 1: Replace AHU-2 in kind. Add DOAS and VRF to remaining spaces

Option 2: Increase size of AHU-2 and add new VAV zones



Option 1- AHU-2 & VRF (ACCU3-3) – Third Floor



Option 2 – Larger AHU-2 – Third Floor

Building Options (AHU-5)

Replace and AHU-5 in new location.
Upgrade unit for proper airflow.




AHU-5 Proposed Correction – Second Floor

Building Options (AHU-6)

Replace AHU-6 in kind with additional cooling section.

Add VAV boxes to spaces.


Requires electric upgrades to support (AHU-4)



AHU-6 Proposed Correction – First Floor

Building Options (AHU-10)


Replace AHU-10 in kind with VAV Rooftop Unit.
Add VAV boxes to spaces.



AHU-10 Proposed Correction – Second Floor

Building Options (Art, Culinary and Science)


New 100% Outside Air Rooftop VAV Unit
(Not recommended)



Art, Culinary and Science Option 1 – Second Floor


Building Options (Art, Culinary and Science)

DOAS with VRF
(Recommended option)




Art, Culinary and Science Option 1 – Second Floor

Building Priorities




KOHLER RONAN

First Floor



Second Floor



Third Floor

Building Priorities

- Budget
 - Adding A/C to all classrooms and replacing ERU-2 ranges from \$3.8M to \$4.7M
 - Complete system upgrades range from \$6.44M to \$7.34M
- Constraints
 - \$1.4 million initial grant.
 - \$1.1 million available inclusive of design fees due to other obligations.
- Anticipated budget for Option 1/Priority 1 spaces
 - \$1,365,460
 - Includes ERU-2, DOAS-4 and VRF for 14 classrooms on 2nd and 3rd floors in 1970 and 1975 building.
- Budget with Base and Alternate 1
 - \$1,614,251
 - Includes 5 classrooms on first floor of 1975 wing.
- Budget with Base and Alternate 2
 - \$2,063,888
 - Includes DOAS-3 and VRF for 5 classrooms on 3rd floor of 1970/1975 wing.
 - Adds ventilation air to classrooms served by mini splits.
- Total budget of base and alternates
 - \$2,312,679
- Alternate Funding Options?

Unit	Serves	Type	Manufacture	Flow CFM	Year	AGE	Condition	Expected Service Life Years	Expected Remaining Life Years	Estimated Reaplcement Cost	Priority	Comments
MAU-1	Kitchen	Draw thru	McQuay	5,000	2007	15	Good	25-35	10-15	NA	LOW	Unit location difficult to service but serviceable
AHU-2	CR's	Packaged RTU	McQuay	9,300	2007	15	Fair	15-25	5-10	\$238,000-\$309,000	6	Two options to consider: Direct replacement or expanded service
AHU-3A	Boys Locker	Draw thru	McQuay	4,000	2007	15	Good	25-35	10-15	\$86,010	LOW	No work required unless AC wanted
AHU-3B	Girls Locker	Draw thru	McQuay	4,000	2007	15	Good	25-35	10-15	\$86,010	LOW	No work required unless AC wanted
AHU-4	Gym	Packaged RTU	McQuay	18,000	2007	15	Good	15-25	5-10	\$476,561	2	Cost includes electrical upgrades to support other unit replacements such as AHU-6 and 2. Do this unit first.
AHU-5	Admin	Packaged RTU	McQuay	7,400	2007	15	Poor	15-25	3-5	\$511,258	4	Unit has fan capacity and distribution issues. Ducts block access doors
AHU-6	Wrestling	Packaged RTU	McQuay	3,600	2007	15	Good	15-25	5-10	\$171,853	3	No AC but unit in good condition
AHU-7	Lobby	Packaged RTU	McQuay	9,000	2007	15	Fair	15-25	5-10	\$237,990	7	Service unit, clean coils and drain pan, condensation of gas burner. Noise concerns to corridor below
AHU-8	Music	Packaged RTU	McQuay	11,400	2007	15	Fair	15-25	5-10	\$234,596	7	Service unit, clean coils and drain pan, some rusting internal. Noise concerns to corridor below
AHU-9	Café	Packaged RTU	Trane	16,000	1995	27	Poor	15-25	0	NA	NOW	Currently being replaced
AHU-10	Media Ctr	Packaged RTU	McQuay	8,450	2007	15	Fair	15-25	5-10	\$222,789	8	Service unit, clean coils and drain pan, some rusting internal. Duct insulation. Poor condition in report should be fair
AHU-11	Studio	Packaged RTU	Trane	NA	2007	15	Poor	15-25	5-10	\$84,468	LOW	Reported unit does not function. Low priority to space utilization
AHU-13	Auditorium	Packaged RTU	Trane	24,000	1995	27	Poor	15-25	0	NA	NOW	Currently being replaced
AHX-1	Core CR's	Split draw thru	Trane	9,200	1975	47	Fair	30-40	5-10	\$237,359	5	Unit has been refurbished multiple times but should be replaced. Does provide AC but has distribution concerns. Depends on option selected.
ACCU-3	AHX-1	Packaged ACCU	McQuay	NA	2007	15	Fair	15-25	5-10	incl with AHX-1	5	Replace with AHX-1
ERU-1	Science Lab	Packaged HRV	Venmar	7,600	2007	15	Fair	20-25	5-10	\$288,000	8	Report indicated poor but unit is fair condition and serviceable. Wheel life is less than unit life
ERU-2	Science Lab	Packaged HRV	Venmar	7,600	2007	15	Poor	20-25	0	\$288,000	1	Energy recovery wheel failed. \$85K to replace
ACCU-1	ERU-1	Packaged ACCU	McQuay	NA	2007	15	Fair	15-25	5-10	Incl with ERU-1	8	Replace when ERU-1 replaced
ACCU-2	ERU-2	Packaged ACCU	McQuay	NA	2007	15	Fair	15-25	5-10	Incl with ERU-2	1	Replace with ERU-2

Good	Serviceable condition. No major work required
Fair	Minor issues but in serviceable condition
Poor	Has issues to address and should be considered for replacement

Building Priorities

- Cost Concerns
 - Prioritized on budget
 - Short window for work summers or breaks
 - Occupied school
 - Escalation
 - Equipment lead times
 - Phasing
 - Immediate needs
 - Some opportunities for economies of scale with alternates
 - ACM concerns (Floor tiles, caulking)
 - Fire proofing
 - Fire ratings



KOHLER RONAN, LLC
CONSULTING ENGINEERS

Thank You