| September 2023 | Beecher Road School |
|----------------------|---|
| | Facilities Department Monthly Report |
| | Completed Projects: |
| | In June a leaky dual temp joint located in the boiler room was replaced. |
| | In August a dripping sprinkler pipe was replaced in classroom S5. |
| CLEAN | • Over the summer a lift was rented and all faulty LED bulbs in the South Gym have |
| | been replaced |
| SAFE | Prior to school reopening all HVAC units had MERV-13 filter changes and preventa- |
| | tive maintenance completed by our HVAC vendor. In July the dual temp valve and actuator servicing D2 was replaced. |
| HEALTHY | During August FCU motors in classrooms spaces E1, E6, K3, and S22 were replaced. |
| | These motors have been difficult to obtain. We now have 8 in stock. |
| SCHOOLS | • Over the summer several humidistats were replaced in dehumidification units locat- |
| SCHOOLS | ed in the A, B, and C-Wings. |
| | • During the months of August over 100+ "fix-it" tickets were closed. This number is |
| | not inclusive of time-sensitive maintenance issues reported outside of fix-it. This |
| | number is also non-inclusive of the majority of HVAC repairs. |
| | Projects in process |
| | Over the summer the electrical issue with North pole lights was pinpointed to the underground wiring run between the North and South school. We have obtained a |
| | quote to run electrical from the North school to power the North pole lights, we |
| | will be abandoning the old underground wires. |
| | In mid/late August, with collaboration between Van Zelm Engineering and Wings, an |
| | indoor air quality assessment was completed on all HVAC units located in the build- |
| With Francis | ing. We are currently awaiting the final report. |
| Vito Esparo | • During the 3rd week of August our new roofing vendor completed assessments of |
| Facilities Manager | all 41 roof levels located at our building. An in person review of the final report is |
| Beecher Road School | imminent. |
| 40 Beecher Road | We are currently battling a new set of minor roof leaks located over the S-Wing. We've resealed around the windows above the Rotunda, but we haven't found the |
| Woodbridge, CT 06525 | source yet. |
| woodonage, C1 00525 | Several classroom UVs have been exhibiting issues with their shaft bearings. Those |
| Phone: 203-389-2195 | classrooms are being monitored on a daily basis. Replacement of the bearing in sev- |
| Fax: 203-389-2196 | eral classroom is imminent. |
| | • Over the summer a faulty controller servicing the locker rooms was identified. A |
| | quote for repair has been obtained. |
| | August test results from our water treatment program for our Dual Temp and Hot |
| | Water loops show both loops were below PH and high range molybdate bench- |
| eecher Road School | marks. Our domestic water is being tested to determine if different chemicals should be used to treat the HVAC loops. |
| | Outstanding issues to be addressed: |
| | Roof leaks above the S-Wing, K-wing & Cafeteria continue to be monitored. |
| 5 3 | • Electrical conduit supports on the K-Wing roof are failing Wood had been added |
| | beneath the supports to restrict damage. |
| | • Issues with the domestic cold water pressure in the North School have returned. |
| | Large pressure fluctuations are once again visible during occupied hours. |