



Photo Report

Client: Pana CUSD #4

Facility: Pana High School

Other: Damaged Valleys

Report Date: 12/04/2020 Title: Valley Damage Report




Photo 4



Rusted valley and end of panel. The EPDM actually trapped moisture causing the panels and valley closure to rust.



Photo 5



Photo 6

Valley is very rusted in areas.



