FACILITIES PRIORITY REPORT February 2025

Planned Maintenance		Planned Capital Projects		Planned Summer Inspections	
	Replace water heater (MES)	~	Clima-Tech (Mulino-South Building)	~	District Wide Fire Alarm Inspections
	Coat roofing seams on 6 th grade wing (MRMS)	~	Replace Front Siding (MHS)	•	Fire Door Drop Test
•	Clean lift stations (MES/MHS)	~	Replace Carpet (Mulino Offices)	~	District Wide Backflow Inspections
~	Tear down, clean and wash boilers 1 & 2 (MRMS)	•	Re-Roof Wrestling Room (MHS)	~	Fire Marshall 2 Year Inspection
	Repair and replace steam traps (MRMS)		Re-Roof Section C (MHS)	~	Elevator Inspection (MHS)
~	Tear down and inspect boilers (MHS- New Wing)			V	Bleachers 2 Year Inspection
•	Run new wiring from well house to building (Rural Dell)			•	Asbestos 3 Year Inspection

<u>Vocab</u>

VSD = Variable Speed Drive

AHU = Air Handler Unit

RTU = Roof Top Unit

High School

- Replaced bearings on supply and return fans on RTU 10
- Replaced GFCI in Home Economics room
- Added water to RTU3 (not firing)
- Cleaned coils on kitchen refrigerator
- Added water to RTU10
- Replaced hot water circulating pump

Middle School

- Painted portion of kitchen
- Repaired power supply unit on fire alarm
- Replaced batteries in fire alarm panel
- Blow down boilers
- Installed new mini split for room 14 (heating and cooling)
- Fixed keyway for room 22

MES

- Replaced transducer for room 1
- Replaced drinking fountain in room 13
- Cleaned coil on walk in cooler
- Replaced air vent valve for boiler
- Replaced transducer in lobby
- Replaced circulating pump and motor in boiler room
- Repaired leaky pipe in boiler room
- Added bark chips to playground
- Replaced roofing screws above room 10

Mulino Elementary

- Added screen drain in kitchen sink
- Replaced coil temperature sensor on RTU4 and RTU5
- Unclogged sink drain in staff room

<u>Clarkes</u>

- Cleaned coil on refrigerator
- Replaced 8 seats on swing set
- Patched roof leak above room 8
- Replaced seats on teeter totters
- Repaired door key cylinder on front door
- Replaced door cylinder for playground access

Rural Dell

• Changed water filter in the north building

DO/PE Facility

• Replaced 2 faucets in boys' restroom

Land Lab

• Repaired leaking fertilizer injector