## ProCare Services



## **Work Order Information**

Service Location ALPENA FIRE DEPT - Contact Tim Slosser tims@alpena.mi.us

ALPENA, Michigan, 49707-2424, United States (989) 354-3151

Work Order NumberWO-06848585Work Order StatusDispatchedService Billing TypeT&MPO NumberPer Tim SlosserWork Order TypeRepairTechnicianRYAN VROOMAN

Problem Description Customer reported the Date of Service 11/26/2023 12:00:00 AM

device's NIBP connector had detached from the bezel.

**Repair/Service Notes** Upon inspection it was discovered the device's NIBP connector had detached from the bezel.

Replaced connector resolving the issue. During performance inspection procedure, device failed NIBP

leakage test, causing the device to XXX.

## **Asset / Product Information**

 Serial Number
 Product Name
 Model Number

 46464607-99577-001955
 LP15,EN,SPO2,3L/12L,EX,NIBP,CO
 99577-001955

 2,TR,VR,BT
 99577-001955

## **Work Order Details**

Time					
Part Number	Description	Qty	<b>Unit Price</b>	Discount	<b>Line Total</b>
LABOR-SMR	Time entry, in hours	1	\$ 316.00	15	\$268.60
				Subtotal	\$268.60
Materials					
40577-000055	KIT - REPAIR, NIBP	1	\$138.00	0	\$0.00
	CONNECTOR, LP15				
40577-000045	KIT - REPAIR, NIBP	1	\$2,292.00	15	\$1,948.20
	ORIONLP15 ROHS				
				Subtotal	\$1,948.20
Expenses					
				Subtotal	\$0.00
				Total	\$2,216.80

Checklist		
Description	Reading	Result

Report Generated: 11/27/2023 12:52:00 PM