District Overview

Estimated Facility Improvement Cost (Phase 1 and Phase 2)

	Phase 1: 2016-2017				Phase 2: 2018-2019				
Facility Name	Installation Costs		Estimated Utility Savings (per year)		Installation Costs		Estimated Utility Savings (per year)		
Jr. High School	5	1,345,479.00	\$		\$	1,071,095.40	S	12,037.77	
Lincoln School	\$	89,328.60	\$	191	\$	114,000.00	5	6,572.51	
Washington School	\$	124,927.20	\$	-	\$	114,000.00	S	7,950.72	
High School	\$	148,200.00	\$	-	\$	157,680.00	S	20,281.60	
Misc. Measures	S	-	\$	-	\$	_	\$	_	
Totals	S	1,707,934.80	\$		\$	1,456,775.40	S	46,842.59	

Jr. High School - Cafeteria and Gym Cost Breakout (\$530,000)



Facility Improvement Measures (FIMs)

· Jr. High School

	eresco Preliminary Facility Im				
FIM Title	Notes	Benefits / Solution		3-5 YEAR PRIORITY	6+ YEAR PRIORITY
Jr. High School					
Cafeteria - New Flooring	New flooring is original, contain ACM, and showing signs of subsurface failure	flooring applied. Base will be rolled and part of the flooring system once installed. Floor will be leveled and cracks repaired prior to application	4		
Cafeteria - Wall Painting	Walls surfaces are showing signs of use	A new high gloss pall paint will be applied for a highly cleanable surface. Damaged surfaces will be patched	4		
Cafeteria - Lighting & Ceilings	Lighting color and fixtures are aged and less efficient then newer LED fixtures.	New LED lighting will be installed	4		
Gym - Flooring	Wood flooring is original and showing signs of wear, contains ACM mastic, and shows signs of exposure to ถ้ามา cits	with new logo & sports lines/markers will be installed. Base will be leveled and cracks repaired prior to application	4		
Gym - Bleachers	Bleachers are worn and in need of replacement to a modern system	the existing bleachers	4		
Gym - Ceiling Clean-up & Wall Paint	Gym ceiling is cluttered with abandoned mechanical equipment and piping, some of which are ACM.	equipment will be abated and removed from the gym, walls patched and repainted.	4		
Gym - New Storage Room	Gym is lacking in usable storage space, New storage space is desired	storage room added to the gym floor and contain two double doors, LED lighting, wall sensors, and impact resistant drywall	4		
Gym - Basketball Backboards Hoist	Basketball backboards do not retract to allow unobstructed views and use during non basketball events	replace the manually operated goals	4		
Theater Curtains	Existing curtains are old and in disrepair	curtain	4		
Fire Alarm Upgrade/Interface	Existing fire alarm is not interfacing with the current BMS	alarms		4	
Building Envelope	Exterior doors and wall to roof seams will be inspected	damaged beyond the useful life will be replaced		1	_
HVAC Building Management System (BMS)	New BMS system will provide better control and monitoring of HVAC and lighting equipment	control existing equipment		1	
Painting Corridor Walls	Corridor walls are cladded with 4"x4" and 2"x4" tile. This creates a dated appearance	Two color multi-step coating over existing tiles will be applied. Broken tiles (or cracks) will be replaced prior to paint treatment.	4	-5	
	Jr. High School Cafeteria - New Flooring Cafeteria - Wall Painting Cafeteria - Lighting & Ceilings Gym - Flooring Gym - Bleachers Gym - Ceiling Clean-up & Wall Paint Gym - New Storage Room Gym - Basketball Backboards Hoist Theater Curtains Fire Alarm Upgrade/Interface Building Envelope HVAC Building Management System (BMS)	Jr. High School Cafeteria - New Flooring New flooring is original, contain ACM, and showing signs of subsurface failure Walls surfaces are showing signs of use Lighting color and fixtures are aged and less efficient then newer LED fixtures. Wood flooring is original and showing signs of wear, contains ACM mastic, and shows signs of exposure to in in cit Gym - Bleachers Gym - Celling Clean-up & Wall Paint Gym ceiling is cluttered with abandoned mechanical equipment and piping, some of which are ACM. Gym is lacking in usable storage space, New storage space is desired Gym - Basketball Backboards Hoist Theater Curtains Existing curtains are old and in disrepair Existing fire alarm is not interfacing with the current BMS Building Envelope Exterior doors and wall to roof seams will be inspected New BMS system will provide better control and monitoring of HVAC and lighting equipment Corridor walls are cladded with 4"x4" and 2"x4" tile. This	Jr. High School Cafeteria - New Flooring New flooring is original, contain ACM, and showing signs of subsurface failure Walls surfaces are showing signs of use Lighting color and fixtures are aged and less efficient then newer LED fixtures. Wood flooring is original and showing signs of wear, contains ACM mastic, and shows signs of exposure to it in a fix in an (t) in a fix in	Jr. High School Cafeteria - Now Flooring New flooring is original, contain ACM, and showing signs of subsurface failure Walls surfaces are showing signs of use Cafeteria - Wall Painting Walls surfaces are showing signs of use Lighting color and fixtures are aged and less efficient then newer LED fixtures. Wood flooring is original and showing signs of wear, contains ACM mastic, and shows signs of exposure to the interfaction of the interfaction of the existing bleachers Gym - Bleachers Gym - Celling Clean-up & Wall Paint Gym - Celling Clean-up & Wall Paint Gym - Resketball Backboards Hoist Theater Curtains Existing curtains are old and in disrepair Existing curtains are old and in disrepair Existing fire alarm is not interfacting with the current BMS Bullding Envelope Exterior doors and wall to roof seams will be inspected HVAC Building Management System New BMS system will provide better control and monitoring contains spoken libe provided in the replaced from contains will be replaced from the grown of the provided better control and monitoring control and provided better control and monitoring contains are cladded with 4"x4" and 2"x4" tile. This Jr. High School Rooming applied. Base will be rolled and part of the flooring applied. Base will be rolled and part of the flooring system once installed. Floor wills be tabeled and cracks repaired prior to application. New LED lighting will be installed An ewh ligh gloss pail paint will be applied for a highly cleanable surface. Damaged surfaces will be patiented. New LED lighting will be installed. New LED lighting will be patiented and a new hardwood licoring with new logo & sports lines/markers will be installed to replace the existing patients. The abandoned mechanical piping and heating equipment will be existed and a new hardwood licoring with new logo & sports lines/markers will be instal	Jr. High School Cafeleria - New Flooring New flooring is original, contain ACM, and showing signs of subsurface failure New Flooring Walls surfaces are showing signs of use Cafeteria - Wall Painting Walls surfaces are showing signs of use Cafeteria - Lighting & Ceilings Lighting color and fixtures are aged and less efficient then never LED fixtures. Gym - Flooring Wood flooring is original and showing signs of wear, contains ACM mastic, and shows signs of exposure to in a not in the flooring is original and showing signs of wear, contains ACM mastic, and shows signs of exposure to in a not in the flooring will be installed. Base will be leveled and cracks repaired prior to application Gym - Bleachers Gym - Ceilling Clean-up & Well Paint Gym ceiling is cluttered with abandoned mechanical acquipment and piping, some of which are ACM. Gym - New Storage Room Gym is lacking in usable storage space. New storage space of the state o