

20 September 2023

To: Ways and Means / Finance Committee

Re: Windsock Light Repair

The windsock light at the approach end of Runway 7 is beyond economical repair. To repair the light will require a new isolation transformer which constitutes the bulk of the cost of the repair.

A quote has been received from J. Rank Electric in the amount of \$7,639.27. It is recommended to accept this quote as J. Rank is performing all of the new installation of electrical systems for the Airport, the repair can be added to the "as built" report for the 2023 runway repairs, and they are already onsite saving mobilization costs.

A request is made to increase Line Number 295-595-933.002 by \$7,639.27. The repair will then be claimed on the 3rd Quarter CARES Act Reimbursement request.

Respectfully



Steven Smigelski
Airport Manager
Alpena County Regional Airport