

#### STATE OF MICHIGAN

#### DEPARTMENT OF ENVIRONMENTAL QUALITY





January 31, 2019

Mr. Don Wood Alpena County Drain Commissioner 603 South Eleventh Street Alpena, Michigan 49707

Dear Mr. Wood:

Section 22 of Part 307, Inland Lake Levels, of the Natural Resources and Environmental Protection Act. 1994 PA 451, as amended (NREPA), requires delegated authorities to submit dam inspection reports to the Michigan Department of Environmental Quality (DEQ) every three years. Dam inspections must be conducted by a licensed professional engineer.

Our records indicate that the Alpena County Drain Commissioner is the delegated authority for the following dams, which are due for inspection this year:

Beaver Lake Dam, Dam ID 1074 Long Lake Level Control Structure, Dam ID 1078

The inspection reports for these dams must be submitted to the Dam Safety Program, DEQ, by December 31, 2019.

A list of consulting engineers offering services in dam safety may be found on our website at:

http://www.michigan.gov/damsafety

Copies of Part 307 and its administrative rules may be found there, as well. Printed copies of Part 307 are also available upon request.

We have developed an inspection report form that should be used for the dams listed above; it may be accessed on our website. Note that this form is intended specifically for dams covered by Part 307 and is not adequate for dams covered by both Part 307 and Part 315, Dam Safety, of the NREPA. If you have any questions regarding inspection report requirements, please contact Mr. James Pawloski, P.E., Hydrologic Studies and Dam Safety Unit, Water Resources Division, at 989-370-1528 or PawloskiJ@michigan.gov, or you may contact me.

Sincerely.

Mario Fusco Jr., M.S., P.E., Supervisor Hydrologic Studies and Dam Safety Unit


Water Resources Division

517-256-4458

cc: Mr. James Pawloski, P.E., DEQ

## Dam Safety Staff

www.mi.gov/damsafety





Water Resources Division 517-284-5567



# STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY

DE

LIESL EICHLER CLARK

LANSING

January 31, 2019

Mr. Don Wood Alpena County Drain Commissioner 603 South Eleventh Street Alpena, Michigan 49707

Dear Mr. Wood:

Section 22 of Part 307, Inland Lake Levels, of the Natural Resources and Environmental Protection Act. 1994 PA 451, as amended (NREPA), requires delegated authorities to submit dam inspection reports to the Michigan Department of Environmental Quality (DEQ) every three years. Dam inspections must be conducted by a licensed professional engineer.

Our records indicate that the Alpena County Drain Commissioner is the delegated authority for the following dams, which are due for inspection this year:

Beaver Lake Dam, Dam ID 1074 Long Lake Level Control Structure, Dam ID 1078

The inspection reports for these dams must be submitted to the Dam Safety Program, DEQ, by December 31, 2019.

A list of consulting engineers offering services in dam safety may be found on our website at:

http://www.michigan.gov/damsafety

Copies of Part 307 and its administrative rules may be found there, as well. Printed copies of Part 307 are also available upon request.

We have developed an inspection report form that should be used for the dams listed above; it may be accessed on our website. Note that this form is intended specifically for dams covered by Part 307 and is not adequate for dams covered by both Part 307 and Part 315, Dam Safety, of the NREPA. If you have any questions regarding inspection report requirements, please contact Mr. James Pawloski, P.E., Hydrologic Studies and Dam Safety Unit, Water Resources Division, at 989-370-1528 or PawloskiJ@michigan.gov, or you may contact me.

Sincerely,

Mario Fusco Jr., M.S., P.E., Supervisor Hydrologic Studies and Dam Safety Unit


Water Resources Division

517-256-4458

cc: Mr. James Pawloski, P.E., DEQ

### Dam Safety Staff

www.mi.gov/damsafety



Mario Fusco 517-256-4458

Supervisor, Hydrologic Studies and Dam Safety PO Box 30458

525 West Allegan Street

Lansing 48909

Lansing 48909





Water Resources Division

517-284-5567