## 2024-25 Operations and Maintenance 7 Year Capital Improvement Cost Summary

Building / Description	Recommendation	Cost Estimate	Priority	Year	Comments	2023-2024 Capital Plan Budget	2023-2024 Capital Plan Carryover Amount	Year 1 2024-2025	Year 2 2025-2026	Year 3 2026-2027	Year 4 2027-2028	Year 5 2028-2029	Year 6 2029-2030	Year 7 2030-2031
Geneva High School-Academic Areas														
Health/Life Safety Improvements (carryover from 2023-24 Capital Plan)	Recommendation to bring the facility up to code and safety standards as per the ROE and 10-Year HLS Requirement.	\$ 452,491.31	н	1	10 Year HLS "B" Repairs	\$ 830,000.00	\$ 452,491.31 \$	452,491.31						
Parking lot- Logan Street Maintenance Building (carryover from 2023-24 Capital Plan)	Resurfacing and drainage improvements.	\$ 119,800.04	н	1	Surface is deteriating and drainage improvements are needed.	\$ 150,000.00	\$ 119,800.04 \$	119,800.04						
(carryover none 2023-24 capital rian)	resurracing and dramage improvements.	\$ 119,800.04			improvements are needed.	\$ 50,000.00								
			н	1		(The total was \$213,647.50, Facilties Task Force and the BOE approved monies due to	\$ 69,107.50 \$	69,107.50						
Concrete sidewalk/curb repairs (carryover from 2023-24 Capital Plan)	Replace cracked and damaged sections.	\$ 69,107.50			Repair for safety concerns.	the Roof bid being under budget.)								
DDC Controls (carryover from 2023-24 Capital Plan)	Replace end of life HVAC controls	\$ 272,563.90	н	1	Convert pneumatic to digital controls.	\$ 2,046,475.00	\$ 272,563.90 \$	272,563.90						
Flashing repair and tuckpointing (carryover from 2023-24 Capital Plan)	Repair cracked and missing brick and mortar joints.	\$ 44,000.00	н	1	Needed for leaking areas and cracked/missing mortar joints	\$ 300,000.00	\$ 44,000.00 \$	44,000.00						
Retaining wall			н	1	Landscape blocks are being pushed forward	\$ 68,000.00	\$ 16,200.50 \$	16,200.50						
(carryover from 2023-24 Capital Plan)	Replace failing retaining wall.	\$ 16,200.50		-	and tipping over causing a safety hazard.	00,000.00	Ç 10,230.30 Ç	10,200.30						
Switchboard			н	1	Current switchboard is 47 years old. The disconnects do not operate properly causing a	\$ 129,370.00	\$ 129,370.00 \$	129,370.00						
(carryover from 2023-24 Capital Plan)	Replace with new switchboard	\$ 129,370.00			safety issue.									
Boiler system (carryover from 2023-24 Capital Plan)	Replace steam boilers with new heating system.	\$ 2,365,250.00	Н	1	Steam line failed and was replaced Summer 2014. Budgeting funds for system upgrade.	\$ 100,000.00	\$ 100,000.00 \$	2,365,250.00						
Flooring replacement			Budget	1,2,3,5	Flooring at least 22 years old. Fraying/Tripping	\$ 169,600.00	\$ 137,294.63 \$	137,294.63	\$ 250,000.00	600,000.00		\$ 600,000.00		
(carryover from 2023-24 Capital Plan)	Replace worn flooring remaining on the 1st floor areas.  Add additional office space in the Deans' and Counseling Advising	\$ 1,587,294.63			hazard. Replace in phases.									
Office space Renovate Cafeteria bathrooms	Office areas.	\$ 95,000.00 \$ 70,000.00	Н	1	Additional office space needed for staff.  50 years old and in need of updating.		\$	95,000.00						-
Renovate Careteria datirooms Renovate Stagecraft area including bathrooms	Update	\$ 70,000.00	H	1	50 years old and in need of updating.		\$	70,000.00					1	1
PVI hot water heaters (500 Gallon) (2)	Replacing 2 - 500 gallon hot water heaters.	\$ 271,000.00	н	1	Typical life cycle of a commercial hot water heater is 12 to 15 years.		\$	271,000.00						
Freezer/Cooler Mechanical Replacement	Replace due to end of life span and consistent failures.	\$ 50,000.00	Н	1	26 years old and in need of replacement.		\$	50,000.00						
Auditorium stage and house lighting	Update the entire lighting system.	\$ 350,000.00	М	2	Lighting panel becoming obsolete and parts are no longer available.				\$ 350,000.00					
Air handlers (7)	Need Re-built or replacement	\$ 500,000.00	М	2	50 years old and nearing estimated service life according to ASHRAE.				\$ 500,000.00					
Make-up Air Unit at 301 McKinley	Replacing current make-up air unit.	\$ 125,000.00	М	2	Installed 1996 and nearing estimated service life according to ASHRAE.				\$ 125,000.00					
made ap 7 in one of 302 including	repaining current make up an unit.	y 125,000.00												
			M	2	HVAC equipment nearing end of service life based on CS2 Design Group, LLC 2021				\$ 6,800,000.00					
End of service life HVAC Equipment	Replace end of life equipment with high efficiency equipment	\$ 6,800,000.00			Mechanical Facility Study.									
Indoor track flooring	Resurface and repair cracking	\$ 145,000.00	М	2	End of life and surfacing needed.				\$ 145,000.00					
	Replace system, parts becoming obsolete and no longer available for		М	2					\$ 300,000.00					
Elevator system upgrade (2)	repairs. 2 elevators in building.	\$ 300,000.00			Consistant breakdowns and repairs.									
Library furniture	Replace furniture	\$ 300,000,00	М	2	End of life and new furniture needed for safety concerns.				\$ 300,000.00					
			М	3	Generator is 22 years old. Nearing end of life					280,000.00				
Emergency back-up generator	Replace unit.	\$ 280,000.00	141		cycle; consistent repairs and breakdowns.					200,000.00				
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 560,000.00	М	4	Energy savings with LED lighting and controls.						\$ 560,000.00			
Parking lot	Periodic maintenance; sealcoating	\$ 250,000.00	M,L	4,7	Sealcoated in 2022.  Nearing end of life cycle and many failing						\$ 125,000.00			\$ 125,000.00
Roof- Standing Seam Metal	Repair/waterproof restoration coating.	\$ 850,000.00	L	6	sections as per FGM Architect Roof Assessment Report.								\$ 850,000.0	0
Air conditioning	Add air conditioning in the athletic area.	\$ 5,100,000.00	L	7	Add air conditioning for staff and student comfort.									\$ 5,100,000.00
Geneva High School-Athletic Areas														
Health/Life Safety Improvements (carryover from 2023-24 Capital Plan)	Recommendation to bring the facility up to code and safety standards as per the ROE and 10-Year HLS Requirement.	\$ 38,733.59	н	1	10 Year HLS "A" Repairs	\$ 82,000.00	\$ 38,733.59 \$	38,733.59						
		\$ 1,342,850.10		1	Turf was installed in 2012. Typical life cycle of	\$ 50,000.00	\$ 50,000.00 \$	1,342,850.10						1
Burgess field turf & track replacement (carryover from 2023-24 Capital Plan)	Turf renewal maintenance.	7 1,342,850.10	Н	1	synthetic turf is 8-10 years. Budgeting \$50K over 10 years.	\$ 50,000.00	50,000.00 \$	1,542,850.10						
		\$ 63,584.40	н	1	Replace scoreboard that was installed in the		\$	63,584.40						
Burgess field scoreboard	Replace scoreboard				early 1990s and having consistent repairs.									1
Softball scoreboard	Replace scoreboard	\$ 50,000.00	н	1	Replace scoreboard that has consistent problems and parts are obsolete.		\$	50,000.00						
Storage shed	Athletic area	\$ 72,080.00	L	7	Needed space for athletic/gym supplies.									\$ 72,080.00
Portable outgries baseball bloods as	Purchase new moveable bleachers.	\$ 98,400.00	L	7	Added bleachers needed at the baseball fields									\$ 98,400.00
Portable exterior baseball bleachers SECURITY	Furctidase flew fliovedule pleacners.				that can be utilized in other areas for events.									
Exterior security cameras	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 66,273.31	H,M,L	1,2,3,5	Replace cameras due to diiscontinued model and outdated.		\$	26,170.75	\$ 11,321.40	24,117.16		\$ 4,664.00		
	Replace discontinued interior cameras and add more to prevent,	\$ 121,368.32	H,M, L	1,2,3,4,5	Replace cameras due to diiscontinued model and outdated and add more for safety		S	32,572.18	\$ 29,732.01	19,777.72	\$ 11,979.16	\$ 27,307.25		
Interior security cameras	monitor, deter, and investigate when incidents occur.		, ,,	, , , , , , ,	reasons.  Adding this feature will enhance the		Ť		-5,: 52:32					1
Add EOR roader and wiring to Access Cantral System	Install a FOB to the hallway doors at the Health Office and Band Room.	\$ 33,814.00	М	2,3	protection of our assets and reduce the risk of				\$ 16,907.00	16,907.00				
Add FOB reader and wiring to Access Control System	Addition of interior security cameras to monitor, prevent, deter, and		1	3.5	Administration (desarted assets				6			6 40.40	1	1
Interior security cameras	Investigate when incidents occur. (Phase 1: Year 3: \$4,400) (Phase 2: Year 5: \$9,900)		M,L	2,5	Administration identified areas where cameras would be of assistance.				\$ 4,664.00			\$ 10,494.00		
Total for GHS GMS-N		\$ 17,453,859.60					\$ 1,429,561.47	5,715,988.90	\$ 8,482,624.41	\$ 940,801.88	\$ 696,979.16	\$ 642,465.25	\$ 850,000.0	0 \$ 125,000.00

Building / Description	Recommendation	Cost Estimate	Priority	Year	Comments	2023-2024 Capital Plan Budget	2023-2024 Capital Plan Carryover Amount	Year 1 2024-2025	Year 2 2025-2026	Year 3 2026-2027	Year 4 2027-2028	Year 5 2028-2029	Year 6 2029-2030	Year 7 2030-2031
Concrete sidewalk repairs (carryover from 2023-24 Capital Plan)	Replace cracked and damaged sections.	\$ 47,400.00	н	1	Repair for safety concerns.	(The total was \$260,700.00, Facilties Task Force and the BOE approved monies due to the Roof bid being under budget.)	\$ 47,400.00	\$ 47,400.00						
LMC air handling unit	Add VAV boxes with associated piping and ductwork as required.	\$ 68,000.00	М	2	Only 2 VAV boxes installed for entire Library area. Add 6-8 boxes.			\$	68,000.00					
		\$ 310,000.00	м	2	End of life and surfacing needed for safety			\$	310,000.00					
Track Resurface	Resurface and repair cracking	\$ 130,000.00	M,L	3,6	Extend the life of pavement. Sealcoated and				ς.	65,000.00			\$ 65,000.00	
Parking Lot	Sealcoating and crack filling				crack filled in 2019.				, , , , , , , , , , , , , , , , , , ,	05,000.00	330,000.00		\$ 05,000.00	
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 330,000.00	М	4	Energy savings with LED lighting and controls.  Life cycle of average flooring is 12-20 years.					\$	·			
Flooring replacement	Replace worn carpet and tile throughout school.	\$ 800,000.00	М	4	Extensive staining and wear.					\$	800,000.00			
Scoreboard	Replace scoreboard	\$ 60,000.00	L	5	Replace scoreboard, nearing end of life cycle							\$ 60,000.00		
		2 400 000 00		_	Nearing end of life cycle and many failing sections as per FGM Architect Roof									\$ 3,100,000.00
Roof	Replace roof/waterproof restoration coating.	\$ 3,100,000.00	L	7	Assessment Report. Roof installed 2000. Replace in sections.								;	\$ 3,100,000.00
		\$ 150,000.00	L	7	Nearing end of life cycle; consistent repairs								:	\$ 150,000.00
Emergency back-up generator SECURITY	Replace unit.				and breakdowns.									
Exterior security cameras	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 16,233.97	Н,М	1,2	Replace cameras due to diiscontinued model			\$ 3,773.80 \$	12,460.17					
	Replace discontinued interior cameras to prevent, monitor, deter,	\$ 29,641.19	м	3,4	Replace cameras due to diiscontinued model				\$	26,570.05 \$	3,071.14			
Interior security cameras	and investigate when incidents occur.			1	and outdated.  Bollards help provide deterrence and									
Security traffic bollards	Install security bollards outside of the front entrance to provide a barrier.	\$ 5,300.00	L	5	protection for both life and property. Identified in the ARCON 2014 Security Assessment.							\$ 5,300.00		
Total for GMS-N		\$ 4,246,575.16					\$ 47,400.00	\$ 51,173.80 \$	390,460.17 \$	91,570.05 \$	333,071.14	\$ 65,300.00	\$ 65,000.00	\$ 3,250,000.00
GMS-S														
Gym flooring [carryover from 2023-24 Capital Plan]	Resurface and seal Auxillary & West Gym.	\$ 11,919.00	Н	1	Floor showing wear.	\$ 38,646.00	\$ 11,919.00	\$ 11,919.00						
						\$ 125,000.00								
		\$ 37,160.00	Н	1		(The total was \$204,380.00, Facilties Task Force and the BOE approved monies due to	\$ 37,160.00	\$ 37,160.00						
Concrete sidewalk/curb repairs [carryover from 2023-24 Capital Plan]	Replace cracked and damaged sections.				Repair for safety concerns.	the Roof bid being under budget.)								
Stage lighting	Update the entire light system.  Recommend in phases. First phase main office, athletic and	\$ 50,000.00	H		Original to the building, starting to fail.			\$ 50,000.00						
Ceiling tile and grid replacement	technology wings.	\$ 205,000.00	М	2	Grid is starting to show discoloration.			\$	205,000.00					
Track resruface	Resurface and repair cracking	\$ 310,000.00	М	2	End of life and surfacing needed for safety concerns.			\$	310,000.00					
Emergency back-up generator	Replace unit.	\$ 175,000.00	м	2	Nearing end of life cycle; consistent repairs and breakdowns.			\$	175,000.00					
Parking lot		\$ 130,000.00	M,L	2,5	Extend life of pavement.			\$	65,000.00			\$ 65,000.00		
Roof	Repair failing sections of roof.	\$ 300,000.00	М	3	Roof assessment found several failing sections of the roof.				\$	300,000.00				
		\$ 2,500,000.00	М	3	HVAC equipment nearing end of service life based on CS2 Design Group, LLC 2021				\$	2,500,000.00				
End of service life HVAC Equipment	Replace end of life equipment with high efficiency equipment				Mechanical Facility Study  DX units are original and beginning to show									
Chiller - 180 ton	Add to replace noisy, inefficient DX units on roof.	\$ 318,600.00	М	3	signs of wear and failure.				\$	318,600.00				
Flooring replacement	Replace worn carpet and tile throughout school.	\$ 800,000.00	М	3	Life cycle of average flooring is 12-20 years.  Extensive staining and wear.				\$	800,000.00				
Elevator upgrade	Replace system, parts becoming obsolete and no longer available for repairs.	\$ 150,000.00	М	3	Consistant breakdowns and repairs.				\$	150,000.00				
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 371,000.00	М	4	Energy savings with LED lighting and controls.					\$	371,000.00			
SECURITY	neplace members mercury vapor and nourescent agreeng.				Energy sowings wan zeo ngriting and controls.									
Exterior security cameras (carryover from 2023-24 Capital Plan)	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 28,579.73	н,м	1,,2,3,4	Replace cameras due to diiscontinued model and outdated.	\$ 8,045.40	\$ 8,045.40	\$ 8,045.40 \$	7,547.60 \$	8,284.78 \$	4,701.95			
Interior security cameras	Replace discontinued interior cameras to prevent, monitor, deter,	\$ 57,781.05	н,м	1,2,3,4	Replace cameras due to diiscontinued model	\$ 16,940.00	\$ 16,940.00	\$ 16,940.00 \$	12,095.01 \$	12,948.02 \$	15,798.02			
Server for cameras	and investigate when incidents occur.  Current server is obsolete and is at the end of it's life.	\$ 13,500.00	Н	1	Replace for safety concerns.			\$ 13,500.00						
Security traffic bollards	Install security bollards outside of the front entrance to provide a barrier.	\$ 4,664.00	L	5								\$ 4,664.00		
Total for GMS-S		\$ 4,458,203.78					\$ 74,064.40	\$ 137,564.40 \$	5 569,642.61 \$	3,289,832.80 \$	391,499.97	\$ 69,664.00	\$ -	\$ -
Harrison Health/Life Safety Improvements	Recommendation to bring the facility up to code and safety													
(carryover from 2023-24 Capital Plan)	standards as per the ROE and 10-Year HLS Requirement.	\$ 41,545.62	Н	1	10 Year HLS "B" Repairs	\$ 125,180.00	\$ 41,545.62	\$ 41,545.62						
						\$ 40,000.00 (The total was \$86,690.00, Facilties Task								
Concrete sidewalk repairs		\$ 15,580.00	Н	1		Force and the BOE approved monies due to	\$ 15,580.00	\$ 15,580.00						
(carryover from 2023-24 Capital Plan)	Replace cracked and damaged sections.				Repair for safety concerns.	the Roof bid being under budget.)								
		\$ 113,458.03	н	1	Nearing end of life cycle and many failing sections as per FGM Architect Roof	\$ 1,530,592.00	\$ 113,458.03	\$ 113,458.03						
Roof (carryoyer from 2023-24 Capital Plan)	Replace roof/waterproof restoration coating.	113,438.03	"	1	Assessment Report. Roof installed 2000. Replace in sections.	1,330,332.00	J 113,436.03	J 113,436.03						
Elevator/Server Room AHU	Replace AHU.	\$ 50,000.00			Nearing end of life cycle as per ASHRAE.			\$ 50,000.00						
Chiller - 80 tons	Replacement will be needed.	\$ 410,000.00	Н	1	Chiller nearing end of life cycle as per ASHRAE.			\$ 410,000.00						
Air Handlers (3) Hot water heater	Rebuild with new components.  Install new commercial unit.	\$ 35,000.00	M M	2	Shell is in good condition.  AO Smith was installed in 2011.			\$ \$	190,800.00 35,000.00					
Gym Floor Refinishing Radiant heat-K Wing	Refinish and seal gym. Replace with new radiant piping.	\$ 60,000.00		2	Floor showing wear.			\$	60,000.00	42,000.00				
		\$ 110,000.00	M	3					Ś	110,000.00				
Cabinet Unit Heaters (15) Parking Lot	Replace with new units.  Sealcoating and crack filling		M,L		Units over 43 years old. Replace as fans fail.  Extend life of pavement				\$	50,000.00			\$ 50,000.00	
					HVAC equipment nearing end of service life									
		\$ 1.823 206 00	M	3	based on CS2 Design Group 11C 2021			1	l ¢	1.823.206.00				
End of service life HVAC Equipment	Replace end of life equipment with high efficiency equipment	\$ 1,823,206.00	М	3	based on CS2 Design Group, LLC 2021 Mechanical Facility Study Nearing estimated service life according to				\$	1,823,206.00				

Building / Description	Recommendation	Cost Estimate	Priority	Year	Comments	2023-2024 Capital Plan Budget	2023-2024 Capital Plan Carryover Amount	Year 1 2024-2025	Year 2 2025-2026	Year 3 2026-2027	Year 4 2027-2028	Year 5 2028-2029	Year 6 2029-2030	Year 7 2030-2031
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 243,800.00	М	4	Energy savings with LED lighting and controls.						\$ 243,800.00			
Emergency back-up generator	Replace unit.	\$ 190,000.00	М	4	Nearing end of life cycle; consistent repairs and breakdowns.						\$ 190,000.00			
Playground Surface	Replacement will be needed.	\$ 270,000.00	L	5	Manufacturer recommended life expectancy 10-15 years. Built in 2008.							\$ 270,000.00		
SECURITY					Replace cameras due to diiscontinued model									
Exterior security camera	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 12,058.58	Н, М	1,2	and outdated.			\$ 4,510.98	\$ 7,547.60					<del> </del>
Interior security camera	Replace discontinued interior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 2,723.61	М	3	Replace cameras due to diiscontinued model and outdated.					\$ 2,723.61				1
Total for Harrison Western		\$ 4,268,171.84					\$ 170,583.65	\$ 635,094.63	\$ 293,347.60	\$ 2,585,929.61	\$ 433,800.00	\$ 270,000.00	\$ 50,000.00	\$ -
Health/Life Safety Improvements	Recommendation to bring the facility up to code and safety	\$ 78,282.55	н	1		\$ 102,000.00	\$ 78,282.55	\$ 78,282.55						
(carryover from 2023-24 Capital Plan)	standards as per the ROE and 10-Year HLS Requirement.	70,202.33	- "	-	10 Year HLS "B" Repairs	Ţ 102,000.00	70,202.33	70,202.33						<del>                                     </del>
Boiler Replacement (2) (carryover from 2023-24 Capital Plan)	Replace with new high efficiency boilers.	\$ 329,248.50	н	1	34-year old boilers are inefficient and nearing the end of their estimated service life as per ASHRAE. Per the IGA, GPD will contribute payment towards boiler replacement.	\$ 2,118,850.00	\$ 329,248.50	\$ 329,248.50						
Unit Ventilator/ Gym AHU/ Cabinet Heater Replacement	Replace end of life equipment with high efficiency equipment. Share costs with Geneva Park District.	\$ 3,239,500.00	н	1	Based on CS2 Design Group, LLC 2021 Mechanical Facility Study, HVAC equipemt nearing end of lift. Heater units over 28 years old. AHU coil replaced in 2009.			\$ 3,239,500.00						
Emergency back-up generator	Replace unit.	\$ 63,282.45	Н	1	Nearing end of life cycle; consistent repairs and breakdowns.			\$ 63,282.45						
Roof	Repair and replace roof/waterproof restoration coating.	\$ 1,600,000.00	M,L	2,6	Roof assessment found several failing sections of the roof.				\$ 400,000.00				\$ 1,200,000.00	
Parking lot Interior doors	Replace damaged doors.	\$ 100,000.00 \$ 15,000.00	M,L M	2,5 2	Sealcoated and crack filled in 2018. Showing excessive wear.				\$ 50,000.00 \$ 15,000.00			\$ 50,000.00		
Gym Floor Refinishing		\$ 40,000.00	M		Floor showing wear.						\$ 40,000.00			
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 205,000.00	М	4	Energy savings with LED lighting and controls.  HVAC equipment nearing end of service life						\$ 205,000.00			<u> </u>
End of service life HVAC Equipment	Replace end of life equipment with high efficiency equipment	\$ 1,656,780.00	М	4	based on CS2 Design Group, LLC 2021 Mechanical Facility Study						\$ 1,656,780.00			1
Gym Divider Curtain	Per manufacturer's reccomendation, end of life expectancy is near.	\$ 200,000.00	L	5	Multiple repiars have been made, continuous failures have been occuring							\$ 200,000.00		
SECURITY  Exterior security camera	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 23,292.11	н,м	1,3	Replace cameras due to diiscontinued model and outdated.			\$ 7,547.60	\$ 15,744.51					
Interior security camera	Replace discontinued interior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 2,723.61	М	3	Replace cameras due to diiscontinued model and outdated.					\$ 2,723.61				
Total for Western		\$ 7,553,109.22					\$ 407,531.05	\$ 3,717,861.10	\$ 480,744.51	\$ 2,723.61	\$ 1,901,780.00	\$ 250,000.00	\$ 1,200,000.00	\$ -
Mill Creek Health/Life Safety Improvements	Recommendation to bring the facility up to code and safety	\$ 11,213.50				\$ 99,500.00	\$ 11,213.50	\$ 11,213.50						
(carryover from 2023-24 Capital Plan) Paving for basketall playground area	standards as per the ROE and 10-Year HLS Requirement.				10 Year HLS "B" Repairs  Deteriorating and pooling water causing safety		\$ 47,916.00							<u> </u>
(carryover from 2023-24 Capital Plan) Boiler and primary pump replacement	Extended paving.	\$ 47,916.00	Н	1	issues.  28 years old and nearing estimated service life	\$ 47,916.00		\$ 47,916.00						<del> </del>
(carryover from 2023-24 Capital Plan) Emergency back-up generator	Replace, install new boiler and primary pumps.	\$ 157,350.00	Н	1	according to ASHRAE.  Nearing end of life cycle; consistent repairs	\$ 1,038,000.00	\$ 157,350.00	\$ 157,350.00						<del>                                     </del>
(carryover from 2023-24 Capital Plan)	Replace unit.  Replace system, parts becoming obsolete and no longer available for	\$ 198,826.95	Н	1	and breakdowns.	\$ 190,000.00	\$ 190,000.00	\$ 198,826.95						<del></del>
Elevator Control System Upgrade	repairs.	\$ 150,000.00	M	2	Consistant breakdowns and repairs.				\$ 150,000.00					<del>                                     </del>
Gym Floor Refinishing  Roof	Refinish and seal gym.  Repair and replace roof/waterproof restoration coating.	\$ 65,000.00	M M,L	2,7	Floor showing wear.  Nearing end of life cycle and many failing sections as per FGM Architect Roof Assessment Report. Roof installed in 2005.				\$ 65,000.00					\$ 1,325,000.00
Flooring replacement	Replace	\$ 600,000.00	М	3	Flooring is 15 years old. Replacement needed due to age, wear and staining.					\$ 600,000.00				
Office cooling system		\$ 70,000.00 \$ 80,000.00	M	3	Update for energy efficiency.					\$ 70,000.00				
Cabinet unit heaters	Replace due to age.	\$ 243,800.00	M	4	Cabinet unit heaters are over 28 years old					\$ 80,000.00	\$ 243,800.00			
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 243,800.00			Energy savings with LED lighting and controls.  Manufacturer recommended life expectancy				+		243,000.00	¢ 240,000,00		<b></b>
Playground Surface SECURITY	Replacement will be needed.	پ 210,000.00	L	5	10-15 years. Built in 2006.							\$ 210,000.00		
Exterior security camera	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 21,554.45	н,м	1,4	Replace cameras due to diiscontinued model			\$ 7,758.22			\$ 13,796.23			
Interior security camera	Replace discontinued interior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 2,723.61	М	3	Replace cameras due to diiscontinued model and outdated.					\$ 2,723.61				
Total for Mill Creek	and investigate when incidents occur.	\$ 2,763,384.51			and outdated.		\$ 406,479.50	\$ 423,064.67	\$ 465,000.00	\$ 82,723.61	\$ 257,596.23	\$ 210,000.00	\$ -	\$ 1,325,000.00
Heartland														
Health/Life Safety Improvements (carryover from 2023-24 Capital Plan)	Recommendation to bring the facility up to code and safety standards as per the ROE and 10-Year HLS Requirement.	\$ 17,803.60	н	1	10 Year HLS "B" Repairs	\$ 121,320.00 \$ 55,000.00	\$ 17,803.60	\$ 17,803.60						
Concrete sidewalk/curb repairs (carryover from 2023-24 Capital Plan)	Replace cracked and damaged sections.	\$ 20,495.00	Н	1	Repair for safety concerns.  Age of carpet is 22 years-2023-24 school year.	(The total was \$112,722.50, Facilties Task Force and the BOE approved monies due to the Roof bid being under budget.)	\$ 20,495.00	\$ 20,495.00						
Flooring Replacement (carryover from 2023-24 Capital Plan)	Replace worn carpet and tile throughout school.	\$ 600,000.00	Н	1	Age of Carpet is 22 years-2023-24 school year. Life cycle 12-20 years. Extensive staining and wear.	\$ 477,000.00	\$ 477,000.00	\$ 600,000.00						
Roof	Repair and replace roof/waterproof restoration coating.	\$ 744,550.00	н	1	Nearing end of life cycle and many failing sections as per FGM Architect Roof Assessment Report. Roof installed in 2002. Original to the building and nearing end of life			\$ 744,550.00						
Chilled water pumps replacement and new VFDs installed (2).	Install new VFDs and chilled water pumps.	\$ 49,000.00	М	2	cycle as per ASHRAE. VFDs will increase effiency and extend motor life.				\$ 49,000.00					<u> </u>

Building / Description	Recommendation	Cost Estimate	Priority	Year	Comments	2023-2024 Capital Plan Budget	2023-2024 Capital Plan Carryover Amount	Year 1 2024-2025	Year 2 2025-2026	Year 3 2026-2027	Year 4 2027-2028	Year 5 2028-2029	Year 6 2029-2030	Year 7 2030-2031
Chiller - 230 tons (2)	Replacement will be needed and addition of another redundant chiller.	\$ 550,000.00	М	2	Chiller nearing end of life cycle as per ASHRAE.				\$ 550,000.00					
Parking lot	Periodic maintenance; sealcoating	\$ 100,000.00	M,L	2,5	Resurfaced/Sealcoated in 2019.				\$ 50,000.00		\$	50,000.00		
Gym Divider Curtain	Per manufacturer's reccomendation, end of life expectancy is near.	\$ 140,000.00	М	3	Multiple repiars have been made, continuous failures have been occuring				\$	140,000.00				
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 212,000.00	М	4	Energy savings with LED lighting and controls.						212,000.00			
					2 Burnham boilers and two primary pumps are									
		\$ 598,000.00	М	4	22-years old. Equipment is inefficient and nearing the end of their estimated service life						598,000.00			
Boiler/primary pumps replacement (2)	Replace with new high efficiency boilers and primary pumps.				as per ASHRAE.  Nearing end of life cycle; consistent repairs									<u> </u>
Emergency back-up generator	Replace unit.	\$ 135,000.00	М	4	and breakdowns.						135,000.00			
SECURITY	Replace discontinued exterior cameras to prevent, monitor, deter,	\$ 11,321.40	н	1,2	Replace cameras due to diiscontinued model			\$ 7,547.60	\$ 3,773.80					
Exterior security camera	and investigate when incidents occur.  Replace discontinued interior cameras to prevent, monitor, deter,			1,2	and outdated.  Replace cameras due to diiscontinued model			\$ 7,547.60	\$ 3,7/3.80					<u> </u>
Interior security camera	and investigate when incidents occur.	\$ 2,723.61	М	3	and outdated.				\$	2,723.61				
Total for Heartland		\$ 3,180,893.61					\$ 515,298.60	\$ 1,390,396.20	\$ 652,773.80 \$	142,723.61	\$ 945,000.00 \$	50,000.00	\$ -	\$ -
Williamsburg														
Hot water heater  Gym Floor resurfacing	Install new commercial units.  Resurface and seal gym.	\$ 164,000.00 \$ 30,000.00	Н	1	Bradford White is nearing end of life cycle.			\$ 164,000.00 \$ 30,000.00						<u> </u>
Parking lot	Periodic maintenance; sealcoating	\$ 100,000.00	H, L		Floor showing wear. Sealcoated and crack filled in 2018.			\$ 50,000.00			\$	50,000.00		
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 275,000.00	М	3	Energy savings with LED lighting and controls.				\$	275,000.00				
		\$ 625,000.00	L	6									\$ 625,000.00	
Chiller - 250 tons	Replacement will be needed.	\$ 500,000.00	L	7	Chiller nearing end of life cycle as per ASHRAE.  Age of carpet is 16 years 2023-2024 school									\$ 500,000.00
Flooring Replacement SECURITY	Replace worn carpet throughout school	- 500,000.00			year. Lifecycle is 12-20 years.									- 300,000.00
	Additional exterior cameras to prevent, monitor, deter, and	\$ 23,752.54	н,м	1,2,3	Replace cameras due to diiscontinued model			\$ 11,535.99	\$ 8,442.75 \$	3,773.80				
Exterior security cameras  Total for Williamsburg	investigate when incidents occur.	\$ 1,717,752.54	,	2,2,3	and outdated.			\$ 255,535.99	\$ 8,442.75 \$	278,773.80		50,000.00	\$ 625,000.00	\$ 500,000.00
Fabyan		1,717,732.34							, 0,442.73	270,773.00	,	30,000.00	- 023,000.00	300,000.00
Health/Life Safety Improvements	Recommendation to bring the facility up to code and safety	\$ 71,197.57	н	1		\$ 180,000.00	71,197.57	\$ 71,197.57						
(carryover from 2023-24 Capital Plan)  Hot water heater	standards as per the ROE and 10-Year HLS Requirement.  Install new commercial units.	\$ 161,000.00	Н.	1	10 Year HLS "B" Repairs  AO Smith is nearing end of life cycle.		13,201131	\$ 161,000.00						
		\$ 200,000.00	н	1	Mositure issue due to damaged brick and			\$ 200,000.00						
Tuckpoinitng	Repair damaged brick and mortar				mortar.  Parts are obsolete and we are unable to make									<del>                                     </del>
Burner Parking lot	Replace discontinued boiler burner and controls  Periodic maintenance; sealcoating	\$ 190,000.00 \$ 100,000.00	H H.L	1 1 5	repairs. Sealcoated and crack filled in 2018.			\$ 190,000.00 \$ 50,000.00			\$	50,000.00		
		\$ 291,500.00	M	2				30,000.00	\$ 291,500.00		<u> </u>	30,000.00		
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	+			Energy savings with LED lighting and controls.  Manufacturer recommended life expectancy						5 250,000.00			<del>                                     </del>
Playground Surface	Replacement will be needed.	\$ 250,000.00	М	4	10-15 years. Built in 2008.						5 250,000.00			<u> </u>
Chiller - 247 tons	Replacement will be needed.	\$ 605,000.00	L	5	Chiller nearing end of life cycle as per ASHRAE.						\$	605,000.00		
SECURITY	Replace discontinued exterior cameras to prevent, monitor, deter,				Replace cameras due to diiscontinued model									
Exterior security camera	and investigate when incidents occur.	\$ 15,990.35	н,м	1,2,3,4	and outdated.			\$ 3,773.80	\$ 3,773.80 \$	3,773.80	\$ 4,668.95			
Interior security camera	Replace discontinued interior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 2,723.61	М	3	Replace cameras due to diiscontinued model and outdated.				\$	2,723.61				
Total for Fabyan		\$ 1,887,411.53					\$ 71,197.57	\$ 675,971.37	\$ 295,273.80 \$	6,497.41	\$ 254,668.95 \$	655,000.00	\$ -	\$ -
Coultrap Education Services Center (4th S	t)													
(carryover from 2023-24 Capital Plan)	Replace 23 failing units.	\$ 483,394.98	н	1	Nearing end of life cycle.	\$ 63,051.98	3 \$ 49,063.98	\$ 483,394.98						
Parking lot (carryover from 2023-24 Capital Plan)	Resurface will be needed.	\$ 414,330.78	н	1	Sealcoated and crack filled in 2022.	\$ 282,000.00	\$ 282,000.00	\$ 414,330.78						
HVAC controls	Upgrading the controls with direct digital controls (DDC).	\$ 99,637.65	н	1	Pneumatic controls discontinued.	\$ 125,000.00	99,637.65	\$ 99,637.65						
VFD for furnace		\$ 10,808.82	н	1		\$ 10,808.82	2 \$ 10,808.82	\$ 10,808.82						
(carryover from 2023-24 Capital Plan)	Install new VFD.  Replace system, parts becoming obsolete and no longer available for				Currently does not work and it is overridden.		25,253.02		ć 457.500.00					<del>                                     </del>
Elevator Control System Upgrade	repairs.  Replace old piping with copper piping and provide new ball valves for	\$ 157,500.00	Н	2	Consistant breakdowns and repairs. Current piping is deteriorating and has				\$ 157,500.00					<del> </del>
Domestic water piping	adequate shut-off.	\$ 180,000.00	Н	2	excessive amount of rust.				\$ 180,000.00					
Lighting/Controls upgrade	Replace inefficient mercury vapor and flourescent lighting.	\$ 238,500.00	М	2	Energy savings with LED lighting and controls.				\$ 238,500.00					
Furnace Burners	Burner replacement; Replace with high efficiency burners.	\$ 115,000.00	М	2	24 year old burners nearing the end of their estimated service life as per ASHRAE.				\$ 115,000.00					
	, , , , , , , , , , , , , , , , , , ,	\$ 100,000.00	м	2	- P				\$ 100,000.00					
Tuckpointing	Repair cracked and missing brick and mortar joints.				Brick and mortar joints beginning to fail.				100,000.00			45,000.00		6 45000
Parking lot	Periodic maintenance; sealcoating	\$ 30,000.00	L	5,7	Sealcoated and crack filled in 2022.						\$	15,000.00		\$ 15,000.00
Automatic Sprinkler System	Install Automatic Sprinkler System for Fire Protection	\$ 525,000.00	L	7	No building-wide automatic sprinkler system. Upgrade to meet current NFPA standards.									\$ 525,000.00
SECURITY SECURITY														
Exterior security camera	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 11,321.40	н	1	Replace cameras due to diiscontinued model and outdated.			\$ 11,321.40						
Total for CESC (4th St)		\$ 2,365,493.63					\$ 441,510.45	\$ 1,019,493.63	\$ 791,000.00 \$	- :	- \$	15,000.00	\$ -	\$ 540,000.00
Transportation														
Architectural precast wall panel replacement/repair (carryover from 2023-24 Capital Plan)	Replace/repair cracked precast wall panel.	\$ 45,320.00	Н	1	Panel cracked in fall 2016.	\$ 45,320.00	\$ 45,320.00	\$ 45,320.00						
Parking lot (carryover from 2023-24 Capital Plan)	Resurfacing and drainage improvements.	\$ 665,220.00	н	1	Sealcoated and crack filled in 2022.	\$ 385,220.00	385,220,00	\$ 665,220.00						
		6 600000				363,220.00	383,220.00	- 303,220.00						
	Expand parking lot and install property lighting at new 8.46 acres	\$ 600,000.00	H	1	Additional Parking is needed for									I
Parking lot expansion (carryover from 2023-24 Capital Plan)	parcel.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	- "		Transportation staff and buses.	\$ 600,000.00	\$ 600,000.00	\$ 600,000.00						

## 2024-25 Operations and Maintenance 7 Year Capital Improvement Cost Summary

Building / Description	Recommendation	Cost Estimate	Priority	Year	Comments	2023-2024 Capital Plan Budget	2023-2024 Capital Plan Carryover Amount	Year 1 2024-2025	Year 2 2025-2026	Year 3 2026-2027	Year 4 2027-2028	Year 5 2028-2029	Year 6 2029-2030	Year 7 2030-2031
Oil Pit safety guard replacement	Grates are rusting and main bracket supports are at end of life cycle.	\$ 175,000.00	н	1	Correct safety violation.			\$ 175,000.00						
Air Compressor replacement	Replace failed air compressor	\$ 35,000.00	Н	1	Failed air compressor.			\$ 35,000.00						
Lighting/Controls upgrade	Install lighting control system	\$ 110,000.00	М	2	Energy savings with lighting and controls.				\$ 110,000.00					
Fire alarm system	Update fire system	\$ 220,000.00	М	3	Currently does not meet NFPA code requirements.					\$ 220,000.00				
Lift Station sewage control and pumps replacement	Replace due to parts being obslete and not manufactured anymore.	\$ 125,000.00	М	4	System is at end of life cycle.						\$ 125,000.00			
Parking lot	Periodic maintenance; sealcoating.	\$ 100,000.00	L	5,7	Sealcoated and crack filled in 2022.							\$ 50,000.00		\$ 50,000.00
SECURITY  Exterior security camera	Replace discontinued exterior cameras to prevent, monitor, deter, and investigate when incidents occur.	\$ 8,475.75	Н	1	Replace cameras due to diiscontinued model and outdated.			\$ 8,475.75						
Total for Transportation		\$ 2,629,015.75					\$ 1,174,658.00	\$ 2,074,015.75	\$ 110,000.00	\$ 220,000.00	\$ 125,000.00	\$ 50,000.00	\$ -	\$ 50,000.00
	7 Year Total	\$ 52,523,871.17						\$ 16,096,160.44	\$ 12,539,309.65	\$ 7,641,576.38	\$ 5,339,395.45	\$ 2,327,429.25	\$ 2,790,000.00	\$ 5,790,000.00
	Year 1 (2024-2025)	\$ 16,096,160.44												
	Year 2 (2025-2026)	\$ 12,539,309.65												
	Year 3 (2026-2027)	\$ 7,641,576.38												
	Year 4 (2027-2028)	\$ 5,339,395.45												
	Year 5 (2028-2029)	\$ 2,327,429.25												
	Year 6 (2029-2030)	\$ 2,790,000.00												
	Year 7 (2030-2031)	\$ 5,790,000.00												
	FUTURE CONSIDERATIONS	\$ 8,137,480.00						\$ -	\$ 555,000.00	\$ 1,512,000.00	\$ 800,000.00	\$ -	\$	\$ 5,270,480.00

## Preliminary Capital Improvement Plan Projects 2024-25

2023-2024 Capital Improvement Carryover \$4,027,016.95
Health/Life Safety Carryover Funds \$711,267.74
2024-2025 Capital Improvement Budget \$16,096,160.44

60E 300 2540 5110			
GHS	Health/Life Safety Improvements	\$	491,224.90
	Parking lot		119,800.04
	Concrete Sidewalk/Curb Repairs	\$	69,107.50
	DDC Controls	\$	272,563.90
	Flashing Repair/Tuckpointing	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	44,000.00
	Retaining Wall	\$	16,200.50
	Switchboard	\$	129,370.00
	Boiler Systems	\$	2,365,250.00
	Flooring Replacement	\$	137,294.63
	Office Space	\$	95,000.00
	Cafeteria Bathrooms	\$	70,000.00
	Stagecraft Area	\$	70,000.00
	PVI Hot Water Heaters	\$	271,000.00
	Freezer/Cooler Mechanical Replacement	\$	50,000.00
	Burgess Field Track & Turf	\$	1,342,850.10
	Burgess Field Scoreboard	\$	63,584.40
	Softball Scoreboard	\$	50,000.00
	Exterior Security Cameras	\$	26,170.75
	Interior Security Cameras	\$	32,572.18
60E 202 2540 5110			
GMSN	Concrete Sidewalk/Curb Repairs	\$ \$	47,400.00
	Exterior Security Cameras	\$	3,773.80
60E 201 2540 5110			
GMSS	Gym Flooring	\$	11,919.00
	Concrete Sidewalk/Curb Repairs	\$	37,160.00
	Stage Lighting	\$ \$ \$ \$	50,000.00
	Exterior Security Cameras	\$	8,045.40
	Interior Security Cameras Server for Cameras	Ş	16,940.00 13,500.00
	Server for Cameras	Ą	13,300.00
60E 102 2540 5110			
HSS	Health/Life Safety Improvements	Ş	41,545.62
	Concrete Sidewalk Repairs Roof	\$ ¢	15,580.00 113,458.03
	Elevator/Server Room AHU	ې <b>خ</b>	50,000.00
	Chiller- 80 tons	\$ \$ \$ \$ \$	410,000.00
	Exterior Security Cameras	\$	4,510.98
	•		

60E 103 2540 5110			
WAS	Health/Life Safety Improvements	\$ \$ \$ \$	78,282.55
	Boiler Replacement	\$ <b>c</b>	329,248.50
	Unit Ventilator/Gym AHU/Cabinet Heater Replacement Emergency Back-up Generator	Ş ¢	3,239,500.00 63,282.45
	Exterior Security Cameras	٠ <	7,547.60
	Exterior Security Carneras	Y	7,547.00
60E 104 2540 5110			
MCS	Health/Life Safety Improvements	\$	11,213.50
	Paving for Playground Area	\$ \$	47,916.00
	Boiler Replacement	\$	157,350.00
	Emergency Back-up Generator	\$	198,826.95
	Exterior Security Cameras	\$ \$ \$	7,758.22
	<b>4</b>	•	,
60E 105 2540 5110			
HES	Health/Life Safety Improvements	\$	17,803.60
	Concrete Sidewalk Repairs	\$	20,495.00
	Flooring Replacement	\$	600,000.00
	Roof	\$ \$ \$	744,550.00
	Exterior Security Cameras	\$	7,547.60
	•		
60E 107 2540 5110			
WES	Hot Water Heater	Ş	164,000.00
	Gym Flooring Replacement	\$	30,000.00
	Parking lot Exterior Security Cameras	\$ \$ \$	50,000.00 11,535.99
	Exterior Security Carrieras	Ą	11,555.55
60E 106 2540 5110			
FES	Health/Life Safety Improvements	\$	71,197.57
	Hot Water Heater		161,000.00
	Tuckpointing	\$ \$ \$ \$	200,000.00
	Burner	\$	190,000.00
	Parking lot	\$	50,000.00
	Exterior Security Cameras	\$	3,773.80
	•	•	
60E 500 2540 5110			
CESC	Fan Coil and Condensing Units	\$	483,394.98
	Parking Lot	\$	414,330.78
	HVAC Controls	Ş	99,637.65
	VFD for Furnace Exterior Security Cameras	\$ \$ <b>\$</b>	10,808.82 11,321.40
	Exterior Security Carrieras	Ş	11,321.40
60E 600 2540 5110			
КТВ	Wall Panel Replacement	\$	45,320.00
	Parking Lot	\$	665,220.00
	Parking Lot Expansion	\$	600,000.00
	HVAC	\$	545,000.00
	Oil Pit Safety Guard	\$ \$	175,000.00
	Air Compressor Exterior Security Cameras	\$ \$ \$ \$ \$ \$ \$	35,000.00 8,475.75
	Exterior Security Cameras	Ş	0,4/3./3

TOTAL: \$ 16,096,160.44

BUDGET: \$ 16,096,160.44

**Additional Projects** 

**ADDITIONAL PROJECTS TOTAL:**