



# TOC

SECTION	<u>PAGE</u>
ACKNOWLEDGMENTS	
I. EXECUTIVE SUMMARY	2
A. Building Analysis	2
B. Enrollment Projections	3
C. Education Standards	3
D. Education Adequacy Assessments	4
E. Community Meetings F. Board Presentation	4
F. Board Presentation	4
II. ENROLLMENT PROJECTIONS SUMMARY	5
III. COMMUNITY MEETING, LOCAL MUNICIPAL COLLABORATIONLINE SURVEY QUESTIONNAIRE	
IV. FACILITY RECOMMENDATIONS	16
V. APPENDICES	18

**APPENDIX A:** Enrollment Projections Report **APPENDIX B:** Survey Report and Other Responses **APPENDIX C:** Board Presentation

**APPENDIX D:** Educational Adequacy Assessment by Facility

#### **ACKNOWLEDGMENTS**

Cooperative Strategies extends our appreciation to Three Rivers School District for commissioning these assessments and long-range plan and for its cooperation to make this possible. We also thank the following groups.

#### **School Board**

Rich Halsted, Board Chair Jennifer Johnstun, Board Vice-Chair Kate Dwyer Paul Kelly Danny York

#### **Administration**

David Valenzuela, Superintendent Lisa Cross, District Accountant Don Hiler, Maintenance Operations Coordinator Ric Ross, Maintenance Operations Coordinator

#### **Cooperative Strategies**

David Sturtz, Partner
Kevin Huber, Senior Director
Ann Hoffsis, REFP, Director of Enrollment Projection Services
Susan Miller, Associate Director
Chris Schmidt, Associate Director
Benjamin Clark, Associate

#### I. EXECUTIVE SUMMARY



#### **Executive Summary of Process**

#### A. Building Analysis

Cooperative Strategies assessed sixteen of the Three Rivers School District facilities in accordance with OAR 851-027-0035, utilizing the Oregon Department of Education "TAP" assessment workbook. The facilities assessed included: Applegate Elementary, Evergreen Elementary, Fort Vannoy Elementary, Fruitdale Elementary, Madrona Elementary, Manzanita Elementary, Williams Elementary, Fleming Middle, Lincoln Savage Middle, Lorna Byrne Middle, Hidden Valley High, Illinois Valley High, and North Valley High Schools. District offices, Food Service, Maintenance Garage and Merlin Alternative School were included in the assessment, but are not included in the Educational Adequacy Report in Appendix D. The assessments took place during the month of November 2018. Initial findings were presented to groups of stakeholders during the month of October 2019.

The assessments included an evaluation of the physical school building systems, as identified with Uniformat level III. This non-destructive assessment evaluated such major building systems as: foundations, roofing, flooring, doors, windows, walls, electrical, HVAC, plumbing, fire protection, communication systems, furniture, fixtures, and equipment. The facility site was also assessed to identify the condition of: school site roadways, parking lots, pedestrian walkways, fencing, site lighting, and utilities.

In addition to the physical condition assessments, a school safety audit and ADA assessment were performed. The safety audit focused on if there were clearly defined drop-off / pick-up areas, appropriate levels of lighting and clear lines of sight for administration to monitor main entrances to the buildings. The ADA assessment focused on ADA accessibility into the school, as well as ADA compliance throughout the facility. All issues were clearly identified and are included in the final recommendations section of this report.

Lastly, three additional audits were conducted with district personnel: one for

information technology, one for harmful substances, and one for indoor air quality. The information technology assessment focused on connectivity speed, wireless coverage, access control, video surveillance and central communications systems. The harmful substance audit identified whether the facility had been tested for lead, asbestos, mold, water quality, PCBs and radon; and if there was treatment or abatement plan in place to remedy any identified issues. The indoor air quality assessment focused on if the school had a HVAC preventative maintenance schedule in place, if rooms were being tested for CO2, and if there was proper ventilation throughout the facility.

#### **B.** Enrollment Projections

Cooperative Strategies developed 10-year enrollment projections for the Three Rivers School District using the cohort survival methodology. The cohort survival method is a popular methodology used to project K-12 enrollment. This methodology uses historical live birth data and historical student enrollment to age a known population throughout the school grades. The percentage of students who move from grade to grade, year to year (survival ratios) are analyzed to determine a projection ratio that is applied to current and future enrollment to develop the enrollment projections. The cohort survival methodology inherently considers the net effects of historical trends in migration, housing, dropouts, transfers to and from charter schools, open enrollment, and deaths. This methodology does not assume changes in policies, program offerings, or future changes in housing and migration patterns.

Three Rivers School District enrollment has decreased by 719 students from 2009-2010. K – 12 enrollment has decreased by 309 students from 2013-14 to 2018-2019. District wide enrollment was 5,131 students in the 2009-2010 school year, compared to 4,412 students in 2018-2019.

A range of enrollment projections, including recommended, moderate, low, and high, were provided to the Three Rivers School District. The moderate projection reflects a 3-year weighted average of survival ratios. The low and high projections offer a more conservative and liberal approach surrounding the moderate projection. The recommended projection is based on a detailed analysis of survival ratios by grade, by year and reflects more recent trends in the District.

There are many factors that can influence student enrollment including, but not limited to, changes or additions in program offerings, student transfer policy changes, housing activity, school voucher programs, school closures, etc. It is important to keep a close eye on these trends as they are difficult to predict, and they do have an impact on projected enrollment. (*The full enrollment projections report is available in Appendix A*).

#### C. Educational Standards

Beginning with floor plans of the District's facilities and national norms as a baseline, draft space types and square footages were established for elementary, middle and high

school. These were modified after review by the District and the resultant space types and square footages were used to assess the facilities. Estimated program capacity was determined between dialogue with Cooperative Strategies and Three Rivers.

#### D. Educational Adequacy Assessments

Educational Adequacy assessments determine the physical capacity of a school building to accommodate the existing programming, or educational courses, being offered. Education adequacy includes variables such as access to operable windows, plumbing, and appropriate technologies in order to begin to determine the ability of a building to facilitate learning. These assessments are inherently subjective, as "adequacy" can be interpreted broadly. Many of the quantitative and qualitative results found here are simple approximations, rather than line-item analyses. If renovations, construction, or other projects are seriously considered, a more in depth architectural and/or engineer analysis would likely be required.

The assessment began with interviews with key administrators who informed the consulting firm, Cooperative Strategies, of the basic conditions of educational adequacy in the district. Educators were engaged and gave their input as well. Out of these conversations, assessment parameters were drafted. Administrators then walked the schools to fill out an assessment form and determine scores for the learning spaces. Those scores are the major information for the report included as Appendix D. There are several times in the report where normative assertions are made regarding pricing, appropriate sizing of classroom, etc. The main external sources used to inform these statements are Square Foot Costs with RS Means data, 2018, 39th annual addition, as well as industry standard best practices.

#### E. Community Meetings

Cooperative Strategies created a web survey to receive community input on the District's priorities. Three community meetings were held to share survey results, facility assessments, enrollment projections, and garner input on district priorities. From these meetings, approximately 20 participants attended. The meetings included an introduction from the Superintendent or staff member, followed by a Cooperative Strategies' led presentation concluding with time for participants to have group discussion, offer feedback and ask questions. (*The full report of the survey is in Appendix B*).

#### F. Board Presentations


The preliminary report was provided for the Three Rivers Board of Directors' meeting on November 20, 2019. This presentation outlined the components of the physical building assessments, the calculated enrollment projections, and the educational adequacy assessments. Cooperative Strategies outlined their recommendations, which were based on priority and available funding. The facilities report is included in the section before the appendices. The Educational Adequacy Assessment by facility is included in Appendix D.

#### **II.** Enrollment Projections Summary

#### Cohort Survival Method

The cohort survival methodology (sometimes referred to as the grade progression ratio method) is a widely used enrollment projection model that is used by many school districts and state and federal agencies to project K-12 enrollment.

A cohort is a group of persons [in this case, students]. The cohort survival enrollment projection methodology uses historic live birth data and historic student enrollment to "age" a known population or cohort throughout the school grades. For instance, a cohort begins when a group of kindergarteners enrolls in grade K and moves to first grade the following year, second grade the next year, and so on.



A "survival ratio" is developed to track how this group of students increased or decreased in number as they moved through the grade levels. By developing survival ratios for each grade transition [i.e. 2nd to 3rd grade] over a ten-year period of time, patterns emerge. A projection ratio for each grade transition is developed based on analysis of the survival ratios. The projection ratios are used as a multiplier in determining future enrollment.

For example, if student enrollment has consistently increased from the 8th to the 9th grade over the past ten years, the survival ratio would be greater than 100% and could be multiplied by the current 8th grade to develop a projection for next year's 9th grade. This methodology can be carried through to develop ten years of projection figures. Because there is not a grade cohort to follow for students coming into kindergarten, resident live birth counts are used to develop a birth-to-kindergarten survival ratio. Babies born five years previous to the kindergarten class are compared in number, and a ratio can be developed to project future kindergarten enrollments.

The cohort survival method is useful in areas where population is stable [relatively flat, growing steadily, or declining steadily], and where there have been no significant fluctuations in enrollment, births, and housing patterns from year to year. The cohort survival methodology inherently considers the net effects of factors such as migration, housing, dropouts, transfers to and from charter schools, open enrollment, and deaths. This methodology does not assume changes in policies, program offerings, or future changes in housing and migration patterns.

#### **Three Rivers School District**

#### **Historical Enrollment**

As indicated in the table below, over the past ten years, student enrollment in the Three Rivers School District has decreased by 719 students. The varying shades of color in the table represent significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

Historical Enrollment - District-wide

Grade	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19
K	308	296	287	345	329	286	277	294	304	336
1	315	317	310	309	353	328	308	312	318	297
2	347	329	328	313	326	352	329	322	309	310
3	343	352	333	343	317	319	359	337	341	315
4	355	340	357	332	347	310	344	375	360	340
5	422	362	352	360	324	349	306	357	406	355
6	369	414	361	362	369	303	359	339	374	399
7	409	370	418	360	367	357	309	367	341	358
8	427	411	380	408	361	362	374	329	372	332
9	426	432	425	418	437	374	372	386	340	381
10	452	417	423	417	414	428	356	366	382	335
11	463	422	399	379	402	414	388	349	338	342
12	495	487	422	428	375	413	416	381	352	312
Grand Total	5,131	4,949	4,795	4,774	4,721	4,595	4,497	4,514	4,537	4,412


Source: Three Rivers School District

#### Historical Enrollment - District-wide

Grade	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19
K - 5	2,090	1,996	1,967	2,002	1,996	1,944	1,923	1,997	2,038	1,953
6 - 8	1,205	1,195	1,159	1,130	1,097	1,022	1,042	1,035	1,087	1,089
9 - 12	1,836	1,758	1,669	1,642	1,628	1,629	1,532	1,482	1,412	1,370
Grand Total	5,131	4,949	4,795	4,774	4,721	4,595	4,497	4,514	4,537	4,412

Source: Three Rivers School District

#### HISTORICAL ENROLLMENT-DISTRICT-WIDE



#### **Resident Live Birth Data**


Utilization of resident live birth data is recommended when projecting future kindergarten enrollments. This data provides a helpful overall trend. Large bubbles in birth counts, either up or down, can also be planned for or anticipated by the District.

In addition, the live birth counts are used in determining a birth-to-kindergarten and birth-to-first grade survival ratio. This ratio identifies the percentage of children born in a representative area who attend kindergarten and first grade in the District five and six years later. The survival ratios for birth-to-kindergarten, birth-to-first grade, as well as grades 1-12 can be found on page 16 of the Enrollment Projection report.

Data is arranged by the residence of the mother. For example, if a mother lives in Portland but delivers her baby in Salem, the birth is counted in Portland. Live birth counts are different from live birth rates. The live birth count is simply the actual number of live births. A birth rate is the number of births per 1,000 women in a specified population group.

The table and graph include the resident live birth counts for zip codes 97497, 97523, 97526, 97527, 97530, 97531, 97532, 97533, 97534, 97538, 97543, and 97544.


#### RESIDENT LIVE BIRTH COUNTS THREE RIVERS SCHOOL DISTRICT ZIP CODES



#### RESIDENT LIVE BIRTH COUNTS THREE RIVERS SCHOOL DISTRICT ZIP CODES

Year	97497	97523	97526	97527	97530	97531	97532	97533	97534	97538	97543	97544
2003	10	66	349	296	39	7	21	2	5	17	7	17
2004	16	51	347	308	49	7	19	2	4	15	6	18
2005	18	42	328	313	56	6	25	1	5	19	10	22
2006	14	60	385	325	52	8	21	1	7	20	8	22
2007	11	54	362	343	53	6	14	0	10	17	3	31
2008	11	71	394	347	50	6	20	0	7	19	8	22
2009	13	52	345	299	42	6	17	0	9	26	6	22
2010	14	63	345	311	46	4	14	2	6	18	3	18
2011	15	69	324	308	49	9	13	0	4	10	3	22
2012	10	63	336	316	43	13	18	0	4	26	12	27
2013	12	70	354	340	44	7	17	1	9	23	10	11
2014	5	58	379	365	55	12	22	0	4	11	2	21
2015	18	61	381	327	58	9	21	1	3	22	4	19
2016	14	63	338	385	56	6	24	0	4	16	9	22

Source: Oregon Health Authority




#### **Housing Data**

Housing development and building permits are tracked to determine their effect on student enrollment. The table and graph below illustrate the number of single-family and multi-family building permits issued in Josephine County since 2000.

BUILDING PERMITS
Josephine County

	Josephine County									
Year	Single-Family	Multi-Family								
2000	367	57								
2001	396	15								
2002	407	113								
2003	495	129								
2004	635	125								
2005	722	127								
2006	543	84								
2007	385	32								
2008	180	9								
2009	103	2								
2010	94	12								
2011	68	2								
2012	79	2								
2013	130	2								
2014	145	4								
2015	173	64								
2016	209	4								
2017	228	22								
2018*	0	0								



**BUILDING PERMITS** 

Source: SOCDS Building Permits Database


\*preliminary through June 2018

#### **Projected Enrollment**

Cooperative Strategies developed low, moderate, high, and recommended enrollment projections for the Three Rivers School District. The moderate enrollment projections are based on a selected average or weighted average of survival ratios (in this case, a 5 year weighted average, by school). The low and high enrollment projections are developed using statistical distributional theory, providing the District with a more conservative (low) and more liberal (high) enrollment projection. The recommended enrollment projection is based on a detailed analysis of historical enrollment and resulting survival ratios over the past 10 years. Significant shifts in survival ratio patterns are realized and accounted for in determining projection ratios independently for each grade level. The recommended illustrates the most likely direction of the District based on more recent trends.

The range of enrollment projections from low (conservative) to high (liberal) are offered due to the limitations of the cohort survival method in factoring changes to policies, program offerings, and future changes in housing and migration patterns. For example, the low enrollment projection might be used if housing declines significantly more than anticipated; the high enrollment projection might be used if housing growth increases at a more rapid rate than seen in recent years.

It should be noted that actual live birth counts are available through 2016 and project kindergarten enrollment through 2021-22. To project kindergarten through 2028-29, an average of the last 5 years of live birth counts was used.



#### Three Rivers School District

#### Projected Enrollment - Recommended

Based on the recommended enrollment, the student enrollment in the Three Rivers School District is projected to increase from 4,412 in 2018-19 to 4,540 students in 2028-29.

The varying shades of color in the table represent significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

Projected Enrollment - Recommended - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K	332	329	333	330	331	331	331	331	331	331
1	351	347	343	348	345	345	345	346	345	345
2	294	347	343	339	344	341	342	342	342	342
3	317	300	354	350	347	351	348	349	349	349
4	323	325	308	363	359	355	360	357	358	358
5	346	329	330	313	370	365	362	367	363	364
6	361	351	334	335	318	375	371	367	372	369
7	396	358	348	331	333	315	372	368	364	369
8	361	399	361	351	334	335	318	375	371	367
9	341	370	409	370	361	342	344	326	385	381
10	376	336	365	404	365	356	338	339	322	380
11	303	339	304	330	365	330	321	305	307	291
12	328	290	326	291	317	350	316	308	293	294
<b>Grand Total</b>	4,429	4,420	4,458	4,455	4,489	4,491	4,468	4,480	4,502	4,540


Source: Cooperative Strategies

Projected Enrollment - Recommended - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K - 5	1,963	1,977	2,011	2,043	2,096	2,088	2,088	2,092	2,088	2,089
6 - 8	1,118	1,108	1,043	1,017	985	1,025	1,061	1,110	1,107	1,105
9 - 12	1,348	1,335	1,404	1,395	1,408	1,378	1,319	1,278	1,307	1,346
Grand Total	4,429	4,420	4,458	4,455	4,489	4,491	4,468	4,480	4,502	4,540

Source: Cooperative Strategies

### PROJECTED ENROLLMENT - RECOMMENDED - DISTRICT-WIDE



# III. Community Meetings, Local Municipal Collaboration, and Online Survey Questionnaire

#### **Community Meetings**

Cooperative Strategies created a web survey to receive community inputs on the District's priorities and allow the community members to bring forth any additional concerns not directly addressed in the survey questions. The survey was open September 18th through October 1st, 2019. The list of questions asked, and possible responses to them, begin on page 13. A survey results report can be found in Appendix B as well as the answers to all open-ended responses.

On October 15<sup>th</sup> and 16th, community meetings were held at the three high schools to share the information that was collected from the community survey and physical assessments completed by administrators. The intent of these meetings was to garner community input on District priorities. The community meetings consisted of administrators, staff, board members, and community members. Community members were encouraged to attend. Approximately 20 individuals participated in the meetings.

The meetings were run by the Cooperative Strategies' team. During the meetings, Cooperative Strategies presented the results of the community web survey and answered any questions that were raised about the survey and its results. In addition, the community was asked to respond to three questions:

- 1) What are your reactions to the data?
- 2) What else do we need to know about your school facilities?
- 3) What other information should we consider?

Conversations also included the economy students currently face upon graduation and the skill sets needed to find success in the 21<sup>st</sup> century economy. Community members and administration discussed the challenges of retaining students through graduation. In addition, participants discussed need for capital investment in school facilities. All participants agreed the current facilities are old, worn out and need to change for the health, safety and educational adequacy for all students.

#### **Local Municipal Collaboration**

Cooperative Strategies also reached out to Lora Glover of the planning department with the City of Grants Pass to outline the proposed plans and request any collaboration to determine if there was a duplication of work, pursuant to ORS 195.110. A response is pending as of the writing of this report which will be uploaded and resent once received.

#### **Community On-line Survey**

A community survey was conducted online between September 18th and October 1st, 2019 for the facilities master planning process. This online survey helps gather community outreach responses for improving the options development phase of the master plan. A total of 405 community members responded to the survey. However, some respondents skipped specific questions from within the survey. The community expressed support for improved physical condition of the current facilities, move classrooms out of portables to permanent facilities, and improve specialized spaces such as STEM/STEAM and Computer/Technology spaces. Other areas of improvement included heating/air conditioning systems and roof maintenance. Security was also highlighted as a significant need. (*The full report of the survey is in Appendix B on Page 26 of this document.*)

The following are the facility questions included in the web survey:

Q1: Which of the following space types do you believe the District should prioritize when renovating current classrooms and other learning environments? (eg. Improving what we have now) Please select the top 5 that you think are the most important.

- 1. Computer / Technology labs
- 2. Stem/STEAM classrooms
- 3. *Library/Media center(s)*
- 4. Elementary school multi-purpose space
- 5. Science labs
- 6. Career technical education spaces
- 7. Band/Choir
- 8. Art classroom(s)
- 9. *Cafeteria(s)*
- 10. Food preparation: Kitchen
- 11. Outdoor covered areas
- 12. Athletic/Recreation facilities
- 13. Student Health Center
- 14. Auditorium(s)
- 15. Gymnasium(s)
- 16. Office Space(s)
- 17. Conference room(s)
- 18. Auxiliary gymnasiums
- 19. Other (please specify)

Q2: Which of the three (3) most pressing issues that you believe the District should consider when making a comprehensive maintenance plan to improve the current condition of existing facilities? Please select only 3.

- 1. Renovate the schools to improve condition of existing facilities
- 2. Improving or modifying schools to better support current learning approaches and future career opportunities
- 3. Improve physical building conditions (e.g. air conditioning, lighting, aesthetics)
- 4. Adding and/or improving access to specialized programs (e.g. fine arts, STEM, theater, CTE, etc.)
- 5. Addressing over-utilized facilities
- 6. Other (please specify)

# Q3: How important is it to you to move classrooms out of portable buildings and place them in permanent facilities?

- 1. Very important
- 2. Important
- 3. No opinion
- 4. Not important
- 5. Not at all important

#### Q4: Rank the following in order of importance?

- 1. Renovate and/or newly construct multipurpose rooms, gyms, conference rooms, playground, auditorium
- 2. Renovate existing permanent buildings
- 3. Replace portables with permanent constructions
- 4. Upgrade / expand instructional technology such as computer hardware and network infrastructure (servers, cabling, switches, etc.)

# Q5: Which of the following safety & security measures should be put in place at all facilities? Please select only 3.

- 1. Ability to simultaneously lock all exterior doors electronically
- 2. Alarm system
- 3. Entry vestibule at main school entry
- 4. Key card access
- 5. Security cameras throughout the facility
- 6. Security officer on campus
- 7. Perimeter security fencing
- 8. *Increased lighting / visibility*
- 9. *Other (please specify)*

# Q6: Under what conditions would you support rebuilding a school versus repairing it? Check all that apply.

- 1. Repair would cost 50% or greater of new construction
- 2. It would allow for a greater educational experience
- 3. *Other (please specify)*

See "other" responses in Appendix B

#### IV. FACILITY RECOMMENDATIONS

The purpose of the 5 - 10 year Master Plan is to prioritize the major capital investments that will be needed to support the district's educational vision. The plan takes into consideration current and desired educational plans, evaluates facility conditions and related capital needs, and provides guidance of capital investments aligned with budgets, capacity and current/future enrollments.

The Three Rivers School District manages over 957,000 square feet of facilities with an average original construction in the 1960s. These facilities are starting to surpass their life cycles with the average age of 50+ years. The oldest school, Applegate Elementary School was built in 1912, just over 107 years old, compared to Fruitdale Elementary School that was built in 2004. The district operates seven elementary schools, three middle schools, three general education high schools and two alternative high schools. Its facility portfolio also includes three additional buildings that serve its administration, food services and maintenance needs. The facilities will almost certainly need to be rebuilt or replaced within the next 10 to 20 years.

Three Rivers recognized the need to evaluate the balance between investing in new schools or the upgrading of current facilities to meet the needs of its students and the delivery of educational programs. Therefore, it moved forward with an assessment plan to identify its facility needs.

The facilities' assessment began with interviews with key administrators who informed the consulting firm, Cooperative Strategies, of the basic conditions of educational adequacy in the district. Educators were engaged and gave their input as well. Out of these conversations, assessment parameters were drafted. Administrators then walked the schools to fill out an assessment form and determine scores for the learning spaces. Those scores are the major information for the report included as Appendix D. There are several times in the report where normative assertions are made regarding pricing, appropriate sizing of classroom, etc. The main external sources used to inform these statements are Square Foot Costs with RS Means data, 2018, 39th annual addition, as well as industry standard best practices.

From those assessments, the district was able to use the data to determine approximately how much it would cost to replace/renovate/repair each deficiency. This allowed the district to evaluate which deficiencies need to be addressed based on total cost, the district's vision and community input. Further, the district was able to identify: Major, Moderate and Minor repairs.

Cooperative Strategies incorporated the data that was collected through this process with the enrollment data to provide a framework for community and district board discussions. The information is included in the following table:

		Year		Program	2007	2018	%	Current	#	Repl	acement			
	Campus	Built	GSF	Capacity	Enrollment	Enrollment	growth/decline	Utilization	portables	Cost		Rej	pair Cost	FCI
	Applegate	1912	37,284	122	115	100	-13%	82%	6	\$	15,564,206	\$	4,733,016	30%
	Evergeen	1951	56,342	365	461	383	-17%	105%	2	\$	23,519,968	\$	12,492,099	53%
	Fort Vannoy	1952	35,934	268	277	237	-14%	88%	0	\$	15,000,648	\$	7,287,208	49%
ES	Fruitdale	2004	51,643	316	313	386	23%	122%	4	\$	21,558,370	\$	1,116,525	5%
_	Madrona	1967	31,980	365	281	338	20%	93%	1	\$	13,350,051	\$	6,349,401	48%
	Manzanita	1966	36,634	390	354	375	6%	96%	3	\$	15,292,863	\$	6,601,114	43%
	Williams	1949	28,795	49	88	75	-15%	153%	5	\$	12,020,473	\$	4,727,804	39%
		1957	278,612	1,875	1,889	1,894	0%	101%	21	\$	116,306,579	\$	43,307,168	37%
S	Fleming	1962	64,875	457	452	405	-10%	89%	1	\$	28,559,273	\$	12,489,514	44%
ž	Lincoln Savage	1962	62,391	411	499	402	-19%	98%	0	\$	27,465,766	\$	11,424,234	42%
	Lorna Byrne*	2003	70,047	314	286	316	10%	101%	0	\$	30,836,090	\$	2,812,893	9%
		1976	197,313	1,182	1,237	1,123	-9%	95%	1	\$	86,861,129	\$	26,726,641	31%
	Hidden Valley	1976	144,206	868	877	572	-35%	66%	0	\$	67,860,459	\$	26,250,051	39%
S	Illinois Valley	1975	104,093	476	432	309	-28%	65%	3	\$	48,984,084	\$	21,089,006	43%
Ξ̈́	North Valley	1976	136,741	504	718	452	-37%	90%	1	\$	64,347,580	\$	32,145,314	50%
	Jerome Prairie	1938	27,441							\$	12,496,631	\$	6,322,416	51%
	Merlin Alt. HS	1953	14,716							\$	6,701,666	\$	3,002,962	45%
		1964	427,197	1,848	2,027	1,333	-34%	72%	4	\$	200,390,421	\$	88,809,749	44%
.⊑	District Office	1947	28,109							\$	12,800,839	\$	5,253,964	41%
Admin	Food Services	1983	7,500							\$	4,269,375	\$	1,108,321	26%
Ä	Maintenance Blg	1958	18,710							\$	6,068,053	\$	3,625,307	60%
		1963	54,319							\$	23,138,267	\$	9,987,592	43%
	TOTAL	1963	957,441	4,905	5,153	4,350	-16%	89%	26		426,696,396		168,831,150	40%

\*Byrne MS was originally built in 1951 but was mostly rebuilt in 2003

Upon the completion of the community meetings, Cooperative Strategies provided to the district's team a roadmap for moving forward to address the district's capital needs. The plan envisions the facilities will almost certainly need to be rebuilt or replaced within 10-20 years. Therefore, the options development team recommends:

- 1. The district considers a full renovation of identified major repairs for all elementary, middle and high schools
- 2. The district pursues a two-phase bond process for completing those repairs needed at the elementary, middle and high schools

The details of the plan are depicted in the Capital Improvement Program section on page 18. The plan is conservative, for it does not identify additional needed repairs that cannot be assessed through visual inspection and/or components that need replacement when they exceed their useful life (e.g. a 25-year roof in its 25<sup>th</sup> year).

In addition, the proposed strategy for future capital investments could have a significant impact on capital investment priorities. Board direction is needed to ensure near-term capital investments align with the long-term facility needs of the district.

#### **Capital Improvement Plan**

Phase 1- Integrates ALL major facility repairs identified by school: \$106,248,554

	All major repairs	
	Evergreen ES	\$ 6,299,633
ES	Fort Vannoy ES	\$ 3,668,947
[1]	Subtotal Cost	\$ 9,968,580
	Soft Development Factor Subtotal	\$ 13,756,640
3.74 3.7	Fleming MS	\$ 8,033,516
MS	Lincoln Savage MS	\$ 6,737,837
2	Subtotal Cost	\$ 14,771,353
	Soft Development Factor Subtotal	\$ 20,384,467
	Hidden Valley HS	\$ 15,074,074
	Illinois Valley HS	\$ 10,874,060
HS	North Valley HS	\$ 17,863,740
	Subtotal Cost	\$ 43,811,874
	Soft Development Factor Subtotal	\$ 60,460,386

	All roofing, plumbing and restroo	ni rej	
	Apple Gate ES	\$	1,440,109
	Madrona ES	\$	1,683,954
S	Manzanita ES	\$	1,925,596
ES	Williams ES	\$	1,377,062
	Subtotal Cost	\$	6,426,721
78 <u>3</u> 8_2	Soft Development Factor Subtotal	\$	8,868,875
	Jerome Prairie	\$	1,317,581
ALT	Merlin Alternative	\$	695,597
X	Subtotal Cost	\$	2,013,178
	Soft Development Factor Subtotal	\$	2,778,186

Total Phase 1 \$ 106,248,554

**Phase 2-** Integrates ALL remaining moderate repairs identified by school: \$51,948,022

	All Moderate Repairs		
	Apple Gate ES	\$	1,405,538
	Ever Green ES	\$	1,801,454
	Fort Vannoy ES	\$	856,490
	Fruitdale ES	\$	535,076
ES	Madrona ES	\$	1,507,103
	Manzanita ES	\$	727,927
	Williams ES	\$	1,092,615
	Subtotal Cost	\$	7,926,203
	Soft Development Factor Subtotal	\$	10,938,160
	Fleming MS	\$	1,040,453
	Lincoln Savage MS	\$	2,003,252
MS	Lorna Bryne MS	\$	1,459,092
	Subtotal Cost	\$	4,502,797
225_722	Soft Development Factor Subtotal	\$	6,213,860
	Hidden Valley HS	\$	4,024,638
HS	Illinois Valley HS	\$	4,585,527
	North Valley HS	\$	5,794,720
	Jerome Prairie	\$	877,094
H	Merlin Alternative	\$	745,950
ALT	Subtotal Cost	\$	16,027,929
	Soft Development Factor Subtotal	s	22,118,542

	Remaining major repairs from pha	se 1	
	Apple Gate ES	\$	660,058
	Madrona ES	\$	1,686,342
ES	Manzanita ES	\$	2,452,361
[1]	Williams ES	\$	1,363,366
	Subtotal Cost	\$	6,162,127
	Soft Development Factor Subtotal	\$	8,503,735
	Jerome Prairie	\$	2,289,926
ALT	Merlin Alternative	\$	734,512
K	Subtotal Cost	\$	3,024,438
	Soft Development Factor Subtotal	\$	4,173,724

Total Phase 2 \$ 51,948,022



# **Appendices Table of Contents**

APPENDIX A: Enrollment Projections Report

APPENDIX B: Survey Report and Other Responses


APPENDIX C: Board Presentation

APPENDIX D: Educational Adequacy Assessment by Facility

THREE RIVERS SCHOOL DISTRICT EDUCATION FACILITY ASSESSMENT & LONG-RANGE PLANNING



# Appendix A Enrollment Projections Report





# **Table of Contents**

Acknowledgements	2
Executive Summary	3
Enrollment Projection Methodology	5
U.S. Census	8
General Demographics	9
Estimated School Age Population	
Housing Data	12
Resident Live Birth Data	
Survival Ratios	15
Historical Enrollment	16
Projected Enrollment	17
Conclusion	22

#### **ACKNOWLEDGMENTS**

On behalf of Cooperative Strategies, we would like to extend our appreciation to the Three Rivers School District for the opportunity to assist them in developing this Enrollment Projections Report. As a planning team, we hope that this document will serve the Three Rivers School District for years to come.

#### **COOPERATIVE STRATEGIES**

Ann Hoffsis, REFP, Senior Director Galina Kostiv, Senior Associate

> 3325 Hilliard Rome Road Hilliard, OH 43026

> > P. 614.798.8828

www.coopstrategies.com

#### **EXECUTIVE SUMMARY**

The enrollment projections for the Three Rivers School District included in this report were developed using the cohort survival methodology and Cooperative Strategies' custom enrollment projection software, S.T.E.P. [Student Trends & Enrollment Projections]. This custom software was developed in collaboration with The Ohio State University and is based on industry best practices as well as the national experience Cooperative Strategies has with schools, school districts, and state agencies.




The Three Rivers School District is a school district 4,412 students in Josephine County and Jackson County in the 2018-19 school year.

The projections presented in this report are meant to serve as a planning tool for the future, and represent the most likely direction of the District. Enrollment projections were developed using the cohort survival methodology and by analyzing the following data outlined in this report:

- Live birth data
- Historical enrollment by grade

- Census data
- Building permits

Enrollment in the Three Rivers School District has decreased by 719 students since the 2009-10 school year. Based on the cohort survival methodology, enrollment is projected to increase slightly over the next ten years.




THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

As with any projection, the District should pay close attention to the variables associated with determining enrollment projections discussed in this document. Any one or more of these factors can increase or decrease enrollment within the Three Rivers School District. It is recommended that the data contained in this report be reviewed on an annual basis to determine how more recent trends will impact both the enrollment and any new housing development.							


#### **ENROLLMENT PROJECTION METHODOLOGY**

#### Introduction

Tracing the landscape of the country's public school enrollment back over the past fifty years reveals demographic, economic, and social changes. The United States as a whole continues to undergo major shifts in public student enrollment, due in large part to past events including the baby boom, the availability and use of birth control, and the development of suburbs. The baby boom of the late 1940s and 50s was followed by the baby bust of the 1960s and 70s. This gave rise to the echo baby boom of the 1980s.



U.S. POPULATION - LIVE BIRTH RATE PER 1,000 POPULATION



Source: CDC, National Vital Statistics Report

Nationwide, districts have experienced the effects of the echo baby bust of the 1990s. From the 1950s to the 1970s, a dramatic downsizing of the family unit occurred. A direct result was the declining school enrollment of the 1970s and 1980s. As of the 2010 Census, the size of a family was at an all-time low of 3.14 persons. The live birth rate increased for the first time in several years in 1998 and increased again in 2000. However, the birth rate resumed a descending pattern in 2001 and reached an all-time low of 12.4 (per 1,000) in 2015.

When projecting future enrollments, it is vital to track the number of live births, the amount of new housing activity, and the change in household composition. In addition, any of the following factors could cause a significant change in projected student enrollment:

- Boundary adjustments
- New school openings
- Changes / additions in program offerings
- Preschool programs
- Change in grade configuration
- Interest rates / unemployment shifts
- Intra- and inter-district transfer

- Magnet / charter / private school opening or closure
- Zoning changes
- Unplanned new housing activity
- Planned, but not built, housing
- School voucher programs
- School closures

Obviously, certain factors can be gauged and planned for far better than others. For instance, it may be relatively straightforward to gather housing data from local builders regarding the total number of lots in a planned subdivision and calculate the potential student yield. However, planning for changes in the unemployment rate, and how these may either boost or reduce public school enrollment, proves more difficult. In any case, it is essential to gather a wide variety of information in preparation for producing enrollment projections.


When looking ahead at a school district's enrollment over the next two, five, or ten years, it is helpful to approach the process from a global perspective. For example: How many new homes have been constructed each year? How many births have occurred each year in relation to the resident population? Is housing experiencing a turnover—if so, what is the composition of families moving in/out? Are more or less students attending private school or being home-schooled? What has the unemployment rate trend been over the past ten years? What new educational policies are in place that could affect student enrollment figures?

The cohort survival methodology is often used to answer these questions and is standard throughout the educational planning industry. The enrollment projections developed for the Three Rivers School District were developed using the cohort survival method.

#### **Cohort Survival Method**

The cohort survival methodology (sometimes referred to as the grade progression ratio method) is a widely used enrollment projection model that is used by many school districts and state and federal agencies to project K-12 enrollment.

A cohort is a group of persons [in this case, students]. The cohort survival enrollment projection methodology uses historic live birth data and historic student enrollment to "age" a known population or cohort throughout the school grades. For instance, a cohort begins when a group of kindergarteners enrolls in grade K and moves to first grade the following year, second grade the next year, and so on.



A "survival ratio" is developed to track how this group of students increased or decreased in number as they moved through the grade levels. By developing survival ratios for each grade transition [i.e. 2nd to 3rd grade] over a ten year period of time, patterns emerge. A projection ratio for each grade transition is developed based on analysis of the survival ratios. The projections are used as a multiplier in determining future enrollment.

For example, if student enrollment has consistently increased from the 8th to the 9th grade over the past ten years, the survival ratio would be greater than 100% and could be multiplied by the current 8th grade to develop a projection for next year's 9th grade. This methodology can be carried through to develop ten years of projection figures. Because there is not a grade cohort to follow for students coming into kindergarten, resident live birth counts are used to develop a birth-to-kindergarten survival ratio. Babies born five years previous to the kindergarten class are compared in number, and a ratio can be developed to project future kindergarten enrollments.

The cohort survival method is useful in areas where population is stable [relatively flat, growing steadily, or declining steadily], and where there have been no significant fluctuations in enrollment, births, and housing patterns from year to year. The cohort survival methodology inherently considers the net effects of factors such as migration, housing, dropouts, transfers to and from charter schools, open enrollment, and deaths. This methodology does not assume changes in policies, program offerings, or future changes in housing and migration patterns.

#### **U.S. CENSUS**

According to the U.S. Census Bureau, the population in Josephine County increased from 75,726 to 82,713, or approximately 9 percent, between the 2000 and 2010 Census.

In terms of school-aged children [5 -19], the population decreased by 626, or approximately 4 percent. The under age 5 population increased from 4,035 to 4,198, or approximately 4 percent.

The median age of a Josephine County resident is 47.3, an increase of 4.2 years since the 2000 Census.

The average household size decreased from 2.41 to 2.34. The average family size decreased from 2.85 to 2.82.

The number of total housing units increased in tandem with the number of occupied and vacant housing units.

The table to the right provides a comparison of the 2000 and 2010 U.S. Census data.

#### JOSEPHINE COUNTY, OREGON U.S. CENSUS

Subject	2000	2010
Total population	75,726	82,713
SEX AND AGE		
Male	36,813	40,240
Female	38,913	42,473
Under 5 years	4,035	4,198
5 to 19 years	15,179	14,553
20 to 64 years	41,275	45,524
65 years and over	15,237	18,438
Median age (years)	43.1	47.3
RACE		
One Race	97.3%	96.8%
White	93.9%	92.4%
Black or African American	0.3%	0.4%
American Indian and Alaska Native	1.3%	1.4%
Asian	0.6%	0.8%
Native Hawaiian and Other Pacific Islander	0.1%	0.2%
Some Other Race	1.2%	1.5%
Two or More Races	2.7%	3.2%
Hispanic or Latino	4.3%	6.3%
DEMOGRAPHICS		
Average household size	2.41	2.34
Average family size	2.85	2.82
HOUSING OCCUPANCY		
Total housing units	33,239	38,001
Occupied housing units	31,000	34,646
Vacant housing units	2,239	3,355

Source: U.S. Census

#### **GENERAL DEMOGRAPHICS**

The following information represents block group estimates and projections created from market research and U.S. Census data obtained from the Environmental Systems Research Institute [ESRI]. ESRI provides a yearly update to their demographic data in increments of five years. To make updates to their demographic data set, they use American Community Survey [ACS] data that takes a series of monthly sample surveys but only from areas with populations of 65,000 or more. One year of ACS data is a period estimate as a twelve-month average, rather than a single point in time.


According to the ESRI estimates, the total population of Josephine county, Oregon is projected to increase over the next five years. As illustrated in the table below, the number of children, ages 5-18, is projected to increase by 233 children.

JOSEPHINE COUNTY
POPULATION ESTIMATES

Age	2018	2023		
Ages 0-2	2,515	2,603		
Ages 3-4	1,682	1,741		
Ages 5-10	5,255	5,405		
Ages 11-13	2,729	2,799		
Ages 14-18	4,832	4,845		
Ages 5-18	12,816	13,049		
Total Population	88,468	92,845		

Source: ESRI BIS

## JOSEPHINE COUNTY POPULATION ESTIMATES




THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

# THREE RIVERS SCHOOL DISTRICT ESTIMATED SCHOOL AGE POPULATION CHANGE 2018-2023

The map on the following page shows school age population change in the U.S. Census block groups within / around the Three Rivers School District boundary. Population changes are based on 2018 and 2023 estimates.

A block group is defined by the U.S. Census Bureau as, "a statistical division of a census tract, generally defined to contain between 600 and 3,000 people and 240 and 1,200 housing units, and the smallest geographic unit for which the Census Bureau tabulates sample data."



THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

#### **HOUSING DATA**


Housing development and building permits are tracked to determine their effect on student enrollment. The tables below illustrates the number of single- and multi-family building permits issued in Josephine County since 2000.

BUILDING PERMITS
Josephine County

y i i i i								
Year	Single-Family	Multi-Family						
2000	367	57						
2001	396	15						
2002	407	113						
2003	495	129						
2004	635	125						
2005	722	127						
2006	543	84						
2007	385	32						
2008	180	9						
2009	103	2						
2010	94	12						
2011	68	2						
2012	79	2						
2013	130	2						
2014	145	4						
2015	173	64						
2016	209	4						
2017	228	22						
2018*	0	0						

Source: SOCDS Building Permits Database

BUILDING PERMITS JOSEPHINE COUNTY



<sup>\*</sup>preliminary through June 2018

#### RESIDENT LIVE BIRTH DATA

Utilization of resident live birth data is recommended when projecting future kindergarten enrollments. This data provides a helpful overall trend. Large bubbles in birth counts, either up or down, can also be planned for or anticipated by the District.

In addition, the live birth counts are used in determining a birth-to-kindergarten and birth-to-first grade survival ratio. This ratio identifies the percentage of children born in a representative area who attend kindergarten and first grade in the District five and six years later. The survival ratios for birth-to-kindergarten, birth-to-first grade, as well as grades 1-12 can be found on page 16 of this report.

Data is arranged by the residence of the mother. For example, if a mother lives in Portland but delivers her baby in Salem, the birth is counted in Portland. Live birth counts are different from live birth rates. The live birth count is simply the actual number of live births. A birth rate is the number of births per 1,000 women in a specified population group.

The table and graph include the resident live birth counts for zip codes 97497, 97523, 97526, 97527, 97530, 97531, 97532, 97533, 97534, 97538, 97543, and 97544.




#### RESIDENT LIVE BIRTH COUNTS THREE RIVERS SCHOOL DISTRICT ZIP CODES

Year	97497	97523	97526	97527	97530	97531	97532	97533	97534	97538	97543	97544
2003	10	66	349	296	39	7	21	2	5	17	7	17
2004	16	51	347	308	49	7	19	2	4	15	6	18
2005	18	42	328	313	56	6	25	1	5	19	10	22
2006	14	60	385	325	52	8	21	1	7	20	8	22
2007	11	54	362	343	53	6	14	0	10	17	3	31
2008	11	71	394	347	50	6	20	0	7	19	8	22
2009	13	52	345	299	42	6	17	0	9	26	6	22
2010	14	63	345	311	46	4	14	2	6	18	3	18
2011	15	69	324	308	49	9	13	0	4	10	3	22
2012	10	63	336	316	43	13	18	0	4	26	12	27
2013	12	70	354	340	44	7	17	1	9	23	10	11
2014	5	58	379	365	55	12	22	0	4	11	2	21
2015	18	61	381	327	58	9	21	1	3	22	4	19
2016	14	63	338	385	56	6	24	0	4	16	9	22

Source: Oregon Health Authority

THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT



THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

### **SURVIVAL RATIOS**

The chart below demonstrates the ten-year changes in enrollment as students move through the system. Percentages greater than 100 indicate that there are more students than there were in the previous grade the previous year. In other words, there was an increase in student population where new students were added to the system. Percentages less than 100 indicate that there was decline or students left the system. If the exact number of students in 1st grade during the 2010-11 school year were present in 2nd grade for the 2011-12 school year, the survival ratio would be 100 percent.

Birth-to-Kindergarten and Birth-to-First Grade: This ratio indicates the number of children born in the area who attend kindergarten and first grade in the District five and six years later. What is important to note is the trend in survival ratios, not necessarily the actual number.

The following table illustrates the historical survival ratios in the Three Rivers School District over the past ten years by grade level.

Survival	Ratios	<ul> <li>District-wide</li> </ul>

from	to	Birth to K	K to 1	Birth to 1	1 to 2	2 to 3	3 to 4	4 to 5	5 to 6	6 to 7	7 to 8	8 to 9	9 to 10	10 to 11	11 to 12
2009	2010	35.03%	102.92%	37.65%	104.44%	101.44%	99.13%	101.97%	98.10%	100.27%	100.49%	101.17%	97.89%	93.36%	105.18%
2010	2011	31.09%	104.73%	36.69%	103.47%	101.22%	101.42%	103.53%	99.72%	100.97%	102.70%	103.41%	97.92%	95.68%	100.00%
2011	2012	38.16%	107.67%	33.48%	100.97%	104.57%	99.70%	100.84%	102.84%	99.72%	97.61%	110.00%	98.12%	89.60%	107.27%
2012	2013	34.45%	102.32%	39.05%	105.50%	101.28%	101.17%	97.59%	102.50%	101.38%	100.28%	107.11%	99.04%	96.40%	98.94%
2013	2014	34.17%	99.70%	34.35%	99.72%	97.85%	97.79%	100.58%	93.52%	96.75%	98.64%	103.60%	97.94%	100.00%	102.74%
2014	2015	32.82%	107.69%	36.80%	100.30%	101.99%	107.84%	98.71%	102.87%	101.98%	104.76%	102.76%	95.19%	90.65%	100.48%
2015	2016	35.59%	112.64%	36.97%	104.55%	102.43%	104.46%	103.78%	110.78%	102.23%	106.47%	103.21%	98.39%	98.03%	98.20%
2016	2017	35.02%	108.16%	38.50%	99.04%	105.90%	106.82%	108.27%	104.76%	100.59%	101.36%	103.34%	98.96%	92.35%	100.86%
2017	2018	37.42%	97.70%	34.22%	97.48%	101.94%	99.71%	98.61%	98.28%	95.72%	97.36%	102.42%	98.53%	89.53%	92.31%
mean simple a	ll years	34.86%	104.84%	36.41%	101.72%	102.07%	102.00%	101.54%	101.49%	99.96%	101.07%	104.11%	98.00%	93.96%	100.66%
std. dev. simpl	le all years	2.15%	4.68%	1.97%	2.84%	2.25%	3.55%	3.32%	4.88%	2.27%	3.13%	2.72%	1.14%	3.78%	4.30%
mean simple 5	years	35.00%	105.18%	36.17%	100.22%	102.02%	103.32%	101.99%	102.04%	99.45%	101.72%	103.07%	97.80%	94.11%	98.92%
std. dev. simpl	le 5 years	1.71%	6.26%	1.84%	2.64%	2.85%	4.40%	4.09%	6.54%	3.03%	3.89%	0.47%	1.51%	4.64%	4.03%
mean simple 3	years	36.01%	106.17%	36.56%	100.36%	103.42%	103.66%	103.55%	104.61%	99.51%	101.73%	102.99%	98.63%	93.30%	97.12%
std. dev. simpl	le 3 years	1.25%	7.67%	2.17%	3.71%	2.16%	3.62%	4.83%	6.26%	3.38%	4.57%	0.50%	0.30%	4.33%	4.38%
mean simple 2	years	36.22%	102.93%	36.36%	98.26%	103.92%	103.27%	103.44%	101.52%	98.16%	99.36%	102.88%	98.75%	90.94%	96.58%
std. dev. simpl	le 2 years	1.69%	7.40%	3.03%	1.10%	2.80%	5.03%	6.83%	4.59%	3.44%	2.83%	0.65%	0.31%	1.99%	6.05%
mean weighte	d all years	35.58%	104.33%	36.20%	100.14%	102.64%	102.84%	101.90%	102.17%	99.15%	100.85%	103.36%	98.20%	92.88%	97.96%
std. dev. weigl	hted all years	1.80%	5.94%	1.99%	2.91%	2.26%	3.72%	4.15%	5.16%	2.87%	3.56%	1.72%	1.15%	3.84%	4.56%
mean weighte	d 5 years	36.24%	102.80%	35.79%	98.95%	102.90%	102.51%	101.76%	101.58%	98.14%	99.94%	102.80%	98.42%	91.62%	95.95%
std. dev. weigl	hted 5 years	1.56%	6.59%	2.09%	2.52%	2.11%	3.82%	4.64%	5.07%	3.08%	3.65%	0.49%	0.93%	3.43%	4.52%
mean weighte	d 3 years	36.92%	100.12%	35.08%	98.03%	102.66%	101.14%	100.51%	99.91%	96.83%	98.42%	102.61%	98.60%	90.36%	94.04%
std. dev. weigl	hted 3 years	1.16%	5.76%	2.04%	1.77%	1.84%	3.40%	4.55%	4.04%	2.62%	2.72%	0.45%	0.21%	2.31%	4.10%
mean weighte	d 2 years	37.30%	98.20%	34.42%	97.56%	102.13%	100.05%	99.07%	98.58%	95.95%	97.55%	102.46%	98.55%	89.66%	92.71%
std. dev. weigl	hted 2 years	0.72%	3.15%	1.29%	0.47%	1.19%	2.14%	2.91%	1.95%	1.47%	1.21%	0.28%	0.13%	0.85%	2.58%

# THREE RIVERS SCHOOL DISTRICT HISTORICAL ENROLLMENT

As indicated in the table below, over the past ten years, enrollment in the Three Rivers School District has decreased by 719 students.

Historical Enrollment - District-wide

Grade	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19
K	308	296	287	345	329	286	277	294	304	336
1	315	317	310	309	353	328	308	312	318	297
2	347	329	328	313	326	352	329	322	309	310
3	343	352	333	343	317	319	359	337	341	315
4	355	340	357	332	347	310	344	375	360	340
5	422	362	352	360	324	349	306	357	406	355
6	369	414	361	362	369	303	359	339	374	399
7	409	370	418	360	367	357	309	367	341	358
8	427	411	380	408	361	362	374	329	372	332
9	426	432	425	418	437	374	372	386	340	381
10	452	417	423	417	414	428	356	366	382	335
11	463	422	399	379	402	414	388	349	338	342
12	495	487	422	428	375	413	416	381	352	312
Grand Total	5,131	4,949	4,795	4,774	4,721	4,595	4,497	4,514	4,537	4,412


Source: Three Rivers School District

#### Historical Enrollment - District-wide

Grade	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19
K - 5	2,090	1,996	1,967	2,002	1,996	1,944	1,923	1,997	2,038	1,953
6 - 8	1,205	1,195	1,159	1,130	1,097	1,022	1,042	1,035	1,087	1,089
9 - 12	1,836	1,758	1,669	1,642	1,628	1,629	1,532	1,482	1,412	1,370
Grand Total	5,131	4,949	4,795	4,774	4,721	4,595	4,497	4,514	4,537	4,412

Source: Three Rivers School District

### HISTORICAL ENROLLMENT-DISTRICT-WIDE




THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

### PROJECTED ENROLLMENT

Cooperative Strategies developed low, moderate, high, and recommended enrollment projections for the Three Rivers School District. The moderate enrollment projections are based on a selected average or weighted average of survival ratios (in this case, a 3-year weighted average). The low and high enrollment projections are developed using statistical distributional theory, providing the District with a more conservative (low) and more liberal (high) enrollment projection. The recommended enrollment projection is based on a detailed analysis of historical enrollment and resulting survival ratios over the past 10 years. Significant shifts in survival ratio patterns are realized and accounted for in determining projection ratios independently for each grade level. The recommended illustrates the most likely direction of the District based on more recent trends.

The range of enrollment projections from low (conservative) to high (liberal) are offered due to the limitations of the cohort survival method in factoring changes to policies, program offerings, and future changes in housing and migration patterns. For example, the low enrollment projection might be used if housing declines significantly more than anticipated; the high enrollment projection might be used if housing growth increases at a more rapid rate than seen in recent years.

It should be noted that actual live birth counts are available through 2016 and project kindergarten enrollment through 2021-22. To project kindergarten through 2028-29, a weighted average of the last 5 years of live birth counts was used.



# THREE RIVERS SCHOOL DISTRICT PROJECTED ENROLLMENT—RECOMMENDED

Based on the recommended projected enrollment, the student enrollment in the Three Rivers School District is projected to increase from 4,412 in 2018-19 to 4,540 students in 2028-29.

Projected Enrollment - Recommended - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K	332	329	333	330	331	331	331	331	331	331
1	351	347	343	348	345	345	345	346	345	345
2	294	347	343	339	344	341	342	342	342	342
3	317	300	354	350	347	351	348	349	349	349
4	323	325	308	363	359	355	360	357	358	358
5	346	329	330	313	370	365	362	367	363	364
6	361	351	334	335	318	375	371	367	372	369
7	396	358	348	331	333	315	372	368	364	369
8	361	399	361	351	334	335	318	375	371	367
9	341	370	409	370	361	342	344	326	385	381
10	376	336	365	404	365	356	338	339	322	380
11	303	339	304	330	365	330	321	305	307	291
12	328	290	326	291	317	350	316	308	293	294
<b>Grand Total</b>	4,429	4,420	4,458	4,455	4,489	4,491	4,468	4,480	4,502	4,540


Source: Cooperative Strategies

### Projected Enrollment - Recommended - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K - 5	1,963	1,977	2,011	2,043	2,096	2,088	2,088	2,092	2,088	2,089
6 - 8	1,118	1,108	1,043	1,017	985	1,025	1,061	1,110	1,107	1,105
9 - 12	1,348	1,335	1,404	1,395	1,408	1,378	1,319	1,278	1,307	1,346
Grand Total	4,429	4,420	4,458	4,455	4,489	4,491	4,468	4,480	4,502	4,540

Source: Cooperative Strategies

### PROJECTED ENROLLMENT - RECOMMENDED - DISTRICT-WIDE



THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

# THREE RIVERS SCHOOL DISTRICT PROJECTED ENROLLMENT—MODERATE

Based on the moderate projected enrollment, the student enrollment in the Three Rivers School District is projected to decrease from 4,412 in 2018-19 to 4,306 students in 2028-29.

Projected Enrollment - Moderate - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K	345	341	346	343	344	344	344	344	344	344
1	336	345	342	346	343	344	344	344	344	344
2	291	330	338	335	340	336	337	337	337	337
3	318	299	339	347	344	349	345	346	346	346
4	319	322	302	342	351	348	353	349	350	350
5	342	320	324	304	344	353	349	354	351	352
6	355	341	320	323	304	344	353	349	354	351
7	386	343	331	310	313	294	333	342	338	343
8	352	380	338	325	305	308	289	328	336	333
9	341	362	390	347	334	313	316	297	336	345
10	376	336	356	385	342	329	308	312	293	332
11	303	339	304	322	348	309	297	279	282	264
12	322	285	319	285	303	327	291	280	262	265
Grand Total	4,386	4,343	4,349	4,314	4,315	4,298	4,259	4,261	4,273	4,306


Source: Cooperative Strategies

#### Projected Enrollment - Moderate - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K - 5	1,951	1,957	1,991	2,017	2,066	2,074	2,072	2,074	2,072	2,073
6 - 8	1,093	1,064	989	958	922	946	975	1,019	1,028	1,027
9 - 12	1,342	1,322	1,369	1,339	1,327	1,278	1,212	1,168	1,173	1,206
Grand Total	4,386	4,343	4,349	4,314	4,315	4,298	4,259	4,261	4,273	4,306

Source: Cooperative Strategies

### PROJECTED ENROLLMENT - MODERATE - DISTRICT-WIDE



THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

# THREE RIVERS SCHOOL DISTRICT PROJECTED ENROLLMENT—LOW

Based on the low projected enrollment, the student enrollment in the Three Rivers School District is projected to decrease from 4,412 in 2018-19 to 3,938 students in 2028-29.

Projected Enrollment - Low - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K	340	336	341	338	339	339	339	339	339	339
1	328	332	328	333	330	330	330	330	330	330
2	289	319	322	319	323	321	321	321	321	321
3	316	294	324	328	325	329	326	327	327	327
4	314	314	293	323	327	324	328	325	326	326
5	335	309	310	288	318	322	319	323	320	321
6	348	328	303	304	283	312	316	312	317	314
7	382	333	314	290	290	271	299	302	299	303
8	348	371	324	305	282	282	263	290	294	291
9	340	356	380	332	313	289	289	269	297	301
10	375	335	351	374	327	308	284	285	265	293
11	299	335	299	314	334	292	275	254	254	237
12	315	276	309	276	289	308	269	254	234	235
Grand Total	4,329	4,238	4,198	4,124	4,080	4,027	3,958	3,931	3,923	3,938


Source: Cooperative Strategies

### Projected Enrollment - Low - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K - 5	1,922	1,904	1,918	1,929	1,962	1,965	1,963	1,965	1,963	1,964
6 - 8	1,078	1,032	941	899	855	865	878	904	910	908
9 - 12	1,329	1,302	1,339	1,296	1,263	1,197	1,117	1,062	1,050	1,066
Grand Total	4,329	4,238	4,198	4,124	4,080	4,027	3,958	3,931	3,923	3,938

Source: Cooperative Strategies

### PROJECTED ENROLLMENT - LOW - DISTRICT-WIDE



THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

PAGE A20 11/14/2018

# THREE RIVERS SCHOOL DISTRICT PROJECTED ENROLLMENT—HIGH

Based on the high projected enrollment, the student enrollment in the Three Rivers School District is projected to increase from 4,412 in 2018-19 to 4,710 students in 2028-29.

Projected Enrollment - High - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K	350	346	351	348	349	349	349	349	349	349
1	345	359	355	360	357	358	358	358	358	358
2	294	341	355	351	356	353	354	354	354	354
3	321	304	353	367	363	369	365	366	366	366
4	323	329	312	362	377	373	378	375	376	376
5	349	332	338	320	372	387	383	388	385	386
6	361	355	337	344	325	378	394	389	395	391
7	391	354	348	331	337	319	371	386	382	387
8	357	390	353	346	330	336	318	369	384	380
9	341	367	401	363	356	339	345	327	380	395
10	376	337	362	395	358	352	334	341	322	375
11	306	344	308	331	361	327	321	306	311	295
12	328	294	330	295	317	347	314	308	293	298
Grand Total	4,442	4,452	4,503	4,513	4,558	4,587	4,584	4,616	4,655	4,710


Source: Cooperative Strategies

### Projected Enrollment - High - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K - 5	1,982	2,011	2,064	2,108	2,174	2,189	2,187	2,190	2,188	2,189
6 - 8	1,109	1,099	1,038	1,021	992	1,033	1,083	1,144	1,161	1,158
9 - 12	1,351	1,342	1,401	1,384	1,392	1,365	1,314	1,282	1,306	1,363
Grand Total	4,442	4,452	4,503	4,513	4,558	4,587	4,584	4,616	4,655	4,710

Source: Cooperative Strategies

### PROJECTED ENROLLMENT - HIGH - DISTRICT-WIDE



THREE RIVERS SCHOOL DISTRICT ENROLLMENT PROJECTIONS REPORT

### **CONCLUSION**

As with any projection, the District should pay close attention to live birth counts, enrollment in elementary school, open enrollment/transfers, non-public enrollment, in / out migration patterns, and any housing growth. It is recommended that this document be reviewed on an annual basis to determine how more recent growth and enrollment trends will impact the enrollment projections.

Cooperative Strategies is pleased to have had the opportunity to provide the District with enrollment projection services. We hope this document will provide the necessary information to make informed decisions about the future of the Three Rivers School District.



# Appendix B Survey Report and Other Responses





### **EXECUTIVE SUMMARY**



Three Rivers School District hosted a web survey as a part of its 2019 Facilities Master Planning process from September 18th – October 1st, 2019. A total of 403 community members responded to the survey. Respondents expressed support for facility repairs to improve the physical condition of the building, move classrooms out of portables and into permanent facilities, and improve specialized spaces such as STEM/STEAM and Computer and Technology spaces. Improving physical building condition and renovating existing facilities, such as air conditioning and repairing roofs, were identified as being the most important areas of investment for majority of respondents. Security was another area of improvement recognized by most respondents, with the ability to simultaneously lock all exterior doors electronically and a security officer on campus being most notable.






Which of the following space types do you believe the District should prioritize when renovating current classrooms and other learning environments? (e.g. Improving what we have now) Please select the top 5 that you think are the most

important.


ANSWER CHOICES	RESPON	ISES
Art classroom(s)	22.58%	91
Athletic / recreation facilities (stadiums, ball fields, soccer fields, track, etc.)	29.28%	118
Auditorium(s)	7.94%	32
Cafeteria(s)	17.12%	69
Computer and Technology Labs)	44.17%	178
Conference room(s)	1.24%	5
Elementary school multi-purpose space (cafeteria / gymnasium / stage)	28.54%	115
Food preparation: kitchen	16.63%	67
Gymnasium(s)	13.90%	56
Career Technical Education spaces	32.75%	132
Library / media center(s)	32.26%	130
Office spaces (itinerant space, nurse, clinic, counselors, etc.)	13.15%	53
Band / choir	20.84%	84
Science labs	30.52%	123
Auxiliary gymnasiums (secondary practice, non-competition - typically few or no bleachers)	6.70%	27
Outdoor covered areas	23.33%	94
STEM/STEAM Classrooms (science, technology, engineering, math)	49.88%	201
Student Health Center	10.17%	41
Other (please specify)	17.37%	70
Total Respondents: 403		







What are three (3) most pressing issues that you believe the District should consider when making a comprehensive maintenance plan to improve the current condition of existing facilities? Please select only 3.




ANSWER CHOICES	RESPON	ISES
Renovating the schools to improve the condition of existing facilities(eg. roofs, foundations, flooring, etc.)	73.20%	295
Improving or modifying schools to better support current learning approaches and future career opportunities	54.34%	219
Improve physical building conditions (e.g. air conditioning, lighting, aesthetics)	76.43%	308
Adding and/or improving access to specialized programs (e.g. fine arts, STEM, theater, CTE, etc.)	42.93%	173
Addressing over-utilized facilities	19.11%	77
Other (please specify)	7.20%	29
Total Respondents: 403		





How important is it to you to move classrooms out of portable buildings and place them in permanent facilities?




ANSWER CHOICES	RESPONSES	
Very Important	26.30%	106
Important	21.59%	87
No Opinion	24.07%	97
Not Important	20.60%	83
Not at all Important	7.44%	30
TOTAL		403





### Rank the following in order of importance.




	1	2	3	4	TOTAL	SCORE
Renovate and/or newly construct multipurpose rooms, gyms, conference rooms, playground, auditorium	17.95% 70	30.77% 120	32.56% 127	18.72% 73	390	2.48
Renovate existing permanent buildings	50.51% 199	30.20% 119	13.96% 55	5.33% 21	394	3.26
Replace portables with permanent construction	14.36% 56	14.36% 56	21.79% 85	49.49% 193	390	1.94
Upgrade / expand instructional technology such as computer hardware and network infrastructure (servers, cabling, switches, etc.)	18.18% 72	24.75% 98	31.57% 125	25.51% 101	396	2.36





# Which of the following safety & security measures should be put in place at all facilities? Please select only 3.




ANSWER CHOICES	RESPONSES	
Ability to simultaneously lock all exterior doors electronically	57.07%	230
Alarm system	20.10%	81
Entry vestibule at main school entry	24.32%	98
Key card entry / access	16.87%	68
Security cameras throughout the facility	58.06%	234
Security officer on campus	58.31%	235
Perimeter security fencing	24.81%	100
Increased lighting / visibility	21.84%	88
Other (please specify)	3.72%	15
Total Respondents: 403		





Under what conditions would you support rebuilding a school versus repairing it? Check all that apply.




ANSWER CHOICES	RESPONSES	
Repair would cost 50% or greater of new construction	72.18%	288
It would allow for a greater educational experience	48.62%	194
Other (please specify)	12.28%	49
Total Respondents: 399		





# Your Age:




ANSWER CHOICES	RESPONSES
Under 18	0.50% 2
18-24	0.76% 3
25-34	17.38% 69
35-44	33.00% 131
45-54	28.72% 114
55-64	15.11% 60
65+	4.53% 18
TOTAL	397





### **Education:**




ANSWER CHOICES	RESPONSES	
Current student	0.50%	2
Not a high school graduate	0.76%	3
High school graduate / GED	13.10%	52
Some college / trade school	31.74%	126
College graduate	25.19%	100
Advanced degree	28.72%	114
TOTAL		397





### Parental / Guardian / Student Status (check all that apply)




ANSWER CHOICES	RESPONSES	
Do not have children in the district	23.47%	92
Parent / guardian of a preschool child	6.63%	26
Parent / guardian of an elementary school student	34.69%	136
Parent / guardian of a middle school student	26.02%	102
Parent / guardian of a high school student	28.32%	111
Parent / guardian of a private / parochial student	0.77%	3
Parent / guardian of a former student or graduate of the District	18.11%	71
Grandparent of a current student or graduate	7.14%	28
Current student	2.04%	8
Total Respondents: 392		





### How many years have you lived in the District?




ANSWER CHOICES	RESPONSES	
Less than 2	5.78%	23
2-5	13.82%	55
6-10	13.07%	52
11-15	14.07%	56
16-20	10.55%	42
More than 20	35.43%	141
Not applicable	7.29%	29
TOTAL		398





### Are you an employee or retiree of the District?




ANSWER CHOICES	RESPONSES	
Yes	48.74%	194
No	51.26%	204
TOTAL		398





### Which school(s) are you affiliated with? (check all that apply)

ANSWER CHOICES	RESPONSES	
All	3.02%	12
Applegate ES	3.02%	12
Evergreen ES	13.35%	53
Fruitdale ES	10.33%	41
Fort Vannoy ES	13.10%	52
Madrona ES	11.08%	44
Manzanita ES	13.60%	54
Williams ES	3.02%	12
Fleming MS	22.17%	88
Lincoln Savage MS	16.88%	67
Lorna Byrne MS	10.83%	43
Hidden Valley HS	22.67%	90
Illinois Valley HS	11.59%	46
New Bridge HS	1.01%	4
North Valley HS	21.16%	84
Merlin Alternative Center	2.52%	10
Sunny Wolf Charter	1.51%	6
Transition Center	2.27%	9
Woodland Charter School	2.02%	8
None	0.50%	2
Other	1.51%	6
Total Respondents: 397		



### **Survey Open-Ended Responses**

### **Question 1: Priorities**

- Bathrooms
- Air conditioning
- Heating and Air conditioning in classrooms
- Updated training for ALL regarding No
   Child Left Behind!! Kids not identified or
   referred for testing. No information
   when requested. No council that oversees
   this behavior . punishment and downgrading instead of IEP/ spec. Ed refer.
   Regardless of excessive medical records,
   meds, years of proff. How it was handled
   was horrible! ...
- Any classroom, in order of which needs the most repair first. After classrooms are finished move through the remainder of the building/property according to which places need the most attention first.
- Exterior Doors
- Classrooms
- Outdoor garden space
- Wood/metal shops

- STUDENT BATHROOMS!
- Depends on what specific upgrades in each of theses areas being proposed.
- wages for bus drivers need to be competative with over district. We loss good drivers because of wages.
- general classrooms, all subjects
- New Elementary buildings
- no portables...add on to schools
- Air conditioning
- Air conditioning throughout schools
- Classrooms
- Single occupancy restrooms and changing facilities
- PE
- Life skills classrooms
- Elementary Classrooms
- Bring music back to elementary
- The grounds! They are in terrible shape.
   Many have weeds and star thistle and look run down and shabby. Prospective parents looking for schools wold proba-

- bly not think too highly by looking on the outside.
- Classrooms that the kids spend most of their time in
- Air conditioning in classrooms
- Regular classrooms
- Playgrounds
- General classrooms
- Removing Portables and adding additional Wings
- Bathrooms
- Fence and gate around bathroom area by cafeteria.
- Classrooms
- Regular classrooms
- Security of Evergreen Elementary
- classrooms
- AC in classrooms
- Teach cursive writing
- Special Education departments (resource and life skills)



- Alternative education facilities with with insufficient restroom facilities and kitchens.
- Air conditioning
- School-wide updates, such as the floors, roof, electrical, HVAC, etc.
- paint outside and inside
- Entire building -- parts of our building flood every winter, sewage issues, windows are not double pane
- Career Training in all kinds of Trades
- Front offices should have the ability to lock the front doors without being put in the line of fire. A buzzer system (like a jewelry stores) with an override to keep kids in and others out.
- we need to address facilities maintenance. Most school need roof work. what good is school if you dont have a building
- Core classes. It's important that students are focused in these rooms to maximize learning; creating a calm and inviting environment is a huge part of that. Stained

- roof tiles and particle board walls (with no windows or AC) do not make for the best learning environment.
- All areas with asbestos!
- Air conditioning/ceiling fans in classrooms, cafeteria, gym
- Multi Handicapped classrooms
- classrooms/ sped rooms
- Add Restroom to IVAC
- Quiet areas for double dose/reading groups
- changing out current old windows throughout.
- classrooms-
- We need a sensory room on each campus
   where kids who have specialneeds can
   descslte with out blowing out and dis ruptuing other students
- All classrooms that lack air conditioning or have inadequate heating systems
- Classrooms: air conditioning & new furniture
- Improving existing classrooms.
- Classrooms on the south side of the building. We cook when it is hot outside.

- Regular classrooms and very old schools like Fort Vannoy that flood every winter.
- Elementary classrooms
- My elementary classroom floor is old asbestos tiles and they need to be replaced with something different. Our outside bathrooms, that are used by the community during schoolwide events are embarrasing even when they are clean(urine stained. smelly). Our classroom walls are dirty, scuffed and need a fresh coat of paint.
- general ed classrooms
- classrooms
- Weight rooms
- Furniture/ air conditioning in all classrooms at Fleming Middle School 1,2
- elementary classrooms that flood each year
- Classrooms



### **Question 2: Pressing Issues**

- unfortunately, to make the schools safer.
   Secured entrances to the school. Especially Evergreen. Someone could walk right off the streets to the front class rooms.
- Adding portable buildings to address overcrowding in Lifeskills! programs
- Teaching staff and teachers, principles..how to know if a child needs an IEP or special help. what \* on meds. \* having constant trouble \*when to refer. Give info to parents refer them for a application. Testing. Make it mandatory not a judgement call. Have a council over look this closely .s
- Making outdoor play viable when it's raining, I don't like hearing that recess is always a movie in the gym when it rains or the outdoor equipment is wet. Please think about investing in indoor items, such as were in schools less than twenty years ago.
- Exterior doors so we may lock them for the safety of our students and staff.
- safety and security upgrades

- Adding bathrooms to portables so students don't have to walk inside the school during class
- better wages for bus driverss
- Save monies and build new elementary buildings
- Let's try to support new learning opportunities that actually engage the kids.
   More hands on learning less teaching to testing.
- Special.education classes
- Adding classroom space for students with Special Needs
- Improve the over all asthetics and environment not just computer related job tracking
- Put a perimeter fence up!
- removing portables and building on to school
- Parking lot needs to be re-done. We need new furniture, (desks, chairs, etc)
- Make campus safer!
- Security and updates for Evergreen Elementray
- Improving restroom and water access to

- alternative education facilities.
- Paint on walls and overhaul of aesthetics for first impression. Information/ motivational posters/warm & welcoming spaces
- Make the schools safer for the students and the staff. In the current climate of shootings it should be the districts top priority to enclose buildings that have outside walkways to permit kids to walk from class to class without having to go outside in the cold.
- Air conditioning, new ceiling tiles, and a new gym floor for LSMS
- ENERGY EFFICIENCY/SUSTAINABLE, RENEWABLE OPTIONS!!! OUR YOUTH WILL SUFFER FROM OUR INATTEN-TION TO CLIMATE CRISIS
- removing portables.
- Replacing old and warn out equipment, kitchens are often forgotten
- Safety of school- indoor schools or fencing with one entry



- Go for a bond to build a brand new Fort
  Vannoy and Manzanita. Make improvements at the middle schools and high
  schools. Make sure the roofs do not leak,
  fix the heating and air or add air, replace
  carpets, and take care of all potential
  flooding, asbestos and possible mold
  growth. Make sure the water pipes are
  lead free.
- Built in furniture, closets, book shelving study areas
- Ac, ac, ac!! Art and music in elementary schools



### **Question 5: Safety / Security**

- Teachers should have the options to lock their doors. The entry at the main office should have a weapon scanner, when one is detected the alarm system should be tripped to alert all staff. and confidential security protocol set in motion by all staff members.
- Talk about mental health, maybe even have a mental health day...
- I don't want my students school to feel or look like a prison, very hard to answer this question.
- An alarm system which includes security cameras inside and outside; Alarm should specify threat.
- Police officers
- More secure door locking device in case of intruders.
- All of these options plus metal detectors
- There is a locking mechanisms to lock doors from inside a room in case of a shooting or intruder. Put one in ever room

- A way to immediately notify parents and other TRSD employees that a school is on lock-down (especially employees who travel to different schools).
- mechanism in every teacher's doorway
  that keeps the door from shutting completely while engaged. In this way, all
  doors can stay permanently locked during school hours and can be easily and
  swiftly closed in the event of an emergency.
- Ways to direct community into the office without being able to access outdoor hallways directly into school hallways.

  Cut down on the access directly to students without having to check in first. It may seem overly "secure" looking, but is terribly important. We have adults walking into hallways without any interaction with staff before doing so. Wandering facilities without supervision with access to students.
- Enclosed/locked interior and exterior hallways with limited public access without signing in through a single entry point
- There is a lock mechanism so classrooms

- can lock intruders out at each classroom door. Add to ALL classrooms. Maybe add a keyless entry pass.
- some of these would be very difficult with the current grounds we have
- The middle schools (Fleming, LS) have two many entrances. Despite being locked with minimal effort anyone could come in the far hallway doors and wreak havoc without the front office knowing for quite sometime.

PAGE B19



### Question 6: Rebuild vs Repair

- Safety is major issue for me in this day in age, if a school needs to be repaired or rebuilt for safety issues, I support that whole heartily. If repairs need to be made such as the leaking roof. I support that as well.
- Whatever is more cost efficient to get the updates our schools desperately need is the way to go.
- It would be a facility for all the kids currently being left behind, punished, not identified, just judged and left with More problems and a substandard education!
- Repair cost 30% or greater of new construction
- If the very foundation needed to be repaired as well as water and mold damage to the structures.
- If other, higher priority items were already being taken care of.
- I would say both of the above answers need to apply as well as there being no possible future expansion to an existing

- structure which would allow for the ideal learning experience.
- Student population is greater than existing facility can support
- Not sure.
- If it burned down due to forrest fire
- No new taxes
- Everything sooner or later has to be able to handle the number of students attending school. To better their education we need a up dated school to handle the kids from class rooms not being crowded more one on one if needed and up dated equipment to help their learning process
- Use monies to build new elementary schools
- The charm of the 2 schools in my community is of greatest value to me.
   (Williams Elementary and Applegate).
- Aspestos
- Location change that would benefit a majority of the students. Environmental health concern The overall expense would pay for itself over time due to constant repair costs.
- School district needs to find a way to

have a maintenance schedule and budget that takes care of their buildings not just have a plan to replace buildings. Buildings should last a lifetime, not just 30 Years.

- Not sure
- if there are buildings that are a danger to children if an earthquake or other natural disaster due to building standards when it was built
- I would say 33% should be the threshold of rebuilding vs repairs.
- This would need to be an ongoing discussion... the current construction of most of the school facilities are of concrete and very permanent, with proper care and implementation of new construction technologies like ductless HVAC, insulation products, and more, I don't see why the majority of current facilities can't be updated at a reasonable cost.
- I would need more information to make a decision
- Flooding, no AC or true heat, bigger for class sizes, new special ed classes in ALL schools



- It would be amazing if rebuilding could be done in a sustainable, future looking way and not just a temporary fix with limited funds that will be outdated and needing constant repairs. Natural lighting and a conscious effort to make the environment peaceful and comfortable for learning to take place should be taken into account.
- The high schools are old and in much need of modernizing and optimizing.
   There is only 5 air conditioned classrooms currently at Hidden Valley
- New construction schools would be able to be built smarter and safer! Three Rivers Schools are not adequate!
- Overcrowded facility.
- Depends on facility
- Evergreen elementary schools campus is unacceptable for elementary aged children. The school needs to be completely torn down and rebuilt with the safety and security of children 5-11 in mind.
   With the current safety concerns of our

- country evergreen would not be able to properly secure the children in the event of a threat. There are way too many open areas that are major safety concerns. Remodeling wouldn't work because of the open layout of the school.
- If kids are sitting in overheated or underheated classrooms and not in comfortable positions. Enough kids come from homes that are that way, they need to come to school and feel comfortable, safe and happy:)
- If it saves any money that can go to supporting education I support repair.
- A safer campus.
- None.
- Safety or health issues like leaking roof, moldy walls, flooding, asbestos, etc.
   Walls crumbling. Many of the elementary buildings are like 60+ years old and need to be rebuilt.
- The ability to provide more vocational programs
- If it is deemed unfixable
- If we had a flood or disaster that collapsed a building it would be best to ren-

- ovate. I feel people get disgusted with what looks like a waste of their tax dollars. Use the same principal you would for a 'home budget'. Needs and Wants should be treated accordingly.
- Rebuild only if air conditioning can be added.
- I'd like to know where the money would come from, and if it'd affect teacher pay or benefits. Also, I'd like to see improvements across the whole district, not just at the high schools. If we can afford new buildings, then great. If not, I'd love to see some repairs happening in my school, as well as other schools.
- If the district received a grant or other outside source of funding to pay for the construction of a new facility.
- Safety...many of the schools have asbestos, no air conditioning, poor heat.
- Not sure
- If you could increase safety by renovating



- Many buildings are old. Newer buildings are more efficient for heating and air as well as safer in design.
- safety and age of building
- It would increase the safety and security of students and staff
- I would support rebuilding now...for as many building we can get. They are all outdated on so many different levels.
   They have been repaired for year upon year.
- The school found it had toxic material that was out of compliance and a safety issue as the buildings are over 58 years old.
- Do it



# **Appendix C Board Presentation**





# AGENDA | MASTER FACILITY PLAN BOARD PRESENTATION

**MASTER FACILITY PLAN: OVERVIEW** 

SCHOOL DISTRICT BACKGROUND DATA

**FACILITY ASSESSMENTS** 

**SUMMARY** 

### DEFINITION | FACILITIES MASTER PLAN



- A 5-10 year plan to prioritize major capital investments towards the goal of supporting the district's educational vision
  - Considers current & desired educational programs
  - Facility condition analysis of all capital assets to identify needs for capital improvements
  - > Operates under the constraints of overall budgets, capacity, and current/projected enrollments

Collect Facility
Data

• Began fall 2018

Engage the community

- Survey fall 2019
- Community Dialogues Oct 15-16

Develop facility options

• November 6, 2019

Board presentation

• November 20,2019



### ENROLLMENT | HISTORIC ENROLLMENT



#### Historical Enrollment - District-wide

Grade	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19
K	308	296	287	345	329	286	277	294	304	336
1	315	317	310	309	353	328	308	312	318	297
2	347	329	328	313	326	352	329	322	309	310
3	343	352	333	343	317	319	359	337	341	315
4	355	340	357	332	347	310	344	375	360	340
5	422	362	352	360	324	349	306	357	406	355
6	369	414	361	362	369	303	359	339	374	399
7	409	370	418	360	367	357	309	367	341	358
8	427	411	380	408	361	362	374	329	372	332
9	426	432	425	418	437	374	372	386	340	381
10	452	417	423	417	414	428	356	366	382	335
11	463	422	399	379	402	414	388	349	338	342
12	495	487	422	428	375	413	416	381	352	312
Grand Total	5,131	4,949	4,795	4,774	4,721	4,595	4,497	4,514	4,537	4,412

Source: Three Rivers School District

#### Historical Enrollment - District-wide

Grade	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19
K-5	2,090	1,996	1,967	2,002	1,996	1,944	1,923	1,997	2,038	1,953
6-8	1,205	1,195	1,159	1,130	1,097	1,022	1,042	1,035	1,087	1,089
9 - 12	1,836	1,758	1,669	1,642	1,628	1,629	1,532	1,482	1,412	1,370
Grand Total	5,131	4,949	4,795	4,774	4,721	4,595	4,497	4,514	4,537	4,412

Source: Three Rivers School District

## ENROLLMENT | PROJECTED RECOMMENDED



#### Projected Enrollment - Recommended - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K	332	329	333	330	331	331	331	331	331	331
1	351	347	343	348	345	345	345	346	345	345
2	294	347	343	339	344	341	342	342	342	342
3	317	300	354	350	347	351	348	349	349	349
4	323	325	308	363	359	355	360	357	358	358
5	346	329	330	313	370	365	362	367	363	364
6	361	351	334	335	318	375	371	367	372	369
7	396	358	348	331	333	315	372	368	364	369
8	361	399	361	351	334	335	318	375	371	367
9	341	370	409	370	361	342	344	326	385	381
10	376	336	365	404	365	356	338	339	322	380
11	303	339	304	330	365	330	321	305	307	291
12	328	290	326	291	317	350	316	308	293	294
Grand Total	4,429	4,420	4,458	4,455	4,489	4,491	4,468	4,480	4,502	4,540

Source: Cooperative Strategies

#### Projected Enrollment - Recommended - District-wide

Grade	2019-20	2020-21	2021-22	2022-23	2023-24	2024-25	2025-26	2026-27	2027-28	2028-29
K-5	1,963	1,977	2,011	2,043	2,096	2,088	2,088	2,092	2,088	2,089
6 - 8	1,118	1,108	1,043	1,017	985	1,025	1,061	1,110	1,107	1,105
9 - 12	1,348	1,335	1,404	1,395	1,408	1,378	1,319	1,278	1,307	1,346
Grand Total	4,429	4,420	4,458	4,455	4,489	4,491	4,468	4,480	4,502	4,540

Source: Cooperative Strategies

#### ONLINE COMMUNITY SURVEY | EXECUTIVE SUMMARY



- Three Rivers School District hosted a web survey as a part of its 2019 Facilities Master Planning process from September 18th October 1st, 2019.
- A total of 403 community members responded to the survey.
- Respondents expressed support for facility repairs to improve the physical condition of the building, move classrooms
  out of portables and into permanent facilities, and improve specialized spaces such as STEM/STEAM and Computer
  and Technology spaces.
- Improving physical building condition and renovating existing facilities, such as air conditioning and repairing roofs, were identified as being the most important areas of investment for majority of respondents.
- Security was another area of improvement recognized by most respondents, with the ability to simultaneously lock all
  exterior doors electronically and a security officer on campus being most notable.

## EDUCATIONAL ADEQUACY ASSESSMENT | EXECUTIVE SUMMARY



#### **Educational Adequacy Assessment**

- Determines the physical capacity of a school building to accommodate the existing programming, or educational courses being offered.
- Includes access to physical variables: windows, general systems and appropriate technologies to facilitate learning
- Provides a starting point for considering future design standards

#### **Process**

- Cooperative Strategies had interviews with key administrators and educators regarding conditions and adequacy.
- ➤ Administrators walked the buildings and completed assessment forms
- Cost estimates determined using Oregon Department of Education condition assessment model

#### COMMUNITY DIALOGUE | EXECUTIVE SUMMARY



- Reaction to the data from the community survey
- ➤ What else do you need to know about your school facilities?
- > Other considerations that we should know.

### Data

Identify causes for students leaving Three Rivers prior to graduation

Build programs to engage students' interests

Build curriculum to encourage active student participation

Enhance safety and security within building and perimeter of school facilities

Instill community support for SRO

Build Community support for facility plan

## **Facilities**

Need for specialized performance area with effective sound system

Update athletic facilities

Expand activities to keep students in school

Upgrade temperature controls for both facilities and portables

Enhance lighting and air ventilation to learning spaces

Upgrade internet for reliability / 1:1 devices

Design collaborative spaces

Tie space to student needs

# Other Information

Need for increased student services

Address high cost of transportation

Update band instruments

Identify certification pathways with local industry

Identify need for furniture & equipment upgrades

Consider investment for 1:1 devices

Modernize media centers

#### DISCUSSION WITH TEAM MEMBERS | POTENTIAL OUTCOMES



New construction

Major & moderate renovations

Grade configuration changes

Magnet or choice program locations

Major furniture, fixtures & equipment procurement (FFE)

Boundary changes



#### FACILITY OPTIONS DEVELOPMENT | TEAM CONSIDERATIONS



## **Options Development Meeting Summary**

The Superintendent, COO, and members of the Facilities Department, IT Department, and District administration attended an options development meeting on November 5, 2019. In addition to their extensive knowledge of the district, the meeting participants also considered the results from the community survey, which was open from September 18<sup>th</sup> – October 1<sup>st</sup>. The main takeaways from that survey are as follows:

- > Renovating schools to improve the physical condition of existing facilities
- ➤ Move classrooms out of portables and into permanent facilities
- Improvement in Safety and Security
- ➤ Utilization of STEM/STEAM specialized spaces

#### FACILITY OPTIONS DEVELOPMENT | SUMMARY



## Capital Improvement Plan (CIP) (0-5 years)

Three Rivers operates 957,441 square feet of elementary, middle, and high school facilities that were constructed between 1912-2003, averaging in the 1960s. These facilities will almost certainly need rebuilt or replaced within 10-30 years.

- The options development committee recommends the District consider a full renovation of major assessment needs for all elementary, middle, and high schools
- ➤ The committee recommends the District consider a two-phase bond process for completing the repairs needed at all elementary, middle, and high schools (see pages 18 21 for phasing recommendations)

### PRIOR TO DEVELOPING OPTIONS | VISIONING EXERCISE



**Future Considerations** I identified by Options Development Committee & The Community

#### **Future Economic Model**

> Students must be prepared for a service & skills-based economy—soft skills, cultural competency, and skilled trades

## Current Facility Needs

- > Current facilities need immediate repair from assessments completed by Cooperative Strategies
- > Students have outgrown facilities
- Some schools within the School District rely on portable classroom settings

A Capital Investment Plan is advised to repair all major needs for all facilities across the School District.

## PRIOR TO DEVELOPING OPTIONS | FACILITY CONDITION ASSESSMENT



In the winter of 2018, Cooperative Strategies completed Facilities Condition Assessment (FCA) for each school. This process involved having assessors from CS go to each building to access the condition of each part of the building. Upon completion of this assessment, the data collected was used to determine approximately how much it would cost to replace/renovate/repair each deficiency. The district can then determine what deficiencies need can to be addressed based on total costs, the district's vision, and community input.









#### FACILITY ASSESSMENT | SUMMARY



School	GSF	Est. Program Capacity	2007 Enrollment	2018 Enrollment	Growth/Declin	Current Utilization	Est. Replacement Cost	Est. Repair Cost	FCI
Applegate ES	37,284	122	115	100	-13	% 82%	\$ 15,564,206	\$ 4,993,788	32%
Evergeen ES	56,342	365	461	383	-17	% 105%	\$ 23,519,968	\$ 12,960,831	55%
Fort Vannoy ES	35,934	268	277	237	-14	% 88%	\$ 15,000,648	\$ 7,287,208	49%
Fruitdale ES	51,643	316	313	386	23	% 122%	\$ 21,558,370	\$ 1,116,525	5%
Madrona ES	31,980	365	281	338	20	% 93%	\$ 13,350,051	\$ 6,737,888	50%
Manzanita ES	36,634	390	354	375	6	% 96%	\$ 15,292,863	\$ 7,046,136	46%
Williams ES	28,795	49	88	75	-15	% 153%	\$ 12,020,473	\$ 5,289,597	44%
ES TOTALS	278,612	1,875	1,889	1,894	0	% 101%	\$ 116,306,579	\$ 45,431,973	39%
Fleming MS	64,875	457	452	405	-10	% 89%	\$ 28,559,273	\$ 13,277,603	46%
Lincoln Savage MS	62,391	411		402			\$ 27,465,766		
Lorna Byrne MS	70,047			316			\$ 30,836,090		
MS TOTALS	197,313	1,182	1,237	1,123		% 95%	\$ 86,861,129	O CONTRACTOR OF THE CONTRACTOR	
Hidden Valley HS	144,206	868	877	572	-35	% 66%	\$ 67,860,459	\$ 26,780,895	39%
Illinois Valley HS	104,093	476		309			\$ 48,984,084		
North Valley HS	136,741	504		452			\$ 64,347,580		
HS TOTALS	385,040	1,848	2,027	1,333	-34		\$ 181,192,123		
Terome Prairie	27,441						\$ 12,496,631	\$ 6,494,141	52%
Merlin Alternative	14,716						\$ 6,701,666		
TOTALS	42,157		1			il.	\$ 19,198,298		
District Total	860,965	4,905	5,153	4,350	-16	% 89%	\$ 403,558,129	\$ 164,739,079	41%

## All facility assessments have been coded as Major, Moderate, or Minor repairs.

- ➤ All Major repairs are an immediate need for the School District and have exceeded life expectancy.
- All Moderate repairs have not exceeded life expectancy but should be repaired shortly after all Major repairs
- ➤ All Minor repairs will not exceed life expectancy for several years.



## The capital improvement plan will consist of two phases.

- **Phase 1** Integrates ALL major facility repairs from the following schools:
  - ➤ Evergreen Elementary school, Fort Vannoy Elementary School, Fleming Middle School, Lincoln Savage Middle School, Hidden Valley High School, Illinois Valley High School, and North Valley High School.
  - ➤ Includes all major roofing, plumbing, and restroom repairs for: Apple Gate Elementary School, Madrona Elementary School, Manzanita Elementary School, Williams Elementary School, Jerome Prairie Elementary School, and Merlin Alternative High School.



# Capital Improvement Plan | phase 1 capital needs \$106,248,554

	All major repairs	
	Evergreen ES	\$ 6,299,633
ES	Fort Vannoy ES	\$ 3,668,947
[I]	Subtotal Cost	\$ 9,968,580
	Soft Development Factor Subtotal	\$ 13,756,640
(C) — (C)	Fleming MS	\$ 8,033,516
MS	Lincoln Savage MS	\$ 6,737,837
2	Subtotal Cost	\$ 14,771,353
<u></u>	Soft Development Factor Subtotal	\$ 20,384,467
	Hidden Valley HS	\$ 15,074,074
	Illinois Valley HS	\$ 10,874,060
ES	North Valley HS	\$ 17,863,740
	Subtotal Cost	\$ 43,811,874
	Soft Development Factor Subtotal	\$ 60,460,386

	Apple Gate ES	\$	1,440,109
	Madrona ES	\$	1,683,954
S	Manzanita ES	\$	1,925,596
ES	Williams ES	\$	1,377,062
	Subtotal Cost	\$	6,426,721
	Soft Development Factor Subtotal	\$	8,868,875
	Jerome Prairie	\$	1,317,581
ALT	Merlin Alternative	\$	695,597
A	Subtotal Cost	\$	2,013,178
	Soft Development Factor Subtotal	S	2,778,186

Total Phase 1	\$ 106,248,554
---------------	----------------

#### CAPITAL IMPROVEMENT PLAN | MOVING FORWARD



- **Phase 2** Integrates ALL remaining major facility repairs from the following schools:
  - Apple Gate Elementary School, Madrona Elementary School, Manzanita Elementary School, Williams Elementary School, Jerome Prairie Elementary School, and Merlin Alternative High School.
  - ➤ Includes ALL moderate repairs for ALL schools in Three Rivers School District.



# Capital Improvement Plan | phase 2 capital needs

<b>\$</b> 5	1,94	18,022	•

	All Moderate Repairs	
	Apple Gate ES	\$ 1,405,538
	Ever Green ES	\$ 1,801,454
	Fort Vannoy ES	\$ 856,490
	Fruitdale ES	\$ 535,076
ES	Madrona ES	\$ 1,507,103
	Manzanita ES	\$ 727,927
	Williams ES	\$ 1,092,615
	Subtotal Cost	\$ 7,926,203
	Soft Development Factor Subtotal	\$ 10,938,160
188 - 518 1	Fleming MS	\$ 1,040,453
	Lincoln Savage MS	\$ 2,003,252
MS	Lorna Bryne MS	\$ 1,459,092
	Subtotal Cost	\$ 4,502,797
	Soft Development Factor Subtotal	\$ 6,213,860
	Hidden Valley HS	\$ 4,024,638
HS	Illinois Valley HS	\$ 4,585,527
	North Valley HS	\$ 5,794,720
	Jerome Prairie	\$ 877,094
ALT	Merlin Alternative	\$ 745,950
AI	Subtotal Cost	\$ 16,027,929
	Soft Development Factor Subtotal	\$ 22,118,542

	Remaining major repairs from pha	se 1	
	Apple Gate ES	\$	660,058
	Madrona ES	\$	1,686,342
ES	Manzanita ES	\$	2,452,361
[I]	Williams ES	\$	1,363,366
	Subtotal Cost	\$	6,162,127
	Soft Development Factor Subtotal	\$	8,503,735
	Jerome Prairie	\$	2,289,926
ALT	Merlin Alternative	\$	734,512
A	Subtotal Cost	\$	3,024,438
	Soft Development Factor Subtotal	\$	4,173,724

\$ 51,948,022	Total Phase 2
\$ 51,940	Total Fhase 2

#### MASTER FACILITY PLAN | SUMMARY



- ➤ The Facility Condition Assessment uses the Oregon Department of Education standard assessment template.
- ➤ This assessment records what an assessor can determine needs repair or replacement based on a visual inspection. The assessment findings are an evaluation of existing conditions and building types, and do not necessarily account for current building materials being used in construction at this time, which are likely much more efficient than what was installed when the buildings were built.
- ➤ The findings of this assessment should be considered a conservative estimate of needed repairs as needed renovations that cannot be assessed through visual inspection and/or components that needed replaced when they have exceeded their useful life (e.g., a 25-year roof in its 25<sup>th</sup> year).
- Furthermore, the options committee's interest in pursuing a School District repair restoration strategy for future capital investments could have a significant impact on capital investment priorities. Board direction is needed to ensure near-term capital investments align with the long-term facility needs for Three Rivers School District facilities.




Appendix D Educational Adequacy Assessment by Facility

## Three Rivers School District



## Table of Contents

Introduction	3
Term Glossary	4
Applegate Elementary School	5
Evergreen Elementary School	10
Fort Vannoy Elementary School	15
Fruitdale Elementary School	20
Madrona Elementary School	25
Manzanita Elementary School	30
Williams Elementary School	35
Fleming Middle School	39
Lincoln Savage Middle School	44
Lorna Byrne Middle School	49
Hidden Valley High School and Alternative Center	54
Illinois Valley High School	59
North Valley High School	64



# Introduction

#### What is an Educational Adequacy Assessment?

Educational Adequacy assessments determine the physical capacity of a school building to accommodate the existing programming, or educational courses, being offered. Educational adequacy includes variables such as access to operable windows, plumbing, and appropriate technologies in order to begin determining the ability of the building to facilitate learning. These assessments are inherently subjective, as "adequacy" can be interpreted broadly. Many of the quantitative and qualitative results found here are simple approximations, rather than line-item analyses. If renovations, construction, or other projects are seriously considered, a more indepth architectural or engineering analysis would likely be required.

#### **Process**

This assessment began with interviews with key administration who informed the consultant firm, Cooperative Strategies, of the basic conditions of educational adequacy in the district. Educators were engaged and gave their input. Out of these conversations, assessment parameters were drafted. Administration then walked the schools to fill out an assessment form and determine scores for learning spaces. Those scores are the major information source for this report. There are several times in this report where normative assertions are made regarding pricing, appropriate sizing of classrooms, etc. The main external sources used to inform these statements are Square Foot Costs with RS Means data, 2018, 39th annual edition, as well as industry standard best practices.

# Term Glossary

#### Capacity

Capacity is a rough estimation of how many students can be assigned to a school facility. In this study, the capacity of a school was determined by looking only at the main building structure, and does not include portable buildings in its calculations. This number was determined by using a multiplier of average students per classroom by the amount of classrooms in the main building.

#### Portable Buildings

Portable buildings function as interim learning or administrative spaces during times of temporary enrollment bumps at a school building, when it does not otherwise make sense to construct additional rooms onto an existing facility. Such spaces are called portables because they are essentially large trailers, built for this use. These spaces are not considered part of the building facility in this analysis, due to their inherent educational inadequacy and temporary nature.

#### Utilization

Utilization is the comparison of the capacity of a school to the 2017-18 school year enrollment. It is a ratio, represented as a percentage, which indicates how full a school building is.

### Building Overview

Address: 14188 Highway 238, Applegate, OR 97530

Site Size: 3.57 acres

Original Construction Year: 1912

Age: 107 Years


Student Capacity (main facility):1222007 Enrollment:1152018 Enrollment:100Portable Teaching Spaces:6


Current Total Square Footage: 32,564 square feet Replacement Cost (as is): \$ 15.6 million

#### **Select Site Conditions**

	Sufficient but in	
Play Structures	poor condition	
	Sufficient but in	
Fields	poor condition	
Parking	Sufficient but in	
availability	poor condition	Need Paving
Presence of a	Sufficient but in	
bus loop	poor condition	Need Paving

### **Building Utilization**





## Building Summary

Utilization and Portable Teaching

Spaces

Applegate has a unique situation where, according to its approximate capacity (which does not account for portables), it is only at 82% utilization. This means that its portables may not be necessary for use as anything other than special programming, such as arts, music, library, etc. While there is a clear need to provide this programming to students, portables are inherently less able to provide educationally adequate spaces.

Facility Size

The size of the school itself is small, considering the potential for economies of scale that a larger school facility can offer. If the district were to build a new school facility today, it would not be recommended that it be built to this current square footage.


Modernization

All the spaces assessed had poor access to a synchronized clock system, they also all had little to moderate access to wall outlets. There was a mix of access to a digital interactive display system, a digital system with casting, and a telephone/intercom

## Educational Adequacy Assessment

### **Priority Spaces**

Space	Size	Adjacencies	Safety & Security	Improvement Areas
K, 1, 2, 3 All Blended Classrooms	Undersized	Appropriate	Room for Improvement	These spaces are generally undersized; they are averaging at about 740 square feet when the recommended size of a kindergarten classroom is 1200 square feet and the recommended size of a general education elementary classroom is 900 square feet. In terms of safety and security, there is room for improvement in terms of access control and transparency (or the ability to visually assess adjacent spaces, such as seeing out from a classroom into the hallway). These rooms have a flooring finish of carpeting, which is favored among educators, though it can have a lower hygiene standard and higher maintenance requirements than a vinyl sheet floor. It is recommended the the District weigh an alternative flooring type for part or all of these spaces.
Intermediate Classroom Grades 4-5	Appropriate	Appropriate	Generally Appropriate	This room is appropriately sized, and more safe and secure in terms of transparency compared to the other blended classrooms. These rooms have a flooring finish of carpeting, which is favored among educators, though it can have a lower hygiene standard and higher maintenance requirements than a vinyl sheet floor. It is recommended the the District weigh an alternative flooring type for part or all of these spaces. This space also has inadequate lighting control.
Lifeskills	integrated with self contain	pecial needs students, all other students, aed classroom with tions, in terms of t amenities.	or together in a no special	There is no designated classroom for special education and students who have particular needs may not be accommodated for in their current classrooms. For example, a special education student may require special technologies, accessibility, additional plumbing, etc. which does not currently exist in classrooms.
Science & Math Classrooms	Appropriate	Appropriate	Generally Appropriate	In terms of safety and security, there is room for improvement in terms of access control and transparency (or the ability to visually assess adjacent spaces, such as seeing out from a classroom into the hallway). The flooring for these spaces, being carpet, is inappropriate for its use, considering that science can tend to create spillages that may be difficult to clean up from carpeting. This space also has inadequate lighting control.
Resource	Oversized	Appropriate	Generally Appropriate	This space is the size of an appropriately sized classroom, lacks various technologies, and does not have lighting flexibility. Most other factors evaluated are sufficient.



## Educational Adequacy Assessment

### **Priority Spaces**

Space	Size	Adjacencies	Safety &	Improvement Areas	
Space	3126	ragacericies	Security		
Gym	Oversized	Appropriate	More Safe & Secure	The gymnasium is of the recommended size for an enrollment of approximately 400 students, as opposed to the roughly 100 enrolled. It has good access control, though it lacks padding on the walls, appropriate natural lighting, lighting control, and sound absorption. It also lacks appropriate access to a restroom.	
Cafeteria	Somewhat Oversized	Appropriate	Generally Appropriate	This space is somewhat oversized and has inappropriate or insufficient access to water for students. The flooring is in poor condition, as is the concrete masonry wall finish. There is also a lack of lighting control.	
				Portables	
Portables: resource rooms, a computer lab, a library, art room, and music room	These spaces are generally considered educationally inadequate. Applegate's portable spaces all lack appropriate access to restrooms, have lower safety and security, and lower technological availability.				

## Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Lacking
K, 1, 2, 3 All Blended Classrooms	75%	25%
Intermediate Classrooms Grades 4-5	74%	26%
Science & Math Classrooms	73%	27%
Resource	61%	39%
Gym	51%	49%
Cafeteria	74%	26%

### Portable Spaces

Portable Space Type	Sufficient	Lacking
Resource Rooms	61%	39%
Computer Lab	79%	21%
Library	81%	19%
Arts	70%	30%
Music	74%	26%



## Building Overview

**Address:** 520 W River St, Cave Junction, OR 97523

Site Size: 20 acres **Original Construction Year:** 1951


68 Years Age:

Student Capacity (main facility): 365 2007 Enrollment: 461 2018 Enrollment: 383 **Portable Teaching Spaces:** 2


Current Total Square Footage: 56,342 square feet \$23.5 million Replacement Cost (as is):

#### Select Site Conditions

		ı
		Half are old and
		need replacing.
	Sufficient but in	Bark and pea gravel
Play Structures	poor condition	need replacing.
	Sufficient but in	Baseball and dirt
Fields	poor condition	field need care.
Parking	Sufficient but in	Concrete needs
availability	poor condition	resurfacing.
Presence of a	Sufficient but in	
bus loop	poor condition	Needs resurfacing.



0%





## Building Summary

	- 1	
Computer	1 1	2
Combuter.	டவ	$\omega z$

This school has three computer labs, of which two are in the main building and one is in a portable space. It may be beneficial to consider eliminating the portable computer lab space in favor of technology integration in the classrooms, as a more modern alternative.

Ceiling and Wall Finishes

All of the relevant spaces in this school facility have inadequate or low quality ceiling finishes and moderate quality wall finishes.

Comfort and Health

There is a general lack of lighting control and lateral ventilation in this school facility. There is also a mix of availability of natural daylight. Most spaces have moderately appropriate to inappropriate sound absorption capabilities.

Restrooms

Restrooms for students in the building are currently considered inadequate.

Technologies

Access to appropriate technology is generally provided, however there is a lack of a quality synchronized clock system throughout the building. There is also generally only moderately appropriate access to wall outlets.

Additional Spaces


This school building does not have designated spaces for music and visual arts.

D11

## Educational Adequacy Assessment

### **Priority Spaces**

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Kindergarten, 1st, 2nd Grade Classrooms	Appropriate	Appropriate	Appropriate	These rooms have a flooring finish of carpeting, which is favored among educators, though it can have a lower hygiene standard and higher maintenance requirements than a vinyl sheet floor. In these spaces, the condition of the carpeting is poor. There is also room for improvement in terms of tackable surfaces and quality of wall finish. While the 1st and 2nd grade rooms are appropriately sized, the Kindergarten space of the same size is too small for its use.
Intermediate Classrooms Grades 3-4	Appropriate	Appropriate	Appropriate	These rooms have a flooring finish of carpeting, which is favored among educators, though it can have a lower hygiene standard and higher maintenance requirements than a vinyl sheet floor. In these spaces, the condition of the carpeting is poor. There is also room for improvement in terms of tackable surfaces and quality of wall finish.
Resource Rooms	Oversized	Appropriate	Appropriate	These rooms have a flooring finish of carpeting, which is favored among educators, though it can have a lower hygiene standard and higher maintenance requirements than a vinyl sheet floor. In these spaces, the condition of the carpeting is moderate. There is room for improvement in terms of tackable surfaces and quality of wall finish. These spaces have no access to natural light or ventilation and no means of communication with the main office
Computer Lab	Appropriate	Appropriate	Generally Appropriate	This space, like most other spaces in this facility, has good transparency, access control, and flexibility, while it lacks quality of floor finish, wall finish, and ceiling finish.
Lifeskills	Somewhat Oversized	Appropriate	Appropriate	This space is somewhat oversized. It could use improvements to its restroom, sound absorption, and other areas consistent with the rest of the facility.
Gymnasium	Oversized	Appropriate	Generally Appropriate	The gymnasium lacks padding on its walls, appropriate access to restrooms, and a writable surface.
Cafeteria	Somewhat Undersized	Generally Appropriate	Generally Appropriate	The cafeteria lacks quality flooring, appropriate means of communications with the main office, a writable surface, access to potable water for students, and quality sound absorption.



## Educational Adequacy Assessment

### **Priority Spaces**

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Library	Oversized	Appropriate	Generally Appropriate	The library lacks appropriate communications with the main office, quality flooring, wall and ceiling finishes, comfort and health, writable and tackable surfaces, and some technology access. It also lacks a sink for use by administrators.
Portables				
Portables: Pre-Kindergarten and Computer Lab	These spaces are generally considered educationally inadequate.			

## Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Lacking
Kindergarten, 1st, 2nd Grade Classrooms	67%	33%
Intermediate Classrooms Grades 3-4	69%	31%
Resource	58%	42%
Computer Lab	79%	21%
Lifeskills	70%	30%
Gym	62%	38%
Cafeteria	56%	44%
Library	56%	44%

### Portable Spaces

Portable Spaces	Sufficient	Lacking
Portable Pre-Kindergarten	50%	50%
Portable Computer Lab	74%	26%

# Fort Vannoy Elementary School

## Building Overview

Address: 5250 Upper River Rd, Grants Pass, OR

Site Size: 11.7 acres

Original Construction Year: 1952

Age: 67 Years


Student Capacity (main facility):2682007 Enrollment:2772018 Enrollment:237Portable Teaching Spaces:0


Current Total Square Footage: 35,934 square feet Replacement Cost (as is): \$15.0 million

#### **Select Site Conditions**

	Sufficient but in	
Play Structures	poor condition	
Fields	Sufficient	
Parking		There is not enough
availability	Not sufficient	parking availability
Presence of a		
bus loop	Not Available	There is no bus loop

### **Building Utilization**







#### Building Summary

W	ate
, ,	ucc.

All the space types assessed, other than the library, have some access to water (defined as a sink or drinking fountain). These plumbing fixtures faces a need for improvement, either for equitability or quality of access.

#### Finishes

Where there is carpeting or resilient vinyl sheet as a flooring finish, there is a general lack of quality. The flooring and wall finishes are also lacking.

#### Comfort and Health

There if a general lack of access to natural ventilation. There is also room for improvement in terms of natural daylighting, lighting control, and sound absorption.

#### Plumbing

There are no restrooms or water (sinks and water fountains) that were found to be sufficient in either their accessibility or quality.

#### **Technology**

There is a general lack of either quality or accessibility in a synchronized clock system for all spaces assessed.


Access Control | Sufficient access control has been found to be an item where there is room for improvement in all spaces assessed.

#### Additional Spaces

This school building does not have designated spaces for music and visual arts.

### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Kindergarten, 1st, 2nd Grade Classrooms	Appropriate	Appropriate	Room for Improvement	These spaces have room for improvement in their access control, flexibility, flooring/ wall/ ceiling finish quality. There is also a lack of access to natural daylighting, natural ventilation, and lighting control.  Additionally, the quality of access to water is limited, as well as access to a digital system with casting, synchronized clock system, and appropriate wall outlets.
Intermediate Classrooms Grades 3-5	Appropriate	Appropriate	Room for Improvement	These spaces have room for improvement in their access control, flexibility, flooring and ceiling finish quality. There is also a lack of access to natural daylighting, natural ventilation, lighting control, and sounds absorption. Additionally, the quality or access to water is limited, as well as access to a digital system with casting, synchronized clock system, and appropriate wall outlets.
Lifeskills	accommodations, in terms of the space and			There is no designated classroom for special education and students who have particular needs may not be accommodated for in their current classrooms. For example, a special education student may require special technologies, accessibility, additional plumbing, etc. which does not currently exist in classrooms.
Resource	Oversized	Appropriate	Room for Improvement	These spaces are, on average, the same size as classrooms, making them quite oversized for their use. This also indicates that these spaces were originally constructed for use as classrooms. Like the other classrooms, these spaces have room for improvement in their access control, flexibility, flooring/ wall/ ceiling finish quality. There is also a lack of access to natural daylighting, natural ventilation, lighting control, and sounds absorption. Additionally, access to a digital system with casting, synchronized clock system, and appropriate wall outlets has room for improvement.
Computer Lab	Appropriate	Appropriate	Room for Improvement	Like the other classrooms, these spaces have room for improvement in their access control, flexibility, flooring and ceiling finish quality. There is also a lack of access to natural daylighting, natural ventilation, lighting control, and sounds absorption. Additionally, access to a digital system with casting, synchronized clock system, and appropriate wall outlets has room for improvement.
Gymnasium	Generally Appropriate	Appropriate	More Safe & Secure	This space is somewhat lacking in its access control. It also has room for improvements in its flooring/ wall/ and ceiling finishes. It also lacks padding on its walls. There is a lack of access to natural daylighting, natural ventilation, lighting control, and sounds absorption. Access to restrooms and water is limited. There is a lack of quality or access to writable and tackable surfaces. Additionally, access to a digital system with casting, synchronized clock system, and appropriate wall outlets has room for improvement.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Cafeteria	Somewhat Undersized	Appropriate	More Safe &	This space is somewhat lacking in its access control. It also has room for improvements in its flooring/ wall/ and ceiling finishes. There is a lack of access to natural ventilation, lighting control, and sound absorption. The water is limited either in access or quality. There is room from improvement in writable surfaces and tackable surfaces, as well as access to a digital system with casting, a synchronized clock system, and appropriate wall outlets.
Library	Appropriate	Appropriate	Generally Appropriate	The library space is limited in its access control and flexibility. There is also a lack of quality in its carpeting, ceiling finish, and ceiling finish. There is a lack of access to natural ventilation, lighting control, and sound absorption. There is no access to water. There is room from improvement in writable surfaces, as well as access to a digital system with casting, a synchronized clock system, and appropriate wall outlets.

### Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Lacking
Kindergarten, 1st, 2nd Grade Classrooms	62%	38%
Intermediate Classrooms Grades 3-5	62%	38%
Resource	55%	45%
Computer Lab	67%	33%
Gym	58%	42%
Cafeteria	60%	40%
Library	64%	36%

### Building Overview

**Address:** 1560 Bill Baker Way, Grants Pass, OR 97527

Site Size: 6.15 acres

**Original Construction Year:** 2004


15 Years Age:


Student Capacity (main facility): 316 2007 Enrollment: 313 2018 Enrollment: 386 **Portable Teaching Spaces:** 4

Current Total Square Footage: 51,643 square feet \$21.6 million Replacement Cost (as is):

#### Select Site Conditions

		These spaces
Play Structures	Sufficient	require more
		regular
Fields	Sufficient	maintenance.
		There is not enough
Parking		parking
availability	Not sufficient	availability.
Presence of a		
bus loop	Sufficient	







D20

### Building Summary

This school building does not have designated spaces for music and visual arts.

Plumbing

None of the spaces assessed have plumbing, including restrooms and water in appropriate spaces.

Flooring

All spaces that have carpet as its flooring have a lacking score for its quality.


Comfort and Health

All spaces which were assessed regarding lighting control and natural ventilation got a moderate score, or did not have access to such elements at all. There are also few spaces which have appropriate sound absorption.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Kindergarten, 1st, 2nd Grade Classrooms	Appropriate	Appropriate	Generally Appropriate	These spaces are well suited for their use. Where there is room for improvement is in the quality of the carpeting, access to lighting control, natural ventilation, a synchronized clock system, and appropriate wall outlets. These spaces also lack a sink and/ or water fountain.
Intermediate Classrooms Grades 3-5	Appropriate	Appropriate	Generally Appropriate	These spaces are well suited for their use. Where there is room for improvement is in the quality of the carpeting, access to lighting control, natural ventilation, a synchronized clock system, and appropriate wall outlets. These spaces also lack a sink and/ or water fountain.
Lifeskills	Currently, special needs students are either integrated with all other students, or together in a self contained classroom with no special accommodations, in terms of the space and amenities.		or together in a no special	There is no designated classroom for special education and students who have particular needs may not be accommodated for in their current classrooms. For example, a special education student may require special technologies, accessibility, additional plumbing, etc. which does not currently exist in classrooms.
Special Education Resource Rooms	Appropriate	Appropriate	Generally Appropriate	These spaces are well suited for their use. Where there is room for improvement is in the quality of the carpeting, access to lighting control, natural ventilation, a synchronized clock system, and appropriate wall outlets.
Computer Lab	Appropriate	Appropriate	Generally Appropriate	This space has room for improvement considering how it is used. There is a lack of transparency. There is an inappropriate type and low quality flooring finish. There is a lack of lighting control, natural ventilation, and sound absorption. There is also no tackable surface, no access to wi-fi, no synchronized clock system, and lacking access to appropriate wall outlets.
Gym	Appropriate	Appropriate	Generally Appropriate	This space can accommodate the needs of students better. The flooring finish is not sufficient, access to natural daylight, lighting control, natural ventilation, and sound absorption are limited or not available. There is lacking access to water and restrooms. There is no white marker board space, and an insufficient synchronized clock system.
Cafeteria	Oversized	Appropriate	More Safe & Secure	The cafeteria is lacking appropriate access control, lighting control, natural ventilation, sound absorption, water, and a synchronized clock system.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas	
Library	Appropriate	Appropriate	Generally Appropriate	The library lacks appropriate transparency, floor finish, lighting control, natural ventilation, sound absorption, water access, digital display system, synchronized clock system, and appropriate wall outlets.	
	Portables				
Portables: Kindergarten & 1st	Portables: Kindergarten & 1st				
grade classrooms, Camp	rade classrooms, Camp  These spaces are generally considered educationally inadequate. These spaces are generally lacking in technology availability and other recommended				
Sunrise alternative education,	elements.				
and resource room.					

## Educational Adequacy Assessment

#### **Existing Spaces**

Portable Space Type	Sufficient	Lacking
Kindergarten, 1st, 2nd Grade Classrooms	83%	17%
Intermediate Classrooms Grades 3-5	86%	14%
Resource- SPED	87%	13%
Computer Lab	55%	45%
Gym Composite	53%	47%
Cafeteria	74%	26%
Library	69%	31%

### Portable Spaces

Portable Space Type	Sufficient	Lacking
Kindergarten, 1st, 2nd Grade Classrooms	16%	84%
Intermediate Classrooms Grades 3-5	16%	84%

### Building Overview

Address: 520 Detrick Dr, Grants Pass, OR 97527

Site Size: 9.62 acres

Original Construction Year: 1967

Age: 52 Years


Student Capacity (main facility):3652007 Enrollment:2812018 Enrollment:338Portable Teaching Spaces:1


Current Total Square Footage: 31,980 square feet Replacement Cost (as is): \$13.4 million

#### **Select Site Conditions**

		There one of the
		play structures
Play Structures	Sufficient	needs to be
		replaced. The track
		is inappropriately
Fields	Sufficient	located.
Parking		There is not enough
availability	Not Sufficient	space for parking
Presence of a		
bus loop	Not Sufficient	

#### **Building Utilization**







### Building Summary

**Additional Spaces** This school building does not have designated spaces for music and visual arts.

Technologies There is a general lack of an appropriate synchronized clock system throughout the building, as well as lacking digital systems with casting, appropriate wall outlets.


Finishes There is a consistent issue in the ceiling, flooring, and wall finishes of assessed spaces.

Additional Spaces This school building does not have designated spaces for music and visual arts.

D26

### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Kindergarten, 1st, 2nd Grade Classrooms	Somewhat Oversized	Appropriate	Appropriate	These spaces are less appropriate than they could be. The access control and flexibility could be improved. The flooring is of a low quality, as well as the wall and ceiling finishes. There is lacking lighting control, natural ventilation, and and sound absorption. The access to water and restrooms is inconsistent. The writable surfaces are lacking and there is no appropriate tackable surface. There is also a need for more a appropriate digital system with casting, a syncronyzed clock system, and appropriate wall outlets.
Intermediate Classrooms Grades 3-5	Appropriate	Appropriate	Appropriate	These spaces are less apropriate than they could be. The access control and flexibility could be improved. The flooring is of a low quality, as well as the wall and ceiling finishes. There is lacking lighting control, natural ventilation, and and sound absorption. The access to water and restrooms is inconsistent. The writable surfaces are lacking and there is no apropriate tackable surface. There is also a need for more a apropriate digital system with casting, a syncronyzed clock system, and apropriate wall outlets.
Lifeskills	Appropriate	Appropriate	Room for Improvement	These spaces are lacking various elements. There is no access control, and lacking flexibility. The ceilign finish is lacking, as well as the flooring variety. There is lacking lighting control, natural ventilation, and sound absorption. There is room for improvement in access to restrooms and water. There is no tackable surface, and lacking access to a digital system with casting, telephone/ intercom, syncronyzed clock system, and appropriate wall outlets.
Special Education Resource	Appropriate	Appropriate	Generally Appropriate	These spaces were found to be gernerally lacking. There is a need for improvements to transparency, access control, and flexibility. There is room for improvement considering the flooring/ wall/ and ceiling finishes. There is also a lack of appropriate natural daylight, lighting control, natural ventilation, and sound absorption. There is a lack of appropriate restroom and water access. Current writable surface space is inappropriate, there is no tackable surface, and lacking access to a digital system with casting, telephone/ intercom, syncronyzed clock system, and appropriate wall outlets.
Resource	Oversized	Appropriate	Room for Improvement	These spaces, also referred to as pods, are located as a secondary spaces within the classrooms, with equal access among each ring of 6 classrooms. For this reason, they generally lack access to natural daylight, lighting control, natural ventilation, and sound absorption. There is also less access to restrooms and water than would be recommended.
Gym	Oversized	Appropriate	More Safe & Secure	The gymnasium is roughly 1,000 square feet above what would be recommended compared to the current enrollment at this school. There is no access control, and insufficient flooring, wall, and ceiling finishes. There is also insufficient natural daylighting, lighting control, natural ventilation, and sound absorption, as well as lacking access to restrooms. There is also lacking display space and technology.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas		
Cafeteria	Oversized	Appropriate	Generally Appropriate	Like the gymnasium, there is no access control, and insufficient flooring, wall, and ceiling finishes. There is also insufficient natural daylighting, lighting control, natural ventilation, and sound absorption, as well as lacking access to restrooms. There is also lacking display space and technology.		
Library	Appropriate	Appropriate  Room for Improvement  Room for Improvement  Room for Improvement  This space has inappropriate or insufficient access control, transparency, flexibility, floor/ wall/ ceiling finishes, lighting control, natural ventilation, sound absorption, water, writable and tackable surfaces, and various technologies.				
	Portables					
Portables: computer lab	These spaces are generally considered educationally inadequate.					

### Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Lacking
Kindergarten, 1st, 2nd Grade Classrooms	57%	43%
Intermediate Classrooms Grades 3-5	59%	41%
Resource- SPED	44%	56%
Gym Composite	53%	47%
Cafeteria	63%	47%
Library	51%	37%

### Portable Spaces

Portable Spaces	Sufficient	Lacking
Computer Lab	57%	43%

### Building Overview

Address:

Site Size: 22 acres
Original Construction Year: 1966

Age: 53 Years


Student Capacity (main facility):3902007 Enrollment:3542018 Enrollment:375Portable Teaching Spaces:3


Current Total Square Footage: 36,634 square feet Replacement Cost (as is): \$15.3 million

#### **Select Site Conditions**

	_	
	Sufficient but in	
Play Structures	poor condition	
	Sufficient but in	
Fields	poor condition	
Parking		Need to
availability	Not sufficient	pave gravel
Presence of a		Need
bus loop	Sufficient	Paving

#### **Building Utilization**







### Building Summary

wovable wall	able Walls
--------------	------------

There are movable walls separating the classrooms which are in disrepair, and have a more disruptive impact on educational adequacy, due to lack of noise isolation and other factors, than it does to positively impact features such as benefits of flexibility in space usage.

**Technology Systems** 

There are several technology systems which would be appropriate for spaces they are not sufficiently found in. All assessed spaces for a synchronized clock system and appropriate wall outlets were found to be insufficient. Similarly, all spaces assessed for a digital interactive display system only had these fixtures in a somewhat sufficient form.

Windows

None of the spaces assessed have operable windows, meaning that there is a lack of access to natural ventilation in learning spaces.


Additional Spaces

This school building does not have designated spaces for music and visual arts.

D31

### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Kindergarten, 1st, 2nd Grade Classrooms	Appropriate	Generally Appropriate	Appropriate	These spaces have good transparency and access control, wi-fi, and telephone/ intercom access. They are somewhat sufficient in terms of flexibility, natural daylight, access to water, whiteboard and tackable surfaces, and digital interactive display systems. The flooring, wall finish, ceiling finish, lighting control, sound absorption, restroom access, synchronized clock system, and wall outlets were all found to be less sufficient.
Intermediate Classrooms Grades 3-5	Appropriate	Generally Appropriate	Appropriate	These spaces have good transparency and access control, wi-fi, and telephone/ intercom access. They are somewhat sufficient in terms of flexibility, natural daylight, access to water, whiteboard and tackable surfaces, and digital interactive display systems. The flooring, wall finish, ceiling finish, lighting control, sound absorption, restroom access, synchronized clock system, and wall outlets were all found to be less sufficient.
Lifeskills Classroom	Oversized	Generally Appropriate		This space has good access control, ceiling finish, water access, writable board surface, wi-fi access, digital interactive display, and communication with the main office. There is moderate accessibility to appropriate wall finish, sound absorption, restrooms, and tackable surfaces. There is lacking transparency, natural daylight, lighting control, a synchronized clock system, and appropriate wall outlets.
Special Education Resource	Oversized	Generally Appropriate	Appropriate	These spaces have good transparency and access control, wi-fi, and telephone/ intercom access. They are somewhat sufficient in terms of flexibility, natural daylight, access to water, whiteboard and tackable surfaces, and digital interactive display systems. The flooring, wall finish, ceiling finish, lighting control, sound absorption, restroom access, synchronized clock system, and wall outlets were all found to be less sufficient.
Resource	Oversized	Appropriate	Room for Improvement	terms of flexibility, whiteboard and tackable surfaces, and digital interactive display systems. The transparency, lack of access control, floor, wall, and ceiling finishes, natural daylighting, lighting control, sound absorption, restroom access, synchronized clock system, and wall outlets were all found to be less sufficient. There is a lack of an interactive display and access to natural ventilation.
Gym	Oversized	Appropriate	Room for Improvement	The gymnasium is roughly 1,000 square feet above what would be recommended compared to the current enrollment at this school. There is no natural ventilation, restroom access within the space, white marker board surface. There is also lacking display. The wall and flooring finished are inappropriate for this space's use. The access to natural daylight, lighting control, sound absorption, water, tackable surfaces, telephone/intercom, a synchronized clock, and sufficient wall outlets are all lacking.



### Educational Adequacy Assessment

Space	Size	Size Adjacencies Safety & Improvement Areas			
Cafeteria	Undersized	Undersized Appropriate Generally Appropriate This space is roughly 1,000 square feet smaller than what would be recommended, considering current enrollment numbers. This space has good access control, natural daylighting, wi-fi access, and telephone/ intercom. There is moderate to lacking floor wall and ceiling finishes, lighting control, natural ventilation, sound absorption, water, synchronized clock system, and sufficient wall outlets.			
Library	Appropriate	Appropriate  Appro			
	Portables				
Portables: computer lab, Title 1, and Lifeskills	These spaces are generally considered educationally inadequate.				

## Educational Adequacy Assessment

#### **Existing Spaces**

	Sufficient	Lacking
Kindergarten, 1st, 2nd Grade Classrooms	64%	36%
Intermediate Classrooms Grades 3-5	63%	37%
Special Education Resource	63%	37%
Gym	85%	15%
Cafeteria	71%	29%
Library	57%	43%
Overall	66%	34%

#### Portable Spaces

	Sufficient	Lacking
Computer Lab	86%	14%
Resource	80%	20%
Life Skills Classroom (not a pull out room)	61%	39%
Overall	73%	27%

### Building Overview

**Address:** 20691 Williams Hwy, Williams, OR 97544

Site Size: 3.26 acres

**Original Construction Year:** 1949


70 Years Age:


Student Capacity (main facility): 49 2007 Enrollment: 88 2017 Enrollment: 75 **Portable Teaching Spaces:** 5

Current Total Square Footage: 29,795 square feet \$12.0 million Replacement Cost (as is):

#### Select Site Conditions

Play Structures	Sufficient	
	Sufficient but in	
Fields	poor condition	
Parking	Sufficient but in	Needs
availability	poor condition	paving
		Undersized
Presence of a		and needs
bus loop	Not sufficient	paving





### Building Summary

Portab	oles	Α	s1
1 Ortal	ICS	$\Box$	51.

light majority of the learning square footage on the site are portable spaces. These spaces are generally considered to be educationally inadequate.

Additional Spaces

This school building does not have designated spaces for music and visual arts.

Synchronized Clock System


None of the spaces accessed had a synchronized clock system.



D36

### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Intermediate Classroom Grades 4/5 Blend	Appropriate	Generally Appropriate	Room for Improvement	This space has appropriate water access, white marker board surfaces, wi-fi access, digital interactive display, and telephone/ intercom system. There is lacking access to appropriate transparency, access control, flexibility, floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, tackable surfaces, digital system with casting, and appropriate wall outlets.
Computer Lab	Somewhat Undersized	Generally Appropriate	Room for Improvement	This space has appropriate whiteboard marker surfaces and wi-fi access. It is moderately appropriate or lacking in transparency, access control, flexibility, floor, wall, and ceiling finishes, access to natural daylight, lighting control, natural ventilation, sound absorption, tackable surfaces, digital interactive display, telephone/intercom, synchronized clock system, and appropriate wall outlets.
Resource	Generally Appropriate	Generally Appropriate	Room for Improvement	These spaces have appropriate white marker board surfaces. They are lacking in transparency, access control, flexibility, floor, wall, and ceiling finishes, access to natural daylight, lighting control, natural ventilation, sound absorption, tackable surfaces, digital interactive display, display with casting, telephone/intercom, synchronized clock system, and appropriate wall outlets.
Gym	Somewhat Undersized	Generally Appropriate	Room for Improvement	The physical education space has sufficient water and wi-fi access. There is moderate or insufficient access to appropriate access control, floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restrooms, writable surfaces, tackable surfaces, digital system with casting, telephone/intercom, intercom speaker, synchronized clock system, and appropriate wall outlets.
Cafeteria	Generally Appropriate	Appropriate	Generally Appropriate	The cafeteria has sufficient natural daylighting and wi-fi access. It is limited in its access control, floor, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, access to water, white marker board space, tackable surfaces, digital system with casting, telephone/ intercom, synchronized clock system, and appropriate wall outlets.
Library	Generally Appropriate	Appropriate	Appropriate	The library space has appropriate transparency, natural daylight, wi-fi access, and telephone/ intercom systems. The space does not have appropriate access control, flexibility, floor, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, water, white marker board surfaces, tackable surfaces, digital interactive display, digital casting, synchronized clock system, and appropriate wall outlets.
	Portables			
Portables: Prekindergarten, K-3 classrooms, SPED resource, music	These spaces are generally considered educationally inadequate.			



### Educational Adequacy Assessment

#### **Existing Spaces**

	Sufficient	Insufficient
Intermediate Classrooms Grades 4/5 blend	62%	38%
Computer Lab	67%	33%
Avg Resource Room	64%	36%
Gym	58%	42%
Cafeteria	72%	28%
Library	64%	36%
Overall	65%	35%

#### Portable Spaces

	Sufficient	Insufficient
Music	61%	39%
Pre-Kindergarten	61%	39%
K, 1st, 2nd, 2/3 Grade Classrooms	64%	36%
Resource: SPED	63%	37%
Overall	63%	37%

### Building Overview

Address: 6001 Monument Dr, Grants Pass, OR 97526

Site Size: 53.12 acres

Original Construction Year: 1962

Age: 57 Years


Student Capacity (main facility): 457
2007 Enrollment: 452
2018 Enrollment: 405
Portable Teaching Spaces: 1


Current Total Square Footage: 64,875 square feet Replacement Cost (as is): \$28.6 million

#### **Select Site Conditions**

	Sufficient but in	No water
Fields	poor condition	supply
Parking		Need to
availability	Sufficient	pave gravel
Presence of a		Need
bus loop	Sufficient	Paving

#### **Building Utilization**







### Building Summary

	Additional	l Spaces
--	------------	----------

This school building does not have a designated space for visual arts.


Access Control | There is a lack of access control in a majority of spaces. Only the science classrooms and cafeteria have access control, and it has been found to be insufficient.

Synchronized Clock System

In all spaces that were assessed, the synchronized clock system was found to be highly insufficient.

### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Middle Classrooms Grades 6-8	Appropriate	Appropriate	Room for Improvement	These spaces have sufficient wi-fi access and telephone/ intercom systems. There is moderately or highly lacking transparency, access control, flexibility, floor, wall, and ceiling finishes, lacking access to natural daylight, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, digital interactive display with casting, and appropriate wall outlets.
Resource	Appropriate	Appropriate	_	These spaces have sufficient transparency, flexibility, wall padding, wi-fi access, digital interactive display, digital system with casting, and appropriate wall outlets. There is moderately or highly lacking access control, flooring, wall, and ceiling finishes, natural daylighting, lighting control, sound absorption, white marker board surface, tackable surfaces, intercom system, and synchronized clock system.
Science Classroom	Appropriate	Appropriate	Generally Appropriate	These spaces have sufficient transparency, flexibility, wi-fi access, and telephone/ intercom. There is lacking access control, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water, white marker board surfaces, tackable surfaces, digital interactive display, digital system with casting, telephone/ intercom, synchronized clock system, and appropriate wall outlets.
Computer Lab	Appropriate	Appropriate	Room for Improvement	These spaces have sufficient transparency, flexibility, wi-fi access, and telephone/ intercom, and appropriate wall outlets. There is lacking access control, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, digital interactive display, digital system with casting, telephone/ intercom, and synchronized clock system.
Gym	Oversized	Appropriate	Room for Improvement	This space has appropriate transparency, flexibility, telephone/ intercom. There is lacking or insufficient, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restroom and water access, wi-fi access, digital interactive display, digital interactive display, intercom, synchronized clock system, and appropriate wall outlets.
Cafeteria	Undersized	Appropriate	More Safe & Secure	The cafeteria has sufficient transparency, flexibility, and telephone/ intercom. The space has insufficient access control, floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restroom and water access, tackable surfaces, wi-fi access, digital interactive display, digital system with casting, intercom, synchronized clock system, and appropriate wall outlets.
Library	Undersized	Appropriate	Appropriate	This space has appropriate transparency, flexibility, wi-fi access, telephone/ intercom. There is lacking or insufficient access control, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restroom and water access, wi-fi, water, tackable surfaces, digital interactive displays, digital system with casting, intercom, synchronized clock system, and appropriate wall outlets.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Choir / Band	Appropriate Appropriate Appropriate Appropriate Appropriate Appropriate Generally Appropriate Appropriate Appropriate Flooring, wall, and ceiling finish, natural daylight, lighting control, natural ventilation, sound absorption water, white board surface, tackable surface, wi-fi access, digital interactive display, digital system with casting, intercom speaker, synchronized clock system, and appropriate wall outlets.			
Portables				
Portables: family advocate/ leadership	These spaces are generally considered educationally inadequate.			

### Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Insufficient
Middle Classrooms Grades 6-8	52%	48%
Resource	70%	30%
Science Classroom	59%	41%
Computer Lab	67%	33%
Gym	56%	44%
Cafeteria	52%	48%
Library	58%	42%
Music	56%	44%

#### Portable Spaces

	Sufficient	Insufficient
Family Advocate/ Leadership	55%	45%

### Building Overview

Address: 8551 New Hope Rd, Grants Pass, OR 97527

Site Size: 19.5 acres

Original Construction Year: 1962

Age: 57 Years


Student Capacity (main facility): 411
2007 Enrollment: 499
2018 Enrollment: 402
Portable Teaching Spaces: 0

Current Total Square Footage: 62,391 square feet Replacement Cost (as is): \$27.5 million


#### **Select Site Conditions**

	Sufficient but in	
Fields	poor condition	
		Needs
		additional
		bus parking
Parking		and bus
availability	Not sufficient	parking
Presence of a		
bus loop	Sufficient	

### **Building Utilization**



0%



### Building Summary

Additional Spaces	This school building does not have a designated space for visual arts.
-------------------	--


Light and Windows | Most spaces assessed lack appropriate natural daylight, lighting control, and natural ventilation. There is also a lack of appropriate sound absorption and/or isolation.

Display There is a lack of any tackable surfaces in assessed spaces.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Middle Classrooms Grades 6-8	Appropriate	Appropriate	Appropriate	These spaces have sufficient transparency, access control, wi-fi access, digital interactive display, digital display with casting, telephone/ intercom, and appropriate wall outlets. There is lacking flexibility, floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, white board writing surfaces, tackable surfaces, and a synchronized clock system.
Resource	Appropriate	Appropriate	Appropriate	This space has sufficient transparency, access control, white board surface, wi-fi access, telephone/ intercom, and appropriate wall outlets. There is room for improvement in the creation of a movable wall, flexibility, floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, tackable surfaces, digital interactive display, digital system with casting, and synchronized clock system.
Science Classroom	Appropriate	Appropriate	Appropriate	These spaces have sufficient transparency, access control, natural daylight, natural ventilation, water, wi-fi access, digital interactive display, digital system with casting, telephone/intercom, and appropriate outlets. There is lacking flexibility, flooring, wall, and ceiling finishes, lighting control, sound absorption, white marker board surfaces, tackable surfaces, and synchronized clock system.
Computer Lab	Appropriate	Appropriate	Appropriate	These spaces have sufficient transparency, access control, wi-fi access, telephone/ intercom, and appropriate outlets. There is lacking flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, white marker board surfaces, tackable surfaces, digital interactive display, digital system with casting, and synchronized clock system.
Life Skills	Undersized	Appropriate	Appropriate	These spaces have sufficient access control, flooring and ceiling finishes, white board surfaces, wi-fi access, digital interactive display, digital system with casting, telephone/ intercom, and appropriate outlets. There is lacking transparency, flexibility, wall finishes, natural daylight, lighting control, natural ventilation, lack of appropriate restroom access, water, tackable surfaces, and synchronized clock system.
Weight and Fitness Room	Appropriate	Room for Improvement	Room for Improvement	This space lacks appropriate transparency, access control, appropriate floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water, white board surface, wi-fi access, digital interactive display, digital system with casting, telephone/ intercom, synchronized clock system, and appropriate wall outlets.
Gym	Oversized	Appropriate	Generally Appropriate	These spaces have appropriate transparency, access control, and wi-fi access. There is lacking or insufficient flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restroom and water access, white board surface, digital interactive display, digital system with casting, telephone/ intercom, synchronized clock system, and appropriate wall outlets.



### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Cafeteria	Somewhat Undersized	Appropriate	Generally Appropriate	These spaces have appropriate transparency, access control, wall finish, and wi-fi access. There is lacking or insufficient flexibility, flooring, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restroom and water access, tackable surface, digital interactive display, digital system with casting, telephone/intercom, synchronized clock system, and appropriate wall outlets.
Library	Undersized	Appropriate	Generally Appropriate	These spaces have appropriate white board surface, wi-fi access, and appropriate wall outlets. There is lacking or insufficient transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, digital interactive display, digital system with casting, telephone/intercom, and synchronized clock system.
Band Room	Appropriate	Appropriate	Generally Appropriate	This space has appropriate access control, white board surface, wi-fi access, and telephone/ intercom. There is lacking or insufficient transparency, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, tackable surface, digital interactive display, digital system with casting, telephone/ intercom, synchronized clock system, and appropriate wall outlets.

### Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Insufficient
Middle Classrooms Grades 6-8	51%	49%
Resource	49%	51%
Science Classroom	54%	46%
Computer Lab	50%	50%
Life Skills	61%	39%
Weight and Fitness Room	11%	89%
Gym	39%	61%
Cafeteria	39%	61%
Library	43%	57%
Music	43%	57%

# Lorna Byrne Middle School

### Building Overview

**Address:** 102 S Junction Ave, Cave Junction, OR 97523

**Site Size:** 6 acres **Original Construction Year:** 1951, rebuilt 2003

Age: 16 Years


Student Capacity (main facility):3142007 Enrollment:2862018 Enrollment:316Portable Teaching Spaces:0


Current Total Square Footage: 70,047 square feet Replacement Cost (as is): \$30.8 million

#### **Select Site Conditions**

		Asphalt
Baskertball	Sufficient but in	needs
Courts	poor condition	replacing
Fields	Sufficient	
Parking		
availability	Sufficient	
Presence of a		
bus loop	Sufficient	

#### **Building Utilization**







## Lorna Byrne Middle School

### Building Summary

Additional Spaces This school building does not have a designated space for visual arts.

Access Control | There are insufficient locking systems for all spaces that were assessed.

Health and Comfort | There is a lack of sufficient lighting control in all spaces that were assessed. There are appropriate windows in assessed spaces, though they tend to no be operable, as there is a lack of access to natural ventilation.

Synchronized Clock System The synchronized clock system has been found to be insufficient in all assessed spaces.

# Lorna Byrne Middle School

### Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Middle Classrooms Grades 6-8	Appropriate	Appropriate	Generally Appropriate	These spaces have sufficient transparency, flexibility, floor, wall, and ceiling finishes, access to natural daylight, sound absorption, white board surfaces, tackable surfaces, wi-fi access, digital interactive display, telephone/ intercom, and appropriate wall outlets. There is lacking access control, lighting control, natural ventilation, and synchronized clock system.
Resource	Appropriate	Appropriate	Generally Appropriate	This space has sufficient transparency, flexibility, floor, wall, and ceiling finishes, access to natural daylight, sound absorption, white board surfaces, tackable surfaces, wi-fi access, telephone/ intercom, and appropriate wall outlets. There is lacking access control, a movable wall, wall padding, lighting control, natural ventilation, and synchronized clock system.
Science Classroom	Somewhat Undersized	Appropriate	Generally Appropriate	These spaces have sufficient transparency, flexibility, floor, wall, and ceiling finishes, access to natural daylight, sound absorption, water, white board surfaces, tackable surfaces, wi-fi access, digital interactive display, telephone/intercom, and appropriate wall outlets. There is lacking access control, lighting control, natural ventilation, and synchronized clock system.
Computer Lab	Appropriate	Appropriate	Generally Appropriate	These spaces have sufficient transparency, flexibility, floor, wall, and ceiling finishes, access to natural daylight, sound absorption, white board surfaces, tackable surfaces, wi-fi access, digital interactive display, telephone/ intercom, and appropriate wall outlets. There is lacking access control, lighting control, natural ventilation, and synchronized clock system.
Life Skills	Undersized	Appropriate	Generally Appropriate	These spaces have sufficient transparency, flexibility, floor, wall, and ceiling finishes, access to natural daylight, sound absorption, restroom and water access, white board surfaces, tackable surfaces, wi-fi access, telephone/ intercom, and appropriate wall outlets. There is lacking access control, lighting control, natural ventilation, digital interactive display, and synchronized clock system.
5th Grade Classroom	Appropriate	Appropriate	Room for Improvement	These spaces have sufficient transparency, flexibility, ceiling finishes, access to natural daylight, sound absorption, white marker board space, digital interactive display, telephone/ intercom, and appropriate wall outlets. There is room for improvement in the access control, access to a movable wall, floor and wall finishes, lighting control, natural ventilation, water, and access to a digital system with casting.
Gym	Somewhat Undersized	Appropriate	Generally Appropriate	This space has sufficient transparency, floor, wall, and ceiling finishes, sound absorption, water, wi-fi access, telephone/ intercom, and appropriate wall outlets. It is lacking a movable wall, access control, natural daylight, lighting control, natural ventilation, restroom access, tackable surface, and a synchronized clock system.
Cafeteria	Oversized	Appropriate	Generally Appropriate	This space is oversized for the current enrollment count. It is sufficient in terms of transparency, its floor, wall, and ceiling finishes, sound absorption, water and wi-fi access, telephone/ intercom, and appropriate wall outlets. There is room for improvement considering the space's access control, lighting control, natural ventilation, restroom access, and system with casting.

# Lorna Byrne Middle School

## Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Cafeteria	Oversized	Appropriate	Generally Appropriate	This space is oversized for the current enrollment count. It is sufficient in terms of transparency, its floor, wall, and ceiling finishes, sound absorption, water and wi-fi access, telephone/ intercom, and appropriate wall outlets. There is room for improvement considering the space's access control, lighting control, natural ventilation, restroom access, and system with casting.
Library	Somewhat Oversized	Appropriate	Generally Appropriate	This space is sufficient in terms of transparency, flexibility, floor, wall, an ceiling finishes, natural daylight, sound absorption, tackable surfaces, wi-fi access, telephone/ intercom, and appropriate wall outlets. There is insufficient access control, lighting control, natural ventilation, water, digital interactive display, and asynchronized clock system.
Music Room	Somewhat Undersized	Appropriate	Generally Appropriate	This space has appropriate transparency, flexibility, ceiling finish, natural daylight, sound absorption, white board surface, tackable surface, wi-fi access, digital system with casting, telephone/ intercom, and appropriate wall outlets. There is lacking or insufficient access control, floor and wall finishes, lighting control, natural ventilation, water, digital interactive display, and synchronized clock system.

# Lorna Byrne Middle School

## Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Insufficient
Middle Classrooms Grades 6-8	78%	22%
Resource	70%	30%
Science Classroom	65%	35%
Computer Lab	71%	29%
Life Skills	60%	40%
Elementary Classrooms Grade 5	48%	52%
Gym	58%	42%
Cafeteria	50%	50%
Library	67%	33%
Music	59%	41%

# Hidden Valley High School & Alternative Center

## Building Overview

651 Murphy Creek Rd, Grants Pass, OR 97527

Site Size: 133.5 acres

**Original Construction Year:** 1976

43 Years Age:


Student Capacity (main facility): 868 2007 Enrollment: 877 2018 Enrollment: 572 **Portable Teaching Spaces:** 0


144,206 square feet Current Total Square Footage: \$ 67.9 million Replacement Cost (as is):

#### **Select Site Conditions**

Fields	Not sufficient	
		Need more
		lights, very
Parking		dark in
availability	Not sufficient	parking lot.
Presence of a		
bus loop	Sufficient	

## **Building Utilization**







D54

## Building Summary

Consistent Low Scoring Elements

On most elements that were assessed, there were consistently moderate to low scores for access control, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.




# Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Core / General Classroom	Somewhat Undersized	Appropriate	Generally Appropriate	In these spaces there is insufficient access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.
Resource	Appropriate	Appropriate	Generally Appropriate	In this spaces there is insufficient access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, sound absorption, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.
Science Classroom	Undersized	Appropriate	Generally Appropriate	In these spaces there is insufficient transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, sound absorption, water, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.
Science Lab	Oversized	Appropriate	Generally Appropriate	In these spaces there is insufficient transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, sound absorption, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.
Computer Lab	Appropriate	Appropriate	Room for Improvement	These spaces have insufficient transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.
Gym	Oversized	Appropriate	Room for Improvement	These spaces have insufficient movable walls, transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, restroom and water access, white marker board surfaces, tackable surfaces, digital system with casting, telephone/ intercom, synchronized clock system, and appropriate wall outlets.
Weight Room	Appropriate	Generally Appropriate		This space has insufficient transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, access to water, white marker board surfaces, tackable surfaces, digital system with casting, synchronized clock system, and appropriate wall outlets.

## Educational Adequacy Assessment


Space	Size	Adjacencies	Safety & Security	Improvement Areas
Cafeteria	Oversized	Appropriate	Room for Improvement	The cafeteria is more than double the recommended size for this space type, considering the enrollment count of the school. The student dining area has insufficient transparency, access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Library	Oversized	Appropriate	Appropriate	The media center is approximately double the recommended size for this space type, considering the enrollment count of the school. This space has insufficient access control, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, white marker board surfaces, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Visual Arts	Appropriate	Appropriate	More Safe & Secure	This space has insufficient access control, wall and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, white marker board surfaces, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Music: Band and Chorus	Appropriate	Appropriate	More Safe & Secure	The music space has insufficient access control, flexibility, floor, wall and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display system, digital system with casting, synchronized clock system, and appropriate wall outlets.
Career Tech: Manufacturing Woods and Metals	Somewhat Oversized	Appropriate	Generally Appropriate	These spaces have insufficient access control, flexibility, wall and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, general exhaust system, white marker board surfaces, tackable surfaces, wi-fi, telephone/ intercom, synchronized clock system, and appropriate wall outlets.



# Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Insufficient
Core/ general Classroom	54%	46%
Resource: ERC, ED	43%	57%
Science Classroom	46%	54%
Science Lab	41%	59%
Computer Lab	32%	68%
Gym	29%	71%
Weight Room	30%	70%
Cafeteria	35%	65%
Library	54%	46%
Art	40%	60%
Music	39%	61%
Career Tech Education: Manufacturing Woods and Metals	42%	58%



## Building Overview

Address: 625 E River St, Cave Junction, OR 97523

Site Size: 22.39 acres

Original Construction Year: 1975

Age: 44 Years


Student Capacity (main facility): 476
2007 Enrollment: 499
2017 Enrollment: 412
Portable Teaching Spaces: 3

Current Total Square Footage: 104,093 square feet Replacement Cost (as is): \$49.0 million


#### **Select Site Conditions**

		Poor drainage
	Sufficient but in	and lack of
Fields	poor condition	irrigation.
Parking		
availability	Sufficient	
Presence of a		
bus loop	Sufficient	

#### **Building Utilization**



0%





## Building Summary

Additional Spaces

Unlike its other high school counterparts in the district, Illinois Valley does not have a science lab space, only science classrooms.

Access Control


There is insufficient access control in all assessed spaces. This means that most or all classrooms and learning spaces do not have sufficient locking mechanisms.

Comfort and Health

Almost all assesses spaces had insufficient access to natural daylight, lighting control, natural ventilation, and sound absorption.


## Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Core / General Classroom	Undersized	Appropriate	Generally Appropriate	In these spaces there is insufficient access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Resource	Undersized	Appropriate	Generally Appropriate	These spaces have insufficient access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Science Classroom	Undersized	Appropriate	Generally Appropriate	These spaces have insufficient access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Computer Lab	Somewhat Undersized	Appropriate	Generally Appropriate	These spaces have insufficient access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Gym	Oversized	Appropriate	Room for Improvement	This space has insufficient or lacking movable wall, access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, restroom access, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Weight Room	Appropriate	Generally Appropriate	Room for Improvement	In this space, there is insufficient access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water, tackable surfaces, wi-fi, digital system with casting, telephone, synchronized clock system, and appropriate wall outlets.
Cafeteria	Oversized	Appropriate	More Safe & Secure	The cafeteria is more than double the recommended size for this space type, considering the enrollment count of the school. The student dining area has insufficient access control, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, water and restroom access, white marker board surfaces, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.



## Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Library	Oversized	Appropriate	Generally Appropriate	The media center is approximately forty percent larger than the recommended size for this space type, considering the enrollment count of the school. This space has insufficient access control, flexibility, flooring, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, white marker board surfaces, tackable surfaces, wi-fi, digital interactive display, digital system with casting, synchronized clock system, and appropriate wall outlets.
Visual Arts	Somewhat Oversized	Appropriate	Generally Appropriate	This space has insufficient access control, flexibility, floor, wall and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, tackable surfaces, wi-fi, digital system with casting, synchronized clock system, and appropriate wall outlets.
Music: Band and Chorus	Appropriate	Appropriate	Generally Appropriate	The music space has insufficient access control, flexibility, floor, wall and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, tackable surfaces, wi-fi, digital interactive display system, digital system with casting, synchronized clock system, and appropriate wall outlets.
Career Tech: Manufacturing Woods and Metals	Somewhat Oversized	Appropriate	Generally Appropriate	This space has insufficient transparency, access control, flexibility, floor, wall, and ceiling finishes, natural daylight, lighting control, natural ventilation, sound absorption, water access, general exhaust system, white marker board surfaces, tackable surfaces, wi-fi, telephone/intercom, synchronized clock system, and appropriate wall outlets.
				Portables
Portables: Life skills, Alt Center, and Art			Th	ese spaces are generally considered educationally inadequate.



## Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Insufficient
Core/ general Classroom	62%	38%
Resource: ERC, ED	61%	39%
Science Classroom	57%	43%
Computer Lab	62%	38%
Gym	46%	54%
Weight Room	41%	59%
Cafeteria	46%	54%
Library	50%	50%
Art	54%	46%
Music	54%	46%
Career Tech Education: Manufacturing Woods and Metals	49%	51%

#### Portable Spaces

	Sufficient	Insufficient
Lifeskills	49%	51%
Alternative Center	54%	46%
Visual Arts	55%	45%

## Building Overview

6741 Monument Dr, Grants Pass, OR 97526

Site Size: 109.75 acres

**Original Construction Year:** 1976

43 Years Age:


Student Capacity (main facility): 504 2007 Enrollment: 718 2018 Enrollment: 452 **Portable Teaching Spaces:** 1

Current Total Square Footage: 136,741 square feet \$64.3 million Replacement Cost (as is):


#### **Select Site Conditions**

Fields	Not sufficient	
		Need more
Parking		lighting in
availability	Not sufficient	parking area.
Presence of a		
bus loop	Sufficient	

#### **Building Utilization**



0%





D64

## Building Summary

Additional Spaces

Unlike its other high school counterparts in the district, North Valley does not have a visual arts space. There are also no resource spaces, other than the Career Center.


Oversized Spaces

Considering the enrollment of North Valley, there are various spaces that have been found to be oversized, such as the gymnasium spaces and library.



## Educational Adequacy Assessment

Space	Size	Adjacencies	Safety & Security	Improvement Areas
Core / General Classroom	Appropriate	Appropriate		In these spaces there is insufficient access control, floor and wall finishes, sound absorption, white marker board surfaces, telephone/ intercom, and synchronized clock system.
Science Classroom	Undersized	Appropriate	Room for Improvement	There is insufficient flexibility, flooring and wall finishes, natural ventilation, sound absorption, water, white marker board surfaces, digital system with casting, telephone/intercom, and synchronized clock system.
Science Lab	Oversized	Appropriate	Generally Appropriate	In this space there is insufficient flexibility, flooring, wall, and ceiling finishes, natural ventilation, sound absorption, water, general exhaust system, white marker board surfaces, tackable surfaces, digital interactive display, digital system with casting, telephone/ intercom, and synchronized clock system.
Computer Lab	Appropriate	Appropriate	Appropriate	This space has insufficient transparency, flexibility, floor, wall, and ceiling finishes, sound absorption, and digital interactive display.
Gym	Oversized	Appropriate	Room for Improvement	These spaces are sized for roughly 1,000 students or more, but served an enrollment of 512 in 2017. They have insufficient movable walls, transparency, flexibility, restroom access, white marker board surfaces, tackable surfaces, digital system with casting, telephone/ intercom, and synchronized clock system.
Weight Room	Somewhat Oversized	Generally Appropriate	More Safe & Secure	This space has insufficient transparency, flexibility, flooring, wall, and ceiling finishes, lighting control, natural ventilation, sound absorption, white marker board surfaces, tackable surfaces, telephone/ intercom, synchronized clock system, and appropriate wall outlets.
Cafeteria	Somewhat Oversized	Appropriate	Generally Appropriate	The student dining area has insufficient transparency, flexibility, flooring, wall, and ceiling finishes, natural daylight, sound absorption, white marker board surfaces, tackable surfaces, digital system with casting, telephone/intercom, synchronized clock system, and appropriate wall outlets.



## Educational Adequacy Assessment

Space	Size	Adjacencies	Safety &	Improvement Areas					
Space	Security		Security	improvenient rifeas					
				The media center is appropriately sized for roughly 1,200 students, as compared to the 512 enrolled in 2017,					
Library	Oversized	Appropriate	Appropriate f	making it more than double the recommended size. This space has insufficient transparency, access control,					
Library	Oversized	Appropriate		flexibility, flooring finish, natural ventilation, sound absorption, water access, telephone/ intercom, and					
				synchronized clock system.					
	Somewhat Oversized	Appropriate	More Safe & Secure	The music spaces have insufficient flexibility, flooring finish, water access, white marker board surfaces,					
Music: Band and Chorus				tackable surfaces, wi-fi, digital interactive display system, digital system with casting, telephone/ intercom,					
				synchronized clock system, and appropriate wall outlets.					
Career Tech: Manufacturing	Somewhat	Appropriate	More Safe &	These spaces have insufficient, flexibility, floor, wall, and ceiling finishes, natural daylight, lighting control,					
Woods and Metals	Oversized			genreal exhaust system, and tackable surfaces.					
WOOds and Wetais	Oversized		occure	general extratest system, and acknown surfaces.					
				Portables					
Doutshis Cossis Education									
Portables: Special Education			In	ese spaces are generally considered educationally inadequate.					

## Educational Adequacy Assessment

### **Existing Spaces**

	Sufficient	Insufficient
Core / General Classroom	77%	23%
Science Classroom	65%	35%
Science Lab	64%	36%
Computer Lab	74%	26%
Gym	68%	32%
Weight Room	50%	50%
Cafeteria	47%	53%
Library	73%	27%
Music: Band and Chorus	75%	25%
Career Tech Education: Manufacturing Woods & Meta	66%	34%

#### Portable Spaces

	Sufficient	Insufficient
Life Skills (Self-Contained Special Eudcation Classroom	33%	67%



# Physical Assessment by Facility

<b>District Name:</b>	Three Rivers
Site Name:	Applegate ES
<b>Building Name:</b>	Applegate ES
<b>Building ID:</b>	

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

			Г			LEVEL OF ACTION			1			
									% of		Necessity	
			% of Building						System or	<b>Automated Budget</b>	Rank	
Level 1 Level 2	Level 3	Type (as applicable)	or Number	None	Minor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCTUI	RE											
A10 Fou	<u>ındations</u>								-		-	
	A1010 Standard Foundations		30%	x None	Minor	Moderate	Major	Replace		\$0		No Issues, Portables
	A1020 Special Foundations		30%	x None	Minor	Moderate	Major	Replace		\$0		No Issues, 1912 Bldg, Seismic upgrade 2010
	A1030 Slab on Grade		40%	x None	Minor	Moderate	Major	Replace		\$0		No Issues, Gym and Classrooms
A20 Base	ement Construction						_				_	
	A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace				<u>.                                      </u>
	A2020 Basement Walls		30%	x None	Minor	Moderate	Major	Replace		\$0		No Issues, 1912 Bldg
B SHELL												
<u>B10 Sup</u>	<u>erstructure</u>						_					
	B1010 Floor Construction	Wood	-	x None	Minor	Moderate	Major	Replace		\$0		No Issues, 1912 Bldg and Portables
		Steel		o None	Minor	Moderate	Major	Replace		\$0		
		Concrete		o None	Minor	Moderate	Major	Replace		\$0		
	B1020 Roof Construction	Wood		x None	Minor	Moderate	Major	Replace		\$0		No Issues
		Steel	<b>!</b>	o None	Minor	Moderate	Major	Replace		\$0		
		Concrete		o None	Minor	Moderate	Major	Replace		\$0		
B20 Exte	<u>erior Enclosure</u>			_			_		· · · · · · · · · · · · · · · · · · ·			
	B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor		Major	Replace		\$0		
		Masonry		x None	Minor	x Moderate	Major	Replace	20%	\$33,417	S	Old Main Bldg
		Framed w/Panel Siding		x None	Minor	x Moderate	Major	Replace	50%	\$35,804	S	Water damage, Portables siding
		Framed w/Stucco		o None	Minor	Moderate	Major	Replace		\$0		
		Framed w/Masonry Veneer		o None	Minor	Moderate	Major	Replace		\$0		
	B2020 Exterior Windows	Wood	50%	x None	Minor	Moderate	Major	x Replace	100%	\$397,820	l	1912 Main Bldg, wood rot and age
		Aluminum/Steel		x None	Minor	x Moderate	Major	Replace	100%	\$99,455	l	Classrooms and Portable window repairs
		Clad		o None	Minor	Moderate	Major	Replace		\$0		
		Curtain Wall		o None	Minor	Moderate	Major	Replace		\$0		
	B2030 Exterior Doors	Wood	22	x None	Minor	Moderate	Major	x Replace	100%	\$35,211	<u> </u>	Replace all
		Hollow Metal	21	x None	Minor	Moderate	Major	x Replace	10%	\$2,913	l	Multipurpose room, 2 doors
D20 D	c	Storefront		o None	Minor	Moderate	Major	Replace		\$0		
B30 Roo		A amb alt Chinala	1000/	Nama	DA:	DA a da wata	N4=:==	Danilaaa	000/	¢222.770		Gym, Classrooms, Portables
	B3010 Roof Coverings	Asphalt Shingle		x None	Minor	Moderate	Major	x Replace	80%	\$222,779	l e	Gym, Classrooms, Portables
		Built-Up		o None	Minor	Moderate	Major	Replace		\$0		
		Single Ply		o None	Minor	Moderate	Major	Replace		\$0		
		Metal	-	o None	Minor	Moderate	Major	Replace		\$0 \$0		
	P2020 Poof Openings	Concrete Tile		o None	Minor	Moderate	Major	Replace		\$0 \$0		
	B3020 Roof Openings	Skylights	<b>!</b>	o None	Minor	Moderate	Major	Replace		\$0 \$0		
CINTEDIODS		Access Hatch	-	o None	Minor	Moderate	Major	Replace		\$0		
C INTERIORS	erior Construction											
CIOIIIIE	C1010 Partitions	Framed	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	CTOTO I GLUMONS	Masonry		o None	Minor	Moderate		Replace		\$0 \$0		110 155465
		iviasuili y		o mone	IVIIIIOI	Moderate	iviajui	neplace		Ų		

C1020 Interior Doors	Wood	37 x N	one Mir	nor Moderate	Major	Replace		\$0	No Issues, 37 each
	Hollow Metal	5 x N	one Mir	nor Moderate	Major	Replace		\$0	No Issues, 5 each
C1030 Fittings	NOT USED	N	one Mir	nor Moderate	Major	Replace			
C20 Stairs						<u> </u>			
C2010 Stair Construction	Wood	4 x N	one Mir	nor Moderate	Major	Replace		\$0	No Issues
	Metal	o N	one Mir	nor Moderate	Major	Replace		\$0	
	Concrete	4 x N	one Mir	nor Moderate	Major	Replace		\$0	No Issues
62020 61 1 51 1 1	0	500/						40	No leaves. Demaining are wood, no stair fin
C2020 Stair Finishes	Concrete Fill Resilient		one Mir one Mir		Major Major	Replace Replace		\$0 \$0	No Issues. Remaining are wood , no stair fin
C30 Interior Finishes	Resilient	111	IVIII	Moderate	iviajoi	Керіасе		70	
C3010 Wall Finishes	Paint on Masonry	o N	one Mir	nor Moderate	Major	Replace		\$0	
C3010 Wall Fillishes	•				_		100%		Repair and paint all interior finishes
	Wallboard	100% x N			_	x Replace	100%	\$238,692	repair and paint all interior finishes
	Wainscot	o No			-	Replace		\$0	
	Ceramic Tile	o N			_	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	79% x N				x Replace	100%	\$183,853	Replace carpet, all buildings
	Resilient Tile	14% x N			Major	x Replace	100%	\$30,632	I Gym
	Resilient Sheet	7% x N		nor Moderate	_	x Replace	80%	\$13,367	I Multipurpose Room
	Polished Concrete	o N	one Mir	nor Moderate	Major	Replace		\$0	
	Ceramic Tile	o N	one Mir	nor Moderate	Major	Replace		\$0	
	Liquid Applied	o Ne	one Mir	nor Moderate	Major	Replace		\$0	
	<b>Wood Sports Floor</b>	o N	one Mir	nor Moderate	Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	10% x N	one Mir	nor Moderate	Major	Replace		\$0	No Issues
	Lay-In Ceiling Tile	80% x N	one Mir	nor Moderate	Major	Replace		\$0	No Issues
	Glued-Up Ceiling Tile		one Mir		Major	x Replace	100%	\$8,951	I Age, failing/falling tiles
	Painted Structure	5% x N			-	Replace		\$0	No Issues
VICES								·	
D10 Conveying									
D1010 Elevators & Lifts		o N	one Mir	nor Moderate	Maior	Replace		\$0	
D1020 Escalators & Moving	Walks	o N			_	Replace		\$0	
D1090 Other Conveying Sys		o N			-	Replace		\$0	
D20 Plumbing	icems	- O IN	IVIII	Wioderate	IVIAJOI	Керіасс		70	
D2010 Plumbing Fixtures		100% x N	one Mir	nor Moderate	Major	x Replace	80%	\$222,779	I 1912 Bldg, Gym area, 76 total count
D2010 Flumbling Fixtures  D2020 Domestic Water Dis	ribution	100% X N		<b>——</b>	-	Replace	8076	\$0	No Issues
D2020 Domestic Water Dis	indution				<u> </u>		$\vdash$	\$0 \$0	No Issues
D2030 Sallitary Waste		100% x N	one Mir	nor Moderate	iviajoi	Replace		<b>3</b> 0	NO 135de5
D2040 Daire Western Duning		- N	D 4:	NA - dayadaya	N 4 = : = :	Daralaga		ĊO	
D2040 Rain Water Drainage		o No			<u> </u>	Replace		\$0	
D2090 Other Plumbing Syst			one Mir		-	Replace Replace		\$0	
D2090 Other Plumbing Syst		N	one Mir	nor Moderate	Major	Replace			Natara
D2090 Other Plumbing Syst D30 HVAC D3010 Energy Supply	ems NOT USED	100% x N	one Mir	mor Moderate  Moderate	Major Major	Replace Replace		<b>\$</b> 0	No Issues
D2090 Other Plumbing Syst	ems NOT USED tems Boiler	100% x No	one Mir one Mir	nor Moderate nor Moderate nor Moderate	Major Major Major	Replace Replace Replace		\$0 \$0	No Issues
D2090 Other Plumbing Syst D30 HVAC D3010 Energy Supply	ems NOT USED tems Boiler Air Handler	100% x No	one Mir one Mir one Mir one Mir	mor Moderate mor Moderate mor Moderate mor Moderate mor Moderate	Major Major Major Major Major	Replace Replace Replace Replace		\$0 \$0 \$0	
D2090 Other Plumbing Syst D30 HVAC D3010 Energy Supply	ems NOT USED tems Boiler	100% x No	one Mir one Mir one Mir one Mir one Mir	mor Moderate mor Moderate mor Moderate mor Moderate mor Moderate mor Moderate	Major Major Major Major Major	Replace Replace Replace Replace Replace x Replace	100%	\$0 \$0 \$0 \$79,564	No Issues    All buildings
D2090 Other Plumbing Syst D30 HVAC D3010 Energy Supply	ems NOT USED tems Boiler Air Handler	100% x No	one Mir one Mir one Mir one Mir one Mir	mor Moderate mor Moderate mor Moderate mor Moderate mor Moderate mor Moderate	Major Major Major Major Major Major	Replace Replace Replace Replace	100%	\$0 \$0 \$0	
D2090 Other Plumbing Systems D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems	ems NOT USED  tems Boiler Air Handler Furnace	100% x No	one Mir	mor Moderate	Major Major Major Major Major Major Major	Replace Replace Replace Replace Replace x Replace	100%	\$0 \$0 \$0 \$79,564	
D2090 Other Plumbing Systems D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems	ems NOT USED  tems Boiler Air Handler Furnace Heat Exchanger	100% X NO	one Mir	mor Moderate	Major Major Major Major Major Major Major Major Major	Replace Replace Replace Replace X Replace Replace	100%	\$0 \$0 \$0 \$79,564 \$0	
D2090 Other Plumbing Systems D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems	tems NOT USED  tems Boiler Air Handler Furnace Heat Exchanger Syster Component of air handler Stand alone chiller	100% X NO	one Mir	mor Moderate	Major	Replace Replace Replace Replace x Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$79,564 \$0 \$0	
D2090 Other Plumbing Systems D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3030 Cool	tems NOT USED  tems Boiler Air Handler Furnace Heat Exchanger Syster Component of air handler Stand alone chiller	100% X NO	one Mir	mor Moderate	Major	Replace Replace Replace Replace x Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$79,564 \$0 \$0	I All buildings
D2090 Other Plumbing Systems  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating  D3040 Distribution Systems	tems Boiler Air Handler Furnace Heat Exchanger Syster Component of air handler Stand alone chiller Ductwork	100% X NO	one Mir	mor Moderate	Major	Replace Replace Replace Replace x Replace Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$79,564 \$0 \$0 \$0	I All buildings
D2090 Other Plumbing Systems  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating  D3040 Distribution Systems	tems Boiler Air Handler Furnace Heat Exchanger Syster Component of air handler Stand alone chiller Ductwork Hot water return & supply	100% X NO	one Mir	mor Moderate	Major	Replace Replace Replace Replace x Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$79,564 \$0 \$0 \$0 \$0	I All buildings

D3060 Controls & Instrumental	ion	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3070 Systems Testing & Balan		100% x None	Minor	Moderate Major	x Replace	100%	\$39,782	
D3090 Other HVAC Systems & I	<del>-</del>	None	Minor	Moderate Major	Replace	10070	ψ03), 0 <u>2</u>	
D40 Fire Protection	-4			aje:	Портиос			
D4010 Sprinklers		o None	Minor	Moderate	Replace		\$0	
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialti	es	o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Sy		None	Minor	Moderate Major	Replace		, -	
D50 Electrical				,	•			
D5010 Electrical Service & Distr	ribution	100% x None	Minor	Moderate Major	x Replace	20%	\$63,651	I Kitchen area panelboards
D5020 Lighting and Branch Wir	ing	100% x None	Minor	Moderate Major	x Replace	100%	\$477,384	All buildings, old wiring and fixtures
D5030 Communications & Secu	=	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0	
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0	
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace		\$0	
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace			
				<del>_</del> _				<del>-</del>
E EQUIPMENT & FURNISHINGS								
E10 Equipment				<u></u>				
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$79,564	Old equipment
	Vocational	o None	Minor	Moderate Major	Replace		\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0	
	Art	o None	Minor	Moderate Major	Replace		\$0	
	Stage Performance	600 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	x Replace	100%	\$994,551	All Buildings
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Replace			
E20 Furnishings			_		_			
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
E2020 Movable Furnishings		100% x None	Minor	Moderate	Replace		\$0	No Issues
SPECIAL CONSTRUCTION & DEMOLITION - NO	T USED							
BUILDING SITE WORK	NOT USED							
G10 Site Preparation G20 Site Improvements	NOT USED							
G2010 Roadways		8931 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2020 Parking Lots		24447 x None	Minor	Moderate Major	x Replace	100%	\$169,552	Total failure of gravel and asphalt system
G2030 Pedestrian Paving		3100 x None	Minor	Moderate Major	Replace	100/0	\$109,532	No Issues
G2040 Site Development		1878 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2050 Landscaping		55882 x None	Minor	Moderate Major	Replace		\$0	No Issues
G30 Site Mechanical Utilities		33002 A 140116	WIIIIOI	widjoi	Першее		Ψ0	
G3010 Water Supply	Domestic	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
55010 Water Supply	Fire	o None	Minor	Moderate Major	Replace		\$0	1
G3020 Sanitary Sewer	· •	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
G3030 Storm Sewer		o None	Minor	Moderate Major	Replace		\$0	<del>                                     </del>
G3040 Heating Distribution		o None	Minor	Moderate Major	Replace		\$0	<del>                                     </del>
G3050 Cooling Distribution		o None	Minor	Moderate Major	Replace		\$0	<del>                                     </del>
· ·					<u> </u>			State of Orego

G3060 Fuel Distribution	o None Minor	Moderate	Major	Replace	\$0		
G3090 Other Site Mechanical Uti NOT USED	None Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities							
G4010 Electrical Distribution Service	o None Minor	Moderate	Major	Replace	\$0		
Generator	o None Minor	Moderate	Major	Replace	\$0		
G4020 Site Lighting	o None Minor	Moderate	Major	Replace	\$0		
G4030 Site Communications & Security	o None Minor	Moderate	Major	Replace	\$0		
G4090 Other Site Electrical Utiliti NOT USED	None Minor	Moderate	Major	Replace			
G90 Other Site Construction NOT USED	<del></del>						
OTHER							
		Unit of		Unit		Rank	
<u>Description of System</u>		 Measure	Quantity	Budget	Extended	(I,S,L)	Notes
					\$0		
					\$0		
					\$0		
					\$0		
					\$0		
					\$0		
					ΨO		

Physical Condition Budget Sub-Total \$3,429,722
Budgeted Development Costs \$1,303,294
Physical Condition Budget TOTAL \$4,733,016

Replacement Budget \$15,564,206

<b>District Name:</b>	Three Rivers/Josephine County SD
Site Name:	Evergreen ES

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

Site Name: Evergreen ES

Building Name:
Building ID:

			Γ				EVEL OF ACTION						
							LVLL OF ACTION			% of		Necessity	
			% of Building							System or	Automated Budget	Rank	
Level 1 Level 2	Level 3	Type (as applicable)	or Number	None	N	/linor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCTU	URE												
<u>A10 For</u>	<u>undations</u>							_					
	A1010 Standard Foundations		10%	x None	Min		Moderate	Major	Replace		\$0		No Issues
	A1020 Special Foundations			o None	Min	nor	Moderate	Major	Replace		\$0		
	A1030 Slab on Grade		90%	x None	Min	nor	Moderate	Major	Replace		\$0		No Issues
<u>A20 Ba</u>	sement Construction												
	A2010 Basement Excavation	NOT USED		None	Min		Moderate	Major	Replace				
	A2020 Basement Walls			o None	Min	nor	Moderate	Major	Replace		\$0		
B SHELL													
<u>B10 Sur</u>	perstructure			<b></b>				<b>.</b>	<b>—</b> а.		40		T
	B1010 Floor Construction	Wood		o None	Min		Moderate	Major	Replace		\$0		
		Steel	1000/	o None	Min		Moderate	Major	Replace		\$0		100/ Consults 000/ Clab on grade Na leaves
	D4000 D	Concrete	100%	x None	Min		Moderate	Major	Replace		\$0		10% Concrete, 90% Slab on grade, No Issues
	B1020 Roof Construction	Wood	100%	x None	Min		Moderate	Major	Replace		\$0		No Issues
		Steel		o None	Min		Moderate	Major	Replace		\$0 \$0		
D20 Fv/	torior Foologyro	Concrete		o None	Min	ior	Moderate	Major	Replace		\$0		
BZU EXL	terior Enclosure B2010 Exterior Walls	Concrete Formed / Tilt		o None	Min	or	Moderate	Major	Poplace		ćo		T
	B2010 Exterior Walls	·	75%	x None	Min		Moderate	Major	Replace Replace		\$0 \$0		No Issues
		Masonry Framed w/Panel Siding	25%	x None	Min		Moderate	Major	x Replace	100%	\$450,877	1	Moisture damage, rot, age
		Framed w/Stucco	25%	o None	Min		Moderate	Major	Replace	100%	\$430,877	!	Moisture damage, rot, age
		Framed w/Masonry Veneer		o None	Min		Moderate	Major	Replace		\$0		
	B2020 Exterior Windows	Wood	75%	x None	Min		Moderate	Major	x Replace	100%	\$901,754	1	Moisture damage, age, original windows
	B2020 Exterior Williams	Aluminum/Steel	25%	x None	Min		Moderate	Major	x Replace	100%	\$195,380	ı I	Age, 53 years old, single pane
		Clad	2370	o None	Min		Moderate	Major	Replace	10070	\$133,380	<u>'</u>	rige, 33 years old, single pune
		Curtain Wall		o None	Min		Moderate	Major	Replace		\$0		
		Curtain waii		0 None	10111	101	Wioderate	Iviajoi	Періасе		γo		
	B2030 Exterior Doors	Wood	53	x None	Min	nor	Moderate	Major	x Replace	100%	\$84,827	l,	Moisture damage, delamination, original doors
	22000 2Attainer 20010	Hollow Metal	9	x None	Min		Moderate	Major	x Replace	100%	\$12,484	i	53 year old doors
		Storefront		o None	Min		Moderate		Replace		\$0		, , , , , , , , , , , , , , , , , , ,
<u>B30 Ro</u>	ofing										1 -		
	B3010 Roof Coverings	Asphalt Shingle	10%	x None	Min	nor	Moderate	Major	x Replace	50%	\$21,041	S	2 Portables C & D
	g	Built-Up	90%	x None	Min		Moderate	Major	x Replace	100%	\$541,052	ı	Leaks, poor condition
		Single Ply		0 None	Min		Moderate	Major	Replace		\$0		
		Metal		0 None	Min		Moderate	Major	Replace		\$0		
		Concrete Tile		0 None	Min	nor	Moderate	Major	Replace		\$0		
	B3020 Roof Openings	Skylights		0 None	Min	nor	Moderate	Major	Replace		\$0		
		Access Hatch		0 None	Min	nor	Moderate	Major	Replace		\$0		
C INTERIORS													
<u>C10 Int</u>	erior Construction												
	C1010 Partitions	Framed	100%	x None	Min	nor	Moderate	Major	Replace		\$0		No Issues

	Masonry	o None	Minor	Moderate Major	Replace		\$0	
C1030 Interior Decre	· · · · · · · · · · · · · · · · · · ·					1000/		C Ago woor
C1020 Interior Doors	Wood	134 x None	Minor	Moderate Major	x Replace	100%	\$185,871	S Age, wear
	Hollow Metal	1 x None	Minor	Moderate Major	Replace		\$0	No Issues
C1030 Fittings	NOT USED	None	Minor	Moderate	Replace			
C20 Stairs								
C2010 Stair Construction	Wood	2 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate	Replace		\$0	
	Resilient	100% x None	Minor	<b>Moderate</b> Major	Replace		\$0	No Issues
C30 Interior Finishes								
C3010 Wall Finishes	Paint on Masonry	39% x None	Minor	Moderate Major	x Replace	100%	\$46,891	S Age, repaint
	, Wallboard	60% x None	Minor	Moderate Major	x Replace	100%	\$216,421	Minor repairs, repaint
	Wainscot	o None	Minor	Moderate Major	Replace		\$0	
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace		\$0	No Issues, in showers
C3020 Floor Finishes	Carpet / Soft Surface	60% x None	Minor	Moderate Major	x Replace	100%	\$211,010	Wear, age
C3020 Floor Finishes	•				x Replace	100%	\$119,031	Wear, age
	Resilient Tile		Minor	Moderate Major				Kitchen area, wear
	Resilient Sheet	1% x None	Minor	Moderate Major	x Replace	100%	\$3,607	
	Polished Concrete	2% x None	Minor	Moderate	Replace		\$0	No Issues
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	17% x None	Minor	Moderate	x Replace	100%	\$86,869	S Repaint
	Lay-In Ceiling Tile	1% x None	Minor	Moderate	Replace		\$0	No Issues, 2010 install
	Glued-Up Ceiling Tile	80% x None	Minor	Moderate	x Replace	100%	\$216,421	Stained, age, failing and falling tiles
	Painted Structure	2% x None	Minor	<b>Moderate</b> Major	Replace		\$0	No Issues
D SERVICES				<del></del>				
D10 Conveying								
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving \	Walks	o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Syste		o None	Minor	Moderate Major	Replace		\$0	
D20 Plumbing		itolic	············	inidaci dec	Neplace		Ψ0	
<u>D20 Flumbling</u>								Count = 148, replace old fixtures throughout the
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Major	x Replace	75%	\$315,614	building
_	ihutiaa					100%	\$180,351	Rusty water, original pipe
D2020 Domestic Water Distr	ibution		Minor		x Replace			Original SS pipe system
D2030 Sanitary Waste		100% x None	Minor	Moderate Major	x Replace	100%	\$180,351	original 33 pipe system
D2040 Rain Water Drainage		o None	Minor	Moderate Major	Replace		\$0	
D2090 Other Plumbing Syste	ms NOT USED	None	Minor	Moderate	Replace			
D30 HVAC			_					
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3020 Heat Generating Syste	ems Boiler	80% x None	Minor	Moderate Major	x Replace	100%	\$192,374	Replace 2 original boilers, beyond service life
	Air Handler	80% x None	Minor	Moderate Major	x Replace	100%	\$144,281	I Equipment beyond service life
	Furnace	10% x None	Minor	Moderate Major	x Replace	100%	\$12,023	In the 1951 building
	Heat Exchanger	10% x None	Minor	Moderate Major	Replace		\$0	No Issues, Portables installed 2018 and 2015
D3030 Cooling Generating Sy	ste Component of air handler	o None	Minor	Moderate Major	Replace		\$0	
	Stand alone chiller	o None	Minor	Moderate Major	Replace		\$0	
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate Major	x Replace	90%	\$108,210	All buildings except the 1951 bldg.
,	Hot water return & supply	100% x None	Minor	Moderate Major	x Replace	100%	\$300,585	I Beyond service life
D3050 Terminal & Package U		o None	Minor	Moderate Major	Replace		\$0	
	5			., , ,			•	State of Oregon

	In-room ventilator unit	o None	Minor	Moderate Major	Replace		\$0		
	In-room radiant unit	o None	Minor	Moderate Major	Replace		\$0		
D3060 Controls & Instrumental		100% x None	Minor	Moderate Major	Replace		\$0	No	Issues
D3070 Systems Testing & Balar	ncing	100% x None	Minor	Moderate Major	x Replace	100%	\$60,117	I Th	roughout the building
D3090 Other HVAC Systems &	E NOT USED	None	Minor	Moderate Major	Replace				
<u>D40 Fire Protection</u>									
D4010 Sprinklers		5% x None	Minor	Moderate	x Replace	100%	\$11,272	I Sta	nge Sprinkler System, age
D4020 Standpipes		5% x None	Minor	Moderate Major	x Replace	100%	\$6,012	I Sta	nge Sprinkler System, age
D4030 Fire Protection Specialti	es	5% x None	Minor	Moderate Major	x Replace	100%	\$6,012	I Sta	nge Sprinkler System, age
D4090 Other Fire Protection Sy	's NOT USED	None	Minor	Moderate Major	Replace				
D50 Electrical								_	
D5010 Electrical Service & Distr	ribution	100% x None	Minor	Moderate Major	x Replace	100%	\$480,935		iginal Westinghouse Equipment
D5020 Lighting and Branch Wir	ing	100% x None	Minor	Moderate Major	x Replace	100%	\$721,403		d wiring and fixtures
D5030 Communications & Secu	•	100% x None	Minor	Moderate Major	Replace		\$0	No	Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0		
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0		
	Access Control System	o None	Minor	Moderate Major	Replace		\$0		
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0		issues
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	x Replace	100%	\$135,263	I Pa	nel for Stage Sprinkler system
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace				
E EQUIPMENT & FURNISHINGS									
E10 Equipment	5 10 :	4000/				1000/	6420.224	ı Ira	rinment beyond convice life
E1010 Commercial Equipment		100% x None	Minor	Moderate Major	x Replace	100%	\$120,234	I Eq	uipment beyond service life
51020 la atitudi a del Familia de la	Vocational	o None	Minor	Moderate Major	Replace		\$0		
E1020 Institutional Equipment		o None	Minor	Moderate Major	Replace		\$0		
	Art Stage Performance	o None 1488 x None	Minor Minor	Moderate Major	Replace Replace		\$0 \$0	No	Issues
	=			Moderate Major		100%	\$1,502,923		unt = 148 fixtures
F1020 Vahigular Equipment	Restroom Accessories/Stalls NOT USED		Minor	Moderate Major	x Replace	100%	\$1,502,923	ı	JIIL – 140 IIXLUIES
E1030 Vehicular Equipment E1090 Other Equipment	NOT USED	None None	Minor Minor	Moderate Major Moderate Major	Replace Replace				
E20 Furnishings	NOT USED	None	IVIIIIOI	Moderate	Replace				
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$721,403	ı Ol	d and damaged cabinetry
E2020 Movable Furnishings		100% X None	Minor	Moderate Major	Replace	10076	\$0		Issues
F SPECIAL CONSTRUCTION & DEMOLITION - NO	TUSED	100% X None	IVIIIIOI	ividuelate	Керіасе		<del> </del>	INC	133003
3 ECIAL CONSTRUCTION & DEMOLITION - NO	1 0320								
G BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
G20 Site Improvements									
G2010 Roadways		o None	Minor	Moderate Major	Replace		\$0		
G2020 Parking Lots		60500 x None	Minor	Moderate Major	x Replace	100%	\$419,598	I Dr	ve lanes and lot, asphalt failure
G2030 Pedestrian Paving		11500 x None	Minor	Moderate Major	Replace		\$0	No	Issues
G2040 Site Development		2015 x None	Minor	Moderate Major	x Replace	100%	\$139,750	I 0	
G2050 Landscaping		120100 x None	Minor	Moderate Major	Replace		\$0	No	Issues
G30 Site Mechanical Utilities									
G3010 Water Supply	Domestic	100% x None	Minor	Moderate Major	Replace	100%	\$0	S Or	iginal Pipe system
	Fire	o None	Minor	Moderate Major	Replace		\$0		
G3020 Sanitary Sewer		100% x None	Minor	Moderate Major	Replace	100%	\$0	S Or	iginal SS Pipe system
G3030 Storm Sewer		o None	Minor	Moderate Major	Replace		\$0		
			<del></del>						State of Oregon

G3040 Heating Distribution	o None	Minor	Moderate	Major	Replace	\$0		
G3050 Cooling Distribution	o None	Minor	Moderate	Major	Replace	\$0		
G3060 Fuel Distribution	o None	Minor	Moderate	Major	Replace	\$0		
G3090 Other Site Mechanical U1NOT USED	None	Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities			<u>—</u>			_		
G4010 Electrical Distribution Service	o None	Minor	Moderate	Major	Replace	\$0		
Generator	o None	Minor	Moderate	Major	Replace	\$0		
G4020 Site Lighting	o None	Minor	Moderate	Major	Replace	\$0		
G4030 Site Communications & Security	o None	Minor	Moderate	Major	Replace	\$0		
G4090 Other Site Electrical Utilii NOT USED	None	Minor	Moderate	Major	Replace			
G90 Other Site Construction NOT USED								
OTHER								
			Unit of		Unit		Rank	
<u>Description of System</u>			Measure	Quantity	Budget	Extended	(I,S,L)	Notes
			4			\$0		
			4			\$0		
			4			\$0		
			4			\$0		
						\$0		
						\$0 \$0		

Physical Condition Budget Sub-Total \$9,052,246
Budgeted Development Costs \$3,439,853
Physical Condition Budget TOTAL \$12,492,099

Replacement Budget \$23,519,968

District Name:	Three Rivers/Josephine County SD	REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET
Site Name:	Fort Vannoy	An unused cell or system that should not receive direct user input
<b>Building Name:</b>	0	An automatically populated cell from user input elsewhere in the file - do not overwrite
<b>Building ID:</b>	0	

			[			LEVEL OF A	CTION			1			
										% of		Necessity	
			% of Building							System or	<b>Automated Budget</b>	Rank	
Level 1 Le	evel 2 Level 3	Type (as applicable)	or Number	None	Min	or Mod	erate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTR	RUCTURE												
<u>A1</u>	10 Foundations												
	A1010 Standard Foundations		10%	x None	Minor	Mode	rate	Major	Replace		\$0		No Issues
	A1020 Special Foundations			o None	Minor	Mode	rate	Major	Replace		\$0		
	A1030 Slab on Grade		90%	x None	Minor	Mode	rate	Major	Replace		\$0		No Issues
<u>A2</u>	20 Basement Construction												
	A2010 Basement Excavation	NOT USED		None	Minor	Mode	erate	Major	Replace				
	A2020 Basement Walls			o None	Minor	Mode	erate	Major	Replace		\$0		
B SHELL													
<u>B1</u>	10 Superstructure							_					
	B1010 Floor Construction	Wood		o None	Minor	Mode		Major	Replace		\$0		
		Steel		o None	Minor	Mode	erate	Major	Replace		\$0		
		Concrete	100%	x None	Minor	Mode	erate	Major	Replace		\$0		10% Concrete, 90% Slab on grade, No Issues
													Exposed ends of wood roof beams have moisture
	B1020 Roof Construction	Wood	100%	x None	Minor	Mode		Major	x Replace	10%	\$76,683	I	damage/rot
		Steel		o None	Minor	Mode	rate	Major	Replace		\$0		
		Concrete		o None	Minor	Mode	erate	Major	Replace		\$0		
<u>B2</u>	<u>20 Exterior Enclosure</u>												
	B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor			Major	Replace		\$0		
		Masonry	60%	x None	Minor	Mode		Major	Replace		\$0		No Issues
		Framed w/Panel Siding	20%	x None	Minor	Mode		Major	x Replace	100%	\$230,049	I	Moisture damage, rot, age
		Framed w/Stucco	20%	x None	Minor	Mode		Major	x Replace	100%	\$191,708	I	Stucco cracked and moisture damage
		Framed w/Masonry Veneer		o None	Minor	Mode		Major	Replace		\$0		
	B2020 Exterior Windows	Wood	90%	x None	Minor	Mode		Major	x Replace	100%	\$690,148		Moisture damage, rot, single pane, age
		Aluminum/Steel	10%	x None	Minor	Mode		Major	Replace		\$0		No Issues
		Clad		o None	Minor	Mode		Major	Replace		\$0		
		Curtain Wall		o None	Minor	Mode		Major	Replace		\$0		
	B2030 Exterior Doors	Wood	26	x None	Minor	Mode		Major	x Replace	100%	\$41,613	I	Beyond service life, moisture damage
		Hollow Metal	16	x None	Minor	_		Major	Replace	100%	\$5,122	I	Repairs to door and hardware, repaint
		Storefront		o None	Minor	Mode	erate	Major	Replace		\$0		<u> </u>
<u>B3</u>	30 Roofing				_		_	_					Towns to the second
	B3010 Roof Coverings	Asphalt Shingle	10%	x None	Minor	Mode		Major	x Replace	100%	\$26,839	I	1995 shingles, worn, beyond service life
		Built-Up	90%	x None	Minor	Mode		Major	x Replace	100%	\$345,074	I	Beyond service life, over 25 years old
		Single Ply		o None	Minor	Mode		Major	Replace		\$0		
		Metal		o None	Minor	Mode		Major	Replace		\$0		
		Concrete Tile		o None	Minor	Mode		Major	Replace		\$0		
	B3020 Roof Openings	Skylights		o None	Minor	Mode		Major	Replace		\$0		
		Access Hatch		o None	Minor	Mode	rate	Major	Replace		\$0		
C INTERIO													
<u>C1</u>	10 Interior Construction		_										Tax.
	C1010 Partitions	Framed	100%	x None	Minor	Mode	erate	Major	Replace		\$0		No Issues

	Masonry	o None	Minor	Moderate Major	Replace		\$0	
C1020 Interior Doors	Wood	76 x None	Minor	Moderate Major	x Replace	100%	\$105,420	I Beyond Service Life, heavy use
	Hollow Metal	o None	Minor	Moderate Major	Replace		\$0	
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace			
C20 Stairs			<u> </u>		<u> </u>			
C2010 Stair Construction	Wood	2 x None	Minor	Moderate Major	Replace		\$0	No Issues, stairs to stage
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	
	Resilient	100% x None	Minor	Moderate	x Replace	100%	\$11	Replace non-slip coverings
C30 Interior Finishes								
C3010 Wall Finishes	Paint on Masonry	5% x None		Moderate Major	Replace		\$0	No Issues
	Wallboard	94% x None	x Minor	Moderate	Replace	100%	\$54,062	S Repairs and repaint
	Wainscot	o None	Minor	Moderate Major	Replace		\$0	
	Ceramic Tile	1% x None		Moderate Major	Replace		\$0	No Issues, shower area
C3020 Floor Finishes	Carpet / Soft Surface	40% x None	Minor	Moderate Major	x Replace	100%	\$89,719	Replace all, dirty, worn, age
	Resilient Tile	56% x None	Minor	Moderate Major	x Replace	100%	\$118,092	Replace VCT, age and wear
	Resilient Sheet	2% x None	Minor	Moderate Major	x Replace	100%	\$4,601	S Replace, age, wear. Kitchen, girls LR, Café
	Polished Concrete	1% x None	<b>—</b>	Moderate Major	Replace		\$0	No Issues
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace		\$0	No Issues, shower area
	Liquid Applied	o None	Minor	Moderate	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	39% x None	<b></b>	Moderate Major	Replace	100%	\$22,430	Minor repairs and repaint ceilings
	Lay-In Ceiling Tile	o None	Minor	Moderate	Replace		\$0	
	Glued-Up Ceiling Tile	60% x None	Minor	Moderate Major	x Replace	100%	\$103,522	Age, failing, falling, stained
	Painted Structure	1% x None	Minor	Moderate Major	Replace		\$0	No Issues
RVICES								
D10 Conveying		None	Minor	Madarata	Donlage		ćo	
D1010 Elevators & Lifts D1020 Escalators & Moving	Malks	o None o None		Moderate Major	Replace		\$0 \$0	
		o None	Minor	Moderate Major  Moderate Major	Replace Replace		\$0 \$0	
D1090 Other Conveying Syst D20 Plumbing	enis	0 None	WIIIIOI	Moderate Major	Replace		ŞU	
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Major	x Replace	100%	\$268,391	Qty = 104, Age, stained, functionality
D2010 Flumbling Fixtures D2020 Domestic Water Distr	ibution	100% X None	<b></b>	Moderate Major	x Replace	100%	\$115,025	Original Domestic water pipe system
D2030 Sanitary Waste	ibation	100% x None	<b>—</b>	Moderate Major	x Replace	100%	\$115,025	Original SS pipe
D2040 Rain Water Drainage		o None		Moderate Major	Replace	10070	\$113,023	T STIGHTER 33 PIPE
D2090 Other Plumbing Syste	ms NOTUSED	None		Moderate Major	Replace		γo	
D30 HVAC	III3 NOT OSED	None	Willion	Major	Керіасс			
D3010 Energy Supply		100% x None	Minor	Moderate	Replace		\$0	No Issues
D3020 Heat Generating Syst	ems Boiler	66% x None		Moderate Major	x Replace	50%	\$50,611	Replace the 1 old boiler
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Air Handler	o None		Moderate Major	Replace		\$0	<u> </u>
	Furnace	o None	Minor	Moderate Major	Replace		\$0	
	Furnace	o None			Replace x Replace	100%	•	I High maintenance cost, not functional
D3030 Cooling Generating S	Furnace Heat Exchanger	34% x None	Minor	Moderate Major	x Replace	100%	\$32,590	High maintenance cost, not functional
D3030 Cooling Generating S	Furnace Heat Exchanger ystem Component of air handler	34% x None o None	Minor Minor	Moderate Major Moderate Major	x Replace Replace	100%	\$32,590 \$0	High maintenance cost, not functional
	Furnace Heat Exchanger ystem Component of air handler Stand alone chiller	34% x None o None o None	Minor Minor Minor	Moderate Major Moderate Major Moderate Major	x Replace Replace Replace		\$32,590 \$0 \$0	
D3030 Cooling Generating St D3040 Distribution Systems	Furnace Heat Exchanger ystem Component of air handler Stand alone chiller Ductwork	34% x None	Minor Minor Minor Minor	Moderate Major Moderate Major Moderate Major Moderate Major	x Replace Replace Replace x Replace	100%	\$32,590 \$0 \$0 \$76,683	High maintenance cost, not functional     Age, dirty   Original 2-pipe system
D3040 Distribution Systems	Furnace Heat Exchanger ystem Component of air handler Stand alone chiller Ductwork Hot water return & supply	34% x None o None o None	Minor Minor Minor Minor Minor	Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	x Replace Replace Replace x Replace x Replace		\$32,590 \$0 \$0 \$76,683 \$191,708	I Age, dirty
	Furnace Heat Exchanger ystem Component of air handler Stand alone chiller Ductwork Hot water return & supply	34% x None	Minor Minor Minor Minor Minor	Moderate Major Moderate Major Moderate Major Moderate Major	x Replace Replace Replace x Replace	100%	\$32,590 \$0 \$0 \$76,683	I Age, dirty

D3060 Controls & Instrumentation	on	100% x None	Minor	Moderate Major	Replace		\$0	
D3070 Systems Testing & Balanc		100% x None	Minor	Moderate Major	x Replace	100%	\$38,342	ı
D3090 Other HVAC Systems & Ed	=	None	Minor	Moderate Major	Replace			
D40 Fire Protection	•							
D4010 Sprinklers		o None	Minor	Moderate Major	Replace		\$0	
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialties	5	o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Syst	:∈ NOT USED	None	Minor	Moderate	Replace			
D50 Electrical					<u></u>			
D5010 Electrical Service & Distrib	oution	100% x None	Minor	Moderate Major	x Replace	20%	\$61,347	Old panelboards, original to the building
D5020 Lighting and Branch Wirir	g	100% x None	Minor	Moderate Major	x Replace	100%	\$460,099	Old wiring and fixtures
D5030 Communications & Secur	it Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0	
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0	
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace		\$0	
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace			
E EQUIPMENT & FURNISHINGS								
E10 Equipment	Food Comiles	1000/ None	N dim a m	Diagrama Diagram	Danlass	1000/	¢76.602	I Old Equipment
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$76,683	i Old Equipment
F1020 Institutional Fautiament	Vocational	o None	Minor	Moderate Major	Replace		\$0 \$0	
E1020 Institutional Equipment	Science Art	o None o None	Minor	Moderate Major	Replace Replace		\$0 \$0	
	Stage Performance	1120 x None	Minor	Moderate Major  Moderate Major	Replace		\$0 \$0	No Issues
	Restroom Accessories/Stalls		Minor	Moderate Major	x Replace	100%	\$958,539	Qty = 19 stalls
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace	100%	\$330,333	1 Qty - 13 stans
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E20 Furnishings	NOT OSED	None	IVIIIIOI	iviouerate	Періасе			
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$460,099	Old cabinetry, building original equipment
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace	10070	\$0	No issues
F SPECIAL CONSTRUCTION & DEMOLITION - NOT	USFD	100% X None	· · · · · · · · · · · · · · · · · · ·	inidaci dec	періасс		Ψ.	
	•••							
G BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements								
G2010 Roadways		15550 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2020 Parking Lots		24500 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2030 Pedestrian Paving		30000 x None	Minor	Moderate Major	x Replace	20%	\$64,020	Trip hazard, heaving, cracked, damage
G2040 Site Development		2975 x None	Minor	Moderate Major	x Replace	100%	\$206,331	I Cattle type fence
G2050 Landscaping		64000 x None	Minor	Moderate	Replace		\$0	No Issues
G30 Site Mechanical Utilities								
G3010 Water Supply	Domestic	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Fire	o None	Minor	Moderate Major	Replace		\$0	
G3020 Sanitary Sewer		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
G3030 Storm Sewer		o None	Minor	Moderate Major	Replace		\$0	
G3040 Heating Distribution		o None	Minor	Moderate Major	Replace		\$0	
G3050 Cooling Distribution		o None	Minor	Moderate	Replace		\$0	
								State of Oreg

G3060 Fuel Distribution G3090 Other Site Mechanical Utili NOT USED	o None Minor None Minor			Major Major	Replace Replace	\$0		
G40 Site Electrical Utilities					_			
G4010 Electrical Distribution Service	o None Minor	r	Moderate	Major	Replace	\$0		
Generator	o None Minor	r	Moderate	Major	Replace	\$0		
G4020 Site Lighting	o None Minor	r	Moderate	Major	Replace	\$0		
G4030 Site Communications & Security	o None Minor	r	Moderate	Major	Replace	\$0		
G4090 Other Site Electrical Utiliti€ NOT USED	None Minor	ſ	Moderate	Major	Replace			
G90 Other Site Construction NOT USED						-		
OTHER								
			Unit of		Unit		Rank	
<u>Description of System</u>			Measure	Quantity	Budget	Extended	(I,S,L)	Notes
						\$0		
						\$0		
		$\exists$				\$0 \$0		
						\$0		
						\$0 \$0		
						\$0 \$0 \$0		

Physical Condition Budget Sub-Total \$5,280,586
Budgeted Development Costs \$2,006,623
Physical Condition Budget TOTAL \$7,287,208

Replacement Budget \$15,000,648

District Name:	Three Rivers/Josephine County SD
Site Name:	Fruitdale ES
Building Name:	
Building ID:	

#### REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LE	VEL OF ACTION			Ī			
									% of		Necessity	
			% of Building						System or	Automated Budget	Rank	
Level 1 Level		Type (as applicable)	or Number	None	Minor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCT												
<u>A10 F</u>	oundations				DATE:		D 4 - 1 - 1	D 1		¢0		<del></del>
	A1010 Standard Foundations			o None	Minor	Moderate	Major	Replace		\$0		
	A1020 Special Foundations			o None	Minor	Moderate	Major	Replace		\$0		No Issues
420 B	A1030 Slab on Grade		100%	x None	Minor	Moderate	Major	Replace		\$0		NO Issues
<u>A20 B</u>	Sasement Construction A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Poplaco	_			
	A2010 Basement Walls	NOT OSED		-	Minor		Major	Replace		\$0		
B SHELL	A2020 Basement Walls			o None	IVIIIIOI	Moderate	Major	Replace		ŞU		
	uperstructure											
<u>B10 3</u>	B1010 Floor Construction	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	B1010 F100F Construction	Steel		o None	Minor	Moderate	Major	Replace		\$0		
		Concrete		x None	Minor	Moderate	Major	Replace		\$0		Slab on grade, No Issues
	B1020 Roof Construction	Wood		x None	Minor	Moderate	Major	Replace		\$0		No Issues
	DIOZO NOOT CONSTITUCION	Steel		x None	Minor	Moderate	Major	Replace		\$0		No Issues
		Concrete		o None	Minor	Moderate	Major	Replace		\$0		
B20 F	xterior Enclosure	Contracte		o Inone	············	Moderate	.v.ajo:	Періасс		Ψ-		
<u>525 E</u>	B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor	Moderate	Major	Replace		\$0		
		Masonry		x None	Minor	Moderate	Major	Replace		\$0		No Issues
		······································								7.5		Water damage to batting and
		Framed w/Panel Siding	55%	x None	Minor	Moderate	x Major	Replace	100%	\$303,067	l	facia. Paint
		Framed w/Stucco		o None	Minor	Moderate	Major	Replace		\$0		
		Framed w/Masonry Vene	eer	o None	Minor	Moderate	Major	Replace		\$0		
	B2020 Exterior Windows	Wood		0 None	Minor	Moderate	Major	Replace		\$0		
		Aluminum/Steel	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
		Clad		o None	Minor	Moderate	Major	Replace		\$0		
		Curtain Wall		o None	Minor	Moderate	Major	Replace		\$0		
	B2030 Exterior Doors	Wood		o None	Minor	Moderate	Major	Replace		\$0		
		Hollow Metal	6	x None	Minor	Moderate	Major	Replace		\$0		No Issues
		Storefront	30	x None	Minor	Moderate	Major	Replace		\$0		No Issues
<u>B30 R</u>	oofing											
	B3010 Roof Coverings	Asphalt Shingle	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
		Built-Up		o None	Minor	Moderate	Major	Replace		\$0		
		Single Ply		o None	Minor	Moderate	Major	Replace		\$0		
		Metal		o None	Minor	Moderate	Major	Replace		\$0		
		Concrete Tile		o None	Minor	Moderate	Major	Replace		\$0		
	B3020 Roof Openings	Skylights		o None	Minor	Moderate	Major	Replace		\$0		
		Access Hatch		o None	Minor	Moderate	Major	Replace		\$0		

C INTERIORS									
C10 Interior Construction									
C1010 Partitions	Framed	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Masonry	o None	Minor	Moderate Major	Replace		\$0		
C1020 Interior Doors	Wood	67 x None	Minor	Moderate Major	Replace		\$0		No Issues
	Hollow Metal	36 x None	Minor	Moderate Major	Replace		\$0		no Issues
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace				
C20 Stairs									
C2010 Stair Construction	Wood	3 x None	Minor	Moderate Major	Replace		\$0		No Issues
	Metal	0 None	Minor	Moderate Major	Replace		\$0		
	Concrete	0 None	Minor	Moderate Major	Replace		\$0		
C2020 Stair Finishes	Concrete Fill	0 None	Minor	Moderate Major	Replace		\$0		
	Resilient	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
C30 Interior Finishes								•	
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate Major	Replace		\$0		
	Wallboard	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Wainscot	o None	Minor	Moderate Major	Replace		\$0		
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0		
									Wear and age showing, 16 year
C3020 Floor Finishes	Carpet / Soft Surface	85% x None	Minor	Moderate Major	x Replace	100%	\$274,000	S	old carpet
	Resilient Tile	5% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Resilient Sheet	5% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Polished Concrete	2% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0		
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0		
	Wood Sports Floor	3% x None	Minor	Moderate Major	Replace		\$0		No Issues
C3030 Ceiling Finishes	Wallboard	o None	Minor	Moderate Major	Replace		\$0		
	Lay-In Ceiling Tile	85% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Glued-Up Ceiling Tile	10% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Painted Structure	5% x None	Minor	Moderate Major	Replace		\$0		No Issues
D SERVICES				_					
D10 Conveying									_
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0		
D1020 Escalators & Moving Walks		o None	Minor	Moderate	Replace		\$0		
D1090 Other Conveying Systems		1 x None	Minor	Moderate	Replace		\$0		No Issues
D20 Plumbing									
D2010 Plumbing Fixtures		100% x None	Minor	Moderate	Replace		\$0		94 count
D2020 Domestic Water Distribution		100% x None	Minor	Moderate	Replace		\$0		No Issues
D2030 Sanitary Waste		100% x None	Minor	Moderate Major	Replace		\$0		No Issues
D2040 Rain Water Drainage		0 None	Minor	Moderate	Replace		\$0		
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate Major	Replace				
D30 HVAC									
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0		No Issues
D3020 Heat Generating Systems	Boiler	98% x None	Minor	Moderate Major	x Replace	100%	\$216,004	L	Replace
	Air Handler	2% x None	Minor	Moderate Major	Replace		\$0		No Issues - portables
	Furnace	o None	Minor	Moderate Major	Replace		\$0		
	Heat Exchanger	o None	Minor	Moderate Major	Replace		\$0		State of Orego

D3030 Cooling Generating Systems	Component of air handler	o None	Minor	Moderate Major	Replace	\$0	
	Stand alone chiller	o None	Minor	Moderate Major	Replace	\$0	
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Hot water return & supply	y o None	Minor	Moderate Major	Replace	\$0	
D3050 Terminal & Package Units	Above ceiling VAV unit	o None	Minor	Moderate Major	Replace	\$0	
	In-room ventilator unit	o None	Minor	Moderate Major	Replace	\$0	
	In-room radiant unit	o None	Minor	Moderate Major	Replace	\$0	
D3060 Controls & Instrumentation		100% x None	Minor	Moderate Major	Replace	\$0	No Issues
D3070 Systems Testing & Balancing		100% x None	Minor	Moderate Major	Replace	\$0	No Issues
D3090 Other HVAC Systems & Equip	n NOT USED	None	Minor	Moderate Major	Replace		
D40 Fire Protection				.,,		_	
D4010 Sprinklers		100% x None	Minor	Moderate	Replace	\$0	No Issues
D4020 Standpipes		100% x None	Minor	Moderate Major	Replace	\$0	No Issues
D4030 Fire Protection Specialties		100% x None	Minor	Moderate Major	Replace	\$0	No Issues
D4090 Other Fire Protection System	s NOT LISED	None	Minor	Moderate Major	Replace	ΨÜ	
D50 Electrical	3 NOT OSED	None	IVIIIIOI	Widger	Періасс		
D50 Electrical  D5010 Electrical Service & Distribution	on	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	OII		Minor			\$0	No Issues
D5020 Lighting and Branch Wiring	Maior / Bala Contain			Moderate Major	Replace		No Issues
D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate Major	Replace	\$0	NO ISSUES
	Clock / Intercom System	o None	Minor	Moderate Major	Replace	\$0	
	Closed Circuit Surveillance		Minor	Moderate Major	Replace	\$0	
	Access Control System	o None	Minor	Moderate Major	Replace	\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Lighting Control System	o None	Minor	Moderate Major	Replace	\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace		
E EQUIPMENT & FURNISHINGS							
E10 Equipment							
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Vocational	o None	Minor	Moderate Major	Replace	\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace	\$0	
	Art	o None	Minor	Moderate Major	Replace	\$0	
	Stage Performance	1250 x None	Minor	Moderate Major	Replace	\$0	No Issues
	Restroom Accessories/Sta	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace		
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace		
E20 Furnishings				<del>_</del>			
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	Replace	\$0	No Issues
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace	\$0	No Issues
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USE	:D						
G BUILDING SITE WORK							
G10 Site Preparation	NOT USED						
G20 Site Improvements							
G2010 Roadways		15700 x None	Minor	Moderate Major	Replace	\$0	No Issues
G2020 Parking Lots		53360 x None	Minor	Moderate Major	Replace	\$0	No Issues
	!	<u> </u>	<u></u>			•	State of Oregon
							School Facilities Assessment Template

School Facilities Assessment Template

G2030 Pedestrian Paving		10750 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G2040 Site Development		1300 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G2050 Landscaping		71000 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G30 Site Mechanical Utilities		<u> </u>			_					
G3010 Water Supply	Domestic	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Fire	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
G3020 Sanitary Sewer		100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
G3030 Storm Sewer		100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
G3040 Heating Distribution		o None	Minor	Moderate	Major	Replace		\$0		
G3050 Cooling Distribution		o None	Minor	Moderate	Major	Replace		\$0		
G3060 Fuel Distribution		o None	Minor	Moderate	Major	Replace		\$0		
G3090 Other Site Mechanical U	tilities NOT USED	None	Minor	Moderate	Major	Replace				
G40 Site Electrical Utilities					•	·			_	
G4010 Electrical Distribution	Service	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
								·		Will not auto-start, heat sen
	Generator	100% x None	Minor	x Moderate	Major	Replace	100%	\$16,005		failures
G4020 Site Lighting		0 None	Minor	Moderate	Major	Replace		\$0		
G4030 Site Communications & 9	Security	0 None	Minor	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical Utili	•	None		Moderate	Major	Replace		·		
G90 Other Site Construction	NOT USED				,	•				
				Unit of		Unit			Rank	
<u>Description of System</u>				Measure	Quantity	Budget		Extended	(I,S,L)	Notes
								\$0		
							1	\$0		
							1	\$0		
							1	\$0		
							-	\$0		
						-	-	\$0		
								J.	,	

Physical Condition Budget Sub-Total \$809,076

Budgeted Development Costs \$307,449

Physical Condition Budget TOTAL \$1,116,525

Replacement Budget \$21,558,370

District Name:	Three Rivers/Josephine County SD
Site Name:	Jerome Prairie ES
Building Name:	
Building ID:	(

#### REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

						LEVEL OF ACTION	N.		1			
Lavel 4	112	Tura (as applicable)	% of Building	None					% of System or	Automated Budget	Necessity Rank	Nation
Level 1   Level 2   A SUBSTRUCTUR		Type (as applicable)	or Number	None	Minor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A10 Four												
	A1010 Standard Foundations		50% >	None	Minor	Moderate	Major	Replace		\$0		No issues
	A1020 Special Foundations		C	None	Minor	Moderate	Major	Replace		\$0		
	A1030 Slab on Grade		50% >	None	Minor	Moderate	Major	Replace		\$0		No Issues
A20 Base	ement Construction											•
	A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace				
	A2020 Basement Walls		C	None	Minor	Moderate	Major	Replace		\$0		
B SHELL												
B10 Supe	<u>erstructure</u>			_				_				_
	B4040.5l		500/	<b>.</b>						40		No leaves 1029 bldg flooring above becoment
	B1010 Floor Construction	Wood	50% >	None	Minor	Moderate	Major	Replace		\$0		No Issues, 1938 bldg flooring above basement
		Steel Concrete		None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0		Slab on grade, No Issues
	B1020 Roof Construction	Wood		None	Minor	Moderate	Major	Replace		\$0 \$0		No Issues
	B1020 ROOI CONSTIUCTION	Steel		None	Minor	Moderate	Major	Replace		\$0 \$0		110 133463
		Concrete		None	Minor	Moderate	Major	Replace		\$0 \$0		
B20 Exte	erior Enclosure	Concrete		None	IVIIIIOI	Wioderate	iviajoi	Періасе		Ψ.		<u> </u>
<u> </u>	B2010 Exterior Walls	Concrete Formed / Tilt		None	Minor	Moderate	Major	Replace		\$0		
		Masonry		None	Minor	Moderate	Major	Replace		\$0		No Issues
		Framed w/Panel Siding	70% >	None	Minor	Moderate	Major	x Replace	100%	\$614,870	ı	Damage, wood rot, age
		Framed w/Stucco	C	None	Minor	Moderate	Major	Replace		\$0		
		Framed w/Masonry Veneer	5% >	None	Minor	Moderate	Major	Replace		\$0		No Issues
	B2020 Exterior Windows	Wood	95% >	None	Minor	Moderate	Major	x Replace	100%	\$556,311	I	Wood rot, damage, age
		Aluminum/Steel	5% >	None	Minor	Moderate	Major	Replace		\$0		No Issues, Library Bldg
		Clad	C	None	Minor	Moderate	Major	Replace		\$0		
		Curtain Wall		None	Minor	Moderate	Major	Replace		\$0		
	B2030 Exterior Doors	Wood	=	None	Minor	Moderate	Major	x Replace	100%	\$43,214	I	Damage, age
		Hollow Metal		None	Minor	Moderate		x Replace	100%	\$16,645	S	Beyond service life
	_	Storefront	C	None	Minor	Moderate	Major	Replace		\$0		1
<u>B30 Roo</u>				٦		<b>—</b>	<u> </u>	<u> </u>		****		All buildings and an all discolar
	B3010 Roof Coverings	Asphalt Shingle		None	Minor	Moderate	Major	x Replace	100%	\$204,957	I	All buildings, replace all shingles
		Built-Up		None	Minor	Moderate	Major	Replace		\$0		
		Single Ply		None	Minor	Moderate	Major	Replace		\$0		
		Metal		None	Minor	Moderate	Major	Replace		\$0 \$0		
	B3020 Roof Openings	Concrete Tile Skylights		None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0		+
	55020 Root Openings	Access Hatch		None	Minor	Moderate	Major	Replace		\$0 \$0		
C INTERIORS		, 100000 Hutter/		, mone	WIIIIOI	Moderate	iviajoi	Періасс		<del></del>		
	rior Construction											
	C1010 Partitions	Framed	100% >	None	Minor	Moderate	Major	Replace		\$0		No Issues

	Masonry	o None	Minor	Moderate Major	Replace		\$0	
C1020 Interior Doors	Wood	54 x None	Minor	Moderate Major	x Replace	100%	\$74,903	I Age, wear, beyond service life
	Hollow Metal	o None	Minor	Moderate Major	Replace		\$0	
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace		·	
C20 Stairs					•			•
C2010 Stair Construction	Wood	4 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	
	Resilient	o None	Minor	Moderate Major	Replace		\$0	
C30 Interior Finishes				.,,			, -	
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate	Replace		\$0	
	Wallboard	100% x None	Minor	x Moderate Major	Replace	100%	\$87,839	Repaint all interior walls
	Wainscot	o None	Minor	Moderate Major	Replace	10%	\$0	
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	59% x None	Minor	Moderate Major	x Replace	100%	\$101,058	Original carpet, 40+ years, dirty, worn
	Resilient Tile	15% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Resilient Sheet	5% x None	Minor	Moderate Major	x Replace	100%	\$8,784	Girls RR
	Polished Concrete	5% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0	
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	
	Wood Sports Floor	16% x None	Minor	Moderate Major	Replace		\$0	No Issues
C3030 Ceiling Finishes	Wallboard	o None	Minor	Moderate Major	Replace		\$0	
cooo cening rimanes	Lay-In Ceiling Tile	81% x None	Minor	Moderate Major	x Replace	100%	\$120,954	Original ceiling system, dirty, damaged
	Glued-Up Ceiling Tile	18% x None	Minor	Moderate Major	x Replace	100%	\$23,716	Original ceiling system, failing, falling, dirt
	Painted Structure	1% x None	Minor	Moderate Major	Replace	10070	\$0	No Issues
ICES	Tunited Structure	170 X None	IVIIIIOI	Wager	перисе		70	110 100000
D10 Conveying								
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving Wal	(S	o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Systems		o None	Minor	Moderate Major	Replace		\$0	
D20 Plumbing				aje.			7.5	
D2010 Plumbing Fixtures		100% x None	Minor	Moderate	x Replace	100%	\$204,957	All fixtures old, damaged, qty = 80
D2020 Domestic Water Distribut	ion	100% x None	Minor	Moderate Major	x Replace	100%	\$87,839	Original lines, rust
		20070 // 110110		aje.	7			
DZUSU Samiary Wasie		100% x None	Minor	Moderate Major	x Replace	100%	S87.839	Original SS lines
D2030 Sanitary Waste D2040 Rain Water Drainage		100% x None o None	Minor Minor	Moderate Major Moderate Major	x Replace Replace	100%	\$87,839 \$0	Original SS lines
D2040 Rain Water Drainage	NOT USED	o None	Minor	Moderate	Replace	100%	\$87,839 \$0	Original SS lines
D2040 Rain Water Drainage D2090 Other Plumbing Systems	NOT USED					100%		Original SS lines
D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC	NOT USED	o None None	Minor Minor	Moderate Major Moderate Major	Replace Replace	100%	\$0	Original SS lines   No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply		o None None  100% x None	Minor Minor Minor	Moderate Major Moderate Major  Moderate Major	Replace Replace		\$0 \$0	
D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC	Boiler	o None None  100% x None 100% x None	Minor Minor Minor Minor	Moderate Major Moderate Major  Moderate Major  Moderate Major  Moderate Major	Replace Replace Replace x Replace	50%	\$0 \$0 \$58,559	No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler Air Handler	o None None  100% x None 100% x None o None	Minor Minor Minor Minor Minor Minor	Moderate Major Moderate Major  Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace X Replace Replace Replace		\$0 \$0 \$58,559 \$0	No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler Air Handler Furnace	100% x None 100% x None 100% x None 0 None	Minor Minor Minor Minor Minor Minor Minor	Moderate Major Moderate Major  Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace x Replace Replace Replace Replace Replace		\$0 \$0 \$58,559 \$0 \$0	No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger	100% x None 100% x None 100% x None 0 None 0 None x None	Minor Minor Minor Minor Minor Minor Minor Minor	Moderate Major Moderate Major  Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace X Replace Replace Replace Replace Replace Replace		\$0 \$0 \$58,559 \$0 \$0 \$0	No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler Air Handler Furnace Heat Exchanger ms Component of air handler	100% x None 100% x None 100% x None 0 None 0 None 0 None 0 None	Minor	Moderate Major	Replace Replace x Replace Replace Replace Replace Replace Replace Replace		\$0 \$0 \$58,559 \$0 \$0 \$0 \$0	No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems  D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating Syste	Boiler Air Handler Furnace Heat Exchanger ms Component of air handler Stand alone chiller	100% x None 100% x None 100% x None 0 None 0 None 0 None 0 None 0 None	Minor	Moderate Major Moderate Major  Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace x Replace Replace Replace Replace Replace Replace Replace Replace		\$0 \$0 \$58,559 \$0 \$0 \$0 \$0	No Issues  Replace single boiler in Bldg B, original
D2040 Rain Water Drainage D2090 Other Plumbing Systems  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger ms Component of air handler Stand alone chiller Ductwork	100% x None 100% x None 100% x None 0 None	Minor	Moderate Major Moderate Major  Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace x Replace Replace Replace Replace Replace Replace Replace Replace Replace		\$0 \$58,559 \$0 \$0 \$0 \$0 \$0	No Issues
D2040 Rain Water Drainage D2090 Other Plumbing Systems  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating Syste  D3040 Distribution Systems	Boiler Air Handler Furnace Heat Exchanger ms Component of air handler Stand alone chiller Ductwork Hot water return & supply	100% X None 100% X None 100% X None 0 None 0 None 0 None 0 None 100% X None 0 None 0 None 0 None	Minor	Moderate Major	Replace Replace x Replace		\$0 \$58,559 \$0 \$0 \$0 \$0 \$0 \$0	No Issues  I Replace single boiler in Bldg B, original
D2040 Rain Water Drainage D2090 Other Plumbing Systems  D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating Syste	Boiler Air Handler Furnace Heat Exchanger ms Component of air handler Stand alone chiller Ductwork Hot water return & supply	100% x None 100% x None 100% x None 0 None	Minor	Moderate Major Moderate Major  Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace x Replace Replace Replace Replace Replace Replace Replace Replace Replace		\$0 \$58,559 \$0 \$0 \$0 \$0 \$0	No Issues  I Replace single boiler in Bldg B, original

D3060 Controls & Instrumentatio	n	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3070 Systems Testing & Balanci	ng	100% x None	Minor	Moderate Major	x Replace	100%	\$29,280	ı
D3090 Other HVAC Systems & Eq	ui NOT USED	None	Minor	Moderate Major	Replace			
<u>D40 Fire Protection</u>								_
D4010 Sprinklers		o None	Minor	Moderate	Replace		\$0	
D4020 Standpipes		o None	Minor	Moderate	Replace		\$0	
D4030 Fire Protection Specialties		o None	Minor	Moderate	Replace		\$0	
D4090 Other Fire Protection Syste	er NOT USED	None	Minor	Moderate Major	Replace			
D50 Electrical			<u> </u>					
D5010 Electrical Service & Distrib	ution	100% x None	Minor	Moderate Major	x Replace	100%	\$234,236	Building original electrical equipment
D5020 Lighting and Branch Wiring	5	100% x None	Minor	Moderate Major	x Replace	100%	\$351,355	Building original wiring and fixtures
D5030 Communications & Securit	:y Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0	
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0	
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	x Replace	100%	\$19,032	S Beyond Service Life
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace		\$0	
	<b>Lighting Control System</b>	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Replace			
								-
E EQUIPMENT & FURNISHINGS								
E10 Equipment					_			
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$58,559	I Old equipment
	Vocational	o None	Minor	Moderate Major	Replace		\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0	
	Art	o None	Minor	Moderate Major	Replace		\$0	
	Stage Performance	600 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	x Replace	100%	\$731,989	I Old, damaged, wood
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Replace			
E20 Furnishings								
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$351,355	I All old cabinetry
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
F SPECIAL CONSTRUCTION & DEMOLITION - NOT I	JSED							
G BUILDING SITE WORK	NOTUSED							
G10 Site Preparation G20 Site Improvements	NOT USED							
G2010 Roadways		o None	Minor	Moderate Major	Replace		\$0	
G2010 Roadways  G2020 Parking Lots		39300 x None	Minor	Moderate Major	x Replace	100%	\$272,565	S Resurface and stripe
G2030 Pedestrian Paving		2050 x None	Minor	Moderate Major	Replace	10078	\$272,303	No Issues
G2040 Site Development		1900 x None	Minor	Moderate Major	x Replace	90%	\$118,597	Cattle fencing
G2050 Landscaping		11250 x None	Minor	Moderate Major	x Replace	100%	\$34,211	Not in working condition
G30 Site Mechanical Utilities		TTZ50 X NOTICE	IVIIIIOI	iviouelate iviajul	x Neplace	100/0	<b>₩</b> 94,∠11	1 ROCH WORKING CONDITION
<u> </u>	Domestic	100% x None	Minor	Moderate	y Ponlaco	100%	¢20,200	Old piping
G3010 Water Supply	Fire	o None	Minor Minor	Moderate Major Moderate Major	x Replace Replace	100/0	\$29,280 \$0	ι οια ριγιίδ
G3020 Sanitary Sewer	ine	100% x None	Minor	Moderate Major	x Replace	100%	\$29,280	Old piping
G3020 Samtary Sewer G3030 Storm Sewer		o None	Minor	Moderate Major	Replace	100%	\$29,280	ι οια βιβιτίξ
G3040 Heating Distribution		o None		Moderate Major	Replace		\$0 \$0	
G3040 Heating Distribution G3050 Cooling Distribution		o None	Minor Minor	- I			\$0 \$0	
asoso cooming distribution		o inone	IVIIIIOI	Moderate	Replace		ŞU	<u> </u>
								State of Orego

G3060 Fuel Distribution	Г	o None	Minor	Moderate	Major	Replace		\$0		
G3090 Other Site Mechanical	Utilit NOT USED	None	Minor	Moderate	Major	Replace				
G40 Site Electrical Utilities								_		
G4010 Electrical Distribution	Service	o None	Minor	Moderate	Major	Replace		\$0		
	Generator	o None	Minor	Moderate	Major	Replace		\$0		
G4020 Site Lighting		o None	Minor	Moderate	Major	Replace		\$0		
G4030 Site Communications 8	& Security	o None	Minor	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical Ut	ilities NOT USED	None	Minor	Moderate	Major	Replace				
<b>G90 Other Site Construction</b>	NOT USED							_		
OTHER										
OTTLIN										
OTHER				Unit of		Unit			Rank	
<u>Description of System</u>				Unit of Measure	Quantity	Unit Budget		Extended	Rank (I,S,L)	Notes
					Quantity			Extended \$0		Notes
					Quantity					Notes
					Quantity			\$0		Notes
					Quantity		-	\$0 \$0		Notes
					Quantity		-	\$0 \$0 \$0		Notes
					Quantity		-	\$0 \$0 \$0 \$0		Notes

Physical Condition Budget Sub-Total \$4,581,461

Budgeted Development Costs \$1,740,955

Physical Condition Budget TOTAL \$6,322,416

Replacement Budget \$12,496,631

District Name:	Three Rivers/Josephine County SD
Site Name:	Madrona ES
Building Name:	
Building ID:	

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

Level 1   Level 2   Level 3							LEVEL OF ACTION		1				
## AUDIO Standardors  NOT USED  NOTE  AUDIO Standardors  NOT USED  NOTE  AUDIO Standardors  NOT USED  NOTE  NOTE  BIOLI Standardors  Wood  AUDIO Standardors  Wood  AUDIO Standardors  Standardors  Curtardor  AUDIO Standardors  Wood  AUDIO Standardors  Standardors  Curtardor  AUDIO Standardors  Wood  AUDIO Standardors  NOTE  BIOLI Standardors  Wood  AUDIO Stan	Level 1 Level 2 Leve	ol 3	Type (as applicable)	_	None	Minor	Moderate	Major	Replace	System or		Rank	Notes
A 1010 Standard Foundations			Type (as applicable)	0.110	110.10	10	, moderate	11.0,01	Перисе		254111440	(., 0, -,	1.0.00
A1202 Spacial Foundations		on <u>s</u>											
A1830 Sibb on Grade	A10:	10 Standard Foundations		10%	x None	Minor	Moderate	Major	Replace		\$0		Gym, No Issues
## A2DB assement Executation A2DD assement Executation A2DD assement Executation A2DD assement Walls  ## B101 Superstructure  ## B101 Floor Construction  ## B101 Floor Construction  ## B102 Roof Construction  ## Wood  #	A103	20 Special Foundations			o None	Minor	Moderate	Major	Replace		\$0		
A2020 Basement Walfs	A103	30 Slab on Grade		90%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
Note	A20 Basemen	t Construction											
SHELL   SID Superstructure	A20:	10 Basement Excavation	NOT USED		None	Minor		-	Replace				
B1010 Floor Construction	A202	20 Basement Walls			o None	Minor	Moderate	Major	Replace		\$0		
Minor	B SHELL												
Steel										<u></u>		1	
Concrete	B10:			<b>-</b>		l l		<del>-</del>					
Concrete   100%   0   None   Minor   Moderate   Major   Moderate   M			Steel		o None	Minor	Moderate	Major	Replace		\$0		
B1020 Roof Construction Wood Steel ONOR ONOR ONOR Steel ONOR ONOR Steel ONOR ONOR ONOR Steel ONOR ONOR ONOR Steel ONOR ONOR ONOR ONOR ONOR Steel ONOR ONOR ONOR ONOR ONOR ONOR ONOR ONO													•
B1020 Roof Construction  Wood Steel Only None Concrete Only None Minor Moderate Major Moderate			Concrete	100%	o None	Minor	Moderate	Major	Replace		\$0		<u> </u>
Steel				1000/					l L .	4.007	<b>4</b> =4.40.4		·
B20   Exterior Enclosure	B102	20 Roof Construction		<b>-</b>						10%		S	rot
B20   Exterior Enclosure				<b>-</b>			_						
B2010 Exterior Walls  Concrete Formed / Tilt Masonry  95% x None Minor Moderate Major Moderate Major Moderate Major Moderate Major Replace Replace S0 No Insues No Ins	<b>P20</b> F. J. day <b>F</b>		Concrete		o None	Minor	Moderate	Major	Replace		\$0		
Masonry 95% x None Minor Moderate Major Replace \$0 No Issues  Framed w/Panel Siding Framed w/Stucco			Company Forms of / Tilt		. Nama	D 4 :	Na da sata		Danlass		ćo		1
Framed w/Panel Siding Framed w/Stucco Framed w/Masonry Veneer  B2020 Exterior Windows Wood Aluminum/Steel Clad Curtain Wall  B2030 Exterior Doors Wood Aluminum/Steel Clad Curtain Wall  B2030 Exterior Doors  Wood B2030 Exterior Windows  Wood B2030	B2U.	to exterior walls	·				<del></del>						No Issues
Framed w/Stucco Framed w/Masonry Veneer    Framed w/Stucco   Color   None   Minor   Moderate   Major   Replace   \$0   Original wood framed   windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   \$0   Original wood framed   Windows   \$0   Original wood framed   Windows, moisture damage   \$0   Original wood framed   Windows   \$0   Original wood framed   Windows   \$0   Original wood framed   Windows   \$0   Original wood framed   \$0   Original wood frame			Masonry	95%	x None	WIIIOI	Moderate	Iviajor	керіасе		\$U		NO ISSUES
Framed w/Stucco Framed w/Masonry Veneer    Framed w/Stucco   Color   None   Minor   Moderate   Major   Replace   \$0   Original wood framed   windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   Major   Replace   \$0   Original wood framed   Windows, moisture damage   \$0   Original wood framed   Windows   \$0   Original wood framed   Windows, moisture damage   \$0   Original wood framed   Windows   \$0   Original wood framed   Windows   \$0   Original wood framed   Windows   \$0   Original wood framed   \$0   Original wood frame			Framed w/Panel Siding	5%	y None	Minor	Moderate	Maior	y Renlace	100%	\$51 18 <i>1</i>	<u> </u>	Wood rot window area nanels
Framed w/Masonry Veneer  B 2020 Exterior Windows  Wood  Aluminum/Steel  Aluminum/Steel  Clad  Curtain Wall  D None  Minor  Minor  Minor  Moderate  Major  Major  Major  Replace  \$0  Original wood framed windows, moisture damage and rot  Moderate  Major  Moderate  Major  Replace  \$0  Original wood framed windows, moisture damage  and rot  Moderate  Major  Replace  \$0  Moisture damage,  Moi			_	<b>-</b>						10076		<u>'</u>	wood for, willdow area panels
B2020 Exterior Windows  Wood Aluminum/Steel Clad Curtain Wall  B2030 Exterior Doors  Wood Aluminum/Steel Clad Curtain Wall  Wood Aluminum/Steel Clad  Wajor Wood Winor Woderate Wajor Woderate Woderate Woderate Woderat			•								· · · · · · · · · · · · · · · · · · ·		
B2020 Exterior Windows Wood 100% x None Minor Moderate Major x Replace 100% \$682,453 I and rot  Aluminum/Steel O None Minor Moderate Major Replace \$0			Trumed W/Widsomy Veneer		- None	14111101	Wioderate	Iviajoi	Керіасс		<del> </del>		Original wood framed
B2020 Exterior Windows Wood 100% x None Minor Moderate Major x Replace S0 100% \$682,453 I and rot Moderate Major Replace \$0 100% \$682,453 I and rot Moderate \$0 100% \$682,453									1 1				_
Aluminum/Steel Clad Clad Curtain Wall  Do None Minor Moderate Major Moderate Major Major Moderate Major Major Moderate Major Major Moderate Mode	B202	20 Exterior Windows	Wood	100%	x None	Minor	Moderate	Major	x Replace	100%	\$682,453		_
Clad Curtain Wall O None Minor Moderate Major Replace \$0   So   Moisture damage, Moderate Major Replace \$0   None Moderate \$0   None Moderate Major Replace \$0   None Moderate \$0   None Moderate \$0   None Moderate Major Replace \$0   None Moderate \$0   None Moderate \$0   None Moderate \$0   None Moderate Major Replace \$0   None Moderate \$0   None Moderate \$0   None Moderate Major \$0   None Moderate \$0   None Moderate Major \$0   None Moderate \$0   None Moderate \$0   None Moderate Major \$0   None Moderate \$0   None None Moderate \$0   None None Moderate \$0   None None Moderate \$0   None None None Moderate \$0   None None None None None None None None													
Curtain Wall    None			Clad			Minor	<del></del>						
B2030 Exterior Doors Wood 32 x None Minor Moderate Major x Replace 100% \$51,216 I delamination, age delamination, age Minor Moderate Major Replace \$0 No Issues  B30 Roofing  B30 Roof Coverings Asphalt Shingle Built-Up Single Ply  Single Ply  Mood 32 x None Minor Moderate Major Moderate Major Replace \$0 No Issues  Minor Moderate Major Replace \$0 No Issues  Major Replace \$0 No Issues  Replace \$0 No Issues  Replace \$0 No Issues  No Issues  Mood Portables  Major X Replace Najor			Curtain Wall		o None	Minor	Moderate						
Hollow Metal 9 x None Minor Moderate Major Replace \$0 No Issues  B30 Roofing  B3010 Roof Coverings Asphalt Shingle Built-Up Single Ply  Hollow Metal 9 x None None Minor Moderate Major Replace \$0 No Issues  Major Replace \$0 No Issues  Major Replace \$0 No Issues  No									$\Box$				Moisture damage,
Storefront 0 None Minor Moderate Major Replace \$0 \	B203	30 Exterior Doors	Wood	32	x None	Minor	Moderate	Major	x Replace	100%	\$51,216	ı	delamination, age
B30 Roofing  B3010 Roof Coverings Asphalt Shingle Built-Up Single Ply Asphalt Shingle Single Ply  Asphalt Shingle Single Single Ply  Asphalt Shingle Single Ply  Asphalt S			Hollow Metal	9	x None	Minor	Moderate	Major	Replace		\$0		No Issues
B3010 Roof Coverings Asphalt Shingle 5% x None Minor Moderate Major x Replace 100% \$11,943 S Portables  Built-Up 95% x None Minor Moderate Major x Replace 100% \$324,165 I 1997 Roof system, failing  Single Ply O None Minor Moderate Major Replace \$0			Storefront		o None	Minor	Moderate	Major	Replace		\$0		
Built-Up 95% x None Minor Moderate Major x Replace 100% \$324,165 I 1997 Roof system, failing Single Ply o None Minor Moderate Major Replace \$0	B30 Roofing					_ <del></del>							
Single Ply o None Minor Moderate Major Replace \$0	B30:	10 Roof Coverings	Asphalt Shingle	5%	x None	Minor	Moderate	Major	x Replace	100%	\$11,943	S	
			•			Minor				100%		I	1997 Roof system, failing
State of Oregon			Single Ply		o None	Minor	Moderate	Major	Replace		\$0		

							_	
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete Tile	o None	Minor	Moderate Major	Replace		\$0	
B3020 Roof Openings	Skylights	o None	Minor	Moderate Major	Replace		\$0	
· · ·	Access Hatch	o None	Minor	Moderate Major	Replace		\$0	
C INTERIORS			_					-
C10 Interior Construction								
C1010 Partitions	Framed	100% x None	Minor	Moderate	Replace		\$0	No Issues
02020 / 6/ 6/ 6/ 6/	Masonry	o None	Minor	Moderate Major	Replace		\$0	
C1020 Interior Doors	Wood	95 x None	Minor	x Moderate Major	Replace	100%	\$30,410	S Repairs, paint
CIOZO IIICITOI DOOIS	Hollow Metal	o None	Minor	Moderate Major	Replace	10070	\$0	J Repairs, paire
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace		γo	
	NOT O3ED	None	WIIIIOI	Moderate	Керіасе			
C20 Stairs					<u> </u>		<b>I</b> 40	No legues
C2010 Stair Construction	Wood	2 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	
								Replace non-slip treads and
	Resilient	100% x None	Minor	Moderate Major	x Replace	100%	\$11	I nosings
C30 Interior Finishes								
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate Major	Replace		\$0	
	Wallboard	99% x None	Minor	x Moderate Major	Replace	100%	\$101,344	S Minor repairs, touch up
	Wainscot	o None	Minor	Moderate Major	Replace		\$0	
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace		\$0	No Issues
C3020 Floor Finishes	Carpet / Soft Surface	40% x None	Minor	Moderate Major	x Replace	100%	\$79,847	S Worn, dirty, age
	Resilient Tile	53% x None	Minor	Moderate Major	x Replace	100%	\$99,468	l Damage, age
	Resilient Sheet	5% x None	Minor	Moderate Major	x Replace	100%	\$10,237	S Damage, age
	Polished Concrete	1% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	o None	Minor	Moderate Major	Replace		\$0	
esoso cening i manes	Lay-In Ceiling Tile	10% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Lay-III Celling The	10% X None	IVIIIIOI	Widderate	Керіасе		ŞŪ	Falling, failing tiles, original
	Glued-Up Ceiling Tile	88% x None	Minor	Moderate Major	x Replace	100%	\$135,126	installation tiles
	Painted Structure					100%		No Issues
D. CEDVICES	Painted Structure	2% x None	Minor	Moderate Major	Replace		\$0	140 133063
D SERVICES								
D10 Conveying		Name	DA:	Dodoroto Dodoion	Danlaga	<del></del>	¢0	
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving Walks		o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Systems		o None	Minor	Moderate	Replace		\$0	
D20 Plumbing					<del></del>			
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Major	x Replace	100%	\$238,859	I Aged, wear, 110 count
D2020 Domestic Water Distribution		100% x None	Minor	Moderate Major	x Replace	100%	\$102,368	S Old, asbestos insulation
D2030 Sanitary Waste		100% x None	Minor	Moderate Major	x Replace	100%	\$102,368	S Original 1967 SS piping
D2040 Rain Water Drainage		o None	Minor	Moderate Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate Major	Replace			
D30 HVAC				<del></del>				
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
					· ·			State of Orego

D3020 Heat Generating Systems	Boiler	95% x None	Minor	Moderate	Major	x Replace	100%	\$129,666	Ī	Original 1967 equipment
<i>5 .</i>	Air Handler	5% x None	Minor	Moderate	Major	Replace		\$0		No Issues, Portables
	Furnace	o None	Minor	Moderate	Major	Replace		\$0		
	Heat Exchanger	o None	Minor	Moderate	Major	Replace		\$0		
D3030 Cooling Generating Systems	Component of air handler	o None	Minor	Moderate	Major	Replace		\$0		
25050 Cooming Centerating Systems	Stand alone chiller	o None	Minor	Moderate	Major	Replace		\$0		
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate	Major	x Replace	100%	\$68,245	S	Old, original installation
D3040 Distribution Systems	Hot water return & supply	o None	Minor	Moderate	Major	Replace	10070	\$08,243	3	ora, originar motamation
D3050 Terminal & Package Units	Above ceiling VAV unit	o None	Minor	Moderate	Major	Replace	$\vdash$	\$0 \$0		
D3030 Terrillial & Fackage Offics	In-room ventilator unit	o None	Minor	Moderate	Major	Replace		\$0 \$0		
	In-room radiant unit	o None	Minor	Moderate	Major					
D3060 Controls & Instrumentation	III-100III Tadiaiit diiit					Replace		\$0 \$0		No Issues
			Minor	Moderate	Major	Replace	1000/	<u> </u>		NO issues
D3070 Systems Testing & Balancing	MOTUSED	100% x None	Minor	Moderate	Major	x Replace	100%	\$34,123	I	
D3090 Other HVAC Systems & Equip	LINOT OSED	None	Minor	Moderate	Major	Replace	_			_
D40 Fire Protection						<u> </u>		4.5		
D4010 Sprinklers		o None	Minor	Moderate	Major	Replace		\$0		
D4020 Standpipes		o None	Minor	Moderate	Major	Replace		\$0		
D4030 Fire Protection Specialties		o None	Minor	Moderate	Major	Replace		\$0		
D4090 Other Fire Protection System	s NOT USED	None	Minor	Moderate	Major	Replace				
<u>D50 Electrical</u>		<del></del>			_	<del></del>	<del> </del>			
D5010 Electrical Service & Distributi	on	1000/ v None	Minor	Madarata	Major	y Donlage	100%	¢272.001		Main service and panelboard
	Off	100% x None	Minor	Moderate	Major	x Replace		\$272,981	<u>'</u>	-
D5020 Lighting and Branch Wiring	V : 15 : 6 :	100% x None	Minor	Moderate	Major	x Replace	100%	\$409,472	<u>'</u>	Old Fixtures and wiring
D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Clock / Intercom System	o None	Minor	Moderate	Major	Replace		\$0		
	Closed Circuit Surveillance	o None	Minor	Moderate	Major	Replace		\$0		
	Access Control System	o None	Minor	Moderate	Major	Replace		\$0		N
	Intrusion Alarm System	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Fire Alarm / Detection	o None	Minor	Moderate	Major	Replace		\$0		
	Lighting Control System	o None	Minor	Moderate	Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Major	Replace				
EQUIPMENT & FURNISHINGS										
E10 Equipment										
										All equipment is old and som
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate	Major	x Replace	100%	\$68,245	S	non functional
	Vocational	o None	Minor	Moderate	Major	Replace		\$0		
E1020 Institutional Equipment	Science	o None	Minor	Moderate	Major	Replace		\$0		
	Art	o None	Minor	Moderate	Major	Replace		\$0		
	Stage Performance	1250 x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Restroom Accessories/Stalls	100% x None	Minor	Moderate	Major	x Replace	100%	\$853,067	S	106 fixture count
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace				
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace				
E20 Furnishings						•				
		100% x None	x Minor	Moderate	Maior	Replace	10%	\$5,118	S	Cabinetry repairs
E2010 Fixed Furnishings		10070								
E2010 Fixed Furnishings E2020 Movable Furnishings		100% x None	Minor	Moderate	Major	Replace		\$0		No Issues

State of Oregon School Facilities Assessment Template 6/2016

BUILDING SITE WORK											
G10 Site Preparation	NOT USED										
G20 Site Improvements						_					
G2010 Roadways		o None	Minor	Modera	ate	Major	Replace		\$0		
G2020 Parking Lots		46300 x None	Minor	Modera	ate x	Major	Replace	100%	\$444,619	S	Cracks, voids, base failure
G2030 Pedestrian Paving		11000 x None	Minor	Modera	ate	Major	Replace		\$0		No Issues
G2040 Site Development		2540 x None	Minor	Modera	ate	Major	x Replace	80%	\$140,929	ı	North, South, and west fence
G2050 Landscaping		38000 x None	Minor	Modera	ate	Major	Replace		\$0		No Issues
G30 Site Mechanical Utilities									-	-	
G3010 Water Supply	Domestic	100% x None	Minor	Modera	ate	Major	Replace		\$0		No Issues
	Fire	o None	Minor	Modera	ate	Major	Replace		\$0		
G3020 Sanitary Sewer		100% x None	Minor	Modera	ate	Major	Replace		\$0		No Issues
G3030 Storm Sewer		o None	Minor	Modera	ate	Major	Replace		\$0		
G3040 Heating Distribution		o None	Minor	Modera	ate	Major	Replace		\$0		
G3050 Cooling Distribution		o None	Minor	Modera	ate	Major	Replace		\$0		
G3060 Fuel Distribution		o None	Minor	Modera	ate	Major	Replace		\$0		
G3090 Other Site Mechanical Util	litie: NOT USED	None	Minor	Modera	ate	Major	Replace				
G40 Site Electrical Utilities						•			_		
G4010 Electrical Distribution	Service	o None	Minor	Modera	ate	Major	Replace		\$0		
	Generator	o None	Minor	Modera	ate	Major	Replace		\$0		
G4020 Site Lighting		100% x None	Minor	Modera	ate	Major	x Replace	100%	\$102,368	ı	Two pole light fixtures
G4030 Site Communications & Se	ecurity	o None	Minor	Modera	ate	Major	Replace		\$0		
G4090 Other Site Electrical Utiliti	es NOT USED	None	Minor	Modera	ate	Major	Replace				
G90 Other Site Construction	NOT USED	-	<del></del>			•			_		
THER											
				Unit	of		Unit			Rank	
<u>Description of System</u>				Measi	ure	Quantity	Budget		Extended	(I,S,L)	Notes
									(	50	
							1		(	50	
							1		(	50	
							1		(	50	
										50	
								]	Ç.	50	
								7		50	

Physical Condition Budget Sub-Total \$4,601,015

Budgeted Development Costs \$1,748,386

Physical Condition Budget TOTAL \$6,349,401

Replacement Budget \$13,350,051

District Name:	Three Rivers/Josephine County SI
Site Name:	Manzanita ES
Building Name:	
Building ID:	

# REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LEVEL OF ACTION	ON					
								% of		Necessity	
	_ , , , , , ,	% of Building						System or	Automated Budget	Rank	
Level 1   Level 2   Level 3	Type (as applicable)	or Number	None	Minor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCTURE  A10 Foundations											
A1010 Standard Foundations		25%	None	Minor	Moderate	Maior	Replace		\$0		No Issues, Gym foundation
A1020 Special Foundations			None	Minor	Moderate	Major	Replace		\$0		no issues, cym reunauten
A1030 Slab on Grade			None	Minor	Moderate		Replace		\$0		No Issues
A20 Basement Construction		,3,0	·		Moderate	iviajo:	пертисс		Ψ.		
A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace				
A2020 Basement Walls			None	Minor	Moderate		Replace		\$0		
B SHELL					_ <u></u>				·		
B10 Superstructure											
B1010 Floor Construction	Wood	(	None	Minor	Moderate	Major	Replace		\$0		
	Steel	(	None	Minor	Moderate	Major	Replace		\$0		
	Concrete	100%	None	Minor	Moderate	Major	Replace		\$0		25% Concrete, 75% Slab on grade, No Issues
B1020 Roof Construction	Wood	100%	None	Minor	Moderate	x Major	Replace	10%	\$58,633	I	Exterior exposed beams, wood rot
	Steel		None	Minor	Moderate	Major	Replace		\$0		
	Concrete	C	None	Minor	Moderate	Major	Replace		\$0		
B20 Exterior Enclosure											
B2010 Exterior Walls	Concrete Formed / Tilt		None	Minor	Moderate		Replace		\$0		
	Masonry		None	Minor	Moderate	Major	Replace		\$0		No Issues
	Framed w/Panel Siding		None	Minor	Moderate	Major	Replace		\$0		
	Framed w/Stucco		None	Minor	Moderate	Major	Replace		\$0		
D2020 5 1 1 1 1 1 1	Framed w/Masonry Veneer		None	Minor	Moderate	Major	Replace	4000/	\$0		Wood not in france
B2020 Exterior Windows	Wood		None	Minor	Moderate	Major	x Replace	100%	\$781,770	ļi .	Wood rot in frames
	Aluminum/Steel		None	Minor	Moderate	Major	Replace		\$0 \$0		
	Clad Curtain Wall		None	Minor Minor	Moderate	Major	Replace		\$0 \$0		
B2030 Exterior Doors	Wood		None None	Minor	Moderate x Moderate	Major Major	Replace Replace	100%	\$12,804	c	Minor door repairs and paint
B2030 Exterior Doors	Hollow Metal		None	Minor	Moderate		Replace	10076	\$12,804	3	No Issues
	Storefront		None		Moderate	Major	Replace		\$0		140 133003
B30 Roofing	Storenone		None	IVIIIIOI	Woderate	iviajoi	Перисс		ΨŪ		
B3010 Roof Coverings	Asphalt Shingle	5%	None	Minor	Moderate	Maior	x Replace	75%	\$10,261	S	Portables; Comp Lab and Family Advocate
	Built-Up		None	Minor	Moderate	Major	x Replace	100%	\$371,341	S	Original roof, worn, leaking
	Single Ply		None	Minor	Moderate	Major	Replace		\$0		
	Metal		None	Minor	Moderate	Major	Replace		\$0		
	Concrete Tile		None	Minor	Moderate	Major	Replace		\$0		
B3020 Roof Openings	Skylights	(	None	Minor	Moderate	Major	Replace		\$0		
	Access Hatch	C	None	Minor	Moderate	Major	Replace		\$0		
C INTERIORS											
C10 Interior Construction											
C1010 Partitions	Framed		None	Minor	Moderate	Major	Replace		\$0		No Issues
	Masonry	C	None	Minor	Moderate	Major	Replace		\$0		State of Orogo

C1020 Interior Doors	Wood	91	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Hollow Metal		o None	Minor	Moderate	Major	Replace		\$0		
C1030 Fittings	NOT USED		None	Minor	Moderate	Major	Replace				
C20 Stairs											
C2010 Stair Construction	Wood	2	x None	Minor		Major	Replace		\$0		No Issues
	Metal		o None	Minor	Moderate	Major	Replace		\$0		
	Concrete		o None	Minor	Moderate	Major	Replace		\$0		
C2020 Stair Finishes	Concrete Fill		o None	Minor	Moderate	Major	Replace		\$0		
	Resilient	100%	x None	Minor	Moderate	Major	x Replace	100%	\$11	S	Replace tread and nosings
C30 Interior Finishes											
C3010 Wall Finishes	Paint on Masonry		o None	Minor	Moderate	Major	Replace		\$0		
	Wallboard	100%	x None	x Minor	Moderate	Major	Replace	100%	\$58,633	S	Touch up, repairs and repaint
	Wainscot		o None	Minor	Moderate	Major	Replace		\$0		
	Ceramic Tile		o None	Minor	Moderate	Major	Replace		\$0		
C3020 Floor Finishes	Carpet / Soft Surface	5%	x None	Minor	Moderate	Major	x Replace	100%	\$11,433	S	Worn, dirty, aged
	Resilient Tile	88%	x None	Minor	Moderate	Major	x Replace	100%	\$189,188	I	VAT and old VCT
	Resilient Sheet	5%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Polished Concrete	2%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Ceramic Tile		o None	Minor	Moderate	Major	Replace		\$0		
	Liquid Applied		o None	Minor	Moderate	Major	Replace		\$0		
	Wood Sports Floor		o None	Minor	Moderate	Major	Replace		\$0		
C3030 Ceiling Finishes	Wallboard		o None	Minor	Moderate	Major	Replace		\$0		
	Lay-In Ceiling Tile	1%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Glued-Up Ceiling Tile	99%	x None	Minor	Moderate	Major	x Replace	100%	\$174,139	S	Original tile, failing, falling
	Painted Structure		o None	Minor	Moderate	Major	Replace		\$0		
VICES			<u></u>								
D10 Conveying											
D1010 Elevators & Lifts			o None	Minor	Moderate	Major	Replace		\$0		
D1020 Escalators & Moving Walk	5		o None	Minor	Moderate	Major	Replace		\$0		
D1090 Other Conveying Systems			o None	Minor	Moderate	Major	Replace		\$0		
D20 Plumbing							· · · · · · · · · · · · · · · · · · ·				
D2010 Plumbing Fixtures		100%	x None	Minor	Moderate	Major	x Replace	100%	\$273,619	S	104 fixtures, old, damaged
D2020 Domestic Water Distributi	on	100%	x None	Minor	Moderate	Major	x Replace	100%	\$117,265	S	Asbestos insulation. Original piping
D2030 Sanitary Waste		100%	x None	Minor	Moderate	Major	x Replace	100%	\$117,265	S	Original SS piping
D2040 Rain Water Drainage			0 None	Minor	Moderate	Major	Replace		\$0		
D2090 Other Plumbing Systems	NOT USED		None	Minor	Moderate	Major	Poplace				
	NOT OSED				iviouerate	iviajoi	Replace				
D30 HVAC	1101 0325				ivioderate	iviajoi	Replace				
D30 HVAC	1101 0325	100%		Minor					<b>\$</b> 0		No Issues
	Boiler	100% 98%	x None		Moderate Moderate	Major Major	Replace	50%	\$0 \$76,613	S	No Issues Replace the older of two boilers
D30 HVAC D3010 Energy Supply			x None	Minor	Moderate	Major		50%	\$76,613	S	
D30 HVAC D3010 Energy Supply	Boiler	98%	x None x None x None	Minor Minor	Moderate Moderate Moderate	Major Major Major	Replace x Replace Replace	50%	\$76,613 \$0	S	Replace the older of two boilers
D30 HVAC D3010 Energy Supply	Boiler Air Handler Furnace	98%	x None x None x None o None	Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major Major	Replace x Replace Replace Replace	50%	\$76,613 \$0 \$0	S	Replace the older of two boilers
D30 HVAC  D3010 Energy Supply  D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger	98%	x None x None x None o None o None	Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major	Replace x Replace Replace Replace Replace	50%	\$76,613 \$0 \$0 \$0	S	Replace the older of two boilers
D30 HVAC D3010 Energy Supply	Boiler Air Handler Furnace Heat Exchanger as Component of air handler	98%	x None x None x None o None o None o None	Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major	Replace x Replace Replace Replace Replace Replace	50%	\$76,613 \$0 \$0 \$0 \$0 \$0	S	Replace the older of two boilers
D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating System	Boiler Air Handler Furnace Heat Exchanger as Component of air handler Stand alone chiller	98%	x None x None x None O None O None O None O None	Minor Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major Major Major	Replace x Replace Replace Replace Replace Replace Replace Replace		\$76,613 \$0 \$0 \$0 \$0 \$0 \$0	S	Replace the older of two boilers  No Issues, Portables
D30 HVAC  D3010 Energy Supply  D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger as Component of air handler Stand alone chiller Ductwork	98% 2%	x None x None x None o None o None o None o None x None x None	Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate x Moderate	Major	Replace x Replace Replace Replace Replace Replace Replace Replace Replace	100%	\$76,613 \$0 \$0 \$0 \$0 \$0 \$0 \$117,265	S	Replace the older of two boilers  No Issues, Portables  Original system
D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating System  D3040 Distribution Systems	Boiler Air Handler Furnace Heat Exchanger as Component of air handler Stand alone chiller Ductwork Hot water return & supply	98%	x None x None x None O None O None O None X None X None X None	Minor	Moderate	Major	Replace x Replace Replace Replace Replace Replace Replace Replace Replace x Replace		\$76,613 \$0 \$0 \$0 \$0 \$0 \$0 \$117,265 \$195,442	S S I	Replace the older of two boilers  No Issues, Portables  Original system
D30 HVAC  D3010 Energy Supply D3020 Heat Generating Systems  D3030 Cooling Generating System	Boiler Air Handler Furnace Heat Exchanger as Component of air handler Stand alone chiller Ductwork	98% 2%	x None x None x None o None o None o None o None x None x None	Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate x Moderate	Major	Replace x Replace Replace Replace Replace Replace Replace Replace Replace	100%	\$76,613 \$0 \$0 \$0 \$0 \$0 \$0 \$117,265	S S I	Replace the older of two boilers  No Issues, Portables

D3060 Controls & Instrumentation	1	100% x None Minor	Moderate Major	Replace		\$0		No Issues
D3070 Systems Testing & Balancin		100% x None Minor	Moderate Major	x Replace	100%	\$39,088	ı	
D3090 Other HVAC Systems & Equ		None Minor	Moderate Major	Replace				
D40 Fire Protection								
D4010 Sprinklers		o None Minor	Moderate Major	Replace		\$0		
D4020 Standpipes		o None Minor	Moderate Major	Replace		\$0		
D4030 Fire Protection Specialties		o None Minor	Moderate Major	Replace		\$0		
D4090 Other Fire Protection Syste	m NOT USED	None Minor	Moderate Major	Replace				
D50 Electrical				•				
D5010 Electrical Service & Distribu	ution	100% x None Minor	Moderate Major	x Replace	100%	\$312,708	I	Original switchgear and panelboards
D5020 Lighting and Branch Wiring		100% x None Minor	Moderate Major	x Replace	100%	\$469,062	I	Original lighting and wiring
D5030 Communications & Securit	y Voice / Data System	100% x None Minor	Moderate Major	Replace		\$0		No Issues
	Clock / Intercom System	o None Minor	Moderate Major	Replace		\$0		
	Closed Circuit Surveillance	o None Minor	Moderate Major	Replace		\$0		
	Access Control System	o None Minor	Moderate Major	Replace		\$0		
	Intrusion Alarm System	100% x None Minor	Moderate Major	Replace		\$0		No Issues
	Fire Alarm / Detection	o None Minor	Moderate Major	Replace		\$0		
	Lighting Control System	o None Minor	Moderate Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None Minor	Moderate Major	Replace		·		
				-				
QUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	100% x None Minor	Moderate Major	x Replace	100%	\$78,177	S	Old, some equipment not functional
	Vocational	0 None Minor	Moderate Major	Replace		\$0		
E1020 Institutional Equipment	Science	0 None Minor	Moderate Major	Replace		\$0		
	Art	0 None Minor	Moderate Major	Replace		\$0		
	Stage Performance	1250 x None Minor	Moderate Major	Replace		\$0		No Issues
	Restroom Accessories/Stalls	s 100% x None Minor	Moderate Major	x Replace	100%	\$977,212	I	Replace all 80 partitions
E1030 Vehicular Equipment	NOT USED	None Minor	Moderate Major	Replace				
E1090 Other Equipment	NOT USED	None Minor	Moderate Major	Replace				
E20 Furnishings				-				
E2010 Fixed Furnishings		100% x None x Minor	Moderate Major	Replace	100%	\$58,633	S	Repair minor damage, paint
E2020 Movable Furnishings			Moderate Major	Replace		\$0		No Issues
PECIAL CONSTRUCTION & DEMOLITION - NOT U	ISED							
ILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements								
G2010 Roadways		o None Minor	Moderate Major	Replace		\$0		
G2020 Parking Lots		51730 x None x Minor	Moderate Major	Replace	100%	\$165,588	S	Asphalt repair, resurface, marking
G2030 Pedestrian Paving		11300 x None Minor	Moderate Major	Replace		\$0		No Issues
		1500 x None Minor	Moderate Major	Replace		\$0		No Issues
G2040 Site Development			NA a dayata	Replace		\$0		No Issues
G2040 Site Development G2050 Landscaping		116000 x None Minor	Moderate				_	
		116000 x None Minor	Moderate					
G2050 Landscaping	Domestic	116000 x None Minor  100% x None Minor	Moderate Major	Replace		\$0		No Issues
G2050 Landscaping G30 Site Mechanical Utilities	Domestic Fire					\$0 \$0		No Issues
G2050 Landscaping G30 Site Mechanical Utilities		100% x None Minor	Moderate Major	Replace				No Issues No Issues
G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply		100% x None Minor 0 None Minor	Moderate Major Moderate Major	Replace Replace		\$0		
G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer		100% x None Minor 0 None Minor 100% x None Minor	Moderate Major Moderate Major Moderate Major	Replace Replace Replace		\$0 \$0		

School Facilities Assessment Template

G3060 Fuel Distribution G3090 Other Site Mechanical Utilitic	NOT LISED	o None Minor None Minor	Moderate Moderate	Major Major	Replace Replace		\$0		
G40 Site Electrical Utilities	NOT USED	None Ivillo	Moderate	iviajoi	Replace		_		
	Service	o None Minor	Moderate	Major	Replace		\$0		
	Generator	o None Minor	Moderate	Major	Replace		\$0		
G4020 Site Lighting	100%	x None Minor	Moderate	Major	x Replace	100%	\$117,265	5	2 pole light fixtures
G4030 Site Communications & Securi	rity	o None Minor	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical Utilities N	NOT USED	None Minor	Moderate	Major	Replace				
G90 Other Site Construction	NOT USED						_		
OTHER									
			Unit of		Unit			Rank	
<u>Description of System</u>			Measure	Quantity	Budget		Extended	(I,S,L)	Notes
							\$0		
							\$0		
							\$0		
							\$0		
							\$0		
							\$0		
							\$0		

Physical Condition Budget Sub-Total \$4,783,416

Budgeted Development Costs \$1,817,698

Physical Condition Budget TOTAL \$6,601,114

Replacement Budget \$15,292,863

District Name:	Three Rivers/Josephine County SD
Site Name:	Williams ES
<b>Building Name:</b>	
Building ID:	

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

				ſ								T			
							-	LE	VEL OF ACTION	1		0/ - 0			
				0/ - f D 21-11								% of	A I I . I B . I I	Necessity	
Laurald		Laural 2	Time (or applicable)	% of Building		Nama			0.0	D. 0 - 1	Daula sa	System or Finish	Automated Budget	Rank	Notes
Level 1 A SUBST		1	Type (as applicable)	or Number		None	IVI	nor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
	A10 Four														
;		A1010 Standard Foundations		33%	<u>,                                    </u>	None	Mino	r	Moderate	Major	Replace		\$0		No Issues, Portables
		A1020 Special Foundations		33%	_	None	Mino			Major	Replace		\$0 \$0		No Issues, Main Bldg
		A1030 Slab on Grade		34%	_	None	Mino			Major	Replace		\$0 \$0		No Issues, Gym and classrooms
		ement Construction		34/0	Λ	None	IVIIIIC	' L	Moderate	iviajoi	Replace		ŞU		No issues, dyni and classicoms
:		A2010 Basement Excavation	NOT USED			None	Mino	r	Moderate	Major	Replace				
		A2020 Basement Walls	NOT USED	50%			Mino		Moderate x	-	Replace	20%	\$61,449	lı.	Water infiltration, cracks
B SHELL		AZOZO Basement wans		30%		None	IVIIIIC	<u> </u>	iviouerate x	iviajoi	Replace	20%	Ş01,449	Į!	water initiation, cracks
		erstructur <u>e</u>													
•		B1010 Floor Construction	Wood	50%	v	None	Mino	. F	Moderate	Major	Replace		\$0		No Issues
		B1010 F100F Construction	Steel	3076	_	None	Mino		Moderate	Major	Replace		\$0 \$0		140 1554005
			Concrete	50%	_	None	Mino	_	Moderate	Major	Replace		\$0 \$0		No Issues
		B1020 Roof Construction	Wood	100%	_	None	Mino			Major	Replace		\$0 \$0		No Issues
		B1020 R001 CONSTRUCTION	Steel	100%	_	None	Mino			Major	Replace		\$0 \$0		140 133463
			Concrete		_	None	Mino			-			\$0 \$0		
	D20 Euto	rior Englosuro	Concrete		0	None	IVIIIIC	ľ	Moderate	Major	Replace		\$U		
		rior Enclosure	Concrete Formed / Tilt			None	Mina	. г	Moderate	Major	Poplace		ćn		T
		B2010 Exterior Walls	Concrete Formed / Tilt			None	Mino Mino		_	Major	Replace		\$0 \$0		
			Masonry Framed w/Panel Siding	100%		None None	Mino	_	_	Major	Replace x Replace	60%	\$553,037		Main Building, Gym, 3 classroom wing
			•	100%	_				_	Major		60%		l .	Ividin Bullullig, Gym, 3 classi oom wilig
			Framed w/Stucco		_	None	Mino			Major	Replace		\$0		
		D2020 Futanian Windows	Framed w/Masonry Veneer		_	None	Mino	_	_	Major	Replace		\$0		
		B2020 Exterior Windows	Wood	100%	_	None	Mino	_	_	Major	Replace		\$0		No Issues
			Aluminum/Steel	100%	_	None	Mino	_		Major	Replace		\$0		ivo issues
			Clad		_	None	Mino			Major	Replace		\$0		
		D2020 Futuring Dance	Curtain Wall	20	_	None	Mino		_	Major	Replace	1000/	\$0	C	All exterior wood doors
		B2030 Exterior Doors	Wood	29	_	None	Mino	_	_	Major	x Replace	100%	\$46,415	5	No Issues
			Hollow Metal	2	_	None	Mino	_		Major	Replace		\$0		NO ISSUES
	D20 D (	r	Storefront		0	None	Mino	r	Moderate	Major	Replace		\$0		
•	B30 Roof	_		0.60/		I	<b>—</b> ]:		<b>–</b>	1	<u> </u>	1000/	dags 457	6	All shingle roofs are 20+ years old
		B3010 Roof Coverings	Asphalt Shingle	96%	_	None	Mino	_		Major	x Replace	100%	\$206,467	5	,
			Built-Up	1%	_	None	Mino	_		Major	x Replace	100%	\$3,072	5	Restroom roof
			Single Ply	3%	_	None	Mino			Major	Replace		\$0		No issues, breezeway roof, 2003
			Metal		_	None	Mino	_	Moderate	Major	Replace		\$0		
			Concrete Tile		_	None	Mino		Moderate	Major	Replace		\$0		
		B3020 Roof Openings	Skylights			None	Mino		Moderate	Major	Replace		\$0		
			Access Hatch		0	None	Mino	r	Moderate	Major	Replace		\$0		
C INTER		in Court of the													
		rior Construction	Formed	1000/		, I							40		INo legues
		C1010 Partitions	Framed	100%		None	Mino			Major	Replace		\$0		No Issues
		040001	Masonry		_	None	Mino			Major	Replace	5001	\$0		Main Duilding into the days
		C1020 Interior Doors	Wood	28	_	None	Mino		_	Major	x Replace	50%	\$19,419	S	Main Building interior doors
			Hollow Metal		0	None	Mino	r	Moderate	Major	Replace		\$0		State of Ore

C1030 Fittings	NOT USED	N	one Minor	r Moderate	Major	Replace		_	
C20 Stairs			<u> </u>					_	
C2010 Stair Construction	Wood	9 x N	one Minor	r Moderate	Major	Replace		\$0	No Issues, no finishes
	Metal	o N	one Mino	r Moderate	Major	Replace		\$0	
	Concrete	6 x N	one Minor	r Moderate	Major	Replace		\$0	No Issues, no finishes
C2020 Stair Finishes	Concrete Fill	o N	one Mino	r Moderate	Major	Replace		\$0	
	Resilient	o N	one Minor	r Moderate	Major	Replace		\$0	
C30 Interior Finishes						<u> </u>		<u>-</u>	
C3010 Wall Finishes	Paint on Masonry	o N	one Mino	r Moderate	Major	Replace		\$0	
	Wallboard	100% x N	one Mino	r x Moderate		Replace	100%	\$92,173	Touch up and paint all interior walls
	Wainscot	o N				Replace		\$0	
	Ceramic Tile	o N	<b>—</b>			Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	58% x N				x Replace	100%	\$104,247	Replace all, age, wear, torn, odor
	Resilient Tile	20% x N				x Replace	100%	\$33,797	Old VAT, VCT
	Resilient Sheet	2% x N				x Replace	100%	\$3,687	Kitchen floor
	Polished Concrete	20% x N				Replace	10070	\$0	No Issues
	Ceramic Tile	0 N	<b>—</b>			Replace		\$0	
	Liquid Applied	0 N				Replace		\$0	
C2020 Cailing Finishes	Wood Sports Floor	0 N				Replace	1000/	\$0	Repairs and touch up
C3030 Ceiling Finishes	Wallboard	75% x N				Replace	100%	\$57,608	s Repairs and touch up
	Lay-In Ceiling Tile	0 N				Replace	1000/	\$0	Octobrilla de la constantina del constantina de la constantina del constantina de la constantina del
	Glued-Up Ceiling Tile	25% x N			-	x Replace	100%	\$34,565	Original tile system, falling/failing tiles
	Painted Structure	o N	one Minor	r Moderate	Major	Replace		\$0	
RVICES									
D10 Conveying						_			
D1010 Elevators & Lifts		o N				Replace		\$0	
D1020 Escalators & Moving Walks		o N		r Moderate	Major	Replace		\$0	
D1090 Other Conveying Systems		o N	one Minor	r Moderate	Major	Replace		\$0	
D20 Plumbing			<u></u>	<u> </u>		<u></u>		_	
D2010 Plumbing Fixtures		100% x N	one Minor	r Moderate	Major	x Replace	100%	\$215,070	Replace all old fixtures, 44 count
D2020 Domestic Water Distribution		100% x N	one Mino	r Moderate	Major	x Replace	100%	\$92,173	Dirty water
D2030 Sanitary Waste		100% x N	one Mino	r Moderate	Major	Replace		\$0	No Issues
D2040 Rain Water Drainage		o N	one Minor	r Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	N	one Minor	r Moderate		Replace			
D30 HVAC						•			
D3010 Energy Supply		100% x N	one Mino	r Moderate	Major	Replace		\$0	No Issues
D3020 Heat Generating Systems	Boiler	60% x N				Replace		\$0	No Issues
20020 20	Air Handler	40% x N				x Replace	30%	\$11,061	Portables, 3 each, D's and G bldgs
	Furnace	0 N				Replace	3070	\$0	
	Heat Exchanger	0 N				Replace		\$0	
D3030 Cooling Generating Systems	Component of air handler	0 N				Replace		\$0	
D3030 Cooling Generating Systems	Stand alone chiller						$\vdash$		
D2040 Distribution Customs		0 N				Replace		\$0	No Issues
D3040 Distribution Systems	Ductwork	100% x N				Replace		\$0 \$0	No Issues
D0050 T	Hot water return & supply	0 N				Replace		\$0	
D3050 Terminal & Package Units	Above ceiling VAV unit	0 N			-	Replace		\$0	
	In-room ventilator unit	o N			_	Replace		\$0	
	In-room radiant unit	o N			-	Replace		\$0	
D3060 Controls & Instrumentation		100% x N	one Minor	r Moderate	Major	Replace		\$0	No Issues
D3070 Systems Testing & Balancing		100% x N	one Minor	r Moderate	Major	x Replace	100%	\$30,724	
D3090 Other HVAC Systems & Equip	om NOT USED	N	one Minor	r Moderate	Major	Replace			
<u>D40 Fire Protection</u>				<u></u>					

DAGAG Carialdara		None	Minor	Madarata	Donlage		ćo		
D4010 Sprinklers D4020 Standpipes		o None o None	Minor Minor	Moderate Major  Moderate Major	Replace Replace		\$0 \$0		
D4020 Standpipes  D4030 Fire Protection Specialties		o None	Minor	Moderate Major	Replace		\$0 \$0		
D4030 File Protection Specialities  D4090 Other Fire Protection Systematics	ome NOT LISED	None	Minor				ŞÜ		
<u>D50 Electrical</u>	enis NOT USED	None	WIIIIOI	Moderate Major	Replace				
D50 Electrical  D5010 Electrical Service & Distrib	ution	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
D5010 Liectrical Service & Distrib		100% x None	Minor	Moderate Major	x Replace	100%	\$368,691	c	Replace old wiring and fixtures
D5030 Communications & Securit		100% x None	Minor	Moderate Major	Replace	10070	\$0	3	No Issues
D3030 Communications & Securit	Clock / Intercom System	o None	Minor	Moderate Major	Replace	H	\$0		140 155405
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0 \$0		
	Access Control System	o None	Minor	Moderate Major	Replace		\$0		
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace		\$0		1.0.0000
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace		γo		
boost other Electrical systems	1101 0020	None	······································	Major	перисс				
EQUIPMENT & FURNISHINGS									
E10 Equipment									
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$61,449	I	Equipment is old, not functional
	Vocational	o None	Minor	Moderate Major	Replace		\$0		
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0		
·	Art	o None	Minor	Moderate Major	Replace		\$0		
	Stage Performance	364 x None	Minor	Moderate Major	Replace		\$0		No Issues
	Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	x Replace	100%	\$768,107	I	Replace all
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace				
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace				
E20 Furnishings									
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$368,691	S	Original cabinetry
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace		\$0		No Issues
SPECIAL CONSTRUCTION & DEMOLITION - NOT U	JSED							•	
BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
G20 Site Improvements		,	<b>—</b>		<u> </u>		40		
G2010 Roadways		o None	Minor	Moderate Major	Replace	1000/	\$0		Total failure of combalt and group overtons
G2020 Parking Lots		23127 x None	Minor	Moderate Major	x Replace	100%	\$160,397	l	Total failure of asphalt and gravel system
G2030 Pedestrian Paving		800 x None	Minor	Moderate Major	Replace	1000/	\$0		No Issues
G2040 Site Development		1484 x None	Minor	Moderate Major	x Replace	100%	\$102,923	l	Not functional, not 6'
G2050 Landscaping		24368 x None	Minor	Moderate	Replace		\$0		No Issues
G30 Site Mechanical Utilities		1000/			<u> </u>	1000/	422 724		Distr. Mator
G3010 Water Supply	Domestic	100% x None	Minor	Moderate Major	x Replace	100%	\$30,724	I	Dirty Water
C2020 Caritary Carray	Fire	o None	Minor	Moderate Major	Replace		\$0		No issues
G3020 Sanitary Sewer		100% x None	Minor	Moderate Major	Replace		\$0		NO ISSUES
G3030 Storm Sewer		o None	Minor	Moderate Major	Replace		\$0 \$0		
G3040 Heating Distribution		o None	Minor	Moderate Major	Replace		\$0		
G3050 Cooling Distribution		o None	Minor	Moderate Major	Replace		\$0		
G3060 Fuel Distribution	itios NOT USED	o None	Minor	Moderate Major	Replace		\$0		
G3090 Other Site Mechanical Util	ities NUT USED	None	Minor	Moderate Major	Replace				
G40 Site Electrical Utilities	Sarvica	n Naga	N/in ac	Modorata	Danlage		ćo		
G4010 Electrical Distribution	Service	o None	Minor	Moderate Major	Replace		\$0 \$0		
	Generator	o None	Minor	Moderate Major	Replace		\$0		
G4020 Site Lighting		o None	Minor	Moderate Major	Replace		\$0		

School Facilities Assessment Template

	G4030 Site Communications & Secu G4090 Other Site Electrical Utilities		o No	Moderate Moderate	Maj Maj		Replace Replace	\$0		
G90 Othe	r Site Construction	NOT USED								
OTHER									_	
				Unit of			Unit		Rank	
<u>Description</u>	on of System			 Measure	Qu	uantity	Budget	Extended	(I,S,L)	Notes
								\$0		
								\$0		
								\$0		
								\$0		
								\$0		
								\$0		
								\$(		

Physical Condition Budget Sub-Total \$3,425,945

Budgeted Development Costs \$1,301,859

Physical Condition Budget TOTAL \$4,727,804

Replacement Budget \$12,020,473

District Name:	Three Rivers/Josephine County SD	
Site Name:	Fleming MS	
Building Name:		(
Building ID:		

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

							LEVEL OF ACT	ON			1			
							LEVEL OF ACT	T T			% of		Necessity	
				% of Building							System or	Automated Budget	Rank	
Level 1	Level 2	Level 3	Type (as applicable)	or Number	No	ne Minor	Modera	te	Major	Replace	Finish	Estimate		Notes
	TRUCTU		туре (не приненет)		1.10		1111000010	,	,	Портись			(-, -, -,	1
		undations												
		A1010 Standard Foundations		5%	x None	Minor	Moderat	e N	1ajor	Replace		\$0		No Issues, Gym foundation
		A1020 Special Foundations			o None	Minor	Moderat	e N	1ajor	Replace		\$0		
		A1030 Slab on Grade		95%	x None	Minor	Moderat	e N	lajor	Replace		\$0		No Issues
	A20 Base	sement Construction					<u></u>						•	
		A2010 Basement Excavation	NOT USED		None	Minor	Moderat	e N	1ajor	Replace				
		A2020 Basement Walls			o None	Minor	Moderat	e N	1ajor	Replace		\$0		
B SHEL	.L													
	B10 Sup	<u>perstructure</u>												
		B1010 Floor Construction	Wood		o None	Minor	Moderat	e N	1ajor	Replace		\$0		
			Steel		o None	Minor	Moderat	e N	1ajor	Replace		\$0		
			Concrete	100%	x None	Minor	Moderat	e N	1ajor	Replace		\$0		
		B1020 Roof Construction	Wood	100%	x None	Minor	Moderat	e N	1ajor	Replace		\$0		5% Concrete, 95% Slab on grade, No Issues
			Steel		o None	Minor	Moderat	e N	1ajor	Replace		\$0		
			Concrete		o None	Minor	Moderat	e N	1ajor	Replace		\$0		
	B20 Exte	<u>erior Enclosure</u>												
		B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor	Moderat	e N	1ajor	Replace		\$0		
			Masonry	34%	x None		Moderat		-	Replace	10%	\$23,535	I	Kitchen and East Wing water damage
			Framed w/Panel Siding	66%	x None		Moderat		1ajor	x Replace	100%	\$1,370,588	I	Replace all siding, asbestos material
			Framed w/Stucco		o None	Minor	Moderat		1ajor	Replace		\$0		
			Framed w/Masonry Veneer		o None	Minor	Moderat		1ajor	Replace		\$0		
		B2020 Exterior Windows	Wood		o None		Moderat		1ajor	Replace		\$0		
			Aluminum/Steel	100%	x None		Moderat		⁄lajor	x Replace	100%	\$899,881	I	Old, not functional, single pane
			Clad		o None	Minor	Moderat		⁄lajor	Replace		\$0		
			Curtain Wall		o None	Minor	Moderat		⁄lajor	Replace		\$0		
		B2030 Exterior Doors	Wood	55	x None		Moderat		1ajor	x Replace	100%	\$88,028	I	Wear and aged
			Hollow Metal	12	x None		Moderat		1ajor	x Replace	100%	\$16,645	I	Wear and aged
			Storefront		0 None	Minor	Moderat	e N	1ajor	Replace		\$0		
	<u>B30 Roo</u>	<del></del>				_								
		B3010 Roof Coverings	Asphalt Shingle	2%	x None		x Moderat		1ajor	Replace	100%	\$3,461	I	Kitchen walkway 25 yr old shingles, leaking
			Built-Up	97%	x None		Moderat		⁄lajor	x Replace	100%	\$671,450	I	Gym, 8th wing, band wing, walkways
			Single Ply		o None		Moderat		1ajor	Replace		\$0		
			Metal	1%	x None		Moderat		1ajor	Replace		\$0		No Issues
			Concrete Tile		o None		Moderat		/lajor	Replace		\$0		
		B3020 Roof Openings	Skylights		o None		Moderat		/lajor	Replace		\$0		
-			Access Hatch		o None	Minor	Moderat	e N	1ajor	Replace		\$0		
C INTE														
	C10 Inte	erior Construction	Former	000/				_	4-1		<u> </u>	ćo		IN a leaves
		C1010 Partitions	Framed	98%	x None		Moderat		1ajor	Replace		\$0		No Issues
		C4030 lates 5	Masonry	2%	x None		Moderat		1ajor	Replace	40001	\$0		No Issues
		C1020 Interior Doors	Wood	94	x None	Minor	Moderat	.eN	1ajor	x Replace	100%	\$130,387	5	Replace all wood doors

	Hollow Metal	o None	Minor	Moderate M	lajor	Replace		\$0		
C1030 Fittings	NOT USED	None	Minor		lajor lajor	Replace		<b>70</b>		
C20 Stairs				ouc.uto	,	Портаво				
C2010 Stair Construction	Wood	6 x None	Minor	Moderate M	1ajor	Replace		\$0		No Issues
	Metal	o None	Minor		lajor	Replace		\$0		
	Concrete	o None	Minor		lajor	Replace		\$0		
C2020 Stair Finishes	Concrete Fill	o None	Minor		lajor	Replace		\$0		
	Resilient	100% x None	Minor			x Replace	100%	\$11	S	Replace step and nosing material
C30 Interior Finishes										•
C3010 Wall Finishes	Paint on Masonry	1% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
	Wallboard	94% x None	Minor	x Moderate M	lajor	Replace	100%	\$195,205	S	Repairs and painting
	Wainscot	0 None	Minor	Moderate	1ajor	Replace		\$0		
	Ceramic Tile	5% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
C3020 Floor Finishes	Carpet / Soft Surface	30% x None	Minor	Moderate	lajor	x Replace	100%	\$121,484	S	Worn, dirty
	Resilient Tile	61% x None	Minor	Moderate N	1ajor	X Replace	100%	\$232,239	S	VAT and old VCT
	Resilient Sheet	0 None	Minor	Moderate	lajor –	Replace		\$0		
	Polished Concrete	3% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
	Ceramic Tile	1% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
	Liquid Applied	0 None	Minor	Moderate	lajor	Replace		\$0		
	Wood Sports Floor	5% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
C3030 Ceiling Finishes	Wallboard	0 None	Minor	Moderate	lajor	Replace		\$0		
	Lay-In Ceiling Tile	8% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
	Glued-Up Ceiling Tile	80% x None	Minor	Moderate	lajor	x Replace	100%	\$249,198	S	Replace all, failing, falling tiles
	Painted Structure	12% x None	Minor	Moderate	lajor	Replace		\$0		No Issues
SERVICES			_							
D10 Conveying					_					
D1010 Elevators & Lifts		o None	Minor	Moderate M	_	Replace		\$0		
D1020 Escalators & Moving Walks		o None	Minor		lajor	Replace	$\perp$	\$0		
D1090 Other Conveying Systems		o None	Minor	Moderate	lajor	Replace		\$0		
D20 Plumbing			_							Territoria de la companya dela companya dela companya dela companya de la company
D2010 Plumbing Fixtures		100% x None	Minor			x Replace	100%	\$484,551	l .	Fixtures are old, damaged, approx 125 ea.
D2020 Domestic Water Distribution		100% x None	Minor		_	x Replace	100%	\$207,665	l .	Original pipe, asbestos insulation
D2030 Sanitary Waste		100% x None	Minor			x Replace	100%	\$207,665	S	Original SS piping
D2040 Rain Water Drainage		o None	Minor		lajor	Replace		\$0		
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	lajor	Replace				
D30 HVAC		4000/	<b>—</b> ,	na a di i	г	Day 1		60		No legues
D3010 Energy Supply	Dailan	100% x None	Minor		lajor	Replace	$\vdash$	\$0		No Issues No Issues, new 2017 boiler
D3020 Heat Generating Systems	Boiler	99% x None	Minor		lajor	Replace	1000/	\$0	c	NO ISSUES, NEW 2017 BOILEI
	Air Handler	1% x None	Minor	Moderate x N		Replace	100%	\$1,384	5	
	Furnace	o None	Minor		lajor	Replace	$\vdash$	\$0		
D2020 Cooling Congrating Systems	Heat Exchanger	o None	Minor		lajor	Replace	$\vdash$	\$0		
D3030 Cooling Generating Systems	Component of air handler	o None	Minor		lajor Lajor	Replace		\$0		
D2040 Distribution Systems	Stand alone chiller	o None 100% x None	Minor		lajor Lajor	Replace	1000/	\$0		Age
D3040 Distribution Systems	Ductwork		Minor			x Replace	100%	\$138,443	ı	Roof mounted piping, aged, poor insulation
D20E0 Tornsinal & Dadlaga Unita	Hot water return & supply		Minor		-	x Replace	100%	\$346,108	I	Nooi mounted piping, aged, poor insulation
D3050 Terminal & Package Units	Above ceiling VAV unit	o None	Minor		lajor Lajor	Replace		\$0 \$0		
	In-room ventilator unit	o None	Minor Minor		lajor lajor	Replace		\$0 \$0		
D3060 Controls & Instrumentation	In-room radiant unit	o None 100% x None	Minor		lajor lajor	Replace		\$0 \$0		No Issue
D3000 Controls & Instrumentation D3070 Systems Testing & Balancing		100% x None	Minor		lajor lajor	Replace	100%	\$69,222	ı	140 13346
Double of street and of the property		TOO /0 X NOTE	IVIIIIVI	Moderate	lajor	x Replace	100/0	703,22Z	'	

D3090 Other HVAC Systems & Equipme	er NOT USED	None	Minor	Moderate	Major	Replace				
D40 Fire Protection					•	•				
D4010 Sprinklers		o None	Minor	Moderate	Major	Replace		\$0		
D4020 Standpipes		o None	Minor	Moderate	Major	Replace		\$0		
D4030 Fire Protection Specialties		o None	Minor	Moderate	Major	Replace		\$0		
D4090 Other Fire Protection Systems	NOT USED	None	Minor	Moderate	Major	Replace				
D50 Electrical										
D5010 Electrical Service & Distribution		100% x None	Minor	Moderate	Major	x Replace	100%	\$553,773	I	Original switchgear and panelboards
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate	Major	x Replace	100%	\$830,660	I	Original wiring and lighting
D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Clock / Intercom System	o None	Minor	Moderate	Major	Replace		\$0		
	Closed Circuit Surveillance	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Access Control System	o None	Minor	Moderate	Major	Replace		\$0		
	Intrusion Alarm System	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Fire Alarm / Detection	o None	Minor	Moderate	Major	Replace		\$0		
	Lighting Control System	o None	Minor	Moderate	Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Major	Replace				
E EQUIPMENT & FURNISHINGS										
E10 Equipment	Food Comics	1000/ Name	Nainan	Madarata [	N 4 = 1 = 11	x Replace	1000/	¢120.442		Old equipment, not functional
E1010 Commercial Equipment	Food Service Vocational	100% x None 100% x None	Minor Minor	Moderate Moderate	Major	x Replace	100% 100%	\$138,443 \$114,216	l I	Old equipment in Voc lab
E1020 Institutional Equipment	Science	4800 x None	Minor	Moderate	Major Major	x Replace	100%	\$114,216	1	Original Science room equipment
L1020 ilistitutional Equipment	Art	o None	Minor	Moderate	Major	Replace	100%	\$17,320	<u>'</u>	Original science room equipment
	Stage Performance	1440 x None	Minor	Moderate	Major	Replace	$\vdash$	\$0 \$0		No Issues
	Restroom Accessories/Stall		Minor	Moderate	Major	x Replace	100%	\$1,730,541	ı	Replace all
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace	10070	71,730,341	'	
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace				
E20 Furnishings	1101 0325	None		Woderate	Major	періасс				
E2010 Fixed Furnishings		100% x None	Minor	x Moderate	Maior	Replace	100%	\$207,665	S	Cabinetry repairs and paint
E2020 Movable Furnishings		100% x None	Minor	Moderate	Major	Replace		\$0		No issues
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED					- ,					
G BUILDING SITE WORK										
G10 Site Preparation	NOT USED									
G20 Site Improvements										
G2010 Roadways		25800 x None	Minor	Moderate		Replace		\$0		No Issues
G2020 Parking Lots		39000 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G2030 Pedestrian Paving		7000 x None	Minor	Moderate	Major	Replace	$\vdash$	\$0		No Issues
G2040 Site Development		3450 x None	Minor	Moderate	Major	Replace	$\vdash$	\$0		No Issues
G2050 Landscaping		168200 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G30 Site Mechanical Utilities										T., .
G3010 Water Supply	Domestic	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Fire	o None	Minor	Moderate	Major	Replace	$\vdash$	\$0		National
G3020 Sanitary Sewer		100% x None	Minor	Moderate	Major	Replace	$\vdash$	\$0		No Issues
G3030 Storm Sewer		o None	Minor	Moderate	Major	Replace	$\vdash$	\$0		
G3040 Heating Distribution		o None	Minor	Moderate	Major	Replace	$\vdash$	\$0		
G3050 Cooling Distribution		o None	Minor	Moderate	Major	Replace	$\vdash$	\$0 \$0		
G3060 Fuel Distribution	NOT LICED	o None	Minor	Moderate	Major	Replace		\$0		
G3090 Other Site Mechanical Utilities	ואטן מצבט	None	Minor	Moderate	Major	Replace				
G40 Site Electrical Utilities										State of Orego

G4010 Electrical Distribution	Service Generator	100% x None o None	Minor Minor	Moderate Moderate		Replace Replace	\$0 \$0		No Issues
G4020 Site Lighting		o None	Minor	Moderate	Major	Replace	\$0		
G4030 Site Communications & Secur	ity	o None	Minor	Moderate	Major	Replace	\$0		
G4090 Other Site Electrical Utilities	NOT USED	None	Minor	Moderate	Major	Replace			
G90 Other Site Construction	NOT USED	<u> </u>							
OTHER									
				Unit of		Unit		Rank	
<u>Description of System</u>				Measure	Quantity	Budget	Extended	(I,S,L)	Notes
<u>Description of System</u>				Measure	Quantity	Budget	Extended \$0	(I,S,L)	Notes
<u>Description of System</u>				Measure	Quantity	Budget	Extended \$0 \$0	(I,S,L)	Notes
<u>Description of System</u>				Measure	Quantity	Budget	\$0	(I,S,L)	Notes
<u>Description of System</u>				Measure	Quantity	Budget	\$0 \$0	(I,S,L)	Notes
Description of System				Measure	Quantity	Budget	\$0 \$0 \$0	(I,S,L)	Notes
<u>Description of System</u>				Measure	Quantity	Budget	\$0 \$0 \$0 \$0	(I,S,L)	Notes

Physical Condition Budget Sub-Total \$9,050,373

Budgeted Development Costs \$3,439,142

Physical Condition Budget TOTAL \$12,489,514

Replacement Budget \$28,559,273

District Name:	Three Rivers/Josephine County SD
Site Name:	Lincoln Savage Middle School
Building Name:	C
Building ID:	

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LEVEL OF ACTION			1			
Level 1 Level 2 Level 3	Type (as applicable)	% of Building or Number	None	Minor	Moderate	Major	Replace	% of System or Finish	Automated Budget Estimate	Necessity Rank (I, S, L)	Notes
A SUBSTRUCTURE											
A10 Foundations							_				
A1010 Standard Foundations		10%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
A1020 Special Foundations			o None	Minor	Moderate	Major	Replace		\$0		
A1030 Slab on Grade		90%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
A20 Basement Construction								T		_	
A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace				<u>.                                      </u>
A2020 Basement Walls			o None	Minor	Moderate	Major	Replace		\$0		
B SHELL											
<u>B10 Superstructure</u>		_									
B1010 Floor Construction	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	Steel		o None	Minor	Moderate	Major	Replace		\$0		
	Concrete	100%	x None	Minor	Moderate	Major	Replace		\$0		10% Concrete, 90% Slab on grade, No Issues
B1020 Roof Construction	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	Steel	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Concrete		o None	Minor	Moderate	Major	Replace		\$0		
<u>B20 Exterior Enclosure</u>											
B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor	Moderate	Major	Replace		\$0		
	Masonry	50%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Framed w/Panel Siding	50%	x None	Minor	Moderate	Major	x Replace	100%	\$998,568	I	Original siding, asbestos, damaged
	Framed w/Stucco		o None	Minor	Moderate	Major	Replace		\$0		
	Framed w/Masonry Veneer		o None	Minor	Moderate	Major	Replace		\$0		
B2020 Exterior Windows	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	Aluminum/Steel	100%	x None	Minor	Moderate	Major	x Replace	100%	\$865,426	I	Original windows, steel, single pane
	Clad		o None	Minor	Moderate	Major	Replace		\$0		
	Curtain Wall		o None	Minor	Moderate	Major	Replace		\$0		
B2030 Exterior Doors	Wood	54	x None	Minor	Moderate	Major	x Replace	100%	\$86,427	I	Original doors, water damage, age
	Hollow Metal	15	x None	Minor	Moderate	Major	x Replace	100%	\$20,807	S	Metal exterior doors, wear, age
	Storefront		o None	Minor	Moderate	Major	Replace		\$0		
B30 Roofing		-									
B3010 Roof Coverings	Asphalt Shingle		o None	Minor	Moderate	Major	Replace		\$0		
	Built-Up	100%	x None	Minor	Moderate	Major	x Replace	75%	\$499,284	S	All roof except the Cafeteria wing
	Single Ply		o None	Minor	Moderate	Major	Replace		\$0		
	Metal		o None	Minor	Moderate	Major	Replace		\$0		
	Concrete Tile		o None	Minor	Moderate	Major	Replace		\$0		
B3020 Roof Openings	Skylights		o None	Minor	Moderate	Major	Replace		\$0		
	Access Hatch		o None	Minor	Moderate	Major	Replace		\$0		
C INTERIORS											
C10 Interior Construction											
C1010 Partitions	Framed	95%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Masonry	5%	x None	Minor		Major	Replace		\$0		No Issues
C1020 Interior Doors	Wood	79	x None	Minor	Moderate	Major	x Replace	100%	\$109,581		Delamination, damage, age, heavy use

State of Oregon School Facilities Assessment Template

	Hollow Metal	o None	Minor	Moderate Major	Replace		\$0	
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace		,	
C20 Stairs					•			-
C2010 Stair Construction	Wood	6 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	
	Resilient	100% x None	Minor	Moderate Major	x Replace	100%	\$11	S Stair Tread non-slip surfaces worn
C30 Interior Finishes								•
C3010 Wall Finishes	Paint on Masonry	5% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Wallboard	93% x None	x Minor	Moderate Major	Replace	100%	\$92,867	S Paint and minor wall repairs
	Wainscot	o None	Minor	Moderate Major	Replace		\$0	
	Ceramic Tile	2% x None	Minor	Moderate Major	x Replace	100%	\$26,628	S Showers in lockers (currently not used)
C3020 Floor Finishes	Carpet / Soft Surface	25% x None	Minor	Moderate Major	x Replace	100%	\$97,360	I Worn, dirty, aged
	Resilient Tile	66% x None	Minor	Moderate Major	x Replace	100%	\$241,653	I VAT, VCT, damaged, broken, original tile
	Resilient Sheet	o None	Minor	Moderate Major	Replace		\$0	
	Polished Concrete	7% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Ceramic Tile	2% x None	Minor	Moderate Major	x Replace	100%	\$23,966	I Locker Room floors, damage, broken tiles
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	o None	Minor	Moderate Major	Replace		\$0	
	Lay-In Ceiling Tile	o None	Minor	Moderate Major	Replace		\$0	
	Glued-Up Ceiling Tile	90% x None	Minor	Moderate Major	x Replace	100%	\$269,613	I Failing, falling ceiling tiles, original tiles
	Painted Structure	10% x None	Minor	Moderate Major	Replace		\$0	No Issues
ERVICES								<del>-</del>
D10 Conveying		<u> </u>						
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving Wall	cs	o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Systems		o None	Minor	Moderate Major	Replace		\$0	
D20 Plumbing					<u> </u>			
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Major	x Replace	100%	\$465,998	S 117 fixtures, old, damaged, aged fixtures
D2020 Domestic Water Distribut	ion	100% x None	Minor	Moderate Major	x Replace	100%	\$199,714	S Aged
D2030 Sanitary Waste		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D2040 Rain Water Drainage		o None	Minor	Moderate Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate Major	Replace			
D30 HVAC				<del>_</del> _	<u></u>			_
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3020 Heat Generating Systems	Boiler	100% x None	Minor	Moderate Major	x Replace	100%	\$266,285	S Original 1962 boiler
	Air Handler	o None	Minor	Moderate Major	Replace		\$0	
	Furnace	o None	Minor	Moderate Major	Replace		\$0	
	Heat Exchanger	o None	Minor	Moderate Major	Replace		\$0	
D3030 Cooling Generating Syste	ns Component of air handler	o None	Minor	Moderate Major	Replace		\$0	
	Stand alone chiller	o None	Minor	Moderate Major	Replace		\$0	
					П			Special Education Classroom Wing, under sla
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate Major	x Replace	15%	\$19,971	l ducts
·	Hot water return & supply	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3050 Terminal & Package Units		o None	Minor	Moderate Major	Replace		\$0	
Dood Terminal & Lackage Office							\$0	
23030 Terrimial & Facilities	In-room ventilator unit	o None	Minor	Moderate Major	Replace		ŞU	
55050 remindra rackage omto	In-room ventilator unit In-room radiant unit	o None o None	Minor	Moderate Major Moderate Major	Replace		\$0	<del>                                     </del>

D3070 Systems Testing & Balanci	ng	100% x None	Minor	Moderate Major	x Replace	100%	\$66,571	I	
D3090 Other HVAC Systems & Eq	_	None	Minor	Moderate Major	Replace				
D40 Fire Protection									
D4010 Sprinklers		o None	Minor	Moderate Major	Replace		\$0		
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0		
D4030 Fire Protection Specialties		o None	Minor	Moderate Major	Replace		\$0		
D4090 Other Fire Protection Syst		None	Minor	Moderate Major	Replace				
<u>D50 Electrical</u>					·				
D5010 Electrical Service & Distrib	ution	100% x None	Minor	Moderate Major	x Replace	100%	\$532,570	S	Original equipment, main and panelboards
D5020 Lighting and Branch Wirin	g	100% x None	Minor	Moderate Major	x Replace	100%	\$798,854	S	Original building wiring and lighting wiring
D5030 Communications & Securi		100% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0		
	Closed Circuit Surveillance	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Access Control System	o None	Minor	Moderate Major	Replace		\$0		
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace		\$0		
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace		ŞŪ		
D3030 Other Electrical Systems	NOT O3LD	None	WIIIIOI	Major	Керіасе				
UIPMENT & FURNISHINGS									
E10 Equipment									
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$133,142	S	Old equipment, marginally functional
E1010 Commercial Equipment	Vocational	100% x None	Minor	Moderate Major	Replace	10070	\$0	3	No Issues
E1020 Institutional Equipment	Science	4800 x None	Minor	Moderate Major	Replace		\$0		No Issues
E1020 institutional Equipment	Art	o None	Minor	Moderate Major	Replace		\$0		140 155005
	Stage Performance	1440 x None	Minor	Moderate Major	Replace		\$0		No Issues
	=					100%	\$1,664,280	С	24 restroom stalls and accessories
51020 Vahiaulau Fauiranaat	Restroom Accessories/Stalls NOT USED		Minor	Moderate Major	x Replace	100%	\$1,664,280	3	24 Testi both stalls and accessories
E1030 Vehicular Equipment		None	Minor	Moderate Major	Replace				
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			<u>-</u>	
E20 Furnishings		1000/		Danis Danis	D. January	1000/	6700.054	c	Old but functional
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$798,854	5	
E2020 Movable Furnishings		100% x None	Minor	Moderate	Replace		\$0		No Issues
PECIAL CONSTRUCTION & DEMOLITION - NOT	USED								
II DING CITE WORK									
ILDING SITE WORK	NOTUCED								
G10 Site Preparation	NOT USED								
G20 Site Improvements G2010 Roadways		None	Minor	Madarata	Donlage		ćo		
•		o None	Minor	Moderate Major	Replace		\$0		No legues
G2020 Parking Lots		81100 x None	Minor	Moderate Major	Replace	_	\$0		No Issues
G2030 Pedestrian Paving		10600 x None	Minor	Moderate Major	Replace		\$0		No Issues
G2040 Site Development		1883 x None	Minor	Moderate Major	Replace		\$0		No Issues
G2050 Landscaping		15000 x None	Minor	Moderate	Replace		\$0		No Issues
G30 Site Mechanical Utilities									
G3010 Water Supply	Domestic	100% x None	Minor	Moderate	Replace		\$0 		No Issues
	Fire	o None	Minor	Moderate	Replace		\$0		
G3020 Sanitary Sewer		100% x None	Minor	Moderate Major	Replace		\$0		No Issues
G3030 Storm Sewer		o None	Minor	Moderate Major	Replace		\$0		
G3040 Heating Distribution		o None	Minor	Moderate	Replace		\$0		
		o None	Minor	<b>Moderate</b> Major	Replace		\$0		
G3050 Cooling Distribution									
G3050 Cooling Distribution G3060 Fuel Distribution		o None	Minor	Moderate	Replace		\$0		

School Facilities Assessment Template 6/2016

G40 Site Electrical Utilities							
G4010 Electrical Distribution Service	o None	Minor	derate Major	Replace	\$0		
Generator	o None	Minor Mod	derate Major	Replace	\$0		
G4020 Site Lighting	o None	Minor Mod	derate	Replace	\$0		
G4030 Site Communications & Security	o None	Minor	derate	Replace	\$0		
G4090 Other Site Electrical Utilities NOT USED	None	Minor	derate	Replace			
G90 Other Site Construction NOT USED							
OTHER						_	
		Ur	nit of	Unit		Rank	
<u>Description of System</u>		Me	easure Quantity	Budget	Extended	(I,S,L)	Notes
					\$0		
					γU		
					\$0		
					\$0 \$0		
					Ş0		
					\$0		
					\$0 \$0 \$0		

Physical Condition Budget Sub-Total \$8,278,431
Budgeted Development Costs \$3,145,804
Physical Condition Budget TOTAL \$11,424,234

Replacement Budget \$27,465,766

District Name:	Three Rivers/Josephine County S
Site Name:	Lorna Byrne MS
Building Name:	
Building ID:	

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LEVEL OF ACTION			1			
Level 1 Level 2 Level 3	Type (as applicable)	% of Building or Number	None	Minor	Moderate	Major	Replace	% of System or Finish	Automated Budget Estimate	Necessity Rank (I, S, L)	Notes
A SUBSTRUCTURE	•										
A10 Foundations								·			
A1010 Standard For		10%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
A1020 Special Foun			o None	Minor	Moderate	Major	Replace		\$0		
A1030 Slab on Grad	le	90%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
A20 Basement Construction				<b></b>						Ē	
A2010 Basement Ex			None	Minor	Moderate	Major	Replace				
A2020 Basement W	/alls	5%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
B SHELL											
B10 Superstructure	water Ward			D 41	Na danata		D		Ġ0		
B1010 Floor Constru			o None	Minor	Moderate	Major	Replace		\$0		
	Steel	4.000/	o None	Minor	Moderate	Major	Replace		\$0		10% Concrete, 90% Slab on grade, No Issues
D1020 Daref Caratur	Concrete	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
B1020 Roof Constru		100%	x None	Minor	Moderate	Major	Replace		\$0		No issues
	Steel		o None	Minor	Moderate	Major	Replace		\$0		
D20 Futorion Francouro	Concrete		o None	Minor	Moderate	Major	Replace		\$0		
B20 Exterior Enclosure	In Compared Formed / Tile		None	N 4 i	Na danata F	Nasian	Danlass		ćo		1
B2010 Exterior Wal	·	200/	o None	Minor	Moderate	Major	Replace		\$0		No Issues
	Masonry	30% 45%	x None	Minor	Moderate	Major	Replace		\$0 \$0		No Issues
	Framed w/Panel Siding		x None	Minor	Moderate	Major	Replace		·		No Issues
	Framed w/Stucco	25%	x None	Minor	Moderate	Major	Replace		\$0		No issues
D2020 F. A. die a Wile	Framed w/Masonry Veneer		o None	Minor	Moderate	Major	Replace		\$0		
B2020 Exterior Win		4.000/	o None	Minor	Moderate	Major	Replace		\$0		No Issues
	Aluminum/Steel	100%	x None	Minor	Moderate	Major	Replace		\$0		No issues
	Clad		o None	Minor	Moderate	Major	Replace		\$0		
D2020 5.4	Curtain Wall		o None	Minor	Moderate	Major	Replace		\$0		
B2030 Exterior Doo		10	o None	Minor	Moderate	Major	Replace		\$0		No leaves
	Hollow Metal	49	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Storefront		None	Minor	Moderate	Major	Replace		\$0		
B30 Roofing	Annhalt Chinala	750/	Nana	N 4 i m m m	Madanata F	Nasian	Davida ea	1000/	¢202.200	c	Agod
B3010 Roof Coverin		75%	x None	Minor	Moderate	Major	x Replace	100%	\$392,386	5	Aged Leaks, failure
	Built-Up	25%	x None	Minor	Moderate	Major	x Replace	100%	\$186,850		Leaks, failure
	Single Ply		o None	Minor	Moderate	Major	Replace		\$0		
	Metal		o None	Minor	Moderate	Major	Replace		\$0		
D2020 Doof Coordin	Concrete Tile		o None	Minor	Moderate	Major	Replace		\$0 \$0		
B3020 Roof Openin			o None	Minor	Moderate	Major	Replace		\$0 \$0		
C INTERIORS	Access Hatch		o None	Minor	Moderate	Major	Replace		ŞU		
C10 Interior Construction											
C1010 Partitions	Framed	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
CIOIO I di Cicions	Masonry	100/0	o None	Minor		Major	Replace		\$0		
C1020 Interior Door		106	x None	Minor	Moderate		Replace		\$0		No Issues
C1020 litterior Door	.5 WOOU	100	^ NOTIC	IVIIIIOI	iviouerate	iviajoi	Керіасе		γU		State of Oreg

	Hollow Metal	20 x None	Minor	Moderate Major	Replace	\$0	No Issues
C1030 Fittings	NOT USED					30	140 133003
<del>_</del>	NOT USED	None	Minor	Moderate	Replace		
C20 Stairs					<u> </u>		In .
C2010 Stair Construction	Wood	5 x None	Minor	Moderate Major	Replace	\$0	No Issues
	Metal	2 x None	Minor	Moderate Major	Replace	\$0	No Issues
	Concrete	o None	Minor	Moderate Major	Replace	\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate	Replace	\$0	
	Resilient	100% x None	Minor	Moderate	Replace	\$0	No Issues
C30 Interior Finishes				<del>_</del>			
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate Major	Replace	\$0	
			П				Aged, repaint. Repair wood shop wall corn
	Wallboard	99% x None	Minor	Moderate Major	x Replace	100% \$443,956	S damage 100 sq ft
	Wainscot	o None	Minor	Moderate Major	Replace	\$0	
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace	\$0	No Issues, showers
C3020 Floor Finishes	Carpet / Soft Surface	40% x None	Minor	Moderate Major	x Replace	100% \$174,892	S Aged, wear
C3020 Floor Finishes	Resilient Tile	37% x None	Minor	Moderate Major	x Replace	10% \$15,210	Stage (in Gym area) damage,
	Resilient Sheet	2% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Polished Concrete	10% x None	Minor	Moderate Major		\$0	No Issues
					Replace	\$0	No Issues, showers
	Ceramic Tile		Minor	Moderate Major	Replace		INO ISSUES, SHOWERS
	Liquid Applied	o None	Minor	Moderate Major	Replace	\$0	Natara
	Wood Sports Floor	10% x None	Minor	Moderate	Replace	\$0	No Issues
C3030 Ceiling Finishes	Wallboard	10% x None	Minor	Moderate	Replace	\$0	No Issues
	Lay-In Ceiling Tile	25% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Glued-Up Ceiling Tile	50% x None	Minor	Moderate Major	Replace	\$0	No Issues
	•						
	Painted Structure	15% x None	Minor	Moderate Major	Replace	\$0	No Issues
ICES	•					\$0	No Issues
ICES D10 Conveying	•					\$0	No Issues
	•					\$0	No Issues  No Issues
D10 Conveying	Painted Structure	15% x None	Minor	Moderate Major	Replace		
<u>D10 Conveying</u> D1010 Elevators & Lifts	Painted Structure  Valks	15% x None	Minor	Moderate Major  Moderate Major	Replace	\$0	
<u>D10 Conveying</u> D1010 Elevators & Lifts D1020 Escalators & Moving V	Painted Structure  Valks	15% x None  1 x None 0 None	Minor  Minor  Minor	Moderate Major  Moderate Major  Moderate Major	Replace Replace Replace	\$0 \$0	No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste	Painted Structure  Valks	1 x None  1 x None  None 1 x None None	Minor  Minor  Minor	Moderate Major  Moderate Major  Moderate Major  Moderate Major	Replace Replace Replace Replace	\$0 \$0 \$0	No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures	Painted Structure  Valks	15% x None  1 x None 0 None 1 x None 1 x None	Minor Minor Minor Minor	Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major	Replace Replace Replace Replace Replace	\$0 \$0 \$0 \$0	No Issues Stage chair lift, No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Districts	Painted Structure  Valks	15% x None  1 x None  None 1 x None  1 00% x None  100% x None  None	Minor Minor Minor Minor Minor Minor	Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major	Replace Replace Replace Replace Replace Replace	\$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water District  D2030 Sanitary Waste	Painted Structure  Valks	15% x None  1 x None  None 1 x None  1 00% x None  100% x None  100% x None  None	Minor Minor Minor Minor Minor Minor Minor	Moderate Major	Replace Replace Replace Replace Replace Replace Replace Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage	Painted Structure  Valks ems  bution	15% x None  1 x None 0 None 1 x None 100% x None 100% x None 100% x None 0 None	Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate Major	Replace Replace Replace Replace Replace Replace Replace Replace Replace	\$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste	Painted Structure  Valks ems  bution	15% x None  1 x None  None 1 x None  1 00% x None  100% x None  100% x None  None	Minor Minor Minor Minor Minor Minor Minor	Moderate Major	Replace Replace Replace Replace Replace Replace Replace Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste	Painted Structure  Valks ems  bution	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures  No Issues  No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply	Painted Structure  Valks  bution  ms NOT USED	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures  No Issues  No Issues  No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste	Painted Structure  Valks bution  ms NOT USED  ms Boiler	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues No Issues  No Issues L Aged
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply	Painted Structure  Valks  bution  ms NOT USED  ms Boiler  Air Handler	1	Minor	Moderate Major	Replace  Replace Replace Replace Replace Replace Replace Replace Replace Replace Replace Replace Replace Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Stage chair lift, No Issues  Count = 128 fixtures  No Issues  No Issues  No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply	Painted Structure  Valks  bution  ms NOT USED  ms Boiler     Air Handler     Furnace	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues No Issues  No Issues L Aged
D10 Conveying  D1010 Elevators & Lifts D1020 Escalators & Moving V D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures D2020 Domestic Water Distri D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Syste	Painted Structure  Valks  bution  ms NOT USED  ms Boiler     Air Handler     Furnace     Heat Exchanger	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues No Issues  No Issues L Aged
D10 Conveying  D1010 Elevators & Lifts D1020 Escalators & Moving V D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures D2020 Domestic Water Distri D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Syste	Painted Structure  Valks  bution  ms NOT USED  ms Boiler     Air Handler     Furnace     Heat Exchanger  stem Component of air handler	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues No Issues  No Issues L Aged
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply  D3020 Heat Generating Syste	Painted Structure  Valks  bution  ms NOT USED  ms Boiler     Air Handler     Furnace     Heat Exchanger	1	Minor	Moderate Major	Replace  Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Count = 128 fixtures  No Issues  No Issues  No Issues  L Aged  No Issues
D10 Conveying  D1010 Elevators & Lifts D1020 Escalators & Moving V D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures D2020 Domestic Water Distri D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Syste	Painted Structure  Valks  bution  ms NOT USED  ms Boiler     Air Handler     Furnace     Heat Exchanger  stem Component of air handler	1	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Stage chair lift, No Issues  Count = 128 fixtures No Issues No Issues  No Issues L Aged
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply  D3020 Heat Generating Syste	Painted Structure  Valks  Ins  Boution  MS NOT USED  MS Boiler  Air Handler  Furnace  Heat Exchanger  Stem Component of air handler  Stand alone chiller	1	Minor	Moderate Major	Replace  Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Count = 128 fixtures  No Issues  No Issues  No Issues  L Aged  No Issues
D10 Conveying  D1010 Elevators & Lifts  D1020 Escalators & Moving V  D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures  D2020 Domestic Water Distri  D2030 Sanitary Waste  D2040 Rain Water Drainage  D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply  D3020 Heat Generating Syste	Painted Structure  Valks  Ins NOT USED  Ins Boiler  Air Handler  Furnace  Heat Exchanger  Stem Component of air handler  Stand alone chiller  Ductwork  Hot water return & supply	15% x None  1 x None 0 None 1 x None 100% x None 100% x None 100% x None 0 None 100% x None 100% x None 0 None	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Count = 128 fixtures No Issues No Issues No Issues No Issues L Aged No Issues No Issues
D10 Conveying  D1010 Elevators & Lifts D1020 Escalators & Moving V D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures D2020 Domestic Water Distri D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Syste  D3040 Distribution Systems	Painted Structure  Valks  Ins NOT USED  Ins Boiler  Air Handler  Furnace  Heat Exchanger  Stem Component of air handler  Stand alone chiller  Ductwork  Hot water return & supply	15% x None  1 x None  None  1 x None  1 x None  100% x None  100% x None  None  100% x None  None  100% x None  None  None  100% x None  None  100% x None  None  100% x None  None  100% x None  None	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Count = 128 fixtures No Issues No Issues No Issues No Issues L Aged No Issues No Issues
D10 Conveying  D1010 Elevators & Lifts D1020 Escalators & Moving V D1090 Other Conveying Syste  D20 Plumbing  D2010 Plumbing Fixtures D2020 Domestic Water Distri D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Syste  D30 HVAC  D3010 Energy Supply D3020 Heat Generating Syste  D3040 Distribution Systems	Painted Structure  Valks  Ins  Boiler  Air Handler  Furnace  Heat Exchanger  Stem Component of air handler  Stand alone chiller  Ductwork  Hot water return & supply  Inits  Above ceiling VAV unit	15% x None  1 x None  1 x None  1 x None  1 x None  100% x None  100% x None  100% x None  None  100% x None  None  100% x None  None  100% x None  None  0 None  0 None  100% x None  None  100% x None  None  0 None  100% x None	Minor	Moderate Major	Replace	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	No Issues  Count = 128 fixtures No Issues No Issues No Issues No Issues L Aged No Issues No Issues

D3070 Systems Testing & Baland	cing	100% x None	Minor	Moderate	x Replace	100% \$	74,740 I	
D3090 Other HVAC Systems & E	qι NOT USED	None	Minor	Moderate	Replace			
<u>D40 Fire Protection</u>							. –	
D4010 Sprinklers		100% x None	Minor	Moderate	Replace		\$0	No Issues
D4020 Standpipes		100% x None	Minor	Moderate	Replace		\$0	No Issues
D4030 Fire Protection Specialtie		100% x None	Minor	Moderate	Replace		\$0	No Issues
D4090 Other Fire Protection Sys	te NOT USED	None	Minor	Moderate	Replace			
<u>D50 Electrical</u>							_	
D5010 Electrical Service & Distri		100% x None	Minor	Moderate Major	Replace		\$0	No Issues, Siemens Equipment
D5020 Lighting and Branch Wiri	=	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D5030 Communications & Secu	· · · · · · · · · · · · · · · · · · ·	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0	
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0	
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Replace			
EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	Replace		\$0	No Issues, Kitchen Equipment
E1010 commercial Equipment	Vocational	100% x None	Minor	Moderate Major	Replace		\$0	No Issues, Shop
E1020 Institutional Equipment	Science	2200 x None	Minor	Moderate Major	Replace		\$0	No Issues
E1020 Moditational Equipment	Art	o None	Minor	Moderate Major	Replace		\$0	1.00.000.00
	Stage Performance	2790 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	Replace		\$0	No Issues, Count = 28 stalls
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace		<del>3</del> 0	tvo issues, count – 20 stans
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E20 Furnishings	NOT USED	INOTIC	IVIIIIOI	Widderate	Керіасе		-	
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
SPECIAL CONSTRUCTION & DEMOLITION - NOT	USED	10070 X None	IVIIIIOI	ividuciate	перисе		<b>30</b>	110 100000
BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements							_	
G2010 Roadways		22000 x None	Minor	Moderate Major	Replace		\$0	No Issues
		33400 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2020 Parking Lots								N1 = 1 = - · · = -
G2030 Pedestrian Paving		14400 x None	Minor	Moderate Major	Replace		\$0	No Issues
_			Minor Minor	Moderate Major Moderate Major		90% \$2	\$0 21,589	Cattle fence and wood fence
G2030 Pedestrian Paving G2040 Site Development		14400 x None 3550 x None	Minor	Moderate Major	Replace x Replace		21,589 I	
G2030 Pedestrian Paving		14400 x None			Replace		•	Cattle fence and wood fence
G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping	Domestic	14400 x None 3550 x None	Minor	Moderate Major	Replace x Replace		21,589 I	Cattle fence and wood fence
G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities	Domestic Fire	14400 x None 3550 x None 151100 x None	Minor	Moderate Major  Moderate Major	Replace x Replace x Replace		21,589   I 29,744   I	Cattle fence and wood fence  Football field irrigation system does not work
G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities		14400 x None 3550 x None 151100 x None	Minor Minor Minor	Moderate Major  Moderate Major	Replace x Replace x Replace		21,589   I 29,744   I \$0	Cattle fence and wood fence  Football field irrigation system does not work  No Issues
G2030 Pedestrian Paving G2040 Site Development  G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply		14400 x None 3550 x None 151100 x None  100% x None 100% x None	Minor Minor Minor	Moderate Major  Moderate Major  Moderate Major  Moderate Major	Replace x Replace x Replace Replace Replace Replace		21,589   I 29,744   I \$0 \$0	Cattle fence and wood fence  Football field irrigation system does not work  No Issues No Issues
G2030 Pedestrian Paving G2040 Site Development  G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply  G3020 Sanitary Sewer G3030 Storm Sewer		14400 x None 3550 x None 151100 x None  100% x None 100% x None 100% x None 0 None	Minor Minor Minor Minor Minor	Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major	x Replace x Replace x Replace Replace Replace Replace Replace Replace		21,589   I 29,744   I \$0 \$0 \$0 \$0 \$0	Cattle fence and wood fence  Football field irrigation system does not work  No Issues No Issues
G2030 Pedestrian Paving G2040 Site Development  G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply  G3020 Sanitary Sewer		14400 x None 3550 x None  151100 x None  100% x None 100% x None 100% x None None	Minor Minor Minor Minor Minor Minor	Moderate Major  Moderate Major  Moderate Major  Moderate Major  Moderate Major	x Replace x Replace x Replace Replace Replace Replace		21,589   I 29,744   I \$0 \$0 \$0	Cattle fence and wood fence  Football field irrigation system does not work  No Issues No Issues

G3090 Other Site Mechanical Uti	ili NOT USED		None	Minor	Moderate	Major	Replace					
G40 Site Electrical Utilities												
G4010 Electrical Distribution	Service		o None	Minor	Moderate	Major	Replace		\$0			
	Generator	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues	
G4020 Site Lighting		100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues	
G4030 Site Communications & Se	ecurity		o None	Minor	Moderate	Major	Replace		\$0			
G4090 Other Site Electrical Utiliti	ie NOT USED		None	Minor	Moderate	Major	Replace					
G90 Other Site Construction	NOT USED									_		
OTHER												
					T					_		
					Unit of		Unit			Rank		
Description of System					Unit of Measure	Quantity	Unit Budget		Extended	Rank (I,S,L)	Notes	
	5'x5' concession stand doors					Quantity 3			Extended		Notes No Issues	
Description of System	5'x5' concession stand doors				Measure	Quantity 3			Extended			
Description of System	5'x5' concession stand doors				Measure	Quantity 3			Extended			
Description of System	5'x5' concession stand doors				Measure	Quantity 3		-				
Description of System	5'x5' concession stand doors				Measure	Quantity 3				(I,S,L) \$0 \$0 \$0		
Description of System	5'x5' concession stand doors				Measure	Quantity 3				(I,S,L) \$0 \$0 \$0		

Physical Condition Budget Sub-Total \$2,038,328
Budgeted Development Costs \$774,565
Physical Condition Budget TOTAL \$2,812,893

Replacement Budget \$30,836,090

**District Name:** Three Rivers/Josephine County SD Hidden Valley HS Site Name:

**Building Name:** 0 **Building ID:** 

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

								L	LEVEL (	OF ACTION				]			
Level 1	Level 2	Level 3	Type (as applicable)	% of Building or Number		None		Minor	N	/loderate	Major		Replace	% of System or Finish	Automated Budget Estimate	Necessity Rank (I, S, L)	Notes
A SUB	STRUCTU	RE															
	A10 Fou	<u>ındations</u>															
		A1010 Standard Foundation			-	None		linor		loderate			Replace		\$0		
		A1020 Special Foundation	S		-	None		linor		loderate	Major		Replace		\$0		
		A1030 Slab on Grade		100%	χI	None	N	linor	M	loderate	Major	R	Replace		\$0		No Issues
	A20 Bas	sement Construction						ī					ī				
		A2010 Basement Excavati	c NOT USED			None		linor		loderate	Major		Replace				
		A2020 Basement Walls			0	None		linor	$\square$	loderate	Major	R	Replace		\$0		
B SHEL																	
	<u>B10 Sup</u>	<u>perstructure</u>			—.				Ш.						40		T
		B1010 Floor Construction			-	None		linor		loderate	Major		Replace	-	\$0		
			Steel	1000/	-	None		linor	-	loderate	Major		Replace		\$0		Clab as grade Na Jasuas
		D4020 D	Concrete	100%	-	None		linor		loderate	Major	-	Replace		\$0		Slab on grade, No Issues
		B1020 Roof Construction		100%	-	None		linor		loderate	Major	_	Replace	-	\$0		No Issues
			Steel		_	None		linor		loderate	Major	-	Replace	-	\$0		
	D20 Ev+	erior Enclosure	Concrete		0	None	IV	linor	IV	loderate	Major		Replace		\$0		
	BZU EXTE	B2010 Exterior Walls	Concrete Formed / Tilt			None		linor		loderate	Major	В	Replace		\$0		T 1
		PZOTO EXTELIOL MAIIZ	Concrete Formed / Tilt		0	None	IV	IIIIOI	H'	louerate	IVIAJOI	N	керіасе	-	ŞU		Main Bldg, renew exterior block coating,
			Masonry	90%	x I	None	N	linor	x N	loderate	Major	R	Replace	100%	\$830,886	I	moisture infiltration
			Framed w/Panel Siding	10%	x I	None	N	linor		1oderate	x Maior	R	Replace	30%	\$46,160		Ag Bldg, metal wall panels, deterioration, rust, age, paint. Replace 1,000 sf fiberglass panel at Ag Bldg near roof as well
			Framed w/Stucco		-	None		linor		loderate	Major		Replace		\$0		
			Framed w/Masonry Veneer		_	None		linor	-	loderate	Major	-	Replace		\$0		
		B2020 Exterior Windows	· · · · · · · · · · · · · · · · · · ·		o I	None	N	linor	_	loderate	Major		Replace		\$0		
			Aluminum/Steel	100%	x I	None	N	linor	$\sim$	loderate	Major	x R	Replace	100%	\$2,000,281	S	Original windows, single pane
			Clad		o I	None	N	linor	M	loderate	Major	R	Replace		\$0		
			Curtain Wall		o I	None	N	linor	M	loderate	Major	R	Replace		\$0		
		B2030 Exterior Doors	Wood		o I	None	N	linor	$\square$	loderate	Major	R	Replace		\$0		
			Hollow Metal	57	-	None		linor	_	1oderate			Replace	100%	\$18,246	I	Repairs to all exterior doors main bldg. Replace the main door, Qty 1, at the AG Bldg
	B06 =	¢.	Storefront		o l	None	N	linor	M	loderate	Major	R	Replace		\$0		
	<u>B30 Roo</u>						<u> </u>	1			<del></del>						
		B3010 Roof Coverings	Asphalt Shingle	0==:	_	None	-	linor	_	loderate			Replace	1000	\$0		Maria Dida 25 consolidadi in 1
			Built-Up	95%	-	None		linor		loderate	Major		Replace	100%	\$1,461,744	5	Main Bldg, 25 year old, original roof
			Single Ply	501	-	None		linor		loderate	Major		Replace		\$0		An Dide No issues
			Metal	5%	-	None		linor	_	loderate	Major		Replace		\$0		Ag Bldg, No issues
		D2020 Df C '	Concrete Tile		-	None		linor	-	loderate	Major		Replace		\$0		
		B3020 Roof Openings	Skylights		0	None	IV	linor	$\square$	loderate	Major		Replace		\$0		

									Qty = 3, 4' x 4' roof access hatches, hardware n
	Access Hatch	48 x None	Minor	Moderate Major	x Replace	100%	\$1,024		functional, rusted
NTERIORS							. , -		
C10 Interior Construction									
C1010 Partitions	Framed	95% x None	Minor	Moderate Major	Replace		\$0		No Issues
							·		
	Masonry	5% x None	Minor	Moderate x Major	Replace	100%	\$153,868	ı	West side classrooms, water infiltration, dama
C1020 Interior Doors	Wood	214 x None	Minor	Moderate x Major	Replace	12%	\$24,661	I	Replace 24 interior asbestos filled doors
	Hollow Metal	12 x None	Minor	Moderate Major	x Replace	100%	\$14,084	S	Beyond useful service life
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace				
C20 Stairs		<del></del>			•			_	
C2010 Stair Construction	n Wood	2 x None	Minor	Moderate Major	Replace		\$0		No Issues
	Metal	o None	Minor	Moderate Major	Replace		\$0		
	Concrete	o None	Minor	Moderate Major	Replace		\$0		
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0		
	Resilient	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
C30 Interior Finishes		2007.					7-		
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate	Replace		\$0		
3323	Wallboard	98% x None	x Minor	Moderate Major	Replace	100%	\$226,186	S	Minor damage throughout bldg, paint
	Wainscot	o None	Minor	Moderate Major	Replace	100/0	\$0		
	Ceramic Tile	2% x None	x Minor	Moderate Major	Replace	100%	\$3,077	S	Minor damage in restrooms, repair
C3020 Floor Finishes	Carpet / Soft Surface	50% x None	Minor	Moderate Major	x Replace	100%	\$450,063		Heavy wear, damage, torn, age
C3020 Floor Fillishes	Resilient Tile	16% x None	Minor	Moderate Major	x Replace	100%	\$135,404		Classrooms, stage, cafeteria
	Resilient Sheet	2% x None	Minor	Moderate Major	Replace	100%	\$135,404		Kitchen
	Polished Concrete	20% x None	Minor	Moderate Major	Replace	10076	\$0		No Issues
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace	-	\$0 \$0		No Issues
	Liquid Applied	o None	Minor				\$0 \$0		NO ISSUES
				Moderate Major	Replace		\$0 \$0		No Issues
C2020 Cailing Finish as	Wood Sports Floor		Minor	Moderate Major	Replace		·		No Issues
C3030 Ceiling Finishes	Wallboard	5% x None	Minor	Moderate Major	Replace	4000/	\$0		
	Lay-In Ceiling Tile	95% x None	Minor	Moderate Major	x Replace	100%	\$745,490	5	Original ceiling system, dirty
	Glued-Up Ceiling Tile	o None	Minor	Moderate Major	Replace		\$0		
	Painted Structure	o None	Minor	Moderate Major	Replace		\$0		
ERVICES									
D10 Conveying			<u> </u>		<u> </u>		4.0		
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0		
D1020 Escalators & Mov	•	o None	Minor	Moderate	Replace		\$0		
D1090 Other Conveying	Systems	o None	Minor	Moderate Major	Replace		\$0		
D20 Plumbing									
D2010 Plumbing Fixture		100% x None	Minor	Moderate Major	x Replace	100%	\$1,077,075		Original fixtures, count = 214
D2020 Domestic Water	Distribution	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
D2030 Sanitary Waste		100% x None	Minor	Moderate	Replace		\$0		No Issues
D2040 Rain Water Drain	•	100% x None	Minor	Moderate Major	Replace		\$0		No Issues
D2090 Other Plumbing S	Sys NOT USED	None	Minor	Moderate	Replace				
D30 HVAC				_					
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0		No Issues
D3020 Heat Generating		100% x None	Minor	Moderate Major	x Replace	50%	\$307,736		Replace the original 1976 boiler, 1 Ea
	Air Handler	100% x None	Minor	Moderate Major	x Replace	100%	\$461,603	I	Replace original equipment
	Furnace	0 None	Minor	Moderate Major	Replace		\$0		
	Heat Exchanger	0 None	Minor	Moderate Major	Replace		\$0		
D3030 Cooling Congrati	ng Component of air handler	100% x None	Minor	Moderate Major	x Replace	100%	\$461,603		Window unit A/C

School Facilities Assessment Template

Stand alone chiller	0 None	Minor	Moderate Major	Replace		\$0	
D3040 Distribution System Ductwork	100% x None	Minor	Moderate Major	x Replace	100%	\$307,736	S Replace
Hot water return & supply	100% x None	Minor	Moderate Major	x Replace	100%	\$769,339	Original 2-pipe system, numerous leaks
D3050 Terminal & Package Above ceiling VAV unit	0 None	Minor	Moderate Major	Replace	100%	\$0	1 Stigmar 2 pipe system) hamerous leaks
In-room ventilator unit	0 None	Minor	Moderate Major	Replace		\$0	
In-room radiant unit	0 None	Minor	Moderate Major	Replace		\$0	
D3060 Controls & Instrumentation		Minor	Moderate Major	Replace		\$0	No Issues
D3070 Systems Testing & Balancing		Minor	Moderate Major		100%	\$153,868	140 133463
D3070 Systems Testing & Balancing D3090 Other HVAC System NOT USED		Minor		x Replace Replace	100%	\$133,606	Į i
D40 Fire Protection	None	IVIIIIOI	Moderate Major	Replace			
<u>D40 File Frotection</u>							
D4010 Sprinklers	1% x None	Minor	Moderate Major	Replace		\$0	Stage only, from domestic water line, No Issues
D4020 Standpipes	o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialties	o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protectic NOT USED	None	Minor	Moderate Major	Replace		7.5	
D50 Electrical			.,.				
D5010 Electrical Service & Distribution	100% x None	Minor	Moderate Major	x Replace	100%	\$1,230,942	Federal Pacific equipment, main and panelboards
D5020 Lighting and Branch Wiring	100% x None	Minor	Moderate Major	x Replace	100%	\$1,846,414	I Original fixtures and wiring
D5030 Communications & Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
Clock / Intercom System	100% x None	Minor	Moderate Major	x Replace	100%	\$769,339	I Not functional
Closed Circuit Surveillance	100% x None	Minor	Moderate Major	x Replace	100%	\$169,255	S Dated technology
Access Control System	o None	Minor	Moderate Major	Replace		\$0	
Intrusion Alarm System	100% x None	Minor	Moderate Major	x Replace	100%	\$100,014	Dated technology
Fire Alarm / Detection	100% x None	Minor	Moderate Major	x Replace	100%	\$346,203	Dated technology
Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Sys NOT USED	None	Minor	Moderate	Replace			
E EQUIPMENT & FURNISHINGS							
E10 Equipment	100% v Nana	N dim a m	Nadarata   Najar	Danless	1000/	6207.726	Old equipment, beyond service life
E1010 Commercial Equipm Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$307,736	
Vocational	100% x None	Minor	Moderate Major  Moderate Major	x Replace x Replace	100%	\$253,882	S Old equipment, beyond service life  S Old equipment, beyond service life
E1020 Institutional Equipm Science	9600 x None	Minor			100%	\$35,851	
Art	2000 x None	Minor	Moderate Major	Replace		\$0	No Issues
Stage Performance	1800 x None	Minor	Moderate Major	Replace	1000/	\$0	No Issues S 28 restroom stalls
Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	x Replace	100%	\$3,846,695	S 28 restroom stalls
E1030 Vehicular Equipmer NOT USED	None	Minor	Moderate Major	Replace			
E1090 Other Equipment NOT USED	None	Minor	Moderate	Replace			
E20 Furnishings	100% v Nana	N dim a m	Nadarata   Najar	Danless	200/	¢200,202	S Old equipment, beyond service life
E2010 Fixed Furnishings	100% x None	Minor	Moderate Major	x Replace	20%	\$369,283	No Issues
E2020 Movable Furnishings	100% x None	Minor	Moderate Major	Replace	$\Box$	\$0	INO ISSUES
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED							
G BUILDING SITE WORK							
G10 Site Preparation NOT USED							
G20 Site Improvements							
G2010 Roadways	81600 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2020 Parking Lots	131000 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2030 Pedestrian Paving	8000 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2040 Site Development	4050 x None	Minor	Moderate Major	Replace		\$0	No Issues
							State of Orego

School Facilities Assessment Template

G2050 Landscaping	163000 x None	Minor	Moderate	Major	Replace	\$0		No Issues
G30 Site Mechanical Utilities								
G3010 Water Supply Domestic	100% x None	Minor	Moderate	Major	Replace	\$0		No Issues
Fire	o None	Minor	Moderate	Major	Replace	\$0		
G3020 Sanitary Sewer	100% x None	Minor	Moderate	Major	Replace	\$0		No Issues
G3030 Storm Sewer	o None	Minor	Moderate	Major	Replace	\$0		
G3040 Heating Distribution	o None	Minor	Moderate	Major	Replace	\$0		
G3050 Cooling Distribution	o None	Minor	Moderate	Major	Replace	\$0		
G3060 Fuel Distribution	o None	Minor	Moderate	Major	Replace	\$0		
G3090 Other Site Mechani NOT USED	None	Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities								
G4010 Electrical Distributic Service	o None	Minor	Moderate	Major	Replace	\$0		
Generator	100% x None	Minor	Moderate	Major	x Replace	100% \$96,030	I	Original generator, beyond service life
G4020 Site Lighting	100% x None	Minor	Moderate	Major	Replace	\$0		No Issues
G4030 Site Communications & Security	o None	Minor	Moderate	Major	Replace	\$0		
G4090 Other Site Electrica NOT USED	None	Minor	Moderate	Major	Replace			
G90 Other Site Construction NOT USED			<del></del>					
THER								
			Unit of		Unit		Rank	
<u>Description of System</u>			Measure	Quantity	Budget	Extended	(I,S,L)	Notes
2030 Exterior Door OVH Exterior OVH / Sliding Doors	100% x		ea	3			50 S	AG Building, exterior sliding doors, replace
							50	
							50	
							50	
							50	
	·						50	

Physical Condition Budget Sub-Total \$19,021,776

Budgeted Development Costs \$7,228,275

Physical Condition Budget TOTAL \$26,250,051

Replacement Budget \$67,860,459

District Name:	Three Rivers/Josephine County SD
Site Name:	Illinois Valley HS
Building Name:	
Building ID:	

# REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					EVEL OF ACTION			1			
								% of		Necessity	
		% of Building						System or	<b>Automated Budget</b>	Rank	
Level 1   Level 2   Level 3	Type (as applicable)	or Number	None	Minor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCTURE											
A10 Foundations A1010 Standard Foundard	ations	8% x N	ono	Minor	Moderate	Major	Replace		\$0		No Issues
A1010 Standard Foundati		0 N		Minor	Moderate	Major	Replace	-	\$0 \$0		140 133463
A1020 Special Foundation	Olis	92% x N		Minor	Moderate	Major	Replace		\$0 \$0		No Issues
A20 Basement Construction		92/0 X IV	one	WIIIIOI	ivioderate	iviajoi	Replace		<b>Ψ</b>		140 155005
A2010 Basement Excav	ation NOT USED	N	one	Minor	Moderate	Major	Replace				
A2020 Basement Walls		o N		Minor	Moderate		Replace		\$0		
B SHELL			One	IVIIIIOI	Wioderate	iviajoi	перисе		, , , , , , , , , , , , , , , , , , ,		
B10 Superstructure											
B1010 Floor Construction	on Wood	8% x N	one	Minor	Moderate	Major	Replace		\$0		Portables
	Steel	o N		Minor	Moderate	Major	Replace		\$0		
	Concrete	92% x N	one	Minor	Moderate	Major	Replace		\$0		Slab on grade, No issues
B1020 Roof Construction	on Wood	100% x N	one	Minor	Moderate	Major	Replace		\$0		No Issues
	Steel	o N	one	Minor	Moderate	Major	Replace		\$0		
	Concrete	o N	one	Minor	Moderate	Major	Replace		\$0		
<b>B20 Exterior Enclosure</b>			_								
B2010 Exterior Walls	Concrete Formed / Tilt	o N	one	Minor	Moderate	Major	Replace		\$0		
	Masonry	92% x N	one	Minor	Moderate	Major	Replace		\$0		Main Building
	Framed w/Panel Siding	8% x N	one	Minor	Moderate	Major	x Replace	100%	\$266,561	l	Portables
	Framed w/Stucco	o N	one	Minor	Moderate	Major	Replace		\$0		
	Framed w/Masonry Venee			Minor	Moderate	Major	Replace		\$0		
B2020 Exterior Window		o N	one	Minor	Moderate	Major	Replace		\$0		
	Aluminum/Steel	100% x N		Minor	Moderate	Major	x Replace	100%	\$1,443,874	l	Single pane, beyond service life, leaks
	Clad	o N	one	Minor	Moderate	Major	Replace		\$0		
	Curtain Wall	o N	one	Minor	Moderate	Major	Replace		\$0		
B2030 Exterior Doors	Wood	8 x N		Minor	Moderate	Major	x Replace	100%	\$12,804	I	Portables
	Hollow Metal		one	Minor	x Moderate	Major	Replace	100%	\$18,886	S	Repairs, door and hardware, paint
	Storefront	o N	one	Minor	Moderate	Major	Replace		\$0		
B30 Roofing			ı	<u> </u>		٦	<u> </u>	1000/	452.400		Dantalda
B3010 Roof Coverings	Asphalt Shingle	8% x N		Minor	Moderate	Major	x Replace	100%	\$62,198	  -	Portables
	Built-Up	92% x N		Minor	Moderate	Major	x Replace	100%	\$1,021,819	<u> </u>	Main Bldg, roof is 27 yrs old, leaks
	Single Ply	0 N		Minor	Moderate	Major	Replace	-	\$0		
	Metal	0 N		Minor	Moderate	Major	Replace		\$0		
D2020 Daaf Onanina	Concrete Tile	0 N		Minor	Moderate	Major	Replace		\$0		
B3020 Roof Openings	Skylights	<u>o</u> N	one	Minor	Moderate	Major	Replace		\$0		Qty = 3, 4' x 4' roof access hatches, hardware not
	Access Hatch	48 x N	one	Minor	Moderate	Major	x Replace	100%	\$1,024		functional, rusted
C INTERIORS	Access Hatell	A IV	5.10	IVIIIIOI	Woderate	iviajoi	А періасе	100/0	71,027	<u>.                                    </u>	
C10 Interior Construction											
C1010 Partitions	Framed	100% x N	one	Minor	Moderate	Major	Replace		\$0		No Issues

	Masonry	o None	Minor	Moderate Major	Replace		\$0	
C1020 Interior Doors	Wood	128 x None	Minor	Moderate Major	x Replace	100%	\$177,549	I Age, damage, wear and delamination
020200	Hollow Metal	20 x None	Minor	Moderate Major	x Replace	100%	\$23,474	I Age, damage, wear
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace	20070	Ψ23) 17 T	1
C20 Stairs				ajo				-
C2010 Stair Construction	Wood	o None	Minor	Moderate Major	Replace		\$0	
CEOID Stail Collist deticit	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	2 x None	Minor	Moderate Major	Replace		\$0	No Issues, stage
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	ito issues, stage
C2020 Stail Tillishes	Resilient	100% x None	Minor	Moderate Major	x Replace	100%	\$11	l Worn
C30 Interior Finishes	Resilient	100% X None	············	wager at a	х періасе	100/0	Ψ	,
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate	Replace		\$0	
CSOLO Wall Fillishes	Wallboard	99% x None	Minor	Moderate Major	x Replace	100%	\$659,739	S Paint all wall finishes
	Wainscot	o None	Minor	Moderate Major	Replace	10070	\$0	5
	Ceramic Tile	1% x None	Minor	Moderate Major	Replace		\$0	No Issues
C3020 Floor Finishes	Carpet / Soft Surface	65% x None	Minor	Moderate Major	x Replace	100%	\$422,333	Worn, torn, dirty, original carpet
C3020 Floor Fillishes	Resilient Tile	7% x None	Minor	Moderate Major	x Replace	100%	\$42,761	S VCT beyond service life
	Resilient Sheet	1% x None	Minor	Moderate Major	x Replace	100%	\$6,664	S Kitchen floor covering
	Polished Concrete	15% x None	Minor	Moderate Major	Replace	10070	\$0	No Issues
	Ceramic Tile	2% x None	Minor	Moderate Major	Replace		\$0	No Issues, locker room showers
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	ite issues, iediter reem shewers
	Wood Sports Floor	10% x None	Minor	Moderate Major	Replace		\$0	No Issues, Gym Floor
C3030 Ceiling Finishes	Wallboard	20% x None	Minor	Moderate Major	x Replace	100%	\$188,814	S Paint all ceiling finishes
esoso cening rimanes	Lay-In Ceiling Tile	60% x None	Minor	Moderate Major	x Replace	100%	\$339,866	Original system, old, dirty, stained
	Glued-Up Ceiling Tile	o None	Minor	Moderate Major	Replace	10070	\$0	
	Painted Structure	20% x None	Minor	Moderate Major	x Replace	100%	\$55,534	S Paint ceilings in Gym and shop areas
SERVICES	Tairited Structure	2070 X None	IVIIIIOI	Widjoi	Х перисе	10070	<del>755,55</del> 4	5 Franciscum go in cymrana onep areas
D10 Conveying								
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving Walks		o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Systems		o None	Minor	Moderate Major	Replace		\$0	
D20 Plumbing		<u>                                     </u>					· · · · · · · · · · · · · · · · · · ·	
D2010 Plumbing Fixtures		100% x None	Minor	Moderate	x Replace	100%	\$777,471	Original fixtures, old, stained, qty = 205
D2020 Domestic Water Distribution	n	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D2030 Sanitary Waste		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D2040 Rain Water Drainage		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate Major	Replace		·	
D30 HVAC								
D3010 Energy Supply		100% x None	Minor	Moderate	Replace		\$0	No Issues
D3020 Heat Generating Systems	Boiler	100% x None	Minor	Moderate Major	x Replace	100%	\$444,269	Beyond service life, original boiler
<u> </u>	Air Handler	100% x None	Minor	Moderate Major	x Replace	100%	\$333,202	Beyond service life, original AHU's
	Furnace	o None	Minor	Moderate Major	Replace		\$0	
	Heat Exchanger	o None	Minor	Moderate Major	Replace		\$0	
D3030 Cooling Generating System	<del>-</del>	100% x None	Minor	Moderate Major	x Replace	100%	\$333,202	I Window A/C Units, qty = 9
ζ ,	Stand alone chiller	o None	Minor	Moderate Major	Replace		\$0	
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate Major	x Replace	100%	\$222,134	Original, dirty, beyond service life
·,	Hot water return & supply		Minor	Moderate Major	x Replace	100%	\$555,336	S 2-pipe hot water loop is 43 years old
D3050 Terminal & Package Units	Above ceiling VAV unit	o None	Minor	Moderate Major	Replace		\$0	
<b>9</b> -1-1-1	In-room ventilator unit	o None	Minor	Moderate Major	Replace		\$0	
	In-room radiant unit	o None	Minor	Moderate Major	Replace		\$0	
	iii-iooiii radiant dint	O INONE	IVIIIIOI	Widaciateivialor	INCUIACE		JU	

D3060 Controls & Instrumentation	1	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3070 Systems Testing & Balancir	g	100% x None	Minor	Moderate Major	x Replace	100%	\$111,067	I
D3090 Other HVAC Systems & Equ	ip NOT USED	None	Minor	Moderate Major	Replace			
D40 Fire Protection								
D4010 Sprinklers		2% x None	Minor	Moderate Major	x Replace	100%	\$8,330	Stage area, domestic water line sprinkler
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialties		o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Syste	m: NOT USED	None	Minor	Moderate Major	Replace			
D50 Electrical						-		
D5010 Electrical Service & Distribu	ution	100% x None	Minor	Moderate Major	x Replace	100%	\$888,538	Original ITE Electrical Equipment
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate Major	x Replace	100%	\$1,332,807	Original fixtures and building wiring
D5030 Communications & Securit	y Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	100% x None	Minor	Moderate Major	x Replace	100%	\$555,336	I Does not work
	Closed Circuit Surveillance	e 100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Access Control System	0 None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	x Replace	100%	\$72,194	S Replace
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	Replace		\$0	New 2016
	<b>Lighting Control System</b>	0 None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace			
				<del>_</del> _		_		
EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$222,134	I Old equipment
	Vocational	100% x None	Minor	Moderate Major	x Replace	100%	\$183,261	Old equipment
E1020 Institutional Equipment	Science	3060 x None	Minor	Moderate Major	x Replace	100%	\$11,428	Old, original science tables and equipment
	Art	1020 x None	Minor	Moderate Major	x Replace	100%	\$3,265	Old, original art tables and equipment
	Stage Performance	1800 x None	Minor	Moderate Major	Replace		\$0	No Issues
	Restroom Accessories/Sta	III 100% x None	Minor	Moderate Major	x Replace	100%	\$2,776,681	Damaged, missing, beyond service life
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E20 Furnishings					<u>—</u>			
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$1,332,807	Original cabinetry, damaged, worn
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
SPECIAL CONSTRUCTION & DEMOLITION - NOT L	ISED							
BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements			·		<b></b>			
G2010 Roadways		40400 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2020 Parking Lots		87000 x None	x Minor	Moderate Major	Replace	100%	\$278,487	S Resurface and stripe
G2030 Pedestrian Paving		10000 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2040 Site Development		6600 x None	Minor	Moderate Major	Replace		\$0	No Issues
620501 1 :		372000 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2050 Landscaping		372000 x None						
G2050 Landscaping G30 Site Mechanical Utilities								
	Domestic	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
G30 Site Mechanical Utilities	Domestic Fire		Minor Minor	Moderate Major Moderate Major	Replace Replace		\$0 \$0	
G30 Site Mechanical Utilities		100% x None						No Issues No Issues
G30 Site Mechanical Utilities G3010 Water Supply		100% x None o None	Minor	Moderate Major	Replace		\$0	
G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer		100% x None	Minor Minor	Moderate Major Moderate Major	Replace Replace		\$0 \$0	

G3060 Fuel Distribution			o None	Minor		Moderate	ı	Major	Replace		\$0		
G3090 Other Site Mechanical Ut	tilitie NOT USED		None	Minor		Moderate	ſ	Major	Replace				
G40 Site Electrical Utilities													
G4010 Electrical Distribution	Service		o None	Minor		Moderate	ı	Major	Replace		\$0		
	Generator	100%	x None	Minor		Moderate	ı	Major	x Replace	100%	\$96,030	I	Original 1975, undersized, beyond service life
G4020 Site Lighting			o None	Minor		Moderate	ſ	Major	Replace		\$0		
G4030 Site Communications & S	Security		o None	Minor		Moderate		Major	Replace		\$0		
G4090 Other Site Electrical Utilit	ties NOT USED		None	Minor		Moderate	ſ	Major	Replace				
<b>G90 Other Site Construction</b>	NOT USED												_
OTHER													
						Unit of			Unit			Rank	
<u>Description of System</u>						Measure		Quantity	Budget		Extended	(I,S,L)	Notes
											\$0		
					] /						\$0		
					] /						\$0		
					1 /						\$0		
					1 /						\$0		
					] /						\$0		
					] /						\$0		

Physical Condition Budget Sub-Total \$15,281,888

Budgeted Development Costs \$5,807,117

Physical Condition Budget TOTAL \$21,089,006

Replacement Budget \$48,984,084

District Name:	Three Rivers/Josephine County
Site Name:	North Valley HS
Building Name:	0
Ruilding ID:	0

## REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

		ſ			LEVEL OF ACTION	J .		1			
								% of		Necessity	
		% of Building						System or	<b>Automated Budget</b>	Rank	
Level 1 Level 2 Level 3	Type (as applicable)	or Number	None	Minor	Moderate	Major	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCTURE											
A10 Foundations			<b>—</b>						40		1
A1010 Standard Foundations	5		o None	Minor	Moderate		Replace		\$0		
A1020 Special Foundations			o None	Minor	Moderate		Replace		\$0		No Issues
A1030 Slab on Grade		100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
A20 Basement Construction	NOTLICED		Nana	N diam a m	N 4 a al a wasta	D.4:	Danlage				
A2010 Basement Excavation	NOT USED		None	Minor	Moderate	_	Replace		ćo		
A2020 Basement Walls			o None	Minor	Moderate	iviajor	Replace		\$0		
B SHELL B10 Superstructure											
B1010 Floor Construction	Wood		o None	Minor	Moderate	Major	Replace		\$0		1
B1010 Fl001 Collsti action	Steel		o None	Minor	Moderate		Replace		\$0 \$0		
	Concrete	100%	x None	Minor	Moderate	Major	Replace		\$0 \$0		Slab on grade, No Issues
B1020 Roof Construction	Wood	100%	x None	Minor	Moderate		Replace		\$0 \$0		No Issues
B1020 ROOF CONSTRUCTION	Steel	100%	o None	Minor	Moderate		Replace		\$0 \$0		110 133463
	Concrete		o None	Minor	Moderate		Replace		\$0 \$0		
B20 Exterior Enclosure	Concrete		0 None	WIIIIOI	Moderate	iviajoi	Керіасе		, JO		
B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor	Moderate	Major	Replace		\$0		
BEOTO Externor Walls	concrete rormed, riic		- Home		- Wiodelate	.viajo:	періасс		Ψ.		
											South facing exterior walls of Gym and
											classrooms have water infiltration and damage to
	Masonry	95%	x None	Minor	Moderate	x Major	Replace	15%	\$207,911	I	the CMU, repair and seal the exterior walls
	Framed w/Panel Siding	5%	x None	Minor	x Moderate	Major	Replace	100%	\$43,771	ļ	Metal paneling over windows, repaint
	Framed w/Stucco		o None	Minor	Moderate	Major	Replace		\$0		
	Framed w/Masonry Veneer		o None	Minor	Moderate	Major	Replace		\$0		
B2020 Exterior Windows	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	Aluminum/Steel	100%	x None	Minor	Moderate	Major	x Replace	100%	\$1,896,734	I	Single pane original windows
	Clad		o None	Minor	Moderate	Major	Replace		\$0		
	Curtain Wall		o None	Minor	Moderate	Major	Replace		\$0		
B2030 Exterior Doors	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	Hollow Metal	198	x None	Minor	Moderate	Major	x Replace	100%	\$274,646	l	Doors and hardware are beyond service life
	Storefront		o None	Minor	Moderate	Major	Replace		\$0		
B30 Roofing											
B3010 Roof Coverings	Asphalt Shingle		o None	Minor	Moderate		Replace		\$0		
	Built-Up	100%	x None	Minor	Moderate		x Replace	100%	\$1,459,026	l	Numerous leaks, 26 years old
	Single Ply		o None	Minor	Moderate		Replace		\$0		
	Metal		o None	Minor	Moderate	=	Replace		\$0		
	Concrete Tile		o None	Minor	Moderate	Major	Replace		\$0		
B3020 Roof Openings	Skylights		o None	Minor	Moderate	Major	Replace		\$0		
											QTY = 3 roof hatches, 4' x 4', hardware broken,
C INTERIORS	Access Hatch	48	x None	Minor	Moderate	Major	x Replace	100%	\$1,024	<u> </u>	rusty, not functional

**C** INTERIORS

\$0 No Issues \$0 \$205,984 I Asbestos filled core material \$0 No Issues \$0 No Issues	\$0 \$205,984 I	75%	Replace Replace	Moderate Major Moderate Major	Minor Minor	100% x None o None	Masonry	
\$205,984 I Asbestos filled core material \$0 No Issues	\$205,984	750/	перисс				IVIASOTITY	
\$0 No Issues		/5%	x Replace	Moderate Major	Minor	198 x None	Wood	C1020 Interior Doors
		7370	Replace	Moderate Major	Minor	15 x None	Hollow Metal	CIOZO IIICIIOI BOOIS
\$0 No Issues	γo		Replace	Moderate Major	Minor	None	NOT USED	C1030 Fittings
\$0 No Issues			Керіасе	Wajor	WIIIIOI	None	NOT OSED	C20 Stairs
	\$0		Replace	Moderate Major	Minor	4 x None	Wood	C2010 Stair Construction
\$0			Replace	Moderate Major	Minor	o None	Metal	CECTO Stail Collistiaction
\$0	·		Replace	Moderate Major	Minor	o None	Concrete	
\$0			Replace	Moderate Major	Minor	o None	Concrete Fill	C2020 Stair Finishes
\$0 No Issues			Replace	Moderate Major	Minor	100% x None	Resilient	CZOZO Stall Tillishes
110 133463	ŞÜ		Керіасе	Wajor	WIIIIOI	100% X None	Resilient	C30 Interior Finishes
Repaint all interior walls, repair interior so								eso menor rimanes
CMU walls where water infiltration has ca								
\$109,427 I damage	\$109 427	100%	Replace	Moderate Major	x Minor	50% x None	Paint on Masonry	C3010 Wall Finishes
\$214,477   Repaint all interior walls		100%	Replace	x Moderate Major	Minor	49% x None	Wallboard	CSG10 Wall Fillishes
\$0		10070	Replace	Moderate Major	Minor	o None	Wainscot	
\$0 No Issues, Shower walls			Replace	Moderate Major	Minor	1% x None	Ceramic Tile	
\$571,865   Original carpet, worn, dirty	· · · · · · · · · · · · · · · · · · ·	100%	x Replace	Moderate Major	Minor	67% x None	Carpet / Soft Surface	C3020 Floor Finishes
\$80,246 I Age, worn, beyond service life		100%	x Replace	Moderate Major	Minor	10% x None	Resilient Tile	C3020 Floor Fillishes
\$0		100%	Replace	Moderate Major	Minor	o None	Resilient Sheet	
\$0 No Issues			Replace	Moderate Major	Minor	10% x None	Polished Concrete	
\$0 No Issues			Replace	Moderate Major	Minor	1% X None	Ceramic Tile	
\$0			Replace	Moderate Major	Minor	o None	Liquid Applied	
·		100%	Replace	Moderate Major	Minor x Minor		Wood Sports Floor Wallboard	C2020 Cailing Finish as
			Replace	Moderate Major				C3030 Ceiling Finishes
		100%	x Replace	Moderate Major	Minor	65% x None	Lay-In Ceiling Tile	
\$0			Replace	Moderate Major	Minor	o None	Glued-Up Ceiling Tile	
\$0 No Issues	\$0		Replace	Moderate Major	Minor	25% x None	Painted Structure	40FC
								VICES D10 Conveying
¢0	ćo		Poplace	Moderate Major	Minor	o None		D1010 Elevators & Lifts
\$0 \$0						o None	Malks	D1010 Elevators & Lifts D1020 Escalators & Moving \( \)
			Replace		Minor			D1020 Escalators & Moving V
\$0	\$U		Replace	Moderate	Minor	o None	ems	, , ,
\$1,021,319   Count = 204 fixtures, old, stained, damage	¢1 021 210	100%	x Replace	Moderate Major	Minor	100% x None		D20 Plumbing D2010 Plumbing Fixtures
\$437,708   Rusty water, multiple breaks		100%	x Replace	Moderate Major	Minor	100% X None	ibution	D2010 Fluitibilig Fixtures  D2020 Domestic Water Distr
\$437,708 I Multiple breaks, leaks		100%	x Replace	Moderate Major	Minor	100% X None	ibution	D2030 Sanitary Waste
\$0 No Issues		100%		Moderate Major	Minor	100% X None		D2040 Rain Water Drainage
30 INO 133UE3	ŞU		Replace				mc NOT LISED	D2090 Other Plumbing Syste
<u> </u>			Replace	Moderate	Minor	None	IIIS NOT USED	= :
\$0 No Issues	ćo		Donlage	Madarata	Ndinor	100% v None		D30 HVAC
		100%	Replace	Moderate Major	Minor	100% x None	oms Bailar	D3010 Energy Supply
. ,		100%	x Replace	Moderate Major	Minor	100% x None		D3020 Heat Generating Systo
, ,		100%	x Replace	Moderate Major	Minor	100% x None	Air Handler	
\$0			Replace	Moderate Major	Minor	o None	Furnace	
\$0			Replace	Moderate Major	Minor	o None	Heat Exchanger	2000 0 11 2
\$0			Replace	Moderate Major	Minor	o None	ste Component of air handler	D3U3U Cooling Generating Sy
\$0			Replace	Moderate Major	Minor	o None	Stand alone chiller	
\$291,805   Original, old, dirty		100%	x Replace	Moderate Major	Minor	100% x None	Ductwork	D3040 Distribution Systems

	Hot water return & supply	100% x None	Minor	Moderate	x Replace	100%	\$729,513	Aged, asbestos insulation
D3050 Terminal & Package Uni		o None	Minor	Moderate Major	Replace	20070	\$0	
	In-room ventilator unit	o None	Minor	Moderate Major	Replace		\$0	
	In-room radiant unit	o None	Minor	Moderate Major	Replace		\$0	
D3060 Controls & Instrumental	tion	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3070 Systems Testing & Balar		100% x None	Minor	Moderate Major	x Replace	100%	\$145,903	
D3090 Other HVAC Systems &	=	None	Minor	Moderate Major	Replace		. ,	
D40 Fire Protection					•			
D4010 Sprinklers		5% x None	Minor	Moderate	x Replace	100%	\$27,357	Stage area, domestic water line
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialti	es	o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Sy	s NOT USED	None	Minor	Moderate Major	Replace			
D50 Electrical								
D5010 Electrical Service & Distr	ribution	100% x None	Minor	Moderate Major	x Replace	100%	\$1,167,221	S ITE equipment, 43 years old
D5020 Lighting and Branch Wir	ing	100% x None	Minor	Moderate Major	x Replace	100%	\$1,750,832	Old fixtures and original wiring
D5030 Communications & Secu	ır Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	100% x None	Minor	Moderate Major	x Replace	100%	\$729,513	Not operable
	Closed Circuit Surveillance	100% x None	Minor	Moderate Major	x Replace	100%	\$160,493	Old equipment, outdated technology
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	x Replace	100%	\$328,281	Problematic, high maintenance, life safety
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace			
E EQUIPMENT & FURNISHINGS  E10 Equipment								
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100%	\$291,805	Original, old equipment
	Manational	1000/	0.4:	NA - damaka u NA - iau	D la	500/	Ć47.440	Many pieces of equipment have failed and are no longer used
F1020 Institutional Fautisment	Vocational	100% x None 4500 x None	Minor	Moderate x Major	Replace	50%	\$47,418 \$16,805	Original old Science room equipment
E1020 Institutional Equipment	Science Art	1600 x None	Minor Minor	Moderate Major  Moderate Major	x Replace Replace	100%	\$10,803	No issues
	Stage Performance	2400 x None	Minor	Moderate Major	Replace	$\vdash$	\$0 \$0	No issues
	Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	x Replace	100%	\$3,647,566	I Old and damaged, 15 RR Stalls
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace	10070	\$3,047,300	i old and damaged, 15 intotalis
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E20 Furnishings		None	·······o·	Major	періасс			
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$1,750,832	Original cabinets throughout the school
E2020 Movable Furnishings		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
F SPECIAL CONSTRUCTION & DEMOLITION - NO	T USED				<u> </u>		·	
G BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements								
G2010 Roadways		100000 x None	Minor	Moderate x Major	Replace	100%	\$1,173,700	Repair cracks, seal, recoat, stripe
G2020 Parking Lots		125000 x None	Minor	Moderate x Major	Replace	100%	\$1,200,375	Repair cracks, seal, recoat, stripe
G2030 Pedestrian Paving		10000 x None	Minor	Moderate Major	Replace		\$0	No Issues
G2040 Site Development		9050 x None	Minor	Moderate Major	x Replace	100%	\$627,663	Most of the fence is cattle type
C20F0 Law 2		400000				l l	4504.074	Old football field and the irrigation around the
G2050 Landscaping								
G30 Site Mechanical Utilities		409000 x None	Minor	Moderate Major	x Replace	50%	\$621,874	school building do not work

G3010 Water Supply	Domestic	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Fire		o None	Minor	Moderate	Major	Replace		\$0		
G3020 Sanitary Sewer		100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
G3030 Storm Sewer			o None	Minor	Moderate	Major	Replace		\$0		
G3040 Heating Distribution			o None	Minor	Moderate	Major	Replace		\$0		
G3050 Cooling Distribution			o None	Minor	Moderate	Major	Replace		\$0		
G3060 Fuel Distribution			o None	Minor	Moderate	Major	Replace		\$0		
G3090 Other Site Mechanic	al Ut NOT USED		None	Minor	Moderate	Major	Replace				
G40 Site Electrical Utilities											
G4010 Electrical Distribution	n Service		o None	Minor	Moderate	Major	Replace		\$0		
	Generator	100%	x None	Minor	Moderate	Major	x Replace	100%	\$96,030	I	Equipment is beyond service life
G4020 Site Lighting			o None	Minor	Moderate	Major	Replace		\$0		
G4030 Site Communication	s & Security		o None	Minor	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical	Utilit NOT USED		None	Minor	Moderate	Major	Replace				
G90 Other Site Construction	NOT USED										
OTHER					-			1			
					Unit of		Unit			Rank	
<u>Description of System</u>					Measure	Quantity	Budget		Extended	(I,S,L)	Notes
B2030 Ext Doors OVH					ea	4			\$0	I	Replace, original doors
C1020 Interior doors, OVH					ea	2			\$0		No Issues
									\$0		
									\$0		
									\$0		

Physical Condition Budget Sub-Total \$23,293,706

Budgeted Development Costs \$8,851,608

Physical Condition Budget TOTAL \$32,145,314

Replacement Budget \$64,347,580

District Name:	Three Rivers/Josephine County SD
Site Name:	Merlin Alternative Scjhool
Building Name:	0
Building ID:	0

# REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

							LEVEL OF ACTION						
Level 1	Level 2	Level 3	Type (as applicable)	% of Building or Number	None	Minor	Moderate	Major	Replace	% of System or Finish	Automated Budget Estimate	Necessity Rank (I, S, L)	Notes
A SUBST													
<u> </u>	<u> 410 Fou</u>	<u>undations</u>				_		_	_				_
		A1010 Standard Foundations			o None	Minor	Moderate		Replace		\$0		
		A1020 Special Foundations			o None	Minor	Moderate		Replace		\$0		
		A1030 Slab on Grade		100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
<u> </u>	A20 Bas	sement Construction				<b></b>						-	
		A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace		<b>.</b>		
		A2020 Basement Walls			o None	Minor	Moderate	Major	Replace		\$0		
B SHELL													
<u> </u>	810 Sup	perstructure	Wood		Nana	Minor	Nandauata	N 4 = 1 = 11	Danie e		ĊO		
		B1010 Floor Construction	Wood		o None	Minor	Moderate	Major	Replace		\$0		
			Steel	1000/	o None	Minor	Moderate	Major	Replace		\$0		Slab on grade, No Issues
		B1020 Roof Construction	Concrete	100% 100%	x None x None	Minor Minor	Moderate	Major	Replace		\$0 \$0		No Issues
		B1020 ROOI CONSTRUCTION	Wood Steel	100%			Moderate		Replace		\$0 \$0		140 1550/25
					o None	Minor	Moderate	Major	Replace		\$0 \$0		
	D20 Ev+	orior Englosuro	Concrete		o None	Minor	Moderate	Major	Replace		\$U		
	BZU EXTE	erior Enclosure B2010 Exterior Walls	Concrete Formed / Tilt		Nana	Minor	Madarata	Major	Danlaga		ćo		T
		B2010 Exterior Walls	Concrete Formed / Tilt	30%	o None x None	Minor	Moderate		Replace		\$0 \$0		No Issues
			Masonry Framed w/Panel Siding	70%		Minor	Moderate Moderate		Replace	100%			
			•	70%	x None				Replace	100%	\$109,914		Repairs and paint
			Framed w/Stucco		o None	Minor	Moderate		Replace		\$0 \$0		
		D2020 Futorios Windows	Framed w/Masonry Veneer	1000/	o None	Minor	Moderate	Major	Replace	1000/	\$0		Age, moisture damage, rot, single pane
		B2020 Exterior Windows	Wood	100%	x None	Minor	Moderate	Major	x Replace	100%	\$314,039	-	Age, moisture damage, for, single pane
			Aluminum/Steel		o None	Minor	Moderate	Major	Replace		\$0		
			Clad		o None	Minor	Moderate		Replace		\$0		
		B2030 Exterior Doors	Curtain Wall Wood	1.4	o None	Minor	Moderate	Major	Replace	100%	\$0 \$22,407	<u> </u>	Replace all original doors
		B2030 Exterior Doors	Hollow Metal	14	x None	Minor Minor	Moderate Moderate	Major Major	x Replace x Replace	100%		-	Replace, damage, rust
			Storefront	3	x None	Minor	Moderate			100%	\$4,161 \$0	1	nepiace, damage, rust
	B30 Roo	ofing	Storenont		o None	IVIIIIOI	Moderate	iviajui	Replace		<u>۵</u> 0		<u> </u>
<u>-</u>	550 KUU	B3010 Roof Coverings	Asphalt Shingle	30%	x None	Minor	Moderate	Major	Replace		\$0		No Issues, new 2018
		B3010 K001 Coverings	Built-Up	70%	x None	Minor	Moderate	Major	x Replace	100%	\$109,914	1	Replace, 35 year old roof, leaks
			Single Ply	70%	o None	Minor	Moderate		Replace	100%	\$109,914	-	Replace, 33 year old 1001, leaks
			Metal		o None	Minor	Moderate	Major	Replace		\$0 \$0		+
			Concrete Tile		o None	Minor	Moderate	Major			\$0 \$0		+
		B3020 Roof Openings	Skylights		o None	Minor	Moderate	Major	Replace Replace		\$0 \$0		+
		B3020 NOOL Openings	Access Hatch		o None	Minor	Moderate	Major	Replace		\$0 \$0		+
C INTERI	IORS		ACCESS FIGURE		o Mone	IVIIIIOI	iviouerate	iviajui	Neplace		Ų		
		erior Construction											
7	CTO IIIC	C1010 Partitions	Framed	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
		2220 1 01 11 11 11 11	Masonry	100/0	o None	Minor	Moderate	=	Replace		\$0 \$0		
		C1020 Interior Doors	Wood	18	x None	Minor	Moderate		x Replace	100%	\$24,968	1	Original doors and hardware, 1953
		C1020 IIICHOL D0013	******	10	A NOTIC	IVIIIIOI	iviouerate	iviajoi	7 Neplace	100/0	724,300	<u>'</u>	Original doors and nardware, 1999

State of Oregon

	Hollow Metal	o None	Minor	Moderate Major	Replace		\$0	
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace		7.5	<u>'</u>
C20 Stairs				•	•			
C2010 Stair Construction	Wood	o None	Minor	Moderate Major	Replace		\$0	
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	
	Resilient	o None	Minor	Moderate Major	Replace		\$0	
C30 Interior Finishes					<u> </u>			
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate Major	Replace		\$0	
	Wallboard	100% x None	Minor	x Moderate Major	Replace	100%	\$47,106	S Minor repairs, repaint all interior walls
	Wainscot	o None	Minor	Moderate Major	Replace		\$0	
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	7% x None	Minor	Moderate Major	x Replace	100%	\$6,430	I Old, worn
	Resilient Tile	73% x None	Minor	Moderate Major	x Replace	100%	\$63,043	I VAT and VCT, old tie system
	Resilient Sheet	o None	Minor	Moderate Major	Replace		\$0	
	Polished Concrete	20% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0	
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	o None	Minor	Moderate Major	Replace		\$0	
	Lay-In Ceiling Tile	o None	Minor	Moderate Major	Replace		\$0	
	Glued-Up Ceiling Tile	100% x None	Minor	Moderate Major	X Replace	100%	\$70,659	Original tiles, stained, falling, failing
	Painted Structure	o None	Minor	Moderate Major	Replace		\$0	
SERVICES								
D10 Conveying								
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving V	Valks	o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Syste	ems	o None	Minor	Moderate Major	Replace		\$0	
D20 Plumbing				<u></u>				
						1 1		Qty = 21, replace all except urinals in Men's
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Major	x Replace	90%	\$98,922	I Restroom
D2020 Domestic Water Distri	bution	100% x None	Minor	Moderate	x Replace	100%	\$47,106	Original water pipe system
D2030 Sanitary Waste		100% x None	Minor	Moderate	x Replace	100%	\$47,106	Original SS Pipe system
D2040 Rain Water Drainage		o None	Minor	Moderate	Replace		\$0	
D2090 Other Plumbing Syster	ns NOT USED	None	Minor	Moderate	Replace			
D30 HVAC								<b>1.</b>
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3020 Heat Generating Syste		30% x None	Minor	Moderate Major	x Replace	100%	\$18,842	Original boiler, beyond service life
	Air Handler	o None	Minor	Moderate Major	Replace		\$0	
	Furnace	o None	Minor	Moderate Major	Replace	$\vdash$	\$0 ·	
	Heat Exchanger	70% x None	Minor	Moderate Major	Replace	$\vdash$	\$0	No Issues, new in 2014 and 2018
D3030 Cooling Generating Sy	stem: Component of air handler	o None	Minor	Moderate Major	Replace	$\vdash$	\$0	
	Stand alone chiller	o None	Minor	Moderate Major	Replace	$\vdash$	\$0	N 2002
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate Major	Replace	<b>——</b>	\$0	New 2002
	Hot water return & supply	100% x None	Minor	Moderate	x Replace	100%	\$78,510	2-pipe heat distribution system
D3050 Terminal & Package U	=	o None	Minor	Moderate	Replace	$\vdash$	\$0	
	In-room ventilator unit	o None	Minor	Moderate	Replace	$\vdash$	\$0	
	In-room radiant unit	o None	Minor	Moderate Major	Replace	$\vdash$	\$0	No leaves
D3060 Controls & Instrument	ation	100% x None	Minor	Moderate Major	Replace		\$0	No Issues

D3070 Systems Testing & Balanc	ing	100% x None	Minor	Moderate Major	x Replace	100%	\$15,702	
D3090 Other HVAC Systems & Ec	_	None	Minor	Moderate Major	Replace		, -, -	
D40 Fire Protection	•				•			
D4010 Sprinklers		o None	Minor	Moderate	Replace		\$0	
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialtie	S	o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Sys		None	Minor	Moderate Major	Replace		, -	
D50 Electrical				····ajo·				
D5010 Electrical Service & Distril	bution	100% x None	Minor	Moderate Major	Replace		\$0	No Issues, updated 2002
D5020 Lighting and Branch Wirir	ng	100% x None	Minor	Moderate Major	x Replace	100%	\$188,424	Old wiring and fixtures
D5030 Communications & Secur	_	o None	Minor	Moderate Major	Replace		\$0	<del>                                     </del>
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0	
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace		\$0	
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	<del>                                     </del>
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	Replace		\$0	No Issues, updated 2002
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	110 135405), apatica 2502
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace		γo	
D3030 Other Electrical Systems	NOT USED	INOTIC	WIIIIOI	Moderate	Керіасе			
EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	o None	Minor	Moderate Major	Replace		\$0	
LIGIO COmmercial Equipment	Vocational	o None	Minor	Moderate Major	Replace		\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0	<del>                                     </del>
L1020 Mistitutional Equipment	Art	o None	Minor	Moderate Major	Replace	H 1	\$0	
	Stage Performance	o None	Minor	Moderate Major	Replace	H	\$0	-
	Restroom Accessories/Stalls		Minor	Moderate Major		100%	\$392,549	Old, wooden stalls, qty = 6
F1020 Vahiaular Fruinmant	NOT USED				x Replace	100%	Ş39Z,349	olu, wooden stalls, qty = 0
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Replace			
E20 Furnishings		1000/ Nana	Nainan	Daniero Danier	Danlaga	1000/	Ć100 434	Old cabinets. Building original, damage
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$188,424	
E2020 Movable Furnishings	LICED	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
SPECIAL CONSTRUCTION & DEMOLITION - NOT	USED							
PLUI DING CITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements	NOT USED							
G2010 Roadways		11590 x None	Minor	Moderate Major	x Replace	100%	\$117,482	Asphalt and base failure
G2010 Roadways  G2020 Parking Lots		12875 x None	Minor	Moderate Major	x Replace	100%	\$89,295	Asphalt and base failure  Asphalt and base failure
_						100%		No Issues
G2030 Pedestrian Paving		1750 x None	Minor	Moderate Major Moderate Major	Replace	50%	\$0	West rear fence is cattle type
G2040 Site Development		920 x None	Minor		x Replace		\$31,903	Non working system
G2050 Landscaping		3500 x None	Minor	Moderate	x Replace	100%	\$10,643	I INOIT WOLKING SYSTEM
G30 Site Mechanical Utilities	Damastia	1000/	·	NA odla vala		40007	645.700	Old original site vising
G3010 Water Supply	Domestic	100% x None	Minor	Moderate Major	x Replace	100%	\$15,702	I Old, original site piping
	Fire	o None	Minor	Moderate Major	Replace	100=1	\$0	Old salistical attacks of a tata
000000 11 0		100% x None	Minor	Moderate Major	x Replace	100%	\$15,702	I Old, original site SS piping
G3020 Sanitary Sewer							CO	
G3030 Storm Sewer		o None	Minor	Moderate Major	Replace	<b>——</b>	\$0	
G3030 Storm Sewer G3040 Heating Distribution		o None o None	Minor	Moderate Major	Replace		\$0	
G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution		o None o None o None	Minor Minor	Moderate Major Moderate Major	Replace Replace		\$0 \$0	
G3030 Storm Sewer G3040 Heating Distribution		o None o None	Minor	Moderate Major	Replace		\$0	

School Facilities Assessment Template 6/2016

G40 Site Electrical Utilities									
G4010 Electrical Distribution Service	0 1	None Minor	Moderate	Major	Replace		\$0		
Generator	0	None Minor	Moderate	Major	Replace		\$0		
G4020 Site Lighting	100% x	None Minor	Moderate	Major	x Replace	100%	\$47,106	I	Replace 1 old pole light in the lot
G4030 Site Communications & Security	0	None Minor	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical Utilitie: NOT USED	1	None Minor	Moderate	Major	Replace				
G90 Other Site Construction NOT USED			_	_					
OTHER									
			Unit of		Unit			Rank	
<u>Description of System</u>			Measure	Quantity	Budget		Extended	(I,S,L)	Notes
							\$0		
							\$0		
							\$0		
							\$0		
							\$0		
							\$0		
							\$0		

Physical Condition Budget Sub-Total \$2,176,059

Budgeted Development Costs
Physical Condition Budget TOTAL \$3,002,962

Replacement Budget \$6,701,666

District Name: Three Rivers/Josephine County SD
Site Name: District Office

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

Building Name: Main Building
Building ID: 0

					LEVEL OF ACT	ION		1			
					TEVEL OF ACT	T		% of		Necessity	
	_ ,,	% of Building						System or	Automated Budget	Rank	
Level 1   Level 2   Level 3	Type (as applicable)	or Number	None	Minor	Moderate	e Majo	Replace	Finish	Estimate	(I, S, L)	Notes
A SUBSTRUCTURE											
A10 Foundations A1010 Standard Foundations			o None	Minor	Moderate	Major	Replace		\$0		1
A1010 Standard Foundations A1020 Special Foundations			o None	Minor	Moderate		Replace		\$0		
A1030 Slab on Grade		100%	x None	Minor	Moderate		Replace		\$0		No Issues
A20 Basement Construction		100%	X None	IVIIIIOI	Moderate	iviajoi	Replace		ŞU		140 133403
A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace			-	
A2010 Basement Excavation A2020 Basement Walls	NOT OSED		o None	Minor		Major	Replace		\$0		
B SHELL			o None	IVIIIIOI	Wioderate	Iviajoi	перисс		ΨŪ		
B10 Superstructure											
B1010 Floor Construction	Wood		o None	Minor	Moderate	Major	Replace		\$0		
	Steel		o None	Minor	Moderate		Replace		\$0		
	Concrete	100%	x None	Minor	Moderate	_	Replace		\$0		Slab on grade, No Issues
B1020 Roof Construction	Wood		o None	Minor	Moderate		Replace		\$0		
	Steel		o None	Minor	Moderate		Replace		\$0		
	Concrete		o None	Minor	Moderate		Replace		\$0		
B20 Exterior Enclosure		_							·		
B2010 Exterior Walls	Concrete Formed / Tilt		o None	Minor	Moderate	Major	Replace		\$0		
	Masonry	49%	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Framed w/Panel Siding	51%	x None	Minor	Moderate	Major	x Replace	100%	\$458,882	S	Water damage, warped, old
	Framed w/Stucco		o None	Minor	Moderate	Major	Replace		\$0		
	Framed w/Masonry Venee	r	o None	Minor	Moderate	Major	Replace		\$0		
B2020 Exterior Windows	Wood	100%	x None	Minor	Moderate	Major	x Replace	100%	\$599,846	S	Original 1947 wood, damaged, single pane
	Aluminum/Steel		o None	Minor	Moderate	Major	Replace		\$0		
	Clad		o None	Minor	Moderate	Major	Replace		\$0		
	Curtain Wall		o None	Minor	Moderate	Major	Replace		\$0		
B2030 Exterior Doors	Wood	29	x None	Minor	Moderate		x Replace	100%	\$46,415	S	Original doors and hardware
	Hollow Metal	1	x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Storefront		o None	Minor	Moderate	Major	Replace		\$0		
B30 Roofing						_					
B3010 Roof Coverings	Asphalt Shingle	100%	x None	Minor	Moderate	Major	x Replace	100%	\$209,946	S	All roofs are 25-30 years old, beyond life
	Built-Up		o None	Minor	Moderate		Replace		\$0		
	Single Ply		o None	Minor	Moderate		Replace		\$0		
	Metal		o None	Minor	Moderate	_	Replace		\$0		
	Concrete Tile		o None	Minor	Moderate		Replace		\$0		
B3020 Roof Openings	Skylights		o None	Minor	Moderate	_	Replace		\$0		
	Access Hatch		o None	Minor	Moderate	Major	Replace		\$0		
C INTERIORS											
C10 Interior Construction	Former d	4000/		N 4:	N.C. 1	<b>.</b>			ćo		No Issues
C1010 Partitions	Framed	100%	x None	Minor	Moderate	Major	Replace		\$0		No Issues

	Masonry	o Non	e Minor	Moderate	Major	Replace		\$0	
C1020 Interior Doors	Wood	59 x x	Minor	Moderate	Major	x Replace	100%	\$81,839	S Age and deterioration, doors and hardware
	Hollow Metal	o Non	e Minor	Moderate	Major	Replace		\$0	
C1030 Fittings	NOT USED	Non	e Minor	Moderate	Major	Replace			
C20 Stairs									<del></del>
C2010 Stair Construction	Wood	o Non	e Minor	Moderate	Major	Replace		\$0	
	Metal	o Non	e Minor	Moderate	Major	Replace		\$0	
	Concrete	o Non	e Minor	Moderate	Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o Non	e Minor	Moderate	Major	Replace		\$0	
	Resilient	o Non	e Minor	Moderate	Major	Replace		\$0	
C30 Interior Finishes		<u> </u>				<u></u>	<u> </u>		
C3010 Wall Finishes	Paint on Masonry	o Non	e Minor	Moderate	Major	Replace		\$0	
	Wallboard	100% x Non	e x Minor	Moderate	Major	Replace	50%	\$22,494	S Minor wall damage and paint
	Wainscot	o Non	e Minor	Moderate	Major	Replace		\$0	
	Ceramic Tile	o Non	e Minor	Moderate	Major	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	75% x Non	e Minor	Moderate	Major	x Replace	100%	\$131,591	S All carpet is 15 years old, worn, dirty
	Resilient Tile	10% x Non	e Minor	Moderate	Major	x Replace	100%	\$16,496	S Worn and aged VCT
	Resilient Sheet	o Non	e Minor	Moderate	Major	Replace		\$0	
	Polished Concrete	15% x Non	e Minor	Moderate	Major	Replace		\$0	No Issues
	Ceramic Tile	o Non	e Minor	Moderate	Major	Replace		\$0	
	Liquid Applied	o Non	e Minor	Moderate	Major	Replace		\$0	
	Wood Sports Floor	o Non	Minor	Moderate	Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	o Non	e Minor	Moderate	Major	Replace		\$0	
	Lay-In Ceiling Tile	50% x Non	e Minor	Moderate	Major	Replace		\$0	No Issues
	Glued-Up Ceiling Tile	50% x Non	e Minor	Moderate	Major	x Replace	100%	\$67,483	S Original ceiling tiles, failing/falling
	Painted Structure	o Non	e Minor	Moderate	Major	Replace		\$0	
SERVICES									
D10 Conveying									
D1010 Elevators & Lifts		o Non	e Minor	Moderate	Major	Replace		\$0	
D1020 Escalators & Moving Wall	S	o Non	e Minor	Moderate	Major	Replace		\$0	
D1090 Other Conveying Systems		o Non	Minor	Moderate	Major	Replace		\$0	
D20 Plumbing			<u> </u>						
D2010 Plumbing Fixtures		100% x Non	Minor	Moderate	Major	x Replace	100%	\$209,946	Replace all 29, aged, efficiency
D2020 Domestic Water Distribut	on	100% x Non	e Minor	Moderate	Major	x Replace	100%	\$89,977	S Original water lines 1947
D2030 Sanitary Waste		100% x Non	e Minor	Moderate	Major	x Replace	100%	\$89,977	S Original S.S. lines 1947
D2040 Rain Water Drainage		o Non	e Minor	Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	Non	e Minor	Moderate	Major	Replace			
D30 HVAC									
D3010 Energy Supply		100% x Non	e Minor	Moderate	Major	Replace		\$0	No Issues
D3020 Heat Generating Systems	Boiler	50% x Non		Moderate	Major	x Replace	100%	\$59,985	S Original 1947 equipment, beyond service life
	Air Handler	50% x Non		Moderate	Major	x Replace	100%	\$44,988	S
	Furnace	o Non		Moderate	Major	Replace		\$0	
	Heat Exchanger	o Non		Moderate	Major	Replace		\$0	
D3030 Cooling Generating System	•	100% x Non		Moderate	Major	x Replace	100%	\$89,977	S Beyond service Life
	Stand alone chiller	o Non	Minor	Moderate	Major	Replace		\$0	
		<del></del>							
D3040 Distribution Systems	Ductwork	100% x Non		Moderate	Major	x Replace	100%	\$59,985	S Beyond service Life
D3040 Distribution Systems  D3050 Terminal & Package Units	Ductwork Hot water return & supply		e Minor	Moderate Moderate Moderate	Major Major Major	x Replace x Replace Replace	100% 199%	\$59,985 \$298,423 \$0	S Beyond service Life  I Old 2-pipe system

School Facilities Assessment Template

	In-room ventilator unit	o None	Minor	Moderate	Major	Replace		\$0		
	In-room radiant unit	o None	Minor	Moderate	Major	Replace		\$0		
D3060 Controls & Instrumentatio	n	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
D3070 Systems Testing & Balancii	ng	100% x None	Minor	Moderate	Major	x Replace	100%	\$29,992	I	
D3090 Other HVAC Systems & Eq	ui NOT USED	None	Minor	Moderate	Major	Replace				
D40 Fire Protection										
D4010 Sprinklers		o None	Minor	Moderate	Major	Replace		\$0		
D4020 Standpipes		o None	Minor	Moderate	Major	Replace		\$0		
D4030 Fire Protection Specialties		o None	Minor	Moderate	Major	Replace		\$0		
D4090 Other Fire Protection Syste		None	Minor	Moderate	Major	Replace				
D50 Electrical							_		<u>-</u>	_
D5010 Electrical Service & Distrib	ution	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
D5030 Communications & Securit		o None	Minor	Moderate	Major	Replace		\$0		
	Clock / Intercom System	o None	Minor	Moderate	Major	Replace		\$0		
	Closed Circuit Surveillance	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Access Control System	o None	Minor	Moderate	Major	Replace		\$0		
	Intrusion Alarm System	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
	Fire Alarm / Detection	o None	Minor	Moderate	Major	Replace		\$0		
	Lighting Control System	o None	Minor	Moderate	Major	Replace		\$0		
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Major	Replace		γo		
23030 Other Electrical Systems	1101 0325	World	IVIII IOI	Woderate	Wajor	Керіасс			_	
E EQUIPMENT & FURNISHINGS										
E10 Equipment										
E1010 Commercial Equipment	Food Service	o None	Minor	Moderate	Maior	Replace		\$0		
	Vocational	o None	Minor	Moderate	Major	Replace		\$0		
E1020 Institutional Equipment	Science	o None	Minor	Moderate	Major	Replace		\$0		
	Art	o None	Minor	Moderate	Major	Replace		\$0		
	Stage Performance	o None	Minor	Moderate	Major	Replace		\$0		
	Restroom Accessories/Stall		Minor	Moderate	Major	x Replace	100%	\$749,808	S	12 RR Stalls, old, damaged, not functional
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace	10070	ψ7 13)000	3	
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace				
E20 Furnishings	NOTOSED	None	WIIIIOI	Woderate	IVIajoi	Керіасс			_	
E2010 Fixed Furnishings		100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
E2020 Movable Furnishings		100% x None	Minor		Major	Replace		\$0		No Issues
F SPECIAL CONSTRUCTION & DEMOLITION - NOT U	ICED	100% X Notice	WIIIOI	Woderate	iviajoi	Керіасе		ΨŪ		110 135003
F SPECIAL CONSTRUCTION & DEIVIDENTION - NOT										
G BUILDING SITE WORK										
G10 Site Preparation	NOT USED									
G20 Site Improvements										
G2010 Roadways		0 None	Minor	Moderate	Maior	Replace		\$0		
G2020 Parking Lots		64764 x None	Minor	Moderate	Major	x Replace	100%	\$449,171	1	Deterioration, damage
G2030 Pedestrian Paving		2260 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G2040 Site Development		1382 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G2050 Landscaping		207370 x None	Minor	Moderate	Major	Replace		\$0		No Issues
G30 Site Mechanical Utilities				····oderate		epiace		Υ-		
G3010 Water Supply	Domestic	100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
SSSIS Water Supply	Fire	o None	Minor	Moderate	Major	Replace		\$0		
G3020 Sanitary Sewer		100% x None	Minor	Moderate	Major	Replace		\$0		No Issues
GSOZO Sumai y Sewer		100/3 A MONE	14111101	Moderate	. Alajoi	перисс		γ		State of Oregon
										School Facilities Assessment Template

G3030 Storm Sewer	o None Minor	Moderate	Major	Replace	\$0		
G3040 Heating Distribution	o None Minor	Moderate	Major	Replace	\$0		
G3050 Cooling Distribution	o None Minor	Moderate	Major	Replace	\$0		
G3060 Fuel Distribution	o None Minor	Moderate	Major	Replace	\$0		
G3090 Other Site Mechanical Utiliti NOT USED	None Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities				_			
G4010 Electrical Distribution Service	o None Minor	Moderate	Major	Replace	\$0		
Generator	o None Minor	Moderate	Major	Replace	\$0		
G4020 Site Lighting	o None Minor	Moderate	Major	Replace	\$0		
G4030 Site Communications & Security	o None Minor	Moderate	Major	Replace	\$0		
G4090 Other Site Electrical Utilities NOT USED	None Minor	Moderate	Major	Replace			
G90 Other Site Construction NOT USED		<u>-</u>			 <del>-</del>		
OTHER					 		
		Unit of		Unit		Rank	
<u>Description of System</u>		Measure	Quantity	Budget	Extended	(I,S,L)	Notes
B2030 Exterior Overhead Doors, Qty 2, No Issues		ea	2		\$0		No Issues
					\$0		
					\$0		
					\$0		
					\$0		
					1 -		
					\$0		

Physical Condition Budget Sub-Total \$3,807,220
Budgeted Development Costs \$1,446,744
Physical Condition Budget TOTAL \$5,253,964

Replacement Budget \$12,800,839

District Name:	Three Rivers/Josephine County SD
Site Name:	Food Services
Building Name:	
Building ID:	

# REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

	LEVEL OF ACTION														
							<del></del>	T T			II	% of		Necessity	
				% of Building								System or	Automated Budget	Rank	
Level 1	Level 2	Level 3	Type (as applicable)	or Number	N	lone	Minor	Moder	ate	Major	Replace	-	Estimate		Notes
A SUBST															
		ndations													
		A1010 Standard Foundations			o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
		A1020 Special Foundations			o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
		A1030 Slab on Grade		100%	x Non	ie	Minor	Modera	ite	Major	Replace		\$0		No Issues
,	A20 Base	ement Construction				_						<u> </u>			
		A2010 Basement Excavation	NOT USED		Non	ie	Minor	Modera	ite	Major	Replace				
		A2020 Basement Walls			o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
B SHELL						-									
	B10 Sup	<u>erstructure</u>													
		B1010 Floor Construction	Wood		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Steel		o Non	ie	Minor	Modera		Major	Replace		\$0		
			Concrete	100%	o Non	ie	Minor	Modera		Major	Replace		\$0		Slab on grade, No Issues
		B1020 Roof Construction	Wood		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Steel	100%	x Non	ie	Minor	Modera		Major	Replace		\$0		No Issues
			Concrete		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
	B20 Exte	erior Enclosure								4 ′	· ·		·		
•		B2010 Exterior Walls	Concrete Formed / Tilt		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Masonry		o Non	ie	Minor	Modera		Major	Replace		\$0		
			•							1 1	Ħ ˙		· · · · · · · · · · · · · · · · · · ·		
			Framed w/Panel Siding	100%	x Non	ie	Minor	Modera	ite	Major	x Replace	100%	\$240,075	ı	95% Metal panel, 5% Fiberglass panel, replace
			Framed w/Stucco		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Framed w/Masonry Veneer		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
		B2020 Exterior Windows	Wood		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Aluminum/Steel	100%	x Non	ie	Minor	Modera	ite	Major	x Replace	100%	\$104,033	S	Original 1983 window construction
			Clad		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Curtain Wall		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
		B2030 Exterior Doors	Wood		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Hollow Metal	4	x Non	ie	Minor	x Modera	ite	Major	Replace	100%	\$1,280	S	Repairs and painting
			Storefront		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
	B30 Roo	fing				_				-				_	
		B3010 Roof Coverings	Asphalt Shingle		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Built-Up		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Single Ply		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Metal	100%	x Non	ie	Minor	Modera	ite	Major	x Replace	100%	\$160,050	I	Original roof, numerous leaks
			Concrete Tile		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
		B3020 Roof Openings	Skylights		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
			Access Hatch		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		
C INTER	IORS														
	C10 Inte	rior Construction				_				_					
		C1010 Partitions	Framed	100%	x Non		Minor	Modera		Major	Replace		\$0		No Issues
			Masonry		o Non	ie	Minor	Modera	ite	Major	Replace		\$0		

State of Oregon

C1020 Interior Doors	Wood	5 x None	Minor	x Moderate Maj	or	Replace	100%	\$1,601	S	Repairs needed
	Hollow Metal	o None	Minor	Moderate Maj	or	Replace		\$0		
C1030 Fittings	NOT USED	None	Minor	Moderate	or	Replace				
C20 Stairs									·	
C2010 Stair Construction	Wood	1 x None	Minor	Moderate Maj	or	Replace		\$0		No Issues, wood stairs to mezzanine
	Metal	o None	Minor	Moderate Maj	or	Replace		\$0		
	Concrete	o None	Minor	Moderate Maj	or	Replace		\$0		
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate	or	Replace		\$0		
	Resilient	o None	Minor	Moderate Maj		Replace		\$0		
C30 Interior Finishes		<u> </u>		<b>—</b>			<u> </u>	·		<del>'</del>
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate	or	Replace		\$0		
	, Wallboard	100% x None	Minor	Moderate Maj		Replace		\$0		No Issues
	Wainscot	o None	Minor	Moderate Maj		Replace		\$0		
	Ceramic Tile	o None	Minor	Moderate Maj		Replace		\$0		
C3020 Floor Finishes	Carpet / Soft Surface	o None	Minor	Moderate Maj		Replace		\$0		
esozo i loci i misnes	Resilient Tile	5% x None	Minor	Moderate Maj		Replace		\$0 \$0		No Issues
	Resilient Sheet	o None	Minor	Moderate Maj		Replace		\$0		1.0 133463
	Polished Concrete	95% x None	Minor	Moderate Maj		Replace		\$0 \$0		No Issues
	Ceramic Tile		Minor				-			140 133003
		o None				Replace	-	\$0 \$0		
	Liquid Applied	o None	Minor	Moderate Maj		Replace	-	\$0		
C2020 Calling Finish	Wood Sports Floor	o None	Minor	Moderate Maj		Replace		\$0		No legues
C3030 Ceiling Finishes	Wallboard	5% x None	Minor	Moderate Maj		Replace		\$0		No Issues
	Lay-In Ceiling Tile	o None	Minor	Moderate		Replace		\$0		
	Glued-Up Ceiling Tile	o None	Minor	Moderate		Replace		\$0		
	Painted Structure	o None	Minor	Moderate	or	Replace		\$0		
ERVICES										
D10 Conveying			<b>—</b>			٦		<b>*</b> 0		
D1010 Elevators & Lifts		o None	Minor	Moderate Maj		Replace		\$0		
D1020 Escalators & Moving Walk	S	o None	Minor	Moderate		Replace		\$0		
D1090 Other Conveying Systems		o None	Minor	Moderate	or	Replace		\$0		
<u>D20 Plumbing</u>					_	_				
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Maj		Replace	100%	\$56,018	I	Replace all
D2020 Domestic Water Distribut	on	100% x None	Minor	Moderate		Replace	100%	\$24,008	I	Dirty, rusty water, not potable
D2030 Sanitary Waste		100% x None	Minor	Moderate		Replace		\$0		No Issues
D2040 Rain Water Drainage		o None	Minor	Moderate	or	Replace		\$0		
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate Maj	or	Replace				
D30 HVAC						_				
D3010 Energy Supply		100% x None	Minor	Moderate	or	Replace		\$0		No Issues
D3020 Heat Generating Systems	Boiler	o None	Minor	Moderate Maj	or	Replace		\$0		
	Air Handler	o None	Minor	Moderate Maj	or	Replace		\$0		
	Furnace	100% x None	Minor	Moderate Maj	or >	x Replace	100%	\$16,005	I	Split system
	Heat Exchanger	o None	Minor	Moderate Maj	or	Replace		\$0		
D3030 Cooling Generating Syster	ns Component of air handler	o None	Minor	Moderate Maj	or	Replace		\$0		
- '	Stand alone chiller	o None	Minor	Moderate Maj		Replace		\$0		
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate Maj		x Replace	100%	\$16,005	I	Original ductwork, old
,	Hot water return & supply	o None	Minor	Moderate Maj		Replace		\$0		
D3050 Terminal & Package Units		o None	Minor	Moderate Maj		Replace		\$0		
	In-room ventilator unit	o None	Minor	Moderate Maj		Replace		\$0		<del> </del>
	In-room radiant unit	o None	Minor	Moderate Maj		Replace		\$0		
		5 1.511C						70		
D3060 Controls & Instrumentation	n	100% x None	Minor	Moderate Maj	or	Replace		\$0		No Issues

State of Oregon School Facilities Assessment Template 6/2016

D3070 Systems Testing & Balanci	ing	100% x None	Minor	Moderate	Replace	\$0	No Issues
D3090 Other HVAC Systems & Eq			Minor		Replace	Ų	140 133003
	Jul NOT OSED	None	MILIOI	Moderate	Replace		
D40 Fire Protection		,					
D4010 Sprinklers		o None	Minor	Moderate Major	Replace	\$0	
D4020 Standpipes		o None	Minor	Moderate Major	Replace	\$0	
D4030 Fire Protection Specialties		o None	Minor	Moderate	Replace	\$0	
D4090 Other Fire Protection Syst	en NOT USED	None	Minor	Moderate Major	Replace		
D50 Electrical							
D5010 Electrical Service & Distrib	oution	100% x None	Minor	Moderate Major		100% \$64,020 I	Main switchgear and Gould ITE panels
D5020 Lighting and Branch Wirin	g	100% x None	Minor	Moderate Major	x Replace	100% \$96,030 I	Original wiring and fixtures
D5030 Communications & Securi	ty Voice / Data System	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace	\$0	
	Closed Circuit Surveillance	o None	Minor	Moderate Major	Replace	\$0	
	Access Control System	o None	Minor	Moderate Major	Replace	\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace	\$0	
	Lighting Control System	o None	Minor	Moderate Major	Replace	\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace	ΨO	
D3030 Other Electrical Systems	NOT OSED	None	IVIIIIOI	Widjoi	перисс	-	
QUIPMENT & FURNISHINGS							
E10 Equipment							
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	x Replace	100% \$16,005 I	Walk-in equipment, old, high maintenance
E1010 Commercial Equipment				Moderate Major			waik-in equipment, old, high maintenance
F1020 lastitutional Faulturent	Vocational	o None	Minor		Replace	\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace	\$0	
	Art	o None	Minor	Moderate Major	Replace	\$0	
	Stage Performance	o None	Minor	Moderate Major	Replace	\$0	
	Restroom Accessories/Stalls	100% x None	Minor	Moderate Major	Replace	\$0	No Issues
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Replace		
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Replace		
E20 Furnishings			<u></u>	<u> </u>	<u> </u>		
E2010 Fixed Furnishings		o None	Minor	Moderate Major	Replace	\$0	
E2020 Movable Furnishings		o None	Minor	Moderate Major	Replace	\$0	
SPECIAL CONSTRUCTION & DEMOLITION - NOT	USED						
UILDING SITE WORK							
G10 Site Preparation	NOT USED						
G20 Site Improvements							
G2010 Roadways		o None	Minor	Moderate Major	Replace	\$0	
G2020 Parking Lots		o None	Minor	Moderate Major	Replace	\$0	
G2030 Pedestrian Paving		o None	Minor	Moderate Major	Replace	\$0	
G2040 Site Development		o None	Minor	Moderate Major	Replace	\$0	<u> </u>
G2050 Landscaping		o None	Minor	Moderate Major	Replace	\$0	
G30 Site Mechanical Utilities		- The state of the		dad.ate		ŸŸ	I
G3010 Water Supply	Domestic	100% x None	Minor	Moderate	x Replace	100% \$8,003 I	Dirty, rusty water, not potable
GOOTO Marci Subbis	Fire	o None	Minor	Moderate Major	Replace	\$0	on cy, rusty water, not potable
C2020 Sanitany Sauce	ille						No Issues
G3020 Status Sewer		100% x None	Minor	Moderate Major	Replace	\$0	110 122062
G3030 Storm Sewer		0 None	Minor	Moderate Major	Replace	\$0	
G3040 Heating Distribution		0 None	Minor	Moderate Major	Replace	\$0	
G3050 Cooling Distribution		0 None	Minor	Moderate Major	Replace	\$0	
G3060 Fuel Distribution		0 None	Minor	Moderate Major	Replace	\$0	
G3090 Other Site Mechanical Util			Minor	<b>Moderate</b> Major	Replace		

School Facilities Assessment Template 6/2016

G40 Site Electrical Utilities										
G4010 Electrical Distribution Service	e	o None Mir	nor	Moderate	Major	Replace		\$0		
Gener	ator	o None Mir	nor N	Moderate	Major	Replace		\$0		
G4020 Site Lighting		o None Mir	nor N	Moderate	Major	Replace		\$0		
G4030 Site Communications & Security		o None Mir	nor N	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical Utilities NOT U	SED	None Mir	nor N	Moderate	Major	Replace				
G90 Other Site Construction NOT U	SED						_	_		
OTHER										
Description of Contrar				Unit of	Overtitu	Unit		Fyton dod	Rank	Notes
<u>Description of System</u>				Measure	Quantity	Budget		Extended	(I,S,L)	Notes
	g Finish, Open to deck,									
C3030 not pa	inted 95%	Х						\$0		No Issues
								\$0		
B2030 Exterio	or Doors, OVH 100%	Х	e	ea	2			\$0		No Issues, 2015 and 2017 new
								\$0		

Physical Condition Budget Sub-Total \$803,131

Budgeted Development Costs \$305,190

Physical Condition Budget TOTAL \$1,108,321

Replacement Budget \$4,269,375

District Name:	Three Rivers/Josephine County SD
Site Name:	Maintenance Garage
Building Name:	
Building ID:	

# REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

			LEVEL OF ACTION												
												% of		Necessity	
				% of Building								System or	Automated Budget	Rank	
Level 1	Level 2	Level 3	Type (as applicable)	or Number	No	one	Minor	Moderate	Major		Replace	Finish	Estimate	(I, S, L)	Notes
A SUBS	TRUCTU	RE			<u> </u>		<u>,                                    </u>				<u>.</u>				
	A10 Fou	ndations													
		A1010 Standard Foundations			o None	2	Minor	Moderate	Major		Replace		\$0		
		A1020 Special Foundations			o None	<u> </u>	Minor	Moderate	Major		Replace		\$0		
		A1030 Slab on Grade		100%	x None	è	Minor	Moderate	Major		Replace		\$0		No Issues
	A20 Bas	ement Construction				_		<u> </u>			I	:			
		A2010 Basement Excavation	NOT USED		None	è	Minor	Moderate	Major		Replace				
		A2020 Basement Walls			o None	·	Minor	Moderate	Major		Replace		\$0		
B SHEL	L					<u> </u>									
	B10 Sup	<u>erstructure</u>				_									
		B1010 Floor Construction	Wood		o None	2	Minor	Moderate	Major		Replace		\$0		
			Steel		o None	è	Minor	Moderate	Major		Replace		\$0		
			Concrete	100%	x None	è	Minor	Moderate	Major		Replace		\$0		Slab on grade, No Issues
		B1020 Roof Construction	Wood	100%	x None	è	Minor	Moderate	Major		Replace		\$0		No Issues
			Steel		o None	è	Minor	Moderate	Major		Replace		\$0		
			Concrete		o None	è	Minor	Moderate	Major		Replace		\$0		
	B20 Exte	erior Enclosure									I	<u> </u>			
		B2010 Exterior Walls	Concrete Formed / Tilt		o None		Minor	Moderate	Major		Replace		\$0		
			Masonry	100%	x None	2	Minor	x Moderate	Major		Replace	5%	\$5,816	S	Moderate repairs to CMU cracks
			Framed w/Panel Siding		o None	2	Minor	Moderate	Major		Replace		\$0		
			Framed w/Stucco		o None	2	Minor	Moderate	Major		Replace		\$0		
			Framed w/Masonry Vene	er	o None	2	Minor	Moderate	Major		Replace		\$0		
		B2020 Exterior Windows	Wood	15%	x None	2	Minor	Moderate	Major	Х	Replace	100%	\$58,162	I	Wood rot, window frame
			Aluminum/Steel	85%	x None	2	Minor	Moderate	Major	Х	Replace	100%	\$214,231	I	Age, single pane
			Clad		o None	2	Minor	Moderate	Major		Replace		\$0		
			Curtain Wall		o None	2	Minor	Moderate	Major		Replace		\$0		
		B2030 Exterior Doors	Wood	4	x None	2	Minor	Moderate	Major	Х	Replace	100%	\$6,402	ı	Wood rot, damage, aged
			Hollow Metal	3	x None	2	Minor	x Moderate	Major		Replace	100%	\$960	I	Repairs and paint
			Storefront		o None		Minor	Moderate			Replace		\$0		
	B30 Roc	fing			-						ı	<u> </u>		•	
		B3010 Roof Coverings	Asphalt Shingle		o None	:	Minor	Moderate	Major		Replace		\$0		
			Built-Up	100%	x None	:	Minor	Moderate	Major	-	Replace	100%	\$193,874	I	1995 roof covering, numerous leaks
			Single Ply		o None	•	Minor	Moderate	Major	-	Replace		\$0		
			Metal		o None	2	Minor	Moderate	Major	-	Replace		\$0		
			Concrete Tile		o None		Minor	Moderate	Major	-	Replace		\$0		
		B3020 Roof Openings	Skylights		o None		Minor	Moderate	Major	-	Replace		\$0		
		· -	Access Hatch		o None		Minor	Moderate	Major	-	Replace		\$0		
C INTE	RIORS										_				
		rior Construction													
		C1010 Partitions	Framed	85%	x None		Minor	Moderate	Major		Replace		\$0		No Issues
											i .				State of Oregon

	Masonry	15% x None	Minor	Moderate Major	Replace		\$0	No Issues
C1020 Interior Doors	Wood	16 x None	Minor	Moderate Major	x Replace	100%	\$22,194	S Delamination, Damage, aged
	Hollow Metal	1 x None	Minor	Moderate Major	x Replace	100%	\$1,174	S Replace
C1030 Fittings	NOT USED	None	Minor	Moderate Major	Replace			
C20 Stairs	•							
C2010 Stair Construction	Wood	2 x None	Minor	Moderate Major	Replace		\$0	No Issues, stairs to mezzanine
	Metal	o None	Minor	Moderate Major	Replace		\$0	
	Concrete	o None	Minor	Moderate Major	Replace		\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate Major	Replace		\$0	
	Resilient	o None	Minor	Moderate Major	Replace		\$0	
C30 Interior Finishes	•	<del></del>	<u></u>		<del>-</del>			<del>-</del>
C3010 Wall Finishes	Paint on Masonry	o None	Minor	Moderate Major	Replace		\$0	
	Wallboard	100% x None	Minor	x Moderate Major	Replace	100%	\$58,162	S Repaint all interiors
	Wainscot	o None	Minor	Moderate Major	Replace		\$0	
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	5% x None	Minor	Moderate Major	x Replace	100%	\$5,671	l Worn, dirty, odor
	Resilient Tile	10% x None	Minor	Moderate Major	x Replace	100%	\$10,663	l Worn, damaged
	Resilient Sheet	o None	Minor	Moderate Major	Replace		\$0	
	Polished Concrete	85% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Ceramic Tile	o None	Minor	Moderate Major	Replace		\$0	
	Liquid Applied	o None	Minor	Moderate Major	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	o None	Minor	Moderate Major	Replace		\$0	
g :	Lay-In Ceiling Tile	o None	Minor	Moderate Major	Replace		\$0	
	Glued-Up Ceiling Tile	2% x None	Minor	Moderate Major	x Replace	100%	\$1,745	S Failing/falling tiles
	Painted Structure	98% x None	Minor	Moderate Major	Replace		\$0	No issues
RVICES							7.7	
D10 Conveying								
D1010 Elevators & Lifts		o None	Minor	Moderate Major	Replace		\$0	
D1020 Escalators & Moving Walks		o None	Minor	Moderate Major	Replace		\$0	
D1090 Other Conveying Systems		o None	Minor	Moderate Major	Replace		\$0	
D20 Plumbing		o none	······································	Majer	періасс		Ψ0	
D2010 Plumbing Fixtures		100% x None	Minor	Moderate Major	x Replace	100%	\$135,712	Replace all fixtures, count = 9
D2020 Domestic Water Distribution		100% x None	Minor	Moderate Major	x Replace	100%	\$58,162	l Dirty, rusty water
D2030 Sanitary Waste		100% X None	Minor	Moderate Major	Replace	100%	\$0	No Issues
D2040 Rain Water Drainage		o None	Minor	Moderate Major	Replace	-	\$0 \$0	140 155465
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate Major	Replace		γo	
D30 HVAC	NOT OSED	None	WIIIIOI	Woderate Wajor	Керіасе			
D3010 Energy Supply		100% x None	Minor	Moderate Major	Replace		\$0	No Issues
D3010 Energy Supply  D3020 Heat Generating Systems	Boiler	100% x None	Minor	Moderate Major	x Replace	100%	\$77,550	Original boiler, beyond service life
D3020 Heat Generating systems	Air Handler	o None	Minor	Moderate Major	Replace	100/0	\$77,530	original solici, seyona service inc
	Furnace	o None	Minor	Moderate Major		$\vdash$	\$0	<del>                                     </del>
	Heat Exchanger	o None	Minor	Moderate Major	Replace	$\vdash$	\$0 \$0	1
D2020 Cooling Concreting Systems	Component of air handler		Minor		Replace	$\vdash$	\$0 \$0	1
D3030 Cooling Generating Systems	· · · · · · · · · · · · · · · · · · ·				Replace	$\vdash$		1
D2040 Dietaile ation Control	Stand alone chiller	o None	Minor	Moderate Major	Replace	$\vdash$	\$0	<del></del>
D3040 Distribution Systems	Ductwork	o None	Minor	Moderate Major	Replace	1000/	\$0	1 20+ year old nining no inculation
D2050 T	Hot water return & supply		Minor	Moderate Major	x Replace	100%	\$96,937	30+ year old piping, no insulation
D3050 Terminal & Package Units	Above ceiling VAV unit	o None	Minor	Moderate	Replace	$\sqsubseteq$	\$0	State of

State of Oregon

	In-room ventilator unit	100% x None	Minor	Moderate	x Replace	100%	\$38,775	Old window units, qty 5
	In-room radiant unit	o None	Minor	Moderate Major	Replace		\$0	
D3060 Controls & Instrumentation	1	100% x None	Minor	Moderate Major	x Replace	100%	\$38,775	I Old control system
D3070 Systems Testing & Balancin	g	100% x None	Minor	Moderate Major	x Replace	100%	\$19,387	l l
D3090 Other HVAC Systems & Equ	ip NOT USED	None	Minor	Moderate Major	Replace			
<u>D40 Fire Protection</u>					<u> </u>			
D4010 Sprinklers		o None	Minor	Moderate Major	Replace		\$0	
D4020 Standpipes		o None	Minor	Moderate Major	Replace		\$0	
D4030 Fire Protection Specialties		o None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Syste	m: NOT USED	None	Minor	Moderate	Replace			
D50 Electrical				<u> </u>	<u>—</u>			
D5010 Electrical Service & Distribu	ition	100% x None	Minor	Moderate Major	x Replace	100%	\$155,099	I Federal Pacific equipment
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate Major	x Replace	100%	\$232,649	Original wiring and fixtures
D5030 Communications & Security	/ Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No Issues
	Clock / Intercom System	o None	Minor	Moderate Major	Replace		\$0	
	Closed Circuit Surveilland	ce o None	Minor	Moderate Major	Replace		\$0	
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	o None	Minor	Moderate Major	Replace		\$0	
	Fire Alarm / Detection	o None	Minor	Moderate Major	Replace		\$0	
	<b>Lighting Control System</b>	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate Major	Replace			
		<del></del>	<del></del>	<del></del>	<del></del>	-		
E EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	o None	Minor	Moderate Major	Replace		\$0	
	Vocational	o None	Minor	Moderate Major	Replace		\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0	
	Art	o None	Minor	Moderate Major	Replace		\$0	
	Stage Performance	o None	Minor	Moderate Major	Replace		\$0	
	Restroom Accessories/St	a 100% x None	Minor	Moderate Major	x Replace	100%	\$484,685	I Replace all
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E20 Furnishings					<del></del>			
E2010 Fixed Furnishings		100% x None	Minor	Moderate Major	x Replace	100%	\$232,649	S Maintenance built-in cabinets
E2020 Movable Furnishings		100% x None	Minor	Moderate	Replace		\$0	No Issues
F SPECIAL CONSTRUCTION & DEMOLITION - NOT US	SED			_				
G BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements			<u> </u>				4.	
G2010 Roadways		o None	Minor	Moderate Major	Replace	10.51	\$0	T-A-16-illions of the least to
G2020 Parking Lots		66020 x None	Minor	Moderate Major	x Replace	100%	\$457,882	Total failure of asphalt, base, gravel
G2030 Pedestrian Paving		o None	Minor	Moderate Major	Replace		\$0	Dealess I. I.
G2040 Site Development		1560 x None	Minor	Moderate x Major	Replace	20%	\$333	Replace damaged fence and gates
G2050 Landscaping		o None	Minor	Moderate Major	Replace		\$0	
G30 Site Mechanical Utilities								
G3010 Water Supply	Domestic	100% x None	Minor	Moderate	x Replace	100%	\$19,387	Dirty and rusty water
	Fire	o None	Minor	Moderate	Replace		\$0	
								State of Oregon

State of Oregon School Facilities Assessment Template

G3020 Sanitary Sewer	10	0% x None	Minor	Moderate	Major	Replace		\$0		No Issues
G3030 Storm Sewer		o None	Minor	Moderate	Major	Replace		\$0		
G3040 Heating Distribution		o None	Minor	Moderate	Major	Replace		\$0		
G3050 Cooling Distribution		o None	Minor	Moderate	Major	Replace		\$0		
G3060 Fuel Distribution		o None	Minor	Moderate	Major	Replace		\$0		
G3090 Other Site Mechanical Utilitie NOT	T USED	None	Minor	Moderate	Major	Replace				
G40 Site Electrical Utilities				<u> </u>						
G4010 Electrical Distribution Serv	vice	o None	Minor	Moderate	Major	Replace		\$0		
Gen	nerator	o None	Minor	Moderate	Major	Replace		\$0		
G4020 Site Lighting		o None	Minor	Moderate	Major	Replace		\$0		
G4030 Site Communications & Security		o None	Minor	Moderate	Major	Replace		\$0		
G4090 Other Site Electrical Utilities NOT	T USED	None	Minor	Moderate	Major	Replace				
	T USED									
OTHER										
				Unit of		Unit			Rank	
<u>Description of System</u>				Measure	Quantity	Budget		Extended	(I,S,L)	Notes
	H Door, metal, 10' x 14'			ea	2		_	\$0		Old, worn,
B2030 OVH	H Door, wood, 10' x 14'			ea	2		_	\$0	l	Damaged, wood rot
							_	\$0		
								\$0		
				l			_	\$0		
								\$0		
								\$0		

Physical Condition Budget Sub-Total \$2,627,034

Budgeted Development Costs \$998,273

Physical Condition Budget TOTAL \$3,625,307

Replacement Budget \$6,068,053