Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
DISTRICT ADMINISTRATIVE CENTER	7925 Janes Ave, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/23/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM

NO VIOLATIONS FOUND AT TIME OF INSPECTION

Other Concerns

Passed:

Comments

Inspector Comments

No Inspector comment provided

District Responses

Response by Curtis Saindon on 10/02/2026

As there were no violations noted for the District Administrative Center, no remedial responses are required.

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
Storage Garage	7200 Janes Ave, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/30/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM

NO VIOLATIONS FOUND AT TIME OF INSPECTION

Other Concerns

Passed:

Comments

Inspector Comments

No Inspector comment provided

District Responses

Response by Curtis Saindon on 10/07/2026

As there were no violations noted for the Maintenance Garage, no remedial responses are required.

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
WILLOW CREEK ELEM SCHOOL	2901 Jackson Dr, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/23/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM

NO VIOLATIONS FOUND AT TIME OF INSPECTION

Other Concerns

Passed:

Comments

Inspector Comments

No Inspector comment provided

District Responses

Response by Curtis Saindon on 10/02/2026

As there were no violations noted for Willow Creek Elementary School, no remedial responses are required.

Add Response

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
WILLIAM F MURPHY ELEM SCHOOL	7700 Larchwood Ln, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/16/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM

NO VIOLATIONS FOUND AT TIME OF INSPECTION

Other Concerns

Passed:

Comments

Inspector Comments

No Inspector comment provided

District Responses

Response by Curtis Saindon on 10/02/2026

As there were no violations noted for William F. Murphy Elementary School, no remedial responses are required.

Add Response

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
THOMAS JEFFERSON JR HIGH SCHOOL	7200 Janes Ave, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/30/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	Art Room storeroom - Chair was being used as a hold open device. Please remove.
6	Administration and General	Reduce PE equipment stored in vestibule near Door 15.
26	Administration and General	Maintenance room (U102) near Door 9 - Keep electrical panel clear (at least 36")

Hold-Open Devices

Passed: No

Hold-open devices are prohibited on all doors described as "self-closing." IFC only: Opening protectives shall be maintained in an operative condition in accordance with applicable the edition of NFPA 80. Hold-open devices and automatic door closers, where provided, shall be maintained. Doors that are automatic-closing (e.g., held open with magnetic hold-open devices) are required to close only upon activation of the assigned smoke detectors or upon power loss. During the period that such device is out of service for repairs, the door it operates shall remain in the closed position. BOCA-F only: Fire doors shall be self-closing or automatic closing in accordance with the requirements of the applicable edition of NFPA 80. Fire doors which are not self-closing and which protect openings in horizontal exits, exits, or exit access corridors required to be of fire resistance rated construction shall be automatic-closing by the actuation of smoke detectors or by loss of power to the smoke detector or the hold-open device. Part 175/185 only: Where doors are required to be self-closing such as in opening protectives in enclosures for vertical openings, horizontal exits, limiting wall of open plan buildings, and smoke-stop partitions approved self-closing devices shall be used while the building is occupied or shall be arranged to be automatic-closing upon actuation of the building's fire alarm system.

Comments

Inspector Comments

Art Room storeroom - Chair was being used as a hold open device. Please remove.

District Responses

Response by Curtis Saindon on 10/07/2026

We removed the chair being used as a hold open device and informed the Art Teacher that this is not allowed for fire code reasons. She understood and agreed to comply with this directive.

Add Response

Unobstructed Exits

Passed: No

Safe, reliable and unobstructed means of access travel shall be provided from any location in an occupied room or space to the doorways required as either a part of an exit or which provide a path of travel from a room or space to an exit. Unlatching of doors shall not take more than one motion. Any additional locking devices that impede opening of doors are not permitted. [See Appendix N for more information]

Comments

Inspector Comments

Reduce PE equipment stored in vestibule near Door 15.

District Responses

Response by Curtis Saindon on 10/07/2026

We moved the equipment being stored in the Vestibule near Door 15 and informed the PE Teachers that this equipment must be stored out of the way in a proper storage room or storage area per fire code and egress requirements. They understood and agreed to comply.

Add Response

Electrical Systems

Passed: No

All identified electrical hazards shall be abated. Electrical installations shall comply with the applicable edition of the National Electrical Code, including temporary electrical lighting. Temporary electric power and lighting installations shall be permitted for a period not to exceed 90 days for holiday decorative lighting and similar purposes. Decorative lighting used for holiday lighting and similar purposes shall be listed and shall be labeled on the product. Temporary lighting shall not be used in lieu of permanent lighting.

Comments

Inspector Comments

Maintenance room (U102) near Door 9 - Keep electrical panel clear (at least 36")

District Responses

Response by Curtis Saindon on 10/07/2026

We worked with the Head Custodian at Jefferson to clean up the maintenance room near Door 9, specifically near the electric panel, and asked him to keep this area clean and free from obstructions. He understood and agreed to comply with this directive.

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
EDGEWOOD ELEM SCHOOL	7900 Woodridge Ave, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/23/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	Remove door wedge holding LRC closet open.
15	Administration and General	Art Room - Maintain clearance above storage.
26	Administration and General	Clutter is blocking access to the electrical panel in the LRC closet. Please address.
2000	Other Items	Gym - Storage doors and offices were propped open for the lunch period, but I did not see anyone in the area. Please keep these unoccupied spaces closed when not in use.

Hold-Open Devices

Passed: No

Hold-open devices are prohibited on all doors described as "self-closing." IFC only: Opening protectives shall be maintained in an operative condition in accordance with applicable the edition of NFPA 80. Hold-open devices and automatic door closers, where provided, shall be maintained. Doors that are automatic-closing (e.g., held open with magnetic hold-open devices) are required to close only upon activation of the assigned smoke detectors or upon power loss. During the period that such device is out of service for repairs, the door it operates shall remain in the closed position. BOCA-F only: Fire doors shall be self-closing or automatic closing in accordance with the requirements of the applicable edition of NFPA 80. Fire doors which are not self-closing and which protect openings in horizontal exits, exits, or exit access corridors required to be of fire resistance rated construction shall be automatic-closing by the actuation of smoke detectors or by loss of power to the smoke detector or the hold-open device. Part 175/185 only: Where doors are required to be self-closing such as in opening protectives in enclosures for vertical openings, horizontal exits, limiting wall of open plan buildings, and smoke-stop partitions approved self-closing devices shall be used while the building is occupied or shall be arranged to be automatic-closing upon actuation of the building's fire alarm system.

Comments

Inspector Comments

Remove door wedge holding LRC closet open.

District Responses

Response by Curtis Saindon on 10/07/2026

We removed the door wedge and informed the LRC Coordinator that these manual hold open devices should not be used for fire code reasons. She understood and agreed to comply.

Add Response

Clearance Above Storage

Passed: No

Storage shall be maintained 2 ft or more below the ceiling in nonsprinklered areas of a building. The clearance between the sprinkler deflector and the top of storage shall be 18 in or greater. If special sprinkler heads are used, (which is not common in educational occupancies) such as ESFR and Large Drop sprinklers the clearance between the sprinkler deflector and the top of storage shall be 36 in. [See Appendix M]

Comments

Inspector Comments

Art Room - Maintain clearance above storage.

District Responses

Response by Curtis Saindon on 10/07/2026

We removed/moved these items being stored above the cabinet and within 18 inches of the ceiling and informed the Art Teacher that all items must be stored 18 inches or more below the ceiling for fire code reasons. She understood and agreed to comply with this directive.

Add Response

Electrical Systems

Passed: No

All identified electrical hazards shall be abated. Electrical installations shall comply with the applicable edition of the National Electrical Code, including temporary electrical lighting. Temporary electric power and lighting installations shall be permitted for a period not to exceed 90 days for holiday decorative lighting and similar purposes. Decorative lighting used for holiday lighting and similar purposes shall be listed and shall be labeled on the product. Temporary lighting shall not be used in lieu of permanent lighting.

Comments

Inspector Comments

Clutter is blocking access to the electrical panel in the LRC closet. Please address.

District Responses

Response by Curtis Saindon on 10/07/2026

We cleaned up the clutter in the LRC Closet, thereby allowing clear access to the electrical panel, and we informed the LRC Coordinator of the need to keep this area clean and clear of obstructions. She understood and agreed to comply with this directive.

Add Response

Other Concerns

Passed: No

Comments

Inspector Comments

Gym - Storage doors and offices were propped open for the lunch period, but I did not see anyone in the area. Please keep these unoccupied spaces closed when not in use.

District Responses

Response by Curtis Saindon on 10/07/2026

We remove the manual hold open devices in these areas and informed the P.E Teacher and Lunch Staff to keep these unoccupied areas closed when not in use. They understood and agreed to comply with this directive.

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
GOODRICH ELEM SCHOOL	3450 Hobson Rd, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/30/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	Door wedges were being used in rooms 222 & 229. Please remove.
296	Corridors	Hallway near door 14 - Yoga mats were being stored i n corridor. Please address.

Hold-Open Devices

Passed: No

Hold-open devices are prohibited on all doors described as "self-closing." IFC only: Opening protectives shall be maintained in an operative condition in accordance with applicable the edition of NFPA 80. Hold-open devices and automatic door closers, where provided, shall be maintained. Doors that are automatic-closing (e.g., held open with magnetic hold-open devices) are required to close only upon activation of the assigned smoke detectors or upon power loss. During the period that such device is out of service for repairs, the door it operates shall remain in the closed position. BOCA-F only: Fire doors shall be self-closing or automatic closing in accordance with the requirements of the applicable edition of NFPA 80. Fire doors which are not self-closing and which protect openings in horizontal exits, exits, or exit access corridors required to be of fire resistance rated construction shall be automatic-closing by the actuation of smoke detectors or by loss of power to the smoke detector or the hold-open device. Part 175/185 only: Where doors are required to be self-closing such as in opening protectives in enclosures for vertical openings, horizontal exits, limiting wall of open plan buildings, and smoke-stop partitions approved self-closing devices shall be used while the building is occupied or shall be arranged to be automatic-closing upon actuation of the building's fire alarm system.

Comments

Inspector Comments

Door wedges were being used in rooms 222 & 229. Please remove.

District Responses

Response by Curtis Saindon on 10/07/2026

We removed the door wedges and informed all staff that manual hold open devices such as door wedges are not allowed for fire code reasons and should not be used. We will monitor to ensure compliance.

Add Response

Storage in Corridors and Lobbies

Passed: No

Storage in lobbies and corridors is not permitted except when the corridors and lobbies are protected with sprinklers or smoke detectors. Metal lockers may be used as long as the required width for means of egress is maintained. Coats or other clothing may be hung open in the corridor only under prescribed conditions. 175 only: Permits coats or other clothing to be hung in an open corridor under certain prescribed conditions. Where this is done, the width of the corridor shall be increased 15 inches on each side where cloaks are hung. 185 only: Permits students' cloaks to be hung in the open on the side walls of corridors as long as the following criteria are met: -The resulting clear width of such corridors is not less than 85% of the minimum allowable clear width established by 185, and -The uninterrupted length of cloaks hung along any corridor wall is not more than 25 ft. in an unsprinklered building or 40 ft. in a sprinklered building: Such length shall be measured horizontally from one end of the cloak hanging hooks or bars to the other end. Continuity can be interrupted by a fire break consisting of a doorway or blank wall area not less than 36 in. in width or of a partition extending outward perpendicularly from the corridor wall not less than 12 inches and upwards from the floor to an elevation not less than 24 inches above the top of the cloaks. This fire break partition, if provided, shall be considered in determining compliance with the limitations of the preceding paragraph.

Comments

Inspector Comments

Hallway near door 14 - Yoga mats were being stored i n corridor. Please address.

District Responses

Response by Curtis Saindon on 10/07/2026

We removed the yoga mats from the corridor and informed the teacher that these cannot be stored there due to fire code and egress concerns. She understood and we found an alternate, out of the way location for her to store the mats.

Add Response

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER	COUNTY
Woodridge SD 68	Dupage
FACILITY NAME	FACILITY LOCATION
JOHN L SIPLEY ELEM SCHOOL	2806 83rd St, Woodridge

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 09/16/2026 by Aaron Bacon.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	Room 132 - A desk was being used as a hold open device. There were also a few doors in the building with door wedges. Please remove.
6	Administration and General	Room 119 - Small moveable barricade obstructing exit out of classroom door. Please address. Music hallway - A few instruments need to be moved to maintain proper egress in the hall. Maintain proper egress near Door 16.
15	Administration and General	Room 104 - Maintain clearance above storage.
202	Boiler Room	Some general housekeeping is needed.

Hold-Open Devices

Passed: No

Hold-open devices are prohibited on all doors described as "self-closing." IFC only: Opening protectives shall be maintained in an operative condition in accordance with applicable the edition of NFPA 80. Hold-open devices and automatic door closers, where provided, shall be maintained. Doors that are automatic-closing (e.g., held open with magnetic hold-open devices) are required to close only upon activation of the assigned smoke detectors or upon power loss. During the period that such device is out of service for repairs, the door it operates shall remain in the closed position. BOCA-F only: Fire doors shall be self-closing or automatic closing in accordance with the requirements of the applicable edition of NFPA 80. Fire doors which are not self-closing and which protect openings in horizontal exits, exits, or exit access corridors required to be of fire resistance rated construction shall be automatic-closing by the actuation of smoke detectors or by loss of power to the smoke detector or the hold-open device. Part 175/185 only: Where doors are required to be self-closing such as in opening protectives in enclosures for vertical openings, horizontal exits, limiting wall of open plan buildings, and smoke-stop partitions approved self-closing devices shall be used while the building is occupied or shall be arranged to be automatic-closing upon actuation of the building's fire alarm system.

Comments

Inspector Comments

Room 132 - A desk was being used as a hold open device. There were also a few doors in the building with door wedges. Please remove.

District Responses

Response by Curtis Saindon on 10/02/2026

We spoke with the teacher in Room 132 and confirmed with her that manual hold open devices are not allowed for fire code reasons and especially ones that might create egress concerns and/or partially block the doorway. We also made a general announcement to the entire staff that door wedges and any type of manual hold open devices are not allowed. Only integrated/hard wired hold open devices that are tied in to our fire alarm system are allowed.

Add Response

Unobstructed Exits

Passed: No

Safe, reliable and unobstructed means of access travel shall be provided from any location in an occupied room or space to the doorways required as either a part of an exit or which provide a path of travel from a room or space to an exit. Unlatching of doors shall not take more than one motion. Any additional locking devices that impede opening of doors are not permitted. [See Appendix N for more information]

Comments

Inspector Comments

Room 119 - Small moveable barricade obstructing exit out of classroom door. Please address. Music hallway - A few instruments need to be moved to maintain proper egress in the hall. Maintain proper egress near Door 16.

District Responses

Response by Curtis Saindon on 10/02/2026

We reiterated to the entire staff, as well as specifically to the teacher in Room 119 and the Music Teacher in the Music Hallway, that any and all obstructions (barricades, desks, chairs, musical instruments, bookcases, carts, etc.) to doorways, exits or in hallways that limit or inhibit proper egress, are not allowed for reasons of safety and fire codes. We moved/removed all items inhibiting egress that we saw and spoke directly with the staff members involved to ensure that they understood that such items are not allowed if they create a safety hazard and/or inhibit egress in the event of a need to evacuate the building. All staff agreed and understood this directive.

Add Response

Clearance Above Storage

Passed: No

Storage shall be maintained 2 ft or more below the ceiling in nonsprinklered areas of a building. The clearance between the sprinkler deflector and the top of storage shall be 18 in or greater. If special sprinkler heads are used, (which is not common in educational occupancies) such as ESFR and Large Drop sprinklers the clearance between the sprinkler deflector and the top of storage shall be 36 in. [See Appendix M]

Comments

Inspector Comments

Room 104 - Maintain clearance above storage.

District Responses

Response by Curtis Saindon on 10/02/2026

We removed/relocated the items being stored up near the ceiling and informed the Teacher in Room 104 that at least an 18 inch clearance needs to be maintained to remain in compliance with fire codes. She acknowledged our request and understood the directive.

Add Response

Housekeeping

Passed: No

The boiler room shall be kept free of all material and equipment not necessary to the operations of the heating system. IFC only: Combustible storage of any kind is not permitted in boiler rooms.

Comments

Inspector Comments

Some general housekeeping is needed.

District Responses

Response by Curtis Saindon on 10/02/2026

We cleaned up the Boiler Room and will work with the Custodian going froward to ensure that this area remains clean and organized.