External

Damien,

The pricing for replacing these two HPs is $71,500.00. Attached would be the HPs priced up.

This Includes:

- Reconnecting the ductwork with new.
- Reconnecting the piping with new.
- 2 Daikin FCUs
- Misc hangers, fasteners, sealants
- Temp Control
- Duct and Pipe Insulation
- Test & Balance
- Startup

Excluded:

- Electrical work

On the piping work the pricing was based on the assumption that the units can be isolated properly instead of draining a whole section of the building. If extensive draining is needed, pricing will need to be revised.

Any questions please let me know.

Thank you,
Adam