Holt Cat Truck Center
5033 US-271
Tyler, TX 75708

Prepared By: Dustin Christopher
Date: 2/2/2026
Work Order #:

PHONE #:

Estimate

Name Henderson ISD
Address
City State Zip
Phone 903-646-5588

Customer No
Contact Attn: Tom & Sam
Model:
Serial No

Description of Repair

Retrofit seats for 3 point seat belts

Qty	Part No:	Description	Labor:	Parts Unit Price:	Parts Ext. Price:
39		Seat back		640.00	24,960.00
1		**Labor to retrofit**	12,500.00		
1		Freight		3,000.00	3,000.00
		****** If subfloor is damaged there will be**			
		additional parts and labor of est $10,000 or			
		more ***			
		*** Tax not included in total***			

TOTAL PARTS: 27,960.00

litional needed repairs are found at which time an additional estimate will be provided. Also Estimate does n

TOTAL LABOR: 12,500.00

TOTAL: $40,460.00

Customer Signature _____