

MAINTENANCE REPORT SEPTEMBER 2026

Submitted by: Reid Reagan

Maintenance staff has been preparing for winter, cleaning strainer, replacing filters of the heat systems, winterizing the sprinkler systems, by blowing out water lines with air and remove all tanks, pumps.

BHS:

Pick rock, mow grass, fill-in holes, regrade and compact soils on x-country course. Repair broken stall doors (2) in the boys restroom at Sportsplex. Install speed bumps at the cross-walk areas.

BMS:

Replace water supply line to ice machine in the concession stand, clean up water, hydrovac carpet, and set up fans to dry carpet out, service restored. Install new washer/dryer in 8th grade pod.

BULLSHOE-KWB:

Replace faulty solenoid to the dishwasher, service restored. Install speed bumps at the cross-walk area.

BULLSHOE-VC:

Replace faulty controller, blower motor, service restored. Install speed bumps at the cross-walk area.

BABB:

Recharge the refrigerant in the kitchen cooler, service restored. Replace flame sensor and clean heat exchanger on Boiler.

NAPI:

Drain water lines, replace bursted pipes in the women's restroom of the football field. Paint lines on football field for Napi and BMS football teams to practice on. Install speed bumps at the cross-walk area.

ADMIN:

Install new dishwasher in the board room.