MAINTENANCE REPORT
OCTOBER 2026

Submitted by: Reid Reagan

Maintenance assist with traffic control for the Homecoming activities. Inspect the School's facilities trees and delimb the dead branches, winterize the lawns by spreading winterguard weed and feed.

BHS:
Reprogram new FACP (fire alarm control panel) service restored. Replace burnt out lights in the gym upper bleacher areas.

BES:
Snake plugged sewer drain, removed wipes, service restored.

BULLSHOE:
Assist in the whole school evacuation/reunification drill.

NAPI:
Replace faulty flame sensor to hot water heater, service restored. Replace faulty heat elements (2) Napi apartments, service restored.

ANNEX/DAYCARE:
Replace power supply to the FACP (fire alarm control panel) service restored.

FOOD DISTRIBUTION CENTER:
Install new security gate at the cattle guard, leaving Hwy 89 west.

BUS GARAGE:
Replace burnt out lights in bus barn and exterior building lights, service restored.

BABB:
Replace flame sensors, clean out heat exchanger, fire-tubes of the Lochinvar boilers. Recharge kitchen cooler with refrigerant, service restored.