



Lincolnshire-Prairie View School District 103

Memo

To: Board of Education
 From: Anthony Mendoza, CDPT
 CC: Dr. Katie Reynolds
 Date: October 20, 2026
 Re: Transportation Snapshot

October 2026					
Planned Staff		Hired Staff - Breakdown			
Title	# of Positions Planned	# of Certified Staff	# of Spare Drivers	# of Drivers in Training	Total Hired Staff
Bus Drivers	32	26*	3	2	31
Monitors	7	6	0	0	6
Van Drivers	3	2	0	0	2

Routes					Open Route Coverage				
Type of Route	# of Total Routes		# of Routes Covered	Open Routes	# routes needing coverage		# of positions outsourced	# of positions needing coverage	Notes
School Bus	28	-	25	= 3	3	-	1	= 2	Covered by First Student/ 2 internally
Monitors	7	-	6	= 1	1	-	0	= 1	Covered internally
Van	3	-	2	= 1	1	-	1	= 0	Covered by TopLine

- *We have 26 certified drivers hired, but 25 routes covered. One driver is on leave.
- One trainee tests 10/19. The other trainee came to us already certified and should be released from training the week of October 26th.



Fleet Maintenance Update

BUS	BUS DOWN	ISSUE	NOTES
2705		Aggressive creaking noise under driver's seat. plywood trim	Parts arrived
26		Rear AC condenser fan still blowing; circuit breaker fan breaker on here	@ Central State
11		Seat belt in seat 13 and 22 locked fully extended; will get these ordered	
7		ABS light staying on. Front Right abs sensor/ tone ring	
7		ABS light came on again.	
2706		Neither the backup camera nor front camera work. Yellow "Service Engine Soon" light on. The letters on the shifter keep turning to **, and the intercom is unusable because of a screeching noise.	
2701	X	Battery Critical Fault	High voltage battery needs replaced. 3-4 week wait.