

MAINTENANCE REPORT  
NOVEMBER 2020

Submitted by: Reid Reagan

Maintenance staff has been installing walk thru temperature check stations with fever temperature detection at the buildings. Measuring air handlers in each building for installation of UV Germicidal Irradiated lamps, improving indoor air quality and kills 99.9% bacteria, mold, viruses by sterilization.

HIGH SCHOOL:

Painting the floors in the shop areas, also the doors in the VO-AG and gym areas.

BES:

Replaced faulty 5" couplers, causing leak in the boiler room. Replaced faulty coil contactor to the roof unit which supplies the cooler in the kitchen.

BMS:

Replaced 2 faulty actuators to Air Handlers 2&3 old/existing building, reason for the cold/hot offices.

VC:

Replaced faulty defrost switch to the freezer in kitchen.