

Sheridan School District 48J

Facility Survey

Final Results

- 1 B. SHS Classroom Heating Systems updated or replaced
- 2 G. FCS & SHS safety and access issues (e.g. buzz-in doors, handicapped access door)
- 3 A. SHS main Restrooms and Plumbing
- _4_E. SHS Window replacement and wall structural changes to reduce the number of windows
- 5 C. FCS Old Gym Heating System Upgraded
- 6 J. District Technology (networking server upgrades, VOIP Phone System and wireless internet)
- _7_I. SHS Shop Classroom (Ventilation & Air Filtration, Heating, and project & storage spaced added)
- 8 D. SHS Stadium Roof Repaired and Stadium Lights replaced
- 9 H. SHS Track Re-surfaced and add Pole Vault & Javelin area
- 10 F. FCS add a Garbage Pad on the Wes side to manage garbage collection and security



