

Baseball Bleachers

Quote to repair Bleachers - \$ 25,459

↳ Service - 340

\$ 25,799

Cost to replace -

4 Row - 21' Long 56 Spectator Bench → 4,000 \$
x2 - 8,000 \$

4-Row - 12' Long 20 Spectator Bench \$ 2,300

x2
4,600

\$ 12,600

Concrete 20' x 60' → \$ 9,000

\$ 21,600

* No Future inspections or Rails Needed
on a 4 Row Bench style Bleacher *



BLEACHERS

a proud brand of **FacilServ**

Service & Repair Order Sheet

Facility Indoor & Outdoor Service & Repair Order Sheet

√ the end column for Services you would like completed

Report #	Facility Area	Work to be performed	Price	√
24-18305	Boyceville ES, Main Gym	General service, check, adjust and tighten	\$ 1,249	
		Add BR 48" seat level aisle system with "P" handrails for safer egress <i>Note: Does not reduce step rise below 8" to meet egress code. Recommend (1) aisle minimum per bank.</i>	\$ 2,300ea.	
		Code: Install (16) BR Self-Storing End Rails and (4) BR Top Row Corner Fillers to meet required* rail gap codes	\$ 4,590	
		Service and Inspection: (6) backstops, (1) divider curtain	\$ 2,240	
		*Install (2) basketball backstop safety straps on retractable backstops	\$ 1,500	
24-18315	Boyceville MS, Main Gym	General service, check, adjust and tighten	\$ 1,249	
		Service and Inspection: (6) backstops	\$ 1,840	
24-18320	Boyceville HS, Main Gym	General service, check, adjust and tighten	\$ 3,053	
		Service and Inspection: (6) backstops, (1) divider curtain	\$ 2,240	
24-18310	Tiffany Creek ES, Softball	General service, check, adjust and tighten	\$ 170	
		Code: Upgrades to double the walk boards, add risers, and replace side- and rear-guard rails to meet rail system gap and height codes, deck gap code	\$ 13,656	
24-18325	Boyceville MSHS, Football Home	General service, check, adjust and tighten	\$ 2,016	
		Code: Install (19) 1x8 risers and (14) 1x6 risers to meet ramp rail and deck gap codes <i>*Ramp rails need horizontal 2x4/2x6 runners to close the rail gaps to less than 4" to be done by others.</i>	\$ 64,951**	
24-18330	Boyceville MSHS, Baseball	General service, check, adjust and tighten	\$ 340	
		Code: Upgrades to double the walk boards, add risers, and replace side- and rear-guard rails to meet rail system gap and height codes, deck gap code	\$ 25,459**	
		+ Standard BR Bleachers AE Lift Charge	\$300/day*	
		+ Multiple lifts, specialized lift, and/or equipment floor protection	TBD	
		+ Mandatory Service Fee	\$ 795	√
TOTAL SERVICE & REPAIR*				

Continue next page

Softball Field

Quote to Repair BR Bleachers → 13,656

↳ Service - 170

13,916

Cost to Replace →

4 Row 21' Long 56 Spectator Bench 4,000
x2 = 8,000

4 Row 12' Long 20 Spect Bench 2,300

\$ 10,300



BLEACHERS

a proud brand of FaciliServ

Service & Repair Order Sheet

Facility Indoor & Outdoor Service & Repair Order Sheet

V the end column for Services you would like completed

Report #	Facility	Area	Work to be performed	Price	V
24-18305	Boyceville ES,	Main Gym	General service, check, adjust and tighten	\$ 1,249	
			Add BR 48" seat level aisle system with "P" handrails for safer egress <i>Note: Does not reduce step rise below 8" to meet egress code. Recommend (1) aisle minimum per bank.</i>	\$ 2,300ea.	
			Code: Install (16) BR Self-Storing End Rails and (4) BR Top Row Corner Fillers to meet required* rail gap codes	\$ 4,590	
			Service and Inspection: (6) backstops, (1) divider curtain	\$ 2,240	
			*Install (2) basketball backstop safety straps on retractable backstops	\$ 1,500	
24-18315	Boyceville MS,	Main Gym	General service, check, adjust and tighten	\$ 1,249	
			Service and Inspection: (6) backstops	\$ 1,840	
24-18320	Boyceville HS,	Main Gym	General service, check, adjust and tighten	\$ 3,053	
			Service and Inspection: (6) backstops, (1) divider curtain	\$ 2,240	
24-18310	Tiffany Creek ES,	Softball	General service, check, adjust and tighten	\$ 170	
			Code: Upgrades to double the walkboards, add risers, and replace side and rear guard rails to meet rail system gap and height codes, deck gap code	\$ 19,656	
24-18325	Boyceville MSHS,	Football Home	General service, check, adjust and tighten	\$ 2,016	
			Code: Install (19) 1x8 risers and (11) 1x6 risers to meet ramp rail and deck gap codes <i>Ramp rails need horizontal 2x4/2x6 runners to close the rail gaps to less than 4/8" to be done by others.</i>	\$ 64,951**	
24-18330	Boyceville MSHS,	Baseball	General service, check, adjust and tighten	\$ 840	
			Code: Upgrades to double the walkboards, add risers, and replace side and rear guard rails to meet rail system gap and height codes, deck gap code	\$ 25,459	
			+ Standard BR Bleachers AE Lift Charge	\$300/day*	
			+ Multiple lifts, specialized lift, and/or equipment floor protection	TBD	
			+ Mandatory Service Fee	\$ 795	√
TOTAL SERVICE & REPAIR*					

Continue next page

HS Track / Football Bleachers:

↳ quote from BR Bleachers \$ 64,951
service → 2,016

* Copy of Quote * \$ 66,967

↳ Cost For Maint Staff to Complete

Aluminum - \$ 8,000

Handrails - 5,000

Anchors / Bolts - 1,200

Aluminum Chop Saw - 500

\$ 14,700

Save \$ 52,000



BLEACHERS

a proud brand of **FacilServ**

Service & Repair Order Sheet

Facility Indoor & Outdoor Service & Repair Order Sheet

√ the end column for Services you would like completed

Report #	Facility Area	Work to be performed	Price	√
24-18305	Boyceville ES, Main Gym	General service, check, adjust and tighten	\$ 1,249	
	Add BR 48" seat level aisle system with "P" handrails for safer egress <i>Note: Does not reduce step rise below 8" to meet egress code. Recommend (1) aisle minimum per bank.</i>		\$ 2,300ea.	
	Code: Install (16) BR Self-Storing End Rails and (4) BR Top Row Corner Fillers to meet required* rail gap codes		\$ 4,590	
	Service and Inspection: (6) backstops, (1) divider curtain		\$ 2,240	
	*Install (2) basketball backstop safety straps on retractable backstops		\$ 1,500	
24-18315	Boyceville MS, Main Gym	General service, check, adjust and tighten	\$ 1,249	
	Service and Inspection: (6) backstops		\$ 1,840	
24-18320	Boyceville HS, Main Gym	General service, check, adjust and tighten	\$ 3,053	
	Service and Inspection: (6) backstops, (1) divider curtain		\$ 2,240	
24-18310	Tiffany Creek ES, Softball	General service, check, adjust and tighten	\$ 170	
	Code: Upgrades to double the walk boards, add risers, and replace side- and rear-guard rails to meet rail system gap and height codes, deck gap code		\$ 13,656**	
24-18325	Boyceville MSHS, Football Home	General service, check, adjust and tighten	\$ 2,016	
	Code: Install (19) 1x8 risers and (11) 1x6 risers to meet ramp rail and deck gap codes <i>*Ramp rails need horizontal 2x4/2x6 runners to close the rail gaps to less than 4" to be done by others</i>		\$ 64,951**	
24-18330	Boyceville MSHS, Baseball	General service, check, adjust and tighten	\$ 340	
	Code: Upgrades to double the walk boards, add risers, and replace side- and rear-guard rails to meet rail system gap and height codes, deck gap code		\$ 25,459**	
	+ Standard BR Bleachers AE Lift Charge		\$300/day*	
	+ Multiple lifts, specialized lift, and/or equipment floor protection		TBD	
	+ Mandatory Service Fee		\$ 795	√
	TOTAL SERVICE & REPAIR*			

Continue next page