

## Mid-Valley Special Education Cooperative

Dr. Carla Cumblad, Executive Director 1304 Ronzheimer Avenue St. Charles, IL 60174

Phone: 331-228-4873 Fax: 331-228-4874

MEMO TO:

**Executive Advisory Board** 

FROM:

Nancy Sporer

Director of Business & Human Resources

DATE:

May 7, 2014

RE:

5 YEAR CAPITAL IMPROVEMENT PLAN UPDATE

Attached for your review is the updated 5-year Capital Improvement Plan developed by ATS&R (D303 architect firm).

The proposed budget for FY15 includes an amount of \$61,444 for the following projects:

1. Add 3 tall cabinets with doors and locks in MJC conference rooms

\$ 4,921

2. Add 5 base cabinets with doors and 3 tall cabinets with doors in Art room

6,523

3. Replace MJC gym (multi-purpose) rooftop unit

-gas and cooling

**TOTAL** 

\*In the 5 year capital plan, we were given estimates of \$68,315 for a heating unit and \$17,050 for a cooling unit for a total of \$85,365. We have since found out that the replacement will cost under \$50,000, so the budget of the building projects has been reduced by \$35,365. A more thorough explanation follows:

We wanted to get more of an idea of the cost of replacing the rooftop unit so three companies provided us with preliminary quotes. They all stated that replacing the current unit with heat and air would result in just one unit not two so the estimates we received are not separated by a heating unit and cooling unit. We did find out that all of the estimates came in under \$50,000 so we should not have to go out to bid. These are the estimates we received:

Haves Mechanical:

\$23,111

DuPue Mechanical:

\$26,993

Mechanical Air:

\$45,000

Because of the wide range of estimates received, we then had ATS&R develop a request for quotes with specific parameters for the replacement of the rooftop unit. We received the parameters from ATS&R late last week.

So far we have not planned for the replacement of the MJC roof. It was installed in 2000 and when ATS&R developed our 5 year capital plan in 2013, it was noted that the roof has a 20 year life and it was not listed as a priority on our capital improvement plan. Since September we have had many leaks from our roof and so far they have all been repaired with the most recent repairs completed last week. Due to the deterioration of the roof, D303 is arranging a roof evaluation to be done in early June and we will report this information to you after we receive it.

	Ful	Droinet	Individual			
Fund	Fnl. <u>Pr.</u>	Project Year	Building	Project Category	Description of Work	Amount
71						
CF	1	2014	Mades	Storm / Drainage	Admin - Repair grade at 2 downspouts due to	\$ 687
			Johnstone	_	eroslon 2 ea	
CF	1	2014	Mades Johnstone	Doors / Hardware / Windows	MJC-Replace wire glass door lites with tempered glass 86 sf	\$ 2,174
CF	1	2014	Mades Johnstone	Doors / Hardware / Windows	MJC-Replace one way non-tempered glass with one- way tempered glass at observation rooms (6 thus)	\$ 2,403
CF	1	2014	Mades	Doors / Hardware /	96 sf MJC-Replace wire glass at Main Office frame with	\$ 1,716
			Johnstone	Windows	tempered glass 74 sf	
CF	1	2014	Mades Johnstone	Doors / Hardware / Windows	MJC-Remove sliding glass window at Main Office, provide fixed tempered glass 12 sf	\$ 572
CF	1	2014	Mades Johnstone	Doors / Hardware / Windows	MJC-Provide new Time Out Room doors with electromagnetic locks 2 ea	\$ 6,523
CF	1	2014	Mades	Cabinetry	MJC- Replace deteriorated plam countertops,	\$ 969 6,294
CF	1	2014	Johnstone Mades	Cabinetry	remove and reinstall sinks, 6 locations 46 if Add 12 LF of 7'H x 3'W x 2'D tall storage cabinets in	\$4,921
CF	1	2014	Johnstone Mades	Cabinetry	Conference Room 12 if Add 8 LF of wail and base cabs, and 6 LF of tall	s/8/06,523
			Johnstone	•	storage cabs. In Art Room 14 If	*(\$0 ) {
CF	1	2014	Mades Johnstone	Restroom Partitions	MJC- Replace deteriorated metal toilet partitions in Girls toilet room (3 stalls) 3 ea	\$ 21 JU4,011
CF	1	2014	Mades Johnstone	Energy Management Systems	MJC-Provide Boiler Fall Alarms 1 Is	\$ 5,149
CF	1	2014	Mades	Roof top units - DX / Split	MJC-Replace gym rooftop unit - unit required	\$ 68,315
			Johnstone	(heat / fan / filters) / Spot coolers	maintenance winter of 2013/14 1 is	+
CF	1	2014	Mades Johnstone	Roof top units - DX / Split (heat / fan / fillers) / Spot coolers	MJC-Add cooling to new gym rooftop unit 1 is	\$ 17,050
CF	1	2014	Mades	Pumps - condensing, hot	MJC-Replace (2) hot water pumps in Boiler Room 1	\$ 8,582
			Johnstone	water, chilled water, circulation, fuel oil	ls	
CF	1	2014	Mades Johnstone	Fire suppression-	Provide cover on smoke detector in TimeOut room 1 is	\$ 114
CF	1	2014	Mades	Electric panels -	Provide electrical and data to conference room table	\$ 801
			Johnstone	distribution / labeling	via an overfloor raceway system 1 ls SUB_TOTAL	\$ 136,402
2 CF	2	2014	Mades	Flooring / Ceiling	Carpet replacement in 1975 building corridors 2000	\$ 16,364
			Johnstone	•	sf Shelby-Provide vertical platform lift (handlcap lift) at	
CF	2	2014	Mades Johnstone	REMODELING	stairs to main level 1 is	
CF	2	2014	Mades Johnstone	Intrusion Detection	MJC / Admin-Provide security/surveillance system at MJC entry and corridor security cameras (15+/-) with	\$ 54,469
					monitoring at both MJC and Admin. offices - By Owner 1 is	
					SUBITOTAL	\$ 107,909
× 650000000			Madaa	Doors / Hardware /	Admin-Provide manual door holder at offices,	\$ 2,632
CF	3	2014	Mades			
	3	2014	Johnstone	Windows	conference room, work room and interior lounge	
	3	2014	Johnstone Mades		door 13 ea Add book cases/shelves in various rooms - By	\$ -
CF			Johnstone	Windows	door 13 ea	\$ - \$ 256,097
CF CF	3	2014 2014	Johnstone Mades Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 is	\$ 256,097
OF OF OF	3 3 3	2014 2014 2014	Johnstone  Mades Johnstone Mades Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Air handler units / ERU - dampers	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 is MJC-Replace AHU 2 serving south half of 1975 building 1 is	\$ 256,097 \$ 256,097
CF CF	3	2014 2014	Johnstone Mades Johnstone Mades Johnstone Mades	Windows  Cabinetry  Air handler units / ERU - dampers Air handler units / ERU -	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 is MJC-Replace AHU 2 serving south half of 1975	\$ 256,097 \$ 256,097
OF OF OF	3 3 3	2014 2014 2014	Johnstone Mades Johnstone Mades Johnstone Mades Johnstone Mades Johnstone Mades Mades	Windows  Cabinetry  Air handler units / ERU - dampers Air handler units / ERU - dampers Air handler units / ERU - dampers Air handler units / ERU -	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping &	\$ 256,097 \$ 256,097 \$ 256,097
OF OF OF OF	3 3 3	2014 2014 2014 2014	Johnstone  Mades Johnstone Mades Johnstone Mades Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers /	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump	\$ 256,097 \$ 256,097 \$ 256,097
OF OF OF OF OF	3 3 3 3	2014 2014 2014 2014 2014	Johnstone  Mades Johnstone Mades Johnstone Mades Johnstone Mades Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 Is MJC-Replace AHU 2 serving south half of 1975 building 1 Is MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 Is MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 Is	\$ 256,097 \$ 256,097 \$ 256,097
OF OF OF OF OF	3 3 3 3	2014 2014 2014 2014 2014	Johnstone Mades	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels -	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coits associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coits associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097
OF OF OF OF OF	3 3 3 3 3	2014 2014 2014 2014 2014 2014	Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and ejectrical feeders to accommodate	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097
OF OF OF OF OF OF	3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014	Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667
CF CF CF CF CF	3 3 3 3 3	2014 2014 2014 2014 2014 2014	Johnstone Mades	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators / battery backup systems /	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 Is MJC-Replace AHU 2 serving south half of 1975 building 1 Is MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 Is MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 Is MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 Is MJC-Replace water heater & recirculating pump (installed in 1998) 1 Is  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 Is  MJC/Admin-Replace existing battery backup lighting units and provide LED units in their place for energy	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667
OF OF OF OF OF OF	3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014	Johnstone Mades Mades Mades Mades Mades Mades Mades Mades	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators /	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls  MJC/Admin-Replace existing battery backup lighting	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667 \$ 68,315
OF OF OF OF OF OF	3 3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014	Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators / battery backup systems / Inverters	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls  MJC/Admin-Replace existing battery backup lighting units and provide LED units In their place for energy effeciency 30 ea MJC-Some existing fluorescent lighting units appear to be T12 lamps and are in poor condition. Replace	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667 \$ 68,315
OF OF OF OF OF OF	3 3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014	Johnstone Mades Mades Johnstone Mades Mades Mades Mades Mades Mades Mades Mades Mades	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators / battery backup systems / Inverters Lighting - Lamps /	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls  MJC/Admin-Replace existing battery backup lighting units and provide LED units in their place for energy effeciency 30 ea MJC-Some existing fluorescent lighting units appear	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667 \$ 68,315
CF CF CF CF CF CF	3 3 3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014 2014	Johnstone Mades Johnstone  Mades Johnstone  Mades Johnstone  Mades Johnstone  Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controliers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators / battery backup systems / Inverters Lighting - Lamps / ballasts / controls  ADDITIONS	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls  MJC-Admin-Replace existing battery backup lighting units and provide LED units in their place for energy effeciency 30 ea MJC-Some existing fluorescent lighting units appear to be T12 lamps and are in poor condition. Replace with energy efficient T8 lamps. 80 ea 2 classroom addition at north end of Administration wing (2,500 SF Adtn.) 2500 sf	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667 \$ 68,315 \$ 9,040 \$ 20,483 \$ 786,372
CF CF CF CF	3 3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014 2014	Johnstone Mades Johnstone	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controllers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators / battery backup systems / Inverters Lighting - Lamps / ballasts / controls	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 1s MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 1s MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls MJC/Admin-Replace existing battery backup lighting units and provide LED units in their place for energy effeciency 30 ea MJC-Some existing fluorescent lighting units appear to be T12 lamps and are in poor condition. Replace with energy efficient T8 lamps. 80 ea 2 classroom addition at north end of Administration wing (2,500 SF Adtn.) 2500 sf 2 classroom addition at NW corner of 1975 wing; extend conditor through tollet/observation rooms.	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667 \$ 68,315 \$ 9,040 \$ 20,483
CF CF CF CF CF CF	3 3 3 3 3 3 3	2014 2014 2014 2014 2014 2014 2014 2014	Johnstone Mades	Windows  Cabinetry  Air handler units / ERU - dampers Motors / controliers / pumps / systems / VFDs and electrical feeders to accommodate Electric panels - distribution / labeling  Emergency generators / battery backup systems / Inverters Lighting - Lamps / ballasts / controls  ADDITIONS	door 13 ea Add book cases/shelves in various rooms - By Owner MJC-Replace AHU 1 serving north half of 1975 building 1 ls MJC-Replace AHU 2 serving south half of 1975 building 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 1 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace condensing units, refrigerant piping & cooling coils associated with AHU 2 1 ls MJC-Replace water heater & recirculating pump (installed in 1998) 1 ls  MJC-The existing panelboards are approx. 38 years old with circuit breakers that are known to fail at that age. Replace original branch panelboards. 1 ls  MJC-Admin-Replace existing battery backup lighting units and provide LED units in their place for energy effeciency 30 ea MJC-Some existing fluorescent lighting units appear to be T12 lamps and are in poor condition. Replace with energy efficient T8 lamps. 80 ea 2 classroom addition at north end of Administration ving (2,500 SF Adm.) 2500 sf 2 classroom addition at NW corner of 1975 ving; extend coorldor through tollet/observation rooms. (2,500 SF Adm.) 250 SF Remodel) 2750 sf	\$ 256,097 \$ 256,097 \$ 256,097 \$ 256,097 \$ 7,667 \$ 68,315 \$ 9,040 \$ 20,483 \$ 786,372