| Site | Project | Reason the work is needed | Cost |
|----------------|---|---------------------------------------|----------|
| | | | |
| THS | Replace all HM windows with Storefront | Rusted frames and broken seals | \$31,882 |
| | | Pipe has collapsed under the | |
| Pierce St | Replace sanitary sewer line in the restroom | building slab. | \$23,880 |
| | | Security issue, the panels of the | |
| Fillmore | Replace Two Overhead doors | existing doors are not secure | \$2,220 |
| | | Books were fading and they were | . , |
| | | having trouble seeing the | |
| THS | Install Tint at Media | promethean board | \$1,757 |
| СО | Install new windows | broken seals | \$4,815 |
| | Add voicemail for each curriculum team member and add | | |
| HLC | lines | | \$1,100 |
| HLC | Furniture for curriculum department | | \$6,000 |
| СО | Dr. Dillon's furniture | | \$3,420 |
| | Frames for commemerative flags donated to all schools by | | |
| Misc | Woodmen of the World | | \$2,970 |
| HLC | Painting at HLC | Needs fresh coat of paint | \$4,225 |
| | | Play equipment is not age | |
| | | appropriate and both lower | |
| | | elementaries need additional | |
| | | equipment to serve their student | |
| Milam | Relocate playgrounds from Milam to Pierce and Lawhon | populations | \$12,692 |
| | | Carpet needs to be replaced and | |
| | | underneath is asbestos tile and | |
| Transportation | Asbestos Abatement Specs | adhesive | \$2,950 |
| Pierce St | Replace carpet in gym with rubber flooring | | \$25,434 |
| | | Safety. To control access into | |
| Rankin | Re-work Main Entrance | campus. | \$12,257 |
| | | | |
| | | Safety - replenish all playgrounds to | |
| | | ensure appropriate depth of fall | |
| Playgrounds | Mulch | material | \$10,500 |
| | | | |
| Milam | Re-Roof Two Story Classroom Bldg | Roof Leaks | \$50,000 |
| | , , | Safety. To control access into | . , |
| Lawhon | Buzzer for main door | campus. | \$2,000 |
| | | | |
| | | Need to rework head end due to | |
| THS | Intercom Repairs | constant issues with the system | \$15,240 |
| THS | Signage | way finding system | \$7,500 |
| Rankin | Replace fencing with vinyl chain link | Damaged | |
| THS | Replace four rooftop units | Due to age and dependability | \$38,200 |
| - | | Ceiling is crumbling and falling onto | |
| TMS | Repair and Paint Plaster Ceiling of Balcony at Civic Auditorium | seats below. | \$5,790 |
| | | | |
| | | Last year there were several | |
| | | accidents waiting in line b/c there | |
| Carver | Renovate R/Rs main floor | aren't enough toilets/urinals | \$49,856 |
| | | | |
| | | • | 1 |
| | | Have continuous trouble with these | |

| | | T | |
|-----------|---|-------------------------------------|----------|
| | | Parts of B Building appear to not | |
| 1 | | have been painted since | |
| | | construction (20 years)! Other | |
| | | parts were apparently painted with | |
| | | the wrong type of paint about four | |
| | | coats ago and most of the rooms | |
| | | on the first floor are constantly | |
| | | peelingThe lintels are rusted and | |
| | | really need new paint. The bridge | |
| | Paint B Building, Lintels at all porticos and Bridge and fascia | needs a fresh coat of paint as does | |
| THS | board and soffit of the north guard booth | the north guard booth. | \$43,240 |
| | | The entire exterior of Fillmore | |
| Fillmore | Paint exterior | Center needs painting | \$21,500 |
| Carver | Repair Flooring at principal's office | Painting | \$4,900 |
| Thomas St | Drainage | | \$30,000 |
| THS | Fencing at Maintenance Shop | | \$7,500 |
| Thomas St | Replaced Sewer line from the cafeteria to the street | | \$6,365 |