

Baseball Bleachers

Quote to repair Bleachers - \$ 25,459

↳ Service - 340

\$ 25,799

Cost to replace -

4 Row - 21' Long 56 Spectator Bench → 4,000 \$
x2 - 8,000 \$

4-Row - 12' Long 20 Spectator Bench \$ 2,300

x2
4,600

\$ 12,600

Concrete 20' x 60' → \$ 9,000

\$ 21,600

* No Future inspections or Rails Needed
on a 4 Row Bench style Bleacher *



BLEACHERS

a proud brand of **FacilServ**

Service & Repair Order Sheet

Facility Indoor & Outdoor Service & Repair Order Sheet

√ the end column for Services you would like completed

Report #	Facility Area	Work to be performed	Price	√
24-18305	Boyceville ES, Main Gym	General service, check, adjust and tighten	\$ 1,249	
	Add BR 48" seat level aisle system with "P" handrails for safer egress <i>Note: Does not reduce step rise below 8" to meet egress code. Recommend (1) aisle minimum per bank.</i>		\$ 2,300ea.	
	Code: Install (16) BR Self-Storing End Rails and (4) BR Top Row Corner Fillers to meet required* rail gap codes		\$ 4,590	
	Service and Inspection: (6) backstops, (1) divider curtain		\$ 2,240	
	*Install (2) basketball backstop safety straps on retractable backstops		\$ 1,500	
24-18315	Boyceville MS, Main Gym	General service, check, adjust and tighten	\$ 1,249	
	Service and Inspection: (6) backstops		\$ 1,840	
24-18320	Boyceville HS, Main Gym	General service, check, adjust and tighten	\$ 3,053	
	Service and Inspection: (6) backstops, (1) divider curtain		\$ 2,240	
24-18310	Tiffany Creek ES, Softball	General service, check, adjust and tighten	\$ 170	
	Code: Upgrades to double the walk boards, add risers, and replace side- and rear-guard rails to meet rail system gap and height codes, deck gap code		\$ 13,656	
24-18325	Boyceville MSHS, Football Home	General service, check, adjust and tighten	\$ 2,016	
	Code: Install (19) 1x8 risers and (14) 1x6 risers to meet ramp rail and deck gap codes <i>*Ramp rails need horizontal 2x4/2x6 runners to close the rail gaps to less than 4" to be done by others.</i>		\$ 64,951**	
24-18330	Boyceville MSHS, Baseball	General service, check, adjust and tighten	\$ 340	
	Code: Upgrades to double the walk boards, add risers, and replace side- and rear-guard rails to meet rail system gap and height codes, deck gap code		\$ 25,459**	
	+ Standard BR Bleachers AE Lift Charge		\$300/day*	
	+ Multiple lifts, specialized lift, and/or equipment floor protection		TBD	
	+ Mandatory Service Fee		\$ 795	√
TOTAL SERVICE & REPAIR*				

Continue next page