

Softball Field

Quote to Repair BR Bleachers → 13,656

↳ Service - 170

13,916

Cost to Replace →

4 Row 21' Long 56 Spectator Bench 4,000
x2 = 8,000

4 Row 12' Long 20 Spect Bench 2,300

\$ 10,300



BLEACHERS

a proud brand of **FaciliServ**

Service & Repair Order Sheet

Facility Indoor & Outdoor Service & Repair Order Sheet

V the end column for Services you would like completed

Report #	Facility	Area	Work to be performed	Price	V
24-18305	Boyceville ES,	Main Gym	General service, check, adjust and tighten	\$ 1,249	
			Add BR 48" seat level aisle system with "P" handrails for safer egress <i>Note: Does not reduce step rise below 8" to meet egress code. Recommend (1) aisle minimum per bank.</i>	\$ 2,300ea.	
			Code: Install (16) BR Self-Storing End Rails and (4) BR Top Row Corner Fillers to meet required* rail gap codes	\$ 4,590	
			Service and Inspection: (6) backstops, (1) divider curtain	\$ 2,240	
			*Install (2) basketball backstop safety straps on retractable backstops	\$ 1,500	
24-18315	Boyceville MS,	Main Gym	General service, check, adjust and tighten	\$ 1,249	
			Service and Inspection: (6) backstops	\$ 1,840	
24-18320	Boyceville HS,	Main Gym	General service, check, adjust and tighten	\$ 3,053	
			Service and Inspection: (6) backstops, (1) divider curtain	\$ 2,240	
24-18310	Tiffany Creek ES,	Softball	General service, check, adjust and tighten	\$ 170	
			Code: Upgrades to double the walkboards, add risers, and replace side and rear guard rails to meet rail system gap and height codes, deck gap code	\$ 19,656	
24-18325	Boyceville MSHS,	Football Home	General service, check, adjust and tighten	\$ 2,016	
			Code: Install (19) 1x8 risers and (11) 1x6 risers to meet ramp rail and deck gap codes <i>Ramp rails need horizontal 2x4/2x6 runners to close the rail gaps to less than 4" to be done by others.</i>	\$ 64,951**	
24-18330	Boyceville MSHS,	Baseball	General service, check, adjust and tighten	\$ 840	
			Code: Upgrades to double the walkboards, add risers, and replace side and rear guard rails to meet rail system gap and height codes, deck gap code	\$ 25,459	
			+ Standard BR Bleachers AE Lift Charge	\$300/day*	
			+ Multiple lifts, specialized lift, and/or equipment floor protection	TBD	
			+ Mandatory Service Fee	\$ 795	√
TOTAL SERVICE & REPAIR*					

Continue next page