

Transportation and Maintenance Report

Reports for September and October 2025

Transportation

1. Bus #50, replace blown air brake chamber.
2. Bus #50 replace shift selector lamps.
3. Bus #52, add 7.5 gallons of D.E.F.
4. Bus #54, replace wiper blades.
5. Bus #46, died in front of grade school. No start, diagnosed faulty body module; replaced.
6. Bus #46, codes for faulty turbo actuator, ordered parts.
7. Bus #46, replace tail lamp lenses.
8. Bus #46, repair broken wire on door actuator for stop arm function.
9. Bus #46, service transmission filter.
10. Bus #46 and #50, add D.E.F.
11. Bus #46, diagnose power loss to ignition, no start, found bad body control module, parts ordered.
12. Surplus buses #40 and #42 sold at auction. Picked up on 9-18-25.

Driftwood School

1. Put up projector screen in library.
2. Change water filter in drinking fountain, grade school wing.
3. Convert all gym lights to LED; repair all missing cage hardware.
4. All main hall lights converted to LED.
5. Adjust closing speed on entry doors at front of building and install district lock cylinders to match outside door keys.
6. Trim bushes in front of building; yard work.
7. Move shelves from library to Life Skills room and storage, build and place new shelves in library.

Pacific High School

1. Score board at soccer field installed.
2. Paint on south wall.
3. Re-side portion of wood shop's back wall, trim and caulk.
4. New shower heads in locker rooms.
5. Paint new siding and trim on wood shop wall.
6. Mowing at field and trimming.
7. Old cafeteria tables sold at auction.
8. Replace door on storage file container, caulk and paint.
9. Install new doors on each end of the Green House, trim and caulk.
10. Replace electric motor on aerator in primary lagoon.
11. Repair leak in fresh water line.
12. Track down crossover in hot water system main building.
13. Continue with grounds work, mowing and weed eating.
14. Repair door to bus garage.
15. Haul fencing materials from Langlois to PHS horticulture area.