

<b>REPAIR ORDER ID</b>	<b>76532757</b>	<b>AUTH NUMBER</b>	
<b>INVOICE NUMBER</b>	<b>103343</b>		

**SHOP INFORMATION**

<b>NAME</b>	Alpena Buick GMC, INC.
<b>ADDRESS</b>	133 Johnson Street Alpena MI 49707 USA
<b>PHONE</b>	9893569011
<b>RO OPENED</b>	7/24/2025
<b>VEHICLE READY</b>	Unknown

**VEHICLE INFORMATION**

<b>VIN</b>	1GNKVHKDXGJ118576
<b>FMC UNIT ID</b>	25GK24
<b>YEAR</b>	2016
<b>MAKE</b>	Chevrolet
<b>MODEL</b>	Traverse - LT w/2LT All-wheel Drive
<b>ODOMETER</b>	88193
<b>DRIVER NAME</b>	

**LINE ITEMS**

		hrs	\$/hr	Unit Cost	Qty	Total Cost
<b>Service Code</b>	Part - Power Steering Fluid Cooler			\$293.42	1.00	\$293.42
<b>Description</b>	Power Steering Fluid Cooler					
<b>Part Number</b>	22792865					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Labor - Power Steering Fluid Cooler	1.00	\$175.00	\$175.00	1	\$175.00
<b>Operation</b>	Replace					
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Tire Pressure Sensor			\$111.00	2.00	\$222.00
<b>Description</b>	Tire Pressure Sensor					
<b>Part Number</b>	13540600					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Labor - Tire Pressure Sensor	1.50	\$175.00	\$262.50	1	\$262.50
<b>Operation</b>	Replace					
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Full Synthetic Lube Oil Filter			\$44.95	1.00	\$44.95
<b>Description</b>	Full Synthetic Lube Oil Filter					
<b>Part Number</b>						
<b>Manufacturer</b>						
<b>Reason</b>	Preventative Maintenance					
<b>Service Code</b>	Labor - Full Synthetic Lube Oil Filter	0.20	\$145.00	\$29.00	1	\$29.00
<b>Operation</b>	Replace					
<b>Reason</b>	Preventative Maintenance					

		hrs	\$/hr	Unit Cost	Qty	Total Cost
<b>Service Code</b>	Labor - Diagnostics - HVAC	1.00	\$175.00	\$175.00	1	\$175.00
<b>Operation</b>	Diagnose/Test					
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Transmission Drain and Fill			\$11.82	1.00	\$11.82
<b>Description</b>	Fluid - A/T					
<b>Part Number</b>	88865601					
<b>Manufacturer</b>						
<b>Reason</b>	Preventative Maintenance					
<b>Service Code</b>	Labor - Transmission Drain and Fill	0.60	\$175.00	\$105.00	1	\$105.00
<b>Operation</b>	Replace					
<b>Reason</b>	Preventative Maintenance					
<b>Service Code</b>	Part - Refrigerant			\$23.27	2.00	\$46.54
<b>Description</b>	Refrigerant					
<b>Part Number</b>	12356150					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Labor - Air Conditioning Service	0.30	\$175.00	\$52.50	1	\$52.50
<b>Operation</b>	Evacuate/Recharge					
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Coupler HVAC			\$150.00	1.00	\$150.00
<b>Description</b>	Air Conditioning Service					
<b>Part Number</b>	BK29055					
<b>Manufacturer</b>						
<b>Reason</b>	AME Request					
<b>Service Code</b>	Labor - Coupler HVAC	3.30	\$145.00	\$478.50	1	\$478.50
<b>Operation</b>	Reseal					
<b>Reason</b>	AME Request					
<b>Service Code</b>	Part - Refrigerant			\$23.27	2.00	\$46.54
<b>Description</b>	Refrigerant					
<b>Part Number</b>	R134					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Labor Amount</b>						\$1,277.50
<b>Parts Amount</b>						\$815.27
<b>Fees Amount</b>						\$0.00
<b>Tires Amount</b>						\$0.00
<b>SUB TOTAL (exc. Tax)</b>						\$2,092.77
<b>TOTAL (inc. Tax)</b>						\$2,092.77

## REJECTED LINE ITEMS

		hrs	\$/hr	Unit Cost	Qty	Total Cost
<b>Service Code</b>	Part - Power Steering Pump			\$311.49	1.00	\$311.49
<b>Description</b>	Power Steering Pump					
<b>Part Number</b>	85112727					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Labor - Power Steering Pump	6.00	\$175.00	\$1,050.00	1	\$1,050.00
<b>Operation</b>	Replace					
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Evaporator Core			\$180.00	1.00	\$180.00
<b>Description</b>	Diagnostics - HVAC					
<b>Part Number</b>	84802280					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Labor - Evaporator Core	3.90	\$175.00	\$682.50	1	\$682.50
<b>Operation</b>	Diagnose/Test					
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Hose/Line HVAC			\$600.16	1.00	\$600.16
<b>Description</b>	Hose/Line HVAC					
<b>Part Number</b>	84590963					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					
<b>Service Code</b>	Part - Hose/Line HVAC			\$630.68	1.00	\$630.68
<b>Description</b>	Hose/Line HVAC					
<b>Part Number</b>	84590964					
<b>Manufacturer</b>						
<b>Reason</b>	Wear and Tear					