

## Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER Pana Community Unit School District No. 8	COUNTY Christian/Montgomery
FACILITY NAME Junior High School	FACILITY LOCATION 203 West 8th Street, Pana

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 12/14/2020 by Dean Keller.

**Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.**

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	At shop door closer needs adjustment. Broken doors closer in gym storage.
14	Administration and General	Stored items should be 24 inches below ceiling
23	Administration and General	Repair ceiling tile wood shop classroom.
24	Administration and General	Remove all extension cords and daisy chained surge protectors and multi plugs.
25	Administration and General	Stem lab needs gfi by sink. Hallway panels have open slots. Verify art room outlets are on gfi circuit.
131	Fire Escape Stairs	Fire escape should be tested.
176	Kitchens	Back door propped open
283	Storage/Supply/Closets	IT room has a non fire rated wall.



# Office of the State Fire Marshal

## INSPECTION REPORT

<b>Occupant Name:</b>	Pana Junior High School	<b>Inspection Date:</b>	12/14/2020
<b>Address:</b>	203 West 8th Street	<b>Occupant Number:</b>	341963-013-CE
<b>Structure Name:</b>		<b>InspectionType:</b>	Public School
<b>Suite:</b>		<b>Requested By:</b>	ISBE ROE 3
<b>City:</b>	PANA		
<b>State:</b>	IL		
<b>Zip Code:</b>	62557		
<b>Inspected By:</b>	Jeff Miller Office of the State Fire Marshal 1035 Stevenson Dr. Springfield, IL 62703-4259 Fax: 217/558-4992 217-993-2191	<b>Property Owner:</b>	217-562-1500 14 E. Main Pana IL 62557
<b>Important Info for Firefighters:</b>	1-Story, 310 Students, Grades 6, 7, 8; Built 1957 (Part 185), no sprinkler system; FACP located in Principal's office Occupancy loads: Auditorium 500 / Cafeteria 200 / Gym 1200 / Library 49		

Insp. Result	Location	Code Set	Code
--------------	----------	----------	------

<b>Fail</b>		Public School FY 21 (2020-2021) ADMINISTRATION and GENERAL BUILDING REQUIREMENTS	25 - Electrical Systems
-------------	--	--	-------------------------

**Inspector Comments:**  
25

REPEAT VIOLATION FROM 2/13/2019 INSPECTION REPORT:  
REPEAT VIOLATION FROM 10/20/2017 -  
ART ROOM - PROVIDE GFI PROTECTION NEAR ALL SINKS (NORTH SIDE)

REPEAT VIOLATION FROM 10/31/2019 INSPECTION REPORT:  
WOOD SHOP - OUTLETS HANGING FROM THE CEILING HAVE OPEN BACKS.  
KITCHEN - PROVIDE GFI PROTECTION AT SINK.  
CAFETERIA - PROVIDE GFI PROTECTION AT ICE MACHINE AND WATER COOLER.

NEW VIOLATIONS -  
1) STEM LAB - PROVIDE GFI PROTECTION AT THE SINK.  
2) HALLWAY ELECTRICAL PANEL BY LIBRARY - OPEN CIRCUITS IN THE ELECTRICAL PANEL.

(IFC: 605.1; BOCA-F: 310.1) All identified electrical hazards shall be abated.

<b>Fail</b>		Public School FY 21 (2020-2021) GYM AND MULTIPURPOSE ROOMS	143 - Maintenance of Fire-Rated Construction
-------------	--	---	---

**Inspector Comments:**  
REPEAT VIOLATION FROM 2/13/2019 INSPECTION REPORT:  
DOOR CLOSER IS BROKEN ON SOUTH GYM STORAGE ROOM.

(IFC: 703; BOCA-F: 303) Required fire-rated construction shall be maintained. [See Appendix O, P, or Q for requirements]

**Fail** Public School FY 21 (2020-2021) GH.Gen - Greenhouses - General  
GREENHOUSES

**Inspector Comments:**

REPEAT VIOLATION FROM 2/13/2019 INSPECTION REPORT:  
LABEL THE EMERGENCY GAS SHUT OFF IN THE GREENHOUSE.

This does not apply to the "greenhouse windows" commonly found in science laboratories that are installed as a window system. This applies to separate greenhouse buildings or rooms that are glass- or Plexiglas-enclosed permanent spaces with a controlled environment for growing plants, vegetables, and fruits out of season.

---

**Fail** Public School FY 21 (2020-2021) 161 - Maintenance of Fire-Rated  
INDUSTRIAL TECHNOLOGY LABS AND METAL Construction  
WORKING SHOPS

**Inspector Comments:**

REPEAT VIOLATION FROM 9/24/2015 -  
REPLACE MISSING DOOR CLOSER ON DOOR LOCATED BETWEEN THE WELDING SHOP AND  
CLASSROOM.

2020 - DOOR CLOSER HAS BEEN DAMAGED, STILL DOES NOT CLOSE.

(IFC: 703; BOCA-F: 303) Required fire-rated construction shall be maintained. [See Appendix O, P, or Q for requirements]

---

**Fail** Public School FY 21 (2020-2021) 176 - Maintenance of Fire-Rated  
KITCHENS Construction and Door Closers

**Inspector Comments:**

REPEAT VIOLATION FROM 9/24/2015 -  
KITCHEN ROLL DOWN DOORS DO NOT OPERATE PROPERLY, ARE NOT AUTOMATIC CLOSING.

NEW VIOLATION -  
REAR KITCHEN DOOR IS HELD OPEN.

(IFC: 703; BOCA-F: 303) Required fire-rated construction shall be maintained. [See Appendix O, P, or Q for requirements]

---

**Fail** Public School FY 21 (2020-2021) 198 - Maintenance of Fire-Rated  
MECHANICAL AND FURNACE ROOMS Construction and Door Closers

**Inspector Comments:**

REPEAT VIOLATION FROM 10/31/2019 INSPECTION REPORT:  
NEWLY INSTALLED GAS FURNACE IN OLD SHOWER ROOM, PROVIDE FIRE RATED CONSTRUCTION  
AROUND UNIT AND DETECTION.

(IFC: 703; BOCA-F: 303) Required fire-rated construction shall be maintained. [See Appendix O, P, or Q for requirements]

---

**Fail** Public School FY 21 (2020-2021) 301 - Maintenance of Fire-Rated  
TEACHERS' WORKROOMS AND LOUNGES Construction and Door Closers

**Inspector Comments:**

REPEAT VIOLATION FROM 2/13/2019 INSPECTION REPORT:  
TEACHERS LOUNGE TREAT WOOD DOOR CLOSURE WITH A FIRE RETARDANT PAINT.

(IFC: 703; BOCA-F: 303) If the teachers' lounge has any cooking or heating appliances the required fire-rated construction shall be maintained. [See Appendix O, P, or Q for requirements]

---

**Fail** Public School FY 21 (2020-2021) 23 - Interior Wall, Ceiling and Floor Finishes  
ADMINISTRATION and GENERAL BUILDING REQUIREMENTS

**Inspector Comments:**

DRAFTING CLASS - REPLACE CEILING TILE ABOVE DOOR.

Newly installed interior wall, ceiling, and floor finishes need to comply with the requirements found in Appendix L.

---

