

MAINTENANCE REPORT

JULY 2024

Submitted by: Reid Reagan

Maintenance staff has been busy filling summer work order requests throughout the buildings. Also mowing, trimming and watering lawns. Summit Fire performed annual inspection of the schools, consisting of fire sprinkler systems, kitchen hood suppression, fire extinguishers and alarms. Assist the Blackfeet Tribal Health with the unloading, cleaning, and set-up of the Operation Walking Shield medical clinic at BHS.

BHS:

Repair rollup door in VO-AG shop. Replace the damaged or missing fire sprinkler covers in the gym. Replace batteries in the Sportsplex outbuildings FACP.

BMS:

Made necessary corrections for State of Mt Safety Compliance Inspection. Repair the torn down chain link fence in the south playground area, result of pickup driving thru fence and tearing up the lawn and sandpit area.

BES:

Replace power supply to Fire Alarm Control Panel (FACP), delete old FACP service and switch entire building over to newer FACP service.

NAPI:

Repair roof drains, not attached to roof structure, install strapping to hold in place. Paint gym walls and bleachers.