

Transportation and Maintenance Report

February Meeting 2025

Driftwood School

1. Staff room and office area heater repairs; replaced condenser fans on rooftop unit.
2. Room 6 and north hall heater repairs; replace condenser fans and control board.
3. Merry-go-round repaired and put back into service.

Pacific High School

1. Replace door knob on I.T. office door
2. Replace restroom partition door latches.
3. Repair dead bolt on north end boys' restroom.
4. Replace laundry room clothes washer pump.

Transportation

1. Fill DEF Bus #54.
2. Bus #50, fill DEF, check loading handles for sharp edges.
3. Bus #46, fill DEF; check coolant leak and order parts.
4. Bus #44, check air leak, order parts.
5. Bus #52, replace clock spring in steering column and repair horn button assembly.
6. Bus #46, repair coolant leak, order pigtail wire harness for updated turbo charger.
7. Bus #46, replace broken hood latch.
8. Bus #46, replace headlamp, right side.
9. Bus #44, replace bulk head air line manifold, checked for leaks, no leaks.
10. Bus #44, stop arm repairs.
11. Bus #44, replace tail lamp bulb.
12. Clean gutters, bus barn parking area.

Waste Water

1. Work on permit renewal application; renewal issued.