AIA DOCUMENT	MANAGER-ADVISER EDITION G701/CM2 JAN 2 5 2011 0 6 2011	OWNER CONSTRUCTION MANAGER ARCHITECT CONTRACTOR FIELD OTHER	PCO # 121 BID # 1159
PROJECT: DE1	DENFELD HIGH SCHOOL 405 WEST 4TH STREET	CHANGE ORDER NO.:	0330-004
	LUTH, MINNESOTA 55807	INITIATION DATE:	12/28/10
TO CONTRACTOR:	NORTHLAND CONCRETE AND MASONRY 12026 RIVERWOOD DRIVE BURNSVILLE, MINNESOTA 55337	PROJECT NOS.:	0807-03
		CONTRACT FOR:	Contract #330 CIP Concrete Slabs
•		CONTRACT DATE:	8/31/09
The Contract is c	hanged as follows:		
Provide labor and	material as necessary to complete the work for RFG	CO-078 as noted on attached	page.
	DECEI	AEU	

N FEB 0 4 2011

I.S.D. #709 FACILITIES MGMT

Not valid until signed by the Owner, Construction Manager, Architect and Contractor.					
The original (Contract Sum): (Consumment Massissum Price) was Net change by previously authorized Change Orders The (Contract Sum) (Consumment Massissum Price) prior to this Change Order The (Contract Sum) (Consumment Maxissum Price) will be (increase this Change Order The new (Contract Sum): (Consumment Maxissum Price) including the Contract Time will be (increased): (also presented) (unchanged) by The date of Substantial Completion as of the date of this Change	nange Order was	\$ \$ \$ \$ \$ \$ \$ zero	372,370.00 24,466.00 396,836.00 54,051.00 450,887.00 (-0-) days unchanged.		
NOTE: This summary does not reflect changes in the Contract Sum, Conby Construction Change Directive.			ch have been authorized		
PROGRAM MANAGER: JOHNSON CONTROLS, INC.	ARCHITECT:	DSGW A	ARCHITECTS		
ADDRESS 21 North 1st Avenue East, Rm. 100, Duluth, MN 55802	ADDRESS 2 West First S	Street, Duluth, MN 5	5801		
BY: DATE: DA	BY: KELLY CK	DATE:	124111		
CONTRACTOR: NORTHLAND CONCRETE AND MASONRY, LLC	OWNER: INDEPEN	IDENT SCHOOL D	ISTRICT #709		
ADDRESS 12026 Riverwood Drive, Burnsville, MN 55337	ADDRESS 215 North 1st				
BY: The DATE: 1411	BY:	DATE:			



CAUTION: You should use an original AIA document which has this caution printed in red. An original assures that changes will not be obscured as may occur when documents are reproduced.