FACILITIES PRIORITY REPORT November 2024

Planned Maintenance		Planned Capital Projects		Planned Summer Inspections	
	Replace water heater (MES)	~	Clima-Tech (Mulino-South Building)	,	District Wide Fire Alarm Inspections
	Coat roofing seams on 6 th grade wing (MRMS)	~	Replace Front Siding (MHS)	•	Fire Door Drop Test
\ \	Clean lift stations (MES/MHS)	~	Replace Carpet (Mulino Offices)	~	District Wide Backflow Inspections
•	Tear down, clean and wash boilers 1 & 2 (MRMS)	•	Re-Roof Wrestling Room (MHS)	•	Fire Marshall 2 Year Inspection
	Repair and replace steam traps (MRMS)		Re-Roof Section C (MHS)	~	Elevator Inspection (MHS)
~	Tear down and inspect boilers (MHS- New Wing)		Replace Heating/AC Unit West Gym (Rural Dell)	V	Bleachers 2 Year Inspection
~	Run new wiring from well house to building (Rural Dell)				Asbestos 3 Year Inspection

<u>Vocab</u>

VSD = Variable Speed Drive

AHU = Air Handler Unit

RTU = Roof Top Unit

High School

- Troubleshot loose wire on boiler 1 (Not Firing)
- Replaced pump motor and bearing assembly on RTU 5
- Repaired faulty wire on east gym boiler
- Cleaned roof scuppers
- Patched roof leak above Clackamas Children's Room
- Replaced Climatech board on RTU 6

Middle School

- Replaced broken belt on AHU room 34
- Repaired leaking sink in girl's locker room
- Patched roof leak above library
- Replaced lockset on room 34
- Replaced lockset on fitness room door

MES

- Replaced drinking fountain in room 8
- Replaced ignition control module Earth Pod boiler
- Replaced gas valve on boiler
- Repaired door leaks above rooms 10 and 13
- Reattached boy's restroom stall door in 4th-5th Pod
- Replaced damper motor room 12

Mulino Elementary

- Troubleshot loose wire on Climatech control board
- Repaired plumbing under 3 compartment sink (kitchen)
- Replaced 4 heat detectors
- Replaced pilot burner on boiler

Rural Dell

- Purchased and installed new stand up freezer
- Replaced freezer in kitchen

- Replaced blower motor and relay switch on west gym unit
- Replaced blower motor on library unit
- Replaced thermostat in room 3

Clarkes

- Cleaned gutters and down spouts
- Patched roof leak above hallway
- Repaired door cylinder on front door (not locking)
- Replaced air filters in gym
- Repaired swing in ELC room
- Repaired faulty alarm bells and replaced heat detectors
- Replaced air filters on office unit

DO/PE Facility

• Replaced air filters on office unit

Land Lab

- Replaced gas valve on shop heating unit
- Replaced air filters

Completed District Wide Boiler Inspections