Maintenance & Operations Report 2024

Central Support Center

- Installed new security lighting on exterior of building
- Painted some of the offices
- Replaced carpet in office
- Removed dead trees and shrubs
- Repainted parking lot stripes

Coggin Elementary (Pre-K through 5th Grade)

- Removed old sink in three hundred hall
- Built new wall and installed new sinks and wall tile
- Painted parking lot stripes and curbs
- Built new concrete ramps on playground
- RPG backflow test
- Installed new swing sets

Coggin Elementary (6th Grade)

- Painted curbs and parking stripes
- Installed new security lighting on exterior of building
- RPG backflow test
- Gas test
- Removed dead trees

DAEP

- Replaced wood on entry ramps
- Replaced fencing and repaired gates
- Painted ramps and hand rails and installed security lights on building
- RPG backflow test
- Removed four storage buildings

Bus Barn

- Installed new washer and dryer
- Replaced water heater
- Painted break room and replaced ceiling tile
- Installed new lighting bus barn

East Elementary

- Painted curbs and parking spots
- RPG backflow test
- Painted walls and concrete on entry area
- Replaced down spouts on front of building
- Replaced gym floors

Middle School

- Painted curbs and parking spots
- New security lighting on exterior of building
- New security window in front office
- RPG backflow test
- Paint on exterior of building and hand rails
- Replaced four ton a/c unit and replaced 10 ton a/c unit

High School

- Replaced 5 ton a/c unit over 200 hall
- Replaced 5 ton a/c unit over 600 hall
- Painted curbs and parking spots
- RPG backflow test
- New paint in class rooms and hallways
- Repaired plumbing on green house
- Cut out floor in 200 hall bathroom and repaired sewer pipe
- New fence around electric panel on tennis courts

Northwest Elementary

- Replaced heat exchanger for room 203
- Replaced 5 ton compressor for front office
- Replaced heat exchanger for room 308
- Painted curbs and parking spots
- RPG backflow test
- Gas test
- Painted exterior of building and installed security lights on front of building
- New gym floors
- Replaced fire alarm panel

Woodland Heights

- Replaced a/c coil
- Painted curbs and parking spots
- Fixed drainage problem on back side walk
- Paint on exterior of building
- RPG backflow test
- New gym floors