

✓

**Harvey Public Schools District 152**  
**Department Of Buildings & Grounds**  
**Mr. Kreatha Lewis**  
January-February 2014

**Angelou**

- Boiler #2 Alarm & Lock out repaired
- Boiler #1 Leak in Low Pressure Pipe repaired
- Fire Alarm System currently 90% upgraded
- All Emergency Lights repaired or replaced
- Uninvents Coils & Actuators repaired in various classrooms

**Brooks**

- Boiler #1 Cooler, Coil and Air Compressor serviced
- Belt changed on Compressor #2 Oil Change scheduled
- New Actuator ordered for Boiler Room three way valve, south zone
- New Valves installed in Hallway Wash Basins
- Drapes removed for Flame Retardant Treatment
- Exit & Emergency Light installed in Weight room

**Bryant**

- No Boilers enabled on Metasys, Boilers running on Override Johnson Controls notified
- Multiple classrooms Reheat Coils adjusted manually
- Additional Heat Vents on order for Assistant Principals office
- New Snow blower purchased
- Elevator Inspection scheduled with Otis Elevator

**Holmes**

- New Coil installed for Gym Heat
- Basins & Ejector Pumps installed in Crawl Space
- Dedicated Electrical Lines installed in the Crawl Space
- Lights installed in the Crawl Space
- Multiple Uninvent Heat Dampers repaired
- Received quotes for 6 Steam Main repairs

**Lowell**

- Belts replaced, Oil & Filters changed on both Compressors
- Emergency Lights repaired & replaced

**Riley**

- Replaced Air compressor, Motor, and Motor Starter
- Adjusted uninvent dampers in multiple C.O. offices
- Installed Ejector Pump & Basin in Crawl Space
- Installed Dedicated Electrical Service to pump

**Harvey Public Schools District 152**  
**Department Of Buildings & Grounds**  
**Mr. Kreatha Lewis**

- Installed Lighting in Crawl Space
- Installed Fire Doors per South Cook ISC
- Installed Exit signs & Emergency lights
- Removed Blackboard & Paint future boardroom
- Removed Blackboard in Superintendents' secretary office
- Install new Flush Valves in bathrooms

**Sandburg**

- Leak found in Heat Coils, scheduled repairs during spring break
- Repaired & replaced Emergency lights

**Whittier**

- Boiler #1 locked out, repaired by Precision
- Boiler #2 Gas Valve Modulator
- Heat in various rooms Repaired
- Installing Fire Doors per South Cook ISC
- Installing Door Holders

**General**

- All Uniforms & Floor Mats on order
- Upgrade in Equipment & Vehicles in progress
- All Stage Drapes being removed for Fire Retardant Treatment
- Alarm/Burglary system being evaluated
- Storage Containers Purchased