


JOHN S. GRAVES & ASSOCIATES, INC.
ARCHITECTS



202 HORNBY PLACE
UVALDE, TEXAS 78801

Phone (830) 278-6677
Fax (830) 278-6679

**ARCHITECT'S
FIELD REPORT**

OWNER []
ARCHITECT [X]
CONSULTANT []
FIELD []

PROJECT: TRACK RENOVATIONS FOR BRACKETT I.S.D.
BRACKETT VILLE, TEXAS
CONTRACTOR: VIBRA-WHIRL LTD.
OWNER: BRACKETT I.S.D.

DATE: 11/30/06

TIME: 5:30 PM

PRESENT AT SITE: JOHN S. GRAVES, JR. - JOHN S. GRAVES & ASSOCIATES, INC.


- 1 Asphalt at added lanes installed, grading finished.
- 2 Clean up rocks around outside of track
- 3 Check discus area for even grade.
- 4 Note 12' driveway to concession on south side of tree line and septic lines on north side not to have sprinkler system. Coordinate septic location with concession contractor.
- 5 Check cracks at runway and patch corner where broken.

REPORT BY: _____

A handwritten signature in cursive script, appearing to read "John S. Graves, Jr.".

John S. Graves, Jr.

JOHN S. GRAVES & ASSOCIATES, INC.
ARCHITECTS



202 HORNBY PLACE
UVALDE, TEXAS 78801

Phone (830) 278-6677
Fax (830) 278-6679

**ARCHITECT'S
FIELD REPORT**

OWNER []
ARCHITECT [X]
CONSULTANT []
FIELD []

PROJECT: NEW CONCESSION BUILDING & TRACK RENOVATIONS FOR BRACKETT I.S.D
BRACKETT VILLE, TEXAS
CONTRACTOR: PIONEER CONCEPTS, LP
OWNER: BRACKETT I S D.

DATE: 11/30/06

TIME: 5:30 PM

PRESENT AT SITE: JOHN S. GRAVES, JR. - JOHN S. GRAVES & ASSOCIATES, INC.

- 1 Walls completed and roof framing almost complete.
- 2 Coordinate septic location with sprinkler system. Assume driveway to concession will be on south side of trees and septic system on north side of trees.

REPORT BY: _____

A handwritten signature in black ink, appearing to read "JSG".

John S Graves, Jr.