

## **Projected Summer 2017 Facilities Projects**

1. Hard surface behind Gavin South (parking lot to storage area and sidewalk to back door) – estimated cost - \$23,000
2. Hard surface repair for driveway at South (around inside of exit turn) – estimated cost - \$9,000
3. Locker replacement (girls locker room – Gavin South) – estimated cost - \$22,000
4. Concrete replacement by south entrance at Gavin Central – estimated cost - \$10,000
5. Sealcoating front of Central – estimated cost - \$5,000