



Sheridan School District 48J

Facility Survey

Final Results

- 1_B. SHS Classroom Heating Systems – updated or replaced
- 2_G. FCS & SGS safety and access issues (e.g. buzz-in doors, handicapped access door)
- 3_A. SHS main Restrooms and Plumbing
- 4_E. SHS Window replacement and wall structural changes to reduce the number of windows
- 5_C. FCS Old Gym Heating System Upgraded
- 6_J. District Technology (networking server upgrades, VOIP Phone System and wireless internet)
- 7_I. SHS Shop Classroom (Ventilation & Air Filtration, Heating, and project & storage spaced added)
- 8_D. SHS Stadium Roof Repaired and Stadium Lights replaced
- 9_H. SHS Track Re-surfaced and add Pole Vault & Javelin area
- 10_F. FCS add a Garbage Pad on the Wes side to manage garbage collection and security

