

Maintenance Board Report

We have had to work a lot on the boiler this winter. The old pipes and steam traps will have to be replaced in the old gym. Who knows what will happen when we start putting wrenches on the old pipes. The condensate tank will need to be replaced due to it rusting and a small hole in it.

Due to the weather there has been damage to the Middle school and Elementary roofs. It has torn off some of the vinyl roofing and the gutters. There has been water leaking in the outside walls at the middle school.

Tom Muir