

Northland Community Schools

Independent School District #118

School Board Report

Date: Apr25



- MNPCA limited site investigation update– reporting complete and submitted in review with MPCA
- MAU for kitchen lockout alarms - gas valve installed, and ignition replaced
- AHU 2 air handler return motor – motor replacement complete
- Sanitary waste line jetted in playground for large blockage. Noted that the line was 4” inserted into clay liner, it was not ice possible clothing being flushed