

DEPT. OF FACILITIES
CONSTRUCTION REPORT
JUNE 2019

Submitted by: Reid Reagan

BES:

Doing a utility locate for the expansion/addition of playground equipment. Work to include removal of sprinkler system and sod. Ever since the sod and sprinkler system was installed it has leaked into the gym locker rooms located next to playground area. While we are doing work in the area there is the need to excavate the west wall of building down to the footings and seal/waterproof the foundation wall. Also, every time it rains the water sets in the low spots/ when sod was installed it wasn't graded to run to the storm drain.