

**MAINTENANCE REPORT
FEBRUARY 2021**

Submitted by: Reid Reagan

Maintenance staff has been busy trying to keep buildings warm and the water/sewer lines in service with the recent cold snap.

HIGH SCHOOL:

Installed new temperature control switch in the freezer, added freon to the cooler. Repaired faulty heat supply lines to the mechanical room in the A wing. Replaced motor to the air handler in the C wing.

BMS:

Installed new touchless water bottle filling station, new 6th grade pod. Moving back into the building, haul equipment back into the Music and Shop classrooms.

NAPI:

Replaced motor to heater that supplies mechanical room in the basement. Replace leaking water line in basement that supplies Admin, had frozen and cracked when thawing line.

KWB:

Replaced leaking, rusted out water line in Room 5, install new piping, sheetrock and texture.

WBH:

Made necessary corrections to the building after State of Montana Fire Inspection, conducted by Fire Marshall.

ANNEX:

Installed new touchless water bottle filling station, made necessary corrections to the building after State of Montana Fire Inspection, conducted by Fire Marshall.

BABB:

Replaced faulty pressure relief valve to boiler, heat restored.

SPED:

Installed new I-wave air purifier to the furnace .

ADMIN:

Installed new I-wave air purifier to the furnaces.