

MAINTENANCE REPORT OCTOBER 2025

Submitted by: Reid Reagan

Maintenance staff participated in the BPS reunification drill, relocating at BMS. Also assist with traffic control for the Homecoming activities. Inspect the School's facilities trees and delimb the dead branches, winterize the lawns by spreading winterguard weed and feed.

BHS:

Replace faulty pressure reducing control valve to water booster pump, system restored. Replace broken automatic toilet flush valves with manual flush valves (7). Setup new cabinet and install bookshelves in SPED room.

BMS:

Cutout new access panel to boiler shutoff valves, shut down boilers and replace rusted out shutoff valve, gaskets to 6" supply line, heat system restored. Repair automatic handicap door at main entrance, resolder wires, system restored. Install new tetherball poles (2) in playground area.

NAPI:

Disconnect power, remove the old heated serving table. Wire new outlets (2) and install new cooled/heated serving counter/table with sneeze guards. Snake plugged sewer line serving SPED and 4th grade hallway, system restored.

BULLSHOE:

Replace broken window in KW kitchen/cafeteria.

BABB:

Replace worn out fanbelt to the AHU, heat restored.