

# *DERBY SCHOOLS*

**Facilities Report February 2021**

# Derby High School

- Repaired heat in G07
- Repaired cabinet in LRU
- Repaired exterior gate at LRU
- Replaced thermostat in LRU
- New master clock transmitters installed
- Installed new ceiling tiles in numerous areas
- Replaced faulty outlets in G05
- Restroom plumbing repairs in storage area



# Derby Middle School

- Repaired drain issues C2
- Restored power to wall outlets in C3
- Repaired faculty restroom door lock
- Replaced faulty heat valve in C4
- Repaired light fixture in A10
- Changed water fountain filters
- Boiler #2 air metering diaphragm
- Installed new door closer in B9



# Bradley Elementary

- Replaced discharge pump line
- Repaired exhaust fan
- Replaced faulty outlet in upper hallway
- Faucet repairs in 103
- Plumbing repairs in boys lower wing restroom



# Irving Elementary

- Repairs made to Boiler #1 piping
- Assembled and placed 10 new student desks
- Repaired faulty gate lock
- New drain piping installed on boiler #1
- Replaced multiple ceiling tiles on first floor
- Plumbing repairs in faculty restroom



# General

- Summer project plans underway
- Snow removal - 8 storms to date
- JCI in submittal process to state for solar panels; painted pipe wrap in room 103 at Irving
- Plexiglass divider discussion

