Proposed Project		Anticipated Cost
FY 19: Summer, 2019 10 Year Heath/Life Safety Survey (29,500 S.F)		5900
Replace condensing units CU-1, refigerant piping (due to updated code); and cooling coils associated with AHU1 (installed 1993 & 1994; 20 y expecatancy) Replace pump seals on 2 heaeting system pumps Total		266,341 2000 274,241
FY 20: Summer, 2020 Replace condensing units CU-1, refigerant piping (due to updated code); and cooling coils associated with AHU1 (installed 1993 & 1994; 20 y expecatancy) Technology audit of infrastructure Re-chip playground	D303 D303	266,341
Total		266,341
FY 21: Summer, 2021		
Replace Air Handler Units AHU-2 serving south half of 1975 building (installed 1975; 40 y expectancy) Sealcoat/asphalt repairs	D303	350,000
Total		350,000
FY 22: Summer, 2022 Install cameras Adminstration only Total		TBD
FY 23: Summer, 2023 Replace existing flourescent lighting with energy efficient T8 lamps (80 ea)-MJC Repace existing battery backup lighting units with energy efficient LED units (30 ea) Replace carpet in 1975 building corridoors (2000 sf) Total		28,033 12,372 20,705 61,110
FY 25: Summer, 2025 Replace roof areas 1 & 2 (17,765 sf); build-up roof (installed 2000; warrenty expires 8/4/2020; patching performed 2016)		444,125
Total		444,125

FY 30: Summer, 2030Replace roof areas 3 & 3A (11,500 sf); fully adheres EPDM (installed 2005; warrenty expires 8/4/2030 +/-) 287,500 **Total** 287,500