

## Maintenance Summary Report

Director Javier Solis

Coordination w/ GRE consultants completed; walk thru, measurements, final procurement / bid packages ready for bidding

DVA - Tabletop Discussion

DVA Audit Correction - (Signs Now) currently finalizing entry doors numbering - 4inches or larger required per Audit

Maintenance - Main Lift Station: repaired (2) sensor floats w/ assistance from Superior Electrical (electrical wiring short - installed new wiring)

Cafeteria Mob Station - (Audit correction) prep custodian restroom for upgrades (work to be performed by Mr. Shafer)

HVACs - preventative maintenance - clean coils & drain lines that cause overflow

DVA Audit Correction - inventory / order push bars & handles for entry doors

Grounds / Fleet / Custodian will submit there summaries respectively