

**MAINTENANCE REPORT
FACILITIES/CONSTRUCTION REPORT
MARCH 2025**

Submitted by: Reid Reagan

Maintenance staff has been busy with snow removal. Preparing for annual boiler inspection at all the schools, no deficiencies. In addition, we had State Fire Marshal inspections, we are currently making the corrections. Groundskeepers readying the fields/track for spring sporting events. The staff has responded to 80 work orders, all repairs or service calls.

BHS:

Summit Fire Protection performed 12 year hydrotest for kitchen exhaust/fire suppression system, service included 2 new tanks, chemical, double tank cartridges and fuselink.

BABB:

Pump out kitchen grease traps, septic holding tank, and snake sewer line from tank to school, system restored.

NAPI:

Summit Fire Protection upgraded obsolete sentinel control in kitchen exhaust/fire suppression system.

BMS:

Repair hardware to door panic/push bar for automatic/handicap door, system restored.

BULLSHOE-KW Wing:

Summit Fire Protection performed 12 year hydrotest for kitchen exhaust/fire suppression system, service included 1 new tank, chemical, tank cartridge and fuselink. Repair kitchen sprayer to dishwasher, service restored.

BULLSHOE-VC Wing:

Summit Fire Protection performed 12 year hydrotest for kitchen exhaust/fire suppression system, service included 1 new tank, chemical, tank cartridge and fuselink. Repair kitchen garbage disposal, service restored.

SPED:

Remove conference table, install and setup new office desk.

BUS GARAGE:

Install new ground wire for electrical GFI outlets in the offices, service restored.