

Board Report 2/8/21

The press box at the football field is in really poor shape. The roof has rotted due to not having a water proof barrier, which also caused the floor and walls to partially rot. I am in the process of getting estimates to completely dismantle the existing structure and replacing it with a new one.

Each school now has a water bottle filler / drinking fountain installed. The high school also has an extra one installed near the weight room, which was purchased by a student as a senior project.

Dan Aberasturi