

CERTIFICATE OF APPROVAL FOR THE EXPENDITURE OF FIRE PREVENTION AND SAFETY FUNDS

(Section 17-2.11 of the School Code)

| | |
|----------------------------------|--------|
| EUGENE FIELD SPEC SERVICE CENTER | McLean |
| School Building | County |
| McLean County USD 5, 0050 | |
| District Name and Number | |
| Amendment Number 22 | |

| | |
|---------------------------------------|----------|
| Total Previously Approved | |
| Approved to raise with this Amendment | \$396.00 |
| Total Approved to Date | \$396.00 |
| Existing District Funds Approved | \$0.00 |

I, , State Superintendent of Education, acknowledge receipt of the estimate of cost certified by the architect/engineer required:

| | | |
|----|--------------------------|--|
| 1. | <input type="checkbox"/> | to bring this school building into compliance with the safety standards set forth in 23 Ill. Adm. Code Part 175, 23 Ill. Adm. Code Part 180, and or 23 Ill. Adm. Code Part 185 as promulgated by the State Board of Education. |
| 2. | <input type="checkbox"/> | to bring the school building into compliance with the Asbestos Abatement Act 105 ILCS 105/1 et.seq, and the federal Asbestos Hazard Emergency Response Act of 1986 as amended (AHERA). |
| 3. | <input type="checkbox"/> | to provide funds for energy conservation; disabled accessibility; school security; repair of school sidewalks, playgrounds, parking lots, or school bus turnarounds; and other repair purposes pursuant to Section 17-2.11 of the School Code with funds not necessary for the completion of items under No. 1 or No. 2 above. |

I Further certify that the estimate of total approval to date, in the amount of \$396.00 has been examined and determined to be reasonable and is hereby approved.

| | |
|------|--|
| | |
| Date | Signature of State Superintendent of Education |

EXPLANATORY NOTES:

| | | |
|----|-------------------------------------|---|
| 1. | <input checked="" type="checkbox"/> | No items in this amendment were disapproved nor were any of the estimated costs adjusted. |
| 2. | <input type="checkbox"/> | One or more items in this amendment were disapproved and the estimated costs adjusted accordingly. The amount shown above as the total amount approved for this amendment reflects an aggregate cost adjustment of + / - \$0.00. Comments regarding this amendment and a list of the items disapproved and cost adjustments applied are attached to this certificate. |

COMMENTS:

ADJUSTED ITEMS:

| ITEM ID | DESCRIPTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | DIFFERENCE | REASON |
|---------|-------------|------------------|-----------------|------------|--------|
|---------|-------------|------------------|-----------------|------------|--------|

CERTIFICATE OF APPROVAL FOR A TEN YEAR SURVEY REPORT

(Section 2-3.12 of the School Code)

| | |
|----------------------------------|--------|
| EUGENE FIELD SPEC SERVICE CENTER | McLean |
| School Building | County |
| McLean County USD 5, 0050 | |
| District Name and Number | |
| | |

I, , State Superintendent of Education, acknowledge receipt of this ten-year safety survey report, approved for the year **0**. Hence, the next safety survey report will be due in the year **0**. The District architect has provided assurances that the building named above has been surveyed in accordance with 105 ILCS 5/2-3.12. This Certificate of Approval for a Ten Year survey Report does not necessarily imply that Fire Prevention and Safety Funds can be used for the work items listed in this survey report.

| | |
|------|--|
| | |
| Date | Signature of State Superintendent of Education |
| | |

COMMENTS:

| ITEM ID | DESCRIPTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | DIFFERENCE | REASON |
|---------|-------------|------------------|-----------------|------------|--------|
|---------|-------------|------------------|-----------------|------------|--------|

OTHER COMMENTS:

| ITEM ID | DESCRIPTION | REASON |
|---------|---|--------|
| 2 | Rooms listed above all have slab to roof storefront glass and fill panel system. The system includes steel grid supports for the glazing and panels. Some of the caulking is the original 1956 material. It has been tested and contains ACM verified by Ideal Enviornmental. | |

REQUEST FOR AUTHORIZATION To use Fire Prevention and Safety Funds

Amendment Number

PART I. CERTIFICATION OF ESTIMATED COSTS


This is to certify that:

The EUGENE FIELD SPEC SERVICE CENTER school, located at 412 E Cypress St Normal, Illinois, and under the management and control of the Board of Education of School District # 0050, McLean County, was surveyed by me on 3/10/2025.

- ☒ All of the urgent or necessary work as indicated on the attached Form 35-48 is necessary to abate the violations of applicable code requirements and should result in effecting compliance with said requirements within prescribed timelines. No violations of applicable code requirements other than those cited in previously approved safety survey reports or amendments and those noted in this survey or amendment were noted.

- ☒ All other work recommended in the attached Form 35-48, though not required to abate violations of applicable requirements of the Health/Life Safety Code for Public Schools, is recommended for energy conservation; disabled accessibility; school security; repair of school sidewalks, playgrounds, parking lots, or school bus turnarounds; and other repair purposes provided in Section 17 2.11 of the School Code.

The certified estimated cost figures were prepared by me and to the best of my knowledge are true and accurate estimates of the costs to execute the work as specified. The total estimated costs to finance the work involved is \$ **396.00**.

| | |
|---|--|
| Name of Architect/Engineer Randall Middleton | Name of Firm MIDDLETON ASSOCIATES INC. |
| Phone Number (309) 452-1271 | Fax Number (309) 454-8049. |
| License Number 001-007938 | Expiration Date 11/30/2024 |
| Email Address rand@miltonassociates.net |  [Seal and Signature] |



PART II. CERTIFICATION OF NEED (Provided by district through IWAS)

The local Board of Education hereby certifies and assures the State Board of Education:

- Based upon the report of the architect referred to above, the district faces total estimated costs of \$ to finance the work involved.
- The district has \$ available in its operations and maintenance fund, fire prevention and safety fund, school facility occupation tax fund and/or other fund to finance the work.
- If Fire Prevention and Safety funds are to be used, the district certifies that it has levied the maximum authorized rate for its operations and maintenance fund for the most recent year for which tax rates are available.
- The district needs to raise \$ in additional revenue through the levy of the Fire Prevention and Safety Tax or issuance of Bonds to finance the recommended work.
- Plans and specifications for the work will be submitted to the Regional Superintendent for review and approval.
- The work to be financed with Fire Prevention and Safety funds will not commence until the Certificate of Approval of the State Superintendent is received, the detailed plans and specifications have been approved by the regional superintendent and the regional superintendent (or other lawful agency) has issued an appropriate Order to Effect Compliance with the Health/Life Safety Code for public schools (or other lawful order requiring the work to be done).

VIOLATION AND RECOMMENDATION SCHEDULE

(23 IL Adm. Code 180, Sections 180.320)

| | | | | | | |
|-------------------------------|---|--|------------------|---|---|---|
| 1. COUNTY CODE 064, McLean | | 2. DISTRICT CODE/NAME 0050, McLean County USD 5 | | | 3. FACILITY CODE/NAME EUGENE FIELD SPEC SERVICE CENTER | |
| 4. Item ID | 5. Location(s) (Room No) | 6. Priority Code | 7. Rule Violated | 8. Description of the violation | | 9. Recommendation to correct violation |
| 1 | Classroom 7 | c. | 185.50 (a) | Large 1.5 sq ft wet spot in ceiling. | | determine the cause of the wet spot. |
| 2 | Classroom 17, Classroom 16, Girls Restroom 19, 1, and Boys Resrtroom 21 | b. | 105 ILCS 105/4 | Rooms listed above all have slab to roof storefront glass and fill panel system. The system includes steel grid supports for the glazing and panels. Some of the caulking is the original 1956 material. It has been tested and contains ACM veridified by Ideal Enviornmental. | | Remove old cracked caulking and install new glazing sealant. STOP: This is a partial repeat of an amendment from 2007 |

SCHEDULE OF RECOMMENDED WORK ITEMS AND
ESTIMATED COSTS

| 1. COUNTY CODE | | | 2. DISTRICT CODE/NAME | | | | 3. FACILITY CODE/NAME | | | | |
|----------------|----------------|------------------|---|---------------------|-------------|----------------|---|--------------------|---------------------|-------------------------------|------------------|
| 064, McLean | | | 0050, McLean County USD 5 | | | | EUGENE FIELD SPEC SERVICE CENTER | | | | |
| 4. Item I.D. | 5. Action I.D. | 6. Priority Code | 7. Specification(s) | 8. Units Of Measure | 9. Quantity | 10. Labor Code | 11. Estimated Cost (Architect / Engineer) | 12. ROE Adjustment | 13. ISBE Adjustment | 14. Estimated Completion Date | 15. Funding Type |
| 1 | c | c. | Repair and repaint required. | sq. ft. | 2 | 2 | \$330.00 | | | 8/15/2025 | F |
| 2 | f | b. | Install silicone glazing sealant continuous on vertical and horizontal surfaces where ACM caulk has been removed. | lineal ft. | 738 | 2 | \$0.00 | | | 8/15/2026 | O |

| | | | | | |
|--|-----------------------------|----------|-----------------------------|----------|--|
| | Original Subtotal | \$330.00 | Adjusted Subtotal | \$330.00 | |
| | Original 10.00% Contingency | \$33.00 | Adjusted 10.00% Contingency | \$33.00 | |
| | Original 10.00% A/E Fees | \$33.00 | Adjusted 10.00% A/E Fees | \$33.00 | |
| | Original Grand Total | \$396.00 | Adjusted Grand Total | \$396.00 | |

Items with a Funding Type of 'O' are not included in the cost calculation.
35-48 (7/07) (Prescribed by ISBE for Local Board Use)