

Central Office	Replace 5 Coils	\$19,994.35	
Headstart	Replace 5 Coils	\$13,474.25	
DSAC	Replace 1 Compressor	\$28,464.57	
District Wide	Controls PM	\$14,256.00	
	Epoxy Coating on Coils	\$5,330.26	
Headstart	Add Controls	\$30,778.00	
MS Supply Closet	Repairs	\$3,400.00	
Weight Room			
		\$115,697.43	