



J&D ENTERPRISES
Seating & Safety Solutions LLC.

Bleacher Safety Inspection Report



**Winfield School
District 34**
Where Learning is Personal

Facility:

Winfield Central Middle School
OS150 Park Street,
Winfield, IL 60190

Attention:

Antoine Blake

Service date:

October 3, 2025

Inspections:

W24-604A Main Gym



Inspection and maintenance was performed on the following for telescopic bleachers:

Surface Structure: Includes but not limited to seats, foots, risers, and skirt boards, aisle ways, guard rails, hinges, fasteners, seat brackets, and end closures.

Under Structure: Includes but not limited to trucks, guide bars, row locks, wheels, uprights, cantilevers, guides, braces, deck brackets, floor attachments, wall attachments, wiring and power system components.

Code Items: All code violations will be mentioned in the report under each section. **(If any are found)**

Check List:

- 1) Inspect seats and attachment brackets.
- 2) Inspect guard systems.
- 3) Inspect center hand rails.
- 4) Inspect aisle steps.
- 5) Inspect step nose markings.
- 6) Inspect all decks boards.
- 7) Inspect all front and rear risers.
- 8) Inspect wheel chair seating areas.
- 9) Inspect aisle and end closers.
- 10) Inspect pendent controls.
- 11) Verify safety code requirements.
- 12) Verify all athletic equipment above bleachers is equipped with fall protection.
- 13) Inspect wiring and controls.
- 14) Inspect power systems.
- 15) Inspect trucks, cantilevers and deck brackets.
- 16) Inspect truck wheels, axles, guide rods and row locks.
- 17) Inspect cantilever guides and rollers.
- 18) Inspect all floor and wall anchors.
- 19) Inspect all anchor boards and brackets.

These bleachers have been inspected in compliance with the **(IBC15: 1029.1.1; IBC09/06/03: 3401.1; ICC 300-12/07/02; BOCA-F: 106.4; NFPA 102)** where yearly inspection and maintenance is required. All of J&D Enterprises inspectors are experts in the industry and have been factory trained on inspections, installations and repairs of all indoor and outdoor bleacher systems. J&D Enterprises employees are not architects or structural engineers. If structural defects or deficiencies are found on or in any of the bleacher structures we inspected. J&D Enterprises will advise the owners of this bleacher(s) to contact an architect and engineer to complete an inspection.



Winfield Middle School / Main Gym	
Bleachers:	1 Bank
Manufacturer:	Kodiak Bleacher Company
Operation:	Powered
Capacity:	243Net Seating
Banks:	North 6 Rows, 3 Sections, 74'
Rise x Run:	9-5/8" x 24"
End Rails:	42 1/2"
Aisles:	3 @ 52"
ADA:	1 @ 36" and 2 @ 66"
Power:	3 Floor Friction, (2) single wide track 8" x 4" standard 1" Bore
Wheels:	1-1/4"x 5" x 1/2" axle



Seats:
Repairs: <ul style="list-style-type: none">(2) Broken seats, right middle section, rows 1 and 3. 2 men 2 hrs to replace.

Wheelchair:
Repairs: <ul style="list-style-type: none">Nothing needed at this time.
Code: <ul style="list-style-type: none">Meets or exceeds.

Guard Rails:
Repairs: <ul style="list-style-type: none">All rails were properly aligned.
Code: <ul style="list-style-type: none">Meets or exceeds.



Aisles:
Repairs: <ul style="list-style-type: none">• Nothing needed at this time.
Code: <ul style="list-style-type: none">• Meets or exceeds.

Decks and Risers:
Repairs: <ul style="list-style-type: none">• Nothing needed at this time.

Supports:
Repairs: <ul style="list-style-type: none">• All under structure components were lubricated at time of inspection.

Floor and wall attachments:
Repairs: <ul style="list-style-type: none">• Nothing needed at this time.

Wheels:
Repairs: <ul style="list-style-type: none">• Nothing needed at this time.

Power:
Repairs: <ul style="list-style-type: none">• Nothing needed at this time.

Safety Codes:



These bleacher banks meet or exceed the standard safety codes set forth by the **ICC 300-2012 Standard for Bleachers Folding, Telescopic Seating and Grandstands.**

Inspection completion date: 10/3/2025

Summary of additional repairs:

Replace (2) seats.	\$850.00
Total for all materials delivered and installed	\$850.00

Summary of suggested upgrades:

Rail extensions will be priced upon request	
--	--

Note:

- Prices good for 30 days. All labor pricing is based on current 2025 prevailing wage rates.
- All pricing is based off of all work being completed with other work at school district or in area.
- If school district wishes for any job to be completed separately, additional charges may apply.
- These bleacher banks will be safe for spectator use once all the necessary repairs and upgrades have been completed.

Note: This report does not eliminate or transfer the school district's liability in any way. J&D Enterprises is not obligated to fix, replace or discard of any materials mentioned in this report. It is our obligation to inform you of all the findings during our safety inspections. All bleachers folding, telescopic seating and grandstands are to be inspected once a year to comply with the **(IBC15: 1029.1.1; IBC09/06/03: 3401.1; ICC 300-12/07/02; BOCA-F: 106.4; NFPA 102)** Operation of the bleachers should be limited to trained maintenance personnel only. Operation to these bleachers should only be performed in an empty gym. Failure to follow these directions can result in equipment failure resulting in injury or death. A periodic check of these structures should be performed by maintenance personnel. All findings should be reported to J&D Enterprises immediately. Code items are usually covered by a "grandfather clause". If such a clause(s) exists, it is the responsibility of the owner to supply such information deemed necessary to protect the owner of certain liabilities.