

## MAINTENANCE REPORT SEPTEMBER 2025

Submitted by: Reid Reagan

Maintenance staff has been preparing for winter, cleaning strainer, replacing filters of the heat systems, winterizing the sprinkler systems, by blowing out water lines with air and remove all tanks, pumps. Assemble, deliver and set-up the new tele-health pods at all the schools.

### BHS:

Repair faulty circulation pump at hot water storage tank, service restored. Replace faulty, rusted out 6" groove lock pipe/fittings and phalange/gaskets for heating pump lines. Pick rock, mow grass, fill-in holes, regrade and compact soils on new x-country course. Install new wind fence at west side of shotput area. Repair broken stall doors (2) in the boys restroom at Sportsplex. Install speed bumps at the cross-walk area.

### BMS:

Repair gym roof, certified Mule Hide repair person patch rubber membrane along the east and west walls. Repair roof at the old entrance.

### BES:

Replace worn out heat pump gaskets in the boiler room.

### BULLSHOE:

Plant trees along the fence, add mulch and pavers around the planted areas. Install new control board for dishwasher in KW kitchen. Replace broken window at KW classroom. Install speed bumps at the crosswalk, dropoff areas.

### FDC:

Pull weeds, plant trees along the western ditchline, add topsoil.

### NAPI:

Drain heating lines, replace worn out heat pump gaskets add water/glycol back. Replace broken windows in the music room. Install speed bumps at the dropoff area.